Progress Estin 25	D	ontract ID 201218-0 ime Contractor Capital P			d May 15, 2022 Net (inal Contract Amount Change Order Amount ent Contract Amount	t \$30,142.40		
Approval Date							By User		
May 16, 2022		Gen	erated and Approved (and should be consid	lered Draft) at the Pro	ject Office Level by	hessec2		
May 16, 2022		Reviewe	d and Approved (and s	should be considered	Draft) at the Residen	t Engineer Level by	ilesb1		
May 17, 2022			Reviewed	and Approved at the (Central Office Control	lers Office Level by	ramses1		
Original Con	pletion Date	Current Completion	Date Actua	al Completion Date	% of Curr	% of Current Contract Amount Complete			
July 1	, 2022	July 1, 2022				57.34%			
C	ontract Informatio	nal Dates			Milestones				
Date Description	Original Completion Da	Current te Completion Date	Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days		
Acceptance Date			Milestone - Calendar Time	May 10, 2022	May 10, 2022	-7			
Awarded Date	January 6, 2021	January 6, 2021							
Letting Date	December 18, 20	20 December 18, 2020							
Notice to Proceed Date	March 8, 2021	March 8, 2021							
Work Began Date	June 21, 2021	June 21, 2021							

Contract Total Pa	y For Estimate No. 25			
		This Estimate	Previous	To Date
201218-C04				
	Total Posted Items Pay	\$77,157.60	\$4,180,522.68	\$4,257,680.28
	Gross Item Adjustments	\$21,735.50	\$419,956.85	\$441,692.35
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	,		\$4,600,479.53	\$4,699,372.63
Contract Total Pa	yable This Estimate:	\$98,893.10		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J4P3015	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$8.000	124.7	\$997.60			
	0620	4030403	10 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	SQYD	\$35.000	2,176	\$76,160.00			
Project J4P301	15 - Total						\$77,157.60			
Overall - Total	Dverall - Total									

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3015	0060	COMPACTING IN CUT	Material			-30.8	\$1,700.00	(\$52,360.00)
	0060	COMPACTING IN CUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	30.8	\$1,700.00	\$52,360.00
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-4,200.7	\$8.00	(\$33,605.60)
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hessec2	4,200.7	\$8.00	\$33,605.60



Progress	s Estim 25	ate Number	Contract ID Prime Contrac	201218-C tor Capital Pa		Pay Period Start May 2, 2022 Or truction, LLC Pay Period End May 15, 2022 Ne Cu	t Change Or	der Amount	
Project Number	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3015						overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	0120	CONCRE	TE APPROACH PAVEMENT	Material			-397	\$130.00	(\$51,610.00
	0120	CONCRE	TE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	397	\$130.00	\$51,610.00
	0550	SEEDING -	COOL SEASON GRASSES	Material			-0.8	\$1,452.00	(\$1,161.60
	0550	SEEDING -	COOL SEASON GRASSES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 43 on the current Payment Estimate.	0.8	\$1,452.00	\$1,161.60
	0620		ES, ASPHALTIC TE PAVEMENT SP125C	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	2,176	\$5.35	\$11,641.99
	0620		ES, ASPHALTIC TE PAVEMENT SP125C	Other Item Adjustment	Fuel Price	Removing the auto generated Fuel Adjustment. Will add the correct amount.			(\$11,641.99
	0620		ES, ASPHALTIC TE PAVEMENT SP125C	Other Item Adjustment	Fuel Price	Fuel Adjustment Line No. 0620 Installed Quantity = (4039.90 SY @ 4.25" on 5-12-22) (1127.80 SY @ 4.00" on 5-13-22) 1192.45 tons * 2.93 (difference) * 3.32 =			\$11,599.67
	0620		ES, ASPHALTIC TE PAVEMENT SP125C	Other Item Adjustment	Asphalt Cement Price Adjustment	\$11,599.67 AC Adjustment Line No. 0620 Installed Quantity = (4039.90 SY @ 4.25" on 5-12-22) (1127.80 SY @ 4.00" on 5-13-22)			\$10,135.83
						1192.45 tons * 250 (difference) * 3.4% =\$10,135.83			
	0830	BRIDGE AP	PROACH SLAB (MAJOR)	Material			-174	\$280.00	(\$48,720.00
	0830	BRIDGE AP	PROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	174	\$280.00	\$48,720.00
	0880	SLAB ON	I CONCRETE I- GIRDER	Material			-612	\$400.00	(\$244,800.00
	0880	SLAB ON	I CONCRETE I- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 34 on the current Payment Estimate.	612	\$400.00	\$244,800.00
	0890	TY	PE D BARRIER	Material			-314	\$103.00	(\$32,342.00
	0890	ΤΥ	PE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 35 on the current Payment Estimate.	314	\$103.00	\$32,342.00
	0990	BRIDGE AP	PROACH SLAB (MAJOR)	Material			-171	\$257.00	(\$43,947.00
	0990	BRIDGE AP	PROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	171	\$257.00	\$43,947.00

Progress	s Estin 25	nate Number	Contract ID Prime Contrac	201218-C tor Capital Pa		Pay Period Start May 2, 2022 Or ruction, LLC Pay Period End May 15, 2022 Ne Cu	t Change Or	der Amount	
Project Number	Line No.	Item D	escription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3015						Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
	1040		B-2 CONCRETE UCTURE SOLID SLAB)	Material			-273.5	\$820.00	(\$224,270.0
	1040		B-2 CONCRETE UCTURE SOLID SLAB)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 30 on the current Payment Estimate.	273.5	\$820.00	\$224,270.0
	1050	ΤY	PE D BARRIER	Material			-222	\$115.00	(\$25,530.0
	1050	ΤY	/PE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 36 on the current Payment Estimate.	222	\$115.00	\$25,530.00
	1110	BRIDGE AF	PROACH SLAB (MAJOR)	Material			-162	\$255.00	(\$41,310.0
	1110	BRIDGE AF	PROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	162	\$255.00	\$41,310.0
	1170	ΤY	PE D BARRIER	Material			-183	\$130.00	(\$23,790.0
	1170	ТҮ	PE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 37 on the current Payment Estimate.	183	\$130.00	\$23,790.0
I4P3015B	1390	CONCRE	TE APPROACH PAVEMENT	Material			-110	\$150.00	(\$16,500.0
	1390	CONCRETE APPROACH PAVEMENT		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.	110	\$150.00	\$16,500.0
	1510	BRIDGE AF	PROACH SLAB (MAJOR)	Material			-172	\$255.00	(\$43,860.0
	1510	BRIDGE APPROACH SLAB (MAJOR)		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	172	\$255.00	\$43,860.0
	1550		B-1 CONCRETE IBSTRUCTURE)	Material			-36.8	\$1,500.00	(\$55,200.0
	1550	CLASS B-1 CONCRETE (SUBSTRUCTURE)		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 28 on the current Payment Estimate.	36.8	\$1,500.00	\$55,200.0
	1560		B-2 CONCRETE UCTURE SOLID SLAB)	Material			-226.8	\$960.00	(\$217,728.0
	1560		B-2 CONCRETE UCTURE SOLID SLAB)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user hessec2 overridding Payment Estimate Exception 31 on the current Payment Estimate.	226.8	\$960.00	\$217,728.0
	1570	TY	PE D BARRIER	Material			-183	\$130.00	(\$23,790.0

Progress	s Estim 25	ate Number	Contract ID Prime Contrac	201218-C tor Capital Pa	• ·	Pay Period Start May 2, 2022Original Contract Amount\$7,394,731.98struction, LLCPay Period EndMay 15, 2022Net Change Order Amount\$30,142.40Current Contract Amount\$7,424,874.38						
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J4P3015B	1570	TYPE D BARRIER		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user hessec2 overridding Payment Estimate Exception 39 on the current Payment Estimate.	183	\$130.00	\$23,790.00			
Total									\$21,735.50			



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J4P3015	FAF 24-1(45)	Bridge replacement	24	JACKSON	from west of Osage St. to 1 mile west of Rte. H and from Burnley Rd. to 0.2 mile west of Osage St. at Union Pacific RR, Drainage Ditch, and Fire Prairie Creek
J4P3015B	FAF 24-1(84)	Bridge replacement	24	JACKSON	from 0.6 mile east of Burnley Road and 0.2 mile west of Osage Street in Buckner

Totals by Job Numbers

4P3015	This Estimate	Previous	To Date
Posted Item Pay	\$77,157.60	\$3,508,802.98	\$3,585,960.58
Gross Item Adjustments	\$21,735.50	\$411,879.85	\$433,615.35
Gross Item Pay	\$98,893.10	\$3,920,682.83	\$4,019,575.93
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
4P3015B	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$671,719.70	\$671,719.70
Gross Item Adjustments	\$0.00	\$8,077.00	\$8,077.00
Gross Item Pay	\$0.00	\$679,796.70	\$679,796.70
Gross term ray			
	\$0.00	\$0.00	\$0.00
Incentive	\$0.00 \$0.00	\$0.00 \$0.00	\$0.00 \$0.00
	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 2037075, Project Item Line Number 0060, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 3040506, Project Item Line Number 0090, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 0830, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 0830, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 0830, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 0990, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 0990, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 0990, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 1110, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 1110, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5031010A, Project Item Line Number 1110, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5031010A, Project Item Line Number 1510, Material Set 5031010A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5031010A, Project Item Line Number 1510, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5031010A, Project Item Line Number 1510, Material Set 5031010A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5031010A, Project Item Line Number 1510, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5041000, Project Item Line Number 0120, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5041000, Project Item Line Number 0120, Material Set 504100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5041000, Project Item Line Number 0120, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5041000, Project Item Line Number 0120, Material Set 504100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 5041000, Project Item Line Number 0120, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5041000, Project Item Line Number 1390, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5041000, Project Item Line Number 1390, Material Set 504100096, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5041000, Project Item Line Number 1390, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5041000, Project Item Line Number 1390, Material Set 504100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance	Tests have passed but has been entered.	hessec2	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepancies	Explanation	Entered By	Status
Action Generic 0501CCB1.A is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5041000, Project Item Line Number 1390, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5041000, Project Item Line Number 1390, Material Set 504100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 5041000, Project Item Line Number 1390, Material Set 504100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 7034003, Project Item Line Number 1550, Material Set 703400396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 7034003, Project Item Line Number 1550, Material Set 703400396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 7034208, Project Item Line Number 1040, Material Set 703420896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	PAL # has been entered but has yet been authorized.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 7034208, Project Item Line Number 1560, Material Set 703420896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 7034208, Project Item Line Number 1560, Material Set 703420896, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 7034208, Project Item Line Number 1560, Material Set 703420896, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 7034213, Project Item Line Number 0880, Material Set 703421396, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 7034219A, Project Item Line Number 0890, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 7034219A, Project Item Line Number 1050, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 7034219A, Project Item Line Number 1170, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 7034219A, Project Item Line Number 1170, Material Set 7034219A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 7034219A, Project Item Line Number 1570, Material Set 7034219A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 7034219A, Project Item Line Number 1570, Material Set 7034219A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015B, Item 7034219A, Project Item Line Number 1570, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Tests have passed but has been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 8051000A, Project Item Line Number 0550, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.	Certs have been received but has yet been entered.	hessec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3015, Item 8051000A, Project Item Line Number 0550, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Certs have been received but has yet been entered.	hessec2	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
)1218-C04	J4P3015	0001	0010	2013000	CLEARING AND GRUBBING	12.00	0.00	12.00	ACRE	10.00	\$1,800.00	\$18,000.
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$125,000.00	\$112,500.
		0001	0030	2031000	CLASS A EXCAVATION	20,691.00	0.00	20,691.00	CUYD	7,323.00	\$4.80	\$35,150
		0001	0040	2035500	EMBANKMENT IN PLACE	45,774.00	0.00	45,774.00	CUYD	43,774.00	\$9.00	\$393,966
		0001	0050	2036000	COMPACTING EMBANKMENT	12,414.00	0.00	12,414.00	CUYD	2,585.00	\$2.64	\$6,824
		0001	0060	2037075	COMPACTING IN CUT	30.80	0.00	30.80	STA	30.80	\$1,700.00	\$52,360
		0001	0070	2063000	CLASS 3 EXCAVATION	382.00	0.00	382.00	CUYD	87.00	\$22.00	\$1,914
		0001	0080	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	3,010.00	0.00	3,010.00	SQYD	3,010.00	\$9.75	\$29,347
		0001	0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	22,755.00	0.00	22,755.00	SQYD	4,200.70	\$8.00	\$33,605
		0001	0100	3101003	GRAVEL (A)	839.00	0.00	839.00	SQYD	0.00	\$15.00	\$0
		0001	0110	4019905	MISC.OPTIONAL PAVEMENT	3,010.00	0.00	3,010.00	SQYD	3,010.00	\$36.00	\$108,360
		0001	0113	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	10.00	0.00	10.00	TONS	0.00	\$2,000.00	\$0
		0001	0117	4071005	TACK COAT	4.00	0.00	4.00	GAL	0.00	\$2.60	\$0
		0001	0120	5041000	CONCRETE APPROACH PAVEMENT	805.40	0.00	805.40	SQYD	397.00	\$130.00	\$51,610
		0001	0130	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	1.00	\$2,200.00	\$2,200
		0001	0140	6069902	MISC.TYPE C MASH CRASHWORTHY END TERMINAL	3.00	0.00	3.00	EA	3.00	\$4,583.61	\$13,750
		0001	0150	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	64.00	0.00	64.00	CUYD	11.00	\$18.50	\$203
		0001	0160	6096041	PLACING TYPE 1 ROCK DITCH LINER	64.00	0.00	64.00	CUYD	11.00	\$51.00	\$56
		0001	0170	6097000	ROCK LINING	25.00	0.00	25.00	CUYD	0.00	\$120.00	\$
		0001	0180	6113020	FURNISHING TYPE 2 ROCK BLANKET	3,837.00	0.00	3,837.00	CUYD	2,918.00	\$48.00	\$140,06
		0001	0190	6113040	PLACING TYPE 2 ROCK BLANKET	3,837.00	0.00	3,837.00	CUYD	2,918.00	\$15.00	\$43,77
		0001	0200	6161005	CONSTRUCTION SIGNS	1,611.00	0.00	1,611.00	SQFT	760.00	\$5.20	\$3,95
		0001	0210	6161008	ADVANCED WARNING RAIL SYSTEM	20.00	0.00	20.00	EA	4.00	\$46.79	\$18
		0001	0220	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	0.00	\$31.19	\$
		0001	0230	6161025	CHANNELIZER (TRIM LINE)	392.00	0.00	392.00	EA	380.00	\$10.40	\$3,95
		0001	0240	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	91.00	0.00	91.00	EA	60.00	\$129.98	\$7,79
		0001	0250	6161033	DIRECTIONAL INDICATOR BARRICADE	49.00	0.00	49.00	EA	44.00	\$98.78	\$4,34
		0001	0260	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$2,027.63	\$8,11
		0001	0270	6161055	SEQUENTIAL FLASHING WARNING LIGHT	44.00	0.00	44.00	EA	0.00	\$67.59	\$
		0001	0280	6161070	TUBULAR MARKER	204.00	0.00	204.00	EA	204.00	\$77.99	\$15,90
		0001	0290	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	10.00	0.00	10.00	EA	10.00	\$883.84	\$8,83
		0001	0300	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	563.00	0.00	563.00	LF	500.00	\$28.22	\$14,11
		0001	0310	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	1,215.00	0.00	1,215.00	LF	1,200.00	\$41.61	\$49,93
		0001	0320	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$529,000.00	\$264,50
		0001	0330	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$
		0001	0340	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	106.00	0.00	106.00	LF	0.00	\$21.84	\$
		0001	0350	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	4.00	0.00	4.00	EA	0.00	\$337.94	4
		0001	0360	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,025.00	0.00	2,025.00	LF	0.00	\$0.17	S
		0001	0370	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	22,424.00	0.00	22,424.00	LF	0.00	\$0.19	Ş
		0001	0380	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	14,955.00	0.00	14,955.00	LF	0.00	\$0.21	\$
		0001	0390	6207001	PAVEMENT MARKING REMOVAL	56,262.00	0.00	56,262.00	LF	425.00	\$0.36	\$15
		0001	0400	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	3.00	0.00	3.00	EA	0.00	\$77.99	9
		0001	0410	6209903	MISC.TEMPORARY PAVEMENT MARKING	33,034.00	0.00	33,034.00	LF	32,077.00	\$0.11	\$3,52
		0001	0420	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	5,912.00	0.00	5,912.00	SQYD	3,822.00	\$2.40	\$9,17
		0001	0430	6269909	MISC.ALTERNATE RUMBLE STRIP	101.60	0.00	101.60	STA	0.00	\$72.10	\$



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-C04	J4P3015	0001	0440	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$26,000.00	\$13,000.00
		0001	0443	7040104	HALF-SOLE REPAIR	700.00	70.00	770.00	SQFT	770.00	\$75.00	\$57,750.00
		0001	0447	7040106	FULL DEPTH REPAIR	50.00	-50.00	0.00	SQFT	0.00	\$100.00	\$0.00
		0001	0450	7261015	15 IN. PIPE GROUP A	645.00	0.00	645.00	LF	624.00	\$44.00	\$27,456.00
		0001	0460	7261018	18 IN. PIPE GROUP A	96.00	0.00	96.00	LF	96.00	\$60.00	\$5,760.00
		0001	0470	7261021	21 IN. PIPE GROUP A	30.00	0.00	30.00	LF	30.00	\$122.00	\$3,660.00
		0001	0480	7261024	24 IN. PIPE GROUP A	178.00	0.00	178.00	LF	178.00	\$92.00	\$16,376.00
		0001	0490	7261036	36 IN. PIPE GROUP A	40.00	0.00	40.00	LF	40.00	\$195.00	\$7,800.00
		0001	0500	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	8.00	0.00	8.00	EA	8.00	\$193.00	\$1,544.00
		0001	0510	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$163.00	\$326.00
		0001	0520	7320621A	21 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$615.00	\$1,230.00
		0001	0530	7320624A	24 IN: OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$615.00	\$1,230.00
		0001	0540	7320636A	36 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,045.00	\$1,045.00
		0001	0550	8051000A	SEEDING - COOL SEASON GRASSES	10.70	0.00	10.70	ACRE	0.80	\$1,452.00	\$1,161.60
		0001	0560	8061004	SEDIMENT TRAP ROCK	132.00	0.00	132.00	CUYD	86.00	\$100.00	\$8,600.00
		0001	0570	8061005	ROCK DITCH CHECK	1,571.00	0.00	1,571.00	LF	754.00	\$14.88	\$11,219.52
		0001	0580	8061016	SEDIMENT REMOVAL	137.00	0.00	137.00	CUYD	0.00	\$25.00	\$0.00
		0001	0590	8061017	TEMPORARY SEEDING	1.10	0.00	1.10	ACRE	1.10	\$1,246.33	\$1,370.96
		0001	0600	8061019	SILT FENCE	6,759.00	0.00	6,759.00	LF	6,084.00	\$1.43	\$8,700.12
		0001	0610	8061050	TYPE C BERM	575.00	0.00	575.00	LF	50.00	\$25.00	\$1,250.00
		0002	0620	4030403	10 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	17,908.30	0.00	17,908.30	SQYD	2,176.00	\$35.00	\$76,160.00
		0004	0640	4010150	TYPE A2 SHOULDER	4,845.90	0.00	4,845.90	SQYD	0.00	\$36.00	\$0.00
		0010	0660	6061060	MGS GUARDRAIL	1,500.00	0.00	1,500.00	LF	0.00	\$19.83	\$0.00
		0010	0670	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,113.00	0.00	1,113.00	LF	750.00	\$22.15	\$16,612.50
		0010	0680	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	19.00	0.00	19.00	EA	10.00	\$2,600.81	\$26,008.10
		0010	0690	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$824.02	\$0.0
		0010	0700	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	18.00	0.00	18.00	EA	10.00	\$2,420.56	\$24,205.60
		0040	0710	9031010	CONCRETE FOOTINGS, EMBEDDED	0.90	0.00	0.90	CUYD	0.00	\$1,287.53	\$0.00
		0040	0720	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	2.00	0.00	2.00	EA	0.00	\$257.51	\$0.00
		0040	0730	9031270A	2 IN. PSST POST - 12 GA.	876.00	0.00	876.00	LF	0.00	\$11.33	\$0.0
		0040	0740	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	177.00	0.00	177.00	LF	0.00	\$20.60	\$0.0
		0040	0750	9031272	2.25 IN. PSST POST - 12 GA.	12.00	0.00	12.00	LF	0.00	\$12.36	\$0.0
		0040	0760	9031280	2.5 IN. PSST POST - 12 GA.	162.00	0.00	162.00	LF	0.00	\$13.39	\$0.00
		0040	0770	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	30.00	0.00	30.00	LF	0.00	\$51.50	\$0.0
		0040	0780	9035004A	SH-FLAT SHEET	654.00	0.00	654.00	SQFT	0.00	\$18.03	\$0.00
		0040	0790	9035011A	ST-STRUCTURAL	24.00	0.00	24.00	SQFT	0.00	\$20.60	\$0.00
		0040	0800	9035069A	SHF-FLAT SHEET FLUORESCENT	23.00	0.00	23.00	SQFT	0.00	\$20.60	\$0.00
		0070	0810	2061000	CLASS 1 EXCAVATION	125.00	0.00	125.00	CUYD	100.00	\$33.00	\$3,300.00
		0070	0820	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$25,000.00	\$25,000.00
		0070	0830	5031010A	BRIDGE APPROACH SLAB (MAJOR)	174.00	0.00	174.00	SQYD	174.00	\$280.00	\$48,720.00
		0070	0840	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	1,842.00	0.00	1,842.00	LF	1,815.37	\$66.00	\$119,814.42
		0070	0850	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$750.00	\$1,500.0
		0070	0860	7027000	PILE POINT REINFORCEMENT	24.00	0.00	24.00	EA	24.00	\$104.00	\$2,496.00
		0070	0870	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	87.60	0.00	87.60	CUYD	87.60	\$744.00	\$65,174.40
		0070	0880	7034213	SLAB ON CONCRETE I-GIRDER	612.00	0.00	612.00	SQYD	612.00	\$400.00	\$244,800.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

and can differ from the posted amount at the time the Estimate was Generated date

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-C04	J4P3015	0070	0890	7034219A	TYPE D BARRIER	314.00	0.00	314.00	LF	314.00	\$103.00	\$32,342.00
		0070	0900	7056000	TYPE 2 (32 IN.), PRESTRESSED CONCRETE I-GIRDER	790.00	0.00	790.00	LF	790.00	\$155.00	\$122,450.00
		0070	0910	7061060	REINFORCING STEEL (BRIDGES)	3,960.00	0.00	3,960.00	LB	3,000.00	\$1.90	\$5,700.00
		0070	0920	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	5.00	0.00	5.00	EA	5.00	\$700.00	\$3,500.00
		0070	0930	7123610	SLAB DRAIN	22.00	0.00	22.00	EA	22.00	\$210.00	\$4,620.00
		0070	0940	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,600.00	\$3,200.00
		0070	0950	7161000	PLAIN NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	12.00	\$140.00	\$1,680.00
		0070	0960	7161002	LAMINATED NEOPRENE BEARING PAD	24.00	0.00	24.00	EA	24.00	\$200.00	\$4,800.00
		0071	0970	2061000	CLASS 1 EXCAVATION	90.00	0.00	90.00	CUYD	90.00	\$33.00	\$2,970.00
		0071	0980	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$25,000.00	\$25,000.00
		0071	0990	5031010A	BRIDGE APPROACH SLAB (MAJOR)	171.00	0.00	171.00	SQYD	171.00	\$257.00	\$43,947.00
		0071	1000	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	795.00	0.00	795.00	LF	779.00	\$69.00	\$53,751.00
		0071	1010	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	1,120.00	0.00	1,120.00	LF	1,093.00	\$75.00	\$81,975.00
		0071	1020	7027000	PILE POINT REINFORCEMENT	24.00	0.00	24.00	EA	24.00	\$104.00	\$2,496.00
		0071	1030	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	38.20	0.00	38.20	CUYD	38.20	\$1,450.00	\$55,390.00
		0071	1040	7034208	CLASS B-2 CONCRETE (SUPERSTRUCTURE SOLID SLAB)	273.50	0.00	273.50	CUYD	273.50	\$820.00	\$224,270.00
		0071	1050	7034219A	TYPE D BARRIER	222.00	0.00	222.00	LF	222.00	\$115.00	\$25,530.00
		0071	1060	7101000	REINFORCING STEEL (EPOXY COATED)	59,270.00	0.00	59,270.00	LB	59,270.00	\$1.11	\$65,789.70
		0071	1070	7123610	SLAB DRAIN	16.00	0.00	16.00	EA	16.00	\$210.00	\$3,360.00
		0071	1080	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,600.00	\$3,200.00
		0072	1090	2061000	CLASS 1 EXCAVATION	70.00	0.00	70.00	CUYD	70.00	\$33.00	\$2,310.00
		0072	1100	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$25,000.00	\$25,000.00
		0072	1110	5031010A	BRIDGE APPROACH SLAB (MAJOR)	172.00	0.00	172.00	SQYD	162.00	\$255.00	\$41,310.00
		0072	1120	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	1,660.00	0.00	1,660.00	LF	1,660.00	\$68.00	\$112,880.00
		0072	1130	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$700.00	\$1,400.00
		0072	1140	7027000	PILE POINT REINFORCEMENT	20.00	0.00	20.00	EA	20.00	\$104.00	\$2,080.00
		0072	1150	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	36.80	0.00	36.80	CUYD	36.80	\$1,500.00	\$55,200.00
		0072	1160	7034208	CLASS B-2 CONCRETE (SUPERSTRUCTURE SOLID SLAB)	226.80	0.00	226.80	CUYD	226.80	\$960.00	\$217,728.00
		0072	1170	7034219A	TYPE D BARRIER	183.00	0.00	183.00	LF	183.00	\$130.00	\$23,790.00
		0072	1180	7101000	REINFORCING STEEL (EPOXY COATED)	39,180.00	0.00	39,180.00	LB	39,180.00	\$1.17	\$45,840.60
		0072	1190	7123610	SLAB DRAIN	14.00	0.00	14.00	EA	14.00	\$210.00	\$2,940.00
		0072	1200	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,600.00	\$3,200.00
		0073	1210	2061000	CLASS 1 EXCAVATION	515.00	0.00	515.00	CUYD	0.00	\$21.00	\$0.00
		0073	1220	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$75,000.00	\$0.00
		0073	1230	5031010A	BRIDGE APPROACH SLAB (MAJOR)	170.00	0.00	170.00	SQYD	0.00	\$265.00	\$0.00
		0073	1240	6071060	PEDESTRIAN FENCE (STRUCTURES)	240.00	0.00	240.00	LF	0.00	\$152.00	\$0.00
		0073	1250	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	3,654.00	0.00	3,654.00	LF	0.00	\$68.00	\$0.00
		0073	1260	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$700.00	\$1,400.00
		0073	1270	7027000	PILE POINT REINFORCEMENT	36.00	0.00	36.00	EA	0.00	\$104.00	\$0.00
		0073	1280	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	316.90	0.00	316.90	CUYD	0.00	\$600.00	\$0.00
		0073	1290	7034219A		554.00	0.00	554.00	LF	0.00	\$108.00	\$0.00
		0073	1300	7034221	SLAB ON CONCRETE NU-GIRDER	1,152.00	0.00	1,152.00	SQYD	0.00	\$325.00	\$0.00
		0073	1310	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	1,258.00	0.00	1,258.00	LF	0.00	\$250.00	\$0.00
		0073	1320	7061060	REINFORCING STEEL (BRIDGES)	46,070.00	0.00	46,070.00	LB	0.00	\$1.21	\$0.00
		0073	1330	7123610	SLAB DRAIN	12.00	0.00	12.00	EA	0.00	\$210.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1218-C04	J4P3015	0073	1350	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,600.00	\$0.0
		0073	1360	7161000	PLAIN NEOPRENE BEARING PAD	10.00	0.00	10.00	EA	0.00	\$150.00	\$0.0
		0073	1370	7161002	LAMINATED NEOPRENE BEARING PAD	20.00	0.00	20.00	EA	0.00	\$205.00	\$0.0
		0001	5001	6169901	MISC.Temporary Long - Term Rumble Strips	0.00	1.00	1.00	LS	1.00	\$2,247.00	\$2,247.0
		0001	5002	4019901		0.00	1.00	1.00	LS	1.00	\$20,715.40	\$20,715.4
		0001	5003	6069901	MISC.Impact Attenuator	0.00	1.00	1.00	LS	0.00	\$6,930.00	\$0.0
	Project J4	93015 - Tot	al Value I	Posted to Da	te as of Report Generated Date							\$3,585,960.5
	J4P3015B	0001	1380	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000.0
		0001	1390	5041000	CONCRETE APPROACH PAVEMENT	126.60	0.00	126.60	SQYD	110.00	\$150.00	\$16,500.0
		0001	1400	6113020	FURNISHING TYPE 2 ROCK BLANKET	465.00	0.00	465.00	CUYD	400.00	\$49.00	\$19,600.0
		0001	1410	6113040	PLACING TYPE 2 ROCK BLANKET	465.00	0.00	465.00	CUYD	400.00	\$19.00	\$7,600.0
		0001	1420	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$75,000.00	\$75,000.0
		0001	1430	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	698.00	0.00	698.00	SQYD	450.00	\$2.13	\$958.5
		0001	1440	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000.0
		0001	1450	8061050	TYPE C BERM	164.00	0.00	164.00	LF	0.00	\$25.00	\$0.0
		0010	1460	6061060	MGS GUARDRAIL	138.00	0.00	138.00	LF	0.00	\$19.83	\$0.0
		0010	1470	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	0.00	\$2,600.81	\$0.0
		0010	1480	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,420.56	\$0.0
		0070	1490	2061000	CLASS 1 EXCAVATION	70.00	0.00	70.00	CUYD	70.00	\$33.00	\$2,310.0
		0070	1500	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$25,000.00	\$25,000.0
		0070	1510	5031010A	BRIDGE APPROACH SLAB (MAJOR)	172.00	0.00	172.00	SQYD	172.00	\$255.00	\$43,860.0
		0070	1520	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	1,650.00	0.00	1,650.00	LF	1,616.00	\$68.00	\$109,888.0
		0070	1530	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$700.00	\$1,400.0
		0070	1540	7027000	PILE POINT REINFORCEMENT	20.00	0.00	20.00	EA	20.00	\$104.00	\$2,080.0
		0070	1550	7034003	CLASS B-1 CONCRETE (SUBSTRUCTURE)	36.80	0.00	36.80	CUYD	36.80	\$1,500.00	\$55,200.0
		0070	1560	7034208	CLASS B-2 CONCRETE (SUPERSTRUCTURE SOLID SLAB)	226.80	0.00	226.80	CUYD	226.80	\$960.00	\$217,728.0
		0070	1570	7034219A	TYPE D BARRIER	183.00	0.00	183.00	LF	183.00	\$130.00	\$23,790.0
		0070	1580	7101000	REINFORCING STEEL (EPOXY COATED)	39,180.00	0.00	39,180.00	LB	39,180.00	\$1.14	\$44,665.2
		0070	1590	7123610	SLAB DRAIN	14.00	0.00	14.00	EA	14.00	\$210.00	\$2,940.0
		0070	1600	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,600.00	\$3,200.0
	Project J4	93015B - To	otal Value	e Posted to D	Date as of Report Generated Date							\$671,719.7
1218-C04 Ove	arall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$4,257,680.2

Total Paid / All Items / All Estimates (Including this Estimate)

d date and can differ from the posted amount at the time the Estimate was Generated.



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail. location and quantity of work.

Project: J4P3015

FIOJECL	. J4P 301											
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0090	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	5/12/22	5/16/22	124.70	SQYD	The area between 598+00 to 599+40 Bridge A6743 to the West end of the job limits.	598+00		599+40		
0620	4030403	10 IN, ASPH CONC PAVE SP125C	5/13/22	5/16/22	2,176.00	SQYD	Done 5-12-22 First lift Sta. 619+13 to 627+58, and 629+08 to 632+75. Done 5-13-22 Second Lift Sta. 629+08 to 632+75, and 624+00 to 627+58.	619+13		632+75		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	0040	EMBANKMENT IN PLACE	Material	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	5	Jul 15, 2021	SYSTEM	\$8,559.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jul 15, 2021	SYSTEM	(\$8,559.00)	
					6	Aug 2, 2021	SYSTEM	\$8,559.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$8,559.00)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	0040 -	Total						\$0.00	
	0050	COMPACTING EMBANKMENT	Material		5	Jul 15, 2021	SYSTEM	\$224.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jul 15, 2021	SYSTEM	(\$224.40)	
					6	Aug 2, 2021	SYSTEM	\$224.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$224.40)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	0050 -	Total						\$0.00	
	0060	COMPACTING IN CUT	Material		24	May 2, 2022	SYSTEM	\$52,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$52,360.00)	
					25	May 16, 2022	SYSTEM	\$52,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$52,360.00)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	0060 -	Total						\$0.00	
	0090	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		24	May 2, 2022	SYSTEM	\$32,608.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		more			24	May 2, 2022	SYSTEM	(\$32,608.00)	
					25	May 16, 2022	SYSTEM	\$33,605.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$33,605.60)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	0090 -							\$0.00	
	0110	MISC.	Other Item Adjustment	ACAD	7	Aug 16, 2021	hessec2	\$754.25	AC Adjustment Line No. 0110 (BP-1) Installed Quantity:
									106.25 * 1.98 * 1.34 / 36 * 3010 SqYd * 3.2% = \$754.25
					7	Aug 16, 2021	hessec2	\$3,680.64	AC Adjustment Line No. 0110 (Bit Base) Installed Quantity:
									106.25 * 1.98 * 6.75" / 36 * 3010 SqYd * 3.1% = \$3,680.64
				ACAD - Tota	al			\$4,434.89	
				FUEL	7	Aug 16, 2021	hessec2	\$596.73	Fuel Adjustment Line No. 0110 (BP-1) Installed Quantity:



Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4P3015	0110	MISC.	Other Item Adjustment	FUEL					221.9 tons @ 3.32 * 0.81 = \$596.73		
			Tajuotnone		7	Aug 16, 2021	hessec2	\$3,005.07	Fuel Adjustment Line No. 0110 (Bit Base) Installed Quantity:		
									1117.46 tons @ 3.32 * 0.81 = \$3,005.07		
				FUEL - Tota	ıl			\$3,601.80			
			Other Item A	djustment - T	otal			\$8,036.69			
	0110 -							\$8,036.69			
	0120	CONCRETE APPROACH PAVEMENT	Material		22	Apr 4, 2022	SYSTEM	\$51,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					22	Apr 4, 2022	SYSTEM	(\$51,610.00)			
					23	Apr 18, 2022	SYSTEM	\$51,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
					23	Apr 18, 2022	SYSTEM	(\$51,610.00)			
					24	May 2, 2022	SYSTEM	\$51,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
					24	May 2, 2022	SYSTEM	(\$51,610.00)			
					25	May 16, 2022	SYSTEM	\$51,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
					25	May 16, 2022	SYSTEM	(\$51,610.00)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	0120 -	Total						\$0.00			
	0420	PERMANENT EROSION CONTROL GEOTEXTILE	Material		6	Aug 2, 2021	SYSTEM	\$64.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
		GEOTEXTILE			6	Aug 2, 2021	SYSTEM	(\$64.80)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
	0420 -							\$0.00			
	0443	HALF-SOLE REPAIR	Material		6	Aug 2, 2021	SYSTEM	\$52,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					6	Aug 2, 2021	SYSTEM	(\$52,500.00)			
					7	Aug 16, 2021	SYSTEM	\$52,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					7	Aug 16, 2021	SYSTEM	(\$52,500.00)			
							8	Sep 1, 2021	SYSTEM	\$52,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Sep 1, 2021	SYSTEM	(\$52,500.00)			
					9	Sep 15, 2021	SYSTEM	\$52,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hargrr overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					9	Sep 15, 2021	SYSTEM	(\$52,500.00)			
					10	Sep 30, 2021	SYSTEM	\$52,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					10	Sep 30, 2021	SYSTEM	(\$52,500.00)			
						2021					

14



May 18, 2022

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3015	0443	HALF-SOLE REPAIR	Material	турс	11	Oct 18, 2021	SYSTEM	\$52,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$52,500.00)	Estimate Exception 5 on the current rayment Estimate.
				- Total		-		\$0.00	
			Material - Tot					\$0.00	
	0443 -	Total						\$0.00	
	0550	SEEDING - COOL SEASON GRASSES	Material		24	May 2, 2022	SYSTEM	\$1,161.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$1,161.60)	
					25	May 16, 2022	SYSTEM	\$1,161.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$1,161.60)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0550 -	Total						\$0.00	
	0560	SEDIMENT TRAP ROCK	Material		4	Jul 1, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$2,400.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0560 -	Total						\$0.00	
	0570	ROCK DITCH CHECK	Material		4	Jul 1, 2021	SYSTEM	\$1,845.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,845.12)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0570 -							\$0.00	
	0620	10 IN, ASPH CONC PAVE SP125C	Other Item Adjustment	ACAD	25	May 16, 2022	hessec2	\$10,135.83	AC Adjustment Line No. 0620 Installed Quantity = (4039.90 SY @ 4.25" on 5-12-22) (1127.80 SY @ 4.00" on 5-13-22)
									1192.45 tons * 250 (difference) * 3.4% =\$10,135.83
				ACAD - Tota				\$10,135.83	
				FUEL	25	May 16, 2022	hessec2	\$11,599.67	Fuel Adjustment Line No. 0620 Installed Quantity = (4039.90 SY @ 4.25" on 5-12-22) (1127.80 SY @ 4.00" on 5-13-22)
									1192.45 tons * 2.93 (difference) * 3.32 = \$11,599.67
					25	May 16, 2022	hessec2	(\$11,641.99)	Removing the auto generated Fuel Adjustment. Will add the correct amount.
				FUEL - Tota	I			(\$42.32)	
			Other Item A	djustment - T	otal			\$10,093.51	
			Price FUEL		25	May 16, 2022	SYSTEM	\$11,641.99	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$11,641.99	
			Price FUEL -	Total				\$11,641.99	
	0620 -							\$21,735.50	
	0660	MGS GUARDRAIL	Construction Stockpile STMI		1	May 3, 2021	SYSTEM	\$18,630.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$18,630.00	
			Construction	Stockpile ST	MI - Total			\$18,630.00	



May 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	0660 -	Total						\$18,630.00	
	0670	MGS GUARDRAIL, 8 FT. POSTS, 6 FT.	Construction Stockpile		4	Jun 30, 2021	SYSTEM	(\$4,303.57)	Payment Estimate Item Adjustment generated Stockpile Transaction
		- 3 IN			5	Jul 15, 2021	SYSTEM	(\$4,303.57)	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	Aug 16, 2021	SYSTEM	(\$2,151.79)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$10,758.93)	
			Construction	Stockpile - T	ſotal			(\$10,758.93)	
			Construction Stockpile		1	May 3, 2021	SYSTEM	\$14,524.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$14,524.50	
			Construction	Stockpile S1	MI - Tota			\$14,524.50	
			Material		4	Jul 1, 2021	SYSTEM	\$6,645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$6,645.00)	
					5	Jul 15, 2021	SYSTEM	\$13,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jul 15, 2021	SYSTEM	(\$13,290.00)	
					6	Aug 2, 2021	SYSTEM	\$13,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$13,290.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0670 -	Total			_			\$3,765.57	
	0680	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		4	Jun 30, 2021	SYSTEM	(\$3,212.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					5	Jul 15, 2021	SYSTEM	(\$3,212.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	Aug 16, 2021	SYSTEM	(\$9,636.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$16,060.00)	
			Construction	Stockpile - 1	「otal			(\$16,060.00)	
			Construction Stockpile STMI		1	May 3, 2021	SYSTEM	\$30,514.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$30,514.00	
			Construction	Stockpile S1				\$30,514.00	
			Material		4	Jul 1, 2021	SYSTEM	\$5,201.62	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$5,201.62)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0680 -							\$14,454.00	
	0690	MGS END ANCHOR	Construction Stockpile STMI	-	1	May 3, 2021	SYSTEM	\$561.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total				\$561.00	
			Construction	Stockpile S1	MI - Total			\$561.00	
		Total						\$561.00	
	0700	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		4	Jun 30, 2021	SYSTEM	(\$3,152.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)			5	Jul 15, 2021	SYSTEM	(\$3,152.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	Aug 16,	SYSTEM	(\$9,456.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	0700	TYPE A CRASHWORTHY	Construction Stockpile			2021			
		END TERMINAL	Stockpile	- Total				(\$15,760.00)	
		(MASH)	Construction	Stockpile - 1	Fotal			(\$15,760.00)	
			Construction Stockpile STMI		1	May 3, 2021	SYSTEM	\$28,368.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$28,368.00	
			Construction	Stockpile S	TMI - Total			\$28,368.00	
			Material		4	Jul 1, 2021	SYSTEM	\$4,841.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$4,841.12)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0700 -	Total			_	_		\$12,608.00	
	0830	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		23	Apr 18, 2022	SYSTEM	\$48,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					23	Apr 18, 2022	SYSTEM	(\$48,720.00)	
					24	May 2, 2022	SYSTEM	\$48,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$48,720.00)	
					25	May 16, 2022	SYSTEM	\$48,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$48,720.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0830 -	- Total						\$0.00	
	0870	CLASS B CONCRETE (SUBSTRUCTURE)	Material		10	Sep 30, 2021	SYSTEM	\$65,174.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 30, 2021	SYSTEM	(\$65,174.40)	
					11	Oct 18, 2021	SYSTEM	\$65,174.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11 11		SYSTEM SYSTEM	\$65,174.40 (\$65,174.40)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
						2021 Oct 18,			Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
					11	2021 Oct 18, 2021 Nov 2,	SYSTEM	(\$65,174.40)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
					11	2021 Oct 18, 2021 Nov 2, 2021 Nov 2,	SYSTEM SYSTEM	(\$65,174.40) \$65,174.40	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
					11 12 12	2021 Oct 18, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16,	SYSTEM SYSTEM SYSTEM	(\$65,174.40) \$65,174.40 (\$65,174.40)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
					11 12 12 13	2021 Oct 18, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16, Nov 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$65,174.40) \$65,174.40 (\$65,174.40) \$65,174.40	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment
					11 12 12 13 13	2021 Oct 18, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$65,174.40) \$65,174.40 (\$65,174.40) \$65,174.40 (\$65,174.40)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
					11 12 12 13 13 14	2021 Oct 18, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 2, Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$65,174.40) \$65,174.40 (\$65,174.40) \$65,174.40 (\$65,174.40) \$65,174.40	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
					11 12 12 13 13 14 14	2021 Oct 18, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 2, 2021 Dec 2, 2021 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$65,174.40) \$65,174.40 (\$65,174.40) \$65,174.40 (\$65,174.40) \$65,174.40 (\$65,174.40)	Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	0870	CLASS B	Material						Estimate Exception 3 on the current Payment Estimate.
		CONCRETE (SUBSTRUCTURE)			16	Jan 3, 2022	SYSTEM	(\$65,174.40)	
					17	Jan 18, 2022	SYSTEM	\$65,174.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$65,174.40)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0870 -	Total						\$0.00	
	0880	SLAB ON CONCRETE I- GIRDER	Material		12	Nov 2, 2021	SYSTEM	\$48,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$48,800.00)	
					13	Nov 16, 2021	SYSTEM	\$48,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					13	Nov 16, 2021	SYSTEM	(\$48,800.00)	
					14	Dec 2, 2021	SYSTEM	\$48,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					14	Dec 2, 2021	SYSTEM	(\$48,800.00)	
					15	Dec 16, 2021	SYSTEM	\$48,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Dec 16, 2021	SYSTEM	(\$48,800.00)	
					16	Jan 3, 2022	SYSTEM	\$48,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					16	Jan 3, 2022	SYSTEM	(\$48,800.00)	
					17	Jan 18, 2022	SYSTEM	\$48,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$48,800.00)	
					18	Feb 1, 2022	SYSTEM	\$48,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$48,800.00)	
					19	Feb 16, 2022	SYSTEM	\$232,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					19	Feb 16, 2022	SYSTEM	(\$232,800.00)	
					20	Mar 2, 2022	SYSTEM	\$232,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$232,800.00)	
					21	Mar 16, 2022	SYSTEM	\$232,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hessec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$232,800.00)	
					22	Apr 4, 2022	SYSTEM	\$232,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$232,800.00)	
					23	Apr 18,	SYSTEM	\$244,800.00	This adjustment offsets the original system-generated Material Payment



		D		0.11	- .	0.11	0.1.1		
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	0880	SLAB ON CONCRETE I-	Material			2022			Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 32 on the current Payment Estimate.
		GIRDER			23	Apr 18, 2022	SYSTEM	(\$244,800.00)	
					24	May 2, 2022	SYSTEM	\$244,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$244,800.00)	
					25	May 16, 2022	SYSTEM	\$244,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$244,800.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0880 -	· Total						\$0.00	
	0890	TYPE D BARRIER	Material		21	Mar 16, 2022	SYSTEM	\$30,694.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$30,694.00)	
					22	Apr 4, 2022	SYSTEM	\$30,694.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$30,694.00)	
					23	Apr 18, 2022	SYSTEM	\$32,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					23	Apr 18, 2022	SYSTEM	(\$32,342.00)	
					24	May 2, 2022	SYSTEM	\$32,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$32,342.00)	
					25	May 16, 2022	SYSTEM	\$32,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$32,342.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0890 -	Total						\$0.00	
	0900	TYPE 2 (32 IN.), PRESTRESSED CONC I-GIRD	Material		10	Sep 30, 2021	SYSTEM	\$122,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Sep 30, 2021	SYSTEM	(\$122,450.00)	
					11	Oct 18, 2021	SYSTEM	\$122,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$122,450.00)	
					12	Nov 2, 2021	SYSTEM	\$122,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$122,450.00)	
					13	Nov 16, 2021	SYSTEM	\$122,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Nov 16, 2021	SYSTEM	(\$122,450.00)	
				- Total				\$0.00	



May 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	0900	TYPE 2 (32 IN.), PRESTRESSED CONC I-GIRD	Material - To	tal				\$0.00	
	0900 -	Total						\$0.00	
	0950	PLAIN NEOPRENE BEARING PAD	Material		10	Sep 30, 2021	SYSTEM	\$1,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Sep 30, 2021	SYSTEM	(\$1,680.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0950 -	Total			_			\$0.00	
	0960	LAMINATED NEOPRENE BEARING PAD	Material		10	Sep 30, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Sep 30, 2021	SYSTEM	(\$4,800.00)	
					11	Oct 18, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$4,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0960 -	Total						\$0.00	
	0990	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		20	Mar 2, 2022	SYSTEM	\$32,960.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$32,960.25)	
					21	Mar 16, 2022	SYSTEM	\$43,947.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$43,947.00)	
					22	Apr 4, 2022	SYSTEM	\$43,947.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$43,947.00)	
					23	Apr 18, 2022	SYSTEM	\$43,947.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					23	Apr 18, 2022	SYSTEM	(\$43,947.00)	
					24	May 2, 2022	SYSTEM	\$43,947.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$43,947.00)	
					25	May 16, 2022	SYSTEM	\$43,947.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$43,947.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0990 -	Total						\$0.00	
	1030	CLASS B-1 CONCRETE (SUBSTR)	Material		12	Nov 2, 2021	SYSTEM	\$55,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$55,390.00)	
					13	Nov 16, 2021	SYSTEM	\$55,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	1030	CLASS B-1 CONCRETE	Material		13	Nov 16, 2021	SYSTEM	(\$55,390.00)	
		(SUBSTR)			14	Dec 2, 2021	SYSTEM	\$55,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Dec 2, 2021	SYSTEM	(\$55,390.00)	
					15	Dec 16, 2021	SYSTEM	\$55,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Dec 16, 2021	SYSTEM	(\$55,390.00)	
					16	Jan 3, 2022	SYSTEM	\$55,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					16	Jan 3, 2022	SYSTEM	(\$55,390.00)	
					17	Jan 18, 2022	SYSTEM	\$55,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$55,390.00)	
					18	Feb 1, 2022	SYSTEM	\$55,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$55,390.00)	
					19	Feb 16, 2022	SYSTEM	\$55,390.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				19	Feb 16, 2022	SYSTEM	(\$55,390.00)		
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1030 -							\$0.00	
	1040	CLASS B-2 CONCRETE (SUPSTR	Material		12	Nov 2, 2021	SYSTEM	\$111,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$111,520.00)	
					13	Nov 16, 2021	SYSTEM	\$213,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Nov 16, 2021	SYSTEM	(\$213,200.00)	
					14	Dec 2, 2021	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Dec 2, 2021	SYSTEM	(\$224,270.00)	
					15	Dec 16, 2021	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					15	Dec 16, 2021	SYSTEM	(\$224,270.00)	
					16	Jan 3, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	Jan 3, 2022	SYSTEM	(\$224,270.00)	
				1	17	Jan 18, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$224,270.00)	
					18	Feb 1, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks													
,			Туре	Adjustment Type	Number	Date	Ву															
J4P3015	1040	CLASS B-2 CONCRETE	Material		18	Feb 1, 2022	SYSTEM	(\$224,270.00)														
		(SUPSTR			19	Feb 16, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
					19	Feb 16, 2022	SYSTEM	(\$224,270.00)														
					20	Mar 2, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
					20	Mar 2, 2022	SYSTEM	(\$224,270.00)														
					21	Mar 16, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.													
					21	Mar 16, 2022	SYSTEM	(\$224,270.00)														
					22	Apr 4, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.													
					22	Apr 4, 2022	SYSTEM	(\$224,270.00)														
					23	Apr 18, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 28 on the current Payment Estimate.													
					23	Apr 18, 2022	SYSTEM	(\$224,270.00)														
					24	May 2, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 30 on the current Payment Estimate.													
				24	May 2, 2022	SYSTEM	(\$224,270.00)															
					25	May 16, 2022	SYSTEM	\$224,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 30 on the current Payment Estimate.													
					25	May 16, 2022	SYSTEM	(\$224,270.00)														
				- Total				\$0.00														
	10.00		Material - To	tal				\$0.00														
	1040 - 1050	TYPE D BARRIER	Material		21	Mar 16, 2022	SYSTEM	\$0.00 \$24,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
					21	Mar 16, 2022	SYSTEM	(\$24,150.00)														
					22	Apr 4, 2022	SYSTEM	\$24,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 27 on the current Payment Estimate.													
					22	Apr 4, 2022	SYSTEM	(\$24,150.00)														
						:												23	Apr 18, 2022	SYSTEM	\$25,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
								24	May 2, 2022	SYSTEM	\$25,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 36 on the current Payment Estimate.										
					24	May 2, 2022	SYSTEM	(\$25,530.00)														
				;		25	May 16, 2022	SYSTEM	\$25,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 36 on the current Payment Estimate.												
				25	May 16, 2022	SYSTEM	(\$25,530.00)															
				- Total				\$0.00														
			Material - To	tal				\$0.00														



STEL (POX) COATED STEL (POX) COATED Stel (POX) (POATED)	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
Image: State in the image intervent (State in the state intervent (State intervent (S	J4P3015	1050 -	Total						\$0.00			
		1060	STEEL (EPOXY	Material		11		SYSTEM	\$3,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
Image: Control						11		SYSTEM	(\$3,330.00)			
Image: constraint of the second of the s						12		SYSTEM	\$3,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
100 Total 2021 2021 2021 Estimate Exception 12 on the current Payment Estimate. 13 Nov 16, 2021 SYSTEM (\$3,300.0) 2000 This adjustment (0007) due to use hesses2 overridding) 14 Dec 2, 2021 SYSTEM \$86,789.70] This adjustment offsets the original system-generated Material Payment Estimate. • 5000 • 10000						12		SYSTEM	(\$3,330.00)			
1000 10000 1000 1000						13	Nov 16,	SYSTEM	\$3,330.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
Image: state in the s						13		SYSTEM	(\$3,330.00)			
Image: Note of the image: No						14	Dec 2,	SYSTEM	\$65,789.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
Image: Indition in the inditinter indite in the indither indition in the indition in the inditi						14		SYSTEM	(\$65,789.70)			
Material - Total S0.00 1060 - Total 50.00 1080 VERTICAL DRAIN AT END BENTS Material 20 Mar.2 SYSTEM \$3.200.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 13 on the current Payment Estimate. 20 Mar.2 SYSTEM \$3.200.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 13 on the current Payment Estimate. 20 Mar.2 SYSTEM \$3.200.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 18 on the current Payment Estimate. 21 Mar.16 SYSTEM \$3.200.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 18 on the current Payment Estimate. 21 Mar.16 SYSTEM \$3.200.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 33 on the current Payment Estimate. 22 Apr.4 SYSTEM \$3.200.00 Estimate Exception 33 on the current Payment Estimate. 1000 - Total - Total 50.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 33 on the current Payment Estimate. 1110 BRIDER Material 1 Mar.16 SYSTEM \$38.250.00 Estimate Exception 4 on the current					- Total				<u>\$0.00</u>			
1080 VERTICAL DRAIN AT END BENTS Material AT END BENTS Paterial AT END BENTS Paterial A				Material - To	tal							
AT END BENTS AT END BENTS 		1060 -	Total						\$0.00			
1100 -total 2022 2024 2022 2024 2022 2024 2024 2022 2024 <		1080		Material		20		SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.		
1080 - Total 2022 2020 2022 2020 2022 2020 2022 2020 2022 2020 2022 2020 2020 2020 2020 2020 2020 2020 2020 2020 2020 2022 2020 2022 2020 2022 2020 2022 2020 2022 2020 2022 2022 2022 2022<						20		SYSTEM	(\$3,200.00)			
$ \begin{array}{ c c c c c } \hline \\ \hline $						21		SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.		
Image: Problem in the state						21		SYSTEM	(\$3,200.00)			
$ \begin{array}{ c c c c c } \hline & & & & & & & & & & & & & & & & & & $						22		SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 33 on the current Payment Estimate.		
Material - Total \$0.00 1080 - Total 1080 - Total \$0.00 1110 BRIDGE APPROACH SLAB (MAJOR ROAD) Material APPROACH SLAB (MAJOR ROAD) Material APPROACH (S38,250.00) This adjustment offsets the original system-generated Material Paper (S10000) Material APPROACH SLAB (S38,250.00) This adjustment offsets the original system-generated Material Paper (S10000) Material (S38,250.00) This adjustment offsets the original system-generated Material Paper (S10000) Material (S38,250.00) Material (S38,250.00) Material (S38,250.00) <td< td=""><td></td><td></td><td></td><td></td><td>22</td><td></td><td>SYSTEM</td><td>(\$3,200.00)</td><td></td></td<>						22		SYSTEM	(\$3,200.00)			
1080 - Total 1080 - Total 1110 BRIDGE APPROACH SLAB (MAJOR ROAD) Material 21 Mar 16, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 21 Mar 16, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 21 Mar 16, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 22 Apr 4, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate.					- Total				\$0.00			
1110 BRIDGE APPROACH SLAB (MAJOR ROAD) Material 21 Mar 16, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 21 Mar 16, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 21 Mar 16, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 22 Apr 4, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 22 Apr 4, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 22 Apr 4, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate.				Material - To	tal				\$0.00			
APPROACH SLAB (MAJOR ROAD) 2022 2022 Estimate Exception 4 on the current Payment Estimate. 21 Mar 16, 2022 SYSTEM (\$38,250.00) 22 22 Apr 4, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 22 Apr 4, 2022 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Pay Estimate Exception 4 on the current Payment Estimate. 22 Apr 4, 2022 SYSTEM \$38,250.00 Estimate Exception 4 on the current Payment Estimate.		1080 -	· Total						\$0.00			
20222022202220232024SYSTEM\$38,250.00This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0008) due to user hessec2 overridding Estimate Exception 4 on the current Payment Estimate.22Apr 4, 2022SYSTEM\$38,250.00(\$38,250.00)		1110	APPROACH SLAB	Material		21		SYSTEM	\$38,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
2022 2022 Estimate Item Adjustment (0008) due to user hessec2 overridding I Estimate Exception 4 on the current Payment Estimate. 22 Apr 4, 2022 SYSTEM (\$38,250.00)						21		SYSTEM	(\$38,250.00)			
2022						22		SYSTEM	\$38,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
						22		SYSTEM	(\$38,250.00)			
								23	Apr 18, 2022	SYSTEM	\$41,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
23 Apr 18, 2022 (\$41,310.00)						23		SYSTEM	(\$41,310.00)			
						24		SYSTEM	\$41,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
24 May 2, 2022 SYSTEM (\$41,310.00)						24		SYSTEM	(\$41,310.00)			
						25		SYSTEM	\$41,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
25 May 16, SYSTEM (\$41,310.00) 2022						25		SYSTEM	(\$41,310.00)			



Article Test Part Part Part Part Part Part Part Part	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																						
APPRICACE ADD Total 10.00 110 Total 0.00 This injustment official the organic lightim-global dataral Phyment 1130 CLASS 81. CURSTRY Manual 14 Doc 2. 0.00 SYSTEM 55.000 This injustment official the organic lightim-global dataral Phyment 1130 CLASS 81. CURSTRY Manual 14 Doc 2. 0.000 SYSTEM 55.000.00 This adjustment official the organic lightim-global dataral Phyment Editioned Encode on the owner Phyment Hallow 1130 CLASS 82. CURSTRY Nameat 16 Doc 2. 0.0000 SYSTEM 55.000.00 This adjustment official the organic lightim-global dataral Phyment Editioned Encode on the owner Phyment Hallow 1131 CLASS 82. 0.0000 Total distance Encode on the owner Physical Hallow Physical Hallow 1132 CLASS 82. 0.00000 Total distance Encode on the owner Physical Hallow Physical Hallow 1132 CLASS 82. 0.000000 Total distance Encode on the owner Physical Hallow Physical Hallow 1132 CLASS 82. 0.000000 Total distance Encode on the owner Physical Hallow Physical Hallow 1132 CLASS 82. 0.000000 Total distance Encodenot the organic lighthes	.I4P3015	1110	BRIDGE	Material					\$0.00																							
1137 Could be in a counter of space of participation of data is the region of participation of data is the second operating data is the second operati	041 0010	1110	APPROACH SLAB																													
110 CASS 51 CONCEPT Material SUBSTRY 14 Dec.2. 5757E4 455.20.00 The diplateent context Fayment Exclusion. 110 Dec.2. 5757E4 655.20.00 The diplateent context Fayment Exclusion. 111 Dec.2. 5757E4 655.20.00 The diplateent context Fayment Exclusion. 111 Dec.2. 5757E4 655.20.00 The diplateent context Fayment Exclusion. 112 Dec.2. 5757E4 655.20.00 The diplateent context Fayment Exclusion. 113 Dec.3. 5757E4 655.20.00 The diplateent context Fayment Exclusion. 114 Dec.3. 5757E4 655.20.00 The diplateent context Fayment Exclusion. 114 Dec.3. 5757E4 655.20.00 The diplateent context Fayment Exclusion. 116 Jan.2 5757E4 655.20.00 The diplateent context Fayment Exclusion. 116 Jan.2 5757E4 655.20.00 The diplateent context Fayment Exclusion. 117 Jan.2 5757E4 655.20.00 The diplateent context Fayment Exclusion. 118 Pee.		1110 -	, , , , , , , , , , , , , , , , , , ,																													
1 Provide the set of the set			CLASS B-1 CONCRETE	Material		14		SYSTEM		Estimate Item Adjustment (0006) due to user hessec2 overridding Payment																						
Image: Normal Part Part Part Part Part Part Part Part						14		SYSTEM	(\$55,200.00)																							
Image: Normal interval in the image: Normal interval interva						15		SYSTEM	\$55,200.00	Estimate Item Adjustment (0005) due to user hessec2 overridding Payment																						
110 2022 2022 2022 Edimate fram. Adjustment (0005) due to user bessed. A vertilisting Payment. 12 Jan. 16 3VSTEM 655.20.00 This adjustment (0005) due to user bessed. Overtilisting Payment. 17 Jan. 16 SVSTEM 655.20.00 This adjustment (0005) due to user bessed. Overtilisting Payment. 17 Jan. 16 SVSTEM 655.20.00 This adjustment (0005) due to user bessed. Overtilisting Payment. 17 Jan. 18 SVSTEM 655.20.00 This adjustment offsets the original aystem-generated Material Payment. 17 Jan. 18 SVSTEM 655.20.00 This adjustment offsets the original aystem-generated Material Payment. 18 F.1 SVSTEM 655.20.00 This adjustment offsets the original aystem-generated Material Payment. 19 F.201 SVSTEM 655.20.00 This adjustment offsets the original aystem-generated Material Payment. 19 F.201 SVSTEM 655.20.00 This adjustment offsets the original aystem-generated Material Payment. 10 Kan. 2 SVSTEM 655.20.00 This adjustment offsets the original aystem-generated Material Payment. 10						15		SYSTEM	(\$55,200.00)																							
Image: Normal information of the image: Normal informat information of the image: Normal information of the i						16	Jan 3,	SYSTEM	\$55,200.00	Estimate Item Adjustment (0005) due to user hessec2 overridding Payment																						
Image: Normal information of the second se						16		SYSTEM	(\$55,200.00)																							
100 100 <td></td> <td></td> <td rowspan="7"></td> <td></td> <td></td> <td>17</td> <td></td> <td>SYSTEM</td> <td>\$55,200.00</td> <td>Estimate Item Adjustment (0005) due to user hessec2 overridding Payment</td>						17		SYSTEM	\$55,200.00	Estimate Item Adjustment (0005) due to user hessec2 overridding Payment																						
Image: Normal State Image: State Image: State						17		SYSTEM	(\$55,200.00)																							
Image: state in the state in thest. The state is the state in the state in the state i						18		SYSTEM	\$55,200.00	Estimate Item Adjustment (0004) due to user hessec2 overridding Payment																						
160 CLASS B-2 (SUPSTE) Asterial - Total 14 202.2 VSTEM \$195,840.00 1160 CLASS B-2 (SUPSTE) Naterial - Total 14 202.2 \$VSTEM \$195,840.00 1160 CLASS B-2 (SUPSTE) Naterial - Total \$VSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment OBS) due to user hessec2 overridding Payment 1160 - Total \$VSTEM \$85,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Item Adjustment (OBS) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate. 1160 CLASS B-2 (SUPSTE) 195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 1						18		SYSTEM	(\$55,200.00)																							
Image: constraint of the						19		SYSTEM	\$55,200.00	Estimate Item Adjustment (0004) due to user hessec2 overridding Payment																						
Image: base in the second se						19		SYSTEM	(\$55,200.00)																							
$\left \begin{array}{c c c c c } & \hline \begin{array}{c c c c c } & \hline \begin{array}{c c c c c } & 222 & 2 & 0 & h & h & h & h & h & h & h & h & h$						20		SYSTEM	\$55,200.00	Estimate Item Adjustment (0005) due to user hessec2 overridding Payment																						
Image: Figure 1 Image: Figure 1 Image: Figure 1 Estimate tem Adjustment (0008) due to user hessec2 overridding Payment Estimate. Image: 1 Image:						20		SYSTEM	(\$55,200.00)																							
Image: Constraint of the second sec						21		SYSTEM	\$55,200.00	Estimate Item Adjustment (0008) due to user hessec2 overridding Payment																						
Image: Note of the second se						21		SYSTEM	(\$55,200.00)																							
1150 - Total 50.00 1160 CLASS B-2 CONCRETE (SUPSTR Material CONCRETE (SUPSTR Material 14 Dec 2, 2021 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 14 Dec 2, 2021 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 15 Dec 16, 2021 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. 15 Dec 16, 2021 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. 16 Jan 3, 2022 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 17 Jan 18, 2022 SYSTEM \$217,728.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate.					- Total				\$0.00																							
1160 CLASS B-2 CONCRETE (SUPSTR Material 14 Dec 2, 2021 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 14 Dec 2, 2021 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 14 Dec 10, 2021 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate. 15 Dec 16, 2021 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. 16 Jan 3, 2022 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 16 Jan 3, 2022 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 17 Jan 18, 2022 SYSTEM \$217,728.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 17				Material - Tot	tal				\$0.00																							
CONCRETE (SUPSTR 2021 2021 Estimate Estimate <td< td=""><td></td><td>1150 -</td><td>Total</td><td></td><td></td><td></td><td></td><td></td><td>\$0.00</td><td></td></td<>		1150 -	Total						\$0.00																							
15Dec 16, 2021SYSTEM\$195,840.00This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.15Dec 16, 2021SYSTEM(\$195,840.00)16Jan 3, 2022SYSTEM\$195,840.0016Jan 3, 2022SYSTEM\$195,840.0016Jan 3, 2022SYSTEM(\$195,840.00)17Jan 18, 2022SYSTEM\$217,728.0017Jan 18, SYSTEMSYSTEM\$217,728.00		1160	CONCRETE	Material		14		SYSTEM	\$195,840.00	Estimate Item Adjustment (0007) due to user hessec2 overridding Payment																						
20212021Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.15Dec 16, 2021SYSTEM(\$195,840.00)16Jan 3, 2022SYSTEM\$195,840.0016Jan 3, 2022SYSTEM\$195,840.0016Jan 3, 2022SYSTEM(\$195,840.00)17Jan 18, 2022SYSTEM\$217,728.0017Jan 18, SYSTEMSYSTEM(\$217,728.00)						14		SYSTEM	(\$195,840.00)																							
16 Jan 3, 2022 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment 16 Jan 3, 2022 SYSTEM \$195,840.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 16 Jan 3, 2022 SYSTEM \$195,840.00 17 Jan 18, 2022 SYSTEM \$217,728.00 This adjustment offsets the original system-generated Material Payment Estimate. 17 Jan 18, SYSTEM \$217,728.00 This adjustment offsets the original system-generated Material Payment Estimate.																												15		SYSTEM	\$195,840.00	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment
2022 2022 Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate. 16 Jan 3, 2022 SYSTEM (\$195,840.00) 17 Jan 18, 2022 SYSTEM \$217,728.00 17 Jan 18, SYSTEM (\$217,728.00)						15		SYSTEM	(\$195,840.00)																							
2022 2022 2022 17 Jan 18, 2022 SYSTEM 2202 17 Jan 18, SYSTEM 2022 \$217,728.00 17 Jan 18, SYSTEM (\$217,728.00) This adjustment offsets the original system-generated Material Payment Estimate Ltem Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.						16		SYSTEM	\$195,840.00	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment																						
2022 Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 16 on the current Payment Estimate. 17 Jan 18, SYSTEM (\$217,728.00)						16		SYSTEM	(\$195,840.00)																							
						17		SYSTEM	\$217,728.00	Estimate Item Adjustment (0006) due to user hessec2 overridding Payment																						
										17		SYSTEM	(\$217,728.00)																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	1160	CLASS B-2 CONCRETE (SUPSTR	Material		18	Feb 1, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$217,728.00)	
					19	Feb 16, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					19	Feb 16, 2022	SYSTEM	(\$217,728.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1160 -	Total						\$0.00	
	1170	TYPE D BARRIER	Material		22	Apr 4, 2022	SYSTEM	\$21,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$21,450.00)	
					23	Apr 18, 2022	SYSTEM	\$23,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					23	Apr 18, 2022	SYSTEM	(\$23,790.00)	
					24	May 2, 2022	SYSTEM	\$23,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$23,790.00)	
					25	May 16, 2022	SYSTEM	\$23,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$23,790.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1170 -	Total						\$0.00	
	1180	REINFORCING STEEL (EPOXY COATED)	Material		11	Oct 18, 2021	SYSTEM	\$3,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$3,510.00)	
					12	Nov 2, 2021	SYSTEM	\$3,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$3,510.00)	
					13	Nov 16, 2021	SYSTEM	\$3,510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Nov 16, 2021	SYSTEM	(\$3,510.00)	
					14	Dec 2, 2021	SYSTEM	\$45,840.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					14	Dec 2, 2021	SYSTEM	(\$45,840.60)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1180 -	Total						\$0.00	
	1200	VERTICAL DRAIN AT END BENTS	Material		21	Mar 16, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$3,200.00)	
					22	Apr 4, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment



May 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015	1200	VERTICAL DRAIN AT END BENTS	Material						Estimate Exception 34 on the current Payment Estimate.
		AT END BENTS			22	Apr 4, 2022	SYSTEM	(\$3,200.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1200 -							\$0.00	
	1230	BRIDGE APPROACH SLAB (MAJOR ROAD)	Construction Stockpile STMI		13	Nov 16, 2021	SYSTEM	\$7,222.60	Payment Estimate Item Adjustment generated Stockpile Transaction
			0	- Total				\$7,222.60	
	1230 -	Total	Construction	Stockpile S	imi - Total			\$7,222.60 \$7,222.60	
	1290	TYPE D BARRIER	Construction		13	Nov 16,	SYSTEM	\$7,680.75	Payment Estimate Item Adjustment generated Stockpile Transaction
	1290	ITPE D BARRIER	Stockpile	Total	13	2021	STOTEM		Payment Estimate tem Adjustment generated Stockpile transaction
			0	- Total				\$7,680.75	
	1290 -	Total	Construction	Stockpile S	imi - Tota			\$7,680.75	
	1290 -	SLAB ON	Construction		13	Nov 16,	SYSTEM	\$7,680.75 \$45,374,45	Payment Estimate Item Adjustment generated Steelaile Transaction
	1300	CONCRETE NU- GIRDER	Stockpile STMI		13	NOV 16, 2021	STOTEM	\$45,374.45	Payment Estimate Item Adjustment generated Stockpile Transaction
			0	- Total	-			\$45,374.45	
	1000	T .4.1	Construction	Stockpile S	MI - Total			\$45,374.45	
	1300 -		Ormation		40	No. 0	OVOTEM	\$45,374.45	Descent Factor to these Advects and a second of Oto desite its Terror and
	1310	NU 35, PRESTRESSED CONC NU-GIRDER	Construction Stockpile STMA		12	Nov 2, 2021	SYSTEM	\$271,891.54	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$271,891.54	
	1010		Construction	Stockpile S	MA - Tota	al		\$271,891.54	
	1310 -		Construction		40	New 16	OVOTEM	\$271,891.54	Devenue Federate Item Adjustment concented Stealwile Transaction
	1320	REINFORCING STEEL (BRIDGES)	Construction Stockpile STMI		13	Nov 16, 2021	SYSTEM	\$21,655.25	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total				\$21,655.25	
	1320 -	Total	Construction	Stockpile S	imi - Total			\$21,655.25 \$21,655.25	
J4P3015 - '								\$433,615.35	
	1390	CONCRETE APPROACH PAVEMENT	Material		22	Apr 4, 2022	SYSTEM	\$16,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$16,500.00)	
					23	Apr 18, 2022	SYSTEM	\$16,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					23	Apr 18, 2022	SYSTEM	(\$16,500.00)	
					24	May 2, 2022	SYSTEM	\$16,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$16,500.00)	
					25	May 16, 2022	SYSTEM	\$16,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hessec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$16,500.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1390 -	Total						\$0.00	
	1400	FURNISHING TYPE 2 ROCK BLANKET	Material		16	Jan 3, 2022	SYSTEM	\$14,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		DEANNET			16	Jan 3,	SYSTEM	(\$14,700.00)	
						2022			



May 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
4P3015B	1400	FURNISHING TYPE 2 ROCK BLANKET	Material		17	Jan 18, 2022	SYSTEM	\$14,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					17	Jan 18, 2022	SYSTEM	(\$14,700.00)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	1400 -	Total						\$0.00		
	1430	PERMANENT EROSION CONTROL GEOTEXTILE	Material		16	Jan 3, 2022	SYSTEM	\$958.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
		GEOTEXTILE			16	Jan 3, 2022	SYSTEM	(\$958.50)		
					17	Jan 18, 2022	SYSTEM	\$958.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hessec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					17	Jan 18, 2022	SYSTEM	(\$958.50)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	1430 -	Total						\$0.00		
	1460	MGS GUARDRAIL	Construction Stockpile STMI		1	May 3, 2021	SYSTEM	\$1,713.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			O TIVI	- Total				\$1,713.00		
			Construction	Stockpile S	MI - Tota			\$1,713.00		
	1460 -	Total						\$1,713.00		
	1470 MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		1	May 3, 2021	SYSTEM	\$3,212.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
		(REG/NO CORB)	STIVI	- Total				\$3,212.00		
			Construction	Stockpile S	MI - Tota			\$3,212.00		
	1470 -	Total						\$3,212.00		
	1480		Construction Stockpile STMI		1	May 3, 2021	SYSTEM	\$3,152.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
		(MASH)	5111	- Total				\$3,152.00		
			Construction	Stockpile ST	MI - Tota			\$3,152.00		
	1480 -	Total						\$3,152.00		
	1510	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		23	Apr 18, 2022	SYSTEM	\$43,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					23	Apr 18, 2022	SYSTEM	(\$43,860.00)		
						24	May 2, 2022	SYSTEM	\$43,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$43,860.00)		
					25	May 16, 2022	SYSTEM	\$43,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					25	May 16, 2022	SYSTEM	(\$43,860.00)	Estimate Exception 12 on the current raymont Estimate.	
				- Total				\$0.00		
			Material - Tot					\$0.00		
	1510 -	Total						\$0.00		
	1550	CLASS B-1 CONCRETE (SUBSTR)	Material		15	Dec 16, 2021	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
		(15	Dec 16, 2021	SYSTEM	(\$55,200.00)	. ,	
					16	Jan 3, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015B	1550	CLASS B-1 CONCRETE	Material		16	Jan 3, 2022	SYSTEM	(\$55,200.00)	
		(SUBSTR)			17	Jan 18, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$55,200.00)	
					18	Feb 1, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$55,200.00)	
					19	Feb 16, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					19	Feb 16, 2022	SYSTEM	(\$55,200.00)	
					20	Mar 2, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hessec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$55,200.00)	
					21	Mar 16, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$55,200.00)	
					22	Apr 4, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$55,200.00)	
					23	Apr 18, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					23	Apr 18, 2022	SYSTEM	(\$55,200.00)	
					24	May 2, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hessec2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$55,200.00)	
					25	May 16, 2022	SYSTEM	\$55,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$55,200.00)	
				- Total				\$0.00	
	1550	· Total	Material - Tot					\$0.00 \$0.00	
	1560	CLASS B-2 CONCRETE (SUPSTR	Material		16	Jan 3, 2022	SYSTEM	\$206,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		(16	Jan 3, 2022	SYSTEM	(\$206,880.00)	· ·
					17	Jan 18, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hessec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$217,728.00)	
					18	Feb 1, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$217,728.00)	
					19	Feb 16, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015B	1560	CLASS B-2 CONCRETE	Material		19	Feb 16, 2022	SYSTEM	(\$217,728.00)	
		(SUPSTR			20	Mar 2, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hessec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$217,728.00)	
					21	Mar 16, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hessec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$217,728.00)	
					22	Apr 4, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$217,728.00)	
					23	Apr 18, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hessec2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					23	Apr 18, 2022	SYSTEM	(\$217,728.00)	
					24	May 2, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hessec2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$217,728.00)	
					25	May 16, 2022	SYSTEM	\$217,728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hessec2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$217,728.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1560 -							\$0.00	
	1570	TYPE D BARRIER	Material		22	Apr 4, 2022	SYSTEM	\$21,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hessec2 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$21,450.00)	
					23	Apr 18, 2022	SYSTEM	\$23,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hessec2 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					23	Apr 18, 2022	SYSTEM	(\$23,790.00)	
					24	May 2, 2022	SYSTEM	\$23,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hessec2 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					24	May 2, 2022	SYSTEM	(\$23,790.00)	
					25	May 16, 2022	SYSTEM	\$23,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hessec2 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					25	May 16, 2022	SYSTEM	(\$23,790.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1570 -						0.427	\$0.00	
	1600	VERTICAL DRAIN AT END BENTS	Material		21	Mar 16, 2022	SYSTEM	\$3,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hessec2 overridding Payment
		AT END DENTS							Estimate Exception 20 on the current Payment Estimate.
		AT LIND BEINTS			21	Mar 16, 2022	SYSTEM	(\$3,200.00)	Estimate Exception 20 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3015B	1600	VERTICAL DRAIN AT END BENTS	Material		22	Apr 4, 2022	SYSTEM	(\$3,200.00)	
				- Total					
			Material - Tot	tal				\$0.00	
	1600 -	Total					\$0.00		
J4P3015B	- Total						\$8,077.00		
Overall - Total									