

Pay Estimate Created Date: June 30, 2022

17	ess Estima Numi	Prim	tract ID ne tractor	201218-C0 Radmache Co.,Inc.	5 r Brothers Ex	cavating	Pay Period Start Pay Period Enc	June 16, 2022 June 30, 2022	Original Contrac Amount Net Change Ord Amount Current Contrac	\$1. er \$6	,350,898.84 4,015.10 ,414,913.94
Approval Date											By User
June 30, 2022				Genera	ted and App	roved (and	d should be considered	d Draft) at the	Project Office Lev	vel by	needhm1
June 30, 2022				Reviewed a	nd Approved	l (and sho	uld be considered Dra	ft) at the Res	ident Engineer Lev	vel by	penner1
July 5, 2022					Rev	iewed and	Approved at the Cen	tral Office Co	ntrollers Office Lev	vel by	ramses1
Original Cor	mpletion [Date	Current	Completion	Date	Actual	Completion Date	% of	Current Contract	Amount Cor	nplete
Novemb	er 1, 2021		Nove	ember 1, 202	1	Nov	ember 1, 2021		100.00)%	
	(Contract Ir	nformationa	I Dates			Milestone	s			
Date Descri	ption	Original C	ompletion I	Date Curre	nt Completi	on Date	No Milestones Exist	for Contract			
Acceptance Da	te .	luly 1, 202	2	July 1	2022						
Awarded Date		lanuary 6,	2021	Janua	ry 6, 2021						
Letting Date	[December	18, 2020	Decer	nber 18, 202	0					
Notice to Proce	ed Date	ebruary 8	, 2021	Febru	ary 8, 2021						
Work Began Da	ate .	lune 7, 202	21	June 7	, 2021						
201218-C05	Gr Inc		Items Pay djustments	\$0.0	69.83		Previous \$1,414,913.97 \$5,529.86		To Date \$1,414,913 \$7,099.69		
	Lic	sincentive juidated Da		\$0.0 \$0.0 \$0.0)		\$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00 \$0.00		
	Lic Ot	uidated Da her Contra	ct Adjustme	\$0.0 \$0.0 nts \$0.0)))		\$0.00 \$0.00		\$0.00	3.66	
	Lic Ot Payable T	uidated Da her Contra his Estima	ct Adjustme	\$0.0 \$0.0 nts \$0.0)		\$0.00 \$0.00 \$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00	3.66	
Contract Total I ems Paid This No Data Availa ontract Adjustr	Cit Cot Payable Ti Estimate F able nents This	uidated Da her Contra nis Estima Period s Estimate	ct Adjustme ite:	\$0.0 \$0.0 nts \$0.0)))		\$0.00 \$0.00 \$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00	3.66	
No Data Availa No Data Availa Ontract Adjustr	Lic Ot Payable TI Estimate F able nents This stments Ex	uidated Da her Contra nis Estima <u>Period</u> <u>s Estimate</u> ist on Con	ct Adjustme ite: 2 tract	\$0.0 \$0.0 nts \$0.0)))		\$0.00 \$0.00 \$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00	3.66	
ems Paid This I No Data Availa	Lic Ot Payable TI Estimate F able nents This stments Ex ments This	uidated Da her Contra nis Estima <u>Period</u> <u>s Estimate</u> ist on Con	ct Adjustme ite: tract e	\$0.0 \$0.0 nts \$0.0)) ;69.83		\$0.00 \$0.00 \$0.00 \$0.00 \$0.00		\$0.00 \$0.00 \$0.00	3.66 Line Item Adjustment Unit Price	Adjustmer amount
o Contract Adjust ontract Adjustr Contract Adjustr Contract Adjust Contract Adjust	Lic Ot Payable TI Estimate F able nents This stments Ex ments This	uidated Da her Contra his Estima <u>Period</u> s Estimate ist on Con s Estimate	ct Adjustme ite: tract e	\$0.0 \$0.0 \$1, \$ \$1, \$)) i69.83 Other Item Adjustmen	t	\$0.00 \$0.00 \$0.00 \$0.00 \$1,420,443.83		\$0.00 \$0.00 \$1,422,013 Adjustment Quantity	Line Item Adjustment	,



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3255	FAF 291-1(87)	Signal improvements	291	JACKSON	from 0.2 mile north of \$	Stuart Road to 0.1 mile sout	h of Persels Road in Lee's Summit
Totals by J	lob Numbei	rs					
J4P3255					This Estimate	Previous	To Date
	Postec	l Item Pay			\$0.00	\$1,414,913.97	\$1,414,913.97
	Gross	Item Adjustmer	nts		\$1,569.83	\$5,529.86	\$7,099.69
			Gross I	tem Pay	\$1,569.83	\$1,420,443.83	\$1,422,013.66
	Incent	ive			\$0.00	\$0.00	\$0.00
	Disinc	entive			\$0.00	\$0.00	\$0.00
	Liquid	ated Damages			\$0.00	\$0.00	\$0.00
		Contract Adjust	ments		\$0.00	\$0.00	\$0.00



Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-C05	J4P3255	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$57,372.45	\$57,372.45
		0001	0020	2031000	CLASS A EXCAVATION	4,729.00	0.00	4,729.00	CUYD	4,729.00	\$11.10	\$52,491.90
		0001	0030	2035500	EMBANKMENT IN PLACE	478.00	0.00	478.00	CUYD	478.00	\$21.55	\$10,300.90
		0001	0040	2036000	COMPACTING EMBANKMENT	1,604.00	0.00	1,604.00	CUYD	1,604.00	\$1.20	\$1,924.80
		0001	0050	2063000	CLASS 3 EXCAVATION	136.00	0.00	136.00	CUYD	136.00	\$11.60	\$1,577.60
		0001	0060	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	6,260.00	0.00	6,260.00	SQYD	6,260.00	\$10.00	\$62,600.00
		0001	0070	4019905	MISC.OPTIONAL PAVEMENT	3,230.10	0.00	3,230.10	SQYD	3,230.10	\$51.70	\$166,996.17
		0001	0080	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	339.40	121.90	461.30	TONS	461.30	\$115.50	\$53,280.15
		0001	0090	4071005	TACK COAT	283.00	28.00	311.00	GAL	311.00	\$2.25	\$699.75
		0001	0100	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	2,957.00	0.00	2,957.00	SQYD	2,957.00	\$57.20	\$169,140.40
		0001	0110	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	1.00	\$1,670.75	\$1,670.75
		0001	0120	6044012	PIPE COLLAR, TYPE B	5.00	0.00	5.00	EA	5.00	\$1,276.30	\$6,381.50
		0001	0130	6083006	6 IN. CONCRETE MEDIAN STRIP	159.90	0.00	159.90	SQYD	159.90	\$81.50	\$13,031.85
		0001	0140	6085008	PAVED APPROACH, 8 IN.	40.80	0.00	40.80	SQYD	40.80	\$111.20	\$4,536.96
		0001	0150	6091052	CURB AND GUTTER TYPE B	147.00	0.00	147.00	LF	147.00	\$32.40	\$4,762.80
		0001	0160	6091060	PAVED DITCH	29.90	0.00	29.90	SQYD	29.90	\$88.15	\$2,635.68
		0001	0170	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	63.00	0.00	63.00	LF	63.00	\$51.15	\$3,222.45
		0001	0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	-4.00	0.00	EA	0.00	\$0.00	\$0.00
		0001	0190	6161005	CONSTRUCTION SIGNS	1,875.00	-337.00	1,538.00	SQFT	1,538.00	\$7.90	\$12,150.20
		0001	0200	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	-4.00	4.00	EA	4.00	\$89.25	\$357.00
		0001	0210	6161009	FLAG ASSEMBLY	4.00	-4.00	0.00	EA	0.00	\$26.25	\$0.00
		0001	0220	6161010	RELOCATED SIGNS	297.00	0.00	297.00	SQFT	297.00	\$7.90	\$2,346.30
		0001	0230	6161025	CHANNELIZER (TRIM LINE)	96.00	40.00	136.00	EA	136.00	\$21.00	\$2,856.00
		0001	0240	6161030	TYPE III MOVEABLE BARRICADE	8.00	0.00	8.00	EA	8.00	\$194.25	\$1,554.00
		0001	0250	6161040	FLASHING ARROW PANEL	4.00	-3.00	1.00	EA	1.00	\$1,155.00	\$1,155.00
		0001	0260	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,725.00	\$18,900.00
		0001	0270	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	163.00	137.00	300.00	LF	300.00	\$24.50	\$7,350.00
		0001	0280	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$185,261.00	\$185,261.00
		0001	0290	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	493.00	-329.00	164.00	LF	164.00	\$3.15	\$516.60
		0001	0300	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	583.00	420.00	1,003.00	LF	1,003.00	\$14.70	\$14,744.10
		0001	0310	6200018	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	964.00	-868.00	96.00	LF	96.00	\$10.50	\$1,008.00
		0001	0320	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING,	19.00	4.00	23.00	EA	23.00	\$220.50	\$5,071.50
		0001	0330	6205301B	LEFT/RIGHT ARROW TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,697.00	-4,936.00	761.00	LF	761.00	\$0.85	\$646.85
		0001	0340	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	4,375.00	-2,790.00	1,585.00	LF	1,585.00	\$0.85	\$1,347.25
		0001	0350	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	2,557.00	-703.00	1,854.00	LF	1,854.00	\$0.15	\$278.10
		0001	0360	6205902A	MARKING PAINT, TYPE L BEADS 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	5,800.00	-1,918.00	3,882.00	LF	3,882.00	\$0.35	\$1,358.70
		0001	0370	6205906A	PAINT, TYPE L BEADS 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	3,050.00	1,298.00	4,348.00	LF	4,348.00	\$0.55	\$2,391.40
		0001	0380	6206000C	MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	3,602.00	541.00	4,143.00	LF	4,143.00	\$0.15	\$621.45
		0001	0390	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	2,307.00	806.00	3,113.00	LF	3,113.00	\$0.15	\$466.95
		0001	0400	6207001	MARKING PAINT, TYPE P BEADS PAVEMENT MARKING REMOVAL	19,039.00	-14,801.00	4,238.00	LF	4,238.00	\$0.45	\$1,907.10
		0001	0410	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	205.00	629.00	834.00	SQYD	834.00	\$30.05	\$25,061.70
				6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$8,400.00	\$8,400.00
		0001	0420									



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q	uantities	and Value		ased on R	eport Generated date and can differ from the posted amo	unt at the	time the Es	stimate was	Generat	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-C05	J4P3255	0001	0440	7261021	21 IN. PIPE GROUP A	124.00	6.00	130.00	LF	130.00	\$67.60	\$8,788.00
		0001	0450	7261024	24 IN. PIPE GROUP A	15.00	0.00	15.00	LF	15.00	\$190.35	\$2,855.25
		0001	0460	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	7.00	0.00	7.00	EA	7.00	\$1,294.60	\$9,062.20
		0001	0470	7320621A	21 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,432.60	\$2,865.20
		0001	0480	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,432.60	\$1,432.60
		0001	0490	8051000A	SEEDING - COOL SEASON GRASSES	3.70	-0.68	3.02	ACRE	3.02	\$2,404.50	\$7,261.59
		0001	0500	8061003	SEDIMENT TRAP EXCAVATION	50.00	-50.00	0.00	CUYD	0.00	\$11.40	\$0.00
		0001	0510	8061004	SEDIMENT TRAP ROCK	7.00	-7.00	0.00	CUYD	0.00	\$210.95	\$0.00
		0001	0520	8061006	ALTERNATE DITCH CHECK	2,026.00	-2,026.00	0.00	LF	0.00	\$5.95	\$0.00
		0001	0530	8061007A	CURB INLET CHECK	2.00	-1.00	1.00	EA	1.00	\$210.00	\$210.00
		0001	0540	8061016	SEDIMENT REMOVAL	198.00	0.00	198.00	CUYD	198.00	\$11.40	\$2,257.20
		0001	0550	8061019	SILT FENCE	1,353.00	-1,353.00	0.00	LF	0.00	\$1.90	\$0.00
		0020	0560	9011068	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 5	5.00	0.00	5.00	EA	5.00	\$2,172.80	\$10,864.00
		0020	0570	9011104	BRACKET ARM, 4 FT. OR 1.2 M	1.00	0.00	1.00	EA	1.00	\$301.00	\$301.00
		0020	0580	9011106	BRACKET ARM, 6 FT. OR 1.8 M	1.00	0.00	1.00	EA	1.00	\$345.25	\$345.25
		0020	0590	9011108	BRACKET ARM, 8 FT. OR 2.4 M	1.00	0.00	1.00	EA	1.00	\$345.25	\$345.25
		0020	0600	9011115	BRACKET ARM, 15 FT. OR 4.6 M	2.00	0.00	2.00	EA	2.00	\$773.40	\$1,546.80
		0020	0610	9011312	LUMINAIRE, LED-B	5.00	0.00	5.00	EA	5.00	\$601.75	\$3,008.75
		0020	0620	9017008	CABLE, 8 AWG 1 CONDUCTOR	3,500.00	0.00	3,500.00	LF	3,500.00	\$1.65	\$5,775.00
		0020	0630	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	550.00	0.00	550.00	LF	550.00	\$1.10	\$605.00
		0020	0640	9017208	WIRE, 8 AWG, BARE NEUTRAL	1,750.00	0.00	1,750.00	LF	1,750.00	\$1.45	\$2,537.50
		0020	0650	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	5.00	0.00	5.00	EA	5.00	\$1,417.60	\$7,088.00
		0020	0660	9018613	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING AND SIGNALS	1.00	0.00	1.00	EA	1.00	\$13,122.80	\$13,122.80
		0030	0670	9020833	SH-FLAT SHEET - SIGNAL SIGN	53.00	0.00	53.00	SQFT	53.00	\$54.60	\$2,893.80
		0030	0680	9020834	SIGNAL SIGN, MOUNTING HARDWARE	10.00	0.00	10.00	EA	10.00	\$250.30	\$2,503.00
		0030	0690	9021413	SIGNAL HEAD, OPTICALLY LIMITED, TYPE 3B	10.00	0.00	10.00	EA	10.00	\$1,397.35	\$13,973.50
		0030	0700	9021414	SIGNAL HEAD, OPTICALLY LIMITED, TYPE 4B	2.00	0.00	2.00	EA	2.00	\$1,666.05	\$3,332.10
		0030	0710	9023350	POST, TYPE B, LONGEST ARM 50 FT. OR 15.2 M	1.00	0.00	1.00	EA	1.00	\$18,447.75	\$18,447.75
		0030	0720	9023355	POST, TYPE B, LONGEST ARM 55 FT.	1.00	0.00	1.00	EA	1.00	\$20,776.30	\$20,776.30
		0030	0730	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00	\$21,167.85	\$21,167.85
		0030	0740	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	47.00	0.00	47.00	LF	47.00	\$17.30	\$813.10
		0030	0750	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	2,938.00	0.00	2,938.00	LF	2,938.00	\$17.45	\$51,268.10
		0030	0760	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	398.00	0.00	398.00	LF	398.00	\$20.20	\$8,039.60
		0030	0770	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	638.00	0.00	638.00	LF	638.00	\$37.30	\$23,797.40
		0030	0780	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	80.00	0.00	80.00	LF	80.00	\$1.65	\$132.00
		0030	0790	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,630.00	0.00	2,630.00	LF	2,630.00	\$1.90	\$4,997.00
		0030	0800	9028350	FIBER OPTIC CABLE, 6 - FIBER, SINGLE MODE	3,180.00	0.00	3,180.00	LF	3,180.00	\$2.05	\$6,519.00
		0030	0810	9028810	PULL BOX, PREFORMED CLASS 1	3.00	0.00	3.00	EA	3.00	\$1,396.05	\$4,188.15
		0030	0820	9028811	PULL BOX, PREFORMED CLASS 2	9.00	0.00	9.00	EA	9.00	\$1,826.10	\$16,434.90
		0030	0830	9028812	PULL BOX, PREFORMED CLASS 3	2.00	0.00	2.00	EA	2.00	\$2,436.85	\$4,873.70
		0030	0840	9028816	PULL BOX, PREFORMED CLASS 5	2.00	0.00	2.00	EA	2.00	\$2,335.10	\$4,670.20
		0030	0850	9029100		9.30	0.00	9.30	CUYD	9.30	\$2,173.05	\$20,209.36
		0030	0860	9029901	MISC.FIBER OPTIC SPLICING, TESTING AND DOCUMENTATION	1.00	0.00	1.00	LS	1.00	\$11,755.05	\$11,755.05
		0030	0870	9029902	MISC.EMERGENCY VEHICLE DETECTION SYSTEM	4.00	0.00	4.00	EA	4.00	\$3,383.30	\$13,533.20
		0040	0875	9031010	CONCRETE FOOTINGS, EMBEDDED	3.60	0.00	3.60	CUYD	3.60	\$1,575.00	\$5,670.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-C05	J4P3255	0040	0880	9031220	PIPE POSTS	2,280.00	0.00	2,280.00	LB	2,280.00	\$5.25	\$11,970.00
		0040	0890	9031270A	2 IN. PSST POST - 12 GA.	213.00	0.00	213.00	LF	213.00	\$15.75	\$3,354.75
		0040	0900	9031279	OMNIDIRECTIONAL POST ANCHOR FOR 2 IN. PSST - 7 GA.	51.00	0.00	51.00	LF	51.00	\$68.25	\$3,480.75
		0040	0910	9035004A	SH-FLAT SHEET	158.00	9.00	167.00	SQFT	167.00	\$26.25	\$4,383.75
		0040	0920	9035069A	SHF-FLAT SHEET FLUORESCENT	72.00	0.00	72.00	SQFT	72.00	\$36.75	\$2,646.00
		0040	0930	9039901	MISC.SOLAR POWERED FLASHER	1.00	0.00	1.00	LS	1.00	\$12,589.50	\$12,589.50
		0050	0940	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	1.00	0.00	1.00	EA	1.00	\$4,839.40	\$4,839.40
		0050	0950	9109902	MISC.KC District Video Detection System	1.00	0.00	1.00	EA	1.00	\$40,259.20	\$40,259.20
		0001	5001	6139902	MISC.PARTIAL PAVEMENT REPAIR OF RUMBLE STRIPS	0.00	40.00	40.00	EA	40.00	\$557.98	\$22,319.20
		0001	5002	8069903	MISC.SILK SOCK	0.00	1,342.00	1,342.00	LF	1,342.00	\$1.90	\$2,549.80
		0001	5003	6122009	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	0.00	2.00	2.00	EA	2.00	\$2,940.00	\$5,880.00
		0001	5004	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	0.00	192.00	192.00	LF	192.00	\$23.56	\$4,523.52
		0001	5005	4029901	MISC.0.5" SURFACE LEVELING LIFT	0.00	1.00	1.00	LS	1.00	\$6,825.00	\$6,825.00
		0001	5006	8064133	TYPE 1C EROSION CONTROL BLANKET	0.00	14,618.00	14,618.00	SQYD	14,618.00	\$1.55	\$22,657.90
		0001	5007	6189901	MISC ADDITIONAL MOBILIZATION FOR STRIPING	0.00	1.00	1.00	LS	1.00	\$1,785.00	\$1,785.00
		0001	5008	6189901	MISC ADDITIONAL MOBILIZATION FOR SIGN INSTALATION	0.00	1.00	1.00	LS	1.00	\$682.50	\$682.50
	Project J	4P3255 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,414,913.94
201218-C05 Ove	erall - Total	Value Pos	ted to Dat	te as of Repo	ort Generated Date							\$1,414,913.94



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Tota SF to Post
IP3255	0190	June 9,	488	CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		MO 291 N 15.353	LT	1.00	12			
		2021		CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		MO 291 N 15.353	RT	1.00	12			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		SW Scherer Rd W 0.08	RT	1.00	16			
				GO20-2 48x24 8.00 END ROAD WORK		SW Persels Rd. W 0.061	RT	1.00	8			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		SW Persels Rd E 1.072	RT	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		MO 291 N 15.464	LT	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		MO 291 N 15.464	RT	1.00	16			
				WO21-5b 48x48 16.00 SHOULDER WORK AHEAD		MO 291 N 15.531	LT	1.00	16			
				WO21-5b 48x48 16.00 SHOULDER WORK AHEAD		MO 291 N 15.531	RT	1.00	16			
				WO5-5 48x48 16.00 NARROW LANES		MO 291 N 15.636	LT	1.00	16			
				WO5-5 48x48 16.00 NARROW LANES		MO 291 N 15.636	RT	1.00	16			
				WO7-3a 30x24 5.00 NEXT XX MILES (PLAQUE)		MO 291 N 15.636	LT	1.00	5			
				R2-1 36x48 12.00 SPEED LIMIT XX		MO 291 N 15.762	LT	1.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		MO 291 N 15.762	RT	1.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		MO 291 N 15.762	LT	1.00	6			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		MO 291 N 15.762	RT	1.00	6			
				R2-1 36x48 12.00 SPEED LIMIT XX		MO 291 N 16.047	LT	1.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		MO 291 N 16.047	RT	1.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		MO 291 N 16.047	LT	1.00	6			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		MO 291 N 16.047	RT	1.00	6			
				GO20-2 48x24 8.00 END ROAD WORK		MO 291 N 16.703	LT	1.00	8			
				GO20-2 48x24 8.00 END ROAD WORK		MO 291 N 16.703	RT	1.00	8			
				WO7-3a 30x24 5.00 NEXT XX MILES (PLAQUE)		MO 291 N 5.636	RT	1.00	5			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		MO 291 S 32.531	LT	1.00	12			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		MO 291 S 32.531	RT	1.00	12			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		MO 291 S 32.616	Left	1.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		MO 291 S 32.616	RT	1.00	16			
				WO21-5b 48x48 16.00 SHOULDER WORK AHEAD		MO 291 S 32.679	LT	1.00	16			
				WO21-5b 48x48 16.00 SHOULDER WORK AHEAD		MO 291 S 32.679	RT	1.00	16			
				WO5-5 48x48 16.00 NARROW LANES		MO 291 S 32.78	LT	1.00	16			
				WO5-5 48x48 16.00 NARROW LANES		MO 291 S 32.78	RT	1.00	16			
				WO7-3a 30x24 5.00 NEXT XX		MO 291 S	LT	1.00	5			

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3255	0190	June	488	MILES (PLAQUE)		32.78			3			
		9, 2021		WO7-3a 30x24 5.00 NEXT XX MILES (PLAQUE)		MO 291 S 32.78	RT	1.00	5			
				R2-1 36x48 12.00 SPEED LIMIT XX		MO 291 S 32.875	LT	1.00	12			
				R2-1 36x48 12.00 SPEED LIMIT XX		MO 291 S 32.875	RT	1.00	12			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		MO 291 S 32.875	LT	1.00	6			
				G020-5aP 36x24 6.00 WORK ZONE (PLAQUE)		MO 291 S 32.875	RT	1.00	6			
				GO20-2 48x24 8.00 END ROAD WORK		MO 291 S 33.564	LT	1.00	8			
				GO20-2 48x24 8.00 END ROAD WORK		MO 291 S 33.564	RT	1.00	8			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		SE Bailey Rd W 1.749	RT	1.00	16			
				GO20-2 48x24 8.00 END ROAD WORK		SE Bailey Rd. W 1.749	RT	1.00	8			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		SE Thompson Dr W 1.281	RT	1.00	16			
				GO20-2 48x24 8.00 END ROAD WORK		SE Thompson Dr. E 0.104	RT	1.00	8			
		June 22, 2021	96	WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED			SB 291 S	1.00	16			
		2021		WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD			SB 291 S	2.00	16			
				WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)			SB 291 S	1.00	16			
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD			SB 291 S	2.00	16			
		July 30, 2021	244	R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		.019	R of Market NB	1.00	12.5			
				See Special Sign Details		.082	R of Persels WB	0.00		48x48 Scherer Detour (Left)	16.00	
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		.179	R of Market NB	1.00	16			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		.244	R of Thompson NB	1.00	16			
				MO4-8a 24x18 3.00 END DETOUR		.294	R of Scherer WB	0.00	3			
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		.324	R of Market SB	1.00	12.5			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		.411	R of Market SB	1.00	16			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		.471	R of Market SB	1.00	16			
				See Special Sign Details		.597	R of Jefferson NB	1.00		36x60 291 Detour (Right)	15.00	
				See Special Sign Details		.735	R of Jefferson SB	1.00		48x48 Scherer Detour (Right)	16.00	
				WO20-2 48x48 16.00 DETOUR AHEAD		1.222	R of Thompson WB	0.00	16		16.00	
				See Special Sign Details		1.292	R of Thompson	1.00		72x42 Scherer Road Closed	21.00	



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable)

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
P3255	0190	July	244				WB		_			
		30, 2021		See Special Sign Details		1.357	R of Thompson WB	1.00		48x48 Scherer Detour (Right)	16.00	1
				See Special Sign Details		16.159	L of 291 NB	0.00		48x48 Scherer Detour (Straight)	16.00	
				See Special Sign Details		16.159	R of 291 NB	0.00		48x48 Scherer Detour (Straight)	16.00	
				See Special Sign Details		16.413	L of 291 NB	0.00		48x48 Scherer Detour (Left)	16.00	
				See Special Sign Details		16.413	R of 291 NB	0.00		48x48 Scherer Detour (Left)	16.00	
				MO4-8a 24x18 3.00 END DETOUR		16.649	R of 291 NB	0.00	3			
				WO20-2 48x48 16.00 DETOUR AHEAD		3.600	R of Scherer EB	0.00	16			
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		3.681	R of Scherer EB	1.00	12.5			12.
				See Special Sign Details		3.733	R of Scherer EB	1.00		36x60 291 Detour (Left)	15.00	1
				See Special Sign Details		3.755	R of Scherer EB	1.00		36x60 291 Detour (Left)	15.00	1
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		3.811	R of Scherer EB	1.00	12.5			12.5
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		3.862	R of Scherer EB	1.00	16			1
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		3.908	R of Scherer EB	1.00	16			10
				MO4-8a 24x18 3.00 END DETOUR		32.877	R of 291 SB	0.00	3			
			710	See Special Sign Details		.0	R of Persels EB	1.00		36x78 291 N Detour (Left)	19.50	19.
				See Special Sign Details		4.00	R of Scherer EB	1.00		48x48 Thompson Detour (Left)	16.00	1
				See Special Sign Details		.09	R of Persels WB	1.00		48x48 Scherer Detour (Left)	16.00	16
				MO4-8a 24x18 3.00 END DETOUR		.09	R of Bailey EB	1.00	3			3
				See Special Sign Details		.13	R of 16th EB	1.00		48x48 Thompson Detour (Right)	16.00	1
				MO4-8a 24x18 3.00 END DETOUR		.14	R of 16th EB	1.00	3			:
				MO4-8a 24x18 3.00 END DETOUR		.15	R of Persels WB	1.00	3			
				MO4-8a 24x18 3.00 END DETOUR		.20	R of Thompson EB	1.00	3			:
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		.29	R of Market SB	0.00	16			
				See Special Sign Details		.30	R of Jefferson SB	1.00		48x48 Scherer Detour (Straight)	16.00	1
				See Special Sign Details		.57	R of Market NB	1.00		48x48 Thompson Detour (Right)	16.00	10
				See Special Sign Details		.58	R of Jefferson	1.00		36x78 291 N Detour (Right)	19.50	19.



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line	DWR	Total Quantity	ils for Construction Signs (if app Sign Information	Station	Log Mile	Location	Number	SF	Special Sign	SF Each	Total
	Number	Date	Posted For DWR Date	e.gonduon	Clauon	203 1110	Loouton	of Items	Each Sign	eposial orgit	Special Sign	SF to Post
J4P3255	0190	July	710				NB					
		30, 2021		MO4-8a 24x18 3.00 END DETOUR		.63	R of Market NB	1.00	3			3
				MO4-8a 24x18 3.00 END DETOUR		.80	R of Jefferson SB	1.00	3			3
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		1.18	R of Thompson WB	1.00	16			16
				WO20-2 48x48 16.00 DETOUR AHEAD		1.19	R of Thompson WB	1.00	16			16
				See Special Sign Details		1.32	R of Thompson WB	1.00		36x78 291 S Detour (Right)	19.50	19.5
				See Special Sign Details		1.35	R of Thompson WB	1.00		36x78 291 S Detour (Right)	19.50	19.5
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		15.32	R & L of 291 NB	2.00	16			32
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		15.455	R & L of 291 NB	0.00	16			0
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		15.47	R of 291 NB	1.00	16			16
				WO20-2 48x48 16.00 DETOUR AHEAD		15.795	R & L of 291 NB	2.00	16			32
				See Special Sign Details		15.87	L of 291 NB	1.00		48x48 Scherer Detour (Straight)	16.00	16
				See Special Sign Details		15.87	R of 291 NB	1.00		48x48 Scherer Detour (Straight)	16.00	16
				See Special Sign Details		15.87	L of 291 NB	1.00		36x78 291 S Detour (Straight)	19.50	19.5
				See Special Sign Details		15.87	R of 291 NB	1.00		36x78 291 S Detour (Straight)	19.50	19.5
				See Special Sign Details		16.16	L of 291 NB	1.00		48x48 Scherer Detour (Straight)	16.00	16
				See Special Sign Details		16.16	R of 291 NB	1.00		48x48 Scherer Detour (Straight)	16.00	16
				See Special Sign Details		16.16	L of 291 NB	1.00		36x78 291 S Detour (Straight)	19.50	19.5
				See Special Sign Details		16.16	R of 291 NB	1.00		36x78 291 S Detour (Straight)	19.50	19.5
				See Special Sign Details See Special Sign Details		16.34	L of 291 NB R of 291	1.00		36x78 291 S Detour (Left) 36x78 291 S	19.50	19.5
				See Special Sign Details		16.42	NB L of 291	1.00		Detour (Left) 48x48 Scherer	16.00	19.5
				See Special Sign Details		16.42	NB R of 291	1.00		48x48 Scherer	16.00	10
				See Special Sign Details		16.42	NB L of 291	1.00		Detour (Left) 36x84 291 S	21.00	21
				See Special Sign Details		16.42	NB R of 291	1.00		Detour (U-Turn) 36x84 291 S	21.00	21
				MO4-8a 24x18 3.00 END DETOUR		16.65	NB R of 291	1.00	3	Detour (U-Turn)		3
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		3.61	NB R of Scherer EB	1.00	16			16
				WO20-2 48x48 16.00 DETOUR AHEAD		3.67	R of Scherer EB	1.00	16			16
				See Special Sign Details		3.73	R of Scherer	1.00		36x78 291 N Detour (Left)	19.50	19.5

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J4P3255	0190	July	710				EB					
		30, 2021		See Special Sign Details		3.76	R of Scherer EB	1.00		36x78 291 N Detour (Left)	19.50	19.5
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		3.80	R of Scherer EB	1.00	12.5			12.5
				WO20-2 48x48 16.00 DETOUR AHEAD		3.90	R of Scherer EB	1.00	16			16
				WO20-5 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED AHEAD		32.88	R & L of 291 SB	2.00	16			32
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		32.98	R of 291 SB	1.00	16			16
				See Special Sign Details		.00	R of 16th EB	1.00		48x48 Thompson Detour (Straight)	16.00	16
	0190 - To	otal										1537.5



Jul 6, 2022

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Project	LINE	Description	Туре	Adjustment Type		Date	By	Amount	Reinaiks
J4P3255	0020	CLASS A EXCAVATION	Price FUEL		1	Jun 16, 2021	SYSTEM	\$66.88	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					2	Jul 1, 2021	SYSTEM	\$66.88	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 30, 2021	SYSTEM	\$19.86	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Aug 16, 2021	SYSTEM	\$248.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Oct 18, 2021	SYSTEM	\$427.78	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Mar 2, 2022	SYSTEM	\$0.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$829.80	
			Price FUEL	- Total				\$829.80	
	0020 -	Total						\$829.80	
	0030	EMBANKMENT IN PLACE	Material		2	Jul 1, 2021	SYSTEM	\$10,300.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user needhm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$10,300.90)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Price FUEL		2	Jul 1, 2021	SYSTEM	\$118.78	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$118.78	
			Price FUEL	- Total				\$118.78	
	0030 -	Total						\$118.78	
	0040	COMPACTING EMBANKMENT	Material		1	Jun 16, 2021	SYSTEM	\$471.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$471.00)	
					2	Jul 1, 2021	SYSTEM	\$942.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user needhm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$942.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0040 -	Total				_		\$0.00	
	0060	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		2	Jul 1, 2021	SYSTEM	\$18,022.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user needhm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		(Thore)			2	Jul 1, 2021	SYSTEM	(\$18,022.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Price FUEL		2	Jul 1, 2021	SYSTEM	\$294.30	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 30, 2021	SYSTEM	\$200.74	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Aug 16, 2021	SYSTEM	\$322.30	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Sep 2, 2021	SYSTEM	\$285.45	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$1,102.79	
			Price FUEL	- Total				\$1,102.79	
	0060 -	Total						\$1,102.79	
	0070	MISC.	Material		6	Sep 2, 2021	SYSTEM	\$166,991.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4P3255	0070	MISC.	Material	Туре	6	Sep 2,	SYSTEM	(\$166,991.00)	
						2021		(, , ,	
					7	Sep 16, 2021	SYSTEM	\$166,996.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user nguyep1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$166,996.17)	
					8	Oct 1, 2021	SYSTEM	\$166,996.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$166,996.17)	
					9	Oct 18, 2021	SYSTEM	\$166,996.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user needhm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$166,996.17)	
					10	Nov 3, 2021	SYSTEM	\$166,996.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user needhm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$166,996.17)	
					11	Nov 16, 2021	SYSTEM	\$166,996.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user needhm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$166,996.17)	
					12	Dec 1, 2021	SYSTEM	\$166,996.17	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user needhm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$166,996.17)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	FUEL	17	Jun 30, 2022	needhm1	\$1,569.83	Fuel adjustment for optional pavement placed 8/27.
				FUEL - Tota				\$1,569.83	
			Other Item	Adjustment -	Total			\$1,569.83	
	0070 -			Adjustment -				\$1,569.83	
	0070 - 0080	BITUMINOUS PAVEMENT MIXTURE		Adjustment -	Total 7	Sep 16, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		BITUMINOUS PAVEMENT		Adjustment -			SYSTEM	\$1,569.83	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Adjustment -	7	2021 Sep 16,		\$1,569.83 \$39,200.70	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Adjustment -	7 7	2021 Sep 16, 2021 Oct 1,	SYSTEM	\$1,569.83 \$39,200.70 (\$39,200.70)	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Adjustment -	7 7 8	2021 Sep 16, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM	\$1,569.83 \$39,200.70 (\$39,200.70) \$39,200.70	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Adjustment -	7 7 8 8	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18,	SYSTEM SYSTEM SYSTEM	\$1,569.83 \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70)	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Adjustment -	7 7 8 8 9	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,569.83 \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70) \$39,200.70	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment
		BITUMINOUS PAVEMENT MIXTURE		Adjustment -	7 7 8 8 9 9	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,569.83 \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70)	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
		BITUMINOUS PAVEMENT MIXTURE		Adjustment -	7 7 8 8 9 9 9 10	2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,569.83 \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70) \$39,200.70	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.
		BITUMINOUS PAVEMENT MIXTURE		Adjustment -	7 7 8 8 9 9 10 10	2021 Sep 16, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3, 2021 Nov 3, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,569.83 \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70) \$39,200.70 (\$39,200.70)	Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user needhm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Jul 6, 2022

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks											
			Туре	Adjustment Type	Number	Date	Ву													
J4P3255	0800	BITUMINOUS PAVEMENT	Material						Estimate Exception 2 on the current Payment Estimate.											
		MIXTURE PG64-22 (SUR			12	Dec 1, 2021	SYSTEM	(\$39,200.70)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
			Other Item Adjustment	ACAD	16	Jun 16, 2022	alkhan1	\$2,181.95	Placed on 9/13/2021											
				ACAD - Tota	al			\$2,181.95												
			Other Item	Adjustment -	Total			\$2,181.95												
	0080 -	Total						\$2,181.95												
	0090	TACK COAT	Material		7	Sep 16, 2021	SYSTEM	\$636.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					7	Sep 16, 2021	SYSTEM	(\$636.75)												
				- Total				\$0.00												
			Material - Te	otal				\$0.00												
	0090 -	Total						\$0.00												
	0100	CONCRETE PAVEMENT (8 IN. NON-	Material		2	Jul 1, 2021	SYSTEM	\$78,592.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user needhm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
		REINFORCED,			2	Jul 1, 2021	SYSTEM	(\$78,592.80)												
					3	Jul 16, 2021	SYSTEM	\$103,085.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user nguyep1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					3	Jul 16, 2021	SYSTEM	(\$103,085.84)												
																4	Jul 30, 2021	SYSTEM	\$91,919.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
						4	Jul 30, 2021	SYSTEM	(\$91,919.66)											
					5	Aug 16, 2021	SYSTEM	\$14,698.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
								5	Aug 16, 2021	SYSTEM	(\$14,698.86)									
					6	Sep 2, 2021	SYSTEM	\$14,698.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					6	Sep 2, 2021	SYSTEM	(\$14,698.86)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
			Price FUEL		2	Jul 1, 2021	SYSTEM	\$417.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					2	Jul 1, 2021	SYSTEM	\$168.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					3	Jul 16, 2021	SYSTEM	1 \$187.55 Reference Item Price Adjustment Index Adjustmen	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					4	Jul 30, 2021	SYSTEM	\$505.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
				- Total				\$1,278.67												
			Price FUEL	- Total				\$1,278.67												
	0100 -	Total						\$1,278.67												
	0120	PIPE COLLAR, TYPE B	Material		1	Jun 16, 2021	SYSTEM	\$2,552.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					1	Jun 16, 2021	SYSTEM	(\$2,552.60)												
					2	Jul 1,	SYSTEM	\$3,828.90	This adjustment offsets the original system-generated Material Payment											
					-		S. SILIW	<i>40,020.00</i>												



Jul 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4P3255	0120	PIPE COLLAR, TYPE B	Material			2021			Estimate Item Adjustment (0010) due to user needhm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
					2	Jul 1, 2021	SYSTEM	(\$3,828.90)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0120 -	Total						\$0.00													
	0130	6 IN. CONCRETE MEDIAN STRIP	Material		6	Sep 2, 2021	SYSTEM	\$13,031.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user nguyep1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					6	Sep 2, 2021	SYSTEM	(\$13,031.85)													
					7	Sep 16, 2021	SYSTEM	\$13,031.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user nguyep1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					7	Sep 16, 2021	SYSTEM	(\$13,031.85)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0130 -	Total						\$0.00													
	0140	PAVED APPROACH, 8 IN.	Material		4	Jul 30, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user needhm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					4	Jul 30, 2021	SYSTEM	(\$4,536.96)													
					5	Aug 16, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user nguyep1 overridding Payment Estimate Exception 2 on the current Payment Estimate.												
					5	Aug 16, 2021	SYSTEM	(\$4,536.96)													
					6	Sep 2, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user nguyep1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					6	Sep 2, 2021	SYSTEM	(\$4,536.96)													
					7	Sep 16, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user nguyep1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					7	Sep 16, 2021	SYSTEM	(\$4,536.96)													
					8	Oct 1, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user nguyep1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					8	Oct 1, 2021	SYSTEM	(\$4,536.96)													
			9	9	5												9	Oct 18, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user needhm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
						9	Oct 18, 2021	SYSTEM	(\$4,536.96)												
													10	Nov 3, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
												1	1				10	Nov 3, 2021	SYSTEM	(\$4,536.96)	
					11	Nov 16, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					11	Nov 16, 2021	SYSTEM	(\$4,536.96)													
					12	Dec 1, 2021	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user needhm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					12	Dec 1, 2021	SYSTEM	(\$4,536.96)													



Jul 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks													
J4P3255	0140	PAVED	Material	Туре	13	Jan 3,	SYSTEM	\$4,536.96	This adjustment offsets the original system-generated Material Payment													
		APPROACH, 8 IN.			40	2022	OVOTEM	(\$4,500,00)	Estimate Item Adjustment (0001) due to user needhm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					13	Jan 3, 2022	SYSTEM	(\$4,536.96)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
			Price FUEL		4	Jul 30, 2021	SYSTEM	\$17.87	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				- Total				\$17.87														
			Price FUEL	- Total				\$17.87														
	0140 -	Total						\$17.87														
	0150	CURB AND GUTTER TYPE B	Material		6	Sep 2, 2021	SYSTEM	\$4,762.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user nguyep1 overridding Payment Estimate Exception 7 on the current Payment Estimate.													
					6	Sep 2, 2021	SYSTEM	(\$4,762.80)														
				7	Sep 16, 2021	SYSTEM	\$4,762.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user nguyep1 overridding Payment Estimate Exception 6 on the current Payment Estimate.														
					7	Sep 16, 2021	SYSTEM	(\$4,762.80)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0150 - Total 0160 PAVED DITCH						\$0.00															
			Material		4	Jul 30, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user needhm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
									4	Jul 30, 2021	SYSTEM	(\$2,635.68)										
					5	Aug 16, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user nguyep1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
							5	Aug 16, 2021	SYSTEM	(\$2,635.68)												
					6	Sep 2, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user nguyep1 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
					6	Sep 2, 2021	SYSTEM	(\$2,635.68)														
					7	Sep 16, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user nguyep1 overridding Payment Estimate Exception 8 on the current Payment Estimate.													
																		7	Sep 16, 2021	SYSTEM	(\$2,635.68)	
									1						8	Oct 1, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user nguyep1 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					8	Oct 1, 2021	SYSTEM	(\$2,635.68)														
																	9	Oct 18, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user needhm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					9	Oct 18, 2021	SYSTEM	(\$2,635.68)														
					10	Nov 3, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user needhm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					10	Nov 3, 2021	SYSTEM	(\$2,635.68)														
				1	11	Nov 16, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user needhm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					11	Nov 16, 2021	SYSTEM	(\$2,635.68)														



Jul 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
			.)	Туре			_,		
IP3255	0160	PAVED DITCH	Material		12	Dec 1, 2021	SYSTEM	\$2,635.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user needhm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$2,635.68)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0160 -	Total						\$0.00	
	0170	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		3	Jul 16, 2021	SYSTEM	\$3,222.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user nguyep1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$3,222.45)	
					4	Jul 30, 2021	SYSTEM	\$3,222.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user needhm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Jul 30, 2021	SYSTEM	(\$3,222.45)	
					5	Aug 16, 2021	SYSTEM	\$3,222.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user nguyep1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$3,222.45)	
					6	Sep 2, 2021	SYSTEM	\$3,222.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user nguyep1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$3,222.45)	
					7	Sep 16, 2021	SYSTEM	\$3,222.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user nguyep1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$3,222.45)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0170 -	Total						\$0.00	
	0190	CONSTRUCTION SIGNS	Material		1	Jun 16, 2021	SYSTEM	\$3,855.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user nguyep1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$3,855.20)	
					2	Jul 1, 2021	SYSTEM	\$4,613.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user needhm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$4,613.60)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0190 -	Total						\$0.00	
	0200	ADVANCED WARNING RAIL SYSTEM	Material		2	Jul 1, 2021	SYSTEM	\$357.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user needhm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$357.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0200 -	Total						\$0.00	
	0220	RELOCATED SIGNS	Material		9	Oct 18, 2021	SYSTEM	\$2,346.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user needhm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$2,346.30)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
4P3255	0220	RELOCATED SIGNS	Material			2021			Estimate Item Adjustment (0006) due to user needhm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					10	Nov 3, 2021	SYSTEM	(\$2,346.30)													
					11	Nov 16, 2021	SYSTEM	\$2,346.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user needhm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					11	Nov 16, 2021	SYSTEM	(\$2,346.30)													
					12	Dec 1, 2021	SYSTEM	\$2,346.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user needhm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					12	Dec 1, 2021	SYSTEM	(\$2,346.30)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0220 -	Total						\$0.00													
	0230	CHANNELIZER (TRIM LINE)	Material		2	Jul 1, 2021	SYSTEM	\$2,016.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user needhm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.												
					2	Jul 1, 2021	SYSTEM	(\$2,016.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0230 -	Total						\$0.00													
	0250	FLASHING ARROW PANEL	Material		2	Jul 1, 2021	SYSTEM	\$1,155.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user needhm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.												
																	2	Jul 1, 2021	SYSTEM	(\$1,155.00)	
					3	Jul 16, 2021	SYSTEM	\$1,155.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user nguyep1 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
					3	Jul 16, 2021	SYSTEM	(\$1,155.00)													
					4	Jul 30, 2021	SYSTEM	\$1,155.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user needhm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					4	Jul 30, 2021	SYSTEM	(\$1,155.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0250 -	Total						\$0.00													
	0260	CMS W/O COMMUNICATION INTERFACE,	Material		1	Jun 16, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user nguyep1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
		CONT F/			1	Jun 16, 2021	SYSTEM	(\$18,900.00)													
					2	Jul 1, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user needhm1 overridding Payment Estimate Exception 19 on the current Payment Estimate.												
					2	Jul 1, 2021	SYSTEM	(\$18,900.00)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0260 -	Total						\$0.00													
	0290	PREF THERMO PAVEMENT MARKING, 4 IN	Material		9	Oct 18, 2021	SYSTEM	\$516.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user needhm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
		WHITE			9	Oct 18, 2021	SYSTEM	(\$516.60)													
					10	Nov 3, 2021	SYSTEM	\$516.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user needhm1 overridding Payment												



Jul 6, 2022

roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3255	0290	PREF THERMO	Material						Estimate Exception 6 on the current Payment Estimate.
		PAVEMENT MARKING, 4 IN WHITE			10	Nov 3, 2021	SYSTEM	(\$516.60)	
					11	Nov 16, 2021	SYSTEM	\$516.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user needhm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$516.60)	
					12	Dec 1, 2021	SYSTEM	\$516.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user needhm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$516.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0290 -	Total						\$0.00	
	0300	PREF THERMO PVMT MARK, 24 IN WHIT	Material		9	Oct 18, 2021	SYSTEM	\$8,570.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user needhm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$8,570.10)	
					10	Nov 3, 2021	SYSTEM	\$8,570.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user needhm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$8,570.10)	
					11	Nov 16, 2021	SYSTEM	\$8,570.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user needhm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$8,570.10)	
					12	Dec 1, 2021	SYSTEM	\$8,570.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user needhm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$8,570.10)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0300 -							\$0.00	
	0310	PREF THERMO PVMT MARK, 24 IN YELLOW	Material		9	Oct 18, 2021	SYSTEM	\$1,008.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user needhm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$1,008.00)	
					10	Nov 3, 2021	SYSTEM	\$1,008.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user needhm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$1,008.00)	
					11	Nov 16, 2021	SYSTEM	\$1,008.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user needhm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$1,008.00)	
					12	Dec 1, 2021	SYSTEM	\$1,008.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user needhm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$1,008.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0310 -	Total						\$0.00	
	0320	PREF THERMO PVMT MARK,	Material		9	Oct 18, 2021	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user needhm1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3255	0320	LT/RT ARROW	Material						Estimate Exception 10 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$4,189.50)	
					10	Nov 3, 2021	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user needhm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$4,189.50)	
					11	Nov 16, 2021	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user needhm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$4,189.50)	
					12	Dec 1, 2021	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user needhm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$4,189.50)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0320 -				-			\$0.00	
	0340	TEMPORARY REMOVABLE MARKING TAPE	Material		5	Aug 16, 2021	SYSTEM	\$1,347.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user nguyep1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$1,347.25)	
					6	Sep 2, 2021	SYSTEM	\$1,347.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user nguyep1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$1,347.25)	
					7	Sep 16, 2021	SYSTEM	\$1,347.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user nguyep1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$1,347.25)	
					8	Oct 1, 2021	SYSTEM	\$1,347.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user nguyep1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$1,347.25)	
					9	Oct 18, 2021	SYSTEM	\$1,347.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user needhm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$1,347.25)	
					10	Nov 3, 2021	SYSTEM	\$1,347.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user needhm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$1,347.25)	
					11	Nov 16, 2021	SYSTEM	\$1,347.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user needhm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$1,347.25)	
					12	Dec 1, 2021	SYSTEM	\$1,347.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user needhm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$1,347.25)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0340 -	Total						\$0.00	
	0350	4 IN. YELLOW	Material		9	Oct 18,	SYSTEM	\$278.10	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4P3255	0350	HIGH BUILD	Material	Туре		2021			Estimate Item Adjustment (0013) due to user needhm1 overridding Payment
		WATERBORNE PAINT			9	Oct 18, 2021	SYSTEM	(\$278.10)	Estimate Exception 12 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	\$278.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user needhm1 overridding Payment
					10		SYSTEM	(\$278.10)	Estimate term Agastment (0012) due to use needin in ovenduing Payment Estimate Exception 11 on the current Payment Estimate.
					10	Nov 3, 2021	STSTEIM		
			Material - To	- Total otal				\$0.00 \$0.00	
	0350 -	Total						\$0.00	
	0360	6 IN. WHITE HIGH BUILD WATERBORNE	Material		5	Aug 16, 2021	SYSTEM	\$150.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user nguyep1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		PAINT			5	Aug 16, 2021	SYSTEM	(\$150.15)	
					6	Sep 2, 2021	SYSTEM	\$150.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user nguyep1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$150.15)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0360 -	Total						\$0.00	
	0460	18 IN. GROUP A FLARED END SECT	Material		1	Jun 16, 2021	SYSTEM	\$2,589.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user nguyep1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$2,589.20)	
					2	Jul 1, 2021	SYSTEM	\$3,883.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user needhm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$3,883.80)	
					3	Jul 16, 2021	SYSTEM	\$6,473.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user nguyep1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$6,473.00)	
					4	Jul 30, 2021	SYSTEM	\$9,062.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user needhm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Jul 30, 2021	SYSTEM	(\$9,062.20)	
					5	Aug 16, 2021	SYSTEM	\$9,062.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user nguyep1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$9,062.20)	
					6	Sep 2, 2021	SYSTEM	\$9,062.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$9,062.20)	
					7	Sep 16, 2021	SYSTEM	\$6,473.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user nguyep1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$6,473.00)	
					8	Oct 1, 2021	SYSTEM	\$6,473.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user nguyep1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$6,473.00)	



ect									
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
255 (0460	18 IN. GROUP A FLARED END SECT	Material		9	Oct 18, 2021	SYSTEM	\$6,473.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$6,473.00)	
					10	Nov 3, 2021	SYSTEM	\$6,473.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user needhm1 overridding Payme Estimate Exception 12 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$6,473.00)	
					11	Nov 16, 2021	SYSTEM	\$6,473.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user needhm1 overridding Payme Estimate Exception 11 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$6,473.00)	
					12	Dec 1, 2021	SYSTEM	\$6,473.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 11 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$6,473.00)	
					13	Jan 3, 2022	SYSTEM	\$6,473.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user needhm1 overridding Payme Estimate Exception 2 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$6,473.00)	
				- Total				\$0.00	
			Material - Te	otal				\$0.00	
	0460 -	Total						\$0.00	
(0470	21 IN. GROUP A FLARED END SECT	Material		5	Aug 16, 2021	SYSTEM	\$2,865.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user nguyep1 overridding Payme Estimate Exception 15 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$2,865.20)	
					6	Sep 2, 2021	SYSTEM	\$2,865.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user nguyep1 overridding Payme Estimate Exception 22 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$2,865.20)	
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
	0470 -	Total	Material - To						
	0470 - 0480	Total 24 IN. GROUP A FLARED END SECT			4	Jul 30, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user needhm1 overridding Paym Estimate Exception 13 on the current Payment Estimate.
		24 IN. GROUP A FLARED END			4	Jul 30,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme
		24 IN. GROUP A FLARED END				Jul 30, 2021 Jul 30,		\$0.00 \$0.00 \$1,432.60	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate.
		24 IN. GROUP A FLARED END			4	Jul 30, 2021 Jul 30, 2021 Aug 16,	SYSTEM	\$0.00 \$0.00 \$1,432.60 (\$1,432.60)	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payme
		24 IN. GROUP A FLARED END			4	Jul 30, 2021 Jul 30, 2021 Aug 16, 2021	SYSTEM SYSTEM	\$0.00 \$0.00 \$1,432.60 (\$1,432.60) \$1,432.60	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payme Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
		24 IN. GROUP A FLARED END		otal	4 5 5	Jul 30, 2021 Jul 30, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60)	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payme Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment
		24 IN. GROUP A FLARED END	Material	otal	4 5 5 6	Jul 30, 2021 Jul 30, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60) \$1,432.60	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payme Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment
	0480	24 IN. GROUP A FLARED END SECT		otal	4 5 5 6	Jul 30, 2021 Jul 30, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60) \$0.00	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payme Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment
		24 IN. GROUP A FLARED END SECT	Material	otal	4 5 5 6 6	Jul 30, 2021 Jul 30, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60) \$0.00	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payme Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment
	0480	24 IN. GROUP A FLARED END SECT	Material	otal	4 5 5 6	Jul 30, 2021 Jul 30, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60) \$1,432.60 (\$1,432.60) \$0.00	Estimate Item Adjustment (0011) due to user needhm1 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payme Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3255	0490	SEEDING - COOL SEASON GRASSES	Material		7	Sep 16, 2021	SYSTEM	\$4,640.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$4,640.68)	
					8	Oct 1, 2021	SYSTEM	\$4,640.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user nguyep1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$4,640.68)	
					9	Oct 18, 2021	SYSTEM	\$4,640.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user needhm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$4,640.68)	
					10	Nov 3, 2021	SYSTEM	\$6,612.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user needhm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$6,612.38)	
					11	Nov 16, 2021	SYSTEM	\$6,612.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user needhm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$6,612.38)	
					12	Dec 1, 2021	SYSTEM	\$6,612.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user needhm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$6,612.38)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0490 -	Total						\$0.00	
	0530	CURB INLET CHECK	Material		6	Sep 2,	SYSTEM	\$210.00	This adjustment offsets the original system-generated Material Payment
		ONLON				2021			Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
		ONLOR			6	2021 Sep 2, 2021	SYSTEM	(\$210.00)	
		UNEOK		- Total	6	Sep 2,	SYSTEM	(\$210.00) \$0.00	
		UNEOK	Material - Te		6	Sep 2,	SYSTEM	, , ,	
	0530 -		Material - To		6	Sep 2,	SYSTEM	\$0.00	
	0530 - 0560		Material - To Material		6 7	Sep 2,	SYSTEM	\$0.00 \$0.00	
		Total LIGHTING POLE, 45 FT. OR 13.5 M,				Sep 2, 2021 Sep 16,		\$0.00 \$0.00 \$0.00	Estimate Exception 28 on the current Payment Estimate.
		Total LIGHTING POLE, 45 FT. OR 13.5 M,			7	Sep 2, 2021 Sep 16, 2021 Sep 16,	SYSTEM	\$0.00 \$0.00 \$0.00 \$10,864.00	Estimate Exception 28 on the current Payment Estimate.
		Total LIGHTING POLE, 45 FT. OR 13.5 M,			7 7	Sep 16, 2021 Sep 16, 2021 Oct 1,	SYSTEM	\$0.00 \$0.00 \$10,864.00 (\$10,864.00)	Estimate Exception 28 on the current Payment Estimate.
		Total LIGHTING POLE, 45 FT. OR 13.5 M,			7 7 8	Sep 16, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,864.00 (\$10,864.00) \$10,864.00	Estimate Exception 28 on the current Payment Estimate.
		Total LIGHTING POLE, 45 FT. OR 13.5 M,		otal - Total	7 7 8	Sep 16, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,864.00 (\$10,864.00) \$10,864.00 (\$10,864.00)	Estimate Exception 28 on the current Payment Estimate.
	0560	Total LIGHTING POLE, 45 FT. OR 13.5 M,	Material	otal - Total	7 7 8	Sep 16, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,864.00 (\$10,864.00) \$10,864.00 (\$10,864.00) (\$10,864.00) \$0.00	Estimate Exception 28 on the current Payment Estimate.
	0560	Total LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	Material	otal - Total	7 7 8	Sep 16, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,864.00 (\$10,864.00) \$10,864.00 (\$10,864.00) (\$10,864.00) \$0.00	Estimate Exception 28 on the current Payment Estimate.
	0560 - 0560 -	Total LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	Material Material - To	otal - Total	7 7 8 8 8	Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,864.00 (\$10,864.00) \$10,864.00 (\$10,864.00) (\$10,864.00) \$0.00 \$0.00	Estimate Exception 28 on the current Payment Estimate.
	0560 - 0560 -	Total LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT	Material Material - To	otal - Total	7 7 8 8 8 8	Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Sep 16, Sep 16, Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$10,864.00 (\$10,864.00) \$10,864.00 (\$10,864.00) (\$10,864.00) \$0.00 \$0.00 \$301.00	Estimate Exception 28 on the current Payment Estimate.



Jul 6, 2022

		Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J4P3255	0570	BRACKET ARM, 4	Material	- Total				\$0.00					
		FT. OR 1.2 M	Material - To	otal				\$0.00					
	0570 -	Total						\$0.00					
	0580	BRACKET ARM, 6 FT. OR 1.8 M	Material		7	Sep 16, 2021	SYSTEM	\$345.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user nguyep1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					7	Sep 16, 2021	SYSTEM	(\$345.25)					
					8	Oct 1, 2021	SYSTEM	\$345.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user nguyep1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					8	Oct 1, 2021	SYSTEM	(\$345.25)					
				- Total				\$0.00					
			Material - T	otal				\$0.00					
	0580 -	Total						\$0.00					
	0590	BRACKET ARM, 8 FT. OR 2.4 M	Material		7	Sep 16, 2021	SYSTEM	\$345.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
					7	Sep 16, 2021	SYSTEM	(\$345.25)					
					8	Oct 1, 2021	SYSTEM	\$345.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user nguyep1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					8	Oct 1, 2021	SYSTEM	(\$345.25)					
				- Total				\$0.00					
			Material - Total					\$0.00					
	0590 -	Total						\$0.00					
	0590 - 0600		Material		7	Sep 16, 2021	SYSTEM	\$1,546.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user nguyep1 overridding Payment Estimate Exception 23 on the current Payment Estimate.				
					7	Sep 16, 2021	SYSTEM	(\$1,546.80)					
					8	Oct 1, 2021	SYSTEM	\$1,546.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment Estimate Exception 13 on the current Payment Estimate.				
					8	Oct 1, 2021	SYSTEM	(\$1,546.80)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0600 -	Total						\$0.00					
	0650	POLE FOUNDATION (45 FT. OR 13.5 M	Material		7	Sep 16, 2021	SYSTEM	\$7,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user nguyep1 overridding Payment Estimate Exception 24 on the current Payment Estimate.				
									7	Sep 16, 2021	SYSTEM	(\$7,088.00)	
					8	Oct 1, 2021	SYSTEM	\$7,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user nguyep1 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
					8	Oct 1, 2021	SYSTEM	(\$7,088.00)					
					9	Oct 18, 2021	SYSTEM	\$7,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user needhm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					9	Oct 18, 2021	SYSTEM	(\$7,088.00)					
					10	Nov 3, 2021	SYSTEM	\$7,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user needhm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					10	Nov 3, 2021	SYSTEM	(\$7,088.00)					
					11	Nov 16,	SYSTEM	\$7,088.00	This adjustment offsets the original system-generated Material Payment				



View View <th< th=""><th>Project</th><th>Line</th><th>Description</th><th>Adjustment</th><th>Other</th><th>Est.</th><th>Created Date</th><th>Created</th><th>Amount</th><th>Remarks</th></th<>	Project	Line	Description	Adjustment	Other	Est.	Created Date	Created	Amount	Remarks
FOUNDATION 465 FOUNDAT				Туре	Adjustment Type	Number		Ву		
Final problem is a set of the set of	I4P3255	0650	FOUNDATION (45	Material			2021			
Nome Earling Electropic Bits of South			FT. OR 13.5 M			11		SYSTEM	(\$7,088.00)	
Image: Note of the image: No						12		SYSTEM	\$7,088.00	Estimate Item Adjustment (0013) due to user needhm1 overridding Payment
Induction Interval Interval Interval Interval Interval						12		SYSTEM	(\$7,088.00)	
OUD Control Control <thcontrol< th=""> <thcontrol< th=""> <thcont< td=""><td></td><td></td><td></td><td></td><td>- Total</td><td></td><td></td><td></td><td>\$0.00</td><td></td></thcont<></thcontrol<></thcontrol<>					- Total				\$0.00	
DDT NFLAT SHEET: SIGNAL SIGN Medical For a spectra of the spectra of				Material - T	otal					
SIGNAL SIGN SIGNAL SIGN Page 1 2021 Page 1 Page 1 <td< td=""><td></td><td>0650 -</td><td>Total</td><td></td><td></td><td></td><td></td><td></td><td>\$0.00</td><td></td></td<>		0650 -	Total						\$0.00	
For the set of the set		0670		Material		7		SYSTEM	\$2,893.80	Estimate Item Adjustment (0018) due to user nguyep1 overridding Payment
						7		SYSTEM	(\$2,893.80)	
						8		SYSTEM	\$2,893.80	Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment
Vision Editability Elemental Element						8		SYSTEM	(\$2,893.80)	
 						9		SYSTEM	\$2,893.80	Estimate Item Adjustment (0017) due to user needhm1 overridding Payment
View Image: Construction of the constructin of the construction of the construction of the construction of						9		SYSTEM	(\$2,893.80)	
0710 POST, TYPE B, SOFT, OR 15, SOFT, OR 16, SOFT, OR						10	Nov 3,	SYSTEM	\$2,893.80	Estimate Item Adjustment (0016) due to user needhm1 overridding Payment
Via adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the ourser neodem1 overridding Payment Estimate Exception 15 on the ourser Neyment Estimate. 12 Dec 1, 2021 SYSTEM \$2,893.80 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the ourser Neyment Estimate. 0 - Total - Total \$2,893.80 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the ourser Neyment Estimate. 0 - Total - Total - Total - Total - Total 0 - Total - Total - Sop 16 SYSTEM \$2,893.80 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the ourser Neyment Estimate. 0 - Total - Total - Sop 16 SYSTEM \$18,847.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the ourser Neyment Estimate. 0 - Total - Total Sop 17, Sop 15 Sop 16 SVSTEM \$18,847.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the ourser Neyment Estimate.						10		SYSTEM	(\$2,893.80)	
Image: bit is a bit is bit abit bit a bit is a bit bit a bit bit abit bit a bit bit a b						11	Nov 16,	SYSTEM	\$2,893.80	Estimate Item Adjustment (0015) due to user needhm1 overridding Payment
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $						11		SYSTEM	(\$2,893.80)	
$ \begin{array}{ c c c c } \hline 12 \\ \hline 12 \\ \hline 2021 \\ $						12	Dec 1,	SYSTEM	\$2,893.80	Estimate Item Adjustment (0014) due to user needhm1 overridding Payment
$ \begin{array}{ $						12		SYSTEM	(\$2,893.80)	
0670 - Total 90.00 0710 POST, TYPE B, LONGEST ARM 50 FT. OR 15. Material Post 7 Sep 16, 2021 SYSTEM \$18,447.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate. 7 Sep 16, 2021 SYSTEM \$18,447.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate. 7 Sep 16, 2021 SYSTEM \$18,447.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 8 Oct 1, 2021 SYSTEM \$18,447.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 0710 - Total - Total SYSTEM \$18,447.75 Statuate Exception 16 on the current Payment Estimate. 0720 POST, TYPE B, LONGEST ARM S5 FT. Material - Total Sep 16, 2021 SYSTEM \$20,776.30 This adjustment offsets the original system-generated Material Payment Estimate Exception 28 on the current Payment Estimate. 0720 POST, TYPE B, LONGEST ARM S5 FT. Material 7 Sep 16, 2021 SYSTEM \$20,776.30 This adjustment offsets the original system					- Total		2021		\$0.00	
0670 - Total S0.00 0710 POST, TYPE B, LONGEST ARM 50 FT. OR 15. Material LONGEST ARM 50 FT. OR 15. Material Payment F 7 Sep 16, 2021 SYSTEM \$18,447.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate. 7 Sep 16, 2021 SYSTEM \$18,447.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate. 7 Sep 16, 2021 SYSTEM \$18,447.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 8 Oct 1, 2021 SYSTEM \$18,447.75 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 0710 - Total - Total SYSTEM \$18,447.75 Sumate Exception 16 on the current Payment Estimate. 0720 POST, TYPE B, LONGEST ARM S5 FT. Material 7 Sep 16, 2021 SYSTEM \$20,776.30 This adjustment offsets the original system-generated Material Payment Estimate Exception 28 on the current Payment Estimate. 0720 POST, TYPE B, LONGEST ARM S5 FT. T Sep 16, 2021 SYSTEM \$20,776.30 Thi				Material - T						
Image: Construct of the		0670 -	Total						\$0.00	
$ \begin{array}{ c c c c } \hline \begin{tabular}{ c c c } \hline \end{tabular} \\ \hline \en$		0710	LONGEST ARM	Material		7		SYSTEM	\$18,447.75	Estimate Item Adjustment (0019) due to user nguyep1 overridding Payment
0720 POST, TYPE B, LONGEST ARM, 55 FT. Material Y						7		SYSTEM	(\$18,447.75)	
$ \begin{array}{ c c c c c } \hline \begin{tabular}{ c c c c } \hline \begin{tabular}{ c c c c } \hline \begin{tabular}{ c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c c } \hline \begin{tabular}{ c c c c c c c c c c c c c c c c c c c$						8	Oct 1,	SYSTEM	\$18,447.75	Estimate Item Adjustment (0016) due to user nguyep1 overridding Payment
$ \begin{array}{ c c c c } \hline \begin{tabular}{ c c c } \hline \end{tabular} \hline \$						8		SYSTEM	(\$18,447.75)	· · · · ·
OT10 - Total \$0.00 0710 - Total \$0.00 0720 POST, TYPE B, LONGEST ARM 55 FT. Material - Total 7 Sep 16, 2021 SYSTEM \$20,776.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user nguyep1 overridding Payment Estimate Exception 28 on the current Payment Estimate.					- T <u>otal</u>				\$0.00	
0710 - Total \$0.00 0720 POST, TYPE B, LONGEST ARM 55 FT. Material 55 FT. 7 Sep 16, 2021 SYSTEM \$20,776.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user nguyen 1 overridding Payment Estimate Exception 28 on the current Payment Estimate. 7 Sep 16, 2021 SYSTEM (\$20,776.30)				Material - T						
0720 POST, TYPE B, LONGEST ARM 55 FT. Material 7 Sep 16, 2021 SYSTEM \$20,776.30 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user nguyep1 overridding Payment Estimate Exception 28 on the current Payment Estimate. 7 Sep 16, 2021 SYSTEM \$20,776.30 This adjustment offsets the original system-generated Material Payment Estimate Exception 28 on the current Payment Estimate.		0710 -	Total							
2021			POST, TYPE B, LONGEST ARM	Material		7	Sep 16, 2021	SYSTEM		Estimate Item Adjustment (0020) due to user nguyep1 overridding Payment
						7		SYSTEM	(\$20,776.30)	
						8		SYSTEM	\$20,776.30	This adjustment offsets the original system-generated Material Payment



Jul 6, 2022

ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
255	0720	POST, TYPE B, LONGEST ARM	Material	Туре		2021			Estimate Item Adjustment (0017) due to user nguyep1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		55 FT.			8	Oct 1, 2021	SYSTEM	(\$20,776.30)	Estimate Exception to on the current Payment Estimate.
				- Total		2021		\$0.00	
			Material - T					\$0.00	
	0720 -	Total						\$0.00	
	0750	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		5	Aug 16, 2021	SYSTEM	\$51,268.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user nguyep1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$51,268.10)	
					6	Sep 2, 2021	SYSTEM	\$51,268.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user nguyep1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$51,268.10)	
				- Total				\$0.00	
			Material - Te	otal				\$0.00	
	0750 -	Total						\$0.00	
	0770	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	Material		5	Aug 16, 2021	SYSTEM	\$21,111.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user nguyep1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$21,111.80)	
					6	Sep 2, 2021	SYSTEM	\$21,111.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user nguyep1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$21,111.80)	
			- Total					\$0.00	
			Material - To	otal				\$0.00	
- 1	0770 -							\$0.00	
	0820	PULL BOX, PREFORMED CLASS 2	Material		5	Aug 16, 2021	SYSTEM	\$9,130.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user nguyep1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$9,130.50)	
					6	Sep 2, 2021	SYSTEM	\$9,130.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user nguyep1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$9,130.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
								\$0.00	
	0820 -	Total						φ0.00	
	0820 - 0840	Total PULL BOX, PREFORMED CLASS 5	Material		5	Aug 16, 2021	SYSTEM	\$2,335.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		PULL BOX, PREFORMED	Material		5		SYSTEM SYSTEM		Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment
		PULL BOX, PREFORMED	Material			2021 Aug 16,		\$2,335.10	Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment
		PULL BOX, PREFORMED	Material		5	2021 Aug 16, 2021 Sep 2,	SYSTEM	\$2,335.10 (\$2,335.10)	Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user nguyep1 overridding Payment
		PULL BOX, PREFORMED	Material	- Total	5	2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	\$2,335.10 (\$2,335.10) \$2,335.10	Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user nguyep1 overridding Payment
		PULL BOX, PREFORMED	Material Material - To		5	2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	\$2,335.10 (\$2,335.10) \$2,335.10 (\$2,335.10)	Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user nguyep1 overridding Payment
		PULL BOX, PREFORMED CLASS 5			5	2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM	\$2,335.10 (\$2,335.10) \$2,335.10 (\$2,335.10) \$0.00	Estimate Item Adjustment (0015) due to user nguyep1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user nguyep1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3255	0850	BASE, CONCRETE	Material		8	Oct 1, 2021	SYSTEM	(\$20,209.36)	
					9	Oct 18, 2021	SYSTEM	\$20,209.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user needhm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$20,209.36)	
					10	Nov 3, 2021	SYSTEM	\$20,209.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user needhm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$20,209.36)	
					11	Nov 16, 2021	SYSTEM	\$20,209.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user needhm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$20,209.36)	
					12	Dec 1, 2021	SYSTEM	\$20,209.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user needhm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$20,209.36)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0850 -	Total						\$0.00	
	0875	CONCRETE FOOTINGS, EMBEDDED	Material		8	Oct 1, 2021	SYSTEM	\$5,055.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user nguyep1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$5,055.75)	
					9	Oct 18, 2021	SYSTEM	\$5,670.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user needhm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$5,670.00)	
					10	Nov 3, 2021	SYSTEM	\$5,670.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user needhm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$5,670.00)	
					11	Nov 16, 2021	SYSTEM	\$5,670.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user needhm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$5,670.00)	
				- Total				\$0.00	
			Material - To	Total				\$0.00	
	0875 -	Total						\$0.00	
	0890	2 IN. PSST POST - 12 GA.	Material		8	Oct 1, 2021	SYSTEM	\$2,535.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user nguyep1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$2,535.75)	
					9	Oct 18, 2021	SYSTEM	\$3,354.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user needhm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$3,354.75)	
					10	Nov 3, 2021	SYSTEM	\$3,354.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user needhm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$3,354.75)	
					11	Nov 16, 2021	SYSTEM	\$3,354.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user needhm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.



Jul 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3255	0890	2 IN. PSST POST - 12 GA.	Material		11	Nov 16, 2021	SYSTEM	(\$3,354.75)	
					12	Dec 1, 2021	SYSTEM	\$3,354.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user needhm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$3,354.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0890 -	· Total						\$0.00	
	0900	OMNI PST ANCH FOR 2 IN. PSST - 7 GA.	Material		8	Oct 1, 2021	SYSTEM	\$2,661.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user nguyep1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$2,661.75)	
					9	Oct 18, 2021	SYSTEM	\$3,480.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user needhm1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$3,480.75)	
					10	Nov 3, 2021	SYSTEM	\$3,480.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user needhm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$3,480.75)	
					11	Nov 16, 2021	SYSTEM	\$3,480.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user needhm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$3,480.75)	
					12	Dec 1, 2021	SYSTEM	\$3,480.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user needhm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$3,480.75)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0900 -		Material	rial				\$0.00	
	0930	MISC. HIGHWAY SIGNING			8	Oct 1, 2021	SYSTEM	\$12,589.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user nguyep1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$12,589.50)	
					9	Oct 18, 2021	SYSTEM	\$12,589.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user needhm1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$12,589.50)	
					10	Nov 3, 2021	SYSTEM	\$12,589.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user needhm1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					10	Nov 3, 2021	SYSTEM	(\$12,589.50)	
					11	Nov 16, 2021	SYSTEM	\$12,589.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user needhm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$12,589.50)	
					12	Dec 1, 2021	SYSTEM	\$12,589.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user needhm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					12	Dec 1, 2021	SYSTEM	(\$12,589.50)	
				- Total				\$0.00	



Jul 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3255	0930 -	Total						\$0.00	
	5003	IMPACT ATTENUATOR 45 MPH (SAND BARREL ARRAY)	Material		6	Sep 2, 2021	SYSTEM	\$5,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user nguyep1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$5,880.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	5003 -	Total						\$0.00	
	5004	TEMP. TRAFFIC BARRIER ANCHORED., CONT	Material		6	Sep 2, 2021	SYSTEM	\$4,523.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user nguyep1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$4,523.52)	
					7	Sep 16, 2021	SYSTEM	\$4,523.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user nguyep1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$4,523.52)	
					8	Oct 1, 2021	SYSTEM	\$4,523.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user nguyep1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$4,523.52)	
					9	Oct 18, 2021	SYSTEM	\$4,523.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user needhm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$4,523.52)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	5004 -	Total						\$0.00	
J4P3255 -	Total							\$7,099.69	
Overall - 1	Total							\$7,099.69	