

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 22, 2022

	Progress Estimate Number 23		Prime Contractor 201218-C08 Pay Period Start Pay Period End Pay Pe		March 2, 2022 April 22, 2022	\$3,506,841.88 \$519,429.03 \$4,026,270.91		
Approval Date	al Date							
April 25, 2022		Generated and Approved (and should be considered Draft) at the Project Office Level by						
April 27, 2022		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by						
May 3, 2022		Reviewed and Approved at the Central Office Controllers Office Level by						
	– .					0/ 00 10 1		

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021	September 11, 2021	100.00%

Cont	Contract Informational Dates									
Date Description										
Acceptance Date										
Awarded Date	January 6, 2021	January 6, 2021								
Letting Date	December 18, 2020	December 18, 2020								
Notice to Proceed Date	March 8, 2021	March 8, 2021								
Work Began Date	March 23, 2021	March 23, 2021								

willestones										
Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days							
September 11, 2021	September 11, 2021	Milestone Complete								
June 25, 2021	June 25, 2021	Milestone Complete								
December 1, 2021	December 1, 2021	Milestone Complete								
December 1, 2021	December 1, 2021	Milestone Complete								
	Original Completion Date September 11, 2021 June 25, 2021 December 1, 2021 December 1,	Original Completion Date September 11, 2021 June 25, 2021 December 1, 2021	Original Completion Date September 11, 2021 June 25, 2021 December 1, December 1, Milestone Complete December 1, December 1, Milestone Complete December 1, December 1, Milestone Complete							

Contract Total Pay For Estimate No. 23									
		This Estimate	Previous	To Date					
201218-C08									
	Total Posted Items Pay	\$0.00	\$4,026,270.95	\$4,026,270.95					
	Gross Item Adjustments	\$0.00	\$152,031.25	\$152,031.25					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$38,126.07	\$38,126.07					
	•		\$4,216,428.27	\$4,216,428.27					
Contract Total Pa	yable This Estimate:	\$0.00							

Items Paid This Estimate Period

No Data Available

No Data Available Contract Adjustments This I	<u>Estimate</u>				
Adj Type	Entered By	Comments	Time Units	Rate	Amount
SPADOther Contract Adjustment	hathak1	Superpave adjustment was paid 1/18/2022. The amount of \$887.07 was paid out for the adjustment but was inadvertently paid out over both J4S3280 and J4S3281 due to system percentage adjustments not corrected by the User. The paid amounts are being underrun back to \$0.00 on this estimate and the Superpave Adjustment will be paid out only to J4S3280.			(\$887.07)
TSROther Contract Adjustment	hathak1	TSR Adjustment for 1704.5 tons of SP125 placed in Lots I-K on J4S3281.			\$2,765.89
TSROther Contract Adjustment	hathak1	TSR adjustment was paid 1/18/2022. The amount of \$9887.16 was paid out for the adjustment but was inadvertently paid out over			(\$9,887.16)

Revision 4/1/2020 Page 1 of 62



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 22, 2022

Progress Estimate Nun 23	Contract ID Prime Contract	201218-C08 Pay Period Stor Ideker, Inc. Pay Period En		Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,506,841.88 \$519,429.03 \$4,026,270.91
Adj Type	Entered By	Comments	Time Units	Rate	Amount
		both J4S3280 and J4S3281 due to system percentage adjustments not corrected by the User. The paid amounts are being underrun back to \$0.00 on this estimate and the TSR Adjustment will be paid out only to J4S3280.			
SPADOther Contract Adjustment	hathak1	Superpave Adjustment for 11,005.84 tons of SP125 21-14 placed on J4S3281. Adjustment covers both Line No;'s 0770 and 5104.			\$24,585
SPADOther Contract Adjustment	hathak1	Superpave Adjustment for 15,669.8 tons of SP095 placed on J4S3280.			\$887
TSROther Contract Adjustment	hathak1	TSR adjustment was paid 1/03/2022. The amount of \$2765.89 was paid out for the adjustment but was inadvertently paid out over both J4S3280 and J4S3281 due to system percentage adjustments not corrected by the User. The paid amounts are being underrun back to \$0.00 on this estimate and the TSR Adjustment will be paid out only to J4S3281.			(\$2,76
TSROther Contract Adjustment	hathak1	TSR Adjustment is based on Lot 1, Sublot K-O for 5821.8 tons of SP095 on J4S3280.			\$9,887
SPADOther Contract Adjustment	hathak1	Superpave adjustment was paid 1/03/2022. The amount of \$24,585.95 was paid out for the adjustment but was inadvertently paid out over both J4S3280 and J4S3281 due to system percentage adjustments not corrected by the User. The paid amounts			(\$24,58

These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

Line Item	<u>Adjustı</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3280	0450	MISC.	Material			-1	\$4,806.00	(\$4,806.00)
	0450	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1	\$4,806.00	\$4,806.00
	0600	SH-FLAT SHEET - SIGNAL SIGN	Material			-12.6	\$120.00	(\$1,512.00)
	0600	SH-FLAT SHEET - SIGNAL SIGN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	12.6	\$120.00	\$1,512.00

Revision 4/1/2020 Page 2 of 62



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 22, 2022

Progress Estimate Number 23 Contract ID Prime Contractor Ideker, Inc. Pay Period Start Pay Period End Prime Contract Amount Current Contract Amount Current Contract Amount Science Space Space

							. , , .	20,270.31
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3280					Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
	0620	POST, SIGNAL 8 FT. OR 2.4 M	Material			-5	\$1,459.00	(\$7,295.00)
	0620	POST, SIGNAL 8 FT. OR 2.4 M	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	5	\$1,459.00	\$7,295.00
	5009	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	Material			-1	\$3,491.25	(\$3,491.25)
	5009	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1	\$3,491.25	\$3,491.25
	5012	MISC.	Material			-1	\$1,309.14	(\$1,309.14)
	5012	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	1	\$1,309.14	\$1,309.14
	5015	MISC.	Material			-1	\$5,150.80	(\$5,150.80)
	5015	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$5,150.80	\$5,150.80
J4S3281	5110	TACK COAT	Material			-338	\$2.25	(\$760.50)
	5110	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	338	\$2.25	\$760.50
	5112	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material			-494	\$10.00	(\$4,940.00)
	5112	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	494	\$10.00	\$4,940.00
Total								\$0.00

Revision 4/1/2020 Page 3 of 62



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information						
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J4S3280	FAF 69-1(30)	Resurface	69	CLAY	from Klamm Road to Denve	n Klamm Road to Denver Avenue						
J4S3281	FAF 69-1(31)	Resurface	69	CLAY	from just north of Garrison F	Road to Denver Avenue						
Γotals by .	Job Numbe	ers										
J4S3280					This Estimate	Previous	To Date					
		ed Item Pay s Item Adjustn		s Item Pa	\$0.00 \$0.00	\$2,358,902.72 \$93,392.85 \$2,452,295.57	\$2,358,902.72 \$93,392.85 \$2,452,295.57					
	Liqui	itive centive dated Damage r Contract Adji	s		\$0.00 \$0.00 \$0.00 (\$11,562.84)	\$0.00 \$0.00 \$0.00 \$0.00 \$22,337.07	\$0.00 \$0.00 \$0.00 \$0.00 \$10,774.23					
J4S3281		ed Item Pay s Item Adjustn		s Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$1,667,368.23 \$58,638.40 \$1,726,006.63	To Date \$1,667,368.23 \$58,638.40 \$1,726,006.63					
	Liqui	itive centive dated Damage r Contract Adji			\$0.00 \$0.00 \$0.00 \$11.562.84	\$0.00 \$0.00 \$0.00 \$15.789.00	\$0.00 \$0.00 \$0.00 \$27.351.84					

Revision 4/1/2020 Page 4 of 62



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3281, Item 4071005, Project Item Line Number 5110, Material Set 407100596, Material 1015EACSS1H - Emulsified Asphalt CSS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3280, Item 6141024, Project Item Line Number 5009, Material Set 614102496, Material 0614DFGTBP - Grates and Bearing Plates, Acceptance Action Generic 0614DFGTBP is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3281, Item 6200018, Project Item Line Number 5112, Material Set 620001896, Material 1048PMPFYL - Performed Thermoplastic Marking Tape YL, Acceptance Action Generic 1048PMPFYL is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3280, Item 7319902, Project Item Line Number 0450, Material Set 7319902, Material 0614DFMNCO - Manhole Cover, Acceptance Action Generic 0614DFMNCO - is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3280, Item 9020833, Project Item Line Number 0600, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3280, Item 9022708, Project Item Line Number 0620, Material Set 902270896, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3280, Item 9022708, Project Item Line Number 0620, Material Set 902270896, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3280, Item 9029901, Project Item Line Number 5012, Material Set 9029901, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	hathak1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3280, Item 9029901, Project Item Line Number 5015, Material Set 9029901, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	No Remark was entered by Engineer	hathak1	Overridden

Revision 4/1/2020 Page 5 of 62



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-C08	J4S3280	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$19,970.10	\$19,970.10
		0001	0020	2063000	CLASS 3 EXCAVATION	929.00	-9.00	920.00	CUYD	920.00	\$12.00	\$11,040.00
		0001	0030	2071000	LINEAR GRADING CLASS 1	6.00	0.00	6.00	STA	6.00	\$7,667.35	\$46,004.10
		0001	0040	4011208	BITUMINOUS PAVEMENT MIXTURE PG70-22, (BP-2)	935.00	81.90	1,016.90	TONS	1,016.90	\$69.41	\$70,583.03
		0001	0050	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	14,468.00	1,201.80	15,669.80	TONS	15,669.80	\$56.61	\$887,067.38
		0001	0060	4079912	MISC.POLYMER EMULSION MEMBRANE	15,165.00	15,302.00	30,467.00	GAL	30,467.00	\$2.25	\$68,550.75
		0001	0070	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	1.00	\$1,610.00	\$1,610.00
		0001	0080	6081010	CONCRETE CURB RAMP	108.00	0.00	108.00	SQYD	108.00	\$189.15	\$20,428.20
		0001	0090	6081012	TRUNCATED DOMES	495.00	-365.00	130.00	SQFT	130.00	\$20.54	\$2,670.20
		0001	0100	6086004	CONCRETE SIDEWALK, 4 IN.	304.00	-170.00	134.00	SQYD	134.00	\$59.65	\$7,993.10
		0001	0110	6091052	CURB AND GUTTER TYPE B	109.00	42.00	151.00	LF	151.00	\$51.40	\$7,761.40
		0001	0120	6099902	MISC.WATER VALVE AND MANHOLE HEIGHT ADJUSTMENT	76.00	-69.00	7.00	EA	7.00	\$125.00	\$875.00
		0001	0130	6099903	MISC.APWA CURB AND GUTTER TYPE 2 ROLLBACK CURB	14.00	2.00	16.00	LF	16.00	\$82.05	\$1,312.80
		0001	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0150	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	693.00	-72.40	620.60	SQYD	620.60	\$255.75	\$158,718.45
		0001	0160	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	139.00	-139.00	0.00	SQYD	0.00	\$1.00	\$0.00
		0001	0170	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	139.00	-139.00	0.00	SQYD	0.00	\$1.00	\$0.00
		0001	0180	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	2,728.00	-117.00	2,611.00	LF	2,611.00	\$1.65	\$4,308.15
		0001	0190	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,140.00	-26.00	1,114.00	EA	1,114.00	\$4.65	\$5,180.10
		0001	0200	6143013	MANHOLE FRAME AND COVER, TYPE 3	5.00	-1.00	4.00	EA	4.00	\$258.00	\$1,032.00
		0001	0210	6149902	MISC.GRATE AND BEARING PLATE (3FT X 2 FT)	1.00	-1.00	0.00	EA	0.00	\$4,350.00	\$0.00
		0001	0220	6149902	MISC.GRATE AND BEARING PLATE (4FT X 2FT)	2.00	-2.00	0.00	EA	0.00	\$4,968.00	\$0.00
		0001	0230	6161005	CONSTRUCTION SIGNS	1,858.00	-487.00	1,371.00	SQFT	1,371.00	\$4.00	\$5,484.00
		0001	0240	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	-6.00	2.00	EA	2.00	\$35.00	\$70.00
		0001	0250	6161009	FLAG ASSEMBLY	26.00	-26.00	0.00	EA	0.00	\$35.00	\$0.00
		0001	0260	6161025	CHANNELIZER (TRIM LINE)	200.00	140.00	340.00	EA	340.00	\$20.00	\$6,800.00
		0001	0270	6161030	TYPE III MOVEABLE BARRICADE	2.00	3.00	5.00	EA	5.00	\$90.00	\$450.00
		0001	0280	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	4.00	\$1,500.00	\$6,000.00
		0001	0290	6161055	SEQUENTIAL FLASHING WARNING LIGHT	22.00	-22.00	0.00	EA	0.00	\$95.00	\$0.00
		0001	0300	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$4,000.00	\$16,000.00
		0001	0310	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$246,313.91	\$246,313.91
		0001	0320	6200003	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 4 IN., WHITE	6,229.00	-6,229.00	0.00	LF	0.00	\$2.50	\$0.00
		0001	0330	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	2,411.00	-1,559.00	852.00	LF	852.00	\$10.00	\$8,520.00
		0001	0340	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	589.00	172.00	761.00	LF	761.00	\$10.00	\$7,610.00
		0001	0350	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	94.00	-25.00	69.00	EA	69.00	\$180.00	\$12,420.00
		0001	0360	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	1.00	-1.00	0.00	EA	0.00	\$350.00	\$0.00
		0001	0370	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	252.00	-101.00	151.00	EA	151.00	\$90.00	\$13,590.00
		0001	0380	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	55,788.00	5,864.00	61,652.00	LF	61,652.00	\$0.20	\$12,330.40
		0001	0390	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	49,832.00	-375.00	49,457.00	LF	49,457.00	\$0.20	\$9,891.40
		0001	0400	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	151,647.00	-2,167.00	149,480.00	SQYD	149,480.00	\$1.20	\$179,376.00
		0001	0410	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0001	0420	7250312A	12 IN. PIPE GROUP B	37.00	0.00	37.00	LF	37.00	\$175.00	\$6,475.00
		0001	0430	7250318A	18 IN. PIPE GROUP B	652.00	0.00	652.00	LF	652.00	\$147.00	\$95,844.00

Revision 4/1/2020 Page 6 of 62



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

March 1989 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1982 1	Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
March March Michael	201218-C08	J4S3280	0001	0440	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	39.00	0.00	39.00	FT		\$1,075.00	\$41,925.00
Math			0001	0450	7319902	MISC.REPLACE DROP INLET COVER 7'X3'	1.00	0.00	1.00	EA	1.00	\$4,806.00	\$4,806.00
			0001	0460	8061016	SEDIMENT REMOVAL	7.00	-7.00	0.00	CUYD	0.00	\$100.00	\$0.00
			0001	0470	8061017	TEMPORARY SEEDING	0.50	-0.50	0.00	ACRE	0.00	\$10,500.00	\$0.00
100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100			0001	0480	8061019	SILT FENCE	669.00	-669.00	0.00	LF	0.00	\$3.00	\$0.00
Color Colo			0010	0490	6061010	GUARDRAIL TYPE A	2,500.00	-275.00	2,225.00	LF	2,225.00	\$18.75	\$41,718.75
			0010	0500	6061060	MGS GUARDRAIL	350.00	200.00	550.00	LF	550.00	\$19.50	\$10,725.00
			0010	0510	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	175.00	-175.00	0.00	LF	0.00	\$28.50	\$0.00
CO10 0540 0400161 TYPE A CENSINIVORTHY END TERMINAL (MAGN) 2.0 0.0 2.0 0.0 EA 2.0 \$2,250.00 \$4,170.00 \$600 0500 050017 \$1776. A CENSINIVORTHY SIN TERMINAL 10.00 1.100 1.00 1.00 EA 0.0 \$2,450.00 \$22,250.00 \$22,250.00 \$22,250.00 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$200 \$			0010	0520	6061065	MGS GUARDRAIL, 6 FT. POSTS, 1 FT 6.75 IN. SPACING	37.50	-37.50	0.00	LF	0.00	\$50.00	\$0.00
ONTO 0550 0500015 TYPE A CRASHYMORTHY DNO TERMANAL 10.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -1.00 -			0010	0530	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	2.00	\$800.00	\$1,600.00
COURT COUR			0010	0540	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$2,350.00	\$4,700.00
16700 6977 6917002 CARLE, 2 AWG I CONDUCTOR 16700 0.00 14700 EF 147.00 88.50 \$779-10			0010	0550	6063015	TYPE A CRASHWORTHY END TERMINAL	10.00	-1.00	9.00	EA	9.00	\$2,450.00	\$22,050.00
			0010	0560	6066610	END ANCHOR	12.00	-1.00	11.00	EA	11.00	\$800.00	\$8,800.00
			0030	0570	9017002	CABLE, 2 AWG 1 CONDUCTOR	147.00	0.00	147.00	LF	147.00	\$5.30	\$779.10
1000 0000 0000033 SHFLAT SHEET - SIGNAL SIGN 12.00 0.000 12.00 0.0007 12.00 5.0007 12.00 5.0000 5.0000 5.00000 5.00000 5.00000 5.00000 5.00000 5.00000 5.00000 5.00000 5.00000 5.00000 5.00000 5.00000 5.000000 5.000000 5.000000 5.000000 5.000000 5.000000 5.000000 5.0000000 5.0000000000			0030	0580	9017008	CABLE, 8 AWG 1 CONDUCTOR	28.00	0.00	28.00	LF	28.00	\$8.00	\$224.00
0.003			0030	0590	9020811	SIGNAL HEAD, TYPE 1S, PEDESTRIAN	13.00	0.00	13.00	EA	13.00	\$972.00	\$12,636.00
Mathematical Controller Assembly Housing, Nema 182 Controller 1.00 1.00 5.00 EA 5.00 \$1,456.00 \$7,256.00 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000			0030	0600	9020833	SH-FLAT SHEET - SIGNAL SIGN	12.60	0.00	12.60	SQFT	12.60	\$120.00	\$1,512.00
0030 0030 0024/283 CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER 1.00 0.00 1.00 EA 1.00 \$14,001.00 \$14,201.00 \$14,201.00 \$22,188.00 \$0030 0060 9025/280 CONDUIT, 3 IN, TERNICH WITH TRACER WIRE 156.00 36.00 192.00 LF 192.00 \$44.40 \$7,048.80 \$1,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,000 \$10,0			0030	0610	9020834	SIGNAL SIGN, MOUNTING HARDWARE	16.00	0.00	16.00	EA	16.00	\$11.00	\$176.00
0030 0640 0024820 DETECTOR, PUSHBUTTON 20.00 4.00 16.00 EA 16.00 \$1,448.00 \$23,168.00 \$2030 \$050 \$022300 \$202300 \$20000 \$20000 \$2000 \$2000 \$2000 \$2000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$20000 \$200000 \$20000 \$20000 \$20000 \$20000 \$200000 \$20000 \$20000 \$20000 \$20000 \$20000 \$200000 \$200000 \$200000 \$200000 \$200000 \$200000 \$200000 \$200000 \$200000 \$200000 \$200000 \$200000 \$200000 \$20000000000			0030	0620	9022708	POST, SIGNAL 8 FT. OR 2.4 M	4.00	1.00	5.00	EA	5.00	\$1,459.00	\$7,295.00
Color			0030	0630	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00	\$14,301.00	\$14,301.00
0330 0660 9027300 CONDUIT, 3 INL, PUSHED WITH TRACER WIRE 20 00 0.00 20 00 LF 20 00 \$130.00 \$2,800.00			0030	0640	9024920	DETECTOR, PUSHBUTTON	20.00	-4.00	16.00	EA	16.00	\$1,448.00	\$23,168.00
0300 0670 028300 CABLE, 16 AWG 2 CONDUCTOR 348.00 0.00 348.00 LF 348.00 \$3.50 \$1.218.00			0030	0650	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	156.00	36.00	192.00	LF	192.00	\$41.40	\$7,948.80
0300 0880 9028310 CABLE, 16 AWG 5 CONDUCTOR 352.00 0.00 352.00 LF 352.00 \$3.90 \$1.372.80			0030	0660	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	20.00	0.00	20.00	LF	20.00	\$130.00	\$2,600.00
0030 0680 9028500 CABLE, LOOP DETECTOR, IN DUCT 144.00 16.00 16.00 LF 160.00 \$33.10 \$5,136.00 0030 0700 9028510 CABLE, LOOP DETECTOR, LEAD-IN 120.00 0.00 120.00 LF 120.00 \$3.55 \$420.00 0030 0710 9028620 POWER SUPPLY ASSEMBLY, TYPE 2 1.00 0.00 1.00 EA 1.00 \$6,474.00 \$6,474.00 0030 0720 9029100 BASE, CONCRETE 2.26 0.44 2.70 CUYD 2.70 \$4,033.00 \$10.899.10 0030 0730 9103700 CCTV CAMERA ASSEMBLY, INSTALLED 2.20 0.00 2.00 EA 2.00 \$6,913.00 \$13.826.00 0010 5001 6069901 MISC End Anchor Installal Highland Avenue 0.00 1.00 1.00 LS 1.00 \$2,108.14 \$2,108.14 0010 5002 6069902 MISC, Core Drill for New Post Installation 0.00 1.00 1.00 LS 1.00 \$10.40.90 \$10.40.90 0030 5003 2022010 REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$5,145.00 \$3,150.00 0001 5004 6181000 MOBILIZATION 0.00 1.00 1.00 LS 1.00 \$3,150.00 \$3,150.00 0001 5005 6169901 MISC, CURB AND GUTTER 0.00 1.00 1.00 LS 1.00 \$3,150.00 \$3,150.00 0001 5006 6099901 MISC, CURB AND GUTTER 0.00 1.00 1.00 LS 1.00 \$3,491.25 \$3,491.25 0001 5008 806410 TYPE 3B EROSION CONTROL BLANKET 0.00 2,420.00 2,242.00 SQYD 2,242.00 \$2,25 \$6,171.00 0001 5009 6141024 GRATE AND BEARING PLATE (F.F. X. 3 FT. OR 1524 MM X 914 0.00 1.00 LS 1.00 \$3,491.25 \$3,491.25 0001 5010 4019901 MISC, DATE INTERVIEWENT MIXTURE (BP-2) 0.00 1.00 1.00 LS 1.00 \$3,491.25 \$3,491.25 0001 5010 4019901 MISC, DATE INTERVIEWENT REPAIR FOR MOISTURE 0.00 1.00 1.00 LS 1.00 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40 \$1,001.40			0030	0670	9028308	CABLE, 16 AWG 2 CONDUCTOR	348.00	0.00	348.00	LF	348.00	\$3.50	\$1,218.00
033 0700 9028510 CABLE, LOOP DETECTOR, LEAD-IN 120.00 0.00 120.00 LF 120.00 \$3.50 \$4.20.00			0030	0680	9028310	CABLE, 16 AWG 5 CONDUCTOR	352.00	0.00	352.00	LF	352.00	\$3.90	\$1,372.80
0030 0710 9028820 POWER SUPPLY ASSEMBLY, TYPE 2 1.00 0.00 1.00 EA 1.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,474.00 \$6,100.00 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$6,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 \$1,000 <th< td=""><td></td><td></td><td>0030</td><td>0690</td><td>9028500</td><td>CABLE, LOOP DETECTOR, IN DUCT</td><td>144.00</td><td>16.00</td><td>160.00</td><td>LF</td><td>160.00</td><td>\$32.10</td><td>\$5,136.00</td></th<>			0030	0690	9028500	CABLE, LOOP DETECTOR, IN DUCT	144.00	16.00	160.00	LF	160.00	\$32.10	\$5,136.00
0030 0720 9029100 BASE, CONCRETE 2.6 0.44 2.70 CUVD 2.70 \$4,033.00 \$10,889.10 0030 0730 9103700 CCTV CAMERA ASSEMBLY, INSTALLED 2.00 0.00 2.00 EA 2.00 \$6,913.00 \$13,826.00 0010 5001 6669901 MISC, Cord Drill for New Post Installation 0.00 1.00 1.00 LS 1.00 \$2,108.14 \$2,210.00 0030 5033 2022010 REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$10,430.90 \$10,430.90 0001 5004 6181000 MOBILIZATION 0.00 1.00 1.00 LS 1.00 \$5,145.00 \$5,145.00 0001 5005 6168901 MISC, CURB AND GUTTER 0.00 1.00 1.00 LS 1.00 \$3,6764.88 \$36,764.88 0001 5007 620000 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. 0.00 2,800.00 LF 2,800.00 \$3,68 \$1,000.4			0030	0700	9028510	CABLE, LOOP DETECTOR, LEAD-IN	120.00	0.00	120.00	LF	120.00	\$3.50	\$420.00
0030 0730 9103700 CCTY CAMERA ASSEMBLY, INSTALLED 2.00 0.00 2.00 EA 2.00 \$8,913.00 \$13,826.00			0030	0710	9028620	POWER SUPPLY ASSEMBLY, TYPE 2	1.00	0.00	1.00	EA	1.00	\$6,474.00	\$6,474.00
O110 S001 6069901 MISC.End Anchor Install at Highland Avenue 0.00 1.00 1.00 1.00 1.00 1.00 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$2,108.14 \$			0030	0720	9029100	BASE, CONCRETE	2.26	0.44	2.70	CUYD	2.70	\$4,033.00	\$10,889.10
0010 5002 6069902 MISC.Core Drill for New Post Installation 0.00 12.00 12.00 EA 12.00 \$185.00 \$2,220.00			0030	0730	9103700	CCTV CAMERA ASSEMBLY, INSTALLED	2.00	0.00	2.00	EA	2.00	\$6,913.00	\$13,826.00
0030 5003 2022010 REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$10,430.90 \$10,430.90			0010	5001	6069901	MISC.End Anchor Install at Highland Avenue	0.00	1.00	1.00	LS	1.00	\$2,108.14	\$2,108.14
0001 5004 6181000 MOBILIZATION 0.00 1.00 1.00 1.00 LS 1.00 \$5,145.00 \$5,145.00			0010	5002	6069902	MISC.Core Drill for New Post Installation	0.00	12.00	12.00	EA	12.00	\$185.00	\$2,220.00
0001 5005 6169901 MISC.TRAFFIC CONTROL 0.00 1.00 1.00 LS 1.00 \$3,150.00 \$3,150.00			0030	5003	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$10,430.90	\$10,430.90
0001 5006 6099901 MISC.CURB AND GUTTER 0.00 1.00 1.00 LS 1.00 \$36,764.68 \$36,764.68 0001 5007 6200009 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE 0.00 280.00 280.00 LF 280.00 \$3.68 \$1,030.40 0001 5008 8064140 TYPE 3B EROSION CONTROL BLANKET 0.00 2,420.00 \$2,420.00 \$2,420.00 \$2,55 \$6,171.00 0001 5009 6141024 GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM) 0.00 1.00 1.00 EA 1.00 \$3,491.25 \$3,491.25 0001 5010 4019901 MISC.BITUMINOUS PAVEMENT MIXTURE (BP-2) 0.00 1.00 LS 1.00 \$70,765.66 \$70,765.66 0001 5011 6139901 MISC.PARTIAL DEPTH PAVEMENT REPAIR FOR MOISTURE FLOPS 0.00 1.00 1.00 LS 1.00 \$14,209.38 \$14,209.38 0001 5012 9029901 MISC.CONDUIT REPAIR 0.00 1.00 1.00 LS			0001	5004	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$5,145.00	\$5,145.00
0001 5007 6200009 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. 0.00 280.00 280.00 LF 280.00 \$3.68 \$1,030.40 WHITE 0001 5008 8064140 TYPE 3B EROSION CONTROL BLANKET 0.00 2,420.00 2,420.00 SQYD 2,420.00 \$2.55 \$6,171.00 \$3,491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3.491.25 \$3			0001	5005	6169901	MISC.TRAFFIC CONTROL	0.00	1.00	1.00	LS	1.00	\$3,150.00	\$3,150.00
WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WHITE WH			0001	5006	6099901	MISC.CURB AND GUTTER	0.00	1.00	1.00	LS	1.00	\$36,764.68	\$36,764.68
0001 5009 6141024 GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 0.00 1.00 1.00 EA 1.00 \$3,491.25 \$3,491.25 0001 5010 4019901 MISC.BITUMINOUS PAVEMENT MIXTURE (BP-2) 0.00 1.00 1.00 LS 1.00 \$70,765.66 \$70,765.66 0001 5011 6139901 MISC.PARTIAL DEPTH PAVEMENT REPAIR FOR MOISTURE 0.00 1.00 1.00 LS 1.00 \$14,209.38 \$14,209.38 0001 5012 9029901 MISC.CONDUIT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,309.14 \$1,309.14 0001 5013 2022010 REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$933.61 \$933.61 0001 5014 6139901 MISC.CONCRETE FOR PAVEMENT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,442.70 \$1,442.70 0030 5015 9029901 MISC.SIGNAL PULL BOX ADJUSTMENT 0.00 1.00 1.00 LS 1.00 \$5,150.80 \$5,150.80			0001	5007	6200009		0.00	280.00	280.00	LF	280.00	\$3.68	\$1,030.40
MM MISC. SITUMINOUS PAVEMENT MIXTURE (BP-2) 0.00 1.00 1.00 LS 1.00 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66 \$70,765.66			0001	5008	8064140	TYPE 3B EROSION CONTROL BLANKET	0.00	2,420.00	2,420.00	SQYD	2,420.00	\$2.55	\$6,171.00
0001 5010 4019901 MISC.BITUMINOUS PAVEMENT MIXTURE (BP-2) 0.00 1.00 1.00 LS 1.00 \$70,765.66 \$70,765.66 0001 5011 6139901 MISC.PARTIAL DEPTH PAVEMENT REPAIR FOR MOISTURE FLOPS 0.00 1.00 1.00 LS 1.00 \$14,209.38 \$14,209.38 0001 5012 9029901 MISC.CONDUIT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,309.14 \$1,309.14 0001 5013 2022010 REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$933.61 \$933.61 0001 5014 6139901 MISC.CONCRETE FOR PAVEMENT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,442.70 \$1,442.70 0030 5015 9029901 MISC.SIGNAL PULL BOX ADJUSTMENT 0.00 1.00 1.00 LS 1.00 \$5,150.80 \$5,150.80			0001	5009	6141024		0.00	1.00	1.00	EA	1.00	\$3,491.25	\$3,491.25
FLOPS 0001 5012 9029901 MISC.CONDUIT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,309.14 \$1,309.14 0001 5013 2022010 REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$933.61 \$933.61 0001 5014 6139901 MISC.CONCRETE FOR PAVEMENT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,442.70 \$1,442.70 0030 5015 9029901 MISC.SIGNAL PULL BOX ADJUSTMENT 0.00 1.00 1.00 LS 1.00 \$5,150.80			0001	5010	4019901		0.00	1.00	1.00	LS	1.00	\$70,765.66	\$70,765.66
0001 5012 9029901 MISC.CONDUIT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,309.14 \$1,309.14 0001 5013 2022010 REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$933.61 \$933.61 0001 5014 6139901 MISC.CONCRETE FOR PAVEMENT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,442.70 \$1,442.70 0030 5015 9029901 MISC.SIGNAL PULL BOX ADJUSTMENT 0.00 1.00 1.00 LS 1.00 \$5,150.80 \$5,150.80			0001	5011	6139901		0.00	1.00	1.00	LS	1.00	\$14,209.38	\$14,209.38
0001 5013 2022010 REMOVAL OF IMPROVEMENTS 0.00 1.00 1.00 LS 1.00 \$933.61 \$933.61 0001 5014 6139901 MISC.CONCRETE FOR PAVEMENT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,442.70 \$1,442.70 0030 5015 9029901 MISC.SIGNAL PULL BOX ADJUSTMENT 0.00 1.00 1.00 LS 1.00 \$5,150.80			0001	5012	9029901		0.00	1.00	1.00	LS	1.00	\$1,309.14	\$1,309.14
0001 5014 6139901 MISC.CONCRETE FOR PAVEMENT REPAIR 0.00 1.00 1.00 LS 1.00 \$1,442.70 \$1,442.70 0030 5015 9029901 MISC.SIGNAL PULL BOX ADJUSTMENT 0.00 1.00 1.00 LS 1.00 \$5,150.80 \$5,150.80				5013	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00		1.00		
0030 5015 9029901 MISC.SIGNAL PULL BOX ADJUSTMENT 0.00 1.00 1.00 LS 1.00 \$5,150.80 \$5,150.80				5014	6139901	MISC.CONCRETE FOR PAVEMENT REPAIR	0.00	1.00	1.00	LS	1.00	\$1,442.70	\$1,442.70
Project J4S3280 - Total Value Posted to Date as of Report Generated Date \$2,358,902.68				5015	9029901	MISC.SIGNAL PULL BOX ADJUSTMENT	0.00	1.00	1.00	LS	1.00	\$5,150.80	\$5,150.80
		Project J	4S3280 - To	tal Value	Posted to I	Date as of Report Generated Date							\$2,358,902.68

Page 7 of 62 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract .CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
218-C08	J4S3281	0001	0740	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$3,350.00	\$3,350.00
		0001	0750	2153000	SHAPING SLOPES, CLASS III	17.00	0.00	17.00	100F	17.00	\$675.00	\$11,475.00
		0001	0760	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,866.00	-172.00	1,694.00	TONS	1,694.00	\$74.44	\$126,101.36
		0001	0770	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	10,767.80	936.70	11,704.50	TONS	11,704.50	\$54.09	\$633,096.40
		0001	0780	4071005	TACK COAT	11,474.00	4,106.00	15,580.00	GAL	15,580.00	\$2.25	\$35,055.00
		0001	0790	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0800	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	152.00	155.00	307.00	SQYD	307.00	\$464.20	\$142,509.40
		0001	0810	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	15.00	-15.00	0.00	SQYD	0.00	\$1.00	\$0.00
		0001	0820	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	15.00	-15.00	0.00	SQYD	0.00	\$1.00	\$0.00
		0001	0830	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	600.00	650.00	1,250.00	LF	1,250.00	\$1.65	\$2,062.50
		0001	0840	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	340.00	48.00	388.00	EA	388.00	\$4.65	\$1,804.2
		0001	0850	6161005	CONSTRUCTION SIGNS	1,112.00	-314.00	798.00	SQFT	798.00	\$4.00	\$3,192.0
		0001	0860	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	-5.00	3.00	EA	3.00	\$35.00	\$105.00
		0001	0870	6161009	FLAG ASSEMBLY	8.00	-8.00	0.00	EA	0.00	\$35.00	\$0.0
		0001	0880	6161025	CHANNELIZER (TRIM LINE)	200.00	90.00	290.00	EA	290.00	\$20.00	\$5,800.0
		0001	0890	6161040	FLASHING ARROW PANEL	2.00	1.00	3.00	EA	3.00	\$1,500.00	\$4,500.0
		0001	0900	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$4,000.00	\$8,000.0
		0001	0910	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$127,790.00	\$127,790.0
		0001	0920	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	2,189.00	-1,352.00	837.00	LF	837.00	\$3.50	\$2,929.5
		0001	0930	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	844.00	68.00	912.00	LF	912.00	\$7.00	\$6,384.0
		0001	0940	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	144.00	340.00	484.00	LF	484.00	\$14.00	\$6,776.0
		0001	0950	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	39.00	0.00	39.00	EA	39.00	\$200.00	\$7,800.0
		0001	0960	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	34,777.00	5,367.00	40,144.00	LF	40,144.00	\$0.18	\$7,225.9
		0001	0970	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	39,336.00	-265.00	39,071.00	LF	39,071.00	\$0.18	\$7,032.7
		0001	0980	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	114,744.00	-998.00	113,746.00	SQYD	113,746.00	\$1.32	\$150,144.7
		0010	0990	6061010	GUARDRAIL TYPE A	250.00	0.00	250.00	LF	250.00	\$18.75	\$4,687.5
		0010	1000	6061060	MGS GUARDRAIL	962.00	0.00	962.00	LF	962.00	\$19.50	\$18,759.0
		0010	1010	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$2,450.00	\$9,800.0
		0010	1020	6061080	MGS END ANCHOR	2.00	2.00	4.00	EA	4.00	\$800.00	\$3,200.0
		0010	1030	6062200A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (ROADWAY AND REHABILITATION WORK ONLY)	6.00	0.00	6.00	EA	6.00	\$1,775.00	\$10,650.0
		0010	1040	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	6.00	0.00	6.00	EA	6.00	\$350.00	\$2,100.0
		0010	1050	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	-2.00	6.00	EA	6.00	\$2,350.00	\$14,100.0
		0010	1060	6063015	TYPE A CRASHWORTHY END TERMINAL	5.00	0.00	5.00	EA	5.00	\$2,450.00	\$12,250.0
		0030	1070	9028500	CABLE, LOOP DETECTOR, IN DUCT	3,640.00	2,660.00	6,300.00	LF	6,300.00	\$12.10	\$76,230.0
		0030	1080	9028510	CABLE, LOOP DETECTOR, LEAD-IN	290.00	-290.00	0.00	LF	0.00	\$3.60	\$0.0
		0001	5101	1099901	MISC.MOBILIZATION FOR FULL DEPTH PAVEMENT REPAIR	0.00	1.00	1.00	LS	1.00	\$3,412.50	\$3,412.5
		0001	5102	4019905	MISC.SHOULDER REPAIR	0.00	511.00	511.00	SQYD	511.00	\$113.00	\$57,743.0
		0001	5103	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	0.00	8,151.00	8,151.00	SQYD	8,151.00	\$1.98	\$16,138.9
		0001	5104	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	0.00	905.00	905.00	TONS	905.00	\$71.04	\$64,291.2
		0001	5105	4071005	TACK COAT	0.00	1,151.00	1,151.00	GAL	1,151.00	\$2.25	\$2,589.7
		0001	5106	6133020	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	0.00	11.00	11.00	TONS	11.00	\$278.39	\$3,062.2
		0001	5107	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	0.00	102.00	102.00	SQYD	102.00	\$154.12	\$15,720.2
		0001	5108	4030003	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP095C MIX)	0.00	152.00	152.00	TONS	152.00	\$213.03	\$32,380.5

Revision 4/1/2020 Page 8 of 62



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-C08	J4S3281	0001	5109	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	0.00	2,121.00	2,121.00	SQYD	2,121.00	\$8.33	\$17,667.93
		0001	5110	4071005	TACK COAT	0.00	338.00	338.00	GAL	338.00	\$2.25	\$760.50
		0001	5111	6169901	MISC.MIsc. Traffic Control	0.00	1.00	1.00	LS	1.00	\$2,751.00	\$2,751.00
		0001	5112	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	0.00	494.00	494.00	LF	494.00	\$10.00	\$4,940.00
	Project J	4S3281 - To	otal Value	e Posted to I	Date as of Report Generated Date							\$1,667,368.24
201218-C08 Ove	rall - Total	Value Pos	ted to Da	te as of Rep	ort Generated Date							\$4,026,270.91

Revision 4/1/2020 Page 9 of 62



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 10 of 62



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4S3280	0040	BIT. PAVEMENT MIXTURE	Other Item Adjustment	ACAD	7	Jul 2, 2021	tribid1	\$3,111.74	AC adjustment for BP-2 Mix ID: BP-2 20-19. 1016.94 TONS placed between 6/15/21 - 6/16/21.													
		PG70-22 (BP-2)		ACAD - Tota	al			\$3,111.74														
			Other Item /	Adjustment -	Total			\$3,111.74														
			Overrun	Overrun	7	Jul 1, 2021	SYSTEM	(\$5,878.45)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					18	Jan 3, 2022	SYSTEM	\$5,878.45	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',71.76718 - 69.41000, 'is applied (if non-zero).													
				Overrun - To	otal			\$0.00														
			Overrun - T	otal				\$0.00														
			Price FUEL		7	Jul 1, 2021	SYSTEM	\$2,397.06	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					18	Jan 3, 2022	SYSTEM	(\$0.03)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
				- Total				\$2,397.03														
			Price FUEL	- Total				\$2,397.03														
	0040 -	Total						\$5,508.77														
	0050	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	Material		6	Jun 15, 2021	SYSTEM	\$782,406.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					6	Jun 15, 2021	SYSTEM	(\$782,406.24)														
					7	Jul 1, 2021	SYSTEM	\$880,061.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
								7	Jul 1, 2021	SYSTEM	(\$880,061.32)											
					8	Jul 16, 2021	SYSTEM	\$880,061.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					8	Jul 16, 2021	SYSTEM	(\$880,061.32)														
					9	Aug 2, 2021	SYSTEM	\$883,457.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					9	Aug 2, 2021	SYSTEM	(\$883,457.92)														
																		10	Aug 16, 2021	SYSTEM	\$883,457.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$883,457.92)														
										11	Sep 2, 2021	SYSTEM	\$883,457.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					11	Sep 2, 2021	SYSTEM	(\$883,457.92)														
					12	Sep 16, 2021	SYSTEM	\$430,577.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.													
					12	Sep 16, 2021	SYSTEM	(\$430,577.92)														
							13	Oct 1, 2021	SYSTEM	\$434,185.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					13	Oct 1, 2021	SYSTEM	(\$434,185.68)														
										14	Nov 2, 2021	SYSTEM	\$434,185.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					14	Nov 2, 2021	SYSTEM	(\$434,185.68)														
					15	Nov 15,	SYSTEM	\$434,185.68	This adjustment offsets the original system-generated Material Payment													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J4S3280	0050	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	Material			2021			Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
		(,			15	Nov 15, 2021	SYSTEM	(\$434,185.68)											
					16	Dec 1, 2021	SYSTEM	\$434,185.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					16	Dec 1, 2021	SYSTEM	(\$434,185.68)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
			Other Item Adjustment	ACAD	4	May 18, 2021	tribid1	\$3,257.55	AC adjustment for SP095C Mix ID: SP0 95 21-15.1270 tons placed on 5/13/21.										
					5	Jun 2, 2021	tribid1	\$3,870.38	AC Adjustment for SP095C Mix ID: SP0 95 21-25. 1508.92 TONS placed between 5/24/21 through 6/1/21.										
					6	Jun 15, 2021	tribid1	\$35,665.88	AC adjustment for SP095C Mix ID:SP0 95 21-15 11042.07 TONS placed between 6/2/21 -6/10/21										
					17	Dec 16, 2021	hathak1	\$5,971.56	For SP095C placed on 6/14 and 6/15/21.										
				ACAD - Tota	al			\$48,765.37											
				FUEL	17	Dec 16, 2021	hathak1	(\$6.12)	For 123.73 tons of SP095C placed on 6/15/21. Tons were paid on 7/19/21 and 9/22/21 which made the fuel adjustment more than being paid accordingly on 6/15/21.										
				FUEL - Tota	ıl			(\$6.12)											
				OVRN	7	Jul 2, 2021	tribid1	(\$63,569.00)	Holding overrun until change order is complete.										
				Other Item		18	Jan 3, 2022	hathak1	\$63,569.00	Correction to adjustment made on 07/02/21 as an OVRN for fuel until change order was completed									
			Other Item	OVRN - Tota				\$0.00											
			Other Item A					\$48,759.25											
				Overrun		Jul 1, 2021	SYSTEM	(\$63,569.00)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					7	Jul 1, 2021	SYSTEM	\$63,569.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 78 on the current Payment Estimate. Material Insufficiency Quantity 15546.040; Overrun Quantity Balance 1078.04.										
										8	Jul 16, 2021	SYSTEM	(\$63,562.61)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35127' is applied (if non-zero).					
																	8	Jul 16, 2021	SYSTEM
					9	Aug 2, 2021	SYSTEM	(\$63,562.61)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35127' is applied (if non-zero).										
					9	Aug 2, 2021	SYSTEM	(\$3,542.02)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
															9	Aug 2, 2021	SYSTEM	\$3,542.02	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 70 on the current Payment Estimate. Material Insufficiency Quantity 15606.040; Overrun Quantity Balance 1138.04.
														9	Aug 2, 2021	SYSTEM	\$63,562.61	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 70 on the current Payment Estimate. Material Insufficiency Quantity 15606.040; Overrun Quantity Balance 1138.04.	
					10	Aug 16, 2021	SYSTEM	(\$67,100.59)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35154' is applied (if non-zero).										
				1	10	Aug 16, 2021	SYSTEM	\$67,100.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 81 on the current Payment Estimate. Material Insufficiency Quantity 15606.040; Overrun Quantity Balance 1138.04.										
					11	Sep 2, 2021	SYSTEM	(\$67,100.59)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35154' is applied (if non-zero).										
					11	Sep 2, 2021	tribid1	(\$64,424.44)	Holding overrun until Change Order is complete.										
					11	Sep 2,	SYSTEM	\$67,100.59	This adjustment offsets the original system-generated Overrun Payment										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4S3280	0050	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	Overrun	Overrun		2021			Estimate Item Adjustment (0006) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 15606.040; Overrun Quantity Balance 1138.04.			
					12	Sep 16, 2021	SYSTEM	(\$67,100.59)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35154' is applied (if non-zero).			
					12	Sep 16, 2021	SYSTEM	\$67,100.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 7606.040; Overrun Quantity Balance 1138.04.			
					13	Oct 1, 2021	SYSTEM	(\$67,100.59)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35154' is applied (if non-zero).			
					13	Oct 1, 2021	warrem1	(\$68,032.20)	Holding overrun until Change Order is complete.			
					13	Oct 1, 2021	SYSTEM	(\$3,760.10)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					13	Oct 1, 2021	warrem1	\$64,424.44	Returning overrun money.			
					13	Oct 1, 2021	SYSTEM	\$3,760.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 23 on the current Payment Estimate. Material Insufficiency Quantity 7669.770; Overrun Quantity Balance 1201.77.			
					13	Oct 1, 2021	SYSTEM	\$67,100.59	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 23 on the current Payment Estimate. Material Insufficiency Quantity 7669.770; Overrun Quantity Balance 1201.77.			
					14	Nov 2, 2021	SYSTEM	(\$70,858.40)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35170' is applied (if non-zero).			
					14	Nov 2, 2021	SYSTEM	\$70,858.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 10 on the current Payment Estimate. Material Insufficiency Quantity 7669.770; Overrun Quantity Balance 1201.77.			
					15	Nov 15, 2021	SYSTEM	(\$70,858.40)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35170' is applied (if non-zero).			
					15	Nov 15, 2021	SYSTEM	\$70,858.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 7669.770; Overrun Quantity Balance 1201.77.			
					16	Dec 1, 2021	SYSTEM	(\$70,858.40)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35170' is applied (if non-zero).			
					16	Dec 1, 2021	SYSTEM	\$70,858.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 7669.770; Overrun Quantity Balance 1201.77.			
					17	Dec 15, 2021	SYSTEM	(\$70,858.40)	Averaged Price Adjustment from this item on all previous payment estimates of '2.35170' is applied (if non-zero).			
					17	Dec 15, 2021	SYSTEM	\$70,858.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					18	Jan 3, 2022	hathak1	\$68,032.20	Correction to adjustment made on 10/01/21, The adjustment was originally made due to a pending change order.			
				Overrun - T	otal			\$0.00				
			Overrun - T	otal				\$0.00				
			Price FUEL		4	May 17, 2021	SYSTEM	\$2,951.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					5	Jun 2, 2021	SYSTEM	\$3,506.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					6	Jun 15, 2021	SYSTEM	\$26,028.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
						7	Jul 1, 2021	SYSTEM	\$4,066.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
									9	Aug 2, 2021	SYSTEM	\$145.42
					13	Oct 1, 2021	SYSTEM	\$152.34	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					18	Jan 3, 2022	SYSTEM	\$0.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$36,850.74				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4S3280	0050	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	Price FUEL	- Total				\$36,850.74													
	0050 -	Total						\$85,609.99													
	0060	MISC. NON STANDARD TACK COAT	Material		5	Jun 2, 2021	SYSTEM	\$6,230.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0150) due to user tribid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.												
					5	Jun 2, 2021	SYSTEM	(\$6,230.25)													
					6	Jun 15, 2021	SYSTEM	\$53,295.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					6	Jun 15, 2021	SYSTEM	(\$53,295.75)													
					7	Jul 1, 2021	SYSTEM	\$63,328.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
					7	Jul 1, 2021	SYSTEM	(\$63,328.50)													
								8	Jul 16, 2021	SYSTEM	\$63,328.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
								8	Jul 16, 2021	SYSTEM	(\$63,328.50)										
														9	Aug 2, 2021	SYSTEM	\$68,550.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
																	9	Aug 2, 2021	SYSTEM	(\$68,550.75)	
								10	Aug 16, 2021	SYSTEM	\$68,550.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
					10	Aug 16, 2021	SYSTEM	(\$68,550.75)													
				- Total				\$0.00													
			Material - To Other Item Adjustment					\$0.00													
			Other Item Adjustment	OVRN		Jun 15, 2021	karlic1	(\$19,174.50)	Holding overrun until change order is complete.												
					9	Aug 3, 2021	karlic1	(\$34,429.50)	Holding overrun amount until change order is complete through Est 9												
							9	Aug 3, 2021	karlic1	\$19,174.50	Removing overrun adjustment entered on Est 6										
					11	Sep 3, 2021	tribid1	\$34,429.50	Holding overrun until Change Order is complete.												
				OVRN - Tot				\$0.00													
				Adjustment -				\$0.00													
						Overrun Overrun			Overrun	Overrun	Overrun	Overrun	Overrun	Overrun Over	Overrui	Overrun	6	Jun 15, 2021	SYSTEM	\$4,664.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0033) overridding Payment Estimate Exception 51 on the current Payment Estimate. Material Insufficiency Quantity 23687.000; Overrun Quantity Balance 8522.00.
									6	Jun 15, 2021	SYSTEM	\$5,422.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0034) overridding Payment Estimate Exception 51 on the current Payment Estimate. Material Insufficiency Quantity 23687.000; Overrun Quantity Balance 8522.00.								
											6	Jun 15, 2021	SYSTEM	\$7,375.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0035) overridding Payment Estimate Exception 51 on the current Payment Estimate. Material Insufficiency Quantity 23687.000; Overrun Quantity Balance 8522.00.						
												6	Jun 15, 2021	SYSTEM	\$1,712.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 51 on the current Payment Estimate. Material Insufficiency Quantity 23687.000; Overrun Quantity Balance 8522.00.					
					6	Jun 15, 2021	SYSTEM	(\$19,174.50)													
				7	Jul 1, 2021	SYSTEM	(\$19,174.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3280	0060	MISC. NON STANDARD TACK COAT	Overrun	Overrun	7	Jul 1, 2021	SYSTEM	\$7,049.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0042) overridding Payment Estimate Exception 89 on the current Payment Estimate. Material Insufficiency Quantity 28146.000; Overrun Quantity Balance 12981.00.
					7	Jul 1, 2021	SYSTEM	\$1,356.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 89 on the current Payment Estimate. Material Insufficiency Quantity 28146.000; Overrun Quantity Balance 12981.00.
					7	Jul 1, 2021	SYSTEM	\$1,626.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 89 on the current Payment Estimate. Material Insufficiency Quantity 28146.000; Overrun Quantity Balance 12981.00.
					7	Jul 1, 2021	SYSTEM	\$19,174.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0045) overridding Payment Estimate Exception 89 on the current Payment Estimate. Material Insufficiency Quantity 28146.000; Overrun Quantity Balance 12981.00.
					7	Jul 1, 2021	SYSTEM	(\$10,032.75)	
					8	Jul 16, 2021	SYSTEM	(\$29,207.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Jul 16, 2021	SYSTEM	\$29,207.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 84 on the current Payment Estimate. Material Insufficiency Quantity 28146.000; Overrun Quantity Balance 12981.00.
					9	Aug 2, 2021	SYSTEM	(\$29,207.25)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Aug 2, 2021	SYSTEM	\$5,222.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0031) overridding Payment Estimate Exception 79 on the current Payment Estimate. Material Insufficiency Quantity 30467.000; Overrun Quantity Balance 15302.00.
					9	Aug 2, 2021	SYSTEM	\$29,207.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) overridding Payment Estimate Exception 79 on the current Payment Estimate. Material Insufficiency Quantity 30467.000; Overrun Quantity Balance 15302.00.
					9	Aug 2, 2021	SYSTEM	(\$5,222.25)	
					10	Aug 16, 2021	SYSTEM	(\$34,429.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Aug 16, 2021	SYSTEM	\$34,429.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 82 on the current Payment Estimate. Material Insufficiency Quantity 30467.000; Overrun Quantity Balance 15302.00.
					11	Sep 2, 2021	SYSTEM	(\$34,429.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					18	Jan 3, 2022	SYSTEM	\$34,429.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.25000 - 2.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
	0060 -	Total	Overrun - T	otal				\$0.00 \$0.00	
	0070	PIPE COLLAR, TYPE A	Material		3	May 3, 2021	SYSTEM	\$1,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$1,610.00)	
					4	May 17, 2021	SYSTEM	\$1,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user tribid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$1,610.00)	
					5	Jun 2, 2021	SYSTEM	\$1,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0151) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$1,610.00)	
					6	Jun 15, 2021	SYSTEM	\$1,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user tribid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J4S3280	0070	PIPE COLLAR, TYPE A	Material		6	Jun 15, 2021	SYSTEM	(\$1,610.00)					
					7	Jul 1, 2021	SYSTEM	\$1,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user tribid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					7	Jul 1, 2021	SYSTEM	(\$1,610.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0070 -	Total						\$0.00					
	0800	CONCRETE CURB RAMP	Material		7	Jul 1, 2021	SYSTEM	\$16,266.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user tribid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.				
					7	Jul 1, 2021	SYSTEM	(\$16,266.90)					
					8	Jul 16, 2021	SYSTEM	\$16,266.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user tribid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.				
					8	Jul 16, 2021	SYSTEM	(\$16,266.90)					
					9	Aug 2, 2021	SYSTEM	\$16,266.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user hathak1 overridding Payment Estimate Exception 25 on the current Payment Estimate.				
					9	Aug 2, 2021	SYSTEM	(\$16,266.90)					
				10	Aug 16, 2021	SYSTEM	\$20,428.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.					
									10	Aug 16, 2021	SYSTEM	(\$20,428.20)	
											- Total		
			Material - Tot	- Total				\$0.00					
	0080 -								\$0.00				
	0090	TRUNCATED DOMES	Material		7	Jul 1, 2021	SYSTEM	\$2,259.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user tribid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.				
					7	Jul 1, 2021	SYSTEM	(\$2,259.40)					
				- Total									
								\$0.00					
			Material - To					\$0.00 \$0.00					
	0090 -		Material - To										
	0100	CONCRETE			7	Jul 1, 2021	SYSTEM	\$0.00 \$0.00 \$7,993.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid 1 overridding Payment Estimate Exception 32 on the current Payment Estimate.				
		CONCRETE			7		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0050) due to user tribid1 overridding Payment				
		CONCRETE				2021 Jul 1,		\$0.00 \$0.00 \$7,993.10	Estimate Item Adjustment (0050) due to user tribid1 overridding Payment				
		CONCRETE			7	Jul 1, 2021 Jul 16,	SYSTEM	\$0.00 \$0.00 \$7,993.10 (\$7,993.10)	Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user tribid1 overridding Payment				
		CONCRETE			7	Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM	\$0.00 \$0.00 \$7,993.10 (\$7,993.10) \$7,993.10	Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user tribid1 overridding Payment				
		CONCRETE			7 8	Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM	\$0.00 \$0.00 \$7,993.10 (\$7,993.10) \$7,993.10	Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user tribid1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hathak1 overridding Payment				
		CONCRETE			7 8 8 9	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$7,993.10 (\$7,993.10) \$7,993.10 (\$7,993.10)	Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user tribid1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hathak1 overridding Payment				
		CONCRETE			7 8 8 9	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$7,993.10 (\$7,993.10) \$7,993.10 (\$7,993.10) (\$7,993.10)	Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user tribid1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hathak1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user tribid1 overridding Payment Estimate Item Adjustment (0039) due to user tribid1 overridding Payment				
		CONCRETE			7 8 8 9 9	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$7,993.10 (\$7,993.10) \$7,993.10 (\$7,993.10) (\$7,993.10) \$7,993.10	Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user tribid1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user hathak1 overridding Payment Estimate Exception 30 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user tribid1 overridding Payment Estimate Item Adjustment (0039) due to user tribid1 overridding Payment				



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3280	0100 -	Total						\$0.00	
	0110	CURB AND GUTTER TYPE B	Material		7	Jul 1, 2021	SYSTEM	\$7,761.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user tribid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$7,761.40)	
					8	Jul 16, 2021	SYSTEM	\$7,761.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user tribid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$7,761.40)	
					9	Aug 2, 2021	SYSTEM	\$7,761.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user hathak1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$7,761.40)	
					10	Aug 16, 2021	SYSTEM	\$7,761.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user tribid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$7,761.40)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OVRN	7	Jul 2, 2021	tribid1	(\$2,158.00)	Holding overrun until change order is complete.
					11	Sep 3, 2021	tribid1	\$2,158.00	Holding overrun until Change Order is complete.
				OVRN - Tota	al			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
			Overrun	Overrun	7	Jul 1, 2021	SYSTEM	\$2,158.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0051) overridding Payment Estimate Exception 90 on the current Payment Estimate. Material Insufficiency Quantity 151.000; Overrun Quantity Balance 42.00.
					7	Jul 1, 2021	SYSTEM	(\$2,158.80)	
					8	Jul 16, 2021	SYSTEM	(\$2,158.80)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Jul 16, 2021	SYSTEM	\$2,158.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 85 on the current Payment Estimate. Material Insufficiency Quantity 151.000; Overrun Quantity Balance 42.00.
					9	Aug 2, 2021	SYSTEM	(\$2,158.80)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Aug 2, 2021	SYSTEM	\$2,158.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 80 on the current Payment Estimate. Material Insufficiency Quantity 151.000; Overrun Quantity Balance 42.00.
					10	Aug 16, 2021	SYSTEM	(\$2,158.80)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Aug 16, 2021	SYSTEM	\$2,158.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 83 on the current Payment Estimate. Material Insufficiency Quantity 151.000; Overrun Quantity Balance 42.00.
					11	Sep 2, 2021	SYSTEM	(\$2,158.80)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					18	Jan 3, 2022	SYSTEM	\$2,158.80	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',51.40000 - 51.40000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0110 -	Total						\$0.00	
	0130	MISC. PAVED DRAINAGE	Material		3	May 3, 2021	SYSTEM	\$1,312.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user tribid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	May 3,	SYSTEM	(\$1,312.80)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J4S3280	0130	MISC. PAVED	Material			2021																		
		DRAINAGE			4	May 17, 2021	SYSTEM	\$1,312.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.															
					4	May 17, 2021	SYSTEM	(\$1,312.80)																
					5	Jun 2, 2021	SYSTEM	\$1,312.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0132) due to user tribid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.															
					5	Jun 2, 2021	SYSTEM	(\$1,312.80)																
					6	Jun 15, 2021	SYSTEM	\$1,312.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user tribid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
					6	Jun 15, 2021	SYSTEM	(\$1,312.80)																
					7	Jul 1, 2021	SYSTEM	\$1,312.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user tribid 1 overridding Payment Estimate Exception 42 on the current Payment Estimate.															
					7	Jul 1, 2021	SYSTEM	(\$1,312.80)																
					8	Jul 16, 2021	SYSTEM	\$1,312.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user tribid1 overridding Payment Estimate Exception 40 on the current Payment Estimate.															
					8	Jul 16, 2021	SYSTEM	(\$1,312.80)																
					9	Aug 2, 2021	SYSTEM	\$1,312.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user hathak1 overridding Payment Estimate Exception 40 on the current Payment Estimate.															
									9	Aug 2, 2021	SYSTEM	(\$1,312.80)												
					10	Aug 16, 2021	SYSTEM	\$1,312.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user tribid1 overridding Payment Estimate Exception 41 on the current Payment Estimate.															
					10	Aug 16, 2021	SYSTEM	(\$1,312.80)																
				- Total				\$0.00																
			Material - To					\$0.00																
			Overrun	Overrun	3	May 3, 2021	SYSTEM	\$164.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 16.000; Overrun Quantity Balance 2.00.															
							3	May 3, 2021	tribid1	\$164.10	This will be removed when the materials exceptions are resolved.													
											3	May 3, 2021	SYSTEM	(\$164.10)										
					4	May 17, 2021	SYSTEM	(\$164.10)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
			4 5 5 6 6	4 5 5								4	May 17, 2021	SYSTEM	\$164.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0055) overridding Payment Estimate Exception 37 on the current Payment Estimate. Material Insufficiency Quantity 16.000; Overrun Quantity Balance 2.00.								
						4	May 17, 2021	tribid1	(\$328.20)	This will be removed once the material exception has been resolved.														
					5	5		-	5	Jun 2, 2021	SYSTEM	(\$164.10)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).											
															5					5	Jun 2, 2021	SYSTEM	\$164.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0131) overridding Payment Estimate Exception 51 on the current Payment Estimate. Material Insufficiency Quantity 16.000; Overrun Quantity Balance 2.00.
															6	Jun 15, 2021	SYSTEM	(\$164.10)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).					
						6	Jun 15, 2021	SYSTEM	\$164.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) overridding Payment Estimate Exception 52 on the current Payment Estimate. Material Insufficiency Quantity 16.000; Overrun Quantity Balance 2.00.														
					7	Jul 1,	SYSTEM	(\$164.10)	Averaged Price Adjustment from this item on all previous payment estimates															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4S3280	0130	MISC. PAVED	Overrun	Overrun		2021			of '0.00000' is applied (if non-zero).													
		DRAINAGE			7	Jul 1, 2021	SYSTEM	\$164.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0053) overridding Payment Estimate Exception 91 on the current Payment Estimate. Material Insufficiency Quantity 16.000; Overrun Quantity Balance 2.00.													
					8	Jul 16, 2021	SYSTEM	(\$164.10)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
					8	Jul 16, 2021	SYSTEM	\$164.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) overridding Payment Estimate Exception 86 on the current Payment Estimate. Material Insufficiency Quantity 16.000; Overrun Quantity Balance 2.00.													
					9	Aug 2, 2021	SYSTEM	(\$164.10)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
					9	Aug 2, 2021	SYSTEM	\$164.10	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) overridding Payment Estimate Exception 81 on the current Payment Estimate. Material Insufficiency Quantity 16.000; Overrun Quantity Balance 2.00.													
					10	Aug 17, 2021	tribid1	\$164.10	Removing overrun adjustment.													
				Overrun - T	otal			\$0.00														
			Overrun - T	otal				\$0.00														
	0130 -	Total						\$0.00														
	0150	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		2	Apr 16, 2021	SYSTEM	\$40,398.27	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user tribid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.													
											2	Apr 16, 2021	SYSTEM	(\$40,398.27)								
							3	May 3, 2021	SYSTEM	\$144,237.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user tribid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.											
										3	May 3, 2021	SYSTEM	(\$144,237.88)									
					4	May 17, 2021	SYSTEM	\$144,237.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user tribid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.													
					4	May 17, 2021	SYSTEM	(\$144,237.88)														
					5	Jun 2, 2021	SYSTEM	\$144,237.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0152) due to user tribid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.													
							5	Jun 2, 2021	SYSTEM	(\$144,237.88)												
															6	Jun 15, 2021	SYSTEM	\$144,237.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user tribid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
					6	Jun 15, 2021	SYSTEM	(\$144,237.88)														
						7	Jul 1, 2021	SYSTEM	\$144,237.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 50 on the current Payment Estimate.												
					7	Jul 1, 2021	SYSTEM	(\$144,237.88)														
				9				8	Jul 16, 2021	SYSTEM	\$144,237.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user tribid1 overridding Payment Estimate Exception 48 on the current Payment Estimate.										
					8	Jul 16, 2021	SYSTEM	(\$144,237.88)														
								9										9	Aug 2, 2021	SYSTEM	\$158,728.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user hathak1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
												9	Aug 2, 2021	SYSTEM	(\$158,728.68)							
															10	Aug 16, 2021	SYSTEM	\$158,728.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user tribid1 overridding Payment Estimate Exception 49 on the current Payment Estimate.			
					10	Aug 16, 2021	SYSTEM	(\$158,728.68)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J4S3280	0150	FURN & PLACE CONC MATL FOR	Material	- Total				\$0.00								
		FULL DEPTH	Material - T	otal				\$0.00								
	0150 -	Total						\$0.00								
	0190	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		2	Apr 16, 2021	SYSTEM	\$1,450.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user tribid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
		INST			2	Apr 16, 2021	SYSTEM	(\$1,450.80)								
					3	May 3, 2021	SYSTEM	\$5,003.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user tribid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					3	May 3, 2021	SYSTEM	(\$5,003.40)								
					4	May 17, 2021	SYSTEM	\$5,003.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user tribid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					4	May 17, 2021	SYSTEM	(\$5,003.40)								
					5	Jun 2, 2021	SYSTEM	\$5,003.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0153) due to user tribid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.							
					5	Jun 2, 2021	SYSTEM	(\$5,003.40)								
					6	Jun 15, 2021	SYSTEM	\$5,003.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user tribid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.							
					6	Jun 15, 2021	SYSTEM	(\$5,003.40)								
											7	Jul 1, 2021	SYSTEM	\$5,003.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user tribid1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	
					7	Jul 1, 2021	SYSTEM	(\$5,003.40)								
					8	Jul 16, 2021	SYSTEM	\$5,003.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user tribid1 overridding Payment Estimate Exception 53 on the current Payment Estimate.							
					8	Jul 16, 2021	SYSTEM	(\$5,003.40)								
					9	Aug 2, 2021	SYSTEM	\$5,180.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user hathak1 overridding Payment Estimate Exception 53 on the current Payment Estimate.							
					9	Aug 2, 2021	SYSTEM	(\$5,180.10)								
						1						10	Aug 16, 2021	SYSTEM	\$5,180.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user tribid1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
							10	Aug 16, 2021	SYSTEM	(\$5,180.10)						
				- Total				\$0.00								
	0400	Total	Material - T	otal				\$0.00								
	0190 -	MANHOLE FRAME AND COVER, TYPE 3	Material		4	May 17, 2021	SYSTEM	\$0.00 \$258.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user tribid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.							
		OOVLIN, HIFE 3			4	May 17, 2021	SYSTEM	(\$258.00)	Estimate Exception 15 on the current rayment Estimate.							
					5	Jun 2, 2021	SYSTEM	\$258.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0154) due to user tribid1 overridding Payment Estimate Exception 31 on the current Payment Estimate.							
					5	Jun 2, 2021	SYSTEM	(\$258.00)								
					6	Jun 15, 2021	SYSTEM	\$1,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user tribid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.							
					6	Jun 15,	SYSTEM	(\$1,032.00)								



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3280	0200	MANHOLE FRAME AND	Material			2021			
		COVER, TYPE 3			7	Jul 1, 2021	SYSTEM	\$1,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user tribid1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$1,032.00)	
					8	Jul 16, 2021	SYSTEM	\$1,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user tribid1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$1,032.00)	
					9	Aug 2, 2021	SYSTEM	\$1,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user hathak1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$1,032.00)	
					10	Aug 16, 2021	SYSTEM	\$1,032.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$1,032.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
J	0200 -	Total						\$0.00	
	0230	CONSTRUCTION SIGNS	Material		1	Apr 5, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user wilsor2 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					1	Apr 5, 2021	SYSTEM	(\$3,000.00)	
					2	Apr 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user tribid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					2	Apr 16, 2021	SYSTEM	(\$3,000.00)	
					3	May 3, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user tribid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$3,000.00)	
					4	May 17, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user tribid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$3,000.00)	
					5	Jun 2, 2021	SYSTEM	\$3,283.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0155) due to user tribid1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$3,283.72)	
					6	Jun 15, 2021	SYSTEM	\$3,283.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user tribid1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					6	Jun 15, 2021	SYSTEM	(\$3,283.72)	
					7	Jul 1, 2021	SYSTEM	\$3,283.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user tribid1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$3,283.72)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0230 -	Total						\$0.00	
	0240	ADVANCED WARNING RAIL SYSTEM	Material		1	Apr 5, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wilsor2 overridding Payment Estimate Exception 9 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3280	0240	ADVANCED WARNING RAIL	Material		1	Apr 5, 2021	SYSTEM	(\$70.00)	
		SYSTEM			2	Apr 16, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user tribid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					2	Apr 16, 2021	SYSTEM	(\$70.00)	
					3	May 3, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user tribid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$70.00)	
					4	May 17, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user tribid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$70.00)	
					5	Jun 2, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0156) due to user tribid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$70.00)	
					6	Jun 15, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user tribid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					6	Jun 15, 2021	SYSTEM	(\$70.00)	
					7	Jul 1, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user tribid1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$70.00)	
					8	Jul 16, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user tribid1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$70.00)	
					9	Aug 2, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user hathak1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$70.00)	
					10	Aug 16, 2021	SYSTEM	\$70.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user tribid1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$70.00)	
				- Total				\$0.00	
	0240 -	Total	Material - To	otal				\$0.00 \$0.00	
	0260	CHANNELIZER (TRIM LINE)	Material		3	May 3, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user tribid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$4,000.00)	·
					4	May 17, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user tribid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$4,000.00)	
					5	Jun 2, 2021	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0135) due to user tribid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$4,800.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J4S3280	0260	CHANNELIZER	Material - To	otal				\$0.00							
		(TRIM LINE)	Other Item Adjustment	OVRN	5	Jun 2, 2021	karlic1	(\$800.00)	Holding Overrun amount until a change order is processed.						
					6	Jun 15, 2021	karlic1	\$800.00	Removing manually enter overrun exception.						
				OVRN - Tota	al			\$0.00							
			Other Item	Adjustment -	Total			\$0.00							
			Overrun	Overrun	5	Jun 2, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0134) overridding Payment Estimate Exception 52 on the current Payment Estimate. Material Insufficiency Quantity 240.000; Overrun Quantity Balance 40.00.						
					5	Jun 2, 2021	SYSTEM	(\$800.00)							
					6	Jun 15, 2021	SYSTEM	(\$800.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
					10	Aug 16, 2021	SYSTEM	(\$2,000.00)							
					18	Jan 3, 2022	SYSTEM	\$2,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).						
				Overrun - Total				\$0.00							
			Overrun - T	otal				\$0.00							
	0260 -	Total						\$0.00							
	0270	TYPE III MOVEABLE BARRICADE	Material		5	Jun 2, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0138) due to user tribid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.						
					5	Jun 2, 2021	SYSTEM	(\$450.00)							
				- Total				\$0.00							
				Material - Total					\$0.00						
			Other Item Adjustment	OVRN	5	Jun 2, 2021	karlic1	(\$270.00)	Holding Overrun amount until a change order is processed.						
			Adjustment		6	Jun 15, 2021	karlic1	\$270.00	Removing manually entered overrun exception						
				OVRN - Tota				\$0.00							
			Other Item	Adjustment -	Total			\$0.00							
			Overrun	Overrun	5	Jun 2, 2021	SYSTEM	\$270.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0137) overridding Payment Estimate Exception 53 on the current Payment Estimate. Material Insufficiency Quantity 5.000; Overrun Quantity Balance 3.00.						
					5	Jun 2, 2021	SYSTEM	(\$270.00)							
					6	Jun 15, 2021	SYSTEM	(\$270.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
					18	Jan 3, 2022	SYSTEM	\$270.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',90.00000 - 90.00000, 'is applied (if non-zero).						
				Overrun - To	otal			\$0.00							
			Overrun - T	otal				\$0.00							
	0270 -	Total						\$0.00							
	0280	FLASHING ARROW PANEL	Material		3	May 3, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user tribid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.						
					3	May 3, 2021	SYSTEM	(\$3,000.00)							
					4	4					4	May 17, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user tribid1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$3,000.00)							
					5	Jun 2, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0157) due to user tribid1 overridding Payment Estimate Exception 40 on the current Payment Estimate.						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J4S3280	0280	FLASHING ARROW PANEL	Material		5	Jun 2, 2021	SYSTEM	(\$3,000.00)											
					6	Jun 15, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user tribid1 overridding Payment Estimate Exception 38 on the current Payment Estimate.										
					6	Jun 15, 2021	SYSTEM	(\$3,000.00)											
					7	Jul 1, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user tribid1 overridding Payment Estimate Exception 62 on the current Payment Estimate.										
					7	Jul 1, 2021	SYSTEM	(\$3,000.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	0280 -	Total						\$0.00											
	0300	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		3	May 3, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user tribid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.										
		OONTTY			3	May 3, 2021	SYSTEM	(\$8,000.00)											
					4	May 17, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user tribid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.										
					4	May 17, 2021	SYSTEM	(\$8,000.00)											
					5	Jun 2, 2021	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0158) due to user karlic1 overridding Payment Estimate Exception 42 on the current Payment Estimate.										
															5	Jun 2, 2021	SYSTEM	(\$16,000.00)	
					6	Jun 15, 2021	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user tribid1 overridding Payment Estimate Exception 40 on the current Payment Estimate.										
					6	Jun 15, 2021	SYSTEM	(\$16,000.00)											
										7	Jul 1, 2021	SYSTEM	\$16,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user tribid1 overridding Payment Estimate Exception 64 on the current Payment Estimate.					
					7	Jul 1, 2021	SYSTEM	(\$16,000.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	0300 -	Total						\$0.00											
	0330	PREF THERMO PVMT MARK, 24 IN WHIT		Material	Material	Material	Material		7	Jul 1, 2021	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user tribid1 overridding Payment Estimate Exception 68 on the current Payment Estimate.						
							7	Jul 1, 2021	SYSTEM	(\$3,300.00)									
										8	8	Jul 16, 2021	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 59 on the current Payment Estimate.				
							8	8	Jul 16, 2021	SYSTEM	(\$3,300.00)								
												9	9	Aug 2, 2021	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user hathak1 overridding Payment Estimate Exception 59 on the current Payment Estimate.		
				9	Aug 2, 2021	SYSTEM	(\$3,300.00)												
						10	Aug 16, 2021	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user tribid1 overridding Payment Estimate Exception 60 on the current Payment Estimate.									
					10	Aug 16, 2021	SYSTEM	(\$3,300.00)											
				- Total				\$0.00											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J4S3280	0330	PREF THERMO PVMT MARK, 24 IN WHIT	Material - To	otal				\$0.00											
	0330 -	Total						\$0.00											
	0340	PREF THERMO PVMT MARK, 24	Overrun	Overrun	11	Sep 2, 2021	SYSTEM	(\$1,720.00)											
		IN YELLOW			18	Jan 3, 2022	SYSTEM	\$1,720.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).										
				Overrun - T	otal			\$0.00											
			Overrun - T	otal				\$0.00											
	0340 -	Total						\$0.00											
	0350	PREF THERMO PVMT MARK, LT/RT ARROW	Material		10	Aug 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user tribid1 overridding Payment Estimate Exception 62 on the current Payment Estimate.										
					10	Aug 16, 2021	SYSTEM	(\$9,000.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	0350 -	Total						\$0.00											
	0370	PREF THERMO PVMT MARK, 30" WHT MIDBL	Material		7	Jul 1, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate.										
					7	Jul 1, 2021	SYSTEM	(\$990.00)											
					8	Jul 16, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user tribid1 overridding Payment Estimate Exception 61 on the current Payment Estimate.										
															8	Jul 16, 2021	SYSTEM	(\$990.00)	
					9	Aug 2, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user hathak1 overridding Payment Estimate Exception 61 on the current Payment Estimate.										
					9	Aug 2, 2021	SYSTEM	(\$990.00)											
							10	Aug 16, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user tribid1 overridding Payment Estimate Exception 63 on the current Payment Estimate.								
					10	Aug 16, 2021	SYSTEM	(\$990.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	0370 -	Total						\$0.00											
	0380	4 IN. WHITE WATERBORNE	Other Item Adjustment	REFL	18	Jan 3, 2022	hathak1	\$604.37	White pavement marking adjustment for 61,652 LF.										
		PAVEMENT MARKING		REFL - Tota	ıl			\$604.37											
			Other Item	Adjustment -	Total			\$604.37											
			Overrun	Overrun	11	Sep 2, 2021	SYSTEM	(\$1,172.80)											
					18	Jan 3, 2022	SYSTEM	\$1,172.80	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.20000 - 0.20000, 'is applied (if non-zero).										
				Overrun - T	otal			\$0.00											
			Overrun - T	otal				\$0.00											
	0380 -	Total																	
	0390	4 IN. YELLOW WATERBORNE PAVEMENT	Other Item Adjustment	REFL	18	Jan 3, 2022	hathak1	\$479.09	Yellow pavement marking adjustment for 49,457 LF.										
		MARKING		REFL - Tota	ıl			\$479.09											
			Other Item /	Adjustment -	Total			\$479.09											
	0390 -	Total						\$479.09											
	0440	PRECAST	Material		4	May 17,	SYSTEM	\$9,675.00	This adjustment offsets the original system-generated Material Payment										



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J4S3280	0440	CONCRETE DROP INLET 5 FT	Material			2021			Estimate Item Adjustment (0069) due to user tribid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
		X3FT			4	May 17, 2021	SYSTEM	(\$9,675.00)	
					5	Jun 2, 2021	SYSTEM	\$38,162.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0159) due to user karlic1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$38,162.50)	
					6	Jun 15, 2021	SYSTEM	\$41,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user tribid 1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					6	Jun 15, 2021	SYSTEM	(\$41,925.00)	
					7	Jul 1, 2021	SYSTEM	\$41,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user tribid 1 overridding Payment Estimate Exception 75 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$41,925.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0440 -	Total						\$0.00	
	0450	MISC. MANHOLES AND DROP INLETS	Material		23	Apr 22, 2022	SYSTEM	\$4,806.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					23	Apr 22, 2022	SYSTEM	(\$4,806.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0450 -	Total						\$0.00	
	0480	SILT FENCE	Material		14	Nov 2, 2021	SYSTEM	\$2,007.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$2,007.00)	
					15	Nov 15, 2021	SYSTEM	\$2,007.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					15	Nov 15, 2021	SYSTEM	(\$2,007.00)	
					16	Dec 1, 2021	SYSTEM	\$2,007.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					16	Dec 1, 2021	SYSTEM	(\$2,007.00)	
					17	Dec 15, 2021	SYSTEM	\$2,007.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Dec 15, 2021	SYSTEM	(\$2,007.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0480 -	Total						\$0.00	
	0490	GUARDRAIL TYPE A	Material		7	Jul 1, 2021	SYSTEM	\$41,718.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user tribid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$41,718.75)	
					8	Jul 16, 2021	SYSTEM	\$41,718.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user tribid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$41,718.75)	
					9	Aug 2,	SYSTEM	\$41,718.75	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3280	0490	GUARDRAIL TYPE A	Material			2021			Estimate Item Adjustment (0046) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$41,718.75)	
					10	Aug 16, 2021	SYSTEM	\$41,718.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user tribid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$41,718.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0490 -	· Total						\$0.00	
	0500	MGS GUARDRAIL	Material		7	Jul 1, 2021	SYSTEM	\$10,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user tribid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$10,725.00)	
					8	Jul 16, 2021	SYSTEM	\$10,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user tribid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$10,725.00)	
					9	Aug 2, 2021	SYSTEM	\$10,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user hathal overridding Payment Estimate Exception 12 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$10,725.00)	
					10	Aug 16, 2021	SYSTEM	\$10,725.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user tribid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$10,725.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	OVRN	7	Jul 2, 2021	tribid1	(\$3,900.00)	Holding overrun until change order is complete.
					11	Sep 3,			
						2021	tribid1	\$3,900.00	
				OVRN - Tota	al	2021	tribid1	\$3,900.00 \$0.00	
			Other Item	OVRN - Tota Adjustment -		2021	tribid1		
			Other Item A		Total	Jul 1, 2021	system	\$0.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0066) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00.
				Adjustment -	Total	2021 Jul 1,		\$0.00 \$0.00	Estimate Item Adjustment (0066) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 550.000;
				Adjustment -	Total 7	Jul 1, 2021	SYSTEM	\$0.00 \$0.00 \$3,900.00	Estimate Item Adjustment (0066) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 550.000;
				Adjustment -	Total 7	Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM	\$0.00 \$0.00 \$3,900.00 (\$3,900.00)	Estimate Item Adjustment (0066) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates
				Adjustment -	7 7 8	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$3,900.00 (\$3,900.00)	Estimate Item Adjustment (0066) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 87 on the current Payment Estimate. Material Insufficiency Quantity 550.000;
				Adjustment -	7 7 8 8 8	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,900.00 (\$3,900.00) (\$3,900.00)	Estimate Item Adjustment (0066) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 87 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates
				Adjustment -	7 7 8 8 9 9	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,900.00 (\$3,900.00) (\$3,900.00) (\$3,900.00)	Estimate Item Adjustment (0066) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 87 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0047) overridding Payment Estimate Exception 82 on the current Payment Estimate. Material Insufficiency Quantity 550.000;
				Adjustment -	7 7 8 8 9 9 9	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$3,900.00 (\$3,900.00) (\$3,900.00) (\$3,900.00) \$3,900.00	Estimate Item Adjustment (0066) overridding Payment Estimate Exception 92 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 87 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0047) overridding Payment Estimate Exception 82 on the current Payment Estimate. Material Insufficiency Quantity 550.000; Overrun Quantity Balance 200.00. Averaged Price Adjustment from this item on all previous payment estimates



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
4S3280	0500	MGS GUARDRAIL	Overrun	Overrun		2021			of '0.00000' is applied (if non-zero).		
					14	Nov 2, 2021	SYSTEM	\$3,900.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.50000 - 19.50000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - T	otal				\$0.00			
	0500 -	Total						\$0.00			
	0530	MGS END ANCHOR	Material		7	Jul 1, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user tribid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
					7	Jul 1, 2021	SYSTEM	(\$1,600.00)			
					8	Jul 16, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user tribid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
					8	Jul 16, 2021	SYSTEM	(\$1,600.00)			
					9	Aug 2, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user hathak1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
							9	Aug 2, 2021	SYSTEM	(\$1,600.00)	
					10	Aug 16, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user tribid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.		
					10	Aug 16, 2021	SYSTEM	(\$1,600.00)			
				- Total				\$0.00			
			Material - T	otal				\$0.00			
	0530 -	Total						\$0.00			
	0540	TYPE A CRASHWORTHY END TERMINAL	Material		7	Jul 1, 2021	SYSTEM	\$4,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user tribid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.		
		(MASH)		7	Jul 1, 2021	SYSTEM	(\$4,700.00)				
					8	Jul 16, 2021	SYSTEM	\$4,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user tribid1 overridding Payment		
									Estimate Exception 21 on the current Payment Estimate.		
					8	Jul 16, 2021	SYSTEM	(\$4,700.00)	Estimate Exception 21 on the current Payment Estimate.		
					8		SYSTEM	(\$4,700.00) \$4,700.00	Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		
						2021 Aug 2,			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment		
					9	2021 Aug 2, 2021 Aug 2,	SYSTEM	\$4,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment		
					9	2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM	\$4,700.00 (\$4,700.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment		
				- Total	9 9 10	Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM	\$4,700.00 (\$4,700.00) \$4,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment		
			Material - T		9 9 10	Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM	\$4,700.00 (\$4,700.00) \$4,700.00 (\$4,700.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment		
	0540 -	Total	Material - T		9 9 10	Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM	\$4,700.00 (\$4,700.00) \$4,700.00 (\$4,700.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment		
	0540 - 0550	Total TYPE A CRASHWORTHY END TERMINAL	Material - T		9 9 10	Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM	\$4,700.00 (\$4,700.00) \$4,700.00 (\$4,700.00) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment		
		TYPE A CRASHWORTHY			9 9 10 10	2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$4,700.00 (\$4,700.00) \$4,700.00 (\$4,700.00) \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user tribid1 overridding Payment		
		TYPE A CRASHWORTHY			9 10 10 7	2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$4,700.00 (\$4,700.00) \$4,700.00 (\$4,700.00) \$0.00 \$0.00 \$22,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user tribid1 overridding Payment		
		TYPE A CRASHWORTHY			9 10 10 7	2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$4,700.00 (\$4,700.00) \$4,700.00 (\$4,700.00) \$0.00 \$0.00 \$22,050.00 (\$22,050.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user hathak1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user tribid1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Item Adjustment (0055) due to user tribid1 overridding Payment		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J4S3280	0550	TYPE A CRASHWORTHY END TERMINAL	Material			2021			Estimate Item Adjustment (0051) due to user hathak1 overridding Payment Estimate Exception 23 on the current Payment Estimate.											
		LIND TERMINAL			9	Aug 2, 2021	SYSTEM	(\$22,050.00)												
					10	Aug 16, 2021	SYSTEM	\$22,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user tribid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.											
					10	Aug 16, 2021	SYSTEM	(\$22,050.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0550 -	Total						\$0.00												
	0560	END ANCHOR	Material		7	Jul 1, 2021	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user tribid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.											
					7	Jul 1, 2021	SYSTEM	(\$8,800.00)												
					8	Jul 16, 2021	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user tribid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.											
					8	Jul 16, 2021	SYSTEM	(\$8,800.00)												
					9	Aug 2, 2021	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user hathak1 overridding Payment Estimate Exception 24 on the current Payment Estimate.											
				9	9	Aug 2, 2021	SYSTEM	(\$8,800.00)												
					10	Aug 16, 2021	SYSTEM	\$8,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user tribid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.											
					10	Aug 16, 2021	SYSTEM	(\$8,800.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0560 -	Total						\$0.00												
	0570	CABLE, 2 AWG 1 CONDUCTOR	Material		10	Aug 16, 2021	SYSTEM	\$779.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user tribid1 overridding Payment Estimate Exception 64 on the current Payment Estimate.											
				1	10	10 Aug 16, 2021	SYSTEM	(\$779.10)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0570 -	Total						\$0.00												
	0600	SH-FLAT SHEET - SIGNAL SIGN	Material		11	Sep 2, 2021	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user tribid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
											1	1	1			11	Sep 2, 2021	SYSTEM	(\$1,512.00)	
										12	Sep 16, 2021	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user tribid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
						12	Sep 16, 2021	SYSTEM	(\$1,512.00)											
					13	13	Oct 1, 2021	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user tribid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
				13	Oct 1, 2021	SYSTEM	(\$1,512.00)													
					1	14	Nov 2, 2021	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hathal overridding Payment Estimate Exception 6 on the current Payment Estimate.										
					14	Nov 2, 2021	SYSTEM	(\$1,512.00)												
					15	Nov 15,	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J4S3280	0600	SH-FLAT SHEET - SIGNAL SIGN	Material			2021			Estimate Item Adjustment (0010) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																					
					15	Nov 15, 2021	SYSTEM	(\$1,512.00)																						
					16	Dec 1, 2021	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																					
					16	Dec 1, 2021	SYSTEM	(\$1,512.00)																						
					17	Dec 15, 2021	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																					
					17	Dec 15, 2021	SYSTEM	(\$1,512.00)																						
					18	Jan 3, 2022	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
					18	Jan 3, 2022	SYSTEM	(\$1,512.00)																						
					19	Jan 18, 2022	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																					
					19	Jan 18, 2022	SYSTEM	(\$1,512.00)																						
					20	Feb 2, 2022	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																					
					20	Feb 2, 2022	SYSTEM	(\$1,512.00)																						
						21	Feb 16, 2022	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																				
						21	Feb 16, 2022	SYSTEM	(\$1,512.00)																					
					22	Mar 1, 2022	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																					
					22	Mar 1, 2022	SYSTEM	(\$1,512.00)																						
					23	Apr 22, 2022	SYSTEM	\$1,512.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
					23	Apr 22, 2022	SYSTEM	(\$1,512.00)																						
				- Total				\$0.00																						
	0600 -	Total	Material - To	otal				\$0.00 \$0.00																						
	0620	POST, SIGNAL 8 FT. OR 2.4 M				Material	Material			Material	11	Sep 2, 2021	SYSTEM	\$5,836.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user tribid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.															
																	-	_	_		-		-	-		11	Sep 2, 2021	SYSTEM	(\$5,836.00)	
										12	Sep 16, 2021															SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user tribid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
										12	Sep 16, 2021									SYSTEM	(\$7,295.00)									
					13	Oct 1, 2021	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																					
					13	Oct 1, 2021	SYSTEM	(\$7,295.00)																						
					14	Nov 2, 2021	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																					
					14	Nov 2,	SYSTEM	(\$7,295.00)																						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3280	0620	POST, SIGNAL 8	Material			2021			
		FT. OR 2.4 M			15	Nov 15, 2021	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Nov 15, 2021	SYSTEM	(\$7,295.00)	
					16	Dec 1, 2021	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	Dec 1, 2021	SYSTEM	(\$7,295.00)	
					17	Dec 15, 2021	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					17	Dec 15, 2021	SYSTEM	(\$7,295.00)	
					18	Jan 3, 2022	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					18	Jan 3, 2022	SYSTEM	(\$7,295.00)	
					19	Jan 18, 2022	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					19	Jan 18, 2022	SYSTEM	(\$7,295.00)	
					20	Feb 2, 2022	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					20	Feb 2, 2022	SYSTEM	(\$7,295.00)	
					21	Feb 16, 2022	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					21	Feb 16, 2022	SYSTEM	(\$7,295.00)	
					22	Mar 1, 2022	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					22	Mar 1, 2022	SYSTEM	(\$7,295.00)	
					23	Apr 22, 2022	SYSTEM	\$7,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					23	Apr 22, 2022	SYSTEM	(\$7,295.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	12	Sep 16, 2021	tribid1	(\$1,459.00)	Holding overrun until change order is complete.
					12	Sep 16, 2021	SYSTEM	\$1,459.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 5.000; Overrun Quantity Balance 1.00.
					12	Sep 16, 2021	SYSTEM	(\$1,459.00)	
					13	Oct 1, 2021	SYSTEM	(\$1,459.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					13	Oct 1, 2021	SYSTEM	\$1,459.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 24 on the current Payment Estimate. Material Insufficiency Quantity 5.000; Overrun Quantity Balance 1.00.
					14	Nov 2, 2021	SYSTEM	(\$1,459.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					14	Nov 2, 2021	SYSTEM	\$1,459.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 5.000;



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3280	0620	POST, SIGNAL 8 FT. OR 2.4 M	Overrun	Overrun					Overrun Quantity Balance 1.00.
					15	Nov 15, 2021	SYSTEM	(\$1,459.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					15	Nov 15, 2021	SYSTEM	\$1,459.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 5.000; Overrun Quantity Balance 1.00.
					16	Dec 1, 2021	SYSTEM	(\$1,459.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					16	Dec 1, 2021	SYSTEM	\$1,459.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 5.000; Overrun Quantity Balance 1.00.
					17	Dec 15, 2021	SYSTEM	(\$1,459.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					17	Dec 15, 2021	SYSTEM	\$1,459.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 5.000; Overrun Quantity Balance 1.00.
					18	Jan 3, 2022	hathak1	\$1,459.00	Correction to adjustment paid on 09/16/21 due to Change Order processing.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0620 -	Total						\$0.00	
	0650	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material	al	8	Jul 16, 2021	SYSTEM	\$3,601.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user tribid1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$3,601.80)	
					9	Aug 2, 2021	SYSTEM	\$3,601.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user hathak1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$3,601.80)	
					10	Aug 16, 2021	SYSTEM	\$3,601.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user tribid1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$3,601.80)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0650 -	Total						\$0.00	
	0660	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	H E	Material	8	Jul 16, 2021	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user tribid1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$2,600.00)	
					9	Aug 2, 2021	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user hathak1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$2,600.00)	
					10	Aug 16, 2021	SYSTEM	\$2,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$2,600.00)	
				- Total				\$0.00	
			Material - To	terial - Total					
	0660 -	Total						\$0.00	
	0670	CABLE, 16 AWG 2 CONDUCTOR	Material		10	Aug 16, 2021	SYSTEM	\$829.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user tribid1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					10	Aug 16,	SYSTEM	(\$829.50)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3280	0670	CABLE, 16 AWG 2 CONDUCTOR	Material			2021			
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0670 -	Total						\$0.00	
	0680	CABLE, 16 AWG 5 CONDUCTOR	Material		10	Aug 16, 2021	SYSTEM	\$947.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user tribid1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$947.70)	
				- Total				\$0.00	
			Material - To	Material - Total					
	0680 -	Total						\$0.00	
	0690	CABLE, LOOP DETECTOR, IN DUCT	Material		8	Jul 16, 2021	SYSTEM	\$5,136.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user tribid1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$5,136.00)	
					9	Aug 2, 2021	SYSTEM	\$5,136.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user hathak1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$5,136.00)	
					10	Aug 16, 2021	SYSTEM	\$5,136.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$5,136.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Other Item Adjustment		8	Jul 16, 2021	tribid1	\$513.60	Holding overrun until changer is complete.
					9	Aug 3, 2021	karlic1	(\$513.60)	Correctly withholding overrun until change order is complete
					9	Aug 3, 2021	karlic1	(\$513.60)	Removing incorrectly applied overrun adjustment from Est 8 (513.60)
					11	Sep 3, 2021	tribid1	\$513.60	Holding overrun until Change Order is complete.
				OVRN - Tota	al			\$0.00	
			Other Item A	Adjustment -	Total			\$0.00	
				verrun Overrun	8	Jul 16, 2021	SYSTEM	\$513.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 88 on the current Payment Estimate. Material Insufficiency Quantity 160.000; Overrun Quantity Balance 16.00.
					8	Jul 16, 2021	SYSTEM	(\$513.60)	
					9	Aug 2, 2021	SYSTEM	(\$513.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Aug 2, 2021	SYSTEM	\$513.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0055) overridding Payment Estimate Exception 83 on the current Payment Estimate. Material Insufficiency Quantity 160.000; Overrun Quantity Balance 16.00.
					10	Aug 16, 2021	SYSTEM	(\$513.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Aug 16, 2021	SYSTEM	\$513.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 86 on the current Payment Estimate. Material Insufficiency Quantity 160.000; Overrun Quantity Balance 16.00.
					11	Sep 2, 2021	SYSTEM	(\$513.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					18	Jan 3, 2022	SYSTEM	\$513.60	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',32.10000 - 32.10000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	



LEAD-IN LEAD-IN LEAD-IN Aug 16, 2021 SQUAR SYSTEM (\$420.00) Material - Total SQUAR SYSTEM (\$10,889.10) This adjustment offsets the original system-generated Material Payment Estimate Exception 67 on the current Payment Estimate. SQUAR SYSTEM (\$10,889.10) This adjustment offsets the original system-generated Material Payment Estimate Exception 67 on the current Payment Estimate. SYSTEM (\$10,889.10) This adjustment offsets the original system-generated Material Payment Estimate Exception 67 on the current Payment Estimate. SYSTEM (\$10,889.10) This adjustment offsets the original system-generated Material Payment System-generated Material	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
10	J4S3280	0690	DETECTOR, IN	Overrun - T	otal				\$0.00	
DETECTOR, LEAD-IN 10		0690 -	· Total						\$0.00	
2021 \$0.00		0700	DETECTOR,	Material		10		SYSTEM	\$420.00	Estimate Item Adjustment (0058) due to user tribid1 overridding Payment
Material - Total						10		SYSTEM	(\$420.00)	
									\$0.00	
BASE, CONCRETE				Material - To	otal					
CONCRETE										
2021 9		0720		Material		8		SYSTEM	\$10,889.10	Estimate Item Adjustment (0031) due to user tribid1 overridding Payment
2021 Estimate Item Adjustment (0058) due to user hathak1 overridding Payme						8		SYSTEM	(\$10,889.10)	
2021						9		SYSTEM	\$10,889.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user hathak1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
2021 Estimate Item Adjustment (0023) due to user tribid1 overridding Paymen Estimate Exception 73 on the current Payment Estimate.						9		SYSTEM	(\$10,889.10)	
Company						10		SYSTEM	\$10,889.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user tribid1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
Material - Total \$0.00						10		SYSTEM	(\$10,889.10)	
Other Item Adjustment OVRN 8					- Total				\$0.00	
Adjustment 9 Aug 3, 2021 9 Aug 3, 2021 11 Sep 3, 2021 COVRN - Total 2021 (\$1,774.52) Correctly withholding overrun until change order is complete (\$1,774.52) Removing incorrectly applied overrun adjustment from Est 8 (1774.52) \$0,000				Material - T	otal				\$0.00	
2021 9					OVRN	8		tribid1	\$1,774.52	Holding overrun until changer is complete.
2021						9		karlic1	(\$1,774.52)	Correctly withholding overrun until change order is complete
						9		karlic1	(\$1,774.52)	Removing incorrectly applied overrun adjustment from Est 8 (1774.52)
								tribid1	\$1,774.52	
Other Item Adjustment - Total \$0.00										
				Other Item A Overrun	n Adjustment -	Total			\$0.00	
					Overrun Overrun	8		SYSTEM	\$1,774.52	
8 Jul 16, 2021 (\$1,774.52)						8		SYSTEM	(\$1,774.52)	
9 Aug 2, 2021 SYSTEM (\$1,774.52) Averaged Price Adjustment from this item on all previous payment estimor of '0.00000' is applied (if non-zero).						9		SYSTEM	(\$1,774.52)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
						9		SYSTEM	\$1,774.52	
Aug 16, SYSTEM (\$1,774.52) Averaged Price Adjustment from this item on all previous payment estimor of '0.00000' is applied (if non-zero).						10		SYSTEM	(\$1,774.52)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
						10		SYSTEM	\$1,774.52	
Sep 2, 2021 System (\$1,774.52) Averaged Price Adjustment from this item on all previous payment estimof '0.00000' is applied (if non-zero).						11		SYSTEM	(\$1,774.52)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
						18		SYSTEM	\$1,774.52	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4033.00000 - 4033.00000 'is applied (if non-zero).
Overrun - Total \$0.00										
					Overrun - T	otal			\$0.00	



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
80	0720 -	Total						\$0.00		
	5007	PREF THERMO PAVMT MARKING, 6 IN WHITE	Material		15	Nov 15, 2021	SYSTEM	\$1,030.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					15	Nov 15, 2021	SYSTEM	(\$1,030.40)		
					16	Dec 1, 2021	SYSTEM	\$1,030.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hathak1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					16	Dec 1, 2021	SYSTEM	(\$1,030.40)		
					17	Dec 15, 2021	SYSTEM	\$1,030.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					17	Dec 15, 2021	SYSTEM	(\$1,030.40)		
					18	Jan 3, 2022	SYSTEM	\$1,030.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					18	Jan 3, 2022	SYSTEM	(\$1,030.40)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	5007 -	Total						\$0.00		
	5009	GRATES AND BEARING PLATES (5 FT X 3 FT)	Material	aterial	18	Jan 3, 2022	SYSTEM	\$3,491.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					18	Jan 3, 2022	SYSTEM	(\$3,491.25)		
					19	Jan 18, 2022	SYSTEM	\$3,491.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					19	Jan 18, 2022	SYSTEM	(\$3,491.25)		
					20	Feb 2, 2022	SYSTEM	\$3,491.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					20	Feb 2, 2022	SYSTEM	(\$3,491.25)		
					21	Feb 16, 2022	SYSTEM	\$3,491.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					21	Feb 16, 2022	SYSTEM	(\$3,491.25)		
					22	Mar 1, 2022	SYSTEM	\$3,491.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					:	22	Mar 1, 2022	SYSTEM	(\$3,491.25)	
					23	Apr 22, 2022	SYSTEM	\$3,491.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					23	Apr 22, 2022	SYSTEM	(\$3,491.25)		
				- Total				\$0.00		
			Material - Total					\$0.00		
	5009 -							\$0.00		
	5010	MISC.	Other Item Adjustment	ACAD	22	Mar 1, 2022	hathak1	\$649.75	For 63.31 Tons of BP-2, 20-19 placed in May 2021 for the amount of \$153.84. For 162.06 Tons of BP-2, 20-19 placed in June 2021 for the amount of \$495.90	
				ACAD - Tota	al			\$649.75		
				FUEL		Mar 1,	hathak1	\$529.14	For 63.31 tons of BP-2, 20-19 placed in May 2021 for the amount of \$147.13.	
						2022			For 162.06 tons of Bp-2, 20-19 placed in June 2021 for the amount of	
									To Toz. oo tons of pp-z, zo-19 placed in June 2021 for the amount of	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4S3280	5010	MISC.	Other Item Adjustment						\$382.00.	
			Aujustinoni	FUEL - Total						
			Other Item /	Adjustment -	Total			\$1,178.89		
	5010 -	· Total						\$1,178.89		
	5011	MISC. PAVEMENT REPAIR		ACAD		Mar 1, 2022	hathak1	\$11.74	For 3.9 Tons of BP-1, 20-16 placed in July 2021 for moisture flop repairs.	
				ACAD - Tot	al			\$11.74		
			Other Item /	n Adjustment - Total				\$11.74		
	5011 -	· Total						\$11.74		
	5012	MISC.	Material		18	Jan 3, 2022	SYSTEM	\$1,309.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					18	Jan 3, 2022	SYSTEM	(\$1,309.14)		
					19	Jan 18, 2022	SYSTEM	\$1,309.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					19	Jan 18, 2022	SYSTEM	(\$1,309.14)		
					20	Feb 2, 2022	SYSTEM	\$1,309.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					20	Feb 2, 2022	SYSTEM	(\$1,309.14)		
					21	Feb 16, 2022	SYSTEM	\$1,309.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					21	Feb 16, 2022	SYSTEM	(\$1,309.14)		
						22	Mar 1, 2022	SYSTEM	\$1,309.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
						22	Mar 1, 2022	SYSTEM	(\$1,309.14)	
					23	Apr 22, 2022	SYSTEM	\$1,309.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					23	Apr 22, 2022	SYSTEM	(\$1,309.14)		
				- Total				\$0.00		
			Material - To	- Total				\$0.00		
	5012 -	· Total						\$0.00		
	5015	MISC.	SC. Material		21	Feb 16, 2022	SYSTEM	\$5,150.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
						21	Feb 16, 2022	SYSTEM	(\$5,150.80)	
						22	Mar 1, 2022	SYSTEM	\$5,150.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					22	Mar 1, 2022	SYSTEM	(\$5,150.80)		
					23	Apr 22, 2022	SYSTEM	\$5,150.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					23	Apr 22, 2022	SYSTEM	(\$5,150.80)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	5015 -	· Total						\$0.00		
J4S3280 -	Total							\$93,392.85		
J4S3281	0760	BIT. PAVEMENT	Other Item	ACAD	4	May 17,	tribid1	\$3,773.28	AC adjustment for BP-1 Mix ID: BP-120-16.2261.29 tons placed between	
	50					., .,,		, 5.25	,	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J4S3281	0760	MIXTURE PG64-22 (BP-1)	Adjustment			2021			5/6/21-5/12/21.																
		. 00 : 22 (8: 1)		ACAD - Tot				\$3,773.28																	
			Other Item	Adjustment -				\$3,773.28																	
			Price FUEL		4	May 17, 2021	SYSTEM	\$2,728.25	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
					5	Jun 2, 2021	SYSTEM	\$1,208.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
					18	Jan 3, 2022	SYSTEM	\$0.17	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
				- Total				\$3,936.90																	
			Price FUEL	- Total				\$3,936.90																	
	0760 -	Total						\$7,710.18																	
	0770	ASPHALTIC CONCRETE MIXTURE PG	Material		3	May 3, 2021	SYSTEM	\$521,066.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
		70-22 (SP125C MIX)			3	May 3, 2021	SYSTEM	(\$521,066.82)																	
					4	May 17, 2021	SYSTEM	\$628,282.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
					4	May 17, 2021	SYSTEM	(\$628,282.94)																	
																		5	Jun 2, 2021	SYSTEM	\$628,282.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0112) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
													5	Jun 2, 2021	SYSTEM	(\$628,282.94)	,								
					6	Jun 15, 2021	SYSTEM	\$628,282.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user tribid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					6	Jun 15, 2021	SYSTEM	(\$628,282.94)																	
					7	Jul 1, 2021	SYSTEM	\$633,096.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user tribid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					7	Jul 1, 2021	SYSTEM	(\$633,096.95)																	
					8	Jul 16, 2021	SYSTEM	\$633,096.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user tribid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
							8	Jul 16, 2021	SYSTEM	(\$633,096.95)															
																					9	Aug 2, 2021	SYSTEM	\$633,096.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
											9	Aug 2, 2021	SYSTEM	(\$633,096.95)											
											10	Aug 16, 2021	SYSTEM	\$633,096.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user tribid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
											10	Aug 16, 2021	SYSTEM	(\$633,096.95)											
																			11	Sep 2, 2021	SYSTEM	\$633,096.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user tribid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					11	Sep 2, 2021	SYSTEM	(\$633,096.95)																	
				- Total				\$0.00																	
			Material - To	otal				\$0.00																	
		Other Item Adjustment	ACAD	2	Apr 16, 2021	tribid1	\$10,478.86	AC adjustment for SP125C Mix ID SP125 21-14. 5,603.67 tons placed between 4/2/21 - 4/15/21. \$10,478.86.																	
		Adjus			3	May 3, 2021	tribid1	\$7,535.46	AC adjustment for SP125C Mix ID SP125 21-14. 4029.66 tons placed between 4/16/21-5/03/21.																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J4S3281	0770	ASPHALTIC	Other Item	ACAD					\$7535.46																			
		CONCRETE MIXTURE PG 70-22 (SP125C	Adjustment		4	May 17, 2021	tribid1	\$4,549.10	AC adjustment for SP125 C Mix ID: SP125 21-14.1997.18 tons placed between 5/3/12-5/5/12.																			
		MIX)			17	Dec 16, 2021	hathak1	\$257.19	For 89 tons of SP125C placed on 6/16/21.																			
				ACAD - Tot	al			\$22,820.61																				
			Other Item	Adjustment -	Total			\$22,820.61																				
			Overrun	Overrun	4	May 17, 2021	SYSTEM	(\$47,822.71)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																			
					4	May 17, 2021	SYSTEM	\$47,822.71	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0029) overridding Payment Estimate Exception 31 on the current Payment Estimate. Material Insufficiency Quantity 11615.510; Overrun Quantity Balance 847.71.																			
					4	May 17, 2021	tribid1	(\$47,822.71)	This will be removed once the material exception has been resolved.																			
				5	5	Jun 2, 2021	SYSTEM	(\$47,449.25)	Averaged Price Adjustment from this item on all previous payment estimates of '1.88345' is applied (if non-zero).																			
								5	Jun 2, 2021	SYSTEM	\$47,449.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0111) overridding Payment Estimate Exception 45 on the current Payment Estimate. Material Insufficiency Quantity 11615.510; Overrun Quantity Balance 847.71.																
						6	Jun 15, 2021	SYSTEM	(\$47,449.25)	Averaged Price Adjustment from this item on all previous payment estimates of '1.88345' is applied (if non-zero).																		
										6	Jun 15, 2021	SYSTEM	\$47,449.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 44 on the current Payment Estimate. Material Insufficiency Quantity 11615.510; Overrun Quantity Balance 847.71.														
					7	Jul 1, 2021	SYSTEM	(\$47,449.25)	Averaged Price Adjustment from this item on all previous payment estimates of '1.88345' is applied (if non-zero).																			
											7	Jul 1, 2021	SYSTEM	(\$5,023.80)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL													
					7	Jul 1, 2021	SYSTEM	\$5,023.80	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 80 on the current Payment Estimate. Material Insufficiency Quantity 11704.510; Overrun Quantity Balance 936.71.																			
					7	Jul 1, 2021	SYSTEM	\$47,449.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 80 on the current Payment Estimate. Material Insufficiency Quantity 11704.510; Overrun Quantity Balance 936.71.																			
					8	Jul 16, 2021	SYSTEM	(\$52,434.26)	Averaged Price Adjustment from this item on all previous payment estimates of '1.88705' is applied (if non-zero).																			
					8	Jul 16, 2021	SYSTEM	\$52,434.26	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 74 on the current Payment Estimate. Material Insufficiency Quantity 11704.510; Overrun Quantity Balance 936.71.																			
																9	Aug 2, 2021	SYSTEM	(\$52,434.26)	Averaged Price Adjustment from this item on all previous payment estimates of '1.88705' is applied (if non-zero).								
																			9	Aug 2, 2021	SYSTEM	\$52,434.26	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 71 on the current Payment Estimate. Material Insufficiency Quantity 11704.510; Overrun Quantity Balance 936.71.					
					10	Aug 16, 2021	SYSTEM	(\$4,981.96)	Averaged Price Adjustment from this item on all previous payment estimates of '1.88705' is applied (if non-zero).																			
									1			1	1	1			10	Aug 17, 2021	tribid1	(\$4,981.96)	Holding overrun adjustment.							
																						10	Aug 17, 2021	tribid1	\$47,822.21	Removing overrun adjustment.		
																												10
										1						11	Sep 2, 2021	SYSTEM	(\$4,981.96)	Averaged Price Adjustment from this item on all previous payment estimates of '1.88705' is applied (if non-zero).								
				11	Sep 2, 2021	SYSTEM	\$4,981.96	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 11704.510; Overrun Quantity Balance 89.00.																				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
J4S3281	0770	ASPHALTIC CONCRETE	Overrun	Overrun	12	Sep 16, 2021	SYSTEM	(\$4,981.96)	Averaged Price Adjustment from this item on all previous payment estimates of '1.88705' is applied (if non-zero).																				
		MIXTURE PG 70-22 (SP125C MIX)			12	Sep 16, 2021	tribid1	\$4,981.96	Releasing manual overrun hold.																				
					18	Jan 3, 2022	SYSTEM	\$4,982.46	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',55.98270 - 54.09000, 'is applied (if non-zero).																				
				Overrun - To	otal			\$0.00																					
			Overrun - T	otal				\$0.00																					
			Price FUEL		2	Apr 16, 2021	SYSTEM	\$603.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
					2	Apr 16, 2021	SYSTEM	\$9,442.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
					3	May 3, 2021	SYSTEM	\$1,978.98	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
					3	May 3, 2021	SYSTEM	\$5,245.39	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
					4	May 17, 2021	SYSTEM	\$4,606.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
					7	Jul 1, 2021	SYSTEM	\$209.79	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
					18	Jan 3, 2022	SYSTEM	(\$0.03)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
				- Total				\$22,086.99																					
			Price FUEL	- Total				\$22,086.99																					
	0770 -	Total						\$44,907.60																					
	0780		Material		2	Apr 16, 2021	SYSTEM	\$12,944.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user tribid1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
						2	Apr 16, 2021	SYSTEM	(\$12,944.25)																				
					3	May 3, 2021	SYSTEM	\$23,170.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user tribid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																				
					3	May 3, 2021	SYSTEM	(\$23,170.50)																					
						4	May 17, 2021	SYSTEM	\$31,466.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user tribid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																			
					4	May 17, 2021	SYSTEM	(\$31,466.25)																					
							5	Jun 2, 2021	SYSTEM	\$32,771.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0117) due to user tribid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																		
					5	Jun 2, 2021	SYSTEM	(\$32,771.25)																					
														6	Jun 15, 2021	SYSTEM	\$32,771.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user tribid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					6	Jun 15, 2021	SYSTEM	(\$32,771.25)																					
							7	7 7 8		7	7	7	7	7	7	7	7			7					7	Jul 1, 2021	SYSTEM	\$32,771.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user tribid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
																		7	Jul 1, 2021	SYSTEM	(\$32,771.25)								
																		8	8	8	8	3					8	Jul 16, 2021	SYSTEM
				8	Jul 16, 2021	SYSTEM	(\$32,771.25)																						
								9	Aug 2, 2021	SYSTEM	\$32,771.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																					
J4S3281	0780	TACK COAT	Material		9	Aug 2, 2021	SYSTEM	(\$32,771.25)																						
					10	Aug 16, 2021	SYSTEM	\$32,771.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user tribid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																					
					10	Aug 16, 2021	SYSTEM	(\$32,771.25)																						
					11	Sep 2, 2021	SYSTEM	\$32,771.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user tribid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																					
					11	Sep 2, 2021	SYSTEM	(\$32,771.25)																						
					12	Sep 16, 2021	SYSTEM	\$35,048.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user tribid 1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																					
					12	Sep 16, 2021	SYSTEM	(\$35,048.25)																						
				- Total				\$0.00																						
			Material - To	otal				\$0.00																						
			Overrun	Overrun	4	May 17, 2021	SYSTEM	\$1,089.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0036) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 13985.000; Overrun Quantity Balance 2511.00.																					
					4	May 17, 2021	SYSTEM	\$2,828.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0037) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 13985.000; Overrun Quantity Balance 2511.00.																					
						4	May 17, 2021	SYSTEM	\$1,262.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0038) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 13985.000; Overrun Quantity Balance 2511.00.																				
					4	May 17, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0039) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 13985.000; Overrun Quantity Balance 2511.00.																					
					4	May 17, 2021	SYSTEM	\$20.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0040) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 13985.000; Overrun Quantity Balance 2511.00.																					
					4	May 17, 2021	tribid1	(\$6,954.75)	This will be removed once the material exception has been resolved.																					
					4	May 17, 2021	SYSTEM	(\$5,649.75)																						
					5	Jun 2, 2021	SYSTEM	(\$5,649.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																					
															5	Jun 2, 2021	SYSTEM	\$1,305.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0115) overridding Payment Estimate Exception 46 on the current Payment Estimate. Material Insufficiency Quantity 14565.000; Overrun Quantity Balance 3091.00.											
																				5	Jun 2, 2021	SYSTEM	\$5,649.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0116) overridding Payment Estimate Exception 46 on the current Payment Estimate. Material Insufficiency Quantity 14565.000; Overrun Quantity Balance 3091.00.						
					5	Jun 2, 2021	SYSTEM	(\$1,305.00)																						
												6	Jun 15, 2021	SYSTEM	(\$6,954.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).														
																										6	Jun 15, 2021	SYSTEM	\$6,954.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 45 on the current Payment Estimate. Material Insufficiency Quantity 14565.000; Overrun Quantity Balance 3091.00.
																				7	Jul 1, 2021	SYSTEM	(\$6,954.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
															7	Jul 1, 2021	SYSTEM	\$6,954.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 81 on the current Payment Estimate. Material Insufficiency Quantity 14565.000; Overrun Quantity Balance 3091.00.											
					8	Jul 16, 2021	SYSTEM	(\$6,954.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J4S3281	0780	TACK COAT	Overrun	Overrun	8	Jul 16, 2021	SYSTEM	\$6,954.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 75 on the current Payment Estimate. Material Insufficiency Quantity 14565.000; Overrun Quantity Balance 3091.00.				
					9	Aug 2, 2021	SYSTEM	(\$6,954.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
					9	Aug 2, 2021	SYSTEM	\$6,954.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 72 on the current Payment Estimate. Material Insufficiency Quantity 14565.000; Overrun Quantity Balance 3091.00.				
					10	Aug 17, 2021	tribid1	\$6,954.75	Removing overrun adjustment.				
				Overrun - T	otal			\$0.00					
			Overrun - T	otal				\$0.00					
	0780 -						0) (0 = =) (\$0.00					
	0800	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		1	Apr 5, 2021	SYSTEM	\$111,454.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.				
					1	Apr 5, 2021	SYSTEM	(\$111,454.42)					
					2	Apr 16, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user tribid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
					2	Apr 16, 2021	SYSTEM	(\$142,295.87)					
					3	May 3, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user tribid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
									3	May 3, 2021	SYSTEM	(\$142,295.87)	
					4	May 17, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user tribid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					4	May 17, 2021	SYSTEM	(\$142,295.87)					
					5	Jun 2, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0120) due to user tribid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					5	Jun 2, 2021	SYSTEM	(\$142,295.87)					
					6	Jun 15, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
					6	Jun 15, 2021	SYSTEM	(\$142,295.87)					
					7	Jul 1, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user tribid1 overridding Payment Estimate Exception 46 on the current Payment Estimate.				
					7	Jul 1, 2021	SYSTEM	(\$142,295.87)					
					8	Jul 16, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user tribid1 overridding Payment Estimate Exception 44 on the current Payment Estimate.				
					8	Jul 16, 2021	SYSTEM	(\$142,295.87)					
					9	Aug 2, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hathak1 overridding Payment Estimate Exception 44 on the current Payment Estimate.				
					9	Aug 2, 2021	SYSTEM	(\$142,295.87)					
					10	Aug 16, 2021	SYSTEM	\$142,295.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user tribid1 overridding Payment Estimate Exception 45 on the current Payment Estimate.				
					10	Aug 16, 2021	SYSTEM	(\$142,295.87)					
				- Total				\$0.00					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J4S3281	0800	FURN & PLACE	Material - T	otal				\$0.00																		
		CONC MATL FOR FULL DEPTH	Other Item Adjustment	OADJ	1	Apr 5, 2021	wilsor2	(\$40,896.02)	This adjustment offsets the system generated overrun adjustment for the overrun quantity of 88.10 SY.																	
					18	Jan 3, 2022	hathak1	\$40,896.02	Correction to adjustment inadvertently paid as OADJ on April 5, 2021.																	
				OADJ - Tota	al			\$0.00																		
				OVRN	2	Apr 16, 2021	tribid1	(\$30,841.84)	This adjustment offsets the system generated overrun adjustment for the overrun quantity of 66.44 sq. yds.																	
					18	Jan 3, 2022	hathak1	\$30,841.84	Correction to adjustment inadvertently paid as OADJ on April 16, 2021.																	
				OVRN - Tota	al			\$0.00																		
			Other Item	Adjustment -	Total			\$0.00																		
			Overrun	Overrun	1	Apr 5, 2021	SYSTEM	\$19,171.46	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 240.100; Overrun Quantity Balance 88.10.																	
				1	Apr 5, 2021	SYSTEM	\$21,724.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 240.100; Overrun Quantity Balance 88.10.																		
					1	Apr 5, 2021	SYSTEM	(\$40,896.02)																		
								Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																		
					2	Apr 16, 2021	SYSTEM	\$30,841.45	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 306.540; Overrun Quantity Balance 154.54.																	
					2	Apr 16, 2021	SYSTEM	\$40,896.02	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 306.540; Overrun Quantity Balance 154.54.																	
							2	Apr 16, 2021	SYSTEM	(\$30,841.45)																
							3	May 3, 2021	SYSTEM	(\$71,737.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					3	May 3, 2021	SYSTEM	\$71,737.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 306.540; Overrun Quantity Balance 154.54.																	
					4	May 17, 2021	SYSTEM	(\$71,737.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
												4	May 17, 2021	SYSTEM	\$71,737.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0043) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 306.540; Overrun Quantity Balance 154.54.										
											5	Jun 2, 2021	SYSTEM	(\$71,737.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).											
																							5	Jun 2, 2021	SYSTEM	\$71,737.47
									6	Jun 15, 2021	SYSTEM	(\$71,737.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
																				6						SYSTEM
																7		7 Jul 1, 2021 SYSTEM (\$71,737.47) Averaged Price Adjustment from this item on a of '0.00000' is applied (if non-zero).		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
																					7					
					8	Jul 16, 2021	SYSTEM	(\$71,737.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
				8	Jul 16,	SYSTEM	\$71,737.47	This adjustment offsets the original system-generated Overrun Payment																		



Б		5	A 11	011	F .	0 1 1	0		2 1											
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J4S3281	0800	FURN & PLACE CONC MATL FOR FULL DEPTH	Overrun	Overrun		2021			Estimate Item Adjustment (0005) overridding Payment Estimate Exception 76 on the current Payment Estimate. Material Insufficiency Quantity 306.540; Overrun Quantity Balance 154.54.											
					9	Aug 2, 2021	SYSTEM	(\$71,737.47)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).											
					9	Aug 2, 2021	SYSTEM	\$71,737.47	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 73 on the current Payment Estimate. Material Insufficiency Quantity 306.540; Overrun Quantity Balance 154.54.											
					10	Aug 17, 2021	tribid1	\$71,737.86	Removing overrun adjustment.											
					18	Jan 3, 2022	hathak1	(\$71,737.86)	Correction to adjustment inadvertently paid as OVRN on 08/17/21.											
				Overrun - T	otal			\$0.00												
			Overrun - T	otal				\$0.00												
	0800 -	- Total						\$0.00												
	0830	FULL DEPTH PAVEMENT	Overrun	Overrun	1	Apr 5, 2021	SYSTEM	(\$643.50)												
		REPAIR SAW CUT (FOR			2	Apr 16, 2021	SYSTEM	(\$429.00)												
				10	Aug 16, 2021	SYSTEM	\$1,072.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.65000 - 1.65000, 'is applied (if non-zero).												
				Overrun - T	otal			\$0.00												
			Overrun - T	otal				\$0.00												
	0830 -	- Total						\$0.00												
	0840	DOWEL BAR (DRILLING, FURNISHING AND	Material		1	Apr 5, 2021	SYSTEM	\$1,469.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wilsor2 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
		FURNISHING AND INST		1 Apr 5, SYSTEM (\$1,469.40)																
					2	Apr 16, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user tribid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.											
							2	Apr 16, 2021	SYSTEM	(\$1,804.20)										
							3	May 3, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user tribid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
												3	May 3, 2021	SYSTEM	(\$1,804.20)					
							4	May 17, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user tribid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
					4	May 17, 2021	SYSTEM	(\$1,804.20)												
					5	Jun 2, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0123) due to user tribid1 overridding Payment Estimate Exception 29 on the current Payment Estimate.											
					5	Jun 2, 2021	SYSTEM	(\$1,804.20)												
					6	Jun 15, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user tribid1 overridding Payment Estimate Exception 30 on the current Payment Estimate.											
																6	Jun 15, 2021	SYSTEM	(\$1,804.20)	
					7	Jul 1, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user tribid1 overridding Payment Estimate Exception 54 on the current Payment Estimate.											
					7	Jul 1, 2021	SYSTEM	(\$1,804.20)												
				{	8	8	Jul 16, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user tribid1 overridding Payment Estimate Exception 52 on the current Payment Estimate.										
					8	Jul 16,	SYSTEM	(\$1,804.20)												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4S3281	0840	DOWEL BAR	Material			2021															
		(DRILLING, FURNISHING AND INST			9	Aug 2, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hathak1 overridding Payment Estimate Exception 52 on the current Payment Estimate.												
					9	Aug 2, 2021	SYSTEM	(\$1,804.20)													
					10	Aug 16, 2021	SYSTEM	\$1,804.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user tribid1 overridding Payment Estimate Exception 53 on the current Payment Estimate.												
					10	Aug 16, 2021	SYSTEM	(\$1,804.20)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
			Other Item Adjustment	OVRN	2	Apr 16, 2021	tribid1	(\$223.20)	This adjustment offsets the system generated overrun adjustment for the overrun quantity of 48 each.												
					18	Jan 3, 2022	hathak1	\$223.20	Correction to adjustment inadvertently paid as OVRN on April 16, 2021.												
				OVRN - Tota	al			\$0.00													
			Other Item /	Adjustment -	Total			\$0.00													
			Overrun	Overrun	2	Apr 16, 2021	SYSTEM	\$223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 22 on the current Payment Estimate. Material Insufficiency Quantity 388.000; Overrun Quantity Balance 48.00.												
					2	Apr 16, 2021	SYSTEM	(\$223.20)													
									3	May 3, 2021	SYSTEM	(\$223.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					3	May 3, 2021	SYSTEM	\$223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 30 on the current Payment Estimate. Material Insufficiency Quantity 388.000; Overrun Quantity Balance 48.00.												
					4	May 17, 2021	SYSTEM	(\$223.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					4	May 17, 2021	SYSTEM	\$223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 388.000; Overrun Quantity Balance 48.00.												
										5	Jun 2, 2021	SYSTEM	(\$223.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
					5	Jun 2, 2021	SYSTEM	\$223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0122) overridding Payment Estimate Exception 48 on the current Payment Estimate. Material Insufficiency Quantity 388.000; Overrun Quantity Balance 48.00.												
														6	Jun 15, 2021	SYSTEM	(\$223.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
														6	Jun 15, 2021	SYSTEM	\$223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) overridding Payment Estimate Exception 47 on the current Payment Estimate. Material Insufficiency Quantity 388.000; Overrun Quantity Balance 48.00.			
									7	Jul 1, 2021	SYSTEM	(\$223.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
																	7	Jul 1, 2021	SYSTEM	\$223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 83 on the current Payment Estimate. Material Insufficiency Quantity 388.000; Overrun Quantity Balance 48.00.
										8	Jul 16, 2021	SYSTEM	(\$223.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).							
					8	Jul 16, 2021	SYSTEM	\$223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 77 on the current Payment Estimate. Material Insufficiency Quantity 388.000; Overrun Quantity Balance 48.00.												
									9	Aug 2, 2021	SYSTEM	(\$223.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					9	Aug 2, 2021	SYSTEM	\$223.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 74 on the current Payment Estimate. Material Insufficiency Quantity 388.000; Overrun Quantity Balance 48.00.												



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks							
,		'	Type	Adjustment Type	Number	Date	Ву									
J4S3281	0840	DOWEL BAR (DRILLING, FURNISHING AND	Overrun	Overrun	10	Aug 17, 2021	tribid1	\$223.20	Removing overrun adjustment.							
		INST			18	Jan 3, 2022	hathak1	(\$223.20)	Correction to adjustment made on 08/17/21, This was to correct the adjustment in the Other Item Adjustment but was not done correctly.							
				Overrun - T	otal			\$0.00								
			Overrun - T	otal				\$0.00								
	0840 -	- Total						\$0.00								
	0850	CONSTRUCTION SIGNS	Material		1	Apr 5, 2021	SYSTEM	\$2,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wilsor2 overridding Payment Estimate Exception 6 on the current Payment Estimate.							
					1	Apr 5, 2021	SYSTEM	(\$2,672.00)								
					2	Apr 16, 2021	SYSTEM	\$2,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user tribid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					2	Apr 16, 2021	SYSTEM	(\$2,672.00)								
										3	May 3, 2021	SYSTEM	\$2,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user tribid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		
										3	May 3, 2021	SYSTEM	(\$2,672.00)			
													4	May 17, 2021	SYSTEM	\$2,672.00
					4	May 17, 2021	SYSTEM	(\$2,672.00)								
					5	Jun 2, 2021	SYSTEM	\$2,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0140) due to user tribid1 overridding Payment Estimate Exception 32 on the current Payment Estimate.							
							5	Jun 2, 2021	SYSTEM	(\$2,672.00)						
					6	Jun 15, 2021	SYSTEM	\$2,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user tribid1 overridding Payment Estimate Exception 33 on the current Payment Estimate.							
											6	Jun 15, 2021	SYSTEM	(\$2,672.00)		
						7	Jul 1, 2021	SYSTEM	\$2,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user tribid1 overridding Payment Estimate Exception 57 on the current Payment Estimate.						
									7	Jul 1,	SYSTEM	(\$0.070.00)				
				- Total		2021	OTOTEM	(\$2,672.00)								
				- Total		2021	OTOTEW	\$0.00								
			Material - T			2021	OTOTEW	(, ,								
	0850 -	- Total	Material - T			2021	OTOTEN	\$0.00								
	0850 - 0860	-Total ADVANCED WARNING RAIL SYSTEM	Material - To		1	Apr 5, 2021	SYSTEM	\$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
		ADVANCED WARNING RAIL			1	Apr 5,		\$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment							
		ADVANCED WARNING RAIL				Apr 5, 2021	SYSTEM	\$0.00 \$0.00 \$0.00 \$105.00	Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment							
		ADVANCED WARNING RAIL			1	Apr 5, 2021 Apr 5, 2021 Apr 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$105.00	Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user tribid1 overridding Payment							
		ADVANCED WARNING RAIL			1	Apr 5, 2021 Apr 5, 2021 Apr 16, 2021 Apr 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$105.00 (\$105.00)	Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user tribid1 overridding Payment							
		ADVANCED WARNING RAIL			2	Apr 5, 2021 Apr 5, 2021 Apr 16, 2021 Apr 16, 2021 May 3,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$0.00 \$105.00 (\$105.00) (\$105.00)	Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user tribid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user tribid1 overridding Payment							
		ADVANCED WARNING RAIL			2 2 3	Apr 5, 2021 Apr 5, 2021 Apr 16, 2021 Apr 16, 2021 May 3, 2021 May 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$105.00 \$105.00 \$105.00 \$105.00	Estimate Item Adjustment (0013) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user tribid1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user tribid1 overridding Payment							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J4S3281	0860	ADVANCED WARNING RAIL SYSTEM	Material		5	Jun 2, 2021	SYSTEM	\$105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0141) due to user tribid1 overridding Payment Estimate Exception 34 on the current Payment Estimate.											
					5	Jun 2, 2021	SYSTEM	(\$105.00)												
					6	Jun 15, 2021	SYSTEM	\$105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user tribid1 overridding Payment Estimate Exception 35 on the current Payment Estimate.											
					6	Jun 15, 2021	SYSTEM	(\$105.00)												
					7	Jul 1, 2021	SYSTEM	\$105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user tribid1 overridding Payment Estimate Exception 59 on the current Payment Estimate.											
					7	Jul 1, 2021	SYSTEM	(\$105.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0860 -	Total						\$0.00												
	0880	CHANNELIZER (TRIM LINE)	Material		1	Apr 5, 2021	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilsor2 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
					1	Apr 5, 2021	SYSTEM	(\$5,800.00)												
																2	Apr 16, 2021	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
													2	Apr 16, 2021	SYSTEM	(\$5,800.00)				
							3	May 3, 2021	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user tribid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.									
								3	May 3, 2021	SYSTEM	(\$5,800.00)									
					4	May 17, 2021	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 24 on the current Payment Estimate.											
								4	May 17, 2021	SYSTEM	(\$5,800.00)									
					5	Jun 2, 2021	SYSTEM	\$5,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0126) due to user tribid1 overridding Payment Estimate Exception 36 on the current Payment Estimate.											
					5	Jun 2, 2021	SYSTEM	(\$5,800.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
			Other Item OADJ Adjustment	OADJ	Item OADJ		1	Apr 5, 2021	wilsor2	(\$1,800.00)	This adjustment offsets the system generated overrun adjustment for the overrun quantity of 90 each.									
					6	Jun 15, 2021	karlic1	\$1,800.00	Removing manually entered overrun adjustment											
				OADJ - Tota	ıl			\$0.00												
			Other Item /	Adjustment -				\$0.00												
		Other Item Overrun							Overrun Overrui	Overrun Overrun	1	Apr 5, 2021	SYSTEM	\$200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 290.000; Overrun Quantity Balance 90.00.					
				1	1	Apr 5, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 290.000; Overrun Quantity Balance 90.00.											
					1	Apr 5, 2021	SYSTEM	(\$1,800.00)												
				2	Apr 16, 2021	SYSTEM	(\$1,800.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
					2	Apr 16, 2021	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 23											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J4S3281	0880	CHANNELIZER (TRIM LINE)	Overrun	Overrun					on the current Payment Estimate. Material Insufficiency Quantity 290.000; Overrun Quantity Balance 90.00.																	
					3	May 3, 2021	SYSTEM	(\$1,800.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
					3	May 3, 2021	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 31 on the current Payment Estimate. Material Insufficiency Quantity 290.000; Overrun Quantity Balance 90.00.																	
					4	May 17, 2021	SYSTEM	(\$1,800.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
					4	May 17, 2021	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0049) overridding Payment Estimate Exception 35 on the current Payment Estimate. Material Insufficiency Quantity 290.000; Overrun Quantity Balance 90.00.																	
					5	Jun 2, 2021	SYSTEM	(\$1,800.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
					5	Jun 2, 2021	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0125) overridding Payment Estimate Exception 49 on the current Payment Estimate. Material Insufficiency Quantity 290.000; Overrun Quantity Balance 90.00.																	
					6	Jun 15, 2021	SYSTEM	(\$1,800.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																	
					18	Jan 3, 2022	SYSTEM	\$1,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',20.00000 - 20.00000, 'is applied (if non-zero).																	
				Overrun - Total				\$0.00																		
	0880 -	Total	Overrun - T	otal				\$0.00																		
	0890		Material		1	Apr 5, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wilsor2 overridding Payment Estimate Exception 11 on the current Payment Estimate.																	
										1	Apr 5, 2021	SYSTEM	(\$4,500.00)													
					2	Apr 16, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user tribid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																	
						2	Apr 16, 2021	SYSTEM	(\$4,500.00)																	
					3	May 3, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user tribid1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																	
					3	May 3, 2021	SYSTEM	(\$4,500.00)																		
				4		4	May 17, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user tribid1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																
							4	4								4					4	May 17, 2021	SYSTEM	(\$4,500.00)		
																						5	Jun 2, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0129) due to user tribid1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					5	Jun 2, 2021	SYSTEM	(\$4,500.00)																		
											6	6	6	6								6	Jun 15, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user tribid1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
															6	Jun 15, 2021	SYSTEM	(\$4,500.00)								
				7	7	Jul 1, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user tribid1 overridding Payment Estimate Exception 61 on the current Payment Estimate.																	
				7	Jul 1, 2021	SYSTEM	(\$4,500.00)																			
				- Total				\$0.00																		
	М	Material - To	otal				\$0.00																			
			Other Item	OADJ	1	Apr 5,	wilsor2	(\$1,500.00)	This adjustment offsets the system generated overrun adjustment for the																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J4S3281	0890	FLASHING ARROW PANEL	Adjustment			2021			overrun quantity of 1 each.														
				OADJ - Tota				(\$1,500.00)															
				OVRN	8	Jul 16, 2021	tribid1	\$1,500.00	Removing manually entered overrun adjustment.														
				OVRN - Tot	al			\$1,500.00															
			Other Item	Adjustment -	Total			\$0.00															
			Overrun	Overrun	1	Apr 5, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.														
					1	Apr 5, 2021	SYSTEM	(\$1,500.00)															
					2	Apr 16, 2021	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).														
					2	Apr 16, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 24 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.														
					3	May 3, 2021	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates														
									3	May 3, 2021	SYSTEM	\$1,500.00	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.										
															4	May 17, 2021	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).				
								4	May 17, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0052) overridding Payment Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.											
						5	Jun 2, 2021	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).													
				5	Jun 2, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0128) overridding Payment Estimate Exception 50 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.															
				6	Jun 15, 2021	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					6	Jun 15, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 49 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.														
											7	Jul 1, 2021	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					7	Jul 1, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 84 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.														
											8	Jul 16, 2021	SYSTEM	(\$1,500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).								
					18	Jan 3, 2022	SYSTEM	\$1,500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1500.00000 - 1500.00000, 'is applied (if non-zero).														
				Overrun - T	otal			\$0.00															
			Overrun - T	otal				\$0.00															
	0890 -	Total						\$0.00															
	0900	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		1	Apr 5, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user wilsor2 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
		CONT F/										7		/				7	1	Apr 5, 2021	SYSTEM	(\$8,000.00)	
					2	2	Apr 16, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user tribid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.													
				2																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J4S3281	0900	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		3	May 3, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user tribid1 overridding Payment Estimate Exception 27 on the current Payment Estimate.				
		CONT F/			3	May 3, 2021	SYSTEM	(\$8,000.00)					
					4	May 17, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user tribid1 overridding Payment Estimate Exception 28 on the current Payment Estimate.				
					4	May 17, 2021	SYSTEM	(\$8,000.00)					
					5	Jun 2, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0142) due to user tribid1 overridding Payment Estimate Exception 41 on the current Payment Estimate.				
					5	Jun 2, 2021	SYSTEM	(\$8,000.00)					
					6	Jun 15, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user tribid 1 overridding Payment Estimate Exception 39 on the current Payment Estimate.				
					6	Jun 15, 2021	SYSTEM	(\$8,000.00)					
					7	Jul 1, 2021	SYSTEM	\$8,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user tribid 1 overridding Payment Estimate Exception 63 on the current Payment Estimate.				
					7	Jul 1, 2021	SYSTEM	(\$8,000.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0900 -							\$0.00					
	0920	PREF THERMO PAVMT MARKING, 6 IN WHITE	Material		7	Jul 1, 2021	SYSTEM	\$2,929.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user tribid 1 overridding Payment Estimate Exception 65 on the current Payment Estimate.				
					7	Jul 1, 2021	SYSTEM	(\$2,929.50)					
					8	Jul 16, 2021	SYSTEM	\$2,929.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid1 overridding Payment Estimate Exception 56 on the current Payment Estimate.				
						8	Jul 16, 2021	SYSTEM	(\$2,929.50)				
						9	Aug 2, 2021	SYSTEM	\$2,929.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hathak1 overridding Payment Estimate Exception 56 on the current Payment Estimate.			
					9	Aug 2, 2021	SYSTEM	(\$2,929.50)					
								10	10	Aug 16, 2021	SYSTEM	\$2,929.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid 1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$2,929.50)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0920 -	Total						\$0.00					
	0930	PREF THERMO PAVMT MARKING, 12 IN WHITE	Material		7	Jul 1, 2021	SYSTEM	\$6,384.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user tribid1 overridding Payment Estimate Exception 66 on the current Payment Estimate.				
					7	Jul 1, 2021	SYSTEM	(\$6,384.00)					
					8	Jul 16, 2021	SYSTEM	\$6,384.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user tribid1 overridding Payment Estimate Exception 57 on the current Payment Estimate.				
					8	Jul 16, 2021	SYSTEM	(\$6,384.00)					
					9	Aug 2, 2021	SYSTEM	\$6,384.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hathak1 overridding Payment Estimate Exception 57 on the current Payment Estimate.				
					9	Aug 2,	SYSTEM	(\$6,384.00)					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
J4S3281	0930	PREF THERMO	Material			2021																										
		PAVMT MARKING, 12 IN WHITE			10	Aug 16, 2021	SYSTEM	\$6,384.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user tribid1 overridding Payment Estimate Exception 58 on the current Payment Estimate.																							
					10	Aug 16, 2021	SYSTEM	(\$6,384.00)																								
				- Total				\$0.00																								
			Material - To	otal				\$0.00																								
			Other Item Adjustment	OVRN	7	Jul 2, 2021	tribid1	(\$476.00)	Holding overrun until change order is complete.																							
					11	Sep 3, 2021	tribid1	\$476.00	Holding overrun until Change Order is complete.																							
				OVRN - Tota	al			\$0.00																								
			Other Item	Adjustment -	Total			\$0.00																								
			Overrun	Overrun	7	Jul 1, 2021	SYSTEM	\$476.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 85 on the current Payment Estimate. Material Insufficiency Quantity 912.000; Overrun Quantity Balance 68.00.																							
					7	Jul 1, 2021	SYSTEM	(\$476.00)																								
					8	Jul 16, 2021	SYSTEM	(\$476.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																							
					8	Jul 16, 2021	SYSTEM	\$476.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 79 on the current Payment Estimate. Material Insufficiency Quantity 912.000; Overrun Quantity Balance 68.00.																							
													9	Aug 2, 2021	SYSTEM	(\$476.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					9	Aug 2, 2021	SYSTEM	\$476.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 75 on the current Payment Estimate. Material Insufficiency Quantity 912.000; Overrun Quantity Balance 68.00.																							
							10	Aug 16, 2021	SYSTEM	(\$476.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																					
					10	Aug 16, 2021	SYSTEM	\$476.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 77 on the current Payment Estimate. Material Insufficiency Quantity 912.000; Overrun Quantity Balance 68.00.																							
						11	Sep 2, 2021	SYSTEM	(\$476.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																						
					18	Jan 3, 2022	SYSTEM	\$476.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',7.00000 - 7.00000, 'is applied (if non-zero).																							
				Overrun - T	otal			\$0.00																								
			Overrun - T	otal				\$0.00																								
	0930 -	Total						\$0.00																								
	0940	PREF THERMO PVMT MARK, 24 IN WHIT	Material		7	Jul 1, 2021	SYSTEM	\$6,776.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user tribid 1 overridding Payment Estimate Exception 67 on the current Payment Estimate.																							
																-		:			7	Jul 1, 2021	SYSTEM	(\$6,776.00)								
																					8	8	8	8	8	8		8	Jul 16, 2021	SYSTEM	\$6,776.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user tribid1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
										9		9	8	Jul 16, 2021	SYSTEM	(\$6,776.00)																
															9		9	Aug 2, 2021	SYSTEM		\$6,776.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hathak1 overridding Payment Estimate Exception 58 on the current Payment Estimate.										
					9	Aug 2, 2021	SYSTEM	(\$6,776.00)																								
					10	Aug 16, 2021	SYSTEM	\$6,776.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user tribid1 overridding Payment Estimate Exception 59 on the current Payment Estimate.																							
					10	Aug 16,	SYSTEM	(\$6,776.00)																								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J4S3281	0940	PREF THERMO PVMT MARK, 24	Material			2021																		
		IN WHIT		- Total				\$0.00																
			Material - T	otal				\$0.00																
			Other Item Adjustment	OVRN	7	Jul 2, 2021	tribid1	(\$4,760.00)	Holding overrun until change order is complete.															
					11	Sep 3, 2021	tribid1	\$4,760.00	Holding overrun until Change Order is complete.															
				OVRN - Tot	al			\$0.00																
			Other Item	- Adjustment -	Total			\$0.00																
			Overrun	Overrun	7	Jul 1, 2021	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) overridding Payment Estimate Exception 86 on the current Payment Estimate. Material Insufficiency Quantity 484.000; Overrun Quantity Balance 340.00.															
					7	Jul 1, 2021	SYSTEM	(\$4,760.00)																
					8	Jul 16, 2021	SYSTEM	(\$4,760.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					8	Jul 16, 2021	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 80 on the current Payment Estimate. Material Insufficiency Quantity 484.000; Overrun Quantity Balance 340.00.															
					9	Aug 2, 2021	SYSTEM	(\$4,760.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).															
					9	Aug 2, 2021	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 76 on the current Payment Estimate. Material Insufficiency Quantity 484.000; Overrun Quantity Balance 340.00.															
									10	Aug 16, 2021	SYSTEM	(\$4,760.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).											
					10	Aug 16, 2021	SYSTEM	\$4,760.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 78 on the current Payment Estimate. Material Insufficiency Quantity 484.000; Overrun Quantity Balance 340.00.															
						11	Sep 2, 2021	SYSTEM	(\$4,760.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).														
					18	Jan 3, 2022	SYSTEM	\$4,760.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',14.00000 - 14.00000, 'is applied (if non-zero).															
				Overrun - T	otal			\$0.00																
			Overrun - T	otal				\$0.00																
	0940 -	Total						\$0.00																
	0950	PREF THERMO PVMT MARK, LT/RT ARROW	Material		7	Jul 1, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user tribid1 overridding Payment Estimate Exception 69 on the current Payment Estimate.															
					7	Jul 1, 2021	SYSTEM	(\$7,800.00)																
			\$							8	Jul 16, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user tribid1 overridding Payment Estimate Exception 60 on the current Payment Estimate.										
										9	9			9	9	9	5			8	Jul 16, 2021	SYSTEM	(\$7,800.00)	
																			9	Aug 2, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hathak1 overridding Payment Estimate Exception 60 on the current Payment Estimate.	
																	9	Aug 2, 2021	SYSTEM	(\$7,800.00)				
												10	Aug 16, 2021	SYSTEM	\$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user tribid1 overridding Payment Estimate Exception 61 on the current Payment Estimate.								
				10	Aug 16, 2021	SYSTEM	(\$7,800.00)																	
				- Total				\$0.00																
			-					\$0.00																
			Material - T	otal				φυ.υυ																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3281	0960	4 IN. WHITE WATERBORNE PAVEMENT	Material		7	Jul 1, 2021	SYSTEM	\$7,225.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user tribid1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
		MARKING			7	Jul 1, 2021	SYSTEM	(\$7,225.92)	
					8	Jul 16, 2021	SYSTEM	\$7,225.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user tribid1 overridding Payment Estimate Exception 62 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$7,225.92)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item	OVRN	7	Jul 2,	tribid1	(\$966.06)	Holding overrun until change order is complete.
			Adjustment	0 7 1 11 1	18	2021 Jan 3,	hathak1	\$966.06	Correction to adjustment inadvertently paid as OVRN on June 2, 2021.
						2022	Hatriaki		Conceded to adjustment matterently paid as OVINN on dutic 2, 2021.
				OVRN - Tot				\$0.00	
				REFL	18	Jan 3, 2022	hathak1	\$355.05	White pavement marking adjustment for 40,144 LF.
				REFL - Tota	ıl			\$355.05	
			Other Item	Adjustment -	Total			\$355.05	
			Overrun	Overrun	7	Jul 1, 2021	SYSTEM	\$966.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 87 on the current Payment Estimate. Material Insufficiency Quantity 40144.000; Overrun Quantity Balance 5367.00.
					7	Jul 1, 2021	SYSTEM	(\$966.06)	
					8	Jul 16, 2021	SYSTEM	(\$966.06)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Jul 16, 2021	SYSTEM	\$966.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 81 on the current Payment Estimate. Material Insufficiency Quantity 40144.000; Overrun Quantity Balance 5367.00.
					9	Aug 2, 2021	SYSTEM	(\$966.06)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Aug 2, 2021	SYSTEM	\$966.06	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$966.06)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Aug 17, 2021	tribid1	\$966.06	Removing overrun adjustment.
					18	Jan 3, 2022	hathak1	(\$966.06)	Correction to adjustment made on 08/17/21, This was originally done to correct the adjustment in the Other Item Adjustment but was not done correctly.
					18	Jan 3, 2022	SYSTEM	\$966.06	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.18000 - 0.18000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0960 -	Total						\$355.05	
	0970	4 IN. YELLOW WATERBORNE PAVEMENT	Material		7	Jul 1, 2021	SYSTEM	\$7,032.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid1 overridding Payment Estimate Exception 73 on the current Payment Estimate.
		MARKING			7	Jul 1, 2021	SYSTEM	(\$7,032.78)	
					8	Jul 16, 2021	SYSTEM	\$7,032.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user tribid1 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$7,032.78)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item	REFL	18	Jan 3,	hathak1	\$333.42	Yellow pavement marking adjustment for 39,071 LF.
			,			,		+3002	,



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
J4S3281	0970	4 IN. YELLOW	Adjustment			2022																										
		WATERBORNE PAVEMENT		REFL - Tota	ı			\$333.42																								
		MARKING	Other Item	Adjustment -	Total			\$333.42																								
	0970 -	Total						\$333.42																								
	0990	GUARDRAIL TYPE A	Material		5	Jun 2, 2021	SYSTEM	\$1,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0143) due to user tribid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																							
					5	Jun 2, 2021	SYSTEM	(\$1,875.00)																								
					6	Jun 15, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user tribid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																							
					6	Jun 15, 2021	SYSTEM	(\$4,687.50)																								
								7	Jul 1, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user tribid 1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																				
					7	Jul 1, 2021	SYSTEM	(\$4,687.50)																								
						8	Jul 16, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user tribid 1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																						
												8	Jul 16, 2021	SYSTEM	(\$4,687.50)																	
					9	Aug 2, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hathak1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																							
					9	Aug 2, 2021	SYSTEM	(\$4,687.50)																								
										10	Aug 16, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user tribid 1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																		
						10	Aug 16, 2021	SYSTEM	(\$4,687.50)																							
					11	Sep 2, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user tribid 1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																							
					11	Sep 2, 2021	SYSTEM	(\$4,687.50)																								
						12	Sep 16, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																						
															12	Sep 16, 2021	SYSTEM	(\$4,687.50)														
									13	Oct 1, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user tribid1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																			
																			13	Oct 1, 2021	SYSTEM	(\$4,687.50)										
																	14	Nov 2, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
																14	Nov 2, 2021	SYSTEM	(\$4,687.50)													
																								1	1:	15		15	Nov 15, 2021	SYSTEM	\$4,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
																												15	Nov 15, 2021	SYSTEM	(\$4,687.50)	
																												16		16	Dec 1, 2021	SYSTEM
						16	Dec 1, 2021	SYSTEM	(\$4,687.50)																							
				- Total				\$0.00																								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J4S3281	0990	GUARDRAIL TYPE A	Material - T	otal				\$0.00																	
	0990 -	Total						\$0.00																	
	1000	MGS GUARDRAIL	Material		5	Jun 2, 2021	SYSTEM	\$1,218.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0144) due to user tribid1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																
					5	Jun 2, 2021	SYSTEM	(\$1,218.75)																	
					6	Jun 15, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user tribid1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																
					6	Jun 15, 2021	SYSTEM	(\$18,759.00)																	
					7	Jul 1, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user tribid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																
					7	Jul 1, 2021	SYSTEM	(\$18,759.00)																	
					8	Jul 16, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user tribid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																
					8	Jul 16, 2021	SYSTEM	(\$18,759.00)																	
					9	Aug 2, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hathak1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																
					9	Aug 2, 2021	SYSTEM	(\$18,759.00)																	
					10	Aug 16, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user tribid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																
					10	Aug 16, 2021	SYSTEM	(\$18,759.00)																	
					11	Sep 2, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					11	Sep 2, 2021	SYSTEM	(\$18,759.00)																	
						12	Sep 16, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user tribid1 overridding Payment Estimate Exception 6 on the current Payment Estimate.															
					12	Sep 16, 2021	SYSTEM	(\$18,759.00)																	
														13	Oct 1, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user tribid1 overridding Payment Estimate Exception 3 on the current Payment Estimate.							
																			13	Oct 1, 2021	SYSTEM	(\$18,759.00)			
																14	Nov 2, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
						14	Nov 2, 2021	SYSTEM	(\$18,759.00)																
																					15	Nov 15, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
																				15	Nov 15, 2021	SYSTEM	(\$18,759.00)		
					16	Dec 1, 2021	SYSTEM	\$18,759.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																
					16	Dec 1, 2021	SYSTEM	(\$18,759.00)																	
				- Total				\$0.00																	
			Material - T	otal				\$0.00																	
	1000 -	Total						\$0.00																	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3281	1010	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Material	71.2	5	Jun 2, 2021	SYSTEM	\$2,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0145) due to user tribid1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		,			5	Jun 2, 2021	SYSTEM	(\$2,450.00)	
					6	Jun 15, 2021	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user tribid1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Jun 15, 2021	SYSTEM	(\$9,800.00)	
					7	Jul 1, 2021	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user tribid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$9,800.00)	
					8	Jul 16, 2021	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$9,800.00)	
					9	Aug 2, 2021	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hathak1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$9,800.00)	
					10	Aug 16, 2021	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user tribid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$9,800.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
		· Total						\$0.00	
	1010	MGS END ANCHOR	Material		5	Jun 2, 2021	SYSTEM	\$0.00 \$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0146) due to user tribid 1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		MGS END	Material		5		SYSTEM SYSTEM		Estimate Item Adjustment (0146) due to user tribid1 overridding Payment
		MGS END	Material			2021 Jun 2,		\$1,600.00	Estimate Item Adjustment (0146) due to user tribid1 overridding Payment
		MGS END	Material		5	Jun 2, 2021 Jun 15,	SYSTEM	\$1,600.00 (\$1,600.00)	Estimate Item Adjustment (0146) due to user tribid1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid1 overridding Payment
		MGS END	Material		5	Jun 2, 2021 Jun 15, 2021 Jun 15,	SYSTEM SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00	Estimate Item Adjustment (0146) due to user tribid1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid1 overridding Payment
		MGS END	Material		5 6	Jun 2, 2021 Jun 15, 2021 Jun 15, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00 (\$3,200.00)	Estimate Item Adjustment (0146) due to user tribid1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid1 overridding Payment
		MGS END	Material		5 6 6 7	2021 Jun 2, 2021 Jun 15, 2021 Jun 15, 2021 Jul 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00 (\$3,200.00) \$3,200.00	Estimate Item Adjustment (0146) due to user tribid1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid1 overridding Payment
		MGS END	Material		5 6 6 7	2021 Jun 2, 2021 Jun 15, 2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00 (\$3,200.00) \$3,200.00	Estimate Item Adjustment (0146) due to user tribid 1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid 1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid 1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid 1 overridding Payment Estimate Item Adjustment (0017) due to user tribid 1 overridding Payment
		MGS END	Material		5 6 7 7 8	2021 Jun 2, 2021 Jun 15, 2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00 (\$3,200.00) \$3,200.00 (\$3,200.00)	Estimate Item Adjustment (0146) due to user tribid 1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid 1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid 1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid 1 overridding Payment Estimate Item Adjustment (0017) due to user tribid 1 overridding Payment
		MGS END	Material		5 6 7 7 8	2021 Jun 2, 2021 Jun 15, 2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00 (\$3,200.00) \$3,200.00 (\$3,200.00) (\$3,200.00)	Estimate Item Adjustment (0146) due to user tribid 1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid 1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid 1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid 1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.
		MGS END	Material		5 6 7 7 8 8 9	2021 Jun 2, 2021 Jun 15, 2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00 (\$3,200.00) \$3,200.00 (\$3,200.00) (\$3,200.00) \$3,200.00	Estimate Item Adjustment (0146) due to user tribid 1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid 1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid 1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid 1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.
		MGS END	Material		5 6 7 7 8 8 9	2021 Jun 2, 2021 Jun 15, 2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00 (\$3,200.00) \$3,200.00 (\$3,200.00) (\$3,200.00) (\$3,200.00)	Estimate Item Adjustment (0146) due to user tribid 1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid 1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid 1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid 1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hathak1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.
		MGS END	Material	- Total	5 6 7 7 8 8 9 9	2021 Jun 2, 2021 Jun 15, 2021 Jun 15, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM	\$1,600.00 (\$1,600.00) \$3,200.00 (\$3,200.00) \$3,200.00 (\$3,200.00) \$3,200.00 (\$3,200.00) \$3,200.00	Estimate Item Adjustment (0146) due to user tribid 1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user tribid 1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid 1 overridding Payment Estimate Exception 16 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user tribid 1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hathak1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
J4S3281	1020	MGS END ANCHOR	Other Item Adjustment	OVRN	6	Jun 15, 2021	karlic1	(\$1,600.00)	Holding overrun until change order is complete.																							
					11	Sep 3, 2021	tribid1	\$1,600.00	Holding overrun until Change Order is complete.																							
				OVRN - Tot	al			\$0.00																								
			Other Item	Adjustment -	Total			\$0.00																								
			Overrun	Overrun	6	Jun 15, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 50 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.																							
					6	Jun 15, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0027) overridding Payment Estimate Exception 50 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.																							
					6	Jun 15, 2021	SYSTEM	(\$1,600.00)																								
					7	Jul 1, 2021	SYSTEM	(\$1,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																							
								7	Jul 1, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0032) overridding Payment Estimate Exception 88 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.																				
										8	Jul 16, 2021	SYSTEM	(\$1,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																		
								8	Jul 16, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 82 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.																				
					9	Aug 2, 2021	SYSTEM	(\$1,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																							
					9	Aug 2, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) overridding Payment Estimate Exception 78 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.																							
									10	Aug 16, 2021	SYSTEM	(\$1,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																			
					10	Aug 16, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 80 on the current Payment Estimate. Material Insufficiency Quantity 4.000; Overrun Quantity Balance 2.00.																							
								11	Sep 2, 2021	SYSTEM	(\$1,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).																				
					14	Nov 2, 2021	SYSTEM	\$1,600.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',800.00000 - 800.00000, 'is applied (if non-zero).																							
				Overrun - T	otal			\$0.00																								
			Overrun - T	otal				\$0.00																								
	1020 -	Total						\$0.00																								
	1030	BRIDGE ANCHOR SECTION, 6 5 FT. POSTS		6	5 6 7		5 6 6 7		rial	Material	5	Jun 2, 2021	SYSTEM	\$8,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0147) due to user tribid1 overridding Payment Estimate Exception 12 on the current Payment Estimate.																	
																				5	Jun 2, 2021	SYSTEM	(\$8,875.00)									
															_	(6	Jun 15, 2021	SYSTEM	\$10,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user tribid1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
																	:	7	7	6	Jun 15, 2021	SYSTEM	(\$10,650.00)									
																												7	Jul 1, 2021	SYSTEM	\$10,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user tribid1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
																												7	7	Jul 1, 2021	SYSTEM	(\$10,650.00)
								8		8	8										8								8	Jul 16, 2021	SYSTEM	\$10,650.00
				8	Jul 16,	SYSTEM	(\$10,650.00)																									



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks									
1400004	1020	PRIDCE ANOLIOS	Motorial	Туре		2024												
J4S3281	1030	BRIDGE ANCHOR SECTION, 6 5 FT.	Material			2021												
		POSTS			9	Aug 2, 2021	SYSTEM	\$10,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hathak1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
					9	Aug 2, 2021	SYSTEM	(\$10,650.00)										
					10	Aug 16, 2021	SYSTEM	\$10,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user tribid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.									
					10	Aug 16, 2021	SYSTEM	(\$10,650.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	1030 -	Total						\$0.00										
	1040	ASYMMETRICAL TRNS. SEC., 6.5 FT. POSTS	Material		5	Jun 2, 2021	SYSTEM	\$1,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0148) due to user tribid1 overridding Payment Estimate Exception 14 on the current Payment Estimate.									
					5	Jun 2, 2021	SYSTEM	(\$1,750.00)	,									
														6	Jun 15, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user tribid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					6	Jun 15, 2021	SYSTEM	(\$2,100.00)										
					7	Jul 1, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user tribid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									
					7	Jul 1, 2021	SYSTEM	(\$2,100.00)										
					8	Jul 16, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user tribid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
					8	Jul 16, 2021	SYSTEM	(\$2,100.00)										
					9	Aug 2, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hathak1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
											9	Aug 2, 2021	SYSTEM	(\$2,100.00)				
								10	Aug 16, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user tribid1 overridding Payment Estimate Exception 19 on the current Payment Estimate.						
					10	Aug 16, 2021	SYSTEM	(\$2,100.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	1040 -	Total						\$0.00										
	1050	TYPE A CRASHWORTHY END TERMINAL	Material		5	Jun 2, 2021	SYSTEM	\$2,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0149) due to user tribid1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
		(MASH)			5	Jun 2, 2021	SYSTEM	(\$2,350.00)										
					6	Jun 15,	SYSTEM	\$14,100.00	This adjustment offsets the original system-generated Material Payment									
						2021			Estimate Item Adjustment (0053) due to user tribid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.									
					6	Jun 15, 2021	SYSTEM	(\$14,100.00)										
					7	Jul 1, 2021	SYSTEM	\$14,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user tribid1 overridding Payment Estimate Exception 21 on the current Payment Estimate.									
					7	Jul 1, 2021	SYSTEM	(\$14,100.00)										
					8	Jul 16, 2021	SYSTEM	\$14,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user tribid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J4S3281	1050	TYPE A CRASHWORTHY	Material		8	Jul 16, 2021	SYSTEM	(\$14,100.00)															
		END TERMINAL (MASH)			9	Aug 2, 2021	SYSTEM	\$14,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hathak1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					9	Aug 2, 2021	SYSTEM	(\$14,100.00)															
					10	Aug 16, 2021	SYSTEM	\$14,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user tribid1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					10	Aug 16, 2021	SYSTEM	(\$14,100.00)															
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	1050 -	Total						\$0.00															
	1060	TYPE A CRASHWORTHY END TERMINAL	Material		5	Jun 2, 2021	SYSTEM	\$7,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0139) due to user tribid1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					5	Jun 2, 2021	SYSTEM	(\$7,350.00)															
					6	Jun 15, 2021	SYSTEM	\$12,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user tribid1 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
					6	Jun 15, 2021	SYSTEM	(\$12,250.00)															
					7	Jul 1, 2021	SYSTEM	\$12,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user tribid1 overridding Payment Estimate Exception 23 on the current Payment Estimate.														
					7	Jul 1, 2021	SYSTEM	(\$12,250.00)															
							8	Jul 16, 2021	SYSTEM	\$12,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user tribid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.												
					8	Jul 16, 2021	SYSTEM	(\$12,250.00)															
						9	Aug 2, 2021	SYSTEM	\$12,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
										9	Aug 2, 2021	SYSTEM	(\$12,250.00)										
					10	Aug 16, 2021	SYSTEM	\$12,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user tribid1 overridding Payment Estimate Exception 22 on the current Payment Estimate.														
					10	Aug 16, 2021	SYSTEM	(\$12,250.00)															
				- Total				\$0.00															
			Material - To	otal				\$0.00															
	1060 -	Total						\$0.00															
	1070	CABLE, LOOP DETECTOR, IN DUCT	Material		6	Jun 15, 2021	SYSTEM	\$38,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user tribid1 overridding Payment Estimate Exception 42 on the current Payment Estimate.														
				7															6	Jun 15, 2021	SYSTEM	(\$38,720.00)	
										7	Jul 1, 2021	SYSTEM	\$38,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user tribid1 overridding Payment Estimate Exception 76 on the current Payment Estimate.									
						7	Jul 1, 2021	SYSTEM	(\$38,720.00)														
											8	Jul 16, 2021	SYSTEM	\$38,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user tribid1 overridding Payment Estimate Exception 68 on the current Payment Estimate.								
					8	Jul 16, 2021	SYSTEM	(\$38,720.00)															
					9	Aug 2, 2021	SYSTEM	\$38,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hathak1 overridding Payment														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3281	1070	CABLE, LOOP	Material						Estimate Exception 64 on the current Payment Estimate.
		DETECTOR, IN DUCT			9	Aug 2, 2021	SYSTEM	(\$38,720.00)	
					10	Aug 16, 2021	SYSTEM	\$38,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user tribid1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
					10	Aug 16, 2021	SYSTEM	(\$38,720.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	14	Nov 2, 2021	SYSTEM	\$32,186.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$32,186.00)	
					15	Nov 15, 2021	SYSTEM	(\$32,186.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					15	Nov 15, 2021	SYSTEM	\$32,186.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					16	Dec 1, 2021	SYSTEM	(\$32,186.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					16	Dec 1, 2021	SYSTEM	\$32,186.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					17	Dec 15, 2021	SYSTEM	(\$32,186.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					17	Dec 15, 2021	SYSTEM	\$32,186.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	1070 -	- Total	Overrun - T	otal				\$0.00 \$0.00	
	1070 - 1080	CABLE, LOOP DETECTOR, LEAD-IN	Overrun - T	otal	6	Jun 15, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
		CABLE, LOOP DETECTOR,		otal	6		SYSTEM	\$0.00	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment
		CABLE, LOOP DETECTOR,		otal		2021 Jun 15,		\$0.00 \$1,044.00	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment
		CABLE, LOOP DETECTOR,		otal	6	Jun 15, 2021 Jul 1,	SYSTEM	\$0.00 \$1,044.00 (\$1,044.00)	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment
		CABLE, LOOP DETECTOR,		otal	6	Jun 15, 2021 Jul 1, 2021 Jul 1,	SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment
		CABLE, LOOP DETECTOR,		otal	6 7	Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment
		CABLE, LOOP DETECTOR,		otal	6 7 7 8	2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00)	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment
		CABLE, LOOP DETECTOR,		otal	6 7 7 8 8 8	2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) (\$1,044.00)	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment
		CABLE, LOOP DETECTOR,		otal	6 7 7 8 8 8 9	2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) (\$1,044.00) \$1,044.00	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment
		CABLE, LOOP DETECTOR,		otal	6 7 7 8 8 8 9 9	2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 4 2021 Aug 16, 4 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) (\$1,044.00) (\$1,044.00)	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 66 on the current Payment Estimate.
		CABLE, LOOP DETECTOR,		- Total	6 7 7 8 8 9 9 10 10	2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) (\$1,044.00) (\$1,044.00) (\$1,044.00) \$1,044.00	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 66 on the current Payment Estimate.
		CABLE, LOOP DETECTOR,		- Total	6 7 7 8 8 9 9 10 10	2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00)	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 66 on the current Payment Estimate.
	1080	CABLE, LOOP DETECTOR,	Material	- Total	6 7 7 8 8 9 9 10 10	2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) (\$1,044.00) (\$1,044.00) (\$1,044.00) (\$1,044.00) \$1,044.00	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 66 on the current Payment Estimate.
	1080	CABLE, LOOP DETECTOR, LEAD-IN	Material	- Total	6 7 7 8 8 8 9 9 10 10 10	2021 Jun 15, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00) \$1,044.00 (\$1,044.00)	Estimate Item Adjustment (0055) due to user tribid1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user tribid1 overridding Payment Estimate Exception 77 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user tribid1 overridding Payment Estimate Exception 70 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user hathak1 overridding Payment Estimate Exception 66 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 66 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4S3281	5102	MISC.	Other Item Adjustment	FUEL	22	Mar 1, 2022	hathak1	\$195.95	For 511 Sq Yds of BP-1, 20-16 placed in May 2021.	
				FUEL - Tota	ı			\$195.95		
			Other Item	Adjustment -	Total			\$383.76		
	5102 -	Total						\$383.76		
	5104	ASPHALTIC CONCRETE MIXTURE PG	Other Item Adjustment	ACAD		Feb 16, 2022	hathak1	\$2,076.88	For 905 Tons of SP125C placed on Palmer Road.	
		70-22 (SP125C MIX)		ACAD - Tota				\$2,076.88		
				FUEL	21	Feb 16, 2022	hathak1	\$2,103.13	For 905 Tons of SP125C placed on Palmer Road.	
				FUEL - Tota	ı			\$2,103.13		
			Other Item	Adjustment -	Total			\$4,180.01		
	5104 -	Total						\$4,180.01		
	5105	TACK COAT	Material		11	Sep 2, 2021	SYSTEM	\$2,589.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user tribid1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					11	Sep 2, 2021	SYSTEM	(\$2,589.75)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
					12	Sep 16, 2021	SYSTEM	\$2,589.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user tribid1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					12	Sep 16, 2021	SYSTEM	(\$2,589.75)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	5105 -	Total						\$0.00		
	5106	FURN & PLACE BIT. MATL FOR CL C PARTIAL	Other Item Adjustment	ACAD	22	Mar 1, 2022	hathak1	\$25.25	For 11 Tons of SP125C, 21-14 placed in May 2021.	
				ACAD - Tota	al			\$25.25		
			Other Item	Adjustment -	Total			\$25.25		
	5106 -							\$25.25		
	5108	ASPH. CONC. MIXTURE PG 70-22 (SP095C)	Other Item Adjustment	ACAD		Dec 16, 2021	hathak1	\$389.88	For 152 tons of SP095 placed on 5/26/21.	
				ACAD - Tota		- 10		\$389.88		
				FUEL	17	Dec 16, 2021	hathak1	\$252.32	For 152 tons of SP095 placed for bridge ends. Line was paid 11/01/21 instead of 5/26/21 when it was placed. This cased the fuel adjustment to be off from the date asphalt was placed.	
				FUEL - Tota	d			\$252.32		
			Other Item	Adjustment -	Total			\$642.20		
			Price FUEL		14	Nov 2, 2021	SYSTEM	\$100.93	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
				- Total				\$100.93		
			Price FUEL	- Total				\$100.93		
	5108 -	Total						\$743.13		
	5110	TACK COAT	Material		14	Nov 2, 2021	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					14	Nov 2, 2021	SYSTEM	(\$760.50)		
				15	Nov 15, 2021	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					15	Nov 15, 2021	SYSTEM	(\$760.50)		
						16	Dec 1, 2021	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hathak1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				16	16	Dec 1, 2021	SYSTEM	(\$760.50)		
					17	Dec 15,	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment	
						200 10,	J. J. LIVI	ψ, σσ.σσ	22-32-20-10 Should be shighted by storing gonerated internal Laymont	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3281	5110	TACK COAT	Material			2021			Estimate Item Adjustment (0005) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Dec 15, 2021	SYSTEM	(\$760.50)	
					18	Jan 3, 2022	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Jan 3, 2022	SYSTEM	(\$760.50)	
					19	Jan 18, 2022	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	Jan 18, 2022	SYSTEM	(\$760.50)	
					20	Feb 2, 2022	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Feb 2, 2022	SYSTEM	(\$760.50)	
					21	Feb 16, 2022	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	Feb 16, 2022	SYSTEM	(\$760.50)	
					22	Mar 1, 2022	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					22	Mar 1, 2022	SYSTEM	(\$760.50)	
					23	Apr 22, 2022	SYSTEM	\$760.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hathak1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					23	Apr 22, 2022	SYSTEM	(\$760.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5110 - Total							\$0.00	
	5112	PREF THERMO PVMT MARK, 24 IN YELLOW	Material	2 2 2 2	18	Jan 3, 2022	SYSTEM	\$4,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hathak1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					18	Jan 3, 2022	SYSTEM	(\$4,940.00)	
					19	Jan 18, 2022	SYSTEM	\$4,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					19	Jan 18, 2022	SYSTEM	(\$4,940.00)	
					20	Feb 2, 2022	SYSTEM	\$4,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					20	Feb 2, 2022	SYSTEM	(\$4,940.00)	
					21	Feb 16, 2022	SYSTEM	\$4,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					21	Feb 16, 2022	SYSTEM	(\$4,940.00)	
					22	Mar 1, 2022	SYSTEM	\$4,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					22	Mar 1, 2022	SYSTEM	(\$4,940.00)	
					23	Apr 22, 2022	SYSTEM	\$4,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hathak1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					23	Apr 22,	SYSTEM	(\$4,940.00)	

May 4, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3281	5112	PREF THERMO PVMT MARK, 24 IN YELLOW				2022			
				- Total				\$0.00	
			Material - Total					\$0.00	
	5112 - Total							\$0.00	
J4S3281 - Total									
Overall - Total									