

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2021

Progress Estimate Number	Contract ID 201218-D0	Pay Period Start July 1, 2021 Original Contract Amount \$1,262,640.83
3	Prime Contractor Capital Pav	ring & Construction, LLC Pay Period End July 15, 2021 Net Change Order Amount \$0.00
3		Current Contract Amount \$1,262,640.83

Approval Date		By User
July 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	hakej1
July 16, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	niemej1
July 19, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		11.05%

	Milestones		
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 6, 2021	January 6, 2021	
Letting Date	December 18, 2020	December 18, 2020	
Notice to Proceed Date	February 8, 2021	February 8, 2021	
Work Began Date	June 21, 2021	June 21, 2021	

Contract Total Pay Fo	or Estimate No. 3				
		This Estimate	Previous	To Date	
201218-D02					
	Total Posted Items Pay	\$68,044.20	\$71,504.50	\$139,548.70	
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$71,504.50	\$139,548.70	
Contract Total Pavab	le This Estimate:	\$68.044.20			

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3338	0050	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	100.1	\$15,215.20		
	0800	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$9.000	431	\$3,879.00
	0090	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$5.000	180	\$900.00
	0390	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	LS	\$16,000.000	0.5	\$8,000.00
	0400	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	LS	\$76,500.000	0.5	\$38,250.00
	0410	7129901	MISC.REMOVE AND REPLACE BOLTS	LS	\$1,800.000	1	\$1,800.00
Project J5	P3338 - To	otal					\$68,044.20
Overall - T	otal						\$68,044.20

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		Stillents Exist on Contract						
Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3338	0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR				-100.1	\$152.00	(\$15,215.20)
	0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user hakej1	100.1	\$152.00	\$15,215.20

Revision 4/1/2020 Page 1 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: July 16, 2021

Progress Estimate Number

Contract ID 201218-D02 Pay Period Start July 1, 2021 Original Contract Amount \$1,262,640.83

Prime Contractor Capital Paving & Construction, LLC Pay Period End July 15, 2021 Net Change Order Amount \$0.00

Current Contract Amount \$1,262,640.83

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3338		REPAIR			overridding Payment Estimate Exception 1 on the current Payment Estimate.			
	0390	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-0.5	\$16,000.00	(\$8,000.00)
	0390	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	0.5	\$16,000.00	\$8,000.00
	0400	DRAINAGE SYSTEM (ON STRUCTURE)	Material			-0.5	\$76,500.00	(\$38,250.00)
	0400	DRAINAGE SYSTEM (ON STRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	0.5	\$76,500.00	\$38,250.00
	0410	MISC.	Material			-1	\$1,800.00	(\$1,800.00)
	0410	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$1,800.00	\$1,800.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	า
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5P3338	FAS S402(5)	Bridge rehabilitation	40	COOPER	over Missouri River in Boo	onville	
Totals by .	Job Numbe	ers					
J5P3338					T1 : F :: 1	Danielania	
					This Estimate	Previous	To Date
	Poste	d Item Pay			\$68,044.20	\$71,504.50	To Date \$139,548.70
		ed Item Pay s Item Adjustm	nents				
				s Item Pay	\$68,044.20	\$71,504.50	\$139,548.70
		s Item Adjustm		s Item Pay	\$68,044.20 \$0.00 \$68,044.20	\$71,504.50 \$0.00 \$71,504.50	\$139,548.70 \$0.00 \$139,548.70
	Gross	s Item Adjustm		s Item Pay	\$68,044.20 \$0.00	\$71,504.50 \$0.00 \$71,504.50 \$0.00	\$139,548.70 \$0.00 \$139,548.70 \$0.00
	Gross Incen Disin	s Item Adjustm	Gross	s Item Pay	\$68,044.20 \$0.00 \$68,044.20 \$0.00	\$71,504.50 \$0.00 \$71,504.50	\$139,548.70 \$0.00 \$139,548.70

Revision 4/1/2020 Page 3 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 6131010, Project Item Line Number 0050, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	Getting Certs for concrete plant inspection, some gradation and deleterious inspection, and need to remove one testing item due to us not using it on the job.	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 6131010, Project Item Line Number 0050, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Getting Certs for concrete plant inspection, some gradation and deleterious inspection, and need to remove one testing item due to us not using it on the job.	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 6131010, Project Item Line Number 0050, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Getting Certs for concrete plant inspection, some gradation and deleterious inspection, and need to remove one testing item due to us not using it on the job.	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 7110200, Project Item Line Number 0390, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	Waiting on Cert for protective coating.	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 7123620, Project Item Line Number 0400, Material Set 712362096, Material 0712STDS - Drainage System on Structure, Acceptance Action Generic 0712STDS is insufficient.	Only half of this is done. The testing for this will be completed when the entire drainage system is installed.	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 7129901, Project Item Line Number 0410, Material Set 7129901, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Bridge division needing to inspect the installation of the bolts	hakej1	Overridden

Revision 4/1/2020 Page 4 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

1218-D02 J5P3338	0001 0001 0001 0001 0001 0001 0001 000	0010 0020 0030 0040 0050 0060 0070 0080 0100 0110 0120 0130 0140 0150 0160 0170 0180 0190	2022010 2153000 2159903 6123000A 6131010 6131012 6131013 6131014 6131015 6161005 6161009 6161025 6161030 6161099 6162004 6169902 6181000 6200021	REMOVAL OF IMPROVEMENTS SHAPING SLOPES, CLASS III MISC.SHAPING SLOPES, CLASS III - MODIFIED MATERIAL TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERPACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	1.00 0.90 0.60 2.00 220.00 22.10 22.10 875.60 286.00 504.00 6.00 165.00 8.00 3.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	1.00 0.90 0.60 2.00 220.00 22.10 27.10 875.60 286.00 504.00 2.00 6.00 165.00 8.00 3.00	LS 100F LF EA SQYD SQYD LF EA SQFT EA EA EA	Qty 0.00 0.00 0.00 0.00 100.10 0.00 431.00 180.00 280.50 2.00 0.00 78.00	\$3,725.68 \$2,250.00 \$3,240.00 \$500.00 \$152.00 \$21.00 \$40.00 \$5.00 \$5.00 \$6.50 \$20.00	\$0.00 \$0.00 \$0.00 \$15,215.20 \$0.00 \$15,215.20 \$0.00 \$1,823.25 \$70.00 \$1,823.25
	0001 0001 0001 0001 0001 0001 0001 000	0030 0040 0050 0060 0070 0080 0090 0110 0120 0130 0140 0150 0160 0170 0180	2159903 6123000A 6131010 6131012 6131013 6131014 6131015 6161005 6161009 6161025 6161030 6161099 6162004 6169902 6181000	MISC.SHAPING SLOPES, CLASS III - MODIFIED MATERIAL TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERPACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	0.60 2.00 220.00 22.10 22.10 875.60 286.00 504.00 2.00 6.00 165.00 8.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	0.60 2.00 220.00 22.10 22.10 875.60 286.00 504.00 2.00 6.00 165.00 8.00	LF EA SQYD SQYD LF EA SQFT EA EA	0.00 0.00 100.10 0.00 0.00 431.00 180.00 280.50 2.00 0.00	\$3,240.00 \$500.00 \$152.00 \$21.00 \$40.00 \$5.00 \$6.50 \$35.00 \$20.00	\$0.00 \$15,215.20 \$0.00 \$0.00 \$3,879.00 \$900.00 \$1,823.25 \$70.00
	0001 0001 0001 0001 0001 0001 0001 000	0040 0050 0060 0070 0080 0090 0110 0120 0130 0140 0150 0160 0170 0180 0190	6123000A 6131010 6131012 6131013 6131014 6131015 6161005 6161008 6161009 6161025 6161030 6161099 6162004 6169902 6181000	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERPACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	2.00 220.00 22.10 22.10 875.60 286.00 504.00 2.00 6.00 165.00 8.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	2.00 220.00 22.10 22.10 875.60 286.00 504.00 2.00 6.00 165.00	EA SQYD SQYD SQYD LF EA SQFT EA EA EA	0.00 100.10 0.00 0.00 431.00 180.00 280.50 2.00 0.00 78.00	\$500.00 \$152.00 \$21.00 \$40.00 \$5.00 \$6.50 \$35.00 \$20.00	\$0.00 \$15,215.20 \$0.00 \$0.00 \$3,879.00 \$900.00 \$1,823.25 \$70.00
	0001 0001 0001 0001 0001 0001 0001 000	0050 0060 0070 0080 0090 0100 0110 0120 0130 0140 0150 0160 0170 0180 0190	6131010 6131012 6131013 6131014 6131015 6161005 6161008 6161009 6161025 6161030 6162004 6162004 6169902 6181000	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	220.00 22.10 22.10 875.60 286.00 504.00 2.00 6.00 165.00 8.00 3.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	220.00 22.10 22.10 875.60 286.00 504.00 2.00 6.00 165.00 8.00	SQYD SQYD SQYD LF EA SQFT EA EA	100.10 0.00 0.00 431.00 180.00 280.50 2.00 0.00 78.00	\$152.00 \$21.00 \$40.00 \$9.00 \$5.00 \$6.50 \$35.00 \$20.00	\$15,215.20 \$0.00 \$0.00 \$3,879.00 \$900.00 \$1,823.25 \$70.00
	0001 0001 0001 0001 0001 0001 0001 000	0060 0070 0080 0090 0100 0110 0120 0130 0140 0150 0160 0170 0180	6131012 6131013 6131014 6131015 6161005 6161009 6161025 6161030 6161099 6162004 6169902 6181000	DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR) TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	22.10 22.10 875.60 286.00 504.00 2.00 6.00 165.00 8.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	22.10 22.10 875.60 286.00 504.00 2.00 6.00 165.00	SQYD SQYD LF EA SQFT EA EA EA	0.00 0.00 431.00 180.00 280.50 2.00 0.00 78.00	\$21.00 \$40.00 \$9.00 \$5.00 \$6.50 \$35.00 \$20.00	\$0.00 \$0.00 \$3,879.00 \$900.00 \$1,823.25 \$70.00
	0001 0001 0001 0001 0001 0001 0001 000	0070 0080 0090 0100 0110 0120 0130 0140 0150 0160 0170 0180 0190	6131013 6131014 6131015 6161005 6161008 6161009 6161025 6161030 6161099 6162004 6169902 6181000	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	22.10 875.60 286.00 504.00 2.00 6.00 165.00 8.00	0.00 0.00 0.00 0.00 0.00 0.00 0.00	22.10 875.60 286.00 504.00 2.00 6.00 165.00	SQYD LF EA SQFT EA EA	0.00 431.00 180.00 280.50 2.00 0.00 78.00	\$40.00 \$9.00 \$5.00 \$6.50 \$35.00 \$20.00	\$0.00 \$3,879.00 \$900.00 \$1,823.25 \$70.00
	0001 0001 0001 0001 0001 0001 0001 000	0080 0090 0100 0110 0120 0130 0140 0150 0160 0170 0180	6131014 6131015 6161005 6161008 6161009 6161025 6161030 6161099 6162004 6169902 6181000	(PAVEMENT REPAIR) FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERPACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	875.60 286.00 504.00 2.00 6.00 165.00 8.00	0.00 0.00 0.00 0.00 0.00 0.00	875.60 286.00 504.00 2.00 6.00 165.00	LF EA SQFT EA EA	431.00 180.00 280.50 2.00 0.00 78.00	\$9.00 \$5.00 \$6.50 \$35.00 \$20.00	\$3,879.00 \$900.00 \$1,823.25 \$70.00
	0001 0001 0001 0001 0001 0001 0001 000	0090 0100 0110 0120 0130 0140 0150 0160 0170 0180 0190	6131015 6161005 6161008 6161009 6161025 6161030 6161099 6162004 6169902 6181000	AND INTERNAL SAW CUTS) DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	286.00 504.00 2.00 6.00 165.00 8.00 3.00	0.00 0.00 0.00 0.00 0.00	286.00 504.00 2.00 6.00 165.00 8.00	EA SQFT EA EA	180.00 280.50 2.00 0.00 78.00	\$5.00 \$6.50 \$35.00 \$20.00	\$900.00 \$1,823.25 \$70.00
	0001 0001 0001 0001 0001 0001 0001 000	0100 0110 0120 0130 0140 0150 0160 0170 0180	6161005 6161008 6161009 6161025 6161030 6161099 6162004 6169902 6181000	FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	504.00 2.00 6.00 165.00 8.00 3.00	0.00 0.00 0.00 0.00	504.00 2.00 6.00 165.00 8.00	SQFT EA EA	280.50 2.00 0.00 78.00	\$6.50 \$35.00 \$20.00 \$20.00	\$1,823.25 \$70.00 \$0.00
	0001 0001 0001 0001 0001 0001 0001 000	0110 0120 0130 0140 0150 0160 0170 0180	6161008 6161009 6161025 6161030 6161099 6162004 6169002 6181000	ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	2.00 6.00 165.00 8.00 3.00	0.00 0.00 0.00 0.00	2.00 6.00 165.00 8.00	EA EA	2.00 0.00 78.00	\$35.00 \$20.00 \$20.00	\$70.00 \$0.00
	0001 0001 0001 0001 0001 0001 0001	0120 0130 0140 0150 0160 0170 0180 0190	6161009 6161025 6161030 6161099 6162004 6169902 6181000	FLAG ASSEMBLY CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	6.00 165.00 8.00 3.00	0.00	6.00 165.00 8.00	EA EA	0.00 78.00	\$20.00 \$20.00	\$0.00
	0001 0001 0001 0001 0001 0001	0130 0140 0150 0160 0170 0180 0190	6161025 6161030 6161099 6162004 6169902 6181000	CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	165.00 8.00 3.00	0.00	165.00 8.00	EA	78.00	\$20.00	
	0001 0001 0001 0001 0001	0140 0150 0160 0170 0180 0190	6161030 6161099 6162004 6169902 6181000	TYPE III MOVEABLE BARRICADE CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	8.00	0.00	8.00				\$1,560.00
	0001 0001 0001 0001 0001	0150 0160 0170 0180 0190	6161099 6162004 6169902 6181000	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE	3.00			EA	7.00	6405.00	
	0001 0001 0001 0001	0160 0170 0180 0190	6162004 6169902 6181000	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED TEMPORARY SHORT-TERM RUMBLE STRIPS MISC.DETECTABLE PED CHANNELIZING BARRICADE		0.00	3.00			\$135.00	\$945.00
	0001 0001 0001	0170 0180 0190	6169902 6181000	MISC.DETECTABLE PED CHANNELIZING BARRICADE	2.00			EA	3.00	\$3,000.00	\$9,000.00
	0001	0180	6181000			0.00	2.00	EA	2.00	\$1,200.00	\$2,400.00
	0001	0190			2.00	0.00	2.00	EA	0.00	\$75.00	\$0.00
			6200021	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$66,000.00	\$33,000.00
	0001	0000		PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	0.00	\$350.00	\$0.00
		0200	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	14,420.00	0.00	14,420.00	LF	6,334.00	\$1.25	\$7,917.50
	0001	0210	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	26,835.00	0.00	26,835.00	LF	6,969.00	\$1.25	\$8,711.25
	0001	0220	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	7,220.00	0.00	7,220.00	LF	0.00	\$0.18	\$0.00
	0001	0230	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,261.00	0.00	6,261.00	LF	0.00	\$0.20	\$0.00
	0001	0240	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	48.00	0.00	48.00	LF	0.00	\$8.00	\$0.0
	0001	0250	6207001	PAVEMENT MARKING REMOVAL	9,350.00	0.00	9,350.00	LF	9,350.00	\$0.65	\$6,077.50
	0001	0260	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	2.00	0.00	2.00	EA	0.00	\$150.00	\$0.00
	0001	0270	6208064A	TEMPORARY RAISED PAVEMENT MARKER	316.00	0.00	316.00	EA	0.00	\$4.00	\$0.00
	0001	0280	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0.00
	0001	0290	8051000A	SEEDING - COOL SEASON MIXTURES	0.40	0.00	0.40	ACRE	0.00	\$13,125.00	\$0.00
	0001	0300	8061004	SEDIMENT TRAP ROCK	1.80	0.00	1.80	CUYD	0.00	\$250.00	\$0.00
	0001	0310	8061005	ROCK DITCH CHECK	32.00	0.00	32.00	LF	0.00	\$22.50	\$0.00
	0001	0320	8061016	SEDIMENT REMOVAL	12.00	0.00	12.00	CUYD	0.00	\$45.00	\$0.00
	0001	0330	8061019	SILT FENCE	574.00	0.00	574.00	LF	0.00	\$2.90	\$0.00
	0010	0340	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	500.00	0.00	500.00	LF	0.00	\$21.13	\$0.00
	0010	0350	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	1.00	0.00	1.00	EA	0.00	\$2,650.00	\$0.00
	0010	0360	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	0.00	\$2,600.00	\$0.00
	0070	0370	6235000	MMA POLYMER SLURRY WEARING SURFACE	11,236.00	0.00	11,236.00	SQYD	0.00	\$81.00	\$0.00
	0070	0380	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	250.00	0.00	250.00	SQFT	0.00	\$125.00	\$0.00
	0075	0390	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.50	\$16,000.00	\$8,000.00
	0070	0400	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	1.00	0.00	1.00	LS	0.50	\$76,500.00	\$38,250.00
	0070		7129901	MISC.REMOVE AND REPLACE BOLTS	1.00	0.00	1.00	LS	1.00	\$1,800.00	\$1,800.00
Project J5		0410	Destard to D	ate as of Report Generated Date							\$139,548.70

Revision 4/1/2020 Page 5 of 7



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

$\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Project: J5P3338

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0050	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	7/13/21	7/14/21	100.10	SQYD	6 sections of full depth repair.	106.835		106.865		
0800	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	7/13/21	7/14/21	431.00	LF	6 sections of full depth repair.	106.835		106.865		
0090	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	7/13/21	7/14/21	180.00	EA	6 sections of full depth repair.	106.835		106.865		
0390	7110200	PROTECTIVE COATING - CONCRETE BENTS AND	7/15/21	7/16/21	0.50	LS	Bent 9	22				
0400	7123620	DRAINAGE SYSTEM (ON STRUCTURE)	7/14/21	7/15/21	0.50	LS	Only for bent 9 drainage system. Work on bent 5 has not started yet.	22				
0410	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	7/14/21	7/14/21	1.00	LS		22				5 bolts around span 2-3

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 6 of 7

Jul 19, 2021



Line Item Adjustments by Estimate

Contract ID:190621-F01

Type	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
CONC MATL FOR PULL				Туре		Number	Date	Ву		
3 Jul 16 SYSTEM (\$15.216.20)	J5P3338	0050	CONC MATL FOR FULL	Material		3		SYSTEM	\$15,215.20	Estimate Item Adjustment (0001) due to user hakej1 overridding Payment
Material - Total So.00 So.00 TEMPORABLE Marking Table 2 Jun 30, SYSTEM S7,917.50 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jun 30, SYSTEM S7,917.50 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jun 30, SYSTEM S7,917.50 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jun 30, SYSTEM S7,917.50 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jun 30, SYSTEM S7,917.50 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jun 30, SYSTEM S7,917.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 2 Jun 30, SYSTEM S7,917.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 2 Jun 30, SYSTEM S7,917.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 Jun 16, SYSTEM S8,000 00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 3 Jun 16, SYSTEM S8,000 00 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. S0,000 Jun 10 Jun						3		SYSTEM	(\$15,215.20)	
1999					- Total				\$0.00	
PROTECTIVE CONTRING- CONCRETE CONCRET				Material - Total					\$0.00	
REMOVABLE ANKING TAPE 2 Jun 30, SYSTEM (87,917.50) Estimate Exception 1 on the current Payment Estimate. 2 Jun 30, SYSTEM (87,917.50)		0050 - Total							\$0.00	
1		0200	REMOVABLE MARKING TAPE	Material		2		SYSTEM	\$7,917.50	Estimate Item Adjustment (0001) due to user hakej1 overridding Payment
Material - Total Sum						2		SYSTEM	(\$7,917.50)	
1-1-22 2 3un 30 3ySTEM \$8,711.25 5 5 5 5 5 5 5 5 5					- Total				\$0.00	
D210 TEMPORARY REMOVABLE Material 2 Jun 30, SYSTEM \$8,711.25 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate.				Material - Total					\$0.00	
REMOVABLE MARKING TAPE 2021 Summaria Item Aglustment (0002) due to user hakeft] overridding Payment Estimate Estimate Exception 2 on the current Payment Estimate.		0200 -	Total						\$0.00	
2021 So.00		0210	REMOVABLE	Material		2		SYSTEM	\$8,711.25	Estimate Item Adjustment (0002) due to user hakej1 overridding Payment
Material - Total \$0.00						2		SYSTEM	(\$8,711.25)	
1030 PROTECTIVE COATING-CONCRETE BENTS AND 2021 3 3 3 3 3 3 3 3 3					- Total				\$0.00	
D390 PROTECTIVE COATING COATING COATING COATING CONCRETE BENTS AND Material COATING CONCRETE BENTS AND Material - Total \$0.00				Material - To	Material - Total				\$0.00	
2021 Settmate Item Adjustment (0002) due to user hakej 1 overridding Payment Estimate Exception 4 on the current Payment Estimate. Summer Summe		0210 -	Total						\$0.00	
3 Jul 16, 2021 \$0.00 -Total		0390	COATING - CONCRETE	Material		3		SYSTEM	\$8,000.00	Estimate Item Adjustment (0002) due to user hakej1 overridding Payment
Material - Total S0.00						3		SYSTEM	(\$8,000.00)	
0400 DRAINAGE SYSTEM (ON STRUCTURE) Material 3 Jul 16, 2021 SYSTEM \$38,250.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 3 Jul 16, 2021 SYSTEM (\$38,250.00)					- Total				\$0.00	
DRAINAGE SYSTEM (ON STRUCTURE) Material 3				Material - Total					\$0.00	
SYSTEM (ON STRUCTURE) 2021 Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		0390 -	390 - Total						\$0.00	
2021 \$0.00		0400	SYSTEM (ON	Material		3		SYSTEM	\$38,250.00	Estimate Item Adjustment (0003) due to user hakej1 overridding Payment
Material - Total \$0.00						3		SYSTEM	(\$38,250.00)	
0400 - Total \$0.00					- Total				\$0.00	
0410 MISC. STRUCTURAL STEEL CONSTRUCTION Address of the control of the current Payment Estimate Exception 6 on the current Payment Estimate. 3 Jul 16, 2021 \$995 SYSTEM \$1,800.00 - Total \$0.00 Material - Total \$0.00 0410 - Total \$0.00 0410 - Total \$0.00				Material - Total					\$0.00	
STRUCTURAL STEEL 2021 Estimate Item Adjustment (0004) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		0400 -	0 - Total						\$0.00	
3 Jul 16, 2021 \$YSTEM (\$1,800.00) -Total \$0.00		0410	STRUCTURAL STEEL	Material		3		SYSTEM	\$1,800.00	Estimate Item Adjustment (0004) due to user hakej1 overridding Payment
Material - Total \$0.00 0410 - Total \$0.00 J5P3338 - Total \$0.00						3		SYSTEM	(\$1,800.00)	
0410 - Total \$0.00 J5P3338 - Total \$0.00				- Total					\$0.00	
J5P3338 - Total \$0.00				Material - Total					\$0.00	
		0410 -	Total						\$0.00	
Overall - Total \$0.00	J5P3338 -	Total							\$0.00	
	Overall -	Total							\$0.00	