

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2021

Progress Estimate Number	Contract ID	201218-D02	Pay Period Start	August 16, 2021	Original Contract Amount \$1,262,640	.83
6	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	September 1, 2021	Net Change Order \$0.00 Amount \$1,262,640	.83

Approval Date		By User
September 2, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	hakej1
September 2, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	niemej1
September 3, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		13.54%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 6, 2021	January 6, 2021	
Letting Date	December 18, 2020	December 18, 2020	
Notice to Proceed Date	February 8, 2021	February 8, 2021	
Work Began Date	June 21, 2021	June 21, 2021	

Contract Total Pay For Estimate No. 6				
	This Estimate	Previous	To Date	
201218-D02				
Total Posted Items Pay	\$19,362.50	\$151,571.20	\$170,933.70	
Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		\$ <mark>151,571.20</mark>	\$170,933.70	
Contract Total Payable This Estimate:	\$19,362.50			

# Contract Total Payable This Estimate: <u>Items Paid This Estimate Period</u>

Project Number	Line Number	Item Code	Item Description	on Unit Unit Price		escription Unit Unit Price Current Installed Q		Current Installed Qty	Current Installed Amount	
J5P3338	0380	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	SQFT	\$125.000	154.9	\$19,362.50			
Project J5P3338	Project J5P3338 - Total									
Overall - Total	Iverall - Total									

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3338	0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-100.1	\$152.00	(\$15,215.20)
	0050	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	100.1	\$152.00	\$15,215.20
	0390	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-0.5	\$16,000.00	(\$8,000.00)
	0390	PROTECTIVE COATING -	Material		This adjustment offsets the original system-	0.5	\$16,000.00	\$8,000.00

Revision 4/1/2020 Page 1 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 2, 2021

Progress Estimate Number	Contract ID	201218-D02	Pay Period Start	August 16, 2021	Original Contract Amount\$	51,262,640.83
6	Prime Contractor	Capital Paving & Construction, LLC	Pay Period End	September 1, 2021	Net Change Order \$ Amount Current Contract Amount \$	60.00 61,262,640.83

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J5P3338		CONCRETE BENTS AND PIERS (EPOXY)			generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
	0410	MISC.	Material			-1	\$1,800.00	(\$1,800.00)			
	0410	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1	\$1,800.00	\$1,800.00			
Total								\$0.00			

Revision 4/1/2020 Page 2 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	1				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J5P3338	FAS S402(5)	Bridge rehabilitation	40	COOPER	over Missouri River in Boo	Missouri River in Boonville					
Totals by .	Job Numbe	ers									
J5P3338					This Estimate	Previous	To Date				
		d Item Pay			\$19,362.50	\$151,571.20	\$170,933.70				
	Gross	Gross Item Adjustments			\$0.00	\$0.00	\$0.00				
			Gross	s Item Pay	\$19,362.50	\$151,571.20	\$170,933.70				
	Incen	tive			\$0.00	\$0.00	\$0.00				
	Disin	centive			\$0.00	\$0.00	\$0.00				
Liquidated Damages					\$0.00	\$0.00	\$0.00				

Revision 4/1/2020 Page 3 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 6131010, Project Item Line Number 0050, Material Set 613101096, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 7110200, Project Item Line Number 0390, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy, Acceptance Action Generic 1059PCECBP is insufficient.	No Remark was entered by Engineer	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3338, Item 7129901, Project Item Line Number 0410, Material Set 7129901, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	No Remark was entered by Engineer	hakej1	Overridden

Revision 4/1/2020 Page 4 of 8



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ontract Project ONTRACT No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	unit	Total Posted Approved	Unit Price	Total Value POSTE To Date (See repo generated date)
8-D02 J5P3338	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	Qty 0.00	\$3,725.68	\$0.0
	0001	0020	2153000	SHAPING SLOPES, CLASS III	0.90	0.00	0.90	100F	0.00	\$2,250.00	\$0.0
	0001	0030	2159903	MISC.SHAPING SLOPES, CLASS III - MODIFIED MATERIAL	0.60	0.00	0.60	LF	0.00	\$3,240.00	\$0.0
	0001	0040	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.0
	0001	0050	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	220.00	0.00	220.00	SQYD	100.10	\$152.00	\$15,215.
				DEPTH PAVEMENT REPAIR							
	0001	0060	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	22.10	0.00	22.10	SQYD	0.00	\$21.00	\$0.
	0001	0070	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	22.10	0.00	22.10	SQYD	0.00	\$40.00	\$0.
	0001	0080	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	875.60	0.00	875.60	LF	431.00	\$9.00	\$3,879
	0001	0090	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	286.00	0.00	286.00	EA	180.00	\$5.00	\$900
	0001	0100	6161005	CONSTRUCTION SIGNS	504.00	0.00	504.00	SQFT	280.50	\$6.50	\$1,823
	0001	0110	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$35.00	\$70
	0001	0120	6161009	FLAG ASSEMBLY	6.00	0.00	6.00	EA	0.00	\$20.00	\$0
	0001	0130	6161025	CHANNELIZER (TRIM LINE)	165.00	0.00	165.00	EA	78.00	\$20.00	\$1,560
	0001	0140	6161030	TYPE III MOVEABLE BARRICADE	8.00	0.00	8.00	EA	8.00	\$135.00	\$1,080
	0001	0150	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	3.00	\$3,000.00	\$9,000
	0001	0160	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	2.00	0.00	2.00	EA	2.00	\$1,200.00	\$2,400
	0001	0170	6169902	MISC.DETECTABLE PED CHANNELIZING BARRICADE	2.00	0.00	2.00	EA	0.00	\$75.00	\$0
	0001	0180	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$66,000.00	\$33,000
	0001	0190	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	0.00	\$350.00	\$0
	0001	0200	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	14,420.00	0.00	14,420.00	LF	6,334.00	\$1.25	\$7,917
	0001	0210	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	26,835.00	0.00	26,835.00	LF	6,969.00	\$1.25	\$8,71
	0001	0220	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	7,220.00	0.00	7,220.00	LF	0.00	\$0.18	\$0
	0001	0230	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6,261.00	0.00	6,261.00	LF	0.00	\$0.20	\$0
	0001	0240	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT	48.00	0.00	48.00	LF	0.00	\$8.00	\$0
	0001	0250	6207001	MARKING PAINT, TYPE P BEADS  PAVEMENT MARKING REMOVAL	9,350.00	0.00	9,350.00	LF	9,350.00	\$0.65	\$6,077
	0001	0260	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	2.00	0.00	2.00	EA	0.00	\$150.00	\$0
	0001	0270	6208064A	TEMPORARY RAISED PAVEMENT MARKER	316.00	0.00	316.00	EA	0.00	\$4.00	\$0
	0001	0280	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$1,500.00	\$0
	0001	0290		SEEDING - COOL SEASON MIXTURES	0.40	0.00	0.40	ACRE		\$13,125.00	\$0
	0001	0300	8061004	SEDIMENT TRAP ROCK	1.80	0.00	1.80	CUYD	0.00	\$250.00	\$0
	0001	0310	8061005	ROCK DITCH CHECK	32.00	0.00	32.00	LF	0.00	\$22.50	\$0
	0001	0320	8061016	SEDIMENT REMOVAL	12.00	0.00	12.00	CUYD	0.00	\$45.00	\$0
	0001	0330	8061019	SILT FENCE	574.00	0.00	574.00	LF	0.00	\$2.90	\$0
	0010	0340	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	500.00	0.00	500.00	LF	0.00	\$21.13	\$(
	0010	0350	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	1.00	0.00	1.00	EA	0.00	\$2,650.00	\$(
	0010			(REGULAR/NO CURB)							
	0010	0360	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	0.00	\$2,600.00	\$0
	0070	0370	6235000	MMA POLYMER SLURRY WEARING SURFACE	11,236.00	0.00	11,236.00	SQYD	0.00	\$81.00	\$0
	0070	0380	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	250.00	0.00	250.00	SQFT	250.00	\$125.00	\$31,250
				DROTEOTINE COATING CONCRETE DENTO AND DIEDO	1.00	0.00	1.00	LS	0.50	\$16,000.00	\$8,000
	0070	0390	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)							
	0070	0390	7110200		1.00	0.00	1.00	LS	0.50	\$76,500.00	\$38,250
				(EPOXY)	1.00	0.00	1.00	LS LS	0.50	\$76,500.00 \$1,800.00	\$38,250 \$1,800

Revision 4/1/2020 Page 5 of 8



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3338

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	Offset/ Distance	Comments
0380	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	8/31/21	8/31/21	154.90	SQFT	This is for various substructure repair that is on the abutment and column pertaining to substructure repairs.	22			

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 8



# Line Item Adjustments by Estimate

Contract ID:190621-F01

Type Adjustment Number Date By Type										
P3330   050	Project	Line	Description		Adjustment				Amount	Remarks
3	J5P3338	0050	CONC MATL FOR FULL	Material	, ,,	3		SYSTEM	\$15,215.20	Estimate Item Adjustment (0001) due to user hakej1 overridding Payment
2021   Editoriale Elex Adjustment (1001) of use is user hateful overviding Payment Estimate Exception 1 on the outrent Payment Estimate Payment Estimate Exception 2 on the outrent Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment Payment Estimate Payment Pa						3		SYSTEM	(\$15,215.20)	
2021   SYSTEM   S15,215.20   This adjustment offices the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate Exception 3 on the current Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current						4	Aug 2, 2021	SYSTEM	\$15,215.20	Estimate Item Adjustment (0001) due to user hakej1 overridding Payment
2011   September   September						4		SYSTEM	(\$15,215.20)	
2021   SYSTEM   \$15,215.20   This adjustment offsets the original system-peccated Material Payment Estimate Elem Adjustment (0001) due to user hake] overridding Payment Estimate Exception 1 on the current Payment Estimate.						5		SYSTEM	\$15,215.20	Estimate Item Adjustment (0001) due to user hakej1 overridding Payment
Section   Sect						5		SYSTEM	(\$15,215.20)	
1-Total   S0.00						6		SYSTEM	\$15,215.20	Estimate Item Adjustment (0001) due to user hakej1 overridding Payment
Material - Total   S0.00						6		SYSTEM	(\$15,215.20)	
Color					- Total				\$0.00	
South   Sout				Material - To	otal				\$0.00	
2		0050 -	Total						\$0.00	
REMOVABLE MARKING TAPE  4 IN.    2				Material		2	Jun 30	SYSTEM		This adjustment offsets the original system-generated Material Payment
Total    S0.00		0200	REMOVABLE MARKING TAPE	Material			2021			Estimate Item Adjustment (0001) due to user hakej1 overridding Payment
						2		SYSTEM	, ,	
TEMPORARY REMOVABLE MARKING TAPE   2				Material - Total					\$0.00	
REMOVABLE   MARKING TAPE   2021   SYSTEM   S8,711.25   Stimate Item Adjustment (0002) due to user hakejf overridding Payment Estimate Exception 2 on the current Payment Estimate.		0200 -	Total						\$0.00	
2021   \$0.00		0210	REMOVABLE	Material	al	2		SYSTEM	\$8,711.25	Estimate Item Adjustment (0002) due to user hakej1 overridding Payment
Material - Total   S0.00						2		SYSTEM	(\$8,711.25)	
Substructure   Repair (UNFORMED)   Aug 2, 2021   System   Stinate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					- Total				\$0.00	
SUBSTRUCTURE REPAIR (UNFORMED)   Material REPAIR (UNFORMED)   A				Material - To	otal				\$0.00	
REPAIR (UNFORMED)  2021  Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  3 Jul 16, 2021  SYSTEM (\$8,000.00)  PROTECTIVE COATING-CONCRETE BENTS AND  Adag 2, 2021  3 Jul 16, 2021  SYSTEM (\$8,000.00)  3 Jul 16, 2021  Aug 2, 2021  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.  3 Jul 16, 2021  SYSTEM (\$8,000.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.  4 Aug 2, 2021  SYSTEM (\$8,000.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate Exception 5 on the current Payment Estimate.  4 Aug 2, 2021  SYSTEM (\$8,000.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.  5 Aug 16, 2021  SYSTEM (\$8,000.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		0210 -	Total						\$0.00	
COATING-CONCRETE BENTS AND   PROTECTIVE BENTS AND   PROTECTIVE BENTS AND   Aug 2, 2021   SYSTEM 2022   SYSTEM 20		0380	REPAIR	Material	terial	4		SYSTEM	\$11,887.50	Estimate Item Adjustment (0002) due to user hakej1 overridding Payment
Solution   Solution						4		SYSTEM	(\$11,887.50)	
Solution   Solution					- Total				\$0.00	
PROTECTIVE COATING - CONCRETE BENTS AND    System				Material - Total					\$0.00	
COATING - CONCRETE BENTS AND  2021  2021  Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  3 Jul 16, 2021  4 Aug 2, 2021  SYSTEM \$8,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  4 Aug 2, 2021  SYSTEM \$8,000.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.  5 Aug 16, SYSTEM \$8,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		0380 -	Total						\$0.00	
3 Jul 16, 2021 (\$8,000.00)  4 Aug 2, 2021 \$SYSTEM \$8,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  4 Aug 2, 2021 \$SYSTEM \$8,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  5 Aug 16, \$SYSTEM \$8,000.00)		0390	COATING - CONCRETE	Material		3		SYSTEM	\$8,000.00	Estimate Item Adjustment (0002) due to user hakej1 overridding Payment
Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  4 Aug 2, 2021  5 Aug 16, SYSTEM \$8,000.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  5 Aug 16, SYSTEM (\$8,000.00)						3		SYSTEM	(\$8,000.00)	
2021  5 Aug 16, 2021  \$8,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  5 Aug 16, SYSTEM (\$8,000.00)						4		SYSTEM	\$8,000.00	Estimate Item Adjustment (0003) due to user hakej1 overridding Payment
Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  5 Aug 16, SYSTEM (\$8,000.00)						4		SYSTEM	(\$8,000.00)	
						5		SYSTEM	\$8,000.00	Estimate Item Adjustment (0002) due to user hakej1 overridding Payment
						5		SYSTEM	(\$8,000.00)	





## Line Item Adjustments by Estimate

Contract ID:190621-F01

JSP3338   DROPE   PROTECTIVE   COATING-CONTRICE   BENTS AND	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1-70tal   1-70	J5P3338	0390	COATING - CONCRETE	Material		6		SYSTEM	\$8,000.00	Estimate Item Adjustment (0002) due to user hakej1 overridding Payment
			DENTS AND			6		SYSTEM	(\$8,000.00)	
DRAINAGE   SYSTEM (ON STRUCTURE)   A   3					- Total				\$0.00	
DRAINAGE SYSTEM (ON STRUCTURE)				Material - To	otal				\$0.00	
2021   SYSTEM (ON STRUCTURE)   2021   SYSTEM   Estimate Item Adjustment (0003) due to user hakej1 overridding Payment		0390 -	Total						\$0.00	
2021   4   Aug 2, 2021   2021   5   SYSTEM   \$38,250.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.   S0.00		0400	SYSTEM (ON	Material		3		SYSTEM	\$38,250.00	Estimate Item Adjustment (0003) due to user hakej1 overridding Payment
2021   System   Estimate Item Adjustment (0004) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						3		SYSTEM	(\$38,250.00)	
Construction   Cons						4		SYSTEM	\$38,250.00	Estimate Item Adjustment (0004) due to user hakej1 overridding Payment
Material - Total   \$0.00						4		SYSTEM	(\$38,250.00)	
Name					- Total				\$0.00	
Material STEEL CONSTRUCTION   Material STEEL CONSTRUCTION   STRUCTURAL STEEL CONSTRUCTION   Material STEEL CONSTRUCTION   STRUCTURAL STRUCTURA				Material - To	otal				\$0.00	
STRUCTURAL STEEL CONSTRUCTION  2021  SYSTEM (\$1,800.00)  4 Aug 2, 2021  \$1,800.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.  4 Aug 2, SYSTEM (\$1,800.00)  5 Aug 16, 2021  5 SYSTEM (\$1,800.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.  5 Aug 16, 2021  6 Sep 2, 2021  SYSTEM (\$1,800.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  5 Aug 16, 2021  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  5 Aug 16, 2021  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  6 Sep 2, SYSTEM (\$1,800.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.  6 Sep 2, SYSTEM (\$1,800.00)		0400 -	Total						\$0.00	
3 Jul 16, 2021 4 Aug 2, 2021 5 SYSTEM (\$1,800.00) 5 Aug 16, 2021 6 Sep 2, 2021 6 Sep 2, 2021 7 SYSTEM \$1,800.00		0410	STRUCTURAL STEEL	Material		3		SYSTEM	\$1,800.00	Estimate Item Adjustment (0004) due to user hakej1 overridding Payment
Estimate Item Adjustment (0005) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  4 Aug 2, 2021 \$1,800.00 \$1,800						3		SYSTEM	(\$1,800.00)	
5 Aug 16, 2021 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  5 Aug 16, 2021 \$1,800.00 (\$1,800.00)  6 Sep 2, 2021 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  6 Sep 2, 2021 \$1,800.00 \$						4		SYSTEM	\$1,800.00	Estimate Item Adjustment (0005) due to user hakej1 overridding Payment
Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  5 Aug 16, 2021 (\$1,800.00)  6 Sep 2, 2021 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  6 Sep 2, 2021 \$1,800.00  - Total \$0.00						4	Aug 2, 2021	SYSTEM	(\$1,800.00)	
6 Sep 2, 2021 \$1,800.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  6 Sep 2, 2021 \$1,800.00  - Total \$0.00						5		SYSTEM	\$1,800.00	Estimate Item Adjustment (0003) due to user hakej1 overridding Payment
Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  6 Sep 2, 2021 (\$1,800.00)  - Total \$0.00						5		SYSTEM	(\$1,800.00)	
2021   \$0.00						6		SYSTEM	\$1,800.00	Estimate Item Adjustment (0003) due to user hakej1 overridding Payment
						6		SYSTEM	(\$1,800.00)	
Material - Total \$0.00					- Total				\$0.00	
				Material - To	otal				\$0.00	
0410 - Total \$0.00		0410 -	Total						\$0.00	
J5P3338 - Total \$0.00	J5P3338 -	Total							\$0.00	
Overall - Total \$0.00	Overall - 7	Total					\$0.00			