

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: March 6, 2023

Final Estimate	Number	Contract ID Prime Contractor							
Approval Date							By User		
March 6, 2023			Generated and Appr	oved (and should be	e considered Draft) a	t the Project Office Level by	browns1		
April 11, 2023		Rev	iewed and Approved	(and should be con	sidered Draft) at the	Resident Engineer Level by	holdtc		
April 18, 2023			Revi	iewed and Approved	d at the Central Office	e Controllers Office Level by	ramses1		
Original Comp	oletion Date	Current Co	mpletion Date	Actual Complet	ion Date %	6 of Current Contract Amoun	t Complete		
December	1, 2021	March	23, 2022	March 23, 2	022	100.00%			
	_								

	Contract Informational Dates											
Date Description	Date Description Original Completion Date O		No Milestones Exist for Contract									
Acceptance Date	April 5, 2023	April 5, 2023										
Awarded Date	January 6, 2021	January 6, 2021										
Letting Date	December 18, 2020	December 18, 2020										
Notice to Proceed Date	February 8, 2021	February 8, 2021										
Work Began Date	October 11, 2021	October 11, 2021										

Contract Total Pay For Estimate No. 14			
	This Estimate	Previous	To Date
201218-D03			
Total Posted Items Pay	\$0.00	\$706,560.53	\$706,560.53
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$706,560.53	\$706,560.53
Contract Total Payable This Estimate:	\$0.00		
Home Daid This Fatherste Davied			

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

No Data Available


Revision 3/23/2023 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informati	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5S3229	FAS S401(98)	Bridge superstructure replacement	Н	COLE	over Bois Brule Creek 2.0	mile south of Rte. E	
Totals by J	Job Numbe	rs					
J5S3229		d Item Pay Item Adjustme		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$706,560.53 \$0.00 \$706,560.53	To Date \$706,560.53 \$0.00 \$706,560.53
	Liquid	tive centive lated Damages Contract Adjusi	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 3/23/2023 Page 2 of 14





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 3/23/2023 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
)1218-D03	J5S3229	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$15,000.00	\$15,000.0
		0001	0020	2035000	UNCLASSIFIED EXCAVATION	229.00	0.00	229.00	CUYD	229.00	\$75.00	\$17,175.
		0001	0030	2035500	EMBANKMENT IN PLACE	111.00	0.00	111.00	CUYD	111.00	\$45.00	\$4,995.
		0001	0040	2036000	COMPACTING EMBANKMENT	170.00	0.00	170.00	CUYD	170.00	\$12.00	\$2,040.
		0001	0050	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	360.00	0.00	360.00	SQYD	360.00	\$9.00	\$3,240.
		0001	0060	4019905	MISC.OPTIONAL PAVEMENT	360.00	-360.00	0.00	SQYD	0.00	\$87.00	\$0.
		0001	0070	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	5.00	0.00	5.00	CUYD	5.00	\$125.00	\$625.
		0001	0080	6096041	PLACING TYPE 1 ROCK DITCH LINER	5.00	0.00	5.00	CUYD	5.00	\$100.00	\$500
		0001	0090	6161005	CONSTRUCTION SIGNS	890.00	-112.00	778.00	SQFT	778.00	\$5.50	\$4,279
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140
		0001	0110	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$20.00	\$40
		0001	0120	6161025	CHANNELIZER (TRIM LINE)	25.00	-15.00	10.00	EA	10.00	\$18.00	\$180
		0001	0130	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	10.00	0.00	10.00	EA	10.00	\$185.00	\$1,850
		0001	0140	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600
		0001	0150	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	-4.00	0.00	EA	0.00	\$1.00	\$0
		0001	0160	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$42,000.00	\$0
		0001	0161	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$37,533.00	\$37,533
		0001	0170	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	4.00	\$600.00	\$2,400
		0001	0180	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,182.00	0.00	1,182.00	LF	1,182.00	\$0.60	\$70
		0001	0190	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,218.00	0.00	2,218.00	LF	2,218.00	\$0.60	\$1,33
		0001	0200	6207001	PAVEMENT MARKING REMOVAL	495.00	199.00	694.00	LF	694.00	\$1.50	\$1,04
		0001	0210	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	16.00	0.00	16.00	SQYD	16.00	\$35.00	\$56
		0001	0220	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$1,500.00	\$1,500
		0001	0230	8059901	MISC.Misc. (Seeding - Coole Season Mixture)	1.00	0.00	1.00	LS	1.00	\$7,500.00	\$7,50
		0001	0240	8061005	ROCK DITCH CHECK	95.00	-85.00	10.00	LF	10.00	\$14.50	\$14
		0001	0250	8061010A	TYPE B BERM	316.00	-316.00	0.00	LF	0.00	\$12.00	\$1
		0001	0260	8061016	SEDIMENT REMOVAL	19.00	-19.00	0.00	CUYD	0.00	\$1.00	\$I
		0001	0270	8061050	TYPE C BERM	526.00	-356.00	170.00	LF	170.00	\$15.00	\$2,550
		0010	0280	6061060	MGS GUARDRAIL	38.00	39.00	77.00	LF	77.00	\$22.50	\$1,73
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	4.00	0.00	4.00	EA	4.00		\$8,400
		0010	0300	6061078	(REGULAR/NO CURB) MGS EMBEDDED ANCHOR SECTION (WITH RUBRAIL)	250.00	-125.00	125.00	LF	125.00	\$30.14	\$3,767
		0010	0310	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	1.00	3.00	EA	3.00	\$2,900.00	\$8,700
		0070	0320	2169901	MISC.Removal of Existing Superstructure	1.00	0.00	1.00	LS	1.00		\$41,000
		0070	0330	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	110.00	-110.00	0.00	SQYD	0.00	\$100.00	\$(
		0070	0340	7034216	TYPE H BARRIER	312.00	0.00	312.00	LF	312.00	\$60.00	\$18,720
			0350	7039905	MISC.Slab on Steel (GFRP Rebar)	463.00	0.00	463.00	SQYD	463.00	\$255.00	\$118,068
		0070			SUBSTRUCTURE REPAIR (FORMED)							
		0070	0360	7040101		20.00	0.00	20.00	SQFT	20.00	\$200.00	\$4,000
		0070	0370	7110500	TEMPORARY COATING - CONCRETE BENTS AND PIERS (WEATHERING STEEL) FABRICATED STRUCTURAL LOW ALLOY STEEL (I-BEAM) A709,	1.00	0.00	60,880.00	LS	1.00	\$7,342.00 \$2.70	\$7,342 \$164,376
		0070			GRADE 50W							
		0070	0390	7123610	SLAB DRAIN	26.00	0.00	26.00	EA	26.00	\$250.00	\$6,50
		0070	0400	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,00
		0070	0410	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$150.00	\$1,20
		0070	0420	7162000	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$1,200.00	\$9,60
		0001	5001	6189901	MISC.Adjust Mobilization for Contract Bond	0.00	1.00	1.00	LS	1.00	\$4,467.00	\$4,46

Revision 3/23/2023 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
201218-D03	J5S3229	0070	5002	7049901	MISC.Fiber Reinforced Polymer Wrap	0.00	1.00	1.00	LS	1.00	\$75,746.76	\$75,746.76
		0001	5003	4019905		0.00	360.00	360.00	SQYD	360.00	\$95.00	\$34,200.00
		0070	5004	5031010A	BRIDGE APPROACH SLAB (MAJOR)	0.00	110.00	110.00	SQYD	110.00	\$235.00	\$25,850.00
		0010	5005	2153000	SHAPING SLOPES, CLASS III	0.00	1.00	1.00	100F	1.00	\$1,250.00	\$1,250.00
		0070	5006	7049901	MISC.Force Account No. 1 - Cold Weathering Cost of FRP Installation	0.00	1.00	1.00	LS	1.00	\$16,787.43	\$16,787.43
		0070	5007	1099901	MISC.COMPENSATION FOR PROJECT DELAY	0.00	1.00	1.00	LS	1.00	\$40,923.34	\$40,923.34
	Project J	5S3229 - To	otal Value	Posted to D	late as of Report Generated Date							\$706,560.53
201218-D03 Ove	rall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$706,560.53

Revision 3/23/2023 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

he info				tal to the Estimate and is provid · Construction Signs (if applicab			tion or dota	, 100atioi	r unu qu	idinity 0	. WOTK!	
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J5S3229	0090	October 18, 2021	778	SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.011	Rt BB EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		6.754	Rt H NB	1.00	15			15
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		0.071	Rt H SB	1.00	12.5			12.5
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.129	MO 17 SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.17	Rt E EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.196	Offramp 54- Mo 17 NB	1.00	15			15
				CONST-5 96x48 32.00 POINT OF PRESENCE		0.206	Rt H SB	1.00	32			32
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.285	Rt BB EB	1.00	15			15
				MO4-8a 24x18 3.00 END DETOUR		0.34	Rt H SB	1.00	3			;
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.348	Rt E EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.829	MO 17 SB	1.00	15			1
				WO20-2 48x48 16.00 DETOUR AHEAD		0.903	Rt H NB	1.00	16			16
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.928	MO 17 SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		1.009	Rt H NB	1.00	15			1:
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		1.154	Rt H NB	1.00	15			1:
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		1.202	Rt E EB	1.00	15			1:
				R11-3a 60x30 12.50 ROAD CLOSED XX MILES AHEAD LOCAL TRAFFIC ONLY		1.213	Rt H NB	1.00	12.5			12.
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		1.726	Rt H SB	1.00	16			10
				MO4-8a 24x18 3.00 END DETOUR		1.784	Rt H NB	1.00	3			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		1.841	Rt H SB	1.00	16			10
				R11-2 48x30 10.00 ROAD CLOSED		1.958	Rt H SB	1.00	10			1
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		115.601	Hwy 54 WB	1.00	15			1
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		115.803	Hwy 54 WB	1.00	15			1
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		116.093	Hwy 54 WB	1.00	15			1
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		117.401	Hwy 54 WB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		119.126	Hwy 54 WB	1.00	15			1
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		122.353	Hwy 54 WB	1.00	15			1
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		149.496	Hwy 54 EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		151.618	Hwy 54 EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		154.447	Hwy 54 EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		155.705	Hwy 54 EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR		155.851	Hwy 54 EB	1.00	15			15

Revision 3/23/2023 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Construction Signs (if applical Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
I5S3229	0090	October	778	ASSEMBLY								
		18, 2021		SPECIAL 36x60 15.00 DETOUR ASSEMBLY		156.01	Hwy 54 EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		156.213	Hwy 54 EB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		186.377	MO 17 NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		186.61	MO 17 NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		186.72	MO 17 NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.277	Rt BB WB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.309	Rt BB WB	1.00	15			15
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		4.393	Rt H NB	1.00	16			16
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.441	Rt BB WB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.448	Rt BB WB	1.00	15			15
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		4.516	Rt H NB	1.00	16			16
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.567	Rt E WB	1.00	15			15
				R11-2 48x30 10.00 ROAD CLOSED		4.646	Rt H NB	1.00	10			10
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		4.682	Rt E WB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.032	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.351	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.599	Rt E WB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		5.603	Rt H SB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		6.476	Rt H NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		6.64	Rt H NB	1.00	15			15
				SPECIAL 36x60 15.00 DETOUR ASSEMBLY		0.02	Offramp 54- Mo 17 NB	1.00	15			15
	0090 - To	otal										778

Revision 3/23/2023 Page 7 of 14



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5S3229	0030	EMBANKMENT IN PLACE	Material	Турс	8	Mar 18, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lafava1 overridding Payment
					8	Mar 18,	SYSTEM	(\$4,995.00)	Estimate Exception 1 on the current Payment Estimate.
					9	2022 Apr 5, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment
					9	Apr 5,	SYSTEM	(\$4,995.00)	Estimate Exception 1 on the current Payment Estimate.
					10	2022 Apr 18, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment
					10	Apr 18,	SYSTEM	(\$4,995.00)	Estimate Exception 1 on the current Payment Estimate.
						2022	0.0.5	(ψ1,000.00)	
					11	May 19, 2022	SYSTEM	\$4,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user browns1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	May 19, 2022	SYSTEM	(\$4,995.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0030 -	Total						\$0.00	
	0040	COMPACTING EMBANKMENT	Material		8	Mar 18, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lafava1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$2,040.00)	
					9	Apr 5, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$2,040.00)	
					10	Apr 18, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$2,040.00)	
					11	May 19, 2022	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user browns1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	May 19, 2022	SYSTEM	(\$2,040.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0040 -	Total						\$0.00	
	0070	FURNISHING TYPE 1 ROCK DITCH LINER	Material		9	Apr 5, 2022	SYSTEM	\$625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$625.00)	
					10	Apr 18, 2022	SYSTEM	\$625.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$625.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0070 -	Total						\$0.00	
	0090	CONSTRUCTION SIGNS	Material		4	Nov 2, 2021	SYSTEM	\$4,279.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$4,279.00)	
					5	Nov 16, 2021	SYSTEM	\$4,279.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks					
			Туре	Adjustment Type		Date	Ву							
J5S3229	0090	CONSTRUCTION SIGNS	Material		5	Nov 16, 2021	SYSTEM	(\$4,279.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0090 -	Total						\$0.00						
	0100	ADVANCED WARNING RAIL SYSTEM	Material		3	Oct 18, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					3	Oct 18, 2021	SYSTEM	(\$140.00)						
					4	Nov 2, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					4	Nov 2, 2021	SYSTEM	(\$140.00)						
					5	Nov 16, 2021	SYSTEM	\$140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					5	Nov 16, 2021	SYSTEM	(\$140.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0100 -	Total						\$0.00						
	0110		Material		3	Oct 18, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 2 on the current Payment Estimate.					
						3	Oct 18, 2021	SYSTEM	(\$40.00)					
					4	Nov 2, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.					
											4	Nov 2, 2021	SYSTEM	(\$40.00)
					5	Nov 16, 2021	SYSTEM	\$40.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					5	Nov 16, 2021	SYSTEM	(\$40.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0110 -	Total						\$0.00						
	0120	CHANNELIZER (TRIM LINE)	Material		3	Oct 18, 2021	SYSTEM	\$144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.					
					3	Oct 18, 2021	SYSTEM	(\$144.00)						
					4	Nov 2, 2021	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					4	Nov 2, 2021	SYSTEM	(\$180.00)						
					5	Nov 16, 2021	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					5	Nov 16, 2021	SYSTEM	(\$180.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0120 -	Total												
	0130	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Material		3	Oct 18, 2021	SYSTEM	\$1,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					3	Oct 18, 2021	SYSTEM	(\$1,850.00)						
					4	Nov 2,	SYSTEM	\$1,850.00	This adjustment offsets the original system-generated Material Payment					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
5S3229	0130	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Material			2021			Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.					
		LIGITIO			4	Nov 2, 2021	SYSTEM	(\$1,850.00)						
					5	Nov 16, 2021	SYSTEM	\$1,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					5	Nov 16, 2021	SYSTEM	(\$1,850.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0130 -	Total						\$0.00						
	0140	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		3	Oct 18, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hensor overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					3	Oct 18, 2021	SYSTEM	(\$5,600.00)						
					4	Nov 2, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					4	Nov 2, 2021	SYSTEM	(\$5,600.00)						
					5	Nov 16, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					5	Nov 16, 2021	SYSTEM	(\$5,600.00)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0140 -	Total						\$0.00						
	0180	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		9	Apr 5, 2022	SYSTEM	\$709.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate.					
										9	Apr 5, 2022	SYSTEM	(\$709.20)	
									10	Apr 18, 2022	SYSTEM	\$709.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hensor overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					10	Apr 18, 2022	SYSTEM	(\$709.20)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0180 -	Total						\$0.00						
	0190	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		9	Apr 5, 2022	SYSTEM	\$1,330.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hensor overridding Payment Estimate Exception 18 on the current Payment Estimate.					
		MARKING			9	Apr 5, 2022	SYSTEM	(\$1,330.80)						
					10	Apr 18, 2022	SYSTEM	\$1,330.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 18 on the current Payment Estimate.					
					10	Apr 18, 2022	SYSTEM	(\$1,330.80)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	0190 -	Total						\$0.00						
	0200	PAVEMENT MARKING REMOVAL	Overrun	Overrun	10	Apr 18, 2022	SYSTEM	(\$298.50)						
					11	May 19, 2022	SYSTEM	\$298.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1.50000 - 1.50000, 'is applied (if non-zero).					
			Overrun - Total					\$0.00						
			Overrun - Tot	tal				\$0.00						
	0200 -	Total						\$0.00						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
S3229	0210	PERMANENT EROSION CONTROL GEOTEXTILE	Material		9	Apr 5, 2022	SYSTEM	\$560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 21 on the current Payment Estimate.		
					9	Apr 5, 2022	SYSTEM	(\$560.00)			
					10	Apr 18, 2022	SYSTEM	\$560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 21 on the current Payment Estimate.		
					10	Apr 18, 2022	SYSTEM	(\$560.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0210 -	Total						\$0.00			
	0240	ROCK DITCH CHECK	Material		13	Nov 2, 2022	SYSTEM	\$145.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					13	Nov 2, 2022	SYSTEM	(\$145.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0240 -	Total						\$0.00			
	0270	TYPE C BERM	Material		4	Nov 2, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					4	Nov 2, 2021	SYSTEM	(\$2,550.00)			
							5	Nov 16, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hensor overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$2,550.00)			
					6	Dec 1, 2021	SYSTEM	\$2,550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					6	Dec 1, 2021	SYSTEM	(\$2,550.00)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0270 -	Total						\$0.00			
	0280	MGS GUARDRAIL	Overrun	Overrun	9	Apr 5, 2022	SYSTEM	(\$877.50)			
					11	May 19, 2022	SYSTEM	\$877.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',22.50000 - 22.50000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - To	tal				\$0.00			
	0280 -	Total						\$0.00			
	0300	MGS EMBEDDED ANCHOR SECTION (W/ RUBRAIL)	Material		9	Apr 5, 2022	SYSTEM	\$3,767.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.		
					9	Apr 5, 2022	SYSTEM	(\$3,767.50)			
					10 Apr 18, SYSTEM \$3,767.50 This adjustment offsets Estimate Item Adjustme	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 13 on the current Payment Estimate.					
					10	Apr 18, 2022	SYSTEM	(\$3,767.50)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	0300	Total						\$0.00			
	0310	TYPE A CRASHWORTHY	Overrun	Overrun	9	Apr 5, 2022	SYSTEM	(\$2,900.00)			



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
29 (0310	TYPE A CRASHWORTHY	Overrun	Overrun					'is applied (if non-zero).
		END TERMINAL		Overrun - T	otal			\$0.00	
	(MASI		Overrun - Tot	errun - Total				\$0.00	
	0310 -	10 - Total						\$0.00	
(0340	TYPE H BARRIER	Material		8	Mar 18, 2022	SYSTEM	\$18,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lafava1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$18,720.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0340 -	10 - Total						\$0.00	
(0350	MISC. CONCRETE CONSTRUCTION	Material		6	Dec 1, 2021	SYSTEM	\$70,839.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Dec 1, 2021	SYSTEM	(\$70,839.00)	
					7	Mar 3, 2022	SYSTEM	\$118,065.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Mar 3, 2022	SYSTEM	(\$118,065.00)	
				- Total				\$0.00	
			Material - Tot	Material - Total				\$0.00	
	0350 -	Total						\$0.00	
(0370	TEMPORARY COATING - CONCRETE BENTS AND P	Material		4	Nov 2, 2021	SYSTEM	\$7,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Nov 2, 2021	SYSTEM	(\$7,342.00)	
					5	Nov 16, 2021	SYSTEM	\$7,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hensor overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Nov 16, 2021	SYSTEM	(\$7,342.00)	
				- Total				\$0.00	
		Material - Total						\$0.00	
	0370 -	Total						\$0.00	
(0380		Construction Stockpile		4	Nov 2, 2021	SYSTEM	(\$133,936.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$133,936.00)	
			Construction	Stockpile - 1	otal			(\$133,936.00)	
			Construction Stockpile STMI		2	Jun 1, 2021	SYSTEM	\$133,936.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$133,936.00	
			Construction Stockpile STMI - Total					\$133,936.00	
3	0380 -	Total							
(0410	PLAIN NEOPRENE BEARING PAD	Construction Stockpile		4	Nov 2, 2021	SYSTEM	(\$560.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total	-4-1		(\$560.00)		
			Construction Stockpile STMI	n Stockpile - Total				(\$560.00)	
					2	Jun 1, 2021	SYSTEM	\$560.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$560.00	
			Construction	Stockpile S	MI - Total			\$560.00	
	0410 - Total 0420	Total LAMINATED	Construction Stockpile		4	Nov 2,	SYSTEM	\$0.00 (\$5,380.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		NEOPRENE BEARING PAD ASSEMBLY				2021			, , , , , , , , , , , , , , , , , , , ,
				- Total				(\$5,380.00)	
			Construction Stockpile - Total					(\$5,380.00)	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3229	0420	LAMINATED NEOPRENE BEARING PAD ASSEMBLY	Construction Stockpile STMI		2	Jun 1, 2021	SYSTEM	\$5,380.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,380.00	
			Construction Stockpile STMI - Total					\$5,380.00	
	0420 -	D - Total						\$0.00	
	5004	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		8	Mar 18, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lafava1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Mar 18, 2022	SYSTEM	(\$25,850.00)	
					9	Apr 5, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Apr 5, 2022	SYSTEM	(\$25,850.00)	
					10	Apr 18, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hensor overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Apr 18, 2022	SYSTEM	(\$25,850.00)	
					11	May 19, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user browns1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	May 19, 2022	SYSTEM	(\$25,850.00)	
					12	Jun 2, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Jun 2, 2022	SYSTEM	(\$25,850.00)	
					13	Nov 2, 2022	SYSTEM	\$25,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hensor overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Nov 2, 2022	SYSTEM	(\$25,850.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	5004 - Total							\$0.00	
J5S3229 -	Total							\$0.00	
Overall -	Total						\$0.00		

MoDOT

Contract Adjustments for Contract - 201218-D03

There are no contract adjustments to display for this contract.

Revision 3/23/2023 Page 14 of 14