

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 3, 2021

| Progress Estimate Number | Contract ID | 201218-D05 | Pay Period Start | August 16, 2021 | Original Contract Amount\$4,181,671.73 | |
|-----------------------------|---------------------|------------------------------------|---------------------|----------------------|--|--|
| 10 | Prime Contractor | Capital Paving & Construction, LLC | Pay Period End | September 1, 2021 | Net Change Order Amount Current Contract Amount \$4,180,721.56 | |

| Approval Date | | By User | | | | | |
|----------------------|--|---------|--|--|--|--|--|
| September 3, 2021 | Generated and Approved (and should be considered Draft) at the Project Office Level by | shankb1 | | | | | |
| September 3, 2021 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | gabelj3 | | | | | |
| September 3, 2021 | Reviewed and Approved at the Central Office Controllers Office Level by | | | | | | |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete |
|--------------------------|-------------------------|------------------------|---------------------------------------|
| November 1, 2021 | November 1, 2021 | | 94.21% |

| | Contract Informational Dates | | | | | | | | |
|------------------------|----------------------------------|-------------------|--|--|--|--|--|--|--|
| Date Description | No Milestones Exist for Contract | | | | | | | | |
| Acceptance Date | | | | | | | | | |
| Awarded Date | January 6, 2021 | January 6, 2021 | | | | | | | |
| Letting Date | December 18, 2020 | December 18, 2020 | | | | | | | |
| Notice to Proceed Date | March 8, 2021 | March 8, 2021 | | | | | | | |
| Work Began Date | | | | | | | | | |

| Contract Total Pa | ay For Estimate No. 10 | | | |
|-------------------|----------------------------|---------------|----------------|----------------|
| | | This Estimate | Previous | To Date |
| 201218-D05 | | | | |
| | Total Posted Items Pay | \$174,948.57 | \$3,763,627.81 | \$3,938,576.38 |
| | Gross Item Adjustments | (\$47,259.00) | \$75,562.60 | \$28,303.60 |
| | Incentive | \$0.00 | \$0.00 | \$0.00 |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 |
| | | | \$3,839,190.41 | \$3,966,879.98 |
| Contract Total Pa | avable This Estimate | \$127 689 57 | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Current Installed Amount | | | | |
|-------------------|-----------------------|--------------|--|-----------------------------|-------------|---------|--------------|--|
| J5S3380 | 0240 | 8061016 | SEDIMENT REMOVAL | \$1,000.00 | | | | |
| Project J5S3 | oject J5S3380 - Total | | | | | | | |
| J5S3384 | 0290 | 2079909 | MISC.MODIFIED LINEAR GRADING CLASS 2 | STA | \$306.510 | 151.7 | \$46,497.57 | |
| | 0330 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | TONS | \$55.880 | 200 | \$11,176.00 | |
| | 0520 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | STA | \$10.000 | 897.2 | \$8,972.00 | |
| | 0530 | 6261001 | BITUMINOUS CENTERLINE RUMBLE STRIP | STA | \$10.000 | 1,104.3 | \$11,043.00 | |
| | 0550 | 8051000A | SEEDING - COOL SEASON MIXTURES | ACRE | \$2,200.000 | 42.3 | \$93,060.00 | |
| | 0590 | 8061016 | SEDIMENT REMOVAL | CUYD | \$10.000 | 320 | \$3,200.00 | |
| Project J5S3 | 384 - Total | | | | | | \$173,948.57 | |
| Overall - Tot | tal | | | | | | \$174,948.57 | |

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| Line Item A | <u>.ine Item Adjustments This Estimate</u> | | | | | | | | | | |
|-------------------|--|---------------------------------|--------------------|----------------------------------|----------|------------------------|---------------------------------------|-------------------|--|--|--|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount | | | |
| J5S3380 | 0040 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | | -135.1 | \$30.00 | (\$4,053.00) | | | |

Revision 4/1/2020 Page 1 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 3, 2021

Pay Period **Progress Estimate Contract ID** 201218-D05 August 16, 2021 Original Contract Amount\$4,181,671.73 Number Start Pay Period End September 1, 2021 Prime Capital Paving & Construction, Net Change Order 10 (\$950.17) Amount (\$950.17)
Current Contract Amount \$4,180,721.56 Contractor LLĊ

| ject nber | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustmen amount |
|--------------|-------------|---|--------------------|----------------------------------|--|------------------------|---------------------------------------|------------------|
| 380 | 0040 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 135.1 | \$30.00 | \$4,053.00 |
| | 0070 | TACK COAT | Material | | | -5,288 | \$2.00 | (\$10,576.00 |
| | 0070 | TACK COAT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 5,288 | \$2.00 | \$10,576.00 |
| | 0090 | CONSTRUCTION SIGNS | Material | | | -987.5 | \$7.25 | (\$7,159.38 |
| | 0090 | CONSTRUCTION SIGNS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | 987.5 | \$7.25 | \$7,159.38 |
| C | 0120 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | Material | | | -2 | \$2,250.00 | (\$4,500.00 |
| | 0120 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | 2 | \$2,250.00 | \$4,500.00 |
| | 0130 | TEMPORARY SHORT-TERM RUMBLE STRIPS | Material | | | -4 | \$1,000.00 | (\$4,000.00 |
| | 0130 | TEMPORARY SHORT-TERM RUMBLE STRIPS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 4 | \$1,000.00 | \$4,000.00 |
| | 0150 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -39,486 | \$0.10 | (\$3,948.60 |
| | 0150 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | 39,486 | \$0.10 | \$3,948.60 |
| | 0160 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -39,078 | \$0.11 | (\$4,298.58 |
| C | 0160 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | 39,078 | \$0.11 | \$4,298.58 |
| | 0200 | SEEDING - COOL SEASON MIXTURES | Material | | | -5.6 | \$2,200.00 | (\$12,320.00 |
| | 0200 | SEEDING - COOL SEASON MIXTURES | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item | 5.6 | \$2,200.00 | \$12,320.00 |

Revision 4/1/2020 Page 2 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 3, 2021

Pay Period **Progress Estimate Contract ID** 201218-D05 August 16, 2021 Original Contract Amount\$4,181,671.73 Number Start Pay Period End September 1, 2021 Prime Capital Paving & Construction, Net Change Order 10 (\$950.17) Amount (\$950.17)
Current Contract Amount \$4,180,721.56 Contractor LLĊ

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|--|---|--|--|------------------------|---------------------------------------|-------------------|
| J5S3380 | | | | | Adjustment (0019) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | |
| J5S3384 (| 0230 | ALTERNATE DITCH CHECK | Material | | | -1,490 | \$8.50 | (\$12,665.00) |
| | 0230 | ALTERNATE DITCH CHECK | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user shankb1 overridding Payment Estimate Exception 20 on the current Payment Estimate. | 1,490 | \$8.50 | \$12,665.00 |
| J5S3384 | 0310 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | | -103.4 | \$20.00 | (\$2,068.00) |
| | 0310 | GRAVEL (A) OR CRUSHED STONE (B) Material Material Material Material Material Material Material Material M | | 103.4 | \$20.00 | \$2,068.00 | | |
| | 0330 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | MIXTURE PG64-22 Adjustment Type applied is FUEL | | 200 | \$2.42 | \$484.72 | |
| | 0330 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Overrun | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | -200 | \$58.30 | (\$11,660.72) |
| 0 | 0330 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | Other Item Adjustment | Asphalt Cement Price Adjustment | 200 Tons x (478.75-387.5) x .036 = \$657.00 | | | \$657.00 |
| | 0340 | TACK COAT | Material | | | -25,499 | \$2.00 | (\$50,998.00) |
| | 0340 | TACK COAT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 25,499 | \$2.00 | \$50,998.00 |
| | 0360 | CONSTRUCTION SIGNS | Material | | | -145 | \$6.50 | (\$942.50) |
| | 0360 | CONSTRUCTION SIGNS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | 145 | \$6.50 | \$942.50 |
| | 0400 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | Material | | | -2 | \$6,300.00 | (\$12,600.00) |
| | 0400 | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | 2 | \$6,300.00 | \$12,600.00 |
| | 0550 | SEEDING - COOL SEASON MIXTURES | Overrun | | | -16.7 | \$2,200.00 | (\$36,740.00) |
| | 0550 | SEEDING - COOL SEASON MIXTURES | Material | | | -42.3 | \$2,200.00 | (\$93,060.00) |
| | 0550 | SEEDING - COOL SEASON MIXTURES | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment | 16.7 | \$2,200.00 | \$36,740.00 |

Revision 4/1/2020 Page 3 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 3, 2021

Pay Period **Progress Estimate Contract ID** 201218-D05 August 16, 2021 Original Contract Amount\$4,181,671.73 Number Start Pay Period End September 1, 2021 Prime Capital Paving & Construction, **Net Change Order** (\$950.17) 10 Amount (\$950.17)

Current Contract Amount \$4,180,721.56 Contractor LLĊ

| | | | | | | | Ct Amount \$4 | ,, |
|-------------------|-------------|-----------------------------------|--------------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| 0 | | | | | Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 42.300; Overrun Quantity Balance 16.70. | | | |
| | 0550 | SEEDING - COOL SEASON MIXTURES | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | 42.3 | \$2,200.00 | \$93,060.00 |
| | 0550 | SEEDING - COOL SEASON MIXTURES | Other Item Adjustment | Overrun Re- adjustment | Overrun adjustment. System mistakenly returned overrun amount. will be cleared up on upcoming change order. | | | (\$36,740.00) |
| | 0570 | ROCK DITCH CHECK | Material | | | -7,577 | \$11.00 | (\$83,347.00 |
| | 0570 | ROCK DITCH CHECK | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | 7,577 | \$11.00 | \$83,347.00 |
| | 0580 | ALTERNATE DITCH CHECK | Material | | | -1,270 | \$8.50 | (\$10,795.00 |
| | 0580 | ALTERNATE DITCH CHECK | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | 1,270 | \$8.50 | \$10,795.00 |
| | 0600 | TEMPORARY SEEDING AND MULCHING | Material | | | -5.1 | \$1,750.00 | (\$8,925.00) |
| | 0600 | TEMPORARY SEEDING AND MULCHING | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 23 on the current Payment Estimate. | 5.1 | \$1,750.00 | \$8,925.00 |
| Fotal | | | | | | | | (\$47,259.00 |

Revision 4/1/2020 Page 4 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | | | | | |
|-------------------|----------------------------|--|--------|-----------|--|---|---|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | Location of Work | | | | | |
| J5S3380 | FAS S402(36) | Pavement and shoulder improvements | CC | OSAGE | from Rte. 50 to the end of state maintenance | | | | | | |
| J5S3384 | FAS S402(30) | Pavement and shoulder improvements | В | GASCONADE | from Rte. 28 near E | om Rte. 28 near Bland to Rte. 68 in St. James | | | | | |
| Totals by | Job Numbe | rs | | | | | | | | | |
| J5S3380 | | d Item Pay Item Adjustme | | Item Pay | This Estimate \$1,000.00 \$0.00 \$1,000.00 | Previous \$749,959.00 \$33,103.83 \$783,062.83 | To Date \$750,959.00 \$33,103.83 \$784,062.83 | | | | |
| | Liquid | tive centive dated Damages Contract Adjus | tments | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | | | |
| J5S3384 | | d Item Pay Item Adjustme | | Item Pay | This Estimate \$173,948.57 (\$47,259.00) \$126,689.57 | Previous \$3,013,668.81 \$42,458.77 \$3,056,127.58 | To Date \$3,187,617.38 (\$4,800.23) \$3,182,817.15 | | | | |
| | Liquid | tive centive lated Damages Contract Adjus | tments | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | | | | |

Revision 4/1/2020 Page 5 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|---|-----------------------------------|---------------|--------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 3105002, Project Item Line Number 0310, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 3105002, Project Item Line Number 0040, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 4071005, Project Item Line Number 0340, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 4071005, Project Item Line Number 0070, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 6161005, Project Item Line Number 0360, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 6161005, Project Item Line Number 0090, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 6161098A, Project Item Line Number 0400, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 6161098A, Project Item Line Number 0120, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 6162004, Project Item Line Number 0130, Material Set 616200496, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 6206000C, Project Item Line Number 0150, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 6206000C, Project Item Line Number 0150, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 6206001C, Project Item Line Number 0160, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 6206001C, Project Item Line Number 0160, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 8051000A, Project Item Line Number 0550, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 8051000A, Project Item Line Number 0550, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 8051000A, Project Item Line Number 0200, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 8051000A, Project Item Line Number 0200, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 8061005, Project Item Line Number 0570, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 8061006, Project Item Line Number 0580, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3380, Item 8061006, Project Item Line Number 0230, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 8061017, Project Item Line Number 0600, Material Set 806101796, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 8061017, Project Item Line Number 0600, Material Set 806101796, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5S3384, Item 8061017, Project Item Line Number 0600, Material Set 806101796, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient. | Pending Test | shankb1 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 201218-D05, Contract Project J5S3384, Project Item Line Number 0330, Contract Line Item Number 0330, Item 4020520, Minor Item. | No Remark was entered by Engineer | shankb1 | Acknowledged |
| | | | |

Revision 4/1/2020 Page 6 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|---|-----------------------------------|---------------|------------|
| Estimate Exception Type: Item Overrun: Contract 201218-D05, Contract Project J5S3384, Project Item Line Number 0550, Contract Line Item Number 0550, Item 8051000A, Minor Item. | No Remark was entered by Engineer | shankb1 | Overridden |

Revision 4/1/2020 Page 7 of 26



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|----------------------|----------------|---|--|--|--|--|---|---|--|---|---|---|
| 218-D05 | J5S3380 | 0001 | 0010 | 2079909 | MISC.MODIFIED LINEAR GRADING CLASS 2 | 490.60 | 0.00 | 490.60 | STA | 490.60 | \$300.35 | \$147,351.71 |
| | | 0001 | 0020 | 2142000 | FURNISHING ROCK FILL | 16.00 | 0.00 | 16.00 | CUYD | 0.00 | \$37.50 | \$0.00 |
| | | 0001 | 0030 | 2143000 | PLACING ROCK FILL | 16.00 | 0.00 | 16.00 | CUYD | 0.00 | \$37.50 | \$0.00 |
| | | 0001 | 0040 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 258.00 | 0.00 | 258.00 | TONS | 135.10 | \$30.00 | \$4,053.00 |
| | | 0001 | 0050 | 4013010 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) | 4,131.80 | -732.40 | 3,399.40 | TONS | 3,399.40 | \$51.99 | \$176,734.81 |
| | | 0001 | 0060 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | 4,510.70 | 919.50 | 5,430.20 | TONS | 5,430.20 | \$54.14 | \$293,991.03 |
| | | 0001 | 0070 | 4071005 | TACK COAT | 5,613.00 | -325.00 | 5,288.00 | GAL | 5,288.00 | \$2.00 | \$10,576.00 |
| | | 0001 | 0080 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$500.00 | \$0.00 |
| | | 0001 | 0090 | 6161005 | CONSTRUCTION SIGNS | 982.00 | 5.50 | 987.50 | SQFT | 987.50 | \$7.25 | \$7,159.38 |
| | | 0001 | 0100 | 6161009 | FLAG ASSEMBLY | 9.00 | 0.00 | 9.00 | EA | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 0110 | 6161025 | CHANNELIZER (TRIM LINE) | 200.00 | 0.00 | 200.00 | EA | 0.00 | \$12.75 | \$0.00 |
| | | 0001 | 0120 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 1.00 | 1.00 | 2.00 | EA | 2.00 | \$2,250.00 | \$4,500.00 |
| | | 0001 | 0130 | 6162004 | TEMPORARY SHORT-TERM RUMBLE STRIPS | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$1,000.00 | \$4,000.00 |
| | | 0001 | 0140 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$59,450.09 | \$59,450.09 |
| | | 0001 | 0150 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 49,357.00 | 0.00 | 49,357.00 | LF | 39,486.00 | \$0.10 | \$3,948.60 |
| | | 0001 | 0160 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 48,848.00 | 0.00 | 48,848.00 | LF | 39,078.00 | \$0.11 | \$4,298.58 |
| | | 0001 | 0170 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 130.00 | 0.00 | 130.00 | SQYD | 130.00 | \$45.56 | \$5,922.80 |
| | | 0001 | 0180 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 347.10 | 0.00 | 347.10 | STA | 0.00 | \$10.00 | \$0.00 |
| | | 0001 | 0190 | 6261001 | BITUMINOUS CENTERLINE RUMBLE STRIP | 226.80 | 0.00 | 226.80 | STA | 0.00 | \$10.00 | \$0.0 |
| | | 0001 | 0200 | 8051000A | SEEDING - COOL SEASON MIXTURES | 5.60 | 3.40 | 9.00 | ACRE | 5.60 | \$2,200.00 | \$12,320.00 |
| | | 0001 | 0210 | 8061004 | SEDIMENT TRAP ROCK | 47.00 | 0.00 | 47.00 | CUYD | 0.00 | \$58.50 | \$0.00 |
| | | 0001 | 0220 | 8061005 | ROCK DITCH CHECK | 1,404.00 | -1,404.00 | 0.00 | LF | 0.00 | \$11.00 | \$0.00 |
| | | 0001 | 0230 | 8061006 | ALTERNATE DITCH CHECK | 374.00 | 1,116.00 | 1,490.00 | LF | 1,490.00 | \$8.50 | \$12,665.00 |
| | | 0001 | 0240 | 8061016 | SEDIMENT REMOVAL | 159.00 | 0.00 | 159.00 | CUYD | 100.00 | \$10.00 | \$1,000.00 |
| | | 0001 | 0250 | 8061017 | TEMPORARY SEEDING AND MULCHING | 1.10 | 0.00 | 1.10 | ACRE | 0.00 | \$1,750.00 | \$0.00 |
| | | 0001 | 0260 | 8061019 | SILT FENCE | 2,340.00 | -2,060.00 | 280.00 | LF | 280.00 | \$2.10 | \$588.00 |
| | | 0040 | 0270 | 9039901 | MISC.ADJUST EXISTING SIGNS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$2,400.00 | \$2,400.00 |
| | J5S3384 | 0001 | | Posted to D | ate as of Report Generated Date | | | | | | | \$750,958.99 |
| | | | 0280 | 2022010 | | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,600.00 | \$0.00 |
| | | | 0280 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS STA | 0.00 | \$3,600.00 \$306.51 | |
| | | 0001 | 0290 | 2079909 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 | 2,198.50 | 0.00 | 2,198.50 | STA | 2,088.50 | \$306.51 | \$640,146.14 |
| | | 0001 | 0290 | 2079909 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III | 2,198.50 | 0.00 | 2,198.50 9.00 | STA 100F | 2,088.50 | \$306.51 \$1,200.00 | \$640,146.14 \$0.00 |
| | | 0001 0001 0001 | 0290 0300 0310 | 2079909 2153000 3105002 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) | 2,198.50 9.00 1,230.00 | 0.00 | 2,198.50 9.00 1,230.00 | STA 100F TONS | 2,088.50 0.00 103.40 | \$306.51 \$1,200.00 \$20.00 | \$640,146.14 \$0.00 \$2,068.00 |
| | | 0001 | 0290 | 2079909 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE | 2,198.50 | 0.00 | 2,198.50 9.00 | STA 100F | 2,088.50 | \$306.51 \$1,200.00 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 |
| | | 0001 0001 0001 0001 | 0290 0300 0310 0320 | 2079909 2153000 3105002 4013010 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) | 2,198.50 9.00 1,230.00 18,506.00 | 0.00 0.00 0.00 0.00 | 2,198.50 9.00 1,230.00 18,506.00 | STA 100F TONS TONS | 2,088.50 0.00 103.40 14,861.10 | \$306.51 \$1,200.00 \$20.00 \$48.48 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 |
| | | 0001 0001 0001 0001 | 0290 0300 0310 0320 0330 | 2079909 2153000 3105002 4013010 4020520 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 | 0.00 0.00 0.00 0.00 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 | STA 100F TONS TONS TONS | 2,088.50 0.00 103.40 14,861.10 24,605.80 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 | \$640,146.1 \$0.00 \$2,068.00 \$720,466.1 \$1,374,972.10 \$50,998.00 |
| | | 0001 0001 0001 0001 0001 | 0290 0300 0310 0320 0330 | 2079909 2153000 3105002 4013010 4020520 4071005 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 | 0.00 0.00 0.00 0.00 0.00 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 | STA 100F TONS TONS TONS GAL | 2,088.50 0.00 103.40 14,861.10 24,605.80 25,499.00 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 \$50,998.00 |
| | | 0001 0001 0001 0001 0001 0001 | 0290 0300 0310 0320 0330 0340 | 2079909 2153000 3105002 4013010 4020520 4071005 6123000A | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 | 0.00 0.00 0.00 0.00 0.00 0.00 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 | STA 100F TONS TONS TONS GAL EA | 2,088.50 0.00 103.40 14,861.10 24,605.80 25,499.00 0.00 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 \$2.00 \$500.00 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 \$50,998.00 \$0.00 |
| | | 0001 0001 0001 0001 0001 0001 0001 | 0290 0300 0310 0320 0330 0340 0350 | 2079909 2153000 3105002 4013010 4020520 4071005 6123000A 6161005 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 2,683.00 | 0.00 0.00 0.00 0.00 0.00 0.00 0.00 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 2,683.00 | STA 100F TONS TONS TONS GAL EA SQFT | 2,088.50 0.00 103.40 14,861.10 24,605.80 25,499.00 0.00 145.00 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 \$2.00 \$500.00 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 \$50,998.00 \$0.00 |
| | | 0001 0001 0001 0001 0001 0001 0001 000 | 0290 0300 0310 0320 0330 0340 0350 0360 | 2079909 2153000 3105002 4013010 4020520 4071005 6123000A 6161005 6161008 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 2,683.00 4.00 | 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 2,683.00 4.00 | STA 100F TONS TONS TONS GAL EA SQFT EA | 2,088.50 0.00 103.40 14,861.10 24,605.80 25,499.00 0.00 145.00 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 \$2.00 \$500.00 \$6.50 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 \$50,998.00 \$0.00 \$942.50 |
| | | 0001 0001 0001 0001 0001 0001 0001 000 | 0290 0300 0310 0320 0330 0340 0350 0360 0370 | 2079909 2153000 3105002 4013010 4020520 4071005 6123000A 6161005 6161008 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 2,683.00 4.00 20.00 | 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 2,683.00 4.00 20.00 | STA 100F TONS TONS TONS GAL EA SQFT EA EA | 2,088.50 0.00 103.40 14,861.10 24,605.80 25,499.00 0.00 145.00 0.00 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 \$2.00 \$500.00 \$6.50 \$50.00 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 \$50,998.00 \$0.00 \$942.50 \$0.00 \$0.00 |
| | | 0001 0001 0001 0001 0001 0001 0001 000 | 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380 | 2079909 2153000 3105002 4013010 4020520 4071005 6123000A 6161005 6161008 6161009 | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 2,683.00 4.00 20.00 250.00 | 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2,683.00 4.00 20.00 250.00 | STA 100F TONS TONS GAL EA SQFT EA EA | 2,088.50 0.00 103.40 14,861.10 24,605.80 25,499.00 0.00 145.00 0.00 0.00 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 \$2.00 \$500.00 \$6.50 \$50.00 \$25.00 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 \$50,998.00 \$0.00 \$942.50 \$0.00 \$0.00 \$12,600.00 |
| | | 0001 0001 0001 0001 0001 0001 0001 000 | 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380 0390 | 2079909 2153000 3105002 4013010 4020520 4071005 6123000A 6161005 6161008 6161009 6161025 6161098A | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2.00 2,683.00 4.00 250.00 2.00 | 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2,683.00 4.00 20.00 250.00 | STA 100F TONS TONS TONS GAL EA SQFT EA EA EA | 2,088.50 0.00 103.40 14,861.10 24,605.80 25,499.00 0.00 145.00 0.00 0.00 0.00 0.00 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 \$2.00 \$500.00 \$6.50 \$50.00 \$13.00 \$6,300.00 | \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 \$50,998.00 \$0.00 \$942.50 \$0.00 \$12,600.00 |
| | | 0001 0001 0001 0001 0001 0001 0001 000 | 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380 0390 0400 | 2079909 2153000 3105002 4013010 4020520 4071005 6123000A 6161005 6161008 6161009 6161025 6161098A | REMOVAL OF IMPROVEMENTS MISC.MODIFIED LINEAR GRADING CLASS 2 SHAPING SLOPES, CLASS III GRAVEL (A) OR CRUSHED STONE (B) BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING) BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING) TACK COAT TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM FLAG ASSEMBLY CHANNELIZER (TRIM LINE) CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2,000 4.00 250.00 2.00 4.00 | 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0 | 2,198.50 9.00 1,230.00 18,506.00 21,051.80 26,165.00 2,683.00 4.00 250.00 2.00 4.00 | STA 100F TONS TONS GAL EA SQFT EA EA EA | 2,088.50 0.00 103.40 14,861.10 24,605.80 25,499.00 0.00 145.00 0.00 0.00 0.00 0.00 | \$306.51 \$1,200.00 \$20.00 \$48.48 \$55.88 \$2.00 \$500.00 \$6.50 \$25.00 \$13.00 \$6,300.00 | \$0.00 \$640,146.14 \$0.00 \$2,068.00 \$720,466.13 \$1,374,972.10 \$50,998.00 \$0.00 \$942.50 \$0.00 \$12,600.00 \$133,194.15 |

Page 8 of 26 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 201218-D05 | J5S3384 | | | | WHITE | | | | | | | |
| | | 0001 | 0450 | 6200018 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW | 148.00 | 0.00 | 148.00 | LF | 0.00 | \$0.35 | \$0.00 |
| | | 0001 | 0460 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$350.00 | \$0.00 |
| | | 0001 | 0470 | 6200042 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES | 14.00 | 0.00 | 14.00 | EA | 0.00 | \$0.50 | \$0.00 |
| | | 0001 | 0480 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 234,992.00 | 0.00 | 234,992.00 | LF | 0.00 | \$0.09 | \$0.00 |
| | | 0001 | 0490 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 196,789.00 | 0.00 | 196,789.00 | LF | 0.00 | \$0.10 | \$0.00 |
| | | 0001 | 0500 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 290.00 | 0.00 | 290.00 | SQYD | 290.00 | \$12.32 | \$3,572.80 |
| | | 0001 | 0510 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 2,022.00 | 0.00 | 2,022.00 | SQYD | 2,022.00 | \$12.32 | \$24,911.04 |
| | | 0001 | 0520 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 1,916.20 | 0.00 | 1,916.20 | STA | 897.20 | \$10.00 | \$8,972.00 |
| | | 0001 | 0530 | 6261001 | BITUMINOUS CENTERLINE RUMBLE STRIP | 1,104.30 | 0.00 | 1,104.30 | STA | 1,104.30 | \$10.00 | \$11,043.00 |
| | | 0001 | 0540 | 7039902 | MISC.CULVERT HEADWALL MODIFICATION | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,000.00 | \$1,000.00 |
| | | 0001 | 0550 | 8051000A | SEEDING - COOL SEASON MIXTURES | 25.60 | 0.00 | 25.60 | ACRE | 42.30 | \$2,200.00 | \$93,060.00 |
| | | 0001 | 0560 | 8061004 | SEDIMENT TRAP ROCK | 212.80 | 0.00 | 212.80 | CUYD | 0.00 | \$53.50 | \$0.00 |
| | | 0001 | 0570 | 8061005 | ROCK DITCH CHECK | 6,384.00 | 1,193.00 | 7,577.00 | LF | 7,577.00 | \$11.00 | \$83,347.00 |
| | | 0001 | 0580 | 8061006 | ALTERNATE DITCH CHECK | 1,703.00 | -433.00 | 1,270.00 | LF | 1,270.00 | \$8.50 | \$10,795.00 |
| | | 0001 | 0590 | 8061016 | SEDIMENT REMOVAL | 723.00 | 0.00 | 723.00 | CUYD | 525.00 | \$10.00 | \$5,250.00 |
| | | 0001 | 0600 | 8061017 | TEMPORARY SEEDING AND MULCHING | 5.10 | 0.00 | 5.10 | ACRE | 5.10 | \$1,750.00 | \$8,925.00 |
| | | 0001 | 0610 | 8061019 | SILT FENCE | 10,641.00 | -9,968.00 | 673.00 | LF | 645.00 | \$2.10 | \$1,354.50 |
| | | 0010 | 0620 | 6061010 | GUARDRAIL TYPE A | 13.00 | 0.00 | 13.00 | LF | 0.00 | \$30.00 | \$0.00 |
| | | 0010 | 0630 | 6061069 | MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB) | 7.00 | 0.00 | 7.00 | EA | 0.00 | \$2,900.00 | \$0.00 |
| | | 0010 | 0640 | 6062100 | BRIDGE ANCHOR SECTION (CURB TYPE) | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$2,100.00 | \$0.00 |
| | | 0010 | 0650 | 6062303 | ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$400.00 | \$0.00 |
| | | 0010 | 0660 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 7.00 | 0.00 | 7.00 | EA | 0.00 | \$2,800.00 | \$0.00 |
| | | 0010 | 0670 | 6066610 | END ANCHOR | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$1,200.00 | \$0.00 |
| | | 0030 | 0680 | 9029902 | MISC.LOOP DETECTOR | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,600.00 | \$0.00 |
| | | 0040 | 0690 | 9039901 | MISC.ADJUST EXISTING SIGNS | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$20,000.00 | \$0.00 |
| | | 0070 | 0700 | 7039902 | MISC.BARRIER END MODIFICATION | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$2,480.00 | \$0.00 |
| | | 0071 | 0710 | 7034600 | CURB BLOCKOUT | 236.00 | 0.00 | 236.00 | LF | 0.00 | \$121.75 | \$0.00 |
| | Project J | 5S3384 - To | otal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$3,187,617.36 |
| 201218-D05 Ove | erall - Total | Value Pos | ted to Da | te as of Repo | ort Generated Date | | | | | | | \$3,938,576.35 |

Page 9 of 26 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3380

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|------------------|-------------|-------------------------|--------------------|-------|--|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0240 | 8061016 | SEDIMENT REMOVAL | 7/19/21 | 9/3/21 | 100.00 | CUYD | Sediment Removal along entire length of project. | .017 | | 4.696 | | |

Project: J5S3384

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|--|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0290 | 2079909 | MISC. GRADING | 9/1/21 | 9/2/21 | -110.00 | STA | 5% withholding for drainage check. | | | | | |
| | | | | 9/2/21 | 261.70 | STA | Finish grading payment. | 0 | | 21.303 | | |
| 0330 | 4020520 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR | 7/19/21 | 9/3/21 | 200.00 | TONS | SBL | 6.8 | | 10.93 | | |
| 0520 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 9/1/21 | 9/2/21 | 897.20 | STA | | 0.00 | | 20.303 | | |
| 0530 | 6261001 | BITUMINOUS CENTERLINE RUMBLE STRIP | 9/1/21 | 9/2/21 | 1,104.30 | STA | | 0.00 | | 20.986 | | |
| 0550 | 8051000A | SEEDING - COOL SEASON MIXTURES | 8/27/21 | 9/2/21 | 42.30 | ACRE | NBL and SBL Rt B Gasconade/Phelps | 0.00 | | 21.303 | | |
| 0590 | 8061016 | SEDIMENT REMOVAL | 7/19/21 | 9/3/21 | 320.00 | CUYD | Sediment Removal along entire length of project. | 0.00 | | 20.303 | | |

<u>The information below this line are details for Construction Signs (if applicable).</u>
No Data Available

Revision 4/1/2020 Page 10 of 26



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------------|--|
| J5S3380 | 0040 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | 4 | Jun 3, 2021 | SYSTEM | \$4,053.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$4,053.00) | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$4,053.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$4,053.00) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$4,053.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$4,053.00) | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$4,053.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$4,053.00) | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$4,053.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$4,053.00) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$4,053.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$4,053.00) | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$4,053.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$4,053.00) | |
| | | | | - Total | | | | \$0.00 | |
| | 0040 - | Total | Material - To | tal | | | | \$0.00 | |
| | 0050 | BITUMINOUS PAVEMENT | Other Item | ACAD | 2 | May 4, 2021 | shankb1 | \$0.00 \$5,795.98 | 3399.4 tons x .031 x (442.5-387.5) = \$5795.98 |
| | | MIXTURE PG64-22 (BAS | Adjustment | ACAD - Tota | al | 2021 | | \$5,795.98 | |
| | | 1 004 22 (8/10 | Other Item A | djustment - T | | | | \$5,795.98 | |
| | | | Price FUEL | | 2 | May 4, 2021 | SYSTEM | \$6,094.45 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$6,094.45 | |
| | | | Price FUEL - | Total | | | | \$6,094.45 | |
| | 0050 - | Total | | | | | | \$11,890.43 | |
| | 0060 | BITUMINOUS PAVEMENT MIXTURE | Material | | 2 | May 4, 2021 | SYSTEM | \$200,918.95 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | PG64-22 (SUR | | | 2 | May 4, 2021 | SYSTEM | (\$200,918.95) | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$293,991.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$293,991.03) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$293,991.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$293,991.03) | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$293,991.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |



| ct | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | |
|----|--------|-------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|---|---|---|----------------|--------|---------------|---|
| 80 | 0060 | BITUMINOUS PAVEMENT | Material | | 5 | Jun 17, 2021 | SYSTEM | (\$293,991.03) | | | | | | |
| | | MIXTURE PG64-22 (SUR | | | 6 | Jul 1, 2021 | SYSTEM | \$293,991.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$293,991.03) | | | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$293,991.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$293,991.03) | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | |
| | | | Other Item Adjustment | ACAD | 2 | May 4, 2021 | shankb1 | \$6,735.65 | 3711.1 Tons x .033 x (442.5-387.5) = 6735.65 | | | | | |
| | | | rajustinoni | | 3 | May 18, 2021 | shankb1 | \$3,829.30 | (455-387.5) x .033 x 1719.1 tons = \$3829.3 | | | | | |
| | | | | ACAD - Tot | al | 2021 | | \$10,564.95 | | | | | | |
| | | | Other Items | | | | | | | | | | | |
| | | | | djustment - T | | | | \$10,564.95 | | | | | | |
| | | | Overrun | Overrun | 3 | May 18, 2021 | SYSTEM | (\$51,918.65) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | |
| | | | | | 3 | May 18, 2021 | shankb1 | (\$51,918.65) | System mistakenly returned overrun adjustment. this will be corrected on upcoming change order. | | | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$51,918.65 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 5430.200; Overrun Quantity Balance 919.50. | | | | | |
| | | | | 4 | Jun 3, 2021 | SYSTEM | (\$51,584.84) | Averaged Price Adjustment from this item on all previous payment estimates of '1.96097' is applied (if non-zero). | | | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$51,584.84 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 13 on the current Payment Estimate. Material Insufficiency Quantity 5430.200; Overrun Quantity Balance 919.50. | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$51,584.84) | Averaged Price Adjustment from this item on all previous payment estimates of '1.96097' is applied (if non-zero). | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$51,584.84 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 5430.200; Overrun Quantity Balance 919.50. | | | | | |
| | | | | | | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$51,584.84) | Averaged Price Adjustment from this item on all previous payment estimates of '1.96097' is applied (if non-zero). |
| | | | | | | | | | | | | | 6 | Jul 1, 2021 |
| | | | | | 7 | Jul 19, 2021 | shankb1 | \$51,918.65 | Returning overrun/material adjustment from pervious estimates. | | | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | | | | |
| | | | Overrun - To | tal | | | | \$0.00 | | | | | | |
| | | | Price FUEL | | 2 | May 4, 2021 | SYSTEM | \$6,653.26 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$3,995.19 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | |
| | | | | - Total | | | | \$10,648.45 | | | | | | |
| | | | Price FUEL - | | | | | \$10,648.45 | | | | | | |
| | 0060 - | Total | - HOUT OLL - | - Fotal | | | | | | | | | | |
| | 0060 - | TACK COAT | Material | | 2 | May 4, 2021 | SYSTEM | \$21,213.40 \$7,080.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment | | | | | |
| | | | | | 2 | May 4, | SYSTEM | (\$7,080.00) | Estimate Exception 2 on the current Payment Estimate. | | | | | |
| | | | | | - | 2021 | CIGILIVI | (Ψ1,000.00) | | | | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$10,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--------------------|--------------------|-----------------------------|----------------|-----------------|---------------|------------------|--|
| J5S3380 | 0070 | TACK COAT | Material | | 3 | May 18, 2021 | SYSTEM | (\$10,576.00) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$10,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$10,576.00) | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$10,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$10,576.00) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$10,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$10,576.00) | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$10,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$10,576.00) | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$10,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$10,576.00) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$10,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$10,576.00) | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$10,576.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$10,576.00) | |
| | | | | - Total | | | | \$0.00 | |
| | 0070 - | Total | Material - To | tal | | | | \$0.00 \$0.00 | |
| | 0090 | CONSTRUCTION SIGNS | Material | | 1 | Apr 18, 2021 | SYSTEM | \$2,990.62 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 1 | Apr 18, 2021 | SYSTEM | (\$2,990.62) | |
| | | | | | 2 | May 4, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 2 | May 4, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| J5S3380 | 0090 | CONSTRUCTION SIGNS | Material | | 6 | Jul 1, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$7,159.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$7,159.38) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Other Item Adjustment | OADJ | | May 4, 2021 | shankb1 | (\$39.88) | System mistakenly return overrun amount of 5.5 sq ft of signs. To be reversed with upcoming change order. |
| | | | | OADJ - Tota | | | | (\$39.88) | |
| | | | Other Item A | | | | | (\$39.88) | |
| | | | Overrun | Overrun | 2 | May 4, 2021 | SYSTEM | \$39.88 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 987.500; Overrun Quantity Balance 5.50. |
| | | | | | 2 | May 4, 2021 | SYSTEM | (\$39.88) | |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$39.88) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$39.88 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 987.500; Overrun Quantity Balance 5.50. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$39.88) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$39.88 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 987.500; Overrun Quantity Balance 5.50. |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$39.88) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$39.88 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 987.500; Overrun Quantity Balance 5.50. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$39.88) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$39.88 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 24 on the current Payment Estimate. Material Insufficiency Quantity 987.500; Overrun Quantity Balance 5.50. |
| | | | | | 7 | Jul 19, 2021 | shankb1 | \$39.88 | Returning overrun/material adjustment from pervious estimates. |
| | | | | Overrun - T | otal | | | \$39.88 | |
| | | | Overrun - To | tal | | | | \$39.88 | |
| | 0090 - | · Total | | | | | | \$0.00 | |
| | 0120 | CMS W/O COMMUNICATION INTERFACE, | Material | | 1 | Apr 18, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | CONT F/ | | | 1 | Apr 18, | SYSTEM | (\$4,500.00) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| J5S3380 | 0120 | CMS W/O | Material | | | 2021 | | | |
| | | COMMUNICATION INTERFACE, CONT F/ | | | 2 | May 4, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 2 | May 4, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$4,500.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$4,500.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | | | | | \$0.00 | |
| | | | Other Item Adjustment | OADJ | | May 4, 2021 | shankb1 | (\$2,250.00) | System mistakenly return overrun amount of 1 CMS board. To be reversed with upcoming change order. |
| | | | | OADJ - Tota | | | | (\$2,250.00) | |
| | | | | djustment - T | | | | (\$2,250.00) | |
| | | | Overrun | Overrun | 1 | Apr 19, 2021 | shankb1 | (\$2,250.00) | System mistakenly return \$2250 in an overrun. Payment will be returned with the approval of upcoming change order. shankb1 4/19/2021 |
| | | | | | 1 | Apr 18, 2021 | SYSTEM | \$2,250.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 2.000; Overrun Quantity Balance 1.00. |
| | | | | | 1 | Apr 18, 2021 | SYSTEM | (\$2,250.00) | |
| | | | | | 2 | May 4, 2021 | SYSTEM | (\$2,250.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero). |
| | | | | | 2 | May 4, 2021 | SYSTEM | \$2,250.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 2.000; Overrun Quantity Balance 1.00. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|-----------------|--------------|--|--|-----------------|-----------------|------------|--|--|------------|---|----------------|--------|------------|---|
| J5S3380 | 0120 | CMS W/O COMMUNICATION | Overrun | Overrun | 3 | May 18, 2021 | SYSTEM | (\$2,250.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | | | | | | |
| | | INTERFACE, CONT F/ | | | 3 | May 18, 2021 | SYSTEM | \$2,250.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 13 on the current Payment Estimate. Material Insufficiency Quantity 2.000; Overrun Quantity Balance 1.00. | | | | | | | | | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$2,250.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | | | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$2,250.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 2.000; Overrun Quantity Balance 1.00. | | | | | | | | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$2,250.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | | | | | | |
| | | | Overrun - Tot | | 5 | Jun 17, 2021 | SYSTEM | \$2,250.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 2.000; Overrun Quantity Balance 1.00. | | | | | | | | | | | | |
| | | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$2,250.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | | | | | |
| | | | | | | 6 | Jul 1, 2021 | SYSTEM | \$2,250.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 2.000; Overrun Quantity Balance 1.00. | | | | | | | | | | | |
| | | | | | | 7 | Jul 19, 2021 | shankb1 | \$4,500.00 | Returning overrun/material adjustment from pervious estimates. | | | | | | | | | | | |
| | | | | Overrun - T | otal | | | \$2,250.00 | | | | | | | | | | | | | |
| | | | | tal | | | | \$2,250.00 | | | | | | | | | | | | | |
| | 0120 - | | | | | | | \$0.00 | | | | | | | | | | | | | |
| | 0130 | TEMPORARY SHORT-TERM RUMBLE STRIPS | Material | | 2 | May 4, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 2 | May 4, 2021 | SYSTEM | (\$4,000.00) | | | | | | | | | | | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | | | | | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$4,000.00) | | | | | | | | | | | | | |
| | | | | | | 4 | Jun 3, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$4,000.00) | | | | | | | | | | | | |
| | | | | | | | | | | | 5 | Jun 17, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$4,000.00) | | | | | | | | | | | | | |
| | | | | | | 6 | Jul 1, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$4,000.00) | | | | | | | | | | | | | |
| | | | | | | | | | | | | | 7 | Jul 19, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$4,000.00) | | | | | | | | | | | | | |
| | | | | | 8 | | | | | 8 | 1 | 8 | | | 8 | | 8 | Aug 3, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$4,000.00) | | | | | | | | | | | | |
| | | | | | | | | | | 9 | Aug 16, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | |
| | | | | | 9 | Aug 16, | SYSTEM | (\$4,000.00) | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks | | | | | | | | | |
|---------|--------|--|----------------|--------------------|------|-----------------|---------|--------------|---|--------|--------------|-----------------|--------|--------------|-----------------|--------|------------|---|
| riojeci | Lille | Description | Туре | Adjustment Type | | Date | By | Amount | IVEIIIdINS | | | | | | | | | |
| J5S3380 | 0130 | TEMPORARY | Material | | | 2021 | | | | | | | | | | | | |
| | | SHORT-TERM RUMBLE STRIPS | | | 10 | Sep 3, 2021 | SYSTEM | \$4,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$4,000.00) | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | |
| | | | Material - Tot | tal | | | | \$0.00 | | | | | | | | | | |
| | 0130 - | · Total | | | | | | \$0.00 | | | | | | | | | | |
| | 0150 | 4 IN. WHITE WATERBORNE PAVEMENT | Material | | 6 | Jul 1, 2021 | SYSTEM | \$3,948.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | |
| | | MARKING | | | 6 | Jul 1, 2021 | SYSTEM | (\$3,948.60) | | | | | | | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$3,948.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$3,948.60) | | | | | | | | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$3,948.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$3,948.60) | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$3,948.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$3,948.60) | | | | | | | | | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$3,948.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | | | | | | |
| | | | | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$3,948.60) | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | |
| | | | Material - Tot | tal | | | | \$0.00 | | | | | | | | | | |
| | 0150 - | · Total | | | | | | \$0.00 | | | | | | | | | | |
| | 0160 | 4 IN. YELLOW WATERBORNE PAVEMENT | Material | | 6 | Jul 1, 2021 | SYSTEM | \$4,298.58 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | | | | | | |
| | | MARKING | | | 6 | Jul 1, 2021 | SYSTEM | (\$4,298.58) | | | | | | | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$4,298.58 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$4,298.58) | | | | | | | | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$4,298.58 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$4,298.58) | | | | | | | | | | |
| | | | 9 | | | | | | | 9 | | 9 | 9 | 9 | Aug 16, 2021 | SYSTEM | \$4,298.58 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | | | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$4,298.58) | | | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$4,298.58 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$4,298.58) | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | |
| | | | Material - Tot | tal | | | | \$0.00 | | | | | | | | | | |
| | 0160 - | · Total | | | | | | \$0.00 | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | |



| | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--------------------------------------|--------------------|-----------------------------|-------------------------|---|--|--|--|
| J5S3380 | 0200 | SEEDING - COOL SEASON MIXTURES | Material | | 5 | Jun 17, 2021 | SYSTEM | \$12,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$12,320.00) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$12,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$12,320.00) | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$12,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$12,320.00) | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$12,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user shankb1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$12,320.00) | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$12,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$12,320.00) | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$12,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$12,320.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0200 - | - Total | | | | | | \$0.00 | |
| | | | | | | | | | |
| | 0230 | ALTERNATE DITCH CHECK | Material | | 1 | Apr 18, 2021 | SYSTEM | \$9,180.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | 0230 | | Material | | 1 | | SYSTEM | \$9,180.00 (\$9,180.00) | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment |
| | 0230 | | Material | | | 2021 Apr 18, | | | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment |
| | 0230 | | Material | | 1 | 2021 Apr 18, 2021 May 4, | SYSTEM | (\$9,180.00) | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment |
| | 0230 | | Material | | 1 2 | 2021 Apr 18, 2021 May 4, 2021 May 4, | SYSTEM SYSTEM | (\$9,180.00) \$12,665.00 | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment |
| | 0230 | | Material | | 1 2 2 | 2021 Apr 18, 2021 May 4, 2021 May 4, 2021 May 18, | SYSTEM SYSTEM SYSTEM | (\$9,180.00) \$12,665.00 (\$12,665.00) | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment |
| | 0230 | | Material | | 1 2 2 3 | 2021 Apr 18, 2021 May 4, 2021 May 4, 2021 May 18, 2021 May 18, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM | (\$9,180.00) \$12,665.00 (\$12,665.00) \$12,665.00 | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment |
| | 0230 | | Material | | 1 2 2 3 3 3 | 2021 Apr 18, 2021 May 4, 2021 May 4, 2021 May 18, 2021 May 18, 2021 Jun 3, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$9,180.00) \$12,665.00 (\$12,665.00) \$12,665.00 | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment |
| | 0230 | | Material | | 1 2 2 3 3 4 | 2021 Apr 18, 2021 May 4, 2021 May 4, 2021 May 18, 2021 May 18, 2021 Jun 3, 2021 Jun 3, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$9,180.00) \$12,665.00 (\$12,665.00) \$12,665.00 (\$12,665.00) | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment |
| | 0230 | | Material | | 1 2 2 3 3 4 4 4 | 2021 Apr 18, 2021 May 4, 2021 May 4, 2021 May 18, 2021 Jun 3, 2021 Jun 3, 2021 Jun 17, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$9,180.00) \$12,665.00 (\$12,665.00) \$12,665.00 (\$12,665.00) (\$12,665.00) | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. |
| | 0230 | | Material | | 1 2 2 3 3 4 4 5 5 | 2021 Apr 18, 2021 May 4, 2021 May 18, 2021 May 18, 2021 Jun 3, 2021 Jun 17, 2021 Jun 17, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$9,180.00) \$12,665.00 (\$12,665.00) \$12,665.00 (\$12,665.00) (\$12,665.00) \$12,665.00 | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. |
| | 0230 | | Material | | 1 2 2 3 3 4 4 5 5 5 | 2021 Apr 18, 2021 May 4, 2021 May 4, 2021 May 18, 2021 Jun 3, 2021 Jun 3, 2021 Jun 17, 2021 Jun 17, 2021 Jun 17, 2021 | SYSTEM | (\$9,180.00) \$12,665.00 (\$12,665.00) \$12,665.00 (\$12,665.00) \$12,665.00 (\$12,665.00) | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. |
| | 0230 | | Material | | 1 2 2 3 3 4 4 5 5 5 6 6 | 2021 Apr 18, 2021 May 4, 2021 May 4, 2021 May 18, 2021 Jun 3, 2021 Jun 17, 2021 Jul 1, 2021 Jul 1, 2021 | SYSTEM | (\$9,180.00) \$12,665.00 (\$12,665.00) \$12,665.00 (\$12,665.00) \$12,665.00 (\$12,665.00) \$12,665.00 (\$12,665.00) | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user shankb1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 14 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | | | | | | | | | | | |
|---------|--------------|--------------------------|--------------------------|-----------------------------|----------------|-----------------|----------------|----------------|--|--|--|------------|--|--------|--------------|---|---|---|-----------------|--------|--------------|---|--------|--------------|---|--|---|----------------|--------|------------|
| J5S3380 | J5S3380 0230 | ALTERNATE DITCH CHECK | Material | | 8 | Aug 3, 2021 | SYSTEM | \$12,665.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$12,665.00) | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$12,665.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$12,665.00) | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$12,665.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user shankb1 overridding Payment Estimate Exception 20 on the current Payment Estimate. | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$12,665.00) | | | | | | | | | | | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | | | | | | | | | | | |
| | | | Other Item Adjustment | OADJ | | May 4, 2021 | shankb1 | (\$3,485.00) | System mistakenly return overrun amount of 410' of ADC. To be reversed with upcoming change order. | | | | | | | | | | | | | | | | | | | | | |
| | | | | OADJ - Tota | | | | (\$3,485.00) | | | | | | | | | | | | | | | | | | | | | | |
| | | | Other Item A | | | | | (\$3,485.00) | | | | | | | | | | | | | | | | | | | | | | |
| | | | Overrun | Overrun | 1 | Apr 19, 2021 | shankb1 | (\$6,001.00) | System mistakenly return \$2250 in an overrun. Payment will be returned with the approval of upcoming change order. shankb1 4/19/2021 | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 1 | Apr 18, 2021 | SYSTEM | \$6,001.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 1080.000; Overrun Quantity Balance 706.00. | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 1 | Apr 18, 2021 | SYSTEM | (\$6,001.00) | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 2 | May 4, 2021 | SYSTEM | (\$6,001.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 2 | May 4, 2021 | SYSTEM | \$3,485.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 13 on the current Payment Estimate. Material Insufficiency Quantity 1490.000; Overrun Quantity Balance 1116.00. | | | | | | | | | | | | | | | | | | | | |
| | | | | | 2 | May 4, 2021 | SYSTEM | \$6,001.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 13 on the current Payment Estimate. Material Insufficiency Quantity 1490.000; Overrun Quantity Balance 1116.00. | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 2 | May 4, 2021 | SYSTEM | (\$3,485.00) | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$9,486.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | 3 | May 18, 2021 | SYSTEM | \$9,486.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 14 on the current Payment Estimate. Material Insufficiency Quantity 1490.000; Overrun Quantity Balance 1116.00. | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$9,486.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | | 4 | Jun 3, 2021 | SYSTEM | \$9,486.00 |
| | | | | | | | | | | | | | | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$9,486.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$9,486.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 1490.000; Overrun Quantity Balance 1116.00. | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 6 | 6 | 6 | | | 6 | Jul 1, 2021 | SYSTEM | (\$9,486.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | |
| | | | | | | | 6 | Jul 1, 2021 | SYSTEM | \$9,486.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 1490.000; Overrun Quantity Balance 1116.00. | | | | | | | | | | | | | | | | | | | |
| | | | | | 7 | Jul 19, 2021 | shankb1 | \$9,486.00 | Returning overrun/material adjustment from pervious estimates. | | | | | | | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks | |
|-----------|---------|---|--------------------------|--------------------|------|-----------------|-----------------|----------------|--|--|
| Troject | LIIIC | Description | Туре | Adjustment Type | | Date | By | Amount | Romano | |
| J5S3380 | 0230 | ALTERNATE | Overrun | Overrun - T | otal | | | \$3,485.00 | | |
| | | DITCH CHECK | Overrun - To | tal | | | | \$3,485.00 | | |
| | 0230 - | - Total | | | | | | \$0.00 | | |
| | 0260 | SILT FENCE | Material | | 1 | Apr 18, 2021 | SYSTEM | \$588.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | |
| | | | | | 1 | Apr 18, 2021 | SYSTEM | (\$588.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | | | | | \$0.00 | | |
| | 0260 - | - Total | | | | | | \$0.00 | | |
| J5S3380 - | - Total | | | | | | | \$33,103.83 | | |
| J5S3384 | 0310 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | 9 | Aug 16, 2021 | SYSTEM | \$2,068.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$2,068.00) | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$2,068.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$2,068.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | tal | | | | \$0.00 | | |
| | 0310 - | - Total | | | | | | \$0.00 | | |
| | 0320 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BAS | Material | | 5 | Jun 17, 2021 | SYSTEM | \$499,683.36 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$499,683.36) | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$720,466.13 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$720,466.13) | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$720,466.13 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$720,466.13) | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$720,466.13 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$720,466.13) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | erial - Total | | | | \$0.00 | | |
| | | | Other Item Adjustment | ACAD | 5 | Jun 17, 2021 | shankb1 | \$27,158.95 | 10307.0 tons x (472.5-387.5) x 3.1 AC = 27158.95 | |
| | | | | | 6 | Jul 1, 2021 | shankb1 | \$12,000.05 | 4554.1 tons x 0.031 x (427.5-387.5) | |
| | | | | ACAD - Tota | al | | | \$39,159.00 | | |
| | | | Other Item A | djustment - T | otal | | | \$39,159.00 | | |
| | | | Price FUEL | | 5 | Jun 17, 2021 | SYSTEM | \$24,295.68 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$10,734.92 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | - Total | | | | \$35,030.60 | | |
| | | | Price FUEL - | Total | | | | \$35,030.60 | | |
| | 0320 | - Total | | | | | | \$74,189.60 | | |
| | 0330 | BITUMINOUS PAVEMENT | Material | | 7 | Jul 19, 2021 | SYSTEM | \$325,640.70 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | |
|---------|--------|--------------|--------------------------|-----------------------------|----------------|-----------------|-----------------|------------------|---|--|--|
| J5S3384 | 0330 | MIXTURE | Material | | | | | | Estimate Exception 3 on the current Payment Estimate. | | |
| | | PG64-22 (SUR | | | 7 | Jul 19, 2021 | SYSTEM | (\$325,640.70) | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$1,363,796.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$1,363,796.10) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - Tot | tal | | | | \$0.00 | | | |
| | | | Other Item Adjustment | ACAD | 7 | Jul 19, 2021 | shankb1 | \$19,143.34 | 5827.5 tons x (478.75-387.5) x 0.036 = \$19,143.34 | | |
| | | | , | | 8 | Aug 3, 2021 | shankb1 | \$61,029.72 | 18578.3 tons x (478.75-387.5) x 0.036 = \$61029.72 | | |
| | | | | | 10 | Sep 3, | shankb1 | \$657.00 | 200 Tons x (478.75-387.5) x .036 = \$657.00 | | |
| | | | | ACAD - Tota | al | 2021 | | \$80,830.06 | | | |
| | | | | OADJ | | Aug 16, | shankb1 | \$195,550.27 | Overrun Re-adjustment. This offsets the adjustment from the previous | | |
| | | | | OADS | 9 | 2021 | SHAHKDI | φ195,550.27 | estimate. | | |
| | | | | OADJ - Tota | al | | | \$195,550.27 | | | |
| | | | Other Item A | djustment - T | otal | | | \$276,380.33 | | | |
| | | | Overrun | Overrun | 8 | Aug 3, 2021 | SYSTEM | (\$195,550.28) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | |
| | | | | | 8 | Aug 3, 2021 | shankb1 | (\$195,550.28) | System mistakenly returned overrun adjustment. Will be resolved with upcoming change order. | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$130,996.53 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 23 on the current Payment Estimate. Material Insufficiency Quantity 24405.800; Overrun Quantity Balance 3354.00. | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$64,553.75 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 23 on the current Payment Estimate. Material Insufficiency Quantity 24405.800; Overrun Quantity Balance 3354.00. | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$195,550.27) | Averaged Price Adjustment from this item on all previous payment estimates of '2.42360' is applied (if non-zero). | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$11,660.72) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | |
| | | | | Overrun - T | otal | | | (\$402,761.27) | | | |
| | | | Overrun - To | tal | | | | (\$402,761.27) | | | |
| | | | Price FUEL | | 7 | Jul 19, 2021 | SYSTEM | \$14,123.53 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$45,026.36 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$484.72 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | |
| | | | | - Total | | | | \$59,634.61 | | | |
| | | | Price FUEL - | Total | | | | \$59,634.61 | | | |
| | 0330 - | Total | | | | | | (\$66,746.33) | | | |
| | 0340 | TACK COAT | Material | | 7 | Jul 19, 2021 | SYSTEM | \$11,258.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$11,258.00) | | | |
| | | | | | | | 8 | Aug 3, 2021 | SYSTEM | \$50,998.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$50,998.00) | | | |
| | | | | | | 9 | Aug 16, 2021 | SYSTEM | \$50,998.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$50,998.00) | | | |
| | | | | | 10 | Sep 3, | SYSTEM | \$50,998.00 | This adjustment offsets the original system-generated Material Payment | | |
| | | | | | | | | | | | |



| ect | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|-----|--------|--|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|--|
| 384 | 0340 | TACK COAT | Material | | | 2021 | | | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$50,998.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | tal | | | | \$0.00 | | |
| | 0340 - | Total | | | | | | \$0.00 | | |
| | 0360 | CONSTRUCTION SIGNS | Material | | 1 | Apr 18, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | |
| | | | | | 1 | Apr 18, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | 2 | May 4, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 2 | May 4, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | | 5 | Jun 17, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$942.50) | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$942.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$942.50) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - To | tal | | | | \$0.00 | | |
| | 0360 - | Total | | | | | | \$0.00 | | |
| | 0400 | CMS W/O COMMUNICATION INTERFACE, | Material | | 1 | Apr 18, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. | |
| | | CONT F/ | | | 1 | Apr 18, 2021 | SYSTEM | (\$12,600.00) | | |
| | | | | | 2 | May 4, | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | |
|---------|----------------|--------------------------------------|--------------------------|-----------------------------|----------------|-----------------|----------------|-----------------------|--|--|--|
| J5S3384 | 0400 | CMS W/O COMMUNICATION | Material | | | 2021 | | | Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | INTERFACE, CONT F/ | | | 2 | May 4, 2021 | SYSTEM | (\$12,600.00) | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$12,600.00) | | | |
| | | | | | | | 4 | Jun 3, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | | | | | 4 | Jun 3, 2021 | SYSTEM |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$12,600.00) | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$12,600.00) | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$12,600.00) | | | |
| | | | | | | 8 | Aug 3, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$12,600.00) | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$12,600.00) | | | |
| | | | | | | 10 | Sep 3, 2021 | SYSTEM | \$12,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$12,600.00) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | 0.400 | | Material - To | ial | | | | \$0.00 | | | |
| | 0400 - 0550 | SEEDING - COOL SEASON MIXTURES | Material | | 10 | Sep 3, 2021 | SYSTEM | \$0.00 \$93,060.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 15 on the current Payment Estimate. | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$93,060.00) | , -, -, -, -, -, -, -, -, -, -, -, -, -, | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - To | al | | | | \$0.00 | | | |
| | | | Other Item Adjustment | OADJ | 10 | Sep 3, 2021 | shankb1 | (\$36,740.00) | Overrun adjustment. System mistakenly returned overrun amount. will be cleared up on upcoming change order. | | |
| | | | | OADJ - Tota | al | | | (\$36,740.00) | | | |
| | | | Other Item A | djustment - T | otal | | | (\$36,740.00) | | | |
| | | | Overrun | | 10 | Sep 3, 2021 | SYSTEM | \$36,740.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 42.300; Overrun Quantity Balance 16.70. | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$36,740.00) | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks | | | | | | | |
|---------|--------|--------------------------------------|---------------|--------------------|--------|-----------------|-----------------|---------------|--|---|----|----|----|----------------|--------|-------------|
| | | | Туре | Adjustment Type | Number | Date | Ву | | | | | | | | | |
| J5S3384 | 0550 | SEEDING - COOL SEASON MIXTURES | Overrun - To | tal | | | | \$0.00 | | | | | | | | |
| | 0550 - | · Total | | | | | | (\$36,740.00) | | | | | | | | |
| | 0570 | ROCK DITCH CHECK | Material | | 2 | May 4, 2021 | SYSTEM | \$32,219.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | |
| | | | | | 2 | May 4, 2021 | SYSTEM | (\$32,219.00) | | | | | | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$65,813.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$65,813.00) | | | | | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$83,347.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$83,347.00) | | | | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$83,347.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate. | | | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$83,347.00) | | | | | | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$83,347.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$83,347.00) | | | | | | | | |
| | | | | | | 7 | Jul 19, 2021 | SYSTEM | \$83,347.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$83,347.00) | | | | | | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$83,347.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | | | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$83,347.00) | | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$83,347.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 16 on the current Payment Estimate. | | | | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$83,347.00) | | | | | | | | |
| | | | | | 1 | | | | | | 10 | 10 | 10 | Sep 3, 2021 | SYSTEM | \$83,347.00 |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$83,347.00) | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | |
| | | | Overrun | Overrun | 4 | Jun 3, 2021 | shankb1 | (\$13,123.00) | Overrun Re-adjustment. Will be addressed on change order. | | | | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$13,123.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 7577.000; Overrun Quantity Balance 1193.00. | | | | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$13,123.00) | | | | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$13,123.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$13,123.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 7577.000; Overrun Quantity Balance 1193.00. | | | | | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$13,123.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | |
|---------|--------|--------------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|--|----------------|--------|--------------|
| J5S3384 | 0570 | ROCK DITCH CHECK | Overrun | Overrun | 6 | Jul 1, 2021 | SYSTEM | \$13,123.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 22 on the current Payment Estimate. Material Insufficiency Quantity 7577.000; Overrun Quantity Balance 1193.00. | | | |
| | | | | | 7 | Jul 19, 2021 | shankb1 | \$13,123.00 | Returning overrun/material adjustment from pervious estimates. | | | |
| | | | | Overrun - T | otal | | | \$0.00 | | | | |
| | | | Overrun - To | tal | | | | \$0.00 | | | | |
| | 0570 - | | | | | | | \$0.00 | | | | |
| | 0580 | ALTERNATE DITCH CHECK | Material | | 2 | May 4, 2021 | SYSTEM | \$5,695.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | |
| | | | | | | | | | 2 | May 4, 2021 | SYSTEM | (\$5,695.00) |
| | | | | | 3 | May 18, 2021 | SYSTEM | \$9,435.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | |
| | | | | | 3 | May 18, 2021 | SYSTEM | (\$9,435.00) | | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$10,795.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$10,795.00) | | | | |
| | | | | | 5 | Jun 17, 2021 | SYSTEM | \$10,795.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user shankb1 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | |
| | | | | | | 5 | Jun 17, 2021 | SYSTEM | (\$10,795.00) | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | \$10,795.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$10,795.00) | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$10,795.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$10,795.00) | | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | \$10,795.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user shankb1 overridding Payment Estimate Exception 18 on the current Payment Estimate. | | | |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$10,795.00) | | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$10,795.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 17 on the current Payment Estimate. | | | |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | (\$10,795.00) | | | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | \$10,795.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | | | |
| | | | | | 10 | Sep 3, 2021 | SYSTEM | (\$10,795.00) | | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | |
| | 0580 - | | | | | | | \$0.00 | | | | |
| | 0600 | TEMPORARY SEEDING AND MULCHING | Material | | 6 | Jul 1, 2021 | SYSTEM | \$8,925.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | |
| | | | | | 6 | Jul 1, 2021 | SYSTEM | (\$8,925.00) | | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | \$8,925.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 21 on the current Payment Estimate. | | | |
| | | | | | 7 | Jul 19, 2021 | SYSTEM | (\$8,925.00) | | | | |



| | otal | | | | | | | \$28,303.60 | |
|-------|--------|--|-----------------------------------|-----------------------------|----------------------|-----------------|---------------|--------------|---|
| 384 - | Total | | | | | | | (\$4,800.23) | |
| | 0670 - | Total | | | | | | \$577.00 | |
| | | | Construction | Stockpile S | TMI - Total | | | \$577.00 | |
| | | | | - Total | | | | \$577.00 | |
| | 0670 | END ANCHOR | Construction Stockpile STMI | | 6 | Jul 1, 2021 | SYSTEM | \$577.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| Į | 0660 - | | | | | | | \$10,892.00 | |
| | | | Construction | Stockpile S | IMI - Total | | | \$10,892.00 | |
| | | (MASH) | | - Total | | | | \$10,892.00 | |
| | 0660 | TYPE A CRASHWORTHY END TERMINAL | | | 6 | Jul 1, 2021 | SYSTEM | \$10,892.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| J | 0650 - | | | | | | | \$152.00 | |
| | | | Construction | Stockpile S | TMI - Total | | | \$152.00 | |
| | | 5515 | | - Total | | | | \$152.00 | |
| | 0650 | ASYMMETRICAL TRNS. SEC., 6.5 FT. POSTS | Construction Stockpile STMI | | 6 Jul 1, SYSTEM 2021 | | | \$152.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | 0640 - | Total | | | | | | \$1,102.00 | |
| | | | Construction | Stockpile S | TMI - Total | | | \$1,102.00 | |
| | | TYPE) | STMI | - Total | | | | \$1,102.00 | |
| | 0640 | BRIDGE ANCHOR SECTION (CURB | Construction Stockpile | Stockpile | | Jul 1, 2021 | SYSTEM | \$1,102.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | 0630 - | Total | | | | | | \$11,599.00 | |
| | | | Construction | Stockpile S | TMI - Total | | | \$11,599.00 | |
| | | (REG/NO CURB) | STMI | - Total | | | | \$11,599.00 | |
| | 0630 | MGS BRIDGE APP. TRANS SEC | Construction Stockpile | | 6 | Jul 1, 2021 | SYSTEM | \$11,599.00 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | 0620 - | Total | | | | | | \$174.50 | |
| | | | Construction | | TMI - Total | | | \$174.50 | |
| | | TYPE A | Stockpile STMI | - Total | | 2021 | | \$174.50 | |
| | 0620 | GUARDRAIL | Construction | | 6 | Jul 1, | SYSTEM | \$174.50 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | 0600 - | Total | | | | | | \$0.00 | |
| | | | Material - Tot | | | | | \$0.00 | |
| | | | | - Total | | 2021 | | \$0.00 | |
| | | | | | 10 | 2021 Sep 3, | SYSTEM | (\$8,925.00) | Estimate Item Adjustment (0011) due to user shankb1 overridding Payme Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 10 | 2021 Sep 3, | SYSTEM | \$8,925.00 | This adjustment offsets the original system-generated Material Payment |
| | | | | | 9 | | SYSTEM | (\$8,925.00) | Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 9 | Aug 16, 2021 | SYSTEM | \$8,925.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payme |
| | | | | | 8 | Aug 3, 2021 | SYSTEM | (\$8,925.00) | |
| 384 | 0600 | TEMPORARY SEEDING AND MULCHING | Material | , | 8 | Aug 3, 2021 | SYSTEM | \$8,925.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user shankb1 overridding Payme Estimate Exception 22 on the current Payment Estimate. |
| ect | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |