

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 27, 2021

Final Estimate Number	Contract ID	210122-B03	<b>Pay Period Start</b>	December 2, 2021	Original Contract Amount	\$1,289,499.51
11	<b>Prime Contractor</b>	Asphalt Stone, Co.	Pay Period End	,	Net Change Order Amount	
• •					Current Contract Amount	\$1,300,007.47

Approval Date		By User
June 21, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	vierss
June 21, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	holdtc
June 22, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
October 1, 2021	October 1, 2021	September 27, 2021	95.05%

	Milestones		
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date	June 6, 2022	June 6, 2022	
Awarded Date	February 3, 2021	February 3, 2021	
Letting Date	January 22, 2021	January 22, 2021	
Notice to Proceed Date	March 8, 2021	March 8, 2021	
Open to Traffic Date	September 27, 2021	September 27, 2021	
Work Began Date	July 21, 2021	July 21, 2021	

Contract Total Pay For Estimate No. 11											
		This Estimate	Previous	To Date							
210122-B03											
	Total Posted Items Pay	\$0.00	\$1,235,626.07	\$1,235,626.07							
	Gross Item Adjustments	\$0.00	\$67,533.18	\$67,533.18							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
			\$ <mark>1,303,159.25</mark>	\$1,303,159.25							
Contract Total Pay	able This Estimate:	\$0.00									

## Items Paid This Estimate Period

No Data Available

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

## Line Item Adjustments This Estimate

No Data Available

Revision 4/1/2020 Page 1 of 8



Incentive Disincentive Liquidated Damages Other Contract Adjustments


## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route County Location of Work								
J2P3283	FAF 63-4(85)	Pavement improvements	63	MACON	from 1.2 miles south of Rte	e. KK to 0.5 mile north of Rt	e. DD in Macon County near Macon				
Totals by J	Job Numb	ers									
J2P3283		ed Item Pay s Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$1,235,626.07 \$67,533.18 \$1,303,159.25	To Date \$1,235,626.07 \$67,533.18 \$1,303,159.25				

\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 2 of 8





# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 8



## Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

0001 0001 0001 0001 0001 0001 0001 000		Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		Total Value POSTED To Date (See report generated date)
0001 0001 0001 0001 0001 0001 0001 000	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$4,360.00	\$4,360.00
0001 0001 0001 0001 0001 0001 0001 000	0020	2153000	SHAPING SLOPES, CLASS III	18.00	0.00	18.00	100F	18.00	\$848.00	\$15,264.00
0001 0001 0001 0001 0001 0001 0001 000	0030	4071005	TACK COAT	9,334.00	0.00	9,334.00	GAL	9,334.00	\$2.00	\$18,630.66
0001 0001 0001 0001 0001 0001 0001 000	0040	4099905	MISC.SURFACE SEALING TREATMENT	171,700.00	0.00	171,700.00	SQYD	171,700.00	\$1.03	\$176,851.00
0001 0001 0001 0001 0001 0001 0001 000	0050	4131000	MICROSURFACING, TYPE II	311,116.00	0.00	311,116.00	SQYD	311,116.00	\$2.74	\$852,457.84
0001 0001 0001 0001 0001 0001 0001 000	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$750.00	\$1,500.00
0001 0001 0001 0001 0001 0001 0001 000	0070	6133021	REMOVAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR	1,052.00	397.00	1,449.00	SQYD	1,449.00	\$9.26	\$13,422.0
0001 0001 0001 0001 0001 0001 0001 000	0800	6139910	MISC.FURNISHING AND PLACING HIGH TENSILE STRENGTH SYNTHETIC FIBER ASPHALTIC PAVEMENT MATERIAL FOR CLASS C PARTIAL DEPTH PAVEMENT REPAIR (SP125C PG 70-22)	113.00	85.00	198.00	TONS	198.00	\$262.43	\$51,961.1
0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0090	6161005	CONSTRUCTION SIGNS	1,637.00	-608.00	1,029.00	SQFT	1,029.00	\$7.00	\$7,203.00
0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.00
0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0001 0010	0110	6161009	FLAG ASSEMBLY	6.00	-6.00	0.00	EA	0.00	\$15.00	\$0.0
0001 0001 0001 0001 0001 0001 0001 000	0120	6161025	CHANNELIZER (TRIM LINE)	150.00	-10.00	140.00	EA	140.00	\$18.00	\$2,520.0
0001 0001 0001 0001 0001 0001 0001 0001 0001 0010	0130	6161033	DIRECTIONAL INDICATOR BARRICADE	38.00	-19.00	19.00	EA	19.00	\$75.00	\$1,425.0
0001 0001 0001 0001 0001 0001 0001 0010	0140	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.0
0001 0001 0001 0001 0001 0001 0010	0150	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.0
0001 0001 0001 0001 0001 0010	0160	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	12.00	-12.00	0.00	EA	0.00	\$850.00	\$0.0
0001 0001 0001 0001 0001 0010	0170	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$39,100.00	\$39,100.0
0001 0001 0001 0010	0180	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	14.00	0.00	14.00	EA	14.00	\$280.00	\$3,920.0
0001 0001 0010 0010	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	141,206.00	0.00	141,206.00	LF	141,206.00	\$0.21	\$29,653.2
0001 0010 0010	0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	111,888.00	0.00	111,888.00	LF	111,888.00	\$0.21	\$23,496.4
0010 0010	0210	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	126.00	0.00	126.00	LF	126.00	\$2.00	\$252.0
0010	0220	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	14.00	9.00	23.00	EA	23.00	\$75.00	\$1,725.0
	0230	6061060	MGS GUARDRAIL	1,550.00	0.00	1,550.00	LF	1,550.00	\$21.92	\$33,976.0
0010	0240	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	2.00	0.00	2.00	EA	2.00	\$2,750.00	\$5,500.0
	0250	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,100.00	\$1,100.0
0010	0260	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3.00	0.00	3.00	EA	3.00	\$2,650.00	\$7,950.0
Project J2P3283 - Tot	tal Value	ue Posted to D	late as of Report Generated Date							\$1,300,007.4

Revision 4/1/2020 Page 4 of 8



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 5 of 8



## Line Item Adjustments by Estimate

## Contract ID:190215-D05

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
83	0030	TACK COAT	Other Item Adjustment	OTHR	8	Nov 1, 2021	vierss	\$1,385.02	An error in AWP resulted in this item not being paid on estimate 0005 & 0006. See Documentation Reocord in eProjects.
				OTHR - Tota	al			\$1,385.02	
			Other Item	Adjustment -	Total			\$1,385.02	
	0030 -	Total						\$1,385.02	
	0040	MISC. SCRUB SEAL	Material		3	Aug 17, 2021	SYSTEM	\$131,023.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vierss overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 17, 2021	SYSTEM	(\$131,023.00)	
					4	Sep 1, 2021	SYSTEM	\$131,023.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Sep 1, 2021	SYSTEM	(\$131,023.00)	
					5	Sep 20, 2021	SYSTEM	\$131,023.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 20, 2021	SYSTEM	(\$131,023.00)	
					6	Oct 1, 2021	SYSTEM	\$176,850.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vierss overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 1, 2021	SYSTEM	(\$176,850.79)	
				- Total			\$0.00		
			Material - To	aterial - Total				\$0.00	
			Other Item Adjustment	OTHR	8	Nov 1, 2021	vierss	\$0.21	An error in AWP resulted in this item not being paid on estimate 0006. See Documentation Reocord in eProjects.
				OTHR - Tota				\$0.21	
			Other Item	Adjustment -	Total			\$0.21	
	0040 -							\$0.21	
	0050	MICROSURFACING, TYPE II	Material		4	Sep 1, 2021	SYSTEM	\$216,970.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Sep 1, 2021	SYSTEM	(\$216,970.74)	
					5	Sep 20,	SYSTEM	\$730,008.72	This adjustment attests the ariginal system-generated Material Payment
						2021		********	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	2021 Sep 20, 2021	SYSTEM	(\$730,008.72)	Estimate Item Adjustment (0005) due to user vierss overridding Payment
					5	Sep 20,			Estimate Item Adjustment (0005) due to user vierss overridding Payment
						Sep 20, 2021 Oct 1,	SYSTEM	(\$730,008.72) \$852,127.51 (\$852,127.51)	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment
				- Total	6	Sep 20, 2021 Oct 1, 2021	SYSTEM	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment
			Material - To	otal	6	Sep 20, 2021 Oct 1, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.
			Material - To Other Item Adjustment	otal OTHR	6	Sep 20, 2021 Oct 1, 2021	SYSTEM	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00 \$0.00 \$62,996.16	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment
			Other Item Adjustment	otal OTHR OTHR - Tota	6 6 8 al	Sep 20, 2021 Oct 1, 2021 Oct 1, 2021 Nov 1,	SYSTEM SYSTEM SYSTEM	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00 \$0.00 \$62,996.16	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  An error in AWP resulted in this item not being paid on estimate 0005. See
	0050	Total	Other Item Adjustment	otal OTHR	6 6 8 al	Sep 20, 2021 Oct 1, 2021 Oct 1, 2021 Nov 1,	SYSTEM SYSTEM SYSTEM	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00 \$0.00 \$62,996.16 \$62,996.16	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  An error in AWP resulted in this item not being paid on estimate 0005. See
	<b>0050</b> - <b>0070</b>	REMOVAL FOR	Other Item Adjustment	otal OTHR OTHR - Tota	6 6 8 al Total	Sep 20, 2021 Oct 1, 2021 Oct 1, 2021 Nov 1,	SYSTEM SYSTEM SYSTEM	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00 \$0.00 \$62,996.16	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  An error in AWP resulted in this item not being paid on estimate 0005. See
			Other Item Adjustment Other Item A	otal OTHR OTHR - Tota Adjustment -	6 6 8 al Total	Sep 20, 2021 Oct 1, 2021 Oct 1, 2021 Nov 1, 2021	SYSTEM SYSTEM SYSTEM vierss	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00 \$0.00 \$62,996.16 \$62,996.16 \$62,996.16	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  An error in AWP resulted in this item not being paid on estimate 0005. See Documentation Reocord in eProjects.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',9.26300 - 9.26300, 'is
		REMOVAL FOR CLASS C PARTIAL DEPTH PAVT	Other Item Adjustment Other Item A	OTHR - Tota Adjustment -	6 8 al Total 4 9	Sep 20, 2021  Oct 1, 2021  Oct 1, 2021  Nov 1, 2021  Sep 1, 2021  Nov 15,	SYSTEM SYSTEM vierss	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00 \$0.00 \$62,996.16 \$62,996.16 \$62,996.16 (\$3,677.41) \$3,677.41	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  An error in AWP resulted in this item not being paid on estimate 0005. See Documentation Reocord in eProjects.  Unit price based on averaged overrun adjustments for installed quantity on all
		REMOVAL FOR CLASS C PARTIAL DEPTH PAVT	Other Item Adjustment Other Item A	OTHR OTHR - Tota Adjustment - Overrun Overrun - To	6 8 al Total 4 9	Sep 20, 2021  Oct 1, 2021  Oct 1, 2021  Nov 1, 2021  Sep 1, 2021  Nov 15,	SYSTEM SYSTEM vierss	(\$730,008.72) \$852,127.51 (\$852,127.51) \$0.00 \$0.00 \$62,996.16 \$62,996.16 \$62,996.16 (\$3,677.41)	Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 3 on the current Payment Estimate.  An error in AWP resulted in this item not being paid on estimate 0005. See Documentation Reocord in eProjects.  Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',9.26300 - 9.26300, 'is



## Line Item Adjustments by Estimate

## Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J2P3283	0800	MISC. PAVEMENT REPAIR	Material		4	Sep 1, 2021	SYSTEM	\$51,961.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vierss overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					4	Sep 1, 2021	SYSTEM	(\$51,961.14)		
					5	Sep 20, 2021	SYSTEM	\$51,961.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vierss overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					5	Sep 20, 2021	SYSTEM	(\$51,961.14)		
					6	Oct 1, 2021	SYSTEM	\$51,961.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vierss overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					6	Oct 1, 2021	SYSTEM	(\$51,961.14)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
			Other Item Adjustment	ACAD		Sep 2, 2021	vierss	\$1,114.49	Doc Record Saved to eProjects	
				ACAD - Tota				\$1,114.49		
			Other Item /	Adjustment -	Total			\$1,114.49		
			Overrun	Overrun	4	Sep 1, 2021	SYSTEM	\$22,306.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 198.000; Overrun Quantity Balance 85.00.	
					4	Sep 1, 2021	SYSTEM	(\$22,306.55)		
					5	Sep 20, 2021	SYSTEM	(\$22,306.55)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	
					5	Sep 20, 2021	SYSTEM	\$22,306.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 198.000; Overrun Quantity Balance 85.00.	
						6	Oct 1, 2021	SYSTEM	(\$22,306.55)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Oct 1, 2021	SYSTEM	\$22,306.55	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 12 on the current Payment Estimate. Material Insufficiency Quantity 198.000; Overrun Quantity Balance 85.00.	
							7	Oct 18, 2021	SYSTEM	(\$22,306.55)
					9	Nov 15, 2021	SYSTEM	\$22,306.55	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',262.43000 - 262.43000, 'is applied (if non-zero).	
				Overrun - To	otal			\$0.00		
			Overrun - T	otal				\$0.00		
	0080 -	Total						\$1,114.49		
	0180	PREF THERMO PVMT MARK, LT/RT ARROW	Material		6	Oct 1, 2021	SYSTEM	\$3,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vierss overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					6	Oct 1, 2021	SYSTEM	(\$3,920.00)		
				- Total				\$0.00		
			Material - Total					\$0.00		
	<b>0180</b> - <b>0190</b>							\$0.00		
		0 6 IN. WHITE HIGH BUILD WATERBORNE PAINT			6	Oct 1, 2021	SYSTEM	\$29,646.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vierss overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					6	Oct 1, 2021	SYSTEM	(\$29,646.96)		
				- Total				\$0.00		
			Material - To					\$0.00		
			Other Item Adjustment	REFL	10	Dec 2, 2021	vierss	\$1,338.40	doc record saved to eprojects	

Jun 23, 2022



## Line Item Adjustments by Estimate

## Contract ID:190215-D05

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J2P3283	0190	6 IN. WHITE HIGH BUILD WATERBORNE	Other Item Adjustment	REFL - Tota	1			\$1,338.40			
		PAINT	Other Item	Adjustment -	Total			\$1,338.40			
	0190	- Total						\$1,338.40			
	0200	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		6	Oct 1, 2021	SYSTEM	\$23,496.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vierss overridding Payment Estimate Exception 9 on the current Payment Estimate.		
		PAINT			6	Oct 1, 2021	SYSTEM	(\$23,496.48)			
				- Total				\$0.00			
			Material - Total					\$0.00			
			Other Item Adjustment	REFL	10	Dec 2, 2021	vierss	\$698.90	Doc Record saved to eProjects		
				REFL - Total				\$698.90			
			Other Item /	Adjustment -	Total			\$698.90			
	0200	- Total						\$698.90			
	0220	PAVEMENT MARKING	Overrun	Overrun	Overrun	Overrun	3	Aug 17, 2021	SYSTEM	(\$675.00)	
		REMOVAL (SYMBOLS)			9	Nov 15, 2021	SYSTEM	\$675.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',75.00000 - 75.00000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Total					\$0.00			
	0220 - Total										
J2P3283 -	Total							\$67,533.18			
Overall - Total								\$67,533.18			