

Pay Estimate Created Date: January 3, 2022

Progrea 19	ss Estimate Number	Contract ID Prime Contractor	210122-0 Radmacl Co.,Inc.	C03 her Brothers E	xcavating	Star	Period Period	2021	nber 16, ry 1, 2022	Amour Net Ch Amour	nange Order nt nt Contract	\$7,541,439.87 \$78,091.65 \$7,619,531.52		
Approval Date												By User		
January 3, 2022			Ger	erated and Ap	proved (and	should	be consi	dered D	raft) at the	Project (Office Level by	scarpm?		
January 3, 2022			Reviewe	ed and Approv	ed (and shou	ld be c	onsidered	d Draft) a	at the Resid	lent Eng	ineer Level by	warrem?		
January 4, 2022				Re	eviewed and	Approv	ved at the	Central	Office Con	trollers (Office Level by	ramses		
Original Co	mpletion Date	e Curre	ent Comple	tion Date	Actual 0	Comple	etion Dat	e	% of C	urrent	Contract Amoun	t Complete		
May 1	5, 2023		May 15, 20	2023 44.02%										
Con	tract Informat	ional Dates						Miles	stones					
Date Description	Original Completic Date		etion	Date	Description		Com	ginal pletion ate	Curr Compl Dat	etion	Days Remainir on Milestone	g Diary Charge Days		
Acceptance Date				Vilestone - Ca J4I3291	lendar Time		Decemi 2021	oer 26,	Decembe 2021	er 26,	Milesto Comple			
Awarded Date	February 3, 2021	February 2021		Vilestone - Co J4I3291 Open		e	Decemi 2021	per 1,	Decembe 2021	er 1,	Milesto Comple			
Letting Date	January 22, 2021	January 2 2021	22,											
Notice to Proceed Date	February 19, 2021	February 2021	19,											
Work Began Date	March 16, 20	21 March 16	, 2021											
Contract Total	Pay For Estim	nate No. 19												
			-	his Estimate			Previous			Т	o Date			
210122-C03	Gross Incent Disinc Liquid		nts	<mark>\$0.00</mark> \$0.00 \$0.00 \$0.00			\$3,351,141.93 \$7,990.83 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00			\$3,354,020.63 \$7,990.83 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00				
Contract Total	Davahlo Thie	Estimato:		2,878.70			\$ <mark>3,359,13</mark>	2.76		\$	3,362,011.46			

Contract Total Payable This Estimate: Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4I3291	0680	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	EA	\$7,699.900	0.05	\$385.00
	0780	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY	EA	\$4,402.650	0.25	\$1,100.66
	5010	9019901	MISC.Lighting Repair I-29 and 56th Street	LS	\$27,860.700	0.05	\$1,393.04
Project J4I3	291 - Total						\$2,878.70
Overall - To	tal						\$2,878.70

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3291	0550	SEEDING - COOL SEASON MIXTURES	Material			-0.4	\$8,022.00	(\$3,208.80)
	0550	SEEDING - COOL SEASON	Material		This adjustment offsets the original system-	0.4	\$8,022.00	\$3,208.80



Pay Estimate Created Date: January 3, 2022

I	Progre 19	ss Estimate Number	Contract ID Prime Contractor	210122-C03 Radmacher I Co.,Inc.	Brothers Exca	avating P	ay Period start ay Period and	December 16, 2021 January 1, 2022	Original Contr Amount Net Change O Amount Current Contra Amount	rder _{\$7}	,541,439.87 8,091.65 ,619,531.52
Project Number	Line No.	Item Description Adjustment Type Other Item Adjustment Type Comments						ients	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmen amount
J4I3291		MIXTURES generated Material Payme Adjustment (0003) due overridding Payment Estimat						due to user scarpi	n1 on		
	0600	CONTROL BLANKET all previous payment estimates of '0.00000						Averaged Price Adjustment from this item or Il previous payment estimates of '0.00000' is applied (if non-zero)			(\$4,009.75
	0600		PE 2D EROSION TROL BLANKET	Material					-2,420	\$2.15	(\$5,203.00
	0600		PE 2D EROSION TROL BLANKET	Overrun		generate Adjus Estimate E Estim	ed Overrun F stment (0001 exception 4 o ate. Materia	ets the original syste Payment Estimate Ito) overridding Paymon n the current Paymon I Insufficiency Quan ntity Balance 1865.	em ent ity	\$2.15	\$4,009.75
	0600	0 TYPE 2D EROSION Material This adjustment offsets the original sy generated Material Payment Estimate Adjustment (0002) due to user sca overridding Payment Estimate Exception the current Payment Est							em n1 on	\$2.15	\$5,203.00
Total											\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information												
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work								
J4I3291	l 29-1(128)	Bridge replacement	29	PLATTE	over 56th Street, 1.8 miles west of Rte. 169 near Riverside								
J4I3297	l 29-1(129)	Bridge replacement	29	PLATTE	over Rte. AA, 0.8 mile west of Rte. 169 near Northmoor								

Totals by Job Numbers

291	This Estimate	Previous	To Date
Posted Item Pay	\$2,878.70	\$3,351,141.93	\$3,354,020.63
Gross Item Adjustments	\$0.00	\$535.83	\$535.83
Gross Item Pay	\$2,878.70	\$3,351,677.76	\$3,354,556.46
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
297	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$0.00	\$0.00
Gross Item Adjustments	\$0.00	\$7,455.00	\$7,455.00
Gross Item Pay	\$0.00	\$7,455.00	\$7,455.00
Incentive	\$0.00	\$0.00	\$0.00
Disingentities	\$0.00	\$0.00	\$0.00
Disincentive			
Liquidated Damages	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4I3291, Item 8051000A, Project Item Line Number 0550, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	Working with the contractor and materials to resolve this exception.	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3291, Item 8051000A, Project Item Line Number 0550, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient.	Working with the contractor and materials to resolve this exception.	scarpm1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4I3291, Item 8064138, Project Item Line Number 0600, Material Set 8064138, Material 0806EKBL - Erosion Control Blanket, Acceptance Action Generic 0806EKBL is insufficient.	Working with the contractor to resolve this exception.	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 210122-C03, Contract Project J4I3291, Project Item Line Number 0600, Contract Line Item Number 0600, Item 8064138, Minor Item.	No Remark was entered by Engineer	scarpm1	Overridden
Estimate Exception Type: Item Overrun: Contract 210122-C03, Contract Project J4I3291, Project Item Line Number 0490, Contract Line Item Number 0490, Item 6206001C, Minor Item.	This item will be placed on the next change order.	scarpm1	Acknowledged



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Note: Posted Q					Report Generated date and can differ from the posted am	ount at the	e time the l	Estimate wa	is Gener	ated.		
Contract Nm.CONTRACT			Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-C03	J4I3291	0001	0010	1041000	TEMPORARY SURFACING	20.00	0.00	20.00	CUYD	20.00	\$406.65	\$8,133.00
		0001	0020	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$4,423.45	\$4,423.45
		0001	0030	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$56,836.55	\$56,836.55
		0001	0040	2031000	CLASS A EXCAVATION	8,112.00	0.00	8,112.00	CUYD	8,112.00	\$6.25	\$50,700.00
		0001	0050	2035500	EMBANKMENT IN PLACE	10.00	0.00	10.00	CUYD	0.00	\$35.75	\$0.00
		0001	0060	2036000	COMPACTING EMBANKMENT	1,163.00	0.00	1,163.00	CUYD	1,163.00	\$1.20	\$1,395.60
		0001	0070	2037075	COMPACTING IN CUT	32.60	-32.60	0.00	STA	0.00	\$759.80	\$0.00
		0001	0080	2063000	CLASS 3 EXCAVATION	2.00	0.00	2.00	CUYD	2.00	\$10.10	\$20.20
		0001	0090	2142000	FURNISHING ROCK FILL	900.00	0.00	900.00	CUYD	900.00	\$52.90	\$47,610.00
		0001	0100	2143000	PLACING ROCK FILL	900.00	0.00	900.00	CUYD	900.00	\$14.85	\$13,365.00
		0001	0110	2153000	SHAPING SLOPES, CLASS III	0.60	0.00	0.60	100F	0.60	\$630.00	\$378.00
		0001	0120	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	3,419.00	-133.00	3,286.00	SQYD	3,286.00	\$7.60	\$24,973.60
		0001	0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	2,698.00	865.00	3,563.00	SQYD	3,563.00	\$11.40	\$40,618.20
		0001	0140	4010150	TYPE A2 SHOULDER	693.00	-577.90	115.10	SQYD	115.10	\$39.65	\$4,563.72
		0001	0150	4039905	MISC.OPTIONAL PAVEMENT 56TH STREET	2,699.00	133.00	2,832.00	SQYD	2,832.00	\$48.90	\$138,484.80
		0001	0160	4039905	MISC.OPTIONAL PAVEMENT SHOULDER/CROSSOVER	2,726.00	1,226.00	3,952.00	SQYD	3,952.00	\$48.20	\$190,486.40
		0001	0170	5041000	CONCRETE APPROACH PAVEMENT	395.00	77.40	472.40	SQYD	472.40	\$118.45	\$55,955.78
		0001	0180	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	1.00	\$2,427.40	\$2,427.40
		0001	0190	6071011A	CHAIN-LINK FENCE (48 IN.)	200.00	0.00	200.00	LF	200.00	\$48.30	\$9,660.00
		0001	0200	6071102	MODIFIED CONCRETE GUTTER TYPE B	428.00	0.00	428.00	LF	428.00	\$30.50	\$13,054.00
		0001	0210	6081010	CONCRETE CURB RAMP	26.30	2.40	28.70	SQYD	28.70	\$75.00	\$2,152.50
		0001	0220	6081012	TRUNCATED DOMES	48.00	0.00	48.00	SQFT	48.00	\$12.65	\$607.20
		0001	0230	6086004	CONCRETE SIDEWALK, 4 IN.	251.00	3.50	254.50	SQYD	254.50	\$39.90	\$10,154.55
		0001	0240	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	38.00	0.00	38.00	LF	38.00	\$44.90	\$1,706.20
		0001	0250	6091041	CONCRETE GUTTER TYPE A	37.00	0.00	37.00	LF	37.00	\$39.70	\$1,468.90
		0001	0260	6097000	ROCK LINING	4.00	9.00	13.00	CUYD	13.00	\$110.70	\$1,439.10
		0001	0270	6099903	MISC.CURB AND GUTTER TYPE CG-1	314.00	14.00	328.00	LF	328.00	\$15.45	\$5,067.60
		0001	0280	6113020	FURNISHING TYPE 2 ROCK BLANKET	30.00	0.00	30.00	CUYD	30.00	\$69.85	\$2,095.50
		0001	0290	6113040	PLACING TYPE 2 ROCK BLANKET	30.00	0.00	30.00	CUYD	30.00	\$40.85	\$1,225.50
		0001	0300	6143013	MANHOLE FRAME AND COVER, TYPE 3	1.00	0.00	1.00	EA	0.00	\$468.90	\$0.00
		0001	0310	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	5.00	0.00	5.00	EA	5.00	\$5,775.00	\$28,875.00
		0001	0320	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	4.00	\$1,102.50	\$4,410.00
		0001	0330	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$162,750.00	\$154,612.50
		0001	0340	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	513.00	0.00	513.00	LF	458.00	\$73.65	\$33,731.70
		0001	0350	6173100	CONCRETE TRAFFIC BARRIER, TYPE D	1,267.00	0.00	1,267.00	LF	1,267.00	\$67.85	\$85,965.95
		0001	0360	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	3,587.00	-335.00	3,252.00	LF	3,252.00	\$15.20	\$49,430.40
		0001	0370	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	8,134.00	-1,491.00	6,643.00	LF	6,643.00	\$9.45	\$62,776.35
		0001	0380	6179902	MISC.CONCRETE TRAFFIC BARRIER TRANSITION	5.00	0.00	5.00	EA	5.00	\$6,053.85	\$30,269.25
		0001	0390	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$377,948.10	\$377,948.10
		0001	0400	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0410	6191000	PAVEMENT EDGE TREATMENT	286.00	0.00	286.00	LF	286.00	\$7.25	\$2,073.50
		0001	0420	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	48.00	0.00	48.00	LF	45.00	\$23.10	\$1,039.50
		0001	0430	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	2.00	\$341.25	\$682.50
		0001	0440	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	18.00	0.00	18.00	EA	15.00	\$173.25	\$2,598.75

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)	
210122-C03	J4I3291	0001	0450	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	6,859.00	0.00	6,859.00	LF	Qty 4,342.00	\$0.20	\$868.40	
		0001	0460	6205903A		4,556.00	0.00	4,556.00	LF	2,784.00	\$0.25	\$696.00	
		0001	0470	6205906A		1,389.00	0.00	1,389.00	LF	1,172.00	\$2.35	\$2,754.20	
		0001	0480	6206000C	MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,462.00	0.00	1,462.00	LF	1,323.00	\$0.15	\$198.45	
		0001	0490	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	898.00	0.00	898.00	LF	917.00	\$0.15	\$137.55	
		0001	0500	6240104A		1,074.00	0.00	1,074.00	SQYD	1,074.00	\$3.70	\$3,973.80	
		0001	0510	6269909	MISC.OPTIONAL SHOULDER RUMBLE STRIPS	33.00	0.00	33.00	STA	28.00	\$78.75	\$2,205.00	
		0001	0520	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.95	\$9,030.00	\$8,578.50	
		0001	0530	7250318A	18 IN. PIPE GROUP B	53.00	0.00	53.00	LF	53.00	\$90.70	\$4,807.10	
		0001	0540	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END	1.00	0.00	1.00	EA	1.00	\$1,445.10	\$1,445.10	
		0004	0550	8051000A	SECTION SEEDING - COOL SEASON MIXTURES	0.50	0.00	0.50	ACRE	0.40	\$8,022.00	\$3,208.80	
		0001	0560	8061005	ROCK DITCH CHECK	264.00	0.00	264.00	LF	121.00	\$0,022.00	\$2,069.10	
		0001		8061005	SEDIMENT REMOVAL		0.00	32.00	CUYD		\$8.65	\$2,009.10	
		0001	0570		TEMPORARY SEEDING AND MULCHING	32.00				10.00			
		0001	0580	8061017	SILT FENCE	0.30	0.00	0.30 937.00	ACRE LF	0.30	\$105.00	\$31.50	
		0001	0590	8061019		937.00	0.00			421.00	\$3.05	\$1,284.05	
		0010 0 0010 0 0010 0	0010	0600	8064138	TYPE 2D EROSION CONTROL BLANKET	555.00	0.00	555.00	SQYD	2,420.00	\$2.15	\$5,203.00
				0610	6061060	MGS GUARDRAIL	400.00	0.00	400.00	LF	400.00	\$21.00	\$8,400.00
			0620	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	500.00	0.00	500.00	LF	500.00	\$25.20	\$12,600.00	
			0630	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	3.00	0.00	3.00	EA	3.00	\$2,713.20	\$8,139.60	
			0640	6061070	MGS VERTICAL CONCRETE BARRIER TRANSITION	2.00	0.00	2.00	EA	2.00	\$2,394.00	\$4,788.00	
		0010	0650	6061074	MGS HEIGHT AND BLOCK TRANSITION	4.00	0.00	4.00	EA	4.00	\$540.75	\$2,163.00	
		0010	0660	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	1.00	\$2,495.85	\$2,495.85	
		0020	0670	9011250	LUMINAIRE, 150 WATT HIGH PRESSURE SODIUM (UNDERPASS)	4.00	-4.00	0.00	EA	0.00	\$665.95	\$0.00	
		0020	0680	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	1.00	\$7,699.90	\$7,699.90	
		0020	0690	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	65.00	0.00	65.00	LF	65.00	\$13.80	\$897.00	
		0020	0700	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	60.00	197.00	257.00	LF	257.00	\$15.25	\$3,919.25	
		0020	0710	9014003	CONDUIT, 3 IN. RIGID, PUSHED	197.00	-197.00	0.00	LF	0.00	\$30.75	\$0.00	
		0020	0720	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	268.00	0.00	268.00	LF	268.00	\$57.35	\$15,369.80	
		0020	0730	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	3.00	\$393.80	\$1,181.40	
		0020	0740	9017004	CABLE, 4 AWG 1 CONDUCTOR	140.00	0.00	140.00	LF	140.00	\$2.85	\$399.00	
		0020	0750	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,120.00	0.00	1,120.00	LF	1,120.00	\$2.05	\$2,296.00	
		0020	0760	9017204	WIRE, 4 AWG, BARE NEUTRAL	70.00	0.00	70.00	LF	70.00	\$2.90	\$203.00	
		0020	0770	9017208	WIRE, 8 AWG, BARE NEUTRAL	560.00	0.00	560.00	LF	560.00	\$2.00	\$1,120.00	
		0020	0780	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY	1.00	0.00	1.00	EA	1.00	\$4,402.65	\$4,402.65	
		0020	0790	9019902	MISC.JUNCTION BOX, NEMA	4.00	0.00	4.00	EA	4.00	\$516.60	\$2,066.40	
		0020	0800	9019903	MISC.CONDUIT, 1" FLEXIBLE	8.00	0.00	8.00	LF	8.00	\$53.45	\$427.60	
		0030	0810	9029902	MISC.ADJUST PULL BOX	1.00	0.00	1.00	EA	0.00	\$3,224.55	\$0.00	
		0040	0820	9031010	CONCRETE FOOTINGS, EMBEDDED	1.80	0.00	1.80	CUYD	1.80	\$540.75	\$973.35	
		0040	0830	9031210	STRUCTURAL STEEL POSTS	220.00	0.00	220.00	LB	220.00	\$5.25	\$1,155.00	
		0040	0840	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	4.00	3.00	7.00	EA	7.00	\$235.20	\$1,646.40	
		0040	0850	9031270A	TUBE) 2 IN. PSST POST - 12 GA.	208.00	-208.00	0.00	LF	0.00	\$12.60	\$0.00	
		0040	0860	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	39.00	-39.00	0.00	LF	0.00	\$19.95	\$0.00	
		0040	0870	9031272	2.25 IN. PSST POST - 12 GA.	112.00	0.00	112.00	LF	112.00	\$12.60	\$1,411.20	
			0880	9031280	2.5 IN. PSST POST - 12 GA.	112.00	208.00	320.00	LF	320.00	\$13.65		

Total Paid / All Items / All Estimates (Including this Estimate)

Vote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
0122-C03	J4I3291	0040	0890	9035004A	SH-FLAT SHEET	190.00	-29.00	161.00	SQFT	161.00	\$21.00	\$3,381.0
		0040	0900	9035069A	SHF-FLAT SHEET FLUORESCENT	13.00	0.00	13.00	SQFT	13.00	\$24.15	\$313.9
		0070	0910	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	6.00	0.00	6.00	SQFT	6.00	\$47.30	\$283.8
		0070	0920	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$51,129.75	\$51,129.7
		0070	0930	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$53,633.70	\$53,633.7
		0070	0940	5031010A	BRIDGE APPROACH SLAB (MAJOR)	243.00	0.00	243.00	SQYD	243.00	\$269.20	\$65,415.6
		0070	0950	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	432.00	0.00	432.00	LF	381.00	\$91.25	\$34,766.2
		0070	0960	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$420.00	\$840.0
		0070	0970	7026000	PRE-BORE FOR PILING	78.00	0.00	78.00	LF	78.00	\$65.10	\$5,077.8
		0070	0980	7027000	PILE POINT REINFORCEMENT	12.00	0.00	12.00	EA	12.00	\$137.00	\$1,644.0
		0070	0990	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	43.00	0.00	43.00	CUYD	43.00	\$874.65	\$37,609.9
		0070	1000	7034219A	TYPE D BARRIER	196.00	0.00	196.00	LF	196.00	\$105.80	\$20,736.8
		0070	1010	7034221	SLAB ON CONCRETE NU-GIRDER	436.00	0.00	436.00	SQYD	436.00	\$371.15	\$161,821.4
		0070	1020	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	412.00	0.00	412.00	LF	412.00	\$272.55	\$112,290.6
		0070	1030	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$2,148.50	\$4,297.0
		0070	1040	7161000	PLAIN NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	12.00	\$161.40	\$1,936.8
		0070	1050	7201300	PIPE PILE SPACERS	12.00	0.00	12.00	EA	12.00	\$891.20	\$10,694.4
		0071	1060	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	6.00	0.00	6.00	SQFT	6.00	\$47.30	\$283.8
		0071	1070	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	1.00	\$51,129.75	\$51,129.7
		0071	1080	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$53,754.45	\$53,754.4
		0071 10 0071 11	1090	5031010A	BRIDGE APPROACH SLAB (MAJOR)	280.00	0.00	280.00	SQYD	280.00	\$254.25	\$71,190.0
			1100	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	539.00	0.00	539.00	LF	467.00	\$82.20	\$38,387.4
		0071	1110	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$420.00	\$840.0
		0071	1120	7026000	PRE-BORE FOR PILING	91.00	0.00	91.00	LF	91.00	\$65.10	\$5,924.
		0071	1130	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$137.00	\$1,918.
		0071	1140	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	48.20	0.00	48.20	CUYD	48.20	\$800.70	\$38,593.
		0071	1150	7034219A	TYPE D BARRIER	209.00	0.00	209.00	LF	209.00	\$102.80	\$21,485.2
		0071	1160	7034221	SLAB ON CONCRETE NU-GIRDER	499.00	0.00	499.00	SQYD	499.00	\$348.10	\$173,701.
		0071	1170	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	481.00	0.00	481.00	LF	481.00	\$274.40	\$131,986.4
		0071	1180	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$2,148.50	\$4,297.0
		0071	1190	7161000	PLAIN NEOPRENE BEARING PAD	14.00	0.00	14.00	EA	14.00	\$149.50	\$2,093.0
		0071	1200	7201300	PIPE PILE SPACERS	14.00	0.00	14.00	EA	14.00	\$892.00	\$12,488.0
		0072	1210	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,282.85	\$3,282.
		0072	1220	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,865.95	\$3,865.
		0072	1230	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,362.00	0.00	3,362.00	SQFT	3,362.00	\$67.50	\$226,935.
		0073	1240	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,320.95	\$3,320.
		0073	1250	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,910.80	\$3,910.
		0073	1260	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,401.00	0.00	3,401.00	SQFT	3,401.00	\$66.80	\$227,186.
		0040	5001	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	0.00	60.00	60.00	LF	60.00	\$53.55	\$3,213.
		0020	5002	9011311	LUMINAIRE, LED-A	0.00	4.00	4.00	EA	4.00	\$718.46	\$2,873.
		0040	5003	9035011A	ST-STRUCTURAL	0.00	33.00	33.00	SQFT	33.00	\$25.38	\$837.
		0040	5004	9035071A	STF-STRUCTURAL FLUORESCENT	0.00	20.00	20.00	SQFT	20.00	\$29.49	\$589.
		0001	5005	6169901	MISC.Detour Sign	0.00	1.00	1.00	LS	1.00	\$13,475.43	\$13,475.
		0001	5006	6173706	TEMPORARY TRAFFIC BARRIER STIFFNESS TRANSITION	0.00	51.00	51.00	LF	51.00	\$28.90	\$1,473.5
		0001	5007	6169901	SECTION, CONTRACTOR FURNISHED / RETAINED MISC.Closed Sign on Truss Install and Remove	0.00	1.00	1.00	LS	1.00	\$4,908.75	\$4,908.7
		0001				0.00			20		+ .,500.70	÷ 1,000.1



Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
0122-C03	J4I3291	0001	5009	6169901	MISC.Furnish, Install and Remove Focus on Bridges POP Signs	0.00	1.00	1.00	LS	1.00	\$2,635.50	\$2,635.5
		0020	5010	9019901	MISC.Lighting Repair I-29 and 56th Street	0.00	1.00	1.00	LS	1.00	\$27,860.70	\$27,860.7
		0001	5011	6149902	MISC.Inlet Grate	0.00	1.00	1.00	EA	1.00	\$1,920.00	\$1,920.0
	Project J	4l3291 - To	tal Value	e Posted to D	late as of Report Generated Date							\$3,354,020.5
	J4I3297	0001	1270	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	0.00	\$4,423.45	\$0.0
		0001	1280	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$60,698.00	\$0.0
		0001	1290	2031000	CLASS A EXCAVATION	10,782.00	0.00	10,782.00	CUYD	0.00	\$6.25	\$0.0
		0001	1300	2032000	CLASS C EXCAVATION	326.00	0.00	326.00	CUYD	0.00	\$20.70	\$0.0
		0001	1310	2036000	COMPACTING EMBANKMENT	1,872.00	0.00	1,872.00	CUYD	0.00	\$1.20	\$0.0
		0001	1320	2037075	COMPACTING IN CUT	5.50	0.00	5.50	STA	0.00	\$759.80	\$0.0
		0001	1330	2063000	CLASS 3 EXCAVATION	285.00	0.00	285.00	CUYD	0.00	\$10.10	\$0.0
		0001	1340	2153000	SHAPING SLOPES, CLASS III	0.90	0.00	0.90	100F	0.00	\$630.00	\$0.0
		0001	1350	3030600	FURNISHING ROCK BASE MATERIAL	922.00	0.00	922.00	SQYD	0.00	\$17.65	\$0.0
		0001	1360	3030610A	PLACING ROCK BASE	922.00	0.00	922.00	SQYD	0.00	\$4.95	\$0.0
		0001	1370	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	4,035.00	0.00	4,035.00	SQYD	0.00	\$11.40	\$0.0
		0001	1380	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	238.00	0.00	238.00	TONS	0.00	\$194.25	\$0.0
		0001	1390	4030306	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP250C MIX)	61.00	0.00	61.00	TONS	0.00	\$236.25	\$0.0
		0001	1400	4030308	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP250C MIX)	577.00	0.00	577.00	TONS	0.00	\$157.50	\$0.0
		0001	1410	4039905	MISC.OPTIONAL PAVEMENT I-29	2,765.00	0.00	2,765.00	SQYD	0.00	\$62.80	\$0.0
		0001	1420	4039905	MISC.OPTIONAL PAVEMENT ROUTE AA	3,655.00	0.00	3,655.00	SQYD	0.00	\$48.55	\$0.0
		0001	1430	4071005	TACK COAT	234.00	0.00	234.00	GAL	0.00	\$2.65	\$0.0
		0001	1440	5041000	CONCRETE APPROACH PAVEMENT	812.00	0.00	812.00	SQYD	0.00	\$122.85	\$0.0
		0001	1450	6071011A	CHAIN-LINK FENCE (48 IN.)	238.00	0.00	238.00	LF	0.00	\$48.30	\$0.0
		0001	1460	6071102	MODIFIED CONCRETE GUTTER TYPE B	506.00	0.00	506.00	LF	0.00	\$30.35	\$0.0
		0001	1470	6081010	CONCRETE CURB RAMP	20.00	0.00	20.00	SQYD	0.00	\$75.00	\$0.0
		0001	1480	6081012	TRUNCATED DOMES	114.00	0.00	114.00	SQFT	0.00	\$12.65	\$0.0
		0001	1490	6083008	8 IN. CONCRETE MEDIAN STRIP	80.00	0.00	80.00	SQYD	0.00	\$81.60	\$0.0
		0001	1500	6086004	CONCRETE SIDEWALK, 4 IN.	514.50	0.00	514.50	SQYD	0.00	\$39.15	\$0.1
		0001	1510	6094010	DRAIN BASIN	2.00	0.00	2.00	EA	0.00	\$7,138.20	\$0.0
		0001	1520	6097000	ROCK LINING	3.00	0.00	3.00	CUYD	0.00	\$110.70	\$0.0
			1530	6099903	MISC.CURB AND GUTTER TYPE CG-1	1,145.00	0.00	1,145.00	LF	0.00	\$15.05	\$0.0
		0001	1540	6113020	FURNISHING TYPE 2 ROCK BLANKET	45.00	0.00	45.00	CUYD	0.00	\$69.85	\$0.0
		0001	1550	6113040	PLACING TYPE 2 ROCK BLANKET	45.00	0.00	45.00	CUYD	0.00	\$40.85	\$0.0
		0001	1560	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	1.00	0.00	1.00	EA	0.00	\$5,775.00	\$0.1
		0001	1570	6162002	RETAINED TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,102.50	\$0.0
		0001	1580	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS		\$204,750.00	\$0.
		0001	1590	6173000	CONCRETE TRAFFIC BARRIER. TYPE C	995.00	0.00	995.00	LF	0.00	\$74.80	\$0.
		0001	1600	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED /	3,559.00	0.00	3.559.00	LF	0.00	\$15.20	\$0.
		0001	1000	01100000	RETAINED	0,000.00	0.00	0,000.00		0.00	ψ10.20	φ0.
		0001	1610	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	2.00	0.00	2.00	EA	0.00	\$303.65	\$0.
		0001	1620	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	6,050.00	0.00	6,050.00	LF	0.00	\$9.45	\$0.
		0001	1630	6179902	MISC.CONCRETE TRAFFIC BARRIER TRANSITION	4.00	0.00	4.00	EA	0.00	\$6,053.85	\$0.
		0001	1640	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$378,387.50	\$0.
		0001	1650	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.0
		0001	1660	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	14.00	0.00	14.00	LF	0.00	\$23.10	\$0.0
		0001	1670	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	123.00	0.00	123.00	LF	0.00	\$24.15	\$0.

Total Paid / All Items / All Estimates (Including this Estimate)



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-C03	J4I3297	0001	1680	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	2.00	0.00	2.00	EA	0.00	\$341.25	\$0.00
		0001	1690	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	20.00	0.00	20.00	EA	0.00	\$173.25	\$0.00
		0001	1700	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	14,862.00	0.00	14,862.00	LF	0.00	\$0.20	\$0.00
		0001	1710	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,329.00	0.00	7,329.00	LF	0.00	\$0.25	\$0.00
		0001	1720	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,174.00	0.00	1,174.00	LF	0.00	\$2.35	\$0.00
		0001	1730	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,161.00	0.00	2,161.00	LF	0.00	\$0.15	\$0.00
		0001	1740	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,361.00	0.00	2,361.00	LF	0.00	\$0.15	\$0.00
		0001	1750	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	2,441.00	0.00	2,441.00	SQYD	0.00	\$23.65	\$0.00
		0001	1760	6269909	MISC.OPTIONAL SHOULDER RUMBLE STRIPS	31.80	0.00	31.80	STA	0.00	\$78.75	\$0.00
		0001	1770	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$8,977.50	\$0.00
		0001	1780	7250315A	15 IN. PIPE GROUP B	194.00	0.00	194.00	LF	0.00	\$78.10	\$0.00
		0001	1790	7250324A	24 IN. PIPE GROUP B	37.00	0.00	37.00	LF	0.00	\$71.25	\$0.00
		0001	1800	7261024	24 IN. PIPE GROUP A	50.00	0.00	50.00	LF	0.00	\$85.35	\$0.00
		0001	1810	7319902	MISC.KCMO TYPE 1 INLET 5 FT X 3 FT	4.00	0.00	4.00	EA	0.00	\$5,162.20	\$0.00
		0001	1820	7319902	MISC.KCMO TYPE 2 INLET 5FT X 3FT	1.00	0.00	1.00	EA	0.00	\$5,383.55	\$0.00
		0001	1830	7320024A	24 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$1,503.75	\$0.00
		0001	1840	8051000A	SEEDING - COOL SEASON MIXTURES	0.60	0.00	0.60	ACRE	0.00	\$7,182.00	\$0.00
		0001	1850	8061005	ROCK DITCH CHECK	206.00	0.00	206.00	LF	0.00	\$17.95	\$0.00
		0001 186	1860	8061007A	CURB INLET CHECK	5.00	0.00	5.00	EA	0.00	\$120.75	\$0.00
			1870	8061016	SEDIMENT REMOVAL	33.50	0.00	33.50	CUYD	0.00	\$8.65	\$0.00
		0001	1880	8061017	TEMPORARY SEEDING AND MULCHING	0.30	0.00	0.30	ACRE	0.00	\$105.00	\$0.00
		0001	1890	8061019	SILT FENCE	794.00	0.00	794.00	LF	0.00	\$3.55	\$0.00
		0001	1900	8064137	TYPE 2C EROSION CONTROL BLANKET	1,195.70	0.00	1,195.70	SQYD	0.00	\$1.90	\$0.00
		0010	1910	6061060	MGS GUARDRAIL	250.00	0.00	250.00	LF	0.00	\$21.00	\$0.00
		0010	1920	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	1.00	0.00	1.00	EA	0.00	\$2,713.20	\$0.00
		0010	1930	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	1.00	0.00	1.00	EA	0.00	\$2,625.00	\$0.00
		0010	1940	6061074	MGS HEIGHT AND BLOCK TRANSITION	2.00	0.00	2.00	EA	0.00	\$540.75	\$0.00
		0020	1950	9011010	RELOCATED POLE	1.00	0.00	1.00	EA	0.00	\$1,001.20	\$0.00
		0020	1960	9011250	LUMINAIRE, 150 WATT HIGH PRESSURE SODIUM (UNDERPASS)	4.00	-4.00	0.00	EA	0.00	\$665.95	\$0.00
		0020	1970	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	0.00	\$7,699.90	\$0.00
		0020	1980	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	164.00	0.00	164.00	LF	0.00	\$13.80	\$0.00
		0020	1990	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	111.00	0.00	111.00	LF	0.00	\$15.25	\$0.00
		0020	2000	9014003	CONDUIT, 3 IN. RIGID, PUSHED	62.00	0.00	62.00	LF	0.00	\$30.75	\$0.00
		0020	2010	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	334.00	0.00	334.00	LF	0.00	\$57.35	\$0.00
		0020	2020	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	0.00	\$393.80	\$0.00
		0020	2030	9016112	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	0.00	\$2,076.90	\$0.00
		0020	2040	9017004	CABLE, 4 AWG 1 CONDUCTOR	220.00	0.00	220.00	LF	0.00	\$2.85	\$0.00
		0020	2050	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,200.00	0.00	1,200.00	LF	0.00	\$2.00	\$0.00
		0020	2060	9017204	WIRE, 4 AWG, BARE NEUTRAL	111.00	0.00	111.00	LF	0.00	\$2.85	\$0.00
		0020	2070	9017208	WIRE, 8 AWG, BARE NEUTRAL	601.00	0.00	601.00	LF	0.00	\$2.05	\$0.00
		0020	2080	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	560.00	0.00	560.00	LF	0.00	\$9.15	\$0.00
		0020	2090	9018245	NEUTRAL, 6 AWG POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$1,184.40	\$0.00
		0020	2100	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE,	1.00	0.00	1.00	EA	0.00	\$4,401.60	\$0.00
		0020	2100	5010010	LIGHTING ONLY	1.00	0.00	1.00	LA	0.00	ψτ,τ01.00	φ 0.0 0



Total Paid / All Items / All Estimates (Including this Estimate)

ct Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
07 0020	2110	9019902	MISC.JUNCTION BOX, NEMA	4.00	0.00	4.00	EA	0.00	\$516.60	\$0.00
0020	2120	9019903	MISC.1" FLEXIBLE CONDUIT	8.00	0.00	8.00	LF	0.00	\$53.45	\$0.00
0040	2130	9031010	CONCRETE FOOTINGS, EMBEDDED	1.90	0.00	1.90	CUYD	0.00	\$540.75	\$0.00
0040	2140	9031210	STRUCTURAL STEEL POSTS	200.00	0.00	200.00	LB	0.00	\$5.25	\$0.00
0040	2150	9031250A	U-CHANNEL POST, 3 LB	7.00	0.00	7.00	LF	0.00	\$52.50	\$0.00
0040	2160	9031270A	2 IN. PSST POST - 12 GA.	256.00	-256.00	0.00	LF	0.00	\$12.60	\$0.00
0040	2170	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	48.00	-48.00	0.00	LF	0.00	\$19.95	\$0.00
0040	2180	9031280	2.5 IN. PSST POST - 12 GA.	80.00	256.00	336.00	LF	0.00	\$13.65	\$0.00
0040	2190	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	15.00	48.00	63.00	LF	0.00	\$53.55	\$0.00
0040	2200	9035004A	SH-FLAT SHEET	210.00	0.00	210.00	SQFT	0.00	\$21.00	\$0.00
0040	2210	9035069A	SHF-FLAT SHEET FLUORESCENT	3.00	0.00	3.00	SQFT	0.00	\$24.15	\$0.00
0070	2220	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	6.00	0.00	6.00	SQFT	0.00	\$47.30	\$0.00
0070	2230	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$51,129.75	\$0.00
0070	2240	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$100,183.20	\$0.00
0070	2250	5031010A	BRIDGE APPROACH SLAB (MAJOR)	310.00	0.00	310.00	SQYD	0.00	\$248.05	\$0.00
0070	2260	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	552.00	0.00	552.00	LF	0.00	\$81.35	\$0.00
0070	2270	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	0.00	\$420.00	\$0.00
0070	2280	7026000	PRE-BORE FOR PILING	184.00	0.00	184.00	LF	0.00	\$114.45	\$0.00
0070	2290	7027000	PILE POINT REINFORCEMENT	16.00	0.00	16.00	EA	0.00	\$137.00	\$0.00
0070	2300	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	92.70	0.00	92.70	CUYD	0.00	\$697.90	\$0.00
0070	2310	7034219A	TYPE D BARRIER	227.00	0.00	227.00	LF	0.00	\$99.35	\$0.00
0070	2320	7034222	SLAB ON CONCRETE BEAM	641.00	0.00	641.00	SQYD	0.00	\$334.10	\$0.00
0070	2330	7056050A	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	718.00	0.00	718.00	LF	0.00	\$321.35	\$0.00
0070	2340	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,148.50	\$0.00
0070	2350	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	18.00	0.00	18.00	EA	0.00	\$279.70	\$0.00
0070	2360	7201300	PIPE PILE SPACERS	16.00	0.00	16.00	EA	0.00	\$891.20	\$0.00
0071	2370	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	6.00	0.00	6.00	SQFT	0.00	\$47.30	\$0.00
0071	2380	2065500	TEMPORARY SHORING	1.00	0.00	1.00	LS	0.00	\$51,129.75	\$0.00
0071	2390	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$69,796.65	\$0.00
0071	2400	5031010A	BRIDGE APPROACH SLAB (MAJOR)	310.00	0.00	310.00	SQYD	0.00	\$248.05	\$0.00
0071	2410	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	752.00	0.00	752.00	LF	0.00	\$84.95	\$0.00
0071	2420	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	0.00	\$420.00	\$0.00
0071	2430	7026000	PRE-BORE FOR PILING	416.00	0.00	416.00	LF	0.00	\$43.05	\$0.00
0071	2440	7027000	PILE POINT REINFORCEMENT	16.00	0.00	16.00	EA	0.00	\$137.00	\$0.00
0071	2450	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	69.90	0.00	69.90	CUYD	0.00	\$779.50	\$0.00
0071	2460	7034219A	TYPE D BARRIER	224.00	0.00	224.00	LF	0.00	\$99.80	\$0.00
0071	2470	7034222	SLAB ON CONCRETE BEAM	641.00	0.00	641.00	SQYD	0.00	\$330.60	\$0.00
0071	2480	7056050A	27 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	718.00	0.00	718.00	LF	0.00	\$321.35	\$0.00
0071	2490	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,148.50	\$0.00
0071	2500	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	18.00	0.00	18.00	EA	0.00	\$402.75	\$0.00
	2510	7201300	PIPE PILE SPACERS	16.00	0.00	16.00	EA	0.00	\$891.20	\$0.00
0072	2520	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$3,630.50	\$0.00
	2530	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$4,275.35	\$0.00
0072	2540	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,718.00	0.00	3,718.00	SQFT	0.00	\$66.55	\$0.00
	2550	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$4,247.60	\$0.00
										\$0.00
0071 0072 0072		2500 2510 2520 2530 2540	2500 7161003 22510 7201300 22520 7110300 22530 7110400 22540 7201000 22550 7110300	25007161003LAMINATED NEOPRENE BEARING PAD (TAPERED)25107201300PIPE PILE SPACERS25207110300CONCRETE AND MASONRY PROTECTION SYSTEM25307110400SACRIFICIAL GRAFFITI PROTECTION SYSTEM25407201000MECHANICALLY STABILIZED EARTH WALL SYSTEMS25507110300CONCRETE AND MASONRY PROTECTION SYSTEM	Z500Z161003LAMINATED NEOPRENE BEARING PAD (TAPERED)18.002510Z201300PIPE PILE SPACERS16.002520Z110300CONCRETE AND MASONRY PROTECTION SYSTEM1.002530Z110400SACRIFICIAL GRAFFITI PROTECTION SYSTEM1.002540Z201000MECHANICALLY STABILIZED EARTH WALL SYSTEMS3,718.002550Z110300CONCRETE AND MASONRY PROTECTION SYSTEM1.00	7161003 LAMINATED NEOPRENE BEARING PAD (TAPERED) 18.00 0.00 2510 7201300 PIPE PILE SPACERS 16.00 0.00 2520 7110300 CONCRETE AND MASONRY PROTECTION SYSTEM 1.00 0.00 2530 7110400 SACRIFICIAL GRAFFITI PROTECTION SYSTEM 1.00 0.00 2540 7201000 MECHANICALLY STABILIZED EARTH WALL SYSTEMS 3,718.00 0.00 2550 7110300 CONCRETE AND MASONRY PROTECTION SYSTEM 1.00 0.00	2500 7161003 LAMINATED NEOPRENE BEARING PAD (TAPERED) 18.00 0.000 18.00 2510 7201300 PIPE PILE SPACERS 16.00 0.000 16.00 2520 7110300 CONCRETE AND MASONRY PROTECTION SYSTEM 1.00 0.000 1.00 2530 7110400 SACRIFICIAL GRAFFITI PROTECTION SYSTEM 1.00 0.000 1.00 2540 7201000 MECHANICALLY STABILIZED EARTH WALL SYSTEMS 3,718.00 0.000 3,718.00 2550 7110300 CONCRETE AND MASONRY PROTECTION SYSTEM 1.00 0.000 1.000	Addition Addition	Z500 Z161003 LAMINATED NEOPRENE BEARING PAD (TAPERED) 18.00 0.00 18.00 EA 0.00 Z510 Z201300 PIPE PILE SPACERS 16.00 0.00 16.00 EA 0.00 Z520 Z110300 CONCRETE AND MASONRY PROTECTION SYSTEM 1.00 0.00 1.00 LS 0.00 Z530 Z110400 SACRIFICIAL GRAFFITI PROTECTION SYSTEM 1.00 0.00 1.00 LS 0.00 Z540 Z01000 MECHANICALLY STABILIZED EARTH WALL SYSTEMS 3,718.00 0.00 3,718.00 SQFT 0.00 Z550 Z110300 CONCRETE AND MASONRY PROTECTION SYSTEM 1.00 0.000 3,718.00 SQFT 0.00	And And

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-C03	J4I3297	0073	2570	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	4,350.00	0.00	4,350.00	SQFT	0.00	\$76.55	\$0.00
		0040	5101	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	0.00	6.00	6.00	EA	0.00	\$235.20	\$0.00
		0020	5102	9011311	LUMINAIRE, LED-A	0.00	4.00	4.00	EA	0.00	\$718.46	\$0.00
	Project J	1413297 - To	otal Value	Posted to D	Date as of Report Generated Date							\$0.00
210122-C03 Ove	rall - Tota	I Value Pos	sted to Da	te as of Rep	oort Generated Date							\$3,354,020.54



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project:	J4I3291											
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0680	9012230	BASE MOUNTED CONTROL STATION	12/22/21	1/3/22	0.05	EA	Lighting Control Station 56th Street and Prairie View Road. Station 23+80 Right 108. Complete	23+80			Right 108	
0780	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120	12/22/21	1/3/22	0.25	EA	Power Supply 56th Street and Prairie view Road. Station 24+21 Right 81ft. Complete	24+21			Right 81	
5010	9019901	MISC. HIGHWAY LIGHTING	12/22/21	1/3/22	0.05	LS	Power Connected for High Mast Lighting Both North and South of 56th Street	902+90		908+00		

The information below this line are details for Construction Signs (if applicable). No Data Available



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3291	0010	TEMPORARY SURFACING	Material		14	Oct 18, 2021	SYSTEM	\$6,099.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$6,099.75)	Estimate Exception Fon the current Payment Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0010 -	Total						\$0.00	
	0040	CLASS A EXCAVATION	Price FUEL		1	Apr 2, 2021	SYSTEM	\$74.30	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					2	Apr 16, 2021	SYSTEM	\$220.86	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	May 3, 2021	SYSTEM	\$24.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Aug 2, 2021	SYSTEM	\$192.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Aug 15, 2021	SYSTEM	\$152.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Sep 2, 2021	SYSTEM	\$132.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Sep 16, 2021	SYSTEM	\$27.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Sep 30, 2021	SYSTEM	\$69.93	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					15	Nov 1, 2021	SYSTEM	\$72.13	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$966.00	
			Price FUEL -	Total				\$966.00	
	0040 -	Total						\$966.00	
	0060	COMPACTING EMBANKMENT	Material		7	Jul 1, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wilsor2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$360.00)	
					8	Jul 16, 2021	SYSTEM	\$610.80	This adjustment offsets the original system-generated Material Payment
									Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$610.80)	
					8 9		SYSTEM SYSTEM	(\$610.80) \$610.80	
						2021 Aug 2,		. ,	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment
					9	2021 Aug 2, 2021 Aug 2,	SYSTEM	\$610.80	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment
					9	2021 Aug 2, 2021 Aug 2, 2021 Aug 15,	SYSTEM SYSTEM	\$610.80 (\$610.80)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment
					9 9 10	2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15,	SYSTEM SYSTEM SYSTEM	\$610.80 (\$610.80) \$610.80	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment
					9 9 10 10	2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$610.80 (\$610.80) \$610.80 (\$610.80)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
					9 9 10 10 11	2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$610.80 (\$610.80) \$610.80 (\$610.80) (\$610.80) \$1,041.60	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
					9 9 10 10 11 11	2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$610.80 (\$610.80) \$610.80 (\$610.80) \$1,041.60 (\$1,041.60)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9 9 10 10 11 11 12	2021 Aug 2, 2021 Aug 12, 2021 Aug 15, 2021 Aug 15, 2021 Seep 2, 2021 Seep 2, 2021 Seep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$610.80 (\$610.80) \$610.80 (\$610.80) \$1,041.60 (\$1,041.60) \$1,386.00	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4I3291	0060	COMPACTING EMBANKMENT	Material	Туре	14	Oct 18, 2021	SYSTEM	\$1,386.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user scarpm1 overridding Payment
					14	Oct 18, 2021	SYSTEM	(\$1,386.00)	Estimate Exception 2 on the current Payment Estimate.
				- Total		2021		\$0.00	
			Material - To					\$0.00	
	0060 -	Total						\$0.00	
	0090	FURNISHING ROCK FILL	Material		8	Jul 16, 2021	SYSTEM	\$7,617.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$7,617.60)	
					9	Aug 2, 2021	SYSTEM	\$7,617.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$7,617.60)	
					10	Aug 15, 2021	SYSTEM	\$7,617.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Aug 15, 2021	SYSTEM	(\$7,617.60)	
					11	Sep 2, 2021	SYSTEM	\$7,617.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$7,617.60)	
					12	Sep 16, 2021	SYSTEM	\$7,617.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$7,617.60)	
					13	Sep 30, 2021	SYSTEM	\$47,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Sep 30, 2021	SYSTEM	(\$47,610.00)	
					14	Oct 18, 2021	SYSTEM	\$47,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$47,610.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0090 - 0120		Material		1	Apr 2, 2021	SYSTEM	\$0.00 \$18,685.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		DAGE			1	Apr 2, 2021	SYSTEM	(\$18,685.36)	Estimate Exception For all current raymon Estimate.
					2	Apr 16, 2021	SYSTEM	\$18,685.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 16, 2021	SYSTEM	(\$18,685.36)	
					3	May 3, 2021	SYSTEM	\$18,685.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$18,685.36)	
					4	May 17, 2021	SYSTEM	\$18,685.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$18,685.36)	



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3291	0120	TYPE 5 AGGREGATE FOR	Material	- Total				\$0.00	
		BASE	Material - Tot	al				\$0.00	
			Overrun	Overrun	13	Sep 30, 2021	SYSTEM	(\$1,038.76)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					16	Nov 16, 2021	SYSTEM	\$1,038.76	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',7.69452 - 7.60000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
			Price FUEL		1	Apr 2, 2021	SYSTEM	\$184.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Sep 30, 2021	SYSTEM	\$78.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total	1			\$262.59	
			Price FUEL -	Total				\$262.59	
	0120 -	Total						\$262.59	
	0130	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		8	Jul 16, 2021	SYSTEM	\$8,333.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		THICK)			8	Jul 16, 2021	SYSTEM	(\$8,333.40)	
					9	Aug 2, 2021	SYSTEM	\$8,333.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$8,333.40)	Estimate Exception 5 on the current Payment Estimate.
				- Total		2021		\$0.00	
			Material - Tot					\$0.00	
			Overrun	Overrun	15	Nov 1, 2021	SYSTEM	(\$1,555.95)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					16	Nov 16, 2021	SYSTEM	\$1,555.95	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.61157 - 11.40000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
			Price FUEL		8	Jul 16, 2021	SYSTEM	\$53.27	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Jul 16, 2021	SYSTEM	\$54.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Aug 15, 2021	SYSTEM	\$100.68	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Sep 2, 2021	SYSTEM	\$148.44	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Sep 16, 2021	SYSTEM	\$29.91	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Oct 18, 2021	SYSTEM	\$65.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Oct 18, 2021	SYSTEM	\$74.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					15	Nov 1, 2021	SYSTEM	\$47.63	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					15	Nov 1, 2021	SYSTEM	\$49.75	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$623.89	
			Price FUEL -	Total				\$623.89	
	0130 -	Total						\$623.89	
	0140	TYPE A2 SHOULDER	Other Item Adjustment	FUEL	13	Oct 1, 2021	scarpm1	\$20.07	Fuel Adjustment for Type A2 Shoulder, 5.75" PCC 65.0 SQYD installed between 9/16/21 – 9/30/21 = \$20.07
					14	Oct 18, 2021	scarpm1	\$22.59	Fuel Adjustment for Type A2 Shoulder, 5.75" PCC 50.1 SQYD installed between 10/1/21 – 10/15/21 = \$22.59
				FUEL - Tota	ıl			\$42.66	



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3291	0140	TYPE A2 SHOULDER	Other Item A	.djustment - T	otal			\$42.66	
	0140 -	Total						\$42.66	
	0150	MISC.	Material		11	Sep 2, 2021	SYSTEM	\$73,565.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$73,565.16)	
					12	Sep 16, 2021	SYSTEM	\$83,658.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$83,658.12)	
					13	Sep 30, 2021	SYSTEM	\$39,643.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Sep 30, 2021	SYSTEM	(\$39,643.72)	
					14	Oct 18, 2021	SYSTEM	\$5,945.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$5,945.02)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	FUEL	11	Sep 2, 2021	scarpm1	\$649.90	Fuel Adjustment for Misc. Optional Pavement 56th Street = 8 IN Concrete Pavement 1504.4 SQYD installed between 8/16/21-9/1/21 = \$649.90
					12	Sep 16, 2021	scarpm1	\$78.02	Fuel Adjustment for Misc. Optional Pavement 56th Street = 8 IN Concrete Pavement 206.4 SQYD installed between 9/2/21-9/15/21 = \$78.02
					14	Oct 18, 2021	scarpm1	\$364.87	Fuel Adjustment for Misc. Optional Pavement 56th Street = 8 IN Concrete Pavement 661.0 SQYD installed between 10/1/21 – 10/15/21 = \$364.87
					15	Nov 2, 2021	scarpm1	\$254.03	Fuel Adjustment for Misc. Optional Pavement 56th Street = 8 IN Concrete Pavement 460.2 SQYD installed between 10/16/21 – 11/1/21 = \$254.03
				FUEL - Tota	I			\$1,346.82	
			Other Item A	djustment - T	otal			\$1,346.82	
			Overrun	Overrun	15	Nov 1, 2021	SYSTEM	(\$6,503.70)	
					16	Nov 16, 2021	SYSTEM	\$6,503.70	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',48.90000 - 48.90000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0150 -	Total						\$1,346.82	
	0160	MISC.	Other Item Adjustment	FUEL	1	Apr 2, 2021	scarpm1	\$737.58	Fuel Adjustment for Misc. Optional Pavement Shoulder / Crossover = 8 IN Concrete Pavement 2458.6 SQYD installed between 3/16/21 – 4/1/21 = \$737.58
					8	Jul 16, 2021	scarpm1	\$280.70	Fuel Adjustment for Misc. Optional Pavement Shoulder / Crossover = 8 IN Concrete Pavement 731.0 SQYD installed between 7/1/21-7/15/21 = \$280.70
					13	Oct 1, 2021	scarpm1	\$288.19	Fuel Adjustment for Misc. Optional Pavement Shoulder / Crossover = 8 IN Concrete Pavement 762.4 SQYD installed between 9/16/21 – 9/30/21 = \$288.19
				FUEL - Tota	I			\$1,306.47	
			Other Item A	.djustment - T	otal			\$1,306.47	
			Overrun	Overrun	8	Jul 16, 2021	SYSTEM	(\$3,576.44)	
					9	Aug 2, 2021	SYSTEM	\$3,576.44	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',48.20000 - 48.20000, 'is applied (if non-zero).
					13	Sep 30, 2021	SYSTEM	(\$36,747.68)	



Jan 5, 2022

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
91	0160	MISC.	Overrun	Overrun	16	Nov 16, 2021	SYSTEM	\$36,747.68	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',48.20000 - 48.20000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0160 -	Total						\$1,306.47	
	0170	CONCRETE APPROACH PAVEMENT	Material		8	Jul 16, 2021	SYSTEM	\$21,522.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$21,522.36)	
					12	Sep 16, 2021	SYSTEM	\$20,417.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$20,417.23)	
					13	Sep 30, 2021	SYSTEM	\$20,417.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Sep 30, 2021	SYSTEM	(\$20,417.23)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Other Item Adjustment	OVRN	12	Sep 16, 2021	scarpm1	(\$9,168.03)	Line item adjustment to withhold the amount over plan quantity. 77.4 SQYD at \$118.45 per SQYD = (\$9,168.03)
					14	Oct 18, 2021	scarpm1	\$9,168.03	Line item adjustment to pay back amount over plan due to material exception being resolved and allow system to withhold the amount over plan quantity. 77.4 SQYD at \$118.45 per SQYD = \$9,168.03
				OVRN - Tota	al			\$0.00	
			Other Item A	djustment - T	otal			\$0.00	
			Overrun	Overrun	12	Sep 16, 2021	SYSTEM	\$9,168.03	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40.
					12	Con 10			
						Sep 16, 2021	SYSTEM	(\$9,168.03)	
					13		SYSTEM SYSTEM	(\$9,168.03) (\$9,168.03)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
						2021 Sep 30,			
					13	2021 Sep 30, 2021 Sep 30,	SYSTEM	(\$9,168.03)	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370;
					13 13	2021 Sep 30, 2021 Sep 30, 2021 Oct 18,	SYSTEM SYSTEM	(\$9,168.03) \$9,168.03	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all
				Overrun - To	13 13 14 16	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16,	SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03)	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is
			Overrun - To		13 13 14 16	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16,	SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03) \$9,168.03	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is
	0170 -	Total	Overrun - To		13 13 14 16	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16,	SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03) \$9,168.03 \$9,168.03	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is
	0170 - 0180	Total PIPE COLLAR, TYPE A	Overrun - To Material		13 13 14 16	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16,	SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03) \$9,168.03 \$9,168.03 \$0.00	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is
		PIPE COLLAR,			13 13 14 16 Otal	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03) \$9,168.03 \$9,168.03 \$0.00 \$0.00	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
		PIPE COLLAR,			13 13 14 16 Dtal	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03) \$9,168.03 \$0.00 \$0.00 \$0.00 \$2,427.40	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
		PIPE COLLAR,		tal - Total	13 13 14 16 Dtal	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03) \$9,168.03 \$0.00 \$0.00 \$2,427.40 (\$2,427.40)	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
		PIPE COLLAR, TYPE A	Material	tal - Total	13 13 14 16 Dtal	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03) \$9,168.03 \$9,168.03 \$0.00 \$0.00 \$0.00 \$2,427.40 (\$2,427.40) \$0.00	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
	0180	PIPE COLLAR, TYPE A	Material Material - Tot	tal - Total	13 13 14 16 Dtal	2021 Sep 30, 2021 Sep 30, 2021 Oct 18, 2021 Nov 16, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$9,168.03) \$9,168.03 (\$9,168.03) \$9,168.03 \$9,168.03 \$0.00 \$0.00 \$2,427.40 (\$2,427.40) (\$2,427.40) \$0.00	of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0012) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 172.370; Overrun Quantity Balance 77.40. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',118.45000 - 118.45000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment



Jan 5, 2022

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
1.10,000	Lino	Decemption	Туре	Adjustment Type	Number	Date	Ву	, ano and	
J4I3291	0190	CHAIN-LINK FENCE (48 IN.)	Material		14	Oct 18, 2021	SYSTEM	\$9,660.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$9,660.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0190 -	Total						\$0.00	
	0200	MODIFIED CONCRETE GUTTER TYPE B	Material		5	Jun 1, 2021	SYSTEM	\$3,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		00112111125			5	Jun 1, 2021	SYSTEM	(\$3,050.00)	
					6	Jun 16, 2021	SYSTEM	\$5,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$5,856.00)	
					7	Jul 1, 2021	SYSTEM	\$5,856.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wilsor2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$5,856.00)	
					12	Sep 16, 2021	SYSTEM	\$13,054.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$13,054.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0200 -	Total						\$0.00	
	0210	CONCRETE CURB RAMP	Material		11	Sep 2, 2021	SYSTEM	\$1,170.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$1,170.00)	
					12	Sep 16, 2021	SYSTEM	\$2,152.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user scarpm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$2,152.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	OVRN		Sep 16, 2021	scarpm1	(\$180.00)	2.4 SQYD at \$75.00 per SQYD = (\$180.00)
					13	Oct 1, 2021	scarpm1	\$180.00	Line item adjustment to pay back amount over plan due to material exception being resolved and allow system to withhold the amount over plan quantity. 2.4 SQYD at \$75.00 per SQYD = \$180.00
				OVRN - Tota	al			\$0.00	
			Other Item A	.djustment - T	otal			\$0.00	
			Overrun	Overrun	12	Sep 16, 2021	SYSTEM	\$180.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 28.700; Overrun Quantity Balance 2.40.
					12	Sep 16, 2021	SYSTEM	(\$180.00)	
					13	Sep 30, 2021	SYSTEM	(\$180.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					16	Nov 16, 2021	SYSTEM	\$180.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',75.00000 - 75.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3291	0210 -	Total						\$0.00	
	0220	TRUNCATED DOMES	Material		11	Sep 2, 2021	SYSTEM	\$278.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$278.30)	
					12	Sep 16, 2021	SYSTEM	\$581.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$581.90)	
					13	Sep 30, 2021	SYSTEM	\$581.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user scarpm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					13	Sep 30, 2021	SYSTEM	(\$581.90)	
					14	Oct 18, 2021	SYSTEM	\$581.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$581.90)	
				- Total		2021		\$0.00	
			Material - To	tal				\$0.00	
	0220 -	Total						\$0.00	
	0230	CONCRETE SIDEWALK, 4 IN.	Material		11	Sep 2, 2021	SYSTEM	\$1,037.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$1,037.40)	
					12	Sep 16, 2021	SYSTEM	\$7,848.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$7,848.33)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	15	Nov 1, 2021	SYSTEM	(\$139.65)	
					16	Nov 16, 2021	SYSTEM	\$139.65	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',39.90000 - 39.90000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0230 - 0240	Total CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	Material		13	Sep 30, 2021	SYSTEM	\$0.00 \$1,706.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user scarpm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		height) the S			13	Sep 30, 2021	SYSTEM	(\$1,706.20)	Esumate Exception to on the current r ayment Esumate.
					14	Oct 18, 2021	SYSTEM	\$1,706.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$1,706.20)	,
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0240 -	Total						\$0.00	
	0260	ROCK LINING	Material		13	Sep 30, 2021	SYSTEM	\$332.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Sep 30, 2021	SYSTEM	(\$332.10)	
					14	Oct 18,	SYSTEM	\$332.10	This adjustment offsets the original system-generated Material Payment



Jan 5, 2022

Image: state Image: state<	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Image: state	0260	ROCK LINING	Material			2021			Estimate Item Adjustment (0013) due to user scarpm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
Interview Interview <thinterview< th=""> <thinterview< th=""> <thi< td=""><td></td><td></td><td></td><td></td><td>14</td><td></td><td>SYSTEM</td><td>(\$332.10)</td><td></td></thi<></thinterview<></thinterview<>					14		SYSTEM	(\$332.10)	
Overnun Overnun 15 Nur 1 SYSTEM (6998-30) Introduce based on averaged overnun adjustments for installed samily previous payment for installed samily previous payment for installed samily payment for insta samily for installed samily payment for installed samily paymen				- Total				\$0.00	
Image: state in the s			Material - To	tal				\$0.00	
Image: Construct Total Sec: Co			Overrun	Overrun	15		SYSTEM	(\$996.30)	
Overnue - Total Overnue - Total Support Support 0270 MSC FAVED DRAINAGE Material 1 Sep 2, 2021 SYSTEM \$1.20.05 This adjustment offerds the original system generated Material Payment Estimate Esception 3 on the output offerds the original system generated Material Payment Estimate Esception 3 on the output offerd to user scapm1 overriding Payment Estimate Esception 12 on the output offerd to user scapm1 overriding Payment Estimate Esception 12 on the output offerd to user scapm1 overriding Payment Estimate Esception 12 on the output offerd to user scapm1 overriding Payment Estimate Esception 12 on the output offerd to user scapm1 overriding Payment Estimate Esception 12 on the current Payment Estimate. 13 Sep 30, Sep 30, SYSTEM S42.264.20 This adjustment offerds the original system-generated Material Payment Estimate Esception 12 on the current Payment Estimate. 13 Sep 30, Sep 30, SYSTEM S42.264.20 This adjustment offerds the original system-generated Material Payment Estimate Esception 12 on the current Payment Estimate. Material - Total Sep 30, SYSTEM S42.264.20 Overnum - Estimate					16		SYSTEM	\$996.30	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',110.70000 - 110.70000, 'is applied (if non-zero).
O220 - Total O320 - Total				Overrun - T	otal	1		\$0.00	
0270 MISC PAVED DRAINAGE Material 1 Sep 2, 2021. SYSTEM \$1/2025. This adjustment for low sciences are determined payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem for 0271 data to use categorie deviced payment betwindle from 4 ginstem 4 ginstem for 0271 data to use			Overrun - To	tal				\$0.00	
DRAINAGE Estimate tem Adjustment (0012) due to user sargent overdiding Payment Estimate. 11 Sep 2, SYSTEM (\$1,20.55) 12 Sep 16, SYSTEM (\$1,20.55) 12 Sep 16, SYSTEM \$42,84.20 13 Sep 0, SYSTEM \$42,84.20 14 Oremun \$42,84.20 15 Sep 0, SYSTEM \$42,84.20 16 Nov:16, SYSTEM \$42,84.20 17 Sep 0, SYSTEM \$42,84.20 18 Sep 0, SYSTEM \$42,84.20 19 Nov:16, SYSTEM \$42,84.20 10 Nov:16, SYSTEM \$216.30 10 Nov:16, SYSTEM \$216.30 10 Nov:16, SYSTEM \$216.30 10 Nov:16, SYSTEM \$216.30 10 Nov:16, SYSTEM	0260 -	Total						\$0.00	
0340 CONCRETE BARRER, TYPE C Vertual 12 Sep 30, 2021 SYSTEM \$4,264.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. 12 Sep 16, 2021 SYSTEM \$4,264.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. 13 Sep 30, 2021 SYSTEM \$4,264.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. Neterial - Total Vertual 14 Oct 18, 2021 SYSTEM (\$4,264.20) Overrun Vertual 14 Oct 18, 2021 SYSTEM (\$216.30) Overrun Vertual 14 Oct 18, 2021 SYSTEM (\$216.30) Overrun Vertual 14 Oct 18, 2021 SYSTEM \$218.30 Unit price based on averaged overrun adjustments for installed quantity previous payment estimates. Price Adjustment of 15.45000 - 15.45000 0340 CONCRETE BARRER, TYPE C 14 Nov 16, 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. <	0270		Material		11		SYSTEM	\$1,220.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
Visite Visite<					11		SYSTEM	(\$1,220.55)	
View View <th< td=""><td></td><td></td><td></td><td></td><td>12</td><td></td><td>SYSTEM</td><td>\$4,264.20</td><td>This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user scarpm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.</td></th<>					12		SYSTEM	\$4,264.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user scarpm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
Image: Part of the second state in the the second					12		SYSTEM	(\$4,264.20)	
Image: Constraint of the control of the con					13		SYSTEM	\$4,264.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
Material - Total SySTEM (\$216.30) Overrun Overrun 14 Oct 18. 2021 SYSTEM (\$216.30) Overrun - Total 0 0 SYSTEM \$216.30 Unit price based on averaged overrun adjustments for installed quantity previous payment estimates. Price Adjustments of '15.45000 - 15.45000 Overrun - Total 0 0 SYSTEM \$216.30 Unit price based on averaged overrun adjustments of '15.45000 - 15.45000 0340 CONCETE Material File SYSTEM \$30.00 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0011) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0011) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm 1 overridding Payment Estimate Item Adjustment (0002) due to user scarpm 1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustet Item Adjustment (0002) due to user scarpm 1 overri					13		SYSTEM	(\$4,264.20)	
Overrun Overrun 14 Oct 18 SYSTEM (S216.30) 16 Nov 16 SYSTEM S216.30 Unit price based on averaged overrun adjustments for installed quantity previous payment estimates. Price Adjustments of ',15.45000 = 15.45000 applied (f non-zero). 0200 - Total Overrun - Total 50.00 0200 - Total SYSTEM S37.731.70 0340 CONCRETE TRAFFIG BARRIER, TYPE C Material 16 Nov 16. SYSTEM S33.731.70 17 De 2, 2021 SYSTEM S33.731.70 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 16 Nov 16. SYSTEM S33.731.70 This adjustment offsets the original system-generated Material Payment Estimate. 17 De 2, 2021 SYSTEM S33.731.70 Estimate Exception 1 on the current Payment Estimate. 0340 - Total Total SySTEM S3.731.70 Estimate Exception 1 on the current Payment Estimate. 17 De 2, 2021 SYSTEM S3.731.70 Estimate Exception 1 on the current Payment Estimate. 0340 - Total Total SySTEM S3.791.70									
Verture - Total Sector Sector Sector 0240 - Total 0									
Visit Visit <th< td=""><td></td><td></td><td>Overrun</td><td>Overrun</td><td>14</td><td></td><td></td><td>(\$216.30)</td><td></td></th<>			Overrun	Overrun	14			(\$216.30)	
Overrun - Total \$0.00 0270 - Total \$0.00 0340 CONCRETE TRAFFIC BARRIER, TYPE C Material 16 Nov 16, 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user scarpm1 overridding Payment Estimate Item Adjustment (0001) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Item Adjustment (0021) due to user scarpm1 overridding Payment Estimate Item Adjustment (0021) due to user scarpm1 overridding Payment Estimate Item Adjustment (0021) due to user scarpm1 overridding Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estim					16		SYSTEM	\$216.30	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.45000 - 15.45000, 'is applied (if non-zero).
0270 - Total \$0.00 0340 CONCRETE TRAFFIC BARRIER, TYPE C Material 16 Nov 16, 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user scarpm 1 overridding Paym Estimate Exception 1 on the current Payment Estimate. 16 Nov 16, 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 17 Dec 2, 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 0340 - Total • Total • Total • SySTEM \$33,731.70 • ONO • ONO<					otal				
0340 CONCRETE TRAFFIC BARRIER, TYPE C Material TRAFFIC BARRIER, TYPE C Material I 16 Nov 16, 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 16 Nov 16, 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. 17 Dec 2, 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate. • Total • • • • • • • • • • • • • • • • • • •	0070		Overrun - To	tal					
TRAFFIC BARRIER, TYPE C ¹⁰ ¹			Madavial		10	New 40	OVOTEM		This a discharged off whether a single control of Material Descent
0340 - Total 2021 2021 SYSTEM \$33,731.70 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate. 0340 - Total -Total Sep 30, 2021 SYSTEM \$9,091.90 This adjustment offsets the original system-generated Material Payment Estimate. 0340 - Total Sep 30, 2021 SYSTEM \$9,091.90 This adjustment offsets the original system-generated Material Payment Estimate. 0340 - Total Sep 30, 2021 SYSTEM \$9,091.90 This adjustment offsets the original system-generated Material Payment Estimate. 0350 CONCRETE TRAFFIC TRAFFIC BARRIER, TYPE D Material 13 Sep 30, 2021 SYSTEM \$9,091.90 This adjustment offsets the original system-generated Material Payment Estimate. 13 Sep 30, 2021 SYSTEM \$9,091.90 This adjustment offsets the original system-generated Material Payment Estimate. 16 Nov 16, 2021 SYSTEM \$22,768.70 This adjustment offsets the original system-generated Material Payment Estimate. 16 Nov 16, 2021 SYSTEM \$22,768.70 This adjustment offsets the original system-generated Material Payment Estimate.	0340	TRAFFIC	Material		10		SYSTEM	\$33,731.70	Estimate Item Adjustment (0011) due to user scarpm1 overridding Payment
Vision Vision Vision Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Vision Vision Vision Vision Vision Vision					16		SYSTEM	(\$33,731.70)	
O340 - Total Superior \$0.00 0340 - Total \$0.00 0340 - Total \$0.00 0350 CONCRETE TRAFFIC BARRIER, TYPE D Material 13 Sep 30, 2021 SYSTEM \$9,091.90 13 Sep 30, 2021 SYSTEM 13 Sep 30, 2021 SYSTEM 14 Nov 16, 2021 SYSTEM 15 Nov 16, 2021 16 Nov 16, SYSTEM 16 Nov 16, SYSTEM 16 Nov 16, SYSTEM 16 Nov 16, SYSTEM					17		SYSTEM	\$33,731.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
Material - Total \$0.00 0340 - Total \$0.00 0350 CONCRETE TRAFFIC BARRIER, TYPE D Material 13 Sep 30, 2021 SYSTEM 2021 \$9,091.90 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate. 13 Sep 30, 2021 SYSTEM (\$9,091.90) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 16 Nov 16, 2021 SYSTEM (\$22,768.70)					17		SYSTEM	(\$33,731.70)	
0340 - Total \$0.00 0350 CONCRETE TRAFFIC BARRIER, TYPE D Material 13 Sep 30, 2021 SYSTEM \$9,091.90 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate. 13 Sep 30, 2021 SYSTEM (\$9,091.90) 16 Nov 16, 2021 SYSTEM \$22,768.70 16 Nov 16, 2021 SYSTEM \$22,768.70)				- Total				\$0.00	
0350 CONCRETE TRAFFIC BARRIER, TYPE D Material TRAFFIC BARRIER, TYPE D Material Nov 16, 2021 Sep 30, 2021 SYSTEM \$9,091.90 This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 13 Sep 30, 2021 SYSTEM (\$9,091.90) This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. 14 Nov 16, 2021 SYSTEM \$22,768.70 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			Material - To	tal				\$0.00	
Image: Second	0340 -	Total						\$0.00	
2021 2021 16 Nov 16, 2021 16 Nov 16, SYSTEM	0350	TRAFFIC	Material		13		SYSTEM	\$9,091.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
2021 Estimate Item Adjustment (0012) due to user scarpm1 overridding Paym Estimate Exception 3 on the current Payment Estimate. 16 Nov 16, SYSTEM (\$22,768.70)					13		SYSTEM	(\$9,091.90)	
					16		SYSTEM	\$22,768.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16		SYSTEM	(\$22,768.70)	
17 Dec 2, SYSTEM \$33,624.70 This adjustment offsets the original system-generated Material Payment									



Jan 5, 2022

t	Line	Description	Adjustment	Other	Eat	Created	Created	Americant	Demerice
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
)1 (0350	CONCRETE TRAFFIC	Material			2021			Estimate Item Adjustment (0006) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		BARRIER, TYPE D			17	Dec 2, 2021	SYSTEM	(\$33,624.70)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0350 -	Total						\$0.00	
(0380	MISC. CONCRETE TRAFFIC BARRIER	Material		16	Nov 16, 2021	SYSTEM	\$30,269.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					16	Nov 16, 2021	SYSTEM	(\$30,269.25)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0380 -	Total						\$0.00	
(0410	PAVEMENT EDGE TREATMENT	Material		12	Sep 16, 2021	SYSTEM	\$326.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$326.25)	
					13	Sep 30, 2021	SYSTEM	\$797.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user scarpm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					13	Sep 30, 2021	SYSTEM	(\$797.50)	
					14	Oct 18, 2021	SYSTEM	\$1,558.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$1,558.75)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
5	0410 -	Total						\$0.00	
(0420	PREF THERMO PVMT MARK, 24 IN	Material		17	Dec 2, 2021	SYSTEM	\$508.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment
		WHIT							Estimate Exception 3 on the current Payment Estimate.
		WHIT			17	Dec 2, 2021	SYSTEM	(\$508.20)	Estimate Exception 3 on the current Payment Estimate.
		WHIT		- Total	17		SYSTEM	(\$508.20) \$0.00	Estimate Exception 3 on the current Payment Estimate.
		WHIT	Material - To		17		SYSTEM	. ,	Estimate Exception 3 on the current Payment Estimate.
(0420 -		Material - To		17		SYSTEM	\$0.00	Estimate Exception 3 on the current Payment Estimate.
	<mark>0420 -</mark> 0430				17	2021	SYSTEM	\$0.00 \$0.00	Estimate Exception 3 on the current Payment Estimate.
		Total PREF THERMO PVMT MARK,				2021 Dec 2,		\$0.00 \$0.00 \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
		Total PREF THERMO PVMT MARK,			17	2021 Dec 2, 2021 Dec 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$682.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
		Total PREF THERMO PVMT MARK,		tal - Total	17	2021 Dec 2, 2021 Dec 2,	SYSTEM	\$0.00 \$0.00 \$682.50 (\$682.50)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
(Total PREF THERMO PVMT MARK, LT/RT ARROW	Material	tal - Total	17	2021 Dec 2, 2021 Dec 2,	SYSTEM	\$0.00 \$0.00 \$682.50 (\$682.50) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
(0430	Total PREF THERMO PVMT MARK, LT/RT ARROW Total 4 IN. YELLOW WATERBORNE PAVEMENT	Material	tal - Total tal Overrun	17 17 17	2021 Dec 2, 2021 Dec 2,	SYSTEM	\$0.00 \$0.00 \$682.50 (\$682.50) \$0.00 \$0.00 \$0.00 (\$2.85)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
(0430 0430 -	Total PREF THERMO PVMT MARK, LT/RT ARROW Total 4 IN. YELLOW WATERBORNE	Material Material - To Overrun	- Total tal Overrun Overrun - To	17 17 17	2021 Dec 2, 2021 Dec 2, 2021 Dec 2, 2021	SYSTEM	\$0.00 \$0.00 \$682.50 (\$682.50) \$0.00 \$0.00 \$0.00 (\$2.85) (\$2.85)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
(0430 0430 - 0490	Total PREF THERMO PVMT MARK, LT/RT ARROW Total 4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material Material - To	- Total tal Overrun Overrun - To	17 17 17	2021 Dec 2, 2021 Dec 2, 2021 Dec 2, 2021	SYSTEM	\$0.00 \$0.00 \$682.50 (\$682.50) \$0.00 \$0.00 \$0.00 (\$2.85) (\$2.85)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
(0430 0430 -	Total PREF THERMO PVMT MARK, LT/RT ARROW Total 4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material Material - To Overrun	- Total tal Overrun Overrun - To	17 17 17	2021 Dec 2, 2021 Dec 2, 2021 Dec 2, 2021	SYSTEM	\$0.00 \$0.00 \$682.50 (\$682.50) \$0.00 \$0.00 \$0.00 (\$2.85) (\$2.85)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
(0430 0430 - 0490	Total PREF THERMO PVMT MARK, LT/RT ARROW Total 4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material Material - To Overrun	- Total tal Overrun Overrun - To	17 17 17	2021 Dec 2, 2021 Dec 2, 2021 Dec 2, 2021	SYSTEM	\$0.00 \$0.00 \$682.50 (\$682.50) \$0.00 \$0.00 \$0.00 (\$2.85) (\$2.85)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment
	0430 0430 - 0490 0490 -	Total PREF THERMO PVMT MARK, LT/RT ARROW Total VATERBORNE PAVEMENT MARKING Total 18 IN. GROUP B	Material Material - To Overrun Overrun - To	- Total tal Overrun Overrun - To	17 17 17 17 50tal	2021 Dec 2, 2021 Dec 2, 2021 Dec 2, 2021 Dec 2, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$682.50 (\$682.50) \$0.00 \$0.00 (\$2.85) (\$2.85) (\$2.85)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.



Project Line Description Adjustment Type Other Mumber Est. Type Createl Date Case By Amount Estimate Exception 19 on the current Payment Estimate. J413291 549 FLARED END SEC Material FLARED END SEC Material FLARED END SEC Material FLARED END SEC System Sector System Se	ng Payment Payment ng Payment
FLARED END SEC I1 Sep 2, 2021 SYSTEM (\$1,445.10) 12 Sep 16, 2021 SYSTEM \$1,445.10) This adjustment offsets the original system-generated Material Pagestimate Exception 18 on the current Payment Estimate. 12 Sep 16, 2021 SYSTEM \$1,445.10) This adjustment offsets the original system-generated Material Pagestimate Exception 18 on the current Payment Estimate. 12 Sep 16, 2021 SYSTEM \$1,445.10) This adjustment offsets the original system-generated Material Pagestimate Exception 24 on the current Payment Estimate. 13 Sep 30, 2021 SYSTEM \$1,445.10) This adjustment offsets the original system-generated Material Pagestimate Exception 24 on the current Payment Estimate. 14 Oct 18, 2021 SYSTEM \$1,445.10) This adjustment offsets the original system-generated Material Pagestimate Exception 24 on the current Payment Estimate. 14 Oct 18, 2021 SYSTEM \$1,445.10) This adjustment offsets the original system-generated Material Pagestimate Exception 19 on the current Payment Estimate. 14 Oct 18, 2021 SYSTEM \$1,445.10) This adjustment offsets the original system-generated Material Pagestimate Exception 19 on the current Payment Estimate. 14 Oct 18, 2021 SYSTEM \$3,008.00 This adjustment offsets the original	ng Payment Payment ng Payment
11 Sep 2, 2021 SYSTEM \$(\$1,445.10) 12 Sep 1, 2021 SYSTEM \$1,445.10 This adjustment offsets the original system-generated Material Pay Estimate tem Adjustment (0016) due to user scarpm1 overridding Estimate tem Adjustment (0016) due to user scarpm1 overridding Estimate tem Adjustment offsets the original system-generated Material Pay Estimate tem Adjustment offsets the original system-generated Material Pay Estimate tem Adjustment (0022) due to user scarpm1 overridding Estimate tem Adjustment (0016) due to user scarpm1 overridding Estimate Exception 19 on the current Payment Estimate. V V V V V V V V V V V V V V	ng Payment Payment ng Payment
6 2021 c Estimate Item Adjustment (0016) due to user scarpm1 overridding Estimate Exception 18 on the current Payment Estimate. 12 Sep 16, 2021 SYSTEM (\$1,445.10) 13 Oct 1, 2021 SYSTEM \$1,445.10 13 Sep 30, 2021 SYSTEM \$1,445.10 14 Oct 18, 2021 SYSTEM \$1,445.10 15 State \$1,000 \$1,000 14 Oct 18,	ng Payment Payment ng Payment
0540 - Total 0540 - Total 0550 SEEDING - COOL MixTURES Material 17 Dec 2, 17 Dec 2, 17 SYSTEM \$1,202.1 SYSTEM Signature item Adjustment offsets the original system-generated Material Pay Estimate item Adjustment (0022) due to user scarpm1 overridding Estimate item Adjustment (0022) due to user scarpm1 overridding Estimate item Adjustment (0022) due to user scarpm1 overridding Estimate item Adjustment (0016) due to user scarpm1 overridding Estimate item Adjustment offsets the original system-generated Material Pay Estimate item Adjustment (0009) due to user scarpm1 overridding Estimate item Adjustment (0009) due to	ng Payment Payment
0540 - Total 0540 - Total 2021 2021 2021 SYSTEM (\$1,445.10) 0550 SEEDING - COOL SEASON MIXTURES Material 17 Dec 2, 2021 SYSTEM \$3,208.80) This adjustment offsets the original system-generated Material Pay Estimate Exception 19 on the current Payment Estimate.	ng Payment Payment
0540 - Total SEEDING - COOL SEASON MIXTURES Material 17 Dec 2, 17 SYSTEM \$1,445.10 This adjustment offsets the original system-generated Material Pay Estimate Exception 19 on the current Payment Estimate. 0550 SEEDING - COOL Material - Total Material 17 Dec 2, 2021 SYSTEM \$3,208.80 This adjustment offsets the original system-generated Material Pay Estimate Exception 19 on the current Payment Estimate.	
0540 - Total 2021 2021 \$0.00 0540 - Total SEEDING - COOL SEASON MIXTURES Material 17 Dec 2, 2021 SYSTEM \$3,208.80 This adjustment (009) due to user scarpm1 overridding Estimate Exception 19 on the current Payment Estimate.	
Osto SEEDING - COOL Material - Total 17 Dec 2, 2021 SYSTEM \$3,208.80 This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0009) due to user scarpm1 overridding Estimate Exception 5 on the current Payment Estimate.	
Material - Total \$0.00 0540 - Total \$0.00 0550 SEEDING - COOL SEASON MIXTURES Material Alterial 17 Dec 2, 2021 SYSTEM 2021 \$3,208.80 This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0009) due to user scarpm1 overridding Estimate Exception 5 on the current Payment Estimate.	
0540 - Total \$0.00 0550 SEEDING - COOL SEASON MIXTURES Material SEASON MIXTURES 17 Dec 2, 2021 SYSTEM 2021 \$3,208.80 This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0009) due to user scarpm1 overridding Estimate Exception 5 on the current Payment Estimate.	
0550 SEEDING - COOL SEASON MIXTURES Material SEASON MIXTURES 17 Dec 2, 2021 SYSTEM \$3,208.80 This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0009) due to user scarpm1 overridding Estimate Exception 5 on the current Payment Estimate. 17 Dec 2, 17 SYSTEM (\$3,208.80)	
SEASON MIXTURES 2021 Estimate Item Adjustment (0009) due to user scarpm1 overridding Estimate Exception 5 on the current Payment Estimate. 17 Dec 2, SYSTEM (\$3,208.80)	
18Dec 16, 2021SYSTEM\$3,208.80This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0003) due to user scarpm1 overridding Estimate Exception 2 on the current Payment Estimate.	
18 Dec 16, 2021 (\$3,208.80)	
19Jan 3, 2022SYSTEM\$3,208.80This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0003) due to user scarpm1 overridding Estimate Exception 1 on the current Payment Estimate.	
19 Jan 3, 2022 (\$3,208.80)	
- Total \$0.00	
Material - Total \$0.00	
0550 - Total \$0.00	
0560 ROCK DITCH CHECK Material 3 May 3, 2021 SYSTEM \$1,795.50 This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0016) due to user scarpm1 overridding Estimate Exception 20 on the current Payment Estimate.	
3 May 3, 2021 (\$1,795.50)	
4 May 17, 2021 SYSTEM SYSTEM \$1,795.50 This adjustment offsets the original system-generated Material Pay Estimate Item Adjustment (0002) due to user scarpm1 overridding Estimate Exception 14 on the current Payment Estimate.	
4 May 17, SYSTEM (\$1,795.50)	
2021	
- Total \$0.00	
- Total \$0.00 Material - Total \$0.00	
- Total \$0.00 Material - Total \$0.00 0560 - Total \$0.00	
Image: Note of the second s	ayment ig Payment
Image: Note of the second s	ayment ig Payment
Material - Total \$0.00 Material - Total \$0.00 0560 - Total \$0.00 0580 TEMPORARY SEEDING AND MULCHING Material Letter in the interval in the interval int	ng Payment Payment
Image: state of the state	ng Payment Payment



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4I3291	0580	TEMPORARY	Material						Estimate Exception 25 on the current Payment Estimate.												
		SEEDING AND MULCHING			13	Sep 30, 2021	SYSTEM	(\$31.50)													
					14	Oct 18, 2021	SYSTEM	\$31.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user scarpm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
					14	Oct 18, 2021	SYSTEM	(\$31.50)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	0580 -	Total						\$0.00													
	0590	SILT FENCE	Material		3	May 3, 2021	SYSTEM	\$960.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user scarpm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.												
					3	May 3, 2021	SYSTEM	(\$960.75)													
					4	May 17, 2021	SYSTEM	\$960.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user scarpm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.												
					4	May 17, 2021	SYSTEM	(\$960.75)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	0590 -	Total						\$0.00													
	0600	TYPE 2D EROSION CONTROL BLANKET	SION TROL		17	Dec 2, 2021	SYSTEM	\$5,203.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user scarpm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
										17	Dec 2, 2021	SYSTEM	(\$5,203.00)								
							18	Dec 16, 2021	SYSTEM	\$5,203.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
																18	Dec 16, 2021	SYSTEM	(\$5,203.00)		
																		19	Jan 3, 2022	SYSTEM	\$5,203.00
					19	Jan 3, 2022	SYSTEM	(\$5,203.00)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
			Other Item Adjustment	OVRN	17	Dec 2, 2021	scarpm1	(\$4,009.75)	Line item adjustment to withhold the amount over plan quantity. 1865 SQYD at \$2.15 per SQYD = (\$4,009.75)												
				OVRN - Tota	al			(\$4,009.75)													
			Other Item A	djustment - T	otal			(\$4,009.75)													
			Overrun	Overrun	17	Dec 2, 2021	SYSTEM	\$4,009.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 2420.000; Overrun Quantity Balance 1865.00.												
					17	Dec 2, 2021	SYSTEM	(\$4,009.75)													
					18	Dec 16, 2021	SYSTEM	(\$4,009.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
												18	Dec 16, 2021	SYSTEM	\$4,009.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 2420.000; Overrun Quantity Balance 1865.00.					
					19	Jan 3, 2022	SYSTEM	(\$4,009.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).												
																	19	Jan 3, 2022	SYSTEM	\$4,009.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 2420.000; Overrun Quantity Balance 1865.00.
				Overrun - T	otal			\$0.00													



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4I3291	0600	TYPE 2D EROSION CONTROL BLANKET	Overrun - To	tal				\$0.00		
	0600 -	Total						(\$4,009.75)		
	0610	MGS GUARDRAIL	Construction Stockpile		8	Jul 16, 2021	SYSTEM	(\$3,990.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					16	Nov 16, 2021	SYSTEM	(\$1,330.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$5,320.00)		
				Stockpile - 1				(\$5,320.00)		
			Construction Stockpile STMI	- Total	3	May 3, 2021	SYSTEM	\$5,320.00 \$5,320.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction	Stockpile S	TML - Total			\$5,320.00		
	0610 -	Total	Construction	l otoekpile o				\$0.00		
	0620	MGS GUARDRAIL, 8 FT. POSTS, 6 FT.	Construction Stockpile		8	Jul 16, 2021	SYSTEM	(\$5,782.50)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		- 3 IN			13	Sep 30, 2021	SYSTEM	(\$1,927.50)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$7,710.00)		
			Construction	Stockpile - 1	ſotal			(\$7,710.00)		
			Construction Stockpile STMI		3	May 3, 2021	SYSTEM	\$7,710.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$7,710.00		
			Construction	Stockpile S	TMI - Tota			\$7,710.00		
	0620 -							\$0.00		
	0630	MGS BRIDGE APP. TRANS SEC (EXT CURB)	APP. TRANS SEC S	Construction Stockpile		8	Jul 16, 2021 Sep 30,	SYSTEM	(\$3,520.00)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
					- Total	15	2021	STOTEM	(\$5,280.00)	rayment Estimate tem Aujustment generated Stockpile Hansaction
			Construction	Stockpile - 1	Fotal			(\$5,280.00)		
			Construction Stockpile		3	May 3, 2021	SYSTEM	\$5,280.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$5,280.00		
			Construction	Stockpile S	TMI - Tota			\$5,280.00		
	0630 -	Total						\$0.00		
	0640	MGS VERTICAL CONCRETE BARRIER			16	Nov 16, 2021	SYSTEM	(\$3,336.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		TRANSITION		- Total				(\$3,336.00)		
				Stockpile - 1				(\$3,336.00)		
			Construction Stockpile		3	May 3, 2021	SYSTEM	\$3,336.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$3,336.00		
			Construction	Stockpile S	TMI - Total			\$3,336.00		
	0640 -	Total						\$0.00		
	0650	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile		8	Jul 16, 2021	SYSTEM	(\$351.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
					13	Sep 30, 2021	SYSTEM	(\$351.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total	16	Nov 16, 2021	SYSTEM	(\$702.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction		[otal					
		((Construction Construction Stockpile	Stockpile - 1	3	May 3, 2021	SYSTEM	(\$1,404.00) \$1,404.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$1,404.00		
				Total				\$1,104.00		



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4I3291	0650	MGS HEIGHT AND BLOCK TRANSITION	Construction	Stockpile S	TMI - Total			\$1,404.00														
	0650 -	Total						\$0.00														
	0660	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		8	Jul 16, 2021	SYSTEM	(\$1,545.00)	Payment Estimate Item Adjustment generated Stockpile Transaction													
		(MASH)		- Total				(\$1,545.00)														
			Construction	Stockpile -	Total			(\$1,545.00)														
			Construction Stockpile STMI		3	May 3, 2021	SYSTEM	\$1,545.00	Payment Estimate Item Adjustment generated Stockpile Transaction													
				- Total				\$1,545.00														
			Construction	Stockpile S	TMI - Total			\$1,545.00														
	0660 -	Total						\$0.00														
	0680	BASE MOUNTED CONTROL STATION	Material		11	Sep 2, 2021	SYSTEM	\$1,924.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
					11	Sep 2, 2021	SYSTEM	(\$1,924.98)														
					12	Sep 16, 2021	SYSTEM	\$5,774.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user scarpm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.													
					12	Sep 16, 2021	SYSTEM	(\$5,774.92)														
																		13	Sep 30, 2021	SYSTEM	\$5,774.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
									13	Sep 30, 2021	SYSTEM	(\$5,774.92)										
														14	Oct 18, 2021	SYSTEM	\$5,774.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
											14	Oct 18, 2021	SYSTEM	(\$5,774.92)								
				- Total				\$0.00														
			Material - Tot	aterial - Total				\$0.00														
	0680 -	Total						\$0.00														
	0690	CONDUIT, 2 IN. RIGID, IN TRENCH	Material		11	Sep 2, 2021	SYSTEM	\$897.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user scarpm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.													
					11	Sep 2, 2021	SYSTEM	(\$897.00)														
					12	Sep 16, 2021	SYSTEM	\$897.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.													
												12	Sep 16, 2021	SYSTEM	(\$897.00)							
																	13	Sep 30, 2021	SYSTEM	\$897.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user scarpm1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
					13	13	Sep 30, 2021	SYSTEM	(\$897.00)													
								14	Oct 18, 2021	SYSTEM	\$897.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.										
					14	Oct 18, 2021	SYSTEM	(\$897.00)														
				- Total				\$0.00														
			Material - Tot	al				\$0.00														
	0690 -	Total						\$0.00														
	0700	CONDUIT, 3 IN. RIGID, IN TRENCH	Material		11	Sep 2, 2021	SYSTEM	\$3,919.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user scarpm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.													
					11	Sep 2,	SYSTEM	(\$3,919.25)	·													



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J4I3291	0700	CONDUIT, 3 IN.	Material	Type		2021										
0410201	0100	RIGID, IN TRENCH	Material		12	Sep 16, 2021	SYSTEM	\$3,919.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.							
					12	Sep 16, 2021	SYSTEM	(\$3,919.25)								
					13	Sep 30, 2021	SYSTEM	\$3,919.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 29 on the current Payment Estimate.							
					13	Sep 30, 2021	SYSTEM	(\$3,919.25)								
					14	Oct 18, 2021	SYSTEM	\$3,919.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.							
					14	Oct 18, 2021	SYSTEM	(\$3,919.25)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0700 -	Total						\$0.00								
	0720	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUC.	Material		14	Oct 18, 2021	SYSTEM	\$15,369.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user scarpm1 overridding Payment Estimate Exception 25 on the current Payment Estimate.							
					14	Oct 18, 2021	SYSTEM	(\$15,369.80)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0720 -	Total						\$0.00								
	0730	0 PULL BOX, PREFORMED CLASS 1	PREFORMED		12	Sep 16, 2021	SYSTEM	\$1,181.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user scarpm1 overridding Payment Estimate Exception 24 on the current Payment Estimate.							
														12	Sep 16, 2021	SYSTEM
					13	Sep 30, 2021	SYSTEM	\$1,181.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user scarpm1 overridding Payment Estimate Exception 30 on the current Payment Estimate.							
					13	Sep 30, 2021	SYSTEM	(\$1,181.40)								
					14	Oct 18, 2021	SYSTEM	\$1,181.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user scarpm1 overridding Payment Estimate Exception 26 on the current Payment Estimate.							
					14	Oct 18, 2021	SYSTEM	(\$1,181.40)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0730 -	Total						\$0.00								
	0740	CABLE, 4 AWG 1 CONDUCTOR	Material		14	Oct 18, 2021	SYSTEM	\$399.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user scarpm1 overridding Payment Estimate Exception 27 on the current Payment Estimate.							
					14	Oct 18, 2021	SYSTEM	(\$399.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0740 -	Total						\$0.00								
	0750	CABLE, 8 AWG 1 CONDUCTOR	Material		14	Oct 18, 2021	SYSTEM	\$1,486.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user scarpm1 overridding Payment Estimate Exception 28 on the current Payment Estimate.							
					14	Oct 18, 2021	SYSTEM	(\$1,486.25)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0750 -	Total						\$0.00								
	0760	WIRE, 4 AWG,	Material		14	Oct 18,	SYSTEM	\$203.00	This adjustment offsets the original system-generated Material Payment							



Jan 5, 2022

								• •	
t L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1 0	760	BARE NEUTRAL	Material			2021			Estimate Item Adjustment (0025) due to user scarpm1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$203.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
0	760 -	Total						\$0.00	
0)770	WIRE, 8 AWG, BARE NEUTRAL	Material		14	Oct 18, 2021	SYSTEM	\$1,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user scarpm1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$1,120.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
0)770 -	Total						\$0.00	
	0790	MISC. HIGHWAY LIGHTING	Material		14	Oct 18, 2021	SYSTEM	\$2,066.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user scarpm1 overridding Payment
					14	Oct 18, 2021	SYSTEM	(\$2,066.40)	Estimate Exception 31 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
			Waterial - TO	lai					
	790 -							\$0.00	
0	0080	MISC. HIGHWAY LIGHTING	Material		14	Oct 18, 2021	SYSTEM	\$427.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user scarpm1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					14	Oct 18, 2021	SYSTEM	(\$427.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
0	800 -	Total						\$0.00	
0	820	CONCRETE FOOTINGS, EMBEDDED	Material		16	Nov 16, 2021	SYSTEM	\$778.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					16	Nov 16, 2021	SYSTEM	(\$778.68)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
0	820 -	Total						\$0.00	
	840	BREAKAWAY ASSEMBLY (PERFORATED	Material		16	Nov 16, 2021	SYSTEM	\$940.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		SQUARE STEEL TUBE)			16	Nov 16, 2021	SYSTEM	(\$940.80)	
				- Total				\$0.00	
			Material - To					\$0.00	
)840 -	Total							
							a) (a==	\$0.00	
0	940	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		8	Jul 16, 2021	SYSTEM	\$65,415.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$65,415.60)	
					9	Aug 2, 2021	SYSTEM	\$65,415.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Aug 2, 2021	SYSTEM	(\$65,415.60)	
			- Total					\$0.00	
			Material - Total					\$0.00	
0	940 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3291	0990	CLASS B CONCRETE (SUBSTRUCTURE)	Material		4	May 17, 2021	SYSTEM	\$37,609.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 17, 2021	SYSTEM	(\$37,609.95)	
					5	Jun 1, 2021	SYSTEM	\$37,609.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jun 1, 2021	SYSTEM	(\$37,609.95)	
					6	Jun 16, 2021	SYSTEM	\$37,609.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$37,609.95)	
					7	Jul 1, 2021	SYSTEM	\$37,609.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wilsor2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 1, 2021	SYSTEM	(\$37,609.95)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0990 -	Total						\$0.00	
	1000	TYPE D BARRIER	Material		8	Jul 16, 2021	SYSTEM	\$20,736.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Jul 16, 2021	SYSTEM	(\$20,736.80)	
			- Total					\$0.00	
		Material - To	tal				\$0.00		
	1000 -	Total						\$0.00	
	1010) SLAB ON CONCRETE NU- GIRDER	Material		6	Jun 16, 2021	SYSTEM	\$79,240.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user scarpm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Jun 16, 2021	SYSTEM	(\$79,240.52)	
					7	Jul 1, 2021	SYSTEM	\$153,841.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7 7		SYSTEM SYSTEM	\$153,841.68 (\$153,841.68)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment
						2021 Jul 1,			Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment
					7	2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM	(\$153,841.68)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7 8	2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	(\$153,841.68) \$161,821.40	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7 8 8	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	(\$153,841.68) \$161,821.40 (\$161,821.40)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment
					7 8 8 9	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$153,841.68) \$161,821.40 (\$161,821.40) \$161,821.40	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment
					7 8 8 9 9	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$153,841.68) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
					7 8 8 9 9 10	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 2, 2021 Aug 2, 2021 Aug 15, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$153,841.68) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40) \$161,821.40	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.
					7 8 8 9 9 10 10	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$153,841.68) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7 8 8 9 9 10 10 10	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$153,841.68) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40) \$161,821.40	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7 8 8 9 10 10 11 11	2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$153,841.68) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40) \$161,821.40 (\$161,821.40) (\$161,821.40)	Estimate Item Adjustment (0004) due to user wilsor2 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
291 1	1010	SLAB ON CONCRETE NU- GIRDER	Material		13	Sep 30, 2021	SYSTEM	\$161,821.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					13	Sep 30, 2021	SYSTEM	(\$161,821.40)							
					14	Oct 18, 2021	SYSTEM	\$161,821.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user scarpm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.						
					14	Oct 18, 2021	SYSTEM	(\$161,821.40)							
					15	Nov 1, 2021	SYSTEM	\$161,821.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					15	Nov 1, 2021	SYSTEM	(\$161,821.40)							
					16	Nov 16, 2021	SYSTEM	\$161,821.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					16	Nov 16, 2021	SYSTEM	(\$161,821.40)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							
1	1010 -	Total						\$0.00							
1	1020	NU 35, PRESTRESSED CONC NU-GIRDER	Material		6	Jun 16, 2021	SYSTEM	\$112,290.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
					6	Jun 16, 2021	SYSTEM	(\$112,290.60)							
					7	Jul 1, 2021	SYSTEM	\$112,290.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wilsor2 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
													7	Jul 1, 2021	SYSTEM
					8	Jul 16, 2021	SYSTEM	\$112,290.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user scarpm1 overridding Payment						
									Estimate Exception 9 on the current Payment Estimate.						
					8	Jul 16, 2021	SYSTEM	(\$112,290.60)	Estimate Exception 9 on the current Payment Estimate.						
					8 9		SYSTEM	(\$112,290.60) \$112,290.60	Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
						2021 Aug 2,			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment						
					9	2021 Aug 2, 2021 Aug 2,	SYSTEM	\$112,290.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment						
					9	2021 Aug 2, 2021 Aug 2, 2021 Aug 15,	SYSTEM	\$112,290.60 (\$112,290.60)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					9 9 10	2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15,	SYSTEM SYSTEM SYSTEM	\$112,290.60 (\$112,290.60) \$112,290.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					9 9 10 10	2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM	\$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
				- Total	9 9 10 10 11	2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) (\$112,290.60) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
			Material - To		9 9 10 10 11	2021 Aug 2, 2021 Aug 2, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) (\$112,290.60) \$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
		Total			9 9 10 11 11	2021 Aug 2, 2021 Aug 12, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$112,290.60 (\$112,290.60) (\$112,290.60) (\$112,290.60) (\$112,290.60) (\$112,290.60) (\$112,290.60) (\$10,000 (\$0.00 (\$0.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.						
		Total PLAIN NEOPRENE BEARING PAD	Material - To Material		9 9 10 10 11 11 5	2021 Aug 2, 2021 Aug 12, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2, 2021 Jun 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) (\$112,290.60) \$112,290.60 \$112,290.60 (\$112,290.60) \$112,290.60 (\$12,290.60) \$112,290.60 (\$12,290.60) \$112,290.60 (\$12,290.60) \$112,290.60 (\$12,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$10,000 \$0.000 \$10,000 \$1,936.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
		PLAIN NEOPRENE			9 9 10 11 11	2021 Aug 2, 2021 Aug 12, 2021 Aug 15, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2, 2021 Jun 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$112,290.60 (\$112,290.60) (\$112,290.60) (\$112,290.60) (\$112,290.60) (\$112,290.60) (\$112,290.60) (\$10,000 (\$0.00 (\$0.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate.						
		PLAIN NEOPRENE			9 9 10 10 11 11 5	2021 Aug 2, 2021 Aug 12, 2021 Aug 15, 2021 Sep 2, 2021 Sep 2, 2021 Jun 1, Jun 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) (\$112,290.60) \$112,290.60 \$112,290.60 (\$112,290.60) \$112,290.60 (\$12,290.60) \$112,290.60 (\$12,290.60) \$112,290.60 (\$12,290.60) \$112,290.60 (\$12,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$112,290.60 (\$112,290.60) \$10,000 \$0.000 \$10,000 \$1,936.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate.						



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
	Lino	Decemption	Туре	Adjustment Type	Number	Date	Ву	, ano ant		
J4I3291	1040	PLAIN NEOPRENE BEARING PAD	Material		7	Jul 1, 2021	SYSTEM	\$1,936.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wilsor2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					7	Jul 1, 2021	SYSTEM	(\$1,936.80)		
					8	Jul 16, 2021	SYSTEM	\$1,936.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user scarpm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					8	Jul 16, 2021	SYSTEM	(\$1,936.80)		
					9	Aug 2, 2021	SYSTEM	\$1,936.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					9	Aug 2, 2021	SYSTEM	(\$1,936.80)		
					10	Aug 15, 2021	SYSTEM	\$1,936.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user scarpm1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					10	Aug 15, 2021	SYSTEM	(\$1,936.80)		
					11	Sep 2, 2021	SYSTEM	\$1,936.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user scarpm1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					11	Sep 2, 2021	SYSTEM	(\$1,936.80)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1040 -	Total						\$0.00		
	1090) BRIDGE APPROACH SLAB (MAJOR ROAD)	Material	Material		12	Sep 16, 2021	SYSTEM	\$35,595.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Sep 16, 2021	SYSTEM	(\$35,595.00)		
					13	Sep 30, 2021	SYSTEM	\$71,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					13	Sep 30, 2021	SYSTEM	(\$71,190.00)		
					14	Oct 18, 2021	SYSTEM	\$71,190.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user scarpm1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					14	Oct 18, 2021	SYSTEM	(\$71,190.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1090 -							\$0.00		
	1100	GALVANIZED STRUCTURAL STEEL PILES (12 IN	Material		10	Aug 15, 2021	SYSTEM	\$38,387.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user scarpm1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
		IIN			10	Aug 15, 2021	SYSTEM	(\$38,387.40)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1100 -							\$0.00		
	1130	PILE POINT REINFORCEMENT	Material		10	Aug 15, 2021	SYSTEM	\$1,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user scarpm1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					10	Aug 15, 2021	SYSTEM	(\$1,918.00)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1130 -							\$0.00		
	1150	TYPE D BARRIER	Material		13	Sep 30,	SYSTEM	\$10,074.40	This adjustment offsets the original system-generated Material Payment	



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
413291	1150	TYPE D BARRIER	Material			2021			Estimate Item Adjustment (0033) due to user scarpm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
					13	Sep 30, 2021	SYSTEM	(\$10,074.40)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1150 -	Total						\$0.00													
	1160	SLAB ON CONCRETE NU- GIRDER	Material		11	Sep 2, 2021	SYSTEM	\$90,506.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
					11	Sep 2, 2021	SYSTEM	(\$90,506.00)													
					12	Sep 16, 2021	SYSTEM	\$165,347.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user scarpm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
					12	Sep 16, 2021	SYSTEM	(\$165,347.50)													
					13	Sep 30, 2021	SYSTEM	\$173,701.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user scarpm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.												
					13	Sep 30, 2021	SYSTEM	(\$173,701.90)													
						14	Oct 18, 2021	SYSTEM	\$173,701.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user scarpm1 overridding Payment Estimate Exception 13 on the current Payment Estimate.											
																	14	Oct 18, 2021	SYSTEM	(\$173,701.90)	
															15	Nov 1, 2021	SYSTEM	\$173,701.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					15	Nov 1, 2021	SYSTEM	(\$173,701.90)													
									16	Nov 16, 2021	SYSTEM	\$173,701.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.								
					16	Nov 16, 2021	SYSTEM	(\$173,701.90)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1160 -	Total						\$0.00													
	1170	NU 35, PRESTRESSED CONC NU-GIRDER	Material		11	Sep 2, 2021	SYSTEM	\$131,986.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user scarpm1 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
					11	Sep 2, 2021	SYSTEM	(\$131,986.40)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1170 -							\$0.00													
	1190	PLAIN NEOPRENE BEARING PAD	Material		11	Sep 2, 2021	SYSTEM	\$2,093.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user scarpm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
					11	Sep 2, 2021	SYSTEM	(\$2,093.00)													
				- Total				\$0.00													
			Material - To	tal				\$0.00													
	1190 -							\$0.00													
	1210	CONCRETE AND MASONRY PROTECTION SYSTEM	Material		13	Sep 30, 2021	SYSTEM	\$3,282.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user scarpm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.												
		GTGTEIM			13	Sep 30, 2021	SYSTEM	(\$3,282.85)													
					14	Oct 18, 2021	SYSTEM	\$3,282.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user scarpm1 overridding Payment												



Jan 5, 2022

J4I3291			Туре	Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																				
	1210	CONCRETE AND	Material	Туре					Estimate Exception 15 on the current Payment Estimate.																				
		MASONRY PROTECTION			14	Oct 18, 2021	SYSTEM	(\$3,282.85)																					
		SYSTEM		- Total		2021		\$0.00																					
			Material - To	tal				\$0.00																					
	1210 -	Total						\$0.00																					
	1220	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	Material		13	Sep 30, 2021	SYSTEM	\$3,865.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user scarpm1 overridding Payment Estimate Exception 22 on the current Payment Estimate.																				
		STSTEM			13	Sep 30, 2021	SYSTEM	(\$3,865.95)																					
					14	Oct 18, 2021	SYSTEM	\$3,865.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user scarpm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.																				
					14	Oct 18, 2021	SYSTEM	(\$3,865.95)																					
				- Total				\$0.00																					
			Material - To	tal				\$0.00																					
	1220 -	Total						\$0.00																					
	1230	MECHANICALLY STABILIZED EARTH WALL SYS	Material		3	May 3, 2021	SYSTEM	\$84,847.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user scarpm1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																				
					3	May 3, 2021	SYSTEM	(\$84,847.50)																					
																			4	May 17, 2021	SYSTEM	\$108,270.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
															4	May 17, 2021	SYSTEM	(\$108,270.00)											
																		5	Jun 1, 2021	SYSTEM	\$109,485.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
					5	Jun 1, 2021	SYSTEM	(\$109,485.00)																					
					6	Jun 16, 2021	SYSTEM	\$109,485.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user scarpm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																				
					6	Jun 16, 2021	SYSTEM	(\$109,485.00)																					
					7	Jul 1, 2021	SYSTEM	\$109,485.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wilsor2 overridding Payment Estimate Exception 15 on the current Payment Estimate.																				
																									7	Jul 1, 2021	SYSTEM	(\$109,485.00)	
									8	Jul 16, 2021	SYSTEM	\$109,485.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																
						5	s 1 1 1	9 9 1 1 1 1	10					5		2						8	Jul 16, 2021	SYSTEM	(\$109,485.00)				
																				S	9	Aug 2, 2021	SYSTEM	\$109,485.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
																	9	Aug 2, 2021	SYSTEM	(\$109,485.00)									
																				10	Aug 15, 2021	SYSTEM	\$220,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user scarpm1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
												1		10	Aug 15, 2021	SYSTEM	(\$220,995.00)												
																		11	11	Sep 2, 2021	SYSTEM	\$225,585.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user scarpm1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
														11	Sep 2, 2021	SYSTEM	(\$225,585.00)												
				- Total				\$0.00																					



Jan 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J4I3291	1230	MECHANICALLY STABILIZED EARTH WALL SYS	Material - To	tal				\$0.00															
	1230 -	Total						\$0.00															
	1240	CONCRETE AND MASONRY PROTECTION	Material		13	Sep 30, 2021	SYSTEM	\$3,320.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user scarpm1 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
		SYSTEM			13	Sep 30, 2021	SYSTEM	(\$3,320.95)															
					14	Oct 18, 2021	SYSTEM	\$3,320.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user scarpm1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					14	Oct 18, 2021	SYSTEM	(\$3,320.95)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	1240 -	Total						\$0.00															
	1250	SACRIFICIAL GRAFFITI PROTECTION	Material		13	Sep 30, 2021	SYSTEM	\$3,910.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user scarpm1 overridding Payment Estimate Exception 23 on the current Payment Estimate.														
		SYSTEM			13	Sep 30, 2021	SYSTEM	(\$3,910.80)															
						14	Oct 18, 2021	SYSTEM	\$3,910.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user scarpm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.													
					14	Oct 18, 2021	SYSTEM	(\$3,910.80)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	1250 -	Total						\$0.00															
	1260	MECHANICALLY STABILIZED EARTH WALL SYS	Material		3	May 3, 2021	SYSTEM	\$83,566.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 11 on the current Payment Estimate.														
																		3	May 3, 2021	SYSTEM	(\$83,566.80)		
																4	May 17, 2021	SYSTEM	\$102,270.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user scarpm1 overridding Payment Estimate Exception 10 on the current Payment Estimate.			
					4	May 17, 2021	SYSTEM	(\$102,270.80)															
									5	Jun 1, 2021	SYSTEM	\$103,473.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user scarpm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
					5	Jun 1, 2021	SYSTEM	(\$103,473.20)															
					6 7														6	Jun 16, 2021	SYSTEM	\$103,473.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user scarpm1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
												6	Jun 16, 2021	SYSTEM	(\$103,473.20)								
														7	Jul 1, 2021	SYSTEM	\$103,473.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wilsor2 overridding Payment Estimate Exception 19 on the current Payment Estimate.					
				7	7	Jul 1, 2021	SYSTEM	(\$103,473.20)															
					8	Jul 16, 2021	SYSTEM	\$103,473.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user scarpm1 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
					8	Jul 16, 2021	SYSTEM	(\$103,473.20)															
					5	9	Aug 2, 2021	SYSTEM	\$134,201.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user scarpm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
					9	Aug 2,	SYSTEM	(\$134,201.20)															
								2021															



Dustant	1 in a	Description	A	Others	E.t.	Onested	One stad	A	Demonto
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3291	1260	MECHANICALLY STABILIZED EARTH WALL SYS	Material		10	Aug 15, 2021	SYSTEM	\$220,506.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user scarpm1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Aug 15, 2021	SYSTEM	(\$220,506.80)	
					11	Sep 2, 2021	SYSTEM	\$227,186.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user scarpm1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					11	Sep 2, 2021	SYSTEM	(\$227,186.80)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1260 - Total							\$0.00	
J4I3291 -	Total	tal						\$535.83	
J4I3297	1910	MGS GUARDRAIL	Construction Stockpile STMI		3	May 3, 2021	SYSTEM	\$3,325.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,325.00	
			Construction Stockpile STMI - Total					\$3,325.00	
	1910 -	1910 - Total						\$3,325.00	
	1920	MGS BRIDGE APP. TRANS SEC (EXT CURB)	Construction Stockpile STMI		3	May 3, 2021	SYSTEM	\$1,760.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,760.00	
			Construction Stockpile STMI - Total					\$1,760.00	
	1920 - Total							\$1,760.00	
	1930	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		3	May 3, 2021	SYSTEM	\$1,668.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,668.00	
			Construction Stockpile STMI - Total					\$1,668.00	
	1930 - Total							\$1,668.00	
	1940	MGS HEIGHT AND BLOCK TRANSITION	Construction Stockpile STMI		3	May 3, 2021	SYSTEM	\$702.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$702.00	
			Construction Stockpile STMI - Total					\$702.00	
	1940 - Total							\$702.00	
J4I3297 -	Total							\$7,455.00	
Overall -	Total							\$7,990.83	