

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number	Contract ID	210122-C07		Original Contract Amount \$1,028	,
6	Prime Contracto	<b>r</b> Lehman Construction, LLC	Pay Period End November 15, 202	1 Net Change Order Amount \$0.00	
•				Current Contract Amount \$1,028	3,179.00

Approval Date					By User				
November 17, 2021		Generated and A	Approved (and should be considered	d Draft) at the Project Office Level by	vohsr1				
November 17, 2021		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by							
November 17, 2021		Reviewed and Approved at the Central Office Controllers Office Level by							
Original Completion Date		Current Completion Date	Actual Completion Date	ion Date % of Current Contract Amount Co					

Original Completion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021		65.36%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	February 3, 2021	February 3, 2021	
Letting Date	January 22, 2021	January 22, 2021	
Notice to Proceed Date	March 1, 2021	March 1, 2021	
Work Began Date			

\$152,549.00

Contract Total Pa	ay For Estimate No. 6			
		This Estimate	Previous	To Date
210122-C07				
	Total Posted Items Pay	\$152,549.00	\$519,494.83	\$672,043.83
	Gross Item Adjustments	\$0.00	\$0.00	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	,		\$519,494.83	\$672,043.83

### Items Paid This Estimate Period

Contract Total Payable This Estimate:

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J4S3375	0030	2031000	CLASS A EXCAVATION	CUYD	\$8.000	458	\$3,664.00			
	0040	2035500	EMBANKMENT IN PLACE	CUYD	\$20.000	252	\$5,040.00			
	0050	2036000	COMPACTING EMBANKMENT	CUYD	\$6.000	35	\$210.00			
	0320	8061005	ROCK DITCH CHECK	LF	\$20.000	8	\$160.00			
	0630	7034222	SLAB ON CONCRETE BEAM	SQYD	\$275.000	513	\$141,075.00			
	0670	7151001	VERTICAL DRAIN AT END BENTS	EA	\$1,200.000	2	\$2,400.00			
Project J4S3375	roject J4S3375 - Total									
Overall - Total	verall - Total									

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjustr	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3375	0040	EMBANKMENT IN PLACE	Material			-252	\$20.00	(\$5,040.00)
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	252	\$20.00	\$5,040.00
	0050	COMPACTING EMBANKMENT	Material			-35	\$6.00	(\$210.00)

Revision 4/1/2020 Page 1 of 15



Pay Estimate Created Date: November 16, 2021

Progress Estimate Number
6
Contract ID 210122-C07 Pay Period Start November 2, 2021 Original Contract Amount \$1,028,179.00
Prime Contractor Lehman Construction, LLC Pay Period End November 15, 2021 Original Contract Amount \$0.00
Current Contract Amount \$1,028,179.00

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3375	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	35	\$6.00	\$210.00
	0250	SEPARATION GEOTEXTILE	Material			-665	\$5.00	(\$3,325.00
	0250	SEPARATION GEOTEXTILE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	665	\$5.00	\$3,325.00
	0280	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material			-2	\$750.00	(\$1,500.00)
	0280	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	2	\$750.00	\$1,500.00
	0560	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-181	\$85.00	(\$15,385.00)
C	0560	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	181	\$85.00	\$15,385.00
	0570	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material			-295	\$95.00	(\$28,025.00
	0570	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	295	\$95.00	\$28,025.00
	0590	PRE-BORE FOR PILING	Material			-313	\$190.00	(\$59,470.00
	0590	PRE-BORE FOR PILING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	313	\$190.00	\$59,470.00
	0600	PILE POINT REINFORCEMENT	Material			-23	\$180.00	(\$4,140.00
	0600	PILE POINT REINFORCEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	23	\$180.00	\$4,140.00
	0610	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-112.7	\$275.00	(\$30,992.50)
(	0610	CLASS B CONCRETE (SUBSTRUCTURE)  Material  This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		112.7	\$275.00	\$30,992.50		
	0630	SLAB ON CONCRETE BEAM	Material			-513	\$275.00	(\$141,075.00
	0630	SLAB ON CONCRETE BEAM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	513	\$275.00	\$141,075.00

Revision 4/1/2020 Page 2 of 15



### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number
6
Contract ID 210122-C07 Pay Period Start November 2, 2021 Original Contract Amount \$1,028,179.00
Prime Contractor Lehman Construction, LLC Pay Period End November 15, 2021 Net Change Order Amount \$0.00
Current Contract Amount \$1,028,179.00

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3375	0640	MISC.	Material			-439	\$350.00	(\$153,650.00)
	0640	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	439	\$350.00	\$153,650.00
	0660	SLAB DRAIN	Material			-20	\$525.00	(\$10,500.00)
	0660	SLAB DRAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	20	\$525.00	\$10,500.00
	0670	VERTICAL DRAIN AT END BENTS	Material			-2	\$1,200.00	(\$2,400.00)
	0670	VERTICAL DRAIN AT END BENTS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	2	\$1,200.00	\$2,400.00
Total								\$0.00

Revision 4/1/2020 Page 3 of 15



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work					
J4S3375	FAS S302(99)	Bridge replacement	PECULIAR DR	CASS	over East Creek, 1 mile south of Main Street and 0.2 mile north of 195th Street						
Totals by J	lob Numbe	rs									
J4S3375					This Estimate	Previous	To Date				
	Poste	d Item Pay			\$152,549.00	\$519,494.83	\$672,043.83				
	Gross	Item Adjustm	ents		\$0.00	\$0.00	\$0.00				
			Gross Iten	n Pay	\$152,549.00	\$519,494.83	\$672,043.83				
	Incent	tive			\$0.00	\$0.00	\$0.00				
	Disino	entive			\$0.00	\$0.00	\$0.00				
	Liquid	lated Damages	5		\$0.00	\$0.00	\$0.00				
		Contract Adju			\$0.00	\$0.00	\$0.00				

Revision 4/1/2020 Page 4 of 15



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 6240104A, Project Item Line Number 0250, Material Set 6240104A96, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7021212, Project Item Line Number 0560, Material Set 702121296, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7021214, Project Item Line Number 0570, Material Set 702121496, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7026000, Project Item Line Number 0590, Material Set 7026000, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7027000, Project Item Line Number 0600, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7032003, Project Item Line Number 0610, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7034222, Project Item Line Number 0630, Material Set 703422296, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7034222, Project Item Line Number 0630, Material Set 703422296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7034222, Project Item Line Number 0630, Material Set 703422296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7034222, Project Item Line Number 0630, Material Set 703422296, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7034222, Project Item Line Number 0630, Material Set 703422296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7059903, Project Item Line Number 0640, Material Set 705990396, Material 0705INCRCPSXX - Girder Nebraska Dsn Various Leng, Acceptance Action Generic 0705INCRCPSXX is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7123610, Project Item Line Number 0660, Material Set 712361096, Material 0712STDRSB - Slab Drain, Acceptance Action Generic 0712STDRSB is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7151001, Project Item Line Number 0670, Material Set 715100196, Material 0715DRVT - Vertical Drain at End Bents, Acceptance Action Generic 0715DRVT is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3375, Item 7320030A, Project Item Line Number 0280, Material Set 7320030A96, Material 1020ESAC - Flared End Section Aluminum coated steel, Acceptance Action Generic 1020ESAC is insufficient.	Working with Materials to resolve exception.	vohsr1	Overridden

Revision 4/1/2020 Page 5 of 15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10122-C07	J4S3375	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE		\$10,000.00	\$10,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$18,000.00	\$18,000.00
		0001	0030	2031000	CLASS A EXCAVATION	458.00	0.00	458.00	CUYD	458.00	\$8.00	\$3,664.00
		0001	0040	2035500	EMBANKMENT IN PLACE	1,014.00	0.00	1,014.00	CUYD	252.00	\$20.00	\$5,040.00
		0001	0050	2036000	COMPACTING EMBANKMENT	366.00	0.00	366.00	CUYD	35.00	\$6.00	\$210.00
		0001	0060	2063000	CLASS 3 EXCAVATION	147.00	0.00	147.00	CUYD	147.00	\$53.00	\$7,791.00
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	3,363.00	0.00	3,363.00	SQYD	0.00	\$11.00	\$0.00
		0001	0800	4039905	MISC.OPTIONAL PAVEMENT	2,647.60	0.00	2,647.60	SQYD	0.00	\$65.00	\$0.00
		0001	0090	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	18.00	0.00	18.00	CUYD	11.00	\$50.00	\$550.00
		0001	0100	6096042	PLACING TYPE 2 ROCK DITCH LINER	18.00	0.00	18.00	CUYD	11.00	\$30.00	\$330.00
		0001	0110	6113020	FURNISHING TYPE 2 ROCK BLANKET	506.00	0.00	506.00	CUYD	506.00	\$45.00	\$22,770.00
		0001	0120	6113040	PLACING TYPE 2 ROCK BLANKET	506.00	0.00	506.00	CUYD	506.00	\$15.00	\$7,590.00
		0001	0130	6161005	CONSTRUCTION SIGNS	391.00	0.00	391.00	SQFT	391.00	\$6.00	\$2,346.00
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	3.00	\$36.00	\$108.00
		0001	0150	6161009	FLAG ASSEMBLY	3.00	0.00	3.00	EA	0.00	\$55.00	\$0.00
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	20.00	0.00	20.00	EA	20.00	\$16.00	\$320.00
		0001	0170	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	18.00	0.00	18.00	EA	18.00	\$115.00	\$2,070.00
		0001	0180	6161052	WARNING LIGHT, TYPE B	36.00	0.00	36.00	EA	36.00	\$40.00	\$1,440.00
		0001	0190	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.00
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$37,373.33	\$37,373.3
		0001	0210	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.0
		0001	0220	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	34.00	0.00	34.00	LF	0.00	\$27.00	\$0.00
		0001	0230	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,827.00	0.00	1,827.00	LF	0.00	\$0.15	\$0.0
		0001	0240	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,907.00	0.00	1,907.00	LF	0.00	\$0.16	\$0.0
		0001	0250	6240104A	SEPARATION GEOTEXTILE	665.00	0.00	665.00	SQYD	665.00	\$5.00	\$3,325.0
		0001	0260	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$7,100.00	\$7,100.0
		0001	0270	7250330A	30 IN. PIPE GROUP B	86.00	0.00	86.00	LF	86.00	\$110.00	\$9,460.0
		0001	0280	7320030A	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$750.00	\$1,500.00
		0001	0290	8051000A	SEEDING - COOL SEASON MIXTURES	0.60	0.00	0.60	ACRE	0.00	\$7,700.00	\$0.0
		0001	0300	8061003	SEDIMENT TRAP EXCAVATION	20.00	0.00	20.00	CUYD	0.00	\$45.00	\$0.0
		0001	0310	8061004	SEDIMENT TRAP ROCK	20.00	0.00	20.00	CUYD	0.00	\$55.00	\$0.0
		0001	0320	8061005	ROCK DITCH CHECK	64.00	0.00	64.00	LF	8.00	\$20.00	\$160.00
		0001	0330	8061016	SEDIMENT REMOVAL	20.00	0.00	20.00	CUYD	0.00	\$4.00	\$0.00
		0001	0340	8061017	TEMPORARY SEEDING AND MULCHING	0.10	0.00	0.10	ACRE	0.00	\$39,000.00	\$0.00
		0001	0350	8061019	SILT FENCE	524.00	0.00	524.00	LF	524.00	\$3.50	\$1,834.0
		0001	0360	8061050	TYPE C BERM	276.00	0.00	276.00	LF	276.00	\$45.00	\$12,420.0
		0001	0370	8064130	TYPE 3 TURF REINFORCEMENT MAT	185.00	0.00	185.00	SQYD	0.00	\$7.00	\$0.0
		0001	0380	8064140	TYPE 3B EROSION CONTROL BLANKET	2,482.00	0.00	2,482.00	SQYD	0.00	\$2.50	\$0.00
		0001	0390	2153000	SHAPING SLOPES. CLASS III	4.00	0.00	4.00	100F	0.00	\$2,250.00	\$0.00
		0010	0400	6061010	GUARDRAIL TYPE A	125.00	0.00	125.00	LF	0.00	\$24.00	\$0.0
		0010	0410	6061060	MGS GUARDRAIL	225.00	0.00	225.00	LF	0.00	\$25.00	\$0.0
		0010	0420	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	325.00	0.00	325.00	LF	0.00	\$27.00	\$0.0
		0010	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION	3.00	0.00	3.00	EA	0.00	\$3,200.00	\$0.00
		0010			(REGULAR/NO CURB)							
		0010	0440	6061074	MGS HEIGHT AND BLOCK TRANSITION	1.00	0.00	1.00	EA	0.00	\$720.00	\$0.00

Revision 4/1/2020 Page 6 of 15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0122-C07	J4S3375	0010	0450	6062204A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (NEW CONSTRUCTION ONLY)	1.00	0.00	1.00	EA	0.00	\$2,300.00	\$0.00
		0010	0460	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$450.00	\$0.00
		0010	0470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,900.00	\$0.00
		0040	0480	9031010	CONCRETE FOOTINGS, EMBEDDED	0.30	0.00	0.30	CUYD	0.00	\$2,400.00	\$0.00
		0040	0490	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	3.00	0.00	3.00	EA	0.00	\$330.00	\$0.00
		0040	0500	9031280	2.5 IN. PSST POST - 12 GA.	36.00	0.00	36.00	LF	0.00	\$20.00	\$0.00
		0040	0510	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	9.00	0.00	9.00	LF	0.00	\$60.00	\$0.00
		0040	0520	9035004A	SH-FLAT SHEET	17.00	0.00	17.00	SQFT	0.00	\$30.00	\$0.00
		0070	0530	2061000	CLASS 1 EXCAVATION	90.00	0.00	90.00	CUYD	90.00	\$18.00	\$1,620.00
		0070	0540	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$33,000.00	\$33,000.00
		0070	0550	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	102.00	0.00	102.00	SQYD	0.00	\$190.00	\$0.00
		0070	0560	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	181.00	0.00	181.00	LF	181.00	\$85.00	\$15,385.00
		0070	0570	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	357.00	0.00	357.00	LF	295.00	\$95.00	\$28,025.00
		0070	0580	7025002	PILE WAVE ANALYSIS	2.00	0.00	2.00	EA	2.00	\$950.00	\$1,900.00
		0070	0590	7026000	PRE-BORE FOR PILING	313.00	0.00	313.00	LF	313.00	\$190.00	\$59,470.00
		0070	0600	7027000	PILE POINT REINFORCEMENT	23.00	0.00	23.00	EA	23.00	\$180.00	\$4,140.00
		0070	0610	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	112.70	0.00	112.70	CUYD	112.70	\$275.00	\$30,992.50
		0070	0620	7034216	TYPE H BARRIER	327.00	0.00	327.00	LF	0.00	\$80.00	\$0.00
		0070	0630	7034222	SLAB ON CONCRETE BEAM	513.00	0.00	513.00	SQYD	513.00	\$275.00	\$141,075.00
		0070	0640	7059903	MISC.24 IN., PRESTRESSED CONCRETE BOX BEAM	439.00	0.00	439.00	LF	439.00	\$350.00	\$153,650.00
		0070	0650	7061060	REINFORCING STEEL (BRIDGES)	8,010.00	0.00	8,010.00	LB	8,010.00	\$1.50	\$12,015.00
		0070	0660	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	20.00	\$525.00	\$10,500.00
		0070	0670	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,200.00	\$2,400.00
		0070	0680	7161000	PLAIN NEOPRENE BEARING PAD	6.00	0.00	6.00	EA	6.00	\$475.00	\$2,850.00
		0070	0690	7161002	LAMINATED NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	12.00	\$635.00	\$7,620.00
	Project J	4S3375 - To	otal Value	Posted to D	ate as of Report Generated Date							\$672,043.83
0122-C07 Ove	erall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$672,043.83

Revision 4/1/2020 Page 7 of 15



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3375

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2031000	CLASS A EXCAVATION	11/10/21	11/16/21	133.00	CUYD	North end of bridge	243+25.00		247+34.75		
			11/15/21	11/16/21	123.00	CUYD	195th St.	21+04.55		22+16.25		
				11/16/21	202.00	CUYD	Peculiar Dr. South End	248+86.37		251+75.00		
0040	2035500	EMBANKMENT IN PLACE	11/15/21	11/16/21	252.00	CUYD	North of Bridge	243+25.00		247+35.33		
0050	2036000	COMPACTING EMBANKMENT	11/15/21	11/16/21	35.00	CUYD	North of Bridge	243+25.00		247+34.75		
0320	8061005	ROCK DITCH CHECK	11/15/21	11/16/21	8.00	LF	North of Bridge right side	247+00.00		247+00.00		
0630	7034222	SLAB ON CONCRETE BEAM	11/11/21	11/16/21	513.00	SQYD		247+35.33		248+85.79		
0670	7151001	VERTICAL DRAIN AT END BENTS	11/15/21	11/16/21	2.00	EA	North end and south end of bridge	247+35.33		248+85.79		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 8 of 15



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J4S3375	0040	EMBANKMENT IN PLACE	Material		6	Nov 16, 2021	SYSTEM	\$5,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					6	Nov 16, 2021	SYSTEM	(\$5,040.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0040 -	· Total						\$0.00									
	0050	COMPACTING EMBANKMENT	Material		6	Nov 16, 2021	SYSTEM	\$210.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					6	Nov 16, 2021	SYSTEM	(\$210.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0050 -	· Total						\$0.00									
	0090	FURN. TYPE 2 ROCK DITCH LINER	Material		4	Oct 18, 2021	SYSTEM	\$550.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					4	Oct 18, 2021	SYSTEM	(\$550.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0090 -	· Total						\$0.00									
	0130	CONSTRUCTION SIGNS	Material		1	Sep 3, 2021	SYSTEM	\$2,091.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					1	Sep 3, 2021	SYSTEM	(\$2,091.00)									
					2	Sep 16, 2021	SYSTEM	\$2,091.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
									2	Sep 16, 2021	SYSTEM	(\$2,091.00)					
															3	Oct 1, 2021	SYSTEM
							3	Oct 1, 2021	SYSTEM	(\$2,346.00)							
					4	Oct 18, 2021	SYSTEM	\$2,346.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					4	Oct 18, 2021	SYSTEM	(\$2,346.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0130 -	· Total						\$0.00									
	0140	ADVANCED WARNING RAIL SYSTEM	Material		1	Sep 3, 2021	SYSTEM	\$108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					1	Sep 3, 2021	SYSTEM	(\$108.00)									
					2	Sep 16, 2021	SYSTEM	\$108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					2	Sep 16, 2021	SYSTEM	(\$108.00)									
					3	Oct 1, 2021	SYSTEM	\$108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					3	Oct 1, 2021	SYSTEM	(\$108.00)									
					4	Oct 18,	SYSTEM	\$108.00	This adjustment offsets the original system-generated Material Payment								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4S3375	0140	ADVANCED WARNING RAIL SYSTEM	Material			2021			Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
		OTOTEM			4	Oct 18, 2021	SYSTEM	(\$108.00)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0140 -	Total						\$0.00														
	0160	CHANNELIZER (TRIM LINE)	Material		3	Oct 1, 2021	SYSTEM	\$320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
					3	Oct 1, 2021	SYSTEM	(\$320.00)														
					4	Oct 18, 2021	SYSTEM	\$320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					4	Oct 18, 2021	SYSTEM	(\$320.00)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0160 -	Total						\$0.00														
	0170	TYPE III MOVEABLE BARRICADE WITH	Material		1	Sep 3, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
		LIGHTS	3			1	Sep 3, 2021	SYSTEM	(\$2,070.00)													
					2	Sep 16, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
																		2	Sep 16, 2021	SYSTEM	(\$2,070.00)	
					3	Oct 1, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					3	Oct 1, 2021	SYSTEM	(\$2,070.00)														
					4	Oct 18, 2021	SYSTEM	\$2,070.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
					4	Oct 18, 2021	SYSTEM	(\$2,070.00)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0170 -	Total						\$0.00														
	0180	WARNING LIGHT, TYPE B	Material		1	Sep 3, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
							1	Sep 3, 2021	SYSTEM	(\$1,440.00)												
					2	Sep 16, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					2	Sep 16, 2021	SYSTEM	(\$1,440.00)														
					3	Oct 1, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.													
					3	Oct 1, 2021	SYSTEM	(\$1,440.00)														
					4	Oct 18, 2021	SYSTEM	\$1,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.													
					4	Oct 18, 2021	SYSTEM	(\$1,440.00)														
				- Total				\$0.00														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
4S3375	0180	WARNING LIGHT, TYPE B	Material - T	otal				\$0.00	
	0180 -	- Total						\$0.00	
	0190	CMS WITH COMMUNICATION INTERFACE,	Material		1	Sep 3, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user voher1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CONT F			1	Sep 3, 2021	SYSTEM	(\$12,000.00)	
					2	Sep 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Sep 16, 2021	SYSTEM	(\$12,000.00)	
					3	Oct 1, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$12,000.00)	
					4	Oct 18, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$12,000.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0190 -	- Total						\$0.00	
	0250	SEPARATION GEOTEXTILE	Material		5	Nov 2, 2021	SYSTEM	\$3,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Nov 2, 2021	SYSTEM	(\$3,325.00)	
					6	Nov 16, 2021	SYSTEM	\$3,325.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Nov 16, 2021	SYSTEM	(\$3,325.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0250 -	- Total						\$0.00	
	0280	30 IN. GROUP B FLARED END SEC	Material		3	Oct 1, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$1,500.00)	
					4	Oct 18, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					4	Oct 18, 2021	SYSTEM	(\$1,500.00)	
					5	Nov 2, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Nov 2, 2021	SYSTEM	(\$1,500.00)	
					6	Nov 16, 2021	SYSTEM	\$1,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Nov 16, 2021	SYSTEM	(\$1,500.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0280	- Total						\$0.00	
	0350	SILT FENCE	Material		1	Sep 3, 2021	SYSTEM	\$1,834.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
375	0350	SILT FENCE	Material						Estimate Exception 7 on the current Payment Estimate.															
					1	Sep 3, 2021	SYSTEM	(\$1,834.00)																
				- Total				\$0.00																
			Material - To	otal				\$0.00																
	0350 -							\$0.00																
	0360	TYPE C BERM	Material		2	Sep 16, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user voher1 overridding Payment Estimate Exception 9 on the current Payment Estimate.															
					2	Sep 16, 2021	SYSTEM	(\$12,420.00)																
					3	Oct 1, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.															
					3	Oct 1, 2021	SYSTEM	(\$12,420.00)																
					4	Oct 18, 2021	SYSTEM	\$12,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.															
					4	Oct 18, 2021	SYSTEM	(\$12,420.00)																
				- Total				\$0.00																
			Material - To	Total Total				\$0.00																
	0360 -	Total						\$0.00																
	0560	GALVANIZED STRUCTURAL STEEL PILES (12 IN	Material		2	Sep 16, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.															
							2	Sep 16, 2021	SYSTEM	(\$15,385.00)														
					3	Oct 1, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.															
																				3	Oct 1, 2021	SYSTEM	(\$15,385.00)	
						4	Oct 18, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.														
											4	Oct 18, 2021	SYSTEM	(\$15,385.00)										
														5	Nov 2, 2021	SYSTEM	\$15,385.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					5	Nov 2, 2021	SYSTEM	(\$15,385.00)																
					6	6	2021 Estimate It	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																
					6	Nov 16, 2021	SYSTEM	(\$15,385.00)																
				- Total				\$0.00																
								\$0.00																
			Material - To	otal				Ψ0.00																
	0560 -	Total	Material - To	otal				\$0.00																
	<b>0560 -</b> 0570	GALVANIZED STRUCTURAL STEEL PILES (14		otal	3	Oct 1, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
		GALVANIZED STRUCTURAL		otal	3		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment															
		GALVANIZED STRUCTURAL STEEL PILES (14		otal		2021 Oct 1,		<b>\$0.00</b> \$28,025.00	Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment															
		GALVANIZED STRUCTURAL STEEL PILES (14		otal	3	2021 Oct 1, 2021 Oct 18,	SYSTEM	\$0.00 \$28,025.00 (\$28,025.00)	Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J4S3375	0570	GALVANIZED	Material						Estimate Exception 3 on the current Payment Estimate.											
		STRUCTURAL STEEL PILES (14 IN			5	Nov 2, 2021	SYSTEM	(\$28,025.00)												
					6	Nov 16, 2021	SYSTEM	\$28,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					6	Nov 16, 2021	SYSTEM	(\$28,025.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0570 -	Total						\$0.00												
	0590	PRE-BORE FOR PILING	Material		1	Sep 3, 2021	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					1	Sep 3, 2021	SYSTEM	(\$12,540.00)												
					2	Sep 16, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
					2	Sep 16, 2021	SYSTEM	(\$59,470.00)												
					3	Oct 1, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					3	Oct 1, 2021	SYSTEM	(\$59,470.00)												
					4	Oct 18, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
					4	Oct 18, 2021	SYSTEM	(\$59,470.00)												
					5	Nov 2, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
						5	Nov 2, 2021	SYSTEM	(\$59,470.00)											
					6	Nov 16, 2021	SYSTEM	\$59,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					6	Nov 16, 2021	SYSTEM	(\$59,470.00)												
				- Total				\$0.00												
			Material - To	I - Total				\$0.00												
	0590 -	Total						\$0.00												
	0600	PILE POINT REINFORCEMENT	Material		2	Sep 16, 2021	SYSTEM	\$4,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
					2	Sep 16, 2021	SYSTEM	(\$4,140.00)												
																3	Oct 1, 2021	SYSTEM	\$4,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Oct 1, 2021	SYSTEM	(\$4,140.00)												
					4	Oct 18, 2021	SYSTEM	\$4,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.											
					4	Oct 18, 2021	SYSTEM	(\$4,140.00)												
					5	Nov 2, 2021	SYSTEM	\$4,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					5	Nov 2, 2021	SYSTEM	(\$4,140.00)												
					6	Nov 16,	SYSTEM	\$4,140.00	This adjustment offsets the original system-generated Material Payment											



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks									
riojeci	Line	Description	Туре	Adjustment		Date	By	Amount	Remains									
J4S3375	0600	PILE POINT	Material	Туре		2021			Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment									
		REINFORCEMENT			6	Nov 16,	SYSTEM	(\$4,140.00)	Estimate Exception 7 on the current Payment Estimate.									
						2021		, , ,										
				- Total				\$0.00										
			Material - To	otal ————				\$0.00										
	0600 -	Total						\$0.00										
	0610	CLASS B CONCRETE (SUBSTRUCTURE)	Material		3	Oct 1, 2021	SYSTEM	\$22,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					3	Oct 1, 2021	SYSTEM	(\$22,000.00)										
					4	Oct 18, 2021	SYSTEM	\$30,992.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					4	Oct 18, 2021	SYSTEM	(\$30,992.50)										
					5	Nov 2, 2021	SYSTEM	\$30,992.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					5	Nov 2, 2021	SYSTEM	(\$30,992.50)										
					6	Nov 16, 2021	SYSTEM	\$30,992.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					6	Nov 16, 2021	SYSTEM	(\$30,992.50)										
				- Total		2021		\$0.00										
			Material - To					\$0.00										
	0040	Tetal	Wateriai - 10	Jiai				\$0.00										
	0610 - 0630	SLAB ON CONCRETE BEAM	Material		6	Nov 16, 2021	SYSTEM	\$141,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					6	Nov 16, 2021	SYSTEM	(\$141,075.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0630 -	Total						\$0.00										
	0640	MISC.	Material		5	Nov 2, 2021	SYSTEM	\$153,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.									
					5	Nov 2, 2021	SYSTEM	(\$153,650.00)										
													6	6	Nov 16, 2021	SYSTEM	\$153,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Nov 16, 2021	SYSTEM	(\$153,650.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0640 -	Total						\$0.00										
	0660	SLAB DRAIN	Material		5	Nov 2, 2021	SYSTEM	\$10,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					5	Nov 2, 2021	SYSTEM	(\$10,500.00)										
					6	Nov 16, 2021	SYSTEM	\$10,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.									
					6	Nov 16, 2021	SYSTEM	(\$10,500.00)	. , , , , , , , , , , , , , , , , , , ,									
				- Total				\$0.00										
			Material - To					\$0.00										





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3375	0660 -	Total						\$0.00	
	0670	VERTICAL DRAIN AT END BENTS	Material		6	Nov 16, 2021	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Nov 16, 2021	SYSTEM	(\$2,400.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0670 -	Total						\$0.00	
J4S3375	- Total							\$0.00	
Overall -	Total						\$0.00		