

Pay Estimate Created Date: February 15, 2022

Progress Estimate Nu 15			10122-D02 .B. West Contractir	ng Compa			22 Original Contract Amount 022Net Change Order Amount Current Contract Amount	nt(\$487,553.85)
Approval Date								By User
February 16, 2022			Generated and A	Approved (and should be considered	d Draft) at	the Project Office Level by	linkd1
February 16, 2022		Re	eviewed and Appro	oved (and s	gabelj3			
February 17, 2022			I	Reviewed	and Approved at the Cent	tral Office	Controllers Office Level by	ramses1
Original Completion	n Date	Current Con	npletion Date Actual Completion Date % of				of Current Contract Amount	Complete
November 1, 202	November 1, 2021 Novem				October 5, 2021		100.00%	
	Contract	Informational Dat	es	Milestones				
Date Description	Original	Completion Date	Current Complet	tion Date	No Milestones Exist for	Contract		
Acceptance Date								
Awarded Date	February	3, 2021	February 3, 2021					
Letting Date	January 2	22, 2021	January 22, 2021					
Notice to Proceed Date	March 8,	2021	March 8, 2021					
Work Began Date	April 19, 2	2021	April 19, 2021					

Contract Total Pag	y For Estimate No. 15				
		This Estimate	Previous	To Date	
210122-D02					
	Total Posted Items Pay	\$4.70	\$4,807,150.89	\$4,807,155.59	
	Gross Item Adjustments	\$0.00	\$191,228.12	\$191,228.12	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			<mark>\$4,998,379.01</mark>	\$4,998,383.71	
Contract Total Pag	yable This Estimate:	\$4.70			

Contract Total Payable This Estimate:

	Items Paid	I NIS ESI	<u>imate Pe</u>	rioa
--	------------	-----------	-----------------	------

Project Number	Line Number	ltem Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3236	0100	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	TONS	\$47.000	0.1	\$4.70
Project J5P323	6 - Total						\$4.70
Overall - Total							\$4.70

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3236	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material			-13,182.54	\$47.00	(\$619,579.38)
	0100	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	13,182.54	\$47.00	\$619,579.38
	0110	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material			-8,676.4	\$48.00	(\$416,467.20)
	0110	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	8,676.4	\$48.00	\$416,467.20
J5S3277	0540	BITUMINOUS PAVEMENT	Material			-296.4	\$46.00	(\$13,634.40)

Pay Estimate Created Date: February 15, 2022

Progres	ss Estii 1	mate Number 5	Contract ID Prime Contrac	210122-D ctorN.B. Wes		Pay Period StartFebruary 2, 2022 Or Company Pay Period End February 15, 2022 Ne Cu	et Change Or	der Amount	
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3277			TURE PG64-22 CE LEVELING)						
	0540	MIXT	JS PAVEMENT FURE PG64-22 CE LEVELING)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	296.4	\$46.00	\$13,634.40
Total									\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J5P3236	FAF 68-1(10)	Resurface and shoulder improvements	68/HH	PHELPS	from Rte. 8 to Rte. 19 near Salem and Rte. HH from Rte. 32 to the end of state maintenance
J5S3277		Pavement improvements	F	DENT	from Rte. 32 to Rte. E
J5S3393	FAS S402(50)	Pavement Improvements	K	PHELPS	from Rte. 63 to the end of state maintenance

Totals by Job Numbers

J5P3236		This Estimate	Previous	To Date
	Posted Item Pay	\$4.70	\$3,497,038.34	\$3,497,043.04
	Gross Item Adjustments	\$0.00	\$129.356.62	\$129,356.62
	Gross Item Pay	\$4.70	\$3,626,394.96	\$3,626,399.66
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
J5S3277		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$341,467.71	\$341,467.71
	Gross Item Adjustments	\$0.00	\$13,976.95	\$13,976.95
	Gross Item Pay	\$0.00	\$355,444.66	\$355,444.66
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	-		•	·
J5S3393		This Estimate	Previous	To Date
	Posted Item Pay	\$0.00	\$968,644.84	\$968,644.84
	Gross Item Adjustments	\$0.00	\$47,894.55	\$47,894.55
	Gross Item Pay	\$0.00	\$1,016,539.39	\$1,016,539.39
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	,		• • • •	



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3236, Item 4013000, Project Item Line Number 0100, Material Set 401300096, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Waiting on QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3236, Item 4020520, Project Item Line Number 0110, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Waiting on QA	linkd1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3277, Item 4020520, Project Item Line Number 0540, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	Waiting on QA	linkd1	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract								timate was (
Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-D02	J5P3236	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$105,600.00	\$105,600.00
		0001	0020	2063000	CLASS 3 EXCAVATION	234.00	0.00	234.00	CUYD	234.00	\$23.10	\$5,405.40
		0001	0030	2063300	CLASS 4 EXCAVATION	670.00	0.00	670.00	CUYD	670.00	\$60.50	\$40,535.00
		0001	0040	2079909	MISC.MODIFIED LINEAR GRADING, CLASS II	2,592.00	-52.60	2,539.40	STA	2,539.40	\$144.25	\$366,308.45
		0001	0050	2142000	FURNISHING ROCK FILL	303.00	15.67	318.67	CUYD	318.67	\$26.50	\$8,444.76
		0001	0060	2143000	PLACING ROCK FILL	303.00	15.67	318.67	CUYD	318.67	\$36.00	\$11,472.12
		0001	0070	2163500	PARTIAL REMOVAL OF CULVERT CONCRETE	1.00	0.00	1.00	LS	1.00	\$10,600.00	\$10,600.00
		0001	0080	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	306.00	0.00	306.00	SQYD	306.00	\$8.50	\$2,601.00
		0001	0090	3105002	GRAVEL (A) OR CRUSHED STONE (B)	1,477.00	-1,022.30	454.70	TONS	454.70	\$50.00	\$22,735.00
		0001	0100	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	21,398.90	-1,916.36	19,482.54	TONS	19,482.54	\$47.00	\$915,679.38
		0001	0110	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	25,306.60	-3,580.20	21,726.40	TONS	21,726.40	\$48.00	\$1,042,867.20
		0001	0120	4071005	TACK COAT	36,782.00	-17,434.00	19,348.00	GAL	19,348.00	\$1.89	\$36,567.72
		0001	0130	6097000	ROCK LINING	59.00	0.00	59.00	CUYD	59.00	\$70.00	\$4,130.00
		0001	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0150	6161005	CONSTRUCTION SIGNS	4,359.00	-640.25	3,718.75	SQFT	3,718.75	\$4.25	\$15,804.69
		0001	0160	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	2.00	\$100.00	\$200.00
		0001	0170	6161009	FLAG ASSEMBLY	37.00	-7.00	30.00	EA	30.00	\$30.00	\$900.00
		0001	0180	6161025	CHANNELIZER (TRIM LINE)	400.00	0.00	400.00	EA	400.00	\$15.00	\$6,000.00
		0001	0190	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	8.00	2.00	10.00	EA	10.00	\$250.00	\$2,500.00
		0001	0200	6161052	WARNING LIGHT, TYPE B	2.00	-2.00	0.00	EA	0.00	\$100.00	\$0.00
		0001	0210	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	8.00	-1.00	7.00	EA	7.00	\$2,500.00	\$17,500.00
		0001	0220	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	-8.00	0.00	EA	0.00	\$100.00	\$0.00
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$455,000.00	\$455,000.00
		0001	0240	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	-3.00	1.00	EA	1.00	\$600.00	\$600.00
		0001	0250	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	18.00	18.00	36.00	LF	36.00	\$20.00	\$720.00
		0001	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	259,585.00	0.00	259,585.00	LF	259,585.00	\$0.09	\$23,362.65
		0001	0270	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	229,234.00	0.00	229,234.00	LF	229,234.00	\$0.10	\$21,777.23
		0001	0280	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	820.00	0.00	820.00	SQYD	820.00	\$10.15	\$8,323.00
		0001	0290	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	631.00	0.00	631.00	SQYD	631.00	\$4.50	\$2,839.50
		0001	0300	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,476.20	0.00	2,476.20	STA	2,476.20	\$10.00	\$24,762.00
		0001	0310	6261001	BITUMINOUS CENTERLINE RUMBLE STRIP	1,320.90	0.00	1,320.90	STA	1,320.90	\$10.00	\$13,209.00
		0001	0320	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$4,500.00	\$4,500.00
		0001	0330	7034041	CLASS B-1 CONCRETE (CULVERTS)	171.00	0.00	171.00	CUYD	171.00	\$1,024.50	\$175,189.50
		0001	0340	7039901	MISC.Culvert Headwall Modification	1.00	-1.00	0.00	LS	0.00	\$8,300.00	\$0.00
		0001	0350	7061030	REINFORCING STEEL (CULVERTS)	25,600.00	0.00	25,600.00	LB	25,600.00	\$3.30	\$84,480.00
		0001	0360	7250424	24 IN. PIPE GROUP C	76.00	0.00	76.00	LF	76.00	\$92.25	\$7,011.00
		0001	0370	7250430	30 IN. PIPE GROUP C	8.00	0.00	8.00	LF	8.00	\$207.00	\$1,656.00
		0001	0380	7250436	36 IN. PIPE GROUP C	8.00	0.00	8.00	LF	8.00	\$215.00	\$1,720.00
		0001	0390	7250442	42 IN. PIPE GROUP C	8.00	0.00	8.00	LF	8.00	\$223.00	\$1,784.00
		0001	0400	7250448	48 IN. PIPE GROUP C	16.00	-16.00	0.00	LF	0.00	\$228.00	\$0.00
		0001	0410	7320824A	24 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$825.00	\$1,650.00
		0001	0420	7320830A	30 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,095.00	\$2,190.00
		0001	0430	7320836A	36 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,254.00	\$2,508.00
		0001	0440	7320842A	42 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,639.00	\$3,278.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted am	ount at the	time the Es	timate was	Generate	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-D02	J5P3236	0001	0450	7320848A	48 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	4.00	-4.00	0.00	EA	0.00	\$1,881.00	\$0.00
		0001	0460	8051000A	SEEDING - COOL SEASON MIXTURES	59.70	-42.20	17.50	ACRE	17.50	\$1.00	\$17.50
		0001	0470	8061004	SEDIMENT TRAP ROCK	150.10	-150.10	0.00	CUYD	0.00	\$66.00	\$0.00
		0001	0480	8061005	ROCK DITCH CHECK	1,001.00	-707.00	294.00	LF	294.00	\$15.40	\$4,527.60
		0001	0490	8061006	ALTERNATE DITCH CHECK	125.00	0.00	125.00	LF	125.00	\$13.50	\$1,687.50
		0001	0500	8061016	SEDIMENT REMOVAL	1,001.00	-1,001.00	0.00	CUYD	0.00	\$2.00	\$0.00
		0001	0510	8061017	TEMPORARY SEEDING AND MULCHING	11.90	-8.40	3.50	ACRE	3.50	\$1.00	\$3.50
		0001	0520	8061019	SILT FENCE	5,003.00	-5,003.00	0.00	LF	0.00	\$2.35	\$0.00
		0040	0660	9039901	MISC.Adjusting Existing Signs	1.00	-1.00	0.00	LS	0.00	\$7,500.00	\$0.00
		0070	0670	7039903	MISC.HEADWALL MODIFICATION	68.00	-68.00	0.00	LF	0.00	\$110.00	\$0.00
		0071	0680	7039903	MISC.HEADWALL MODIFICATION	94.00	-94.00	0.00	LF	0.00	\$110.00	\$0.00
		0072	0690	7039903	MISC.HEADWALL MODIFICATION	45.00	0.00	45.00	LF	45.00	\$110.00	\$4,950.00
		0073	0700	7039903	MISC.HEADWALL MODIFICATION	52.00	-52.00	0.00	LF	0.00	\$110.00	\$0.00
		0073	0710	7040106	FULL DEPTH REPAIR	10.00	-10.00	0.00	SQFT	0.00	\$500.00	\$0.00
		0001	5001	7279901	MISC.48" Pipe including excavation, grading, and pavement.	0.00	1.00	1.00	LS	1.00	\$29,646.32	\$29,646.32
		0001	5002	7039901	MISC.Headwall Modification on Box at Log Mile 29.211 Rte 68	0.00	1.00	1.00	LS	1.00	\$2,800.00	\$2,800.00
	Project J	5P3236 - To	otal Value	Posted to D	Date as of Report Generated Date							\$3,497,043.01
	J5S3277	0001	0530	3105002	GRAVEL (A) OR CRUSHED STONE (B)	270.00	-215.00	55.00	TONS	55.00	\$50.00	\$2,750.00
		0001	0540	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	6,281.60	-1,985.20	4,296.40	TONS	4,296.40	\$46.00	\$197,634.40
		0001	0550	4071005	TACK COAT	7,306.00	-2,117.00	5,189.00	GAL	5,189.00	\$1.89	\$9,807.21
		0001	0560	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
			6161005	CONSTRUCTION SIGNS	1,026.00	0.00	1,026.00	SQFT	1,026.00	\$4.25	\$4,360.50	
			6161009	FLAG ASSEMBLY	11.00	0.00	11.00	EA	11.00	\$30.00	\$330.00	
		0001	0590	6161025	CHANNELIZER (TRIM LINE)	100.00	20.00	120.00	EA	120.00	\$15.00	\$1,800.00
		0001	0600	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0610	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	-4.00	0.00	EA	0.00	\$100.00	\$0.00
		0001	0620	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$75,500.00	\$75,500.00
		0001	0630	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	72,568.00	0.00	72,568.00	LF	72,568.00	\$0.10	\$7,256.80
		0001	0640	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	61,680.00	0.00	61,680.00	LF	61,680.00	\$0.10	\$6,476.40
		0001	0650	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,009.00	453.70	2,462.70	SQYD	2,462.70	\$12.00	\$29,552.40
	Project J	5S3277 - To	otal Value	Posted to D	Date as of Report Generated Date							\$341,467.71
	J5S3393	0001	0720	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$1,200.00	\$1,200.00
		0001	0730	2153000	SHAPING SLOPES, CLASS III	12.00	0.00	12.00	100F	12.00	\$1,200.00	\$14,400.00
		0001	0740	3105002	GRAVEL (A) OR CRUSHED STONE (B)	288.00	-172.20	115.80	TONS	115.80	\$38.00	\$4,400.40
		0001	0750	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	12,063.00	725.70	12,788.70	TONS	12,788.70	\$54.00	\$690,589.80
		0001	0760	4071005	TACK COAT	13,459.00	-470.00	12,989.00	GAL	12,989.00	\$2.00	\$25,978.00
		0001	0770	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0780	6161005	CONSTRUCTION SIGNS	1,265.00	-117.50	1,147.50	SQFT	1,147.50	\$4.25	\$4,876.88
		0001	0790	6161009	FLAG ASSEMBLY	10.00	0.00	10.00	EA	10.00	\$30.00	\$300.00
		0001	0800	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	100.00	\$15.00	\$1,500.00
		0001	0810	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0820	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	-4.00	0.00	EA	0.00	\$100.00	\$0.00
		0001	0830	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$43,500.00	\$43,500.00
		0001	0840	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	136,879.00	0.00	136,879.00	LF	136,879.00	\$0.10	\$13,687.90

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-D02	J5S3393				MARKING PAINT, TYPE P BEADS							
		0001	0860	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	885.00	0.00	885.00	SQYD	885.00	\$6.70	\$5,929.50
		0001	0870	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	817.00	0.00	817.00	SQYD	817.00	\$6.70	\$5,473.90
		0010	0880	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	8.00	0.00	8.00	EA	8.00	\$3,000.00	\$24,000.00
		0010	0890	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	8.00	0.00	8.00	EA	8.00	\$2,800.00	\$22,400.00
		0070	0900	7034600	CURB BLOCKOUT	375.00	0.00	375.00	LF	375.00	\$248.00	\$93,000.00
	Project J	5S3393 - To	otal Value	Posted to D	Date as of Report Generated Date							\$968,644.84
210122-D02 Ove	rall - Total	Value Post	ed to Da	te as of Rep	ort Generated Date							\$4,807,155.56



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

Line Number	ltem Code		Description	DWR DWR Date Approva Date	Quantity I Posted				Location	From Station/ Log Mile	Offs Dista		Offset/ Distance		Comments	
0100	4013000 B	ITUMINOUS PAVE	MENT MIXTURE PG64-22 (BAS	2/9/22 2/9/22	-0.50	TONS F	Precast Box							Wrong Quantity	entered on 1/24 DWR	
				2/9/22		TONS F	Precast Box	Location								
	Line Number		e details for Construction Sign Total Quantity Posted For DWR Date		ble). n Informatio	n	Station	Log Mile	Location	Number of Item	s SF	Each Sign	Spe	cial Sign	SF Each Special Sign	Total SF to Po
5P3236	0150	March 31, 2021	76	GO20-1 60x2 NEXT XX MILE	4 10.00 R S	OAD WORK	C	39.165		1.00	10					
				CONST-8 48 ZONE NO PHO	x36 12.00	WORK		39.051		1.00	12					
				CONST-8 48 ZONE NO PHO	x36 12.00	WORK		17.275		1.00	12					
				GO20-1 60x2	4 10.00 R	OAD WORK	:	17.162		1.00	10	1				
				GO20-2 48x2		ID ROAD		17.062		1.00	8					
				WORK CONST-7-48 48	x24 8.00	RATE OUR		17.057		1.00	8					
				WORK ZONE GO20-2 48x2				39.306		1.00	8					
				WORK CONST-7-48 48				39.278		1.00	8					
			700	WORK ZONE				55.270								
		May 1, 2021	768	WO3-4(48) 48 PREPARED TO	STOP				Various	12.00	16					1
				WO20-4 48x4 ROAD AHEAD	16.00 C	INE LANE			Various	12.00	16					1
				WO20-1 48x4 ROAD/BRIDGE	18 16.00 RAMP WO	RK AHEAD			Various	12.00	16	i				1
				WO20-7 48x4 (SYMBOL) WIT	18 16.00 F H FLAGS	LAGGER			Various	12.00	16	i				1
		May 15, 2021	108	WO20-1 48x4 ROAD/BRIDGE	18 16.00 RAMP WO	RK AHEAD			37.632 -91.539	1.00	16	i				
				WO20-1 48x4 ROAD/BRIDGE	18 16.00 RAMP WO	RK AHEAD			37.629 -91.541	1.00	16	i				
				CONST-8 48 ZONE NO PHO	x36 12.00				37.633 -91.540	1.00	12					
				CONST-8 48 ZONE NO PHO	x36 12.00	WORK			37.591 -91.545	1.00	12					
				GO20-1 60x2	4 10.00 R	OAD WORK	:		37.634 -91.540	1.00	10					
				GO20-1 60x2	4 10.00 R	OAD WORK	:		37.589 -91.545	1.00	10	1				
				NEXT XX MILE CONST-7-48 48		RATE OUR			37.588 -91.545	1.00	8					
				WORK ZONE GO20-2 48x2	4 8.00 EN	ID ROAD			37.636 -91.540	1.00	8					
				WORK GO20-2 48x2	4 8.00 FM	ID ROAD			37.595 -91.545	1.00	8					
				WORK CONST-7-48 48					37.636 -91.540	1.00	8					
				WORK ZONE	x24 0.00	KATE OOK			37.030 -91.340	1.00	0					
583277	0150 - Total 0570	June 3, 2021	590	Variable ??x??	2 1.00 SPI	ECIAL SIGN	1		various location on project	7.50	1		Pilot car in u	se & follow 18x12	1.50	9
				BY QUANTITY WO3-4(48) 48	x48 16.00				various location on project	7.00	16	;				1
				WO20-4 48x4		NELANE			various location on project		16					
				ROAD AHEAD GO20-4a 42x			т		various location on project		8.7					1
				FOR PILOT CA WO20-7a 48x	R				various location on project							1
				(SYMBOL)		LAGGER					16					
				WO20-1 48x4 ROAD/BRIDGE	RAMP WO				various location on project		16					1
				GO20-4 36x1 FOLLOW ME	8 4.50 PI	LOT CAR			various location on project	1.00	4.5	5				4
00000	0570 - Total		70	CONST 8 48	-26 42.00	WORK		42,000		4.00	40					58
583393	0/60	June 1, 2021	76	CONST-8 48 ZONE NO PHO	NE ZONE			13.022		1.00	12					
				GO20-1 60x2 NEXT XX MILE	S		·	13.04		1.00	10					
				GO20-2 48x2 WORK				13.040		1.00	8					
				CONST-7-48 48 WORK ZONE	x24 8.00	RATE OUR		0.026		1.00	8					
				GO20-2 48x2 WORK	4 8.00 EN	ID ROAD		0.007		1.00	8					
				CONST-8 48	x36 12.00	WORK		.297		1.00	12					
				ZONE NO PHO	NE ZONE											
				ZONE NO PHO CONST-7-48 48 WORK ZONE		RATE OUR		13.042		1.00	8					

0780 - Total

76



Feb 25, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0030	CLASS 4 EXCAVATION	Overrun	Overrun	9	Aug 16, 2021	SYSTEM	(\$36.30)	
					14	Feb 2, 2022	SYSTEM	\$36.30	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',60.50000 - 60.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0030 -	Total						\$0.00	
	0050	FURNISHING ROCK FILL	Material		3	May 16, 2021	SYSTEM	\$415.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user mcwhom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$415.26)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	9	Aug 16, 2021	SYSTEM	(\$415.26)	
					13	Dec 2, 2021	SYSTEM	\$415.26	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',26.50000 - 26.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0050 -	Total						\$0.00	
	0060	PLACING ROCK FILL	Overrun	Overrun	9	Aug 16, 2021	SYSTEM	(\$564.12)	
					13	Dec 2, 2021	SYSTEM	\$564.12	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',36.00000 - 36.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0060 -	Total						\$0.00	
	0080	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		9	Aug 16, 2021	SYSTEM	\$2,601.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		mory			9	Aug 16, 2021	SYSTEM	(\$2,601.00)	
					10	Sep 2, 2021	SYSTEM	\$2,601.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10		SYSTEM SYSTEM	\$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
						2021 Sep 2,			Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
					10	2021 Sep 2, 2021 Sep 15,	SYSTEM	(\$2,601.00)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
					10	2021 Sep 2, 2021 Sep 15, 2021 Sep 15,	SYSTEM	(\$2,601.00) \$2,601.00	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
					10 11 11	2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
					10 11 11 12	2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
					10 11 11 12 12	2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
				- Total	10 11 11 12 12 13	2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
			Material - To		10 11 11 12 12 13	2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00)	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
	0080 -	Total	Material - To		10 11 11 12 12 13	2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$0.00	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
	0080 - 0090	Total GRAVEL (A) OR CRUSHED STONE (B)			10 11 11 12 12 13	2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021 Oct 1, 2021 Oct 1, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$2,601.00 (\$2,601.00) \$0.00	Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0090	GRAVEL (A) OR CRUSHED STONE	Material	Туре	8	Aug 2, 2021	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		(B)			8	Aug 2,	SYSTEM	(\$4,400.00)	Esumate Exception Fon the current Payment Esumate.
					9	2021 Aug 16, 2021	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$4,400.00)	
					10	Sep 2, 2021	SYSTEM	\$17,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$17,935.00)	
					11	Sep 15, 2021	SYSTEM	\$17,935.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$17,935.00)	
					12	Oct 1, 2021	SYSTEM	\$22,735.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$22,735.00)	
					13	Dec 2, 2021	SYSTEM	\$22,735.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$22,735.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0090 -	- Total						\$0.00	
	0100	BITUMINOUS PAVEMENT	Material		6	Jul 1, 2021	SYSTEM	\$853,042.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment
		MIXTURE							Estimate Exception 1 on the current Payment Estimate.
		MIXTURE PG64-22 (BAS			6	Jul 1, 2021	SYSTEM	(\$853,042.48)	
					6 7		SYSTEM	(\$853,042.48) \$905,146.68	
						2021 Jul 16,		,	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment
					7	2021 Jul 16, 2021 Jul 16,	SYSTEM	\$905,146.68	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment
					7 7 7	2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM	\$905,146.68 (\$905,146.68)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
					7 7 8	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	\$905,146.68 (\$905,146.68) \$905,146.68	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment
					7 7 8 8	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment
					7 7 8 8 9	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment
					7 7 8 8 9 9	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18 (\$633,651.18)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
					7 7 8 8 9 9 9 10	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18 (\$633,651.18) \$619,551.18	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.
					7 7 8 8 9 9 10 10	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18 (\$633,651.18) \$619,551.18 (\$619,551.18)	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd 1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd 1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd 1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd 1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7 7 8 8 9 9 9 10 10 10 11	2021 Jul 16, 2021 Jul 26, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 15, Sep 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$905,146.68 (\$905,146.68) \$905,146.68 (\$905,146.68) \$633,651.18 (\$633,651.18) \$619,551.18 (\$619,551.18) \$619,551.18	Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd 1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd 1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd 1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd 1 overridding Payment Estimate Exception 4 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0100	BITUMINOUS PAVEMENT MIXTURE	Material		13	Dec 2, 2021	SYSTEM	\$619,551.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		PG64-22 (BAS			13	Dec 2, 2021	SYSTEM	(\$619,551.18)	
					14	Feb 2, 2022	SYSTEM	\$619,574.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 2, 2022	SYSTEM	(\$619,574.68)	
					15	Feb 15, 2022	SYSTEM	\$619,579.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Feb 15, 2022	SYSTEM	(\$619,579.38)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	ACAD	5	Jun 16, 2021	linkd1	\$19,266.67	7533.4 tons
					6	Jul 1, 2021	linkd1	\$27,151.44	10,616.4 tons + \$27,151.44
					7	Jul 16, 2021	linkd1	\$3,063.89	1108.6 tons , 3.3% VAC , +\$3063.89
					9	Aug 16, 2021	linkd1	\$728.33	Line 100 223.5 tons + \$728.33
				ACAD - Tot	al			\$50,210.33	
			Other Item A	djustment - T				\$50,210.33	
	0100 -	Total						\$50,210.33	
					-	1.1.40	OVOTEN		
	0110	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		7	Jul 16, 2021	SYSTEM	\$611,025.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		1 004 22 (0011			7	Jul 16, 2021	SYSTEM	(\$611,025.60)	
					8	Aug 2, 2021	SYSTEM	\$1,032,096.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$1,032,096.00)	
					10	Sep 2, 2021	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$416,467.20)	
					11	Sep 15, 2021	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$416,467.20)	
					12	Oct 1, 2021	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$416,467.20)	
					13	Dec 2, 2021	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$416,467.20)	
					14	Feb 2, 2022	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Feb 2, 2022	SYSTEM	(\$416,467.20)	
					15	Feb 15,	SYSTEM	\$416,467.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment



Feb 25, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
iP3236	0110	BITUMINOUS PAVEMENT MIXTURE	Material		15	Feb 15, 2022	SYSTEM	(\$416,467.20)	
		PG64-22 (SUR		- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	ACAD	7	Jul 16, 2021	linkd1	\$42,644.50	12729.70 tons, 4.00% VAC, +\$42,644.50
					8	Aug 2, 2021	linkd1	\$29,387.21	Line 110 8772.3 Tons +\$29,387.21
					9	Aug 16, 2021	linkd1	\$886.38	Line 110 224.4 tons + \$886.38
				ACAD - Tota	al			\$72,918.09	
			Other Item A	l djustment - T	otal			\$72,918.09	
	0110 -	Total		-				\$72,918.09	
	0120	TACK COAT	Material		5	Jun 16, 2021	SYSTEM	\$1,763.37	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$1,763.37)	
					6	Jul 1, 2021	SYSTEM	\$3,600.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$3,600.45)	
					7	Jul 16, 2021	SYSTEM	\$22,880.34	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$22,880.34)	
					8	Aug 2, 2021	SYSTEM	\$34,808.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$34,808.13)	
					9	Aug 16, 2021	SYSTEM	\$35,084.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$35,084.07)	
					10	Sep 2, 2021	SYSTEM	\$35,084.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$35,084.07)	
					11	Sep 15, 2021	SYSTEM	\$35,084.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$35,084.07)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -	Total						\$0.00	
	0130	ROCK LINING	Material		6	Jul 1, 2021	SYSTEM	\$1,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$1,918.00)	
					7	Jul 16, 2021	SYSTEM	\$1,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$1,918.00)	
					8	Aug 2, 2021	SYSTEM	\$1,918.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.



Feb 25, 2022

ect	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
236	0130	ROCK LINING	Material	Туре	8	Aug 2,	SYSTEM	(\$1,918.00)	
					9	2021 Aug 16, 2021	SYSTEM	\$4,130.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$4,130.00)	Estimate Exception o on the current Payment Estimate.
				- Total		2021		\$0.00	
			Material - To					\$0.00	
	0130 -	Total						\$0.00	
	0160	ADVANCED WARNING RAIL SYSTEM	Material		2	May 3, 2021	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$200.00)	
					3	May 16, 2021	SYSTEM	\$200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcwhom1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$200.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
	0170	FLAG ASSEMBLY	Material		2	May 3, 2021	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$720.00)	
					3	May 16, 2021	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcwhom1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$720.00)	
				- Total				\$0.00	
	0.170		Material - To	tal				\$0.00	
ľ	0170 - 0180	CHANNELIZER (TRIM LINE)	Material		2	May 3, 2021	SYSTEM	\$0.00 \$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$3,000.00)	
					3	May 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$3,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0180 -							\$0.00	
	0190	TYPE III MOVEABLE BARRICADE WITH	Overrun	Overrun		Aug 2, 2021	SYSTEM	(\$500.00)	
		LIGHTS			14	Feb 2, 2022	SYSTEM	\$500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',250.00000 - 250.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
- 5	0190 - 0210	CMS W/O	Material		2	May 3,	SYSTEM	\$0.00 \$10,000.00	This adjustment offsets the original system-generated Material Payment
		COMMUNICATION INTERFACE, CONT F/			2	2021 May 3	SYSTEM	(\$10,000,00)	Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	May 3, 2021	SYSTEM	(\$10,000.00)	This adjustment effects the original system generated Natorial Parmant
					3	May 16, 2021	SISIEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user mcwhom1 overridding Payment



Feb 25, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
I5P3236	0210	CMS W/O	Material	Туре					Estimate Exception 5 on the current Payment Estimate.
01 0200	0210	COMMUNICATION INTERFACE,	Matorial		3	May 16,	SYSTEM	(\$10,000.00)	
		CONT F/		- Total		2021		\$0.00	
			Material - Tot					\$0.00	
			Overrun	Overrun	8	Aug 2, 2021	SYSTEM	(\$7,500.00)	
					13	Dec 2, 2021	SYSTEM	\$7,500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2500.00000 - 2500.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0210 -	Total						\$0.00	
	0260	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		10	Sep 2, 2021	SYSTEM	\$2,271.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		WARKING			10	Sep 2, 2021	SYSTEM	(\$2,271.60)	
					11	Sep 15, 2021	SYSTEM	\$23,362.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$23,362.65)	
					12	Oct 1, 2021	SYSTEM	\$23,362.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$23,362.65)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
			Other Item Adjustment	REFL	12	Oct 1, 2021	linkd1	\$1,168.13	See Adjustment Sheet
				REFL - Tota	ıl			\$1,168.13	
			Other Item A	djustment - T	otal			\$1,168.13	
	0260 -							\$1,168.13	
	0270	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		10	Sep 2, 2021	SYSTEM	\$21,777.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$21,777.23)	
					11	Sep 15, 2021	SYSTEM	\$21,777.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$21,777.23)	
					12	Oct 1, 2021	SYSTEM	\$21,777.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$21,777.23)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
			Other Item Adjustment	REFL	12	Oct 1, 2021	linkd1	\$1,120.95	See Adjustment Worksheet
				REFL - Tota	ıl			\$1,120.95	
			Other Item A	djustment - T	otal			\$1,120.95	
	0270 -	Total						\$1,120.95	
	0330	CLASS B-1 CONCRETE (CULVERTS)	Material		2	May 3, 2021	SYSTEM	\$34,320.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$34,320.75)	
					3	May 16,	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0330	CLASS B-1 CONCRETE	Material	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		2021			Estimate Item Adjustment (0006) due to user mcwhom1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		(CULVERTS)			3	May 16, 2021	SYSTEM	(\$82,216.12)	
					4	Jun 2, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user mcwhom1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$82,216.12)	
					5	Jun 16, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$82,216.12)	
					6	Jul 1, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$82,216.12)	
					7	Jul 16, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$82,216.12)	
					8	Aug 2, 2021	SYSTEM	\$82,216.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$82,216.12)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	SUBI	3	May 17, 2021	mcwhom1	(\$550.00)	Aplex poured the floor in box 0.765 on Rte. HH with Non chlorinated accelerant. I talked to Eric Abbott and we decided that the box Floor would be fine to leave in place but a deduct would need to be taken. A total of 5.25 yards were poured in the floor so Eric decided that a deduct of \$550.00 would be appropriate
				SUBI - Tota	I			(\$550.00)	
			Other Item A	djustment - T	otal			(\$550.00)	
	0330 -							(\$550.00)	
	0360	24 IN. PIPE CULVERT GROUP C	Material		13	Dec 2, 2021	SYSTEM	\$7,011.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$7,011.00)	
				- Total				\$0.00	
	0000	Total	Material - To	tal				\$0.00	
	0360 -	Total 30 IN. PIPE CULVERT GROUP C	Material		13	Dec 2, 2021	SYSTEM	\$0.00 \$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		-			13	Dec 2, 2021	SYSTEM	(\$1,656.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0370 -	Total						\$0.00	
	0380	36 IN. PIPE CULVERT GROUP C	Material		13	Dec 2, 2021	SYSTEM	\$1,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$1,720.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		Total						\$0.00	
	0390	42 IN. PIPE	Material		13	Dec 2,	SYSTEM	\$1,784.00	This adjustment offsets the original system-generated Material Payment



Feb 25, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3236	0390	CULVERT GROUP C	Material			2021			Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$1,784.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0390 -	Total						\$0.00	
	0460	SEEDING - COOL SEASON MIXTURES	Material		12	Oct 1, 2021	SYSTEM	\$17.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$17.50)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0460 -	Total						\$0.00	
	0480	ROCK DITCH CHECK	Material		7	Jul 16, 2021	SYSTEM	\$4,527.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$4,527.60)	
					8	Aug 2, 2021	SYSTEM	\$4,527.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$4,527.60)	
					9	Aug 16, 2021	SYSTEM	\$4,527.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$4,527.60)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0480 -	Total						\$0.00	
	0490	ALTERNATE DITCH CHECK	Material		2	May 3, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$1,687.50)	
					3	May 16, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user mcwhom1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					3	May 16, 2021	SYSTEM	(\$1,687.50)	
					4	Jun 2, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user mcwhom1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$1,687.50)	
					5	Jun 16, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$1,687.50)	
					6	Jul 1, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$1,687.50)	
					7	Jul 16, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$1,687.50)	
					8	Aug 2, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 21 on the current Payment Estimate.



				0.1	- ·	0 1 1	0 1 1		
Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре					
J5P3236	0490	ALTERNATE DITCH CHECK	Material		8	Aug 2, 2021	SYSTEM	(\$1,687.50)	
					9	Aug 16, 2021	SYSTEM	\$1,687.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Aug 16,	SYSTEM	(\$1,687.50)	
				- Total		2021		\$0.00	
			Material - Tot					\$0.00	
	0490 -	· Total	Waterial - Tor	.ai				\$0.00	
	0510	TEMPORARY SEEDING AND MULCHING	Material		7	Jul 16, 2021	SYSTEM	\$3.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		MOLOTING			7	Jul 16, 2021	SYSTEM	(\$3.50)	
					8	Aug 2, 2021	SYSTEM	\$3.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$3.50)	
					9	Aug 16, 2021	SYSTEM	\$3.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$3.50)	
					10	Sep 2, 2021	SYSTEM	\$3.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$3.50)	
					11	Sep 15, 2021	SYSTEM	\$3.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$3.50)	
					12	Oct 1, 2021	SYSTEM	\$3.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$3.50)	
				- Total		2021		\$0.00	
			Material - Tot					\$0.00	
	0510 -	Total	Material - To	.01				\$0.00	
		MISC. CONCRETE CONSTRUCTION		MATL	14	Feb 2, 2022	linkd1		Material Takeover for steel delivered to job that was not used on the other box culverts on the original line item 0340. This steel is left over from Bridges, S0141, S0151, S0171. Price includes 5% overhead above the invoice that was
				MATL - Tota	al			\$4,489.12	received from the contractor.
			Other Item A					\$4,489.12	
	5002	· Total	Other item A	ajustment - I	otai			\$4,489.12	
J5P3236									
J5P3236		BITUMINOUS PAVEMENT	Material		5	Jun 16, 2021	SYSTEM	\$129,356.62 \$197,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Iverarition 1 on the oursers Reviment Estimate
		MIXTURE PG64-22 (SUR			5	Jun 16,	SYSTEM	(\$197,634.40)	Estimate Exception 1 on the current Payment Estimate.
					6	2021 Jul 1,	SYSTEM	\$197,634.40	This adjustment offsets the original system-generated Material Payment
						2021	GTOTLIVI	φ107,00 4.4 0	Estimate lem Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$197,634.40)	
					7	Jul 16, 2021	SYSTEM	\$197,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$197,634.40)	



Droiget	Line	Description	Adiustraant	Other	Eat	Created	Created	Americant	Demorie
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3277	0540	BITUMINOUS PAVEMENT MIXTURE	Material		8	Aug 2, 2021	SYSTEM	\$197,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		PG64-22 (SUR			8	Aug 2, 2021	SYSTEM	(\$197,634.40)	
					9	Aug 16, 2021	SYSTEM	\$59,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$59,634.40)	
					10	Sep 2, 2021	SYSTEM	\$13,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$13,634.40)	
					11	Sep 15, 2021	SYSTEM	\$13,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$13,634.40)	
					12	Oct 1, 2021	SYSTEM	\$13,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$13,634.40)	
					13	Dec 2, 2021	SYSTEM	\$13,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$13,634.40)	
					14	Feb 2, 2022	SYSTEM	\$13,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Feb 2, 2022	SYSTEM	(\$13,634.40)	
					15	Feb 15, 2022	SYSTEM	\$13,634.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Feb 15, 2022	SYSTEM	(\$13,634.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	ACAD	5	Jun 16, 2021	linkd1	\$13,318.84	4296.4 tons
				ACAD - Tot				\$13,318.84	
			Other Item A	.djustment - T	otal			\$13,318.84	
	0540 -	Total						\$13,318.84	
	0550	TACK COAT	Material		5	Jun 16, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$9,807.21)	
					6	Jul 1, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$9,807.21)	
					7	Jul 16, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$9,807.21)	
					8	Aug 2, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$9,807.21)	
						2021			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3277	0550	TACK COAT	Material		9	Aug 16, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$9,807.21)	
					10	Sep 2, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$9,807.21)	
					11	Sep 15, 2021	SYSTEM	\$9,807.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$9,807.21)	
				- Total	1			\$0.00	
			Material - To	tal				\$0.00	
	0550 -							\$0.00	
	0570	CONSTRUCTION SIGNS	Overrun	Overrun	8	Aug 2, 2021	SYSTEM	(\$1,531.06)	
					13	Dec 2, 2021	SYSTEM	\$1,531.06	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.25000 - 4.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0570 -							\$0.00	
	0590	CHANNELIZER (TRIM LINE)	Overrun	Overrun	8	Aug 2, 2021	SYSTEM	(\$300.00)	
					14	Feb 2, 2022	SYSTEM	\$300.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.00000 - 15.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0590 -		Material		c.	hur 40	OVOTEM	\$0.00	This adjustment off statistical and an analysis descent descent
	0630	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		5	Jun 16, 2021	SYSTEM	\$5,805.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$5,805.50)	
					6	Jul 1, 2021	SYSTEM	\$5,805.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$5,805.50)	
					7	Jul 16,	SYSTEM	* 5 005 50	
						2021		\$5,805.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	2021 Jul 16, 2021	SYSTEM	\$5,805.50	Estimate Item Adjustment (0014) due to user linkd1 overridding Payment
					7 8	Jul 16,	SYSTEM		Estimate Item Adjustment (0014) due to user linkd1 overridding Payment
						Jul 16, 2021 Aug 2,		(\$5,805.50)	Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment
					8	Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM	(\$5,805.50) \$5,805.50	Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment
					8	Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM	(\$5,805.50) \$5,805.50 (\$5,805.50)	Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment
					8 8 9	Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM	(\$5,805.50) \$5,805.50 (\$5,805.50) \$5,805.50	Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment
					8 8 9 9	Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,805.50) \$5,805.50 (\$5,805.50) \$5,805.50 (\$5,805.50)	Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.
					8 8 9 9 10	Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, Sep 2, Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,805.50) \$5,805.50 (\$5,805.50) \$5,805.50 (\$5,805.50) \$5,805.50	Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3277	0630	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material						Estimate Exception 14 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$5,805.50)	
					12	Oct 1, 2021	SYSTEM	\$7,256.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$7,256.80)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	REFL	12	Oct 1, 2021	linkd1	\$349.71	See Adjustment Worksheet
				REFL - Tota	d .			\$349.71	
			Other Item A	Adjustment - Total				\$349.71	
	0630 -	- Total						\$349.71	
	0640	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		5	Jun 16, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$5,181.12)	
					6	Jul 1, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$5,181.12)	
					7	Jul 16, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$5,181.12)	
					8	Aug 2, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$5,181.12)	
					9	Aug 16, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$5,181.12)	
					10	Sep 2, 2021	SYSTEM	\$5,181.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$5,181.12)	
						11	Sep 15, 2021	SYSTEM	\$5,181.12
					11	Sep 15, 2021	SYSTEM	(\$5,181.12)	
					12	Oct 1, 2021	SYSTEM	\$6,476.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$6,476.40)	
				- Total					
			Material - To					\$0.00	
			Other Item Adjustment	REFL		Oct 1, 2021	linkd1	\$308.40	See Adjustment Worksheet
				REFL - Tota				\$308.40	
	0.000	T.4.1	Other Item A	djustment - T	otal			\$308.40	
	0640 0650	Total MODIFIED COLDMILLING	Other Item Adjustment	OTHR	13	Dec 2, 2021	linkd1	\$308.40 \$5,444.40	Previous entered adjustment fixed by this entry.
		(DEPTH							



Feb 25, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3277	0650	TRANSITIONS)	Other Item Adjustment						
			Other Item A	djustment - T	otal			\$5,444.40	
			Overrun	Overrun	4	Jun 2, 2021	SYSTEM	\$5,444.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user mcwhom1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					4	Jun 2, 2021	mcwhom1	(\$5,444.40)	This overrun amount is pending change order
					4	Jun 2, 2021	SYSTEM	(\$5,444.40)	
					5	Jun 16, 2021	SYSTEM	(\$5,444.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Jun 16, 2021	SYSTEM	\$5,444.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$5,444.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Jul 1, 2021	SYSTEM	\$5,444.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Jul 16, 2021	SYSTEM	(\$5,444.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Jul 16, 2021	SYSTEM	\$5,444.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$5,444.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					13	Dec 2, 2021	SYSTEM	\$5,444.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',12.00000 - 12.00000, 'is applied (if non-zero).
				Overrun - T	otal			(\$5,444.40)	
			Overrun - To	tal				(\$5,444.40)	
	0650 -	Total						\$0.00	
J5S3277 -	Total							\$13,976.95	
J5S3393	0740	GRAVEL (A) OR CRUSHED STONE (B)	Material		10	Sep 2, 2021	SYSTEM	\$4,400.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$4,400.40)	
					11	Sep 15, 2021	SYSTEM	\$4,400.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$4,400.40)	
					12	Oct 1, 2021	SYSTEM	\$4,400.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$4,400.40)	
					13	Dec 2, 2021	SYSTEM	\$4,400.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Dec 2, 2021	SYSTEM	(\$4,400.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0740 -	Total						\$0.00	
	0750	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		8	Aug 2, 2021	SYSTEM	\$531,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$531,360.00) \$0.00	
				- Total					
			Material - Tot					\$0.00	
			Other Item	ACAD	8	Aug 2,	linkd1	\$34,612.20	Line 750



Feb 25, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3393	0750	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Adjustment	ACAD		2021			98401 tons +\$34612.20
					9	Aug 16, 2021	linkd1	\$12,229.73	Line 750 2948.7 tons + \$12,229.73
				ACAD - Tot	al			\$46,841.93	
			Other Item A	djustment - T	otal			\$46,841.93	
			Overrun	Overrun	9	Aug 16, 2021	SYSTEM	(\$39,187.80)	
					13	Dec 2, 2021	SYSTEM	\$39,187.80	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',54.00000 - 54.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0750 -	Total						\$46,841.93	
	0760	TACK COAT	Material		8	Aug 2, 2021	SYSTEM	\$20,704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$20,704.00)	
					9	Aug 16, 2021	SYSTEM	\$25,978.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user linkd1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$25,978.00)	
					10	Sep 2, 2021	SYSTEM	\$25,978.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$25,978.00)	
					11	Sep 15, 2021	SYSTEM	\$25,978.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$25,978.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0760 -							\$0.00	
	0840	4 IN. WHITE WATERBORNE PAVEMENT MARKING			9	Aug 16, 2021	SYSTEM	\$13,687.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$13,687.90)	
						10	Sep 2, 2021	SYSTEM	\$13,687.90
					10	Sep 2, 2021	SYSTEM	(\$13,687.90)	
					11	Sep 15, 2021	SYSTEM	\$13,687.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$13,687.90)	
					12	Oct 1, 2021	SYSTEM	\$13,687.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$13,687.90)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	REFL		Oct 1, 2021	linkd1	\$676.52	See Adjustment Worksheet
				REFL - Total				\$676.52	
			Other Item A	djustment - T	otal			\$676.52	



Feb 25, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
583393	0840 -	Total						\$676.52	
	0850	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		9	Aug 16, 2021	SYSTEM	\$11,408.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$11,408.46)	
					10	Sep 2, 2021	SYSTEM	\$11,408.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$11,408.46)	
					11	Sep 15, 2021	SYSTEM	\$11,408.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					11	Sep 15, 2021	SYSTEM	(\$11,408.46)	
					12	Oct 1, 2021	SYSTEM	\$11,408.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Oct 1, 2021	SYSTEM	(\$11,408.46)	
				- Total				\$0.00	
			Material - Tot Other Item Adjustment	tal				\$0.00	
				REFL	12	Oct 1, 2021	linkd1	\$376.10	See Adjustment Worksheet
				REFL - Tota	l			\$376.10	
			Other Item A	Other Item Adjustment - Total					
	0850 -	Total						\$376.10	
	0880	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		9	Aug 16, 2021	SYSTEM	(\$13,256.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$13,256.00)	
			Construction	Stockpile - 1				(\$13,256.00)	
			Construction Stockpile STMI		1	Apr 5, 2021	SYSTEM	\$13,256.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$13,256.00	
			Construction	I Stockpile S	FMI - Tota			\$13,256.00	
	0880 -							\$0.00	
	0890	TYPE A CRASHWORTHY END TERMINAL	THY Stockpile		9	Aug 16, 2021	SYSTEM	(\$12,448.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total	Fotol			(\$12,448.00)	
				Stockpile - I	1	Apr 5, 2021	SYSTEM	(\$12,448.00) \$12,448.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total		2021		\$12,448.00	
			Construction		nstruction Stockpile STMI - Total				
	08 <u>90</u> -	90 - Total						\$12,448.00 \$0.00	
	0900	CURB BLOCKOUT	Material		4	Jun 2, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user mcwhom1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Jun 2, 2021	SYSTEM	(\$93,000.00)	
					5	Jun 16, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user linkd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$93,000.00)	
					6	Jul 1, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user linkd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Jul 1, 2021	SYSTEM	(\$93,000.00)	
					7	Jul 16, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user linkd1 overridding Payment
							Jul 1, 2021 Jul 16,		,



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5S3393	0900	CURB BLOCKOUT	Material						Estimate Exception 13 on the current Payment Estimate.	
					7	Jul 16, 2021	SYSTEM	(\$93,000.00)		
					8	Aug 2, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user linkd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
					8	Aug 2, 2021	SYSTEM	(\$93,000.00)		
					9	Aug 16, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user linkd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					9	Aug 16, 2021	SYSTEM	(\$93,000.00)		
						10	Sep 2, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$93,000.00)		
					11	Sep 15, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user linkd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					11	Sep 15, 2021	SYSTEM	(\$93,000.00)		
					12	Oct 1, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user linkd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					12	Oct 1, 2021	SYSTEM	(\$93,000.00)		
					13	Dec 2, 2021	SYSTEM	\$93,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user linkd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
						13	Dec 2, 2021	SYSTEM	(\$93,000.00)	
				- Total				\$0.00		
			Material - To	al				\$0.00		
	0900 -	Total						\$0.00		
J5S3393 -	Total							\$47,894.55		
Overall -	Total						\$191,228.12			