

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2022

Progress Estimate Number	Contract ID	210122-D04	Pay Period Start	March 16, 2022	Original Contract Amount	\$1,413,242.50
15	Prime Contractor	Concrete Strategies, LLC	Pay Period End	June 30, 2022	Net Change Order Amount	\$65,990.91
13					Current Contract Amount	\$1,479,233.41

Approval Date		By User
June 30, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	browns1
June 30, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	browns1
July 5, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	December 1, 2021	March 18, 2022	100.00%

	Contract Informational Dates									
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract							
Acceptance Date										
Awarded Date	February 3, 2021	February 3, 2021								
Letting Date	January 22, 2021	January 22, 2021								
Notice to Proceed Date	March 8, 2021	March 8, 2021								
Work Began Date	July 6, 2021	July 6, 2021								

Contract Total Pa	ay For Estimate No. 15			
		This Estimate	Previous	To Date
210122-D04				
	Total Posted Items Pay	\$11,713.05	\$1,467,520.35	\$1,479,233.40
	Gross Item Adjustments	\$2,046.00	(\$2,046.00)	\$0.00
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$1,465,474.35	\$1,479,233.40
Contract Total Pa	avable This Estimate	\$13 759 0 5		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3399	0230	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$1.500	723	\$1,084.50
	0250	7121100	FABRICATED STRUCTURAL LOW ALLOY STEEL (MISC)	LB	\$4.000	283	\$1,132.00
	0340	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$1.500	746	\$1,119.00
	5003	7119904		SQFT	\$4.250	576	\$2,448.00
	5004	7119904		SQFT	\$4.250	210	\$892.50
	5005	7129901		LS	\$1,031.720	1	\$1,031.72
	5006	7129901		LS	\$1,031.710	1	\$1,031.71
	5007	7129901		LS	\$365.400	1	\$365.40
	5008	7129901		LS	\$2,608.220	1	\$2,608.22
Project J5P33	99 - Total						\$11,713.05
Overall - Tota	1						\$11,713.05

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3399	0195	ROCK DITCH CHECK	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.50000 - 15.50000, 'is	132	\$15.50	\$2,046.00

Revision 4/1/2020 Page 1 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2022

Project Line Item De				Contract ID Prime Contra	210122 actor Concre		LLC Pay Period End June 30, 2022	Original Contract Amount \$1,413 Net Change Order Amount \$65,99 Current Contract Amount \$1,479			5,990.91
,	Project Line Item Desc Number No.		cription	Adjustment Type	Other Item Adjustment	Comments		Adjustment Quantity	Line Item Adjustment	Adjustment amount	

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
					applied (if non-zero).			
Total								\$2,046.00


Revision 4/1/2020 Page 2 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J5P3399	FAF 63-3(111)	Bridge rehabilitation	50,63	GASCONADE	on Rte. 63 and Rte.	on Rte. 63 and Rte. 50 over Gasconade River					
Totals by J	Job Numbe	rs									
J5P3399				Item Pay	This Estimate \$11,713.05 \$2,046.00 \$13,759.05	Previous \$1,467,520.35 (\$2,046.00) \$1,465,474.35	To Date \$1,479,233.40 \$0.00 \$1,479,233.40				
Posted Item Pay Gross Item Adjustments Gross Item Pay Incentive Disincentive Liquidated Damages Other Contract Adjustments					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 3 of 13





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 4 of 13



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q Contract	uantities Project	and Valu Category	es are b	ltem	eport Generated date and can differ from the posted ame Description	ount at the	time the E	Estimate was	S Gener Unit	ated. Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
210122-D04	J5P3399	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$7,500.00	\$7,500.00
		0001	0020	2072000	LINEAR GRADING CLASS 2	42.50	0.00	42.50	STA	42.50	\$1,045.00	\$44,412.50
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	3,638.00	0.00	3,638.00	SQYD	3,638.00	\$11.25	\$40,927.50
		0001	0040	5029905	MISC.Optional Pavement	3,637.70	0.00	3,637.70	SQYD	3,637.70	\$57.50	\$209,167.75
		0001	0043	6122017	IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	2.00	0.00	2.00	EA	2.00	\$4,000.00	\$8,000.00
		0001	0045	6122020	REPLACEMENT SAND BARREL	2.00	-2.00	0.00	EA	0.00	\$320.00	\$0.00
		0001	0047	6122030	IMPACT ATTENUATOR (RELOCATION)	3.00	3.00	6.00	EA	6.00	\$1,165.00	\$6,990.00
		0001	0050	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	1.00	0.00	1.00	EA	1.00	\$5,400.00	\$5,400.00
		0001	0060	6161005	CONSTRUCTION SIGNS	500.00	-112.00	388.00	SQFT	388.00	\$7.50	\$2,910.00
		0001	0070	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$37.50	\$150.00
		0001	0080	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$16.00	\$128.00
		0001	0090	6161010	RELOCATED SIGNS	500.00	-112.00	388.00	SQFT	388.00	\$6.50	\$2,522.00
		0001	0100	6161025	CHANNELIZER (TRIM LINE)	113.00	0.00	113.00	EA	113.00	\$19.25	\$2,175.25
		0001	0110	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	2.00	4.00	EA	4.00	\$2,674.00	\$10,696.00
		0001	0120	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	-4.00	0.00	EA	0.00	\$1,069.25	\$0.00
		0001	0130	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	1,270.00	0.00	1,270.00	LF	1,270.00	\$31.50	\$40,005.00
		0001	0140	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	3,810.00	0.00	3,810.00	LF	3,810.00	\$10.25	\$39,052.50
		0001	0150	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$148,822.00	\$148,822.00
		0001	0155	6191000	PAVEMENT EDGE TREATMENT	4,245.00	0.00	4,245.00	LF	4,245.00	\$0.10	\$424.50
		0001	0160	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,145.00	4,908.00	8,053.00	LF	8,053.00	\$0.80	\$6,442.40
		0001	0170	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,700.00	6,836.00	10,536.00	LF	10,536.00	\$0.86	\$9,060.96
		0001	0180	6207001	PAVEMENT MARKING REMOVAL	16,080.00	36,322.00	52,402.00	LF	52,402.00	\$0.64	\$33,537.28
		0001	0190	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	16,080.00	22,264.00	38,344.00	LF	38,344.00	\$0.53	\$20,322.32
		0001	0191	8052000A	SEEDING - WARM SEASON GRASSES	1.00	-1.00	0.00	ACRE	0.00	\$5,186.00	\$0.00
		0001	0192	8061003	SEDIMENT TRAP EXCAVATION	5.00	-5.00	0.00	CUYD	0.00	\$48.00	\$0.00
		0001	0194	8061004	SEDIMENT TRAP ROCK	5.00	-5.00	0.00	CUYD	0.00	\$69.50	\$0.00
		0001	0195	8061005	ROCK DITCH CHECK	120.00	132.00	252.00	LF	252.00	\$15.50	\$3,906.00
		0001	0196	8061016	SEDIMENT REMOVAL	251.00	-251.00	0.00	CUYD	0.00	\$42.00	\$0.00
		0001	0198	8061019	SILT FENCE	1,386.00	-686.00	700.00	LF	700.00	\$2.50	\$1,750.00
		0070	0200	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	163.00	0.00	163.00	LF	163.00	\$266.00	\$43,358.00
		0070	0210	2169903	MISC.Remove and Replace Barrier Curb	42.00	0.00	42.00	LF	42.00	\$490.00	\$20,580.00
		0070	0220	7034214	CLASS B-2 CONCRETE	30.60	0.00	30.60	CUYD	30.60	\$1,791.00	\$54,804.60
		0070	0230	7101000	REINFORCING STEEL (EPOXY COATED)	1,300.00	723.00	2,023.00	LB	2,023.00	\$1.50	\$3,034.50
		0070	0240	7110100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (URETHANE)	1.00	0.00	1.00	LS	1.00	\$10,700.00	\$10,700.00
		0070	0250	7121100	FABRICATED STRUCTURAL LOW ALLOY STEEL (MISC)	1,700.00	283.00	1,983.00	LB	1,983.00	\$4.00	\$7,932.00
		0070	0260	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	2,700.00	0.00	2,700.00	SQFT	2,700.00	\$69.50	\$187,650.00
		0070	0270	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	2,500.00	0.00	2,500.00	SQFT	2,500.00	\$2.25	\$5,625.00
		0070	0280	7125385A	INTERMEDIATE FIELD COAT (SYSTEM H)	2,500.00	-1,250.00	1,250.00	SQFT	1,250.00	\$2.25	\$2,812.50
		0070	0290	7125390A	FINISH FIELD COAT (SYSTEM H)	2,500.00	-1,250.00	1,250.00	SQFT	1,250.00	\$2.25	\$2,812.50
		0070	0300	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	163.00	0.00	163.00	LF	163.00	\$284.00	\$46,292.00
		0071	0310	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	140.00	0.00	140.00	LF	140.00	\$281.00	\$39,340.00
		0071	0320	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	36.00	0.00	36.00	LF	36.00	\$559.00	\$20,124.00
		0071	0330	7034214	CLASS B-2 CONCRETE	24.10	0.00	24.10	CUYD	24.10	\$2,198.00	\$52,971.80
		0071	0340	7101000	REINFORCING STEEL (EPOXY COATED)	2,900.00	746.00	3,646.00	LB	3,646.00	\$1.50	\$5,469.00

Page 5 of 13 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-D04	J5P3399	0071	0350	7110100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (URETHANE)	1.00	0.00	1.00	LS	1.00	\$10,700.00	\$10,700.00
		0071	0360	7123130	REHABILITATE BEARING	10.00	0.00	10.00	EA	10.00	\$5,200.00	\$52,000.00
		0071	0370	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	2,500.00	0.00	2,500.00	SQFT	2,500.00	\$69.50	\$173,750.00
		0071	0380	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	2,400.00	0.00	2,400.00	SQFT	2,400.00	\$2.25	\$5,400.00
		0071	0390	7125385A	INTERMEDIATE FIELD COAT (SYSTEM H)	2,400.00	0.00	2,400.00	SQFT	2,400.00	\$2.25	\$5,400.00
		0071	0400	7125390A	FINISH FIELD COAT (SYSTEM H)	2,400.00	0.00	2,400.00	SQFT	2,400.00	\$2.25	\$5,400.00
		0071	0410	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	140.00	0.00	140.00	LF	140.00	\$298.00	\$41,720.00
		0001	5001	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	0.00	8.00	8.00	EA	8.00	\$1,069.25	\$8,554.00
		0001	5002	6161070	TUBULAR MARKER	0.00	172.00	172.00	EA	172.00	\$117.00	\$20,124.00
		0070	5003	7119904		0.00	576.00	576.00	SQFT	576.00	\$4.25	\$2,448.00
		0071	5004	7119904		0.00	210.00	210.00	SQFT	210.00	\$4.25	\$892.50
		0070	5005	7129901		0.00	1.00	1.00	LS	1.00	\$1,031.72	\$1,031.72
0071 5006 7129		7129901		0.00	1.00	1.00	LS	1.00	\$1,031.71	\$1,031.71		
		0070	5007	7129901		0.00	1.00	1.00	LS	1.00	\$365.40	\$365.40
		0070	5008	7129901		0.00	1.00	1.00	LS	1.00	\$2,608.22	\$2,608.22
	Project J	5P3399 - To	otal Value	Posted to D	late as of Report Generated Date							\$1,479,233.41
210122-D04 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$1,479,233.41

Page 6 of 13 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0230	7101000	REINFORCING STEEL (EPOXY COATED)	6/28/22	6/28/22	723.00	LB	Bridge #A37601 263 lbs - remaining quantity for barrier curb 460 lbs - additional steel needed at bent #3					
0250	7121100	FAB. STRUCT. LOW ALLOY STEEL (MISC)	6/28/22	6/28/22	283.00	LB	Bridge #A37601 Girder #3 Bent #6					
0340	7101000	REINFORCING STEEL (EPOXY COATED)	6/28/22	6/28/22	746.00	LB	Bridge #A38781 226 lbs - remaining quantity for barrier curb 520 lbs - additional steel needed at bent #7					
5003	7119904	MISC.	6/28/22	6/28/22	576.00	SQFT	Bridge #A37601 Bent cap at #3, 6, and 10					
5004	7119904	MISC.	6/28/22	6/28/22	210.00	SQFT	Bridge #A38781 Bent cap #7 and 9					
5005	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	6/28/22	6/28/22	1.00	LS	Steel plates at various girders on Bridge #A37601					
5006	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	6/28/22	6/28/22	1.00	LS	Steel plates at various girders on Bridge #A38781					
5007	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	6/28/22	6/28/22	1.00	LS	Modifications of stiffeners on Bridge #A37601					
5008	7129901	MISC. STRUCTURAL STEEL CONSTRUCTION	6/28/22	6/28/22	1.00	LS	N/A					Shop Drawings for extra work on bearings and bottom flange of girders

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 7 of 13



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3399	0030	TYPE 5 AGGREGATE FOR BASE	Material		2	Jul 16, 2021	SYSTEM	\$27,260.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lamonr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 16, 2021	SYSTEM	(\$27,260.10)	
					3	Aug 2, 2021	SYSTEM	\$27,260.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user lamonr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$27,260.10)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0030 -	Total						\$0.00	
	0040	MISC.	Material		2	Jul 16, 2021	SYSTEM	\$16,557.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 16, 2021	SYSTEM	(\$16,557.99)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
	0040 -	Total						\$0.00	
	0110	CMS WITH COMMUNICATION INTERFACE,	Overrun	Overrun		Oct 1, 2021	SYSTEM	(\$5,348.00)	
		CONT É			14	Mar 16, 2022	SYSTEM	\$5,348.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2674.00000 - 2674.00000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0110 -	Total						\$0.00	
	0155	PAVEMENT EDGE TREATMENT	Material		14	Mar 16, 2022	SYSTEM	\$424.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Mar 16, 2022	SYSTEM	(\$424.50)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
	0155 -	Total						\$0.00	
	0160	4 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		7	Oct 1, 2021	SYSTEM	\$1,442.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lamonr overridding Payment Estimate Exception 1 on the current Payment Estimate.
		FAINT			7	Oct 1, 2021	SYSTEM	(\$1,442.80)	
					8	Oct 18, 2021	SYSTEM	\$1,442.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$1,442.80)	
					9	Nov 2, 2021	SYSTEM	(\$1,442.80)	
					10	Nov 16, 2021	SYSTEM	(\$1,442.80)	
					11	Dec 2, 2021	SYSTEM	(\$1,442.80)	
					12	Dec 16, 2021	SYSTEM	(\$1,442.80)	
				- Total				(\$5,771.20)	
			Material - Tota	ı				(\$5,771.20)	
			MaterialCredit		10	Nov 16, 2021	SYSTEM	\$1,442.80	
					11	Dec 2, 2021	SYSTEM	\$1,442.80	
					12	Dec 16, 2021	SYSTEM	\$1,442.80	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5P3399	0160	4 IN. YELLOW HIGH BUILD	MaterialCredit		13	Jan 3, 2022	SYSTEM	\$1,442.80	
		WATERBORNE PAINT		- Total				\$5,771.20	
			MaterialCredit	- Total				\$5,771.20	
			Overrun	Overrun	7	Oct 1, 2021	SYSTEM	\$369.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 1803.500; Overrun Quantity Balance 462.00.
					7	Oct 1, 2021	SYSTEM	(\$369.60)	
					8	Oct 18, 2021	SYSTEM	(\$369.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Oct 18, 2021	SYSTEM	\$369.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 1803.500; Overrun Quantity Balance 462.00.
					9	Nov 2, 2021	SYSTEM	(\$369.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Nov 2, 2021	SYSTEM	\$369.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 5 on the current Payment Estimate. Material Insufficiency Quantity 1803.500; Overrun Quantity Balance 462.00.
					10	Nov 16, 2021	SYSTEM	(\$369.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Nov 16, 2021	SYSTEM	\$369.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 8 on the current Payment Estimate. Material Insufficiency Quantity 1803.500; Overrun Quantity Balance 462.00.
					11	Dec 2, 2021	SYSTEM	(\$369.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					11	Dec 2, 2021	SYSTEM	\$369.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate. Material Insufficiency Quantity 1803.500; Overrun Quantity Balance 462.00.
					12	Dec 16, 2021	SYSTEM	(\$369.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					12	Dec 16, 2021	SYSTEM	\$369.60	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 4 on the current Payment Estimate, Material Insufficiency Quantity 1803.500; Overrun Quantity Balance 462.00.
					13	Jan 3, 2022	SYSTEM	(\$369.60)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					13	Jan 3, 2022	SYSTEM	(\$3,556.80)	
					14	Mar 16, 2022	SYSTEM	\$3,926.40	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.80000 - 0.80000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0160 -	Total						\$0.00	
	0170	6 IN. WHITE HIGH BUILD WATERBORNE	Overrun	Overrun	7	Oct 1, 2021	SYSTEM	(\$1,277.10)	
		PAINT			13	Jan 3, 2022	SYSTEM	(\$4,601.86)	
					14	Mar 16, 2022	SYSTEM	\$5,878.96	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.86000 - 0.86000, 'is applied (if non-zero).
				Overrun - To	Overrun - Total			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0170 -	Total						\$0.00	
	0180	PAVEMENT MARKING	Overrun	Overrun	7	Oct 1, 2021	SYSTEM	(\$6,102.40)	
		REMOVAL			10	Nov 16, 2021	SYSTEM	(\$4,119.04)	
					11	Dec 2, 2021	SYSTEM	(\$1,621.12)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
99	0180	PAVEMENT MARKING REMOVAL	Overrun	Overrun	13	Jan 3, 2022	SYSTEM	(\$11,403.52)	
					14	Mar 16, 2022	SYSTEM	\$23,246.08	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.64000 - 0.64000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0180 -	Total						\$0.00	
	0190	4 IN TEMPORARY PAVEMENT MARKING PAINT	Material		2	Jul 16, 2021	SYSTEM	\$6,326.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jul 16, 2021	SYSTEM	(\$6,326.08)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun	5	Sep 1, 2021	SYSTEM	\$2,788.86	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user lamonr overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 1, 2021	SYSTEM	(\$2,788.86)	
					6	Sep 16, 2021	SYSTEM	(\$2,788.86)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Oct 1, 2021	SYSTEM	(\$3,577.50)	G. 6160600 16 applied (i. 1161. 2516).
					10	Nov 16, 2021	SYSTEM	(\$5,433.56)	
					14	Mar 16, 2022	SYSTEM	\$11,799.92	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',0.53000 - 0.53000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Tota	 al				\$0.00	
	0190 -	Total						\$0.00	
ľ	0195	ROCK DITCH CHECK	Overrun	Overrun	7	Oct 1, 2021	SYSTEM	(\$2,046.00)	
					15	Jun 30,	SYSTEM	\$2,046.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.50000 - 15.50000, 'is
						2022			
				Overrun - To	otal	2022		\$0.00	applied (if non-zero).
			Overrun - Tota	Overrun - To	otal	2022		\$0.00 \$0.00	
	0195 -	Total	Overrun - Tota		otal	2022		\$0.00	
	0195 - 0198	Total SILT FENCE			otal 2	Jul 16, 2021	SYSTEM		
						Jul 16,		\$0.00 \$0.00	applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment
					2	Jul 16, 2021	SYSTEM	\$0.00 \$0.00 \$1,750.00	applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment
				al - Total	2	Jul 16, 2021	SYSTEM	\$0.00 \$0.00 \$1,750.00 (\$1,750.00)	applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment
	0198	SILT FENCE	Material	al - Total	2	Jul 16, 2021	SYSTEM	\$0.00 \$0.00 \$1,750.00 (\$1,750.00)	applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment
	0198	SILT FENCE	Material	al - Total	2	Jul 16, 2021	SYSTEM	\$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$0.00	applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment
	0198	SILT FENCE	Material Material - Tota	al - Total	2	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM	\$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$0.00 \$0.00	applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment
	0198	SILT FENCE	Material Material - Tota	al - Total	2 2 2	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	\$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$0.00 \$0.00 \$3,430.00	applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment
	0198	SILT FENCE	Material Material - Tota	al - Total	2 2 2 2	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$0.00 \$0.00 \$3,430.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment
	0198	SILT FENCE	Material Material - Tota	al - Total	2 2 2 3	Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,750.00 (\$1,750.00) \$0.00 \$0.00 \$3,430.00 (\$3,430.00) \$6,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J5P3399	0210	MISC. REMOVALS	Material		5	Sep 1, 2021	SYSTEM	\$10,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					5	Sep 1, 2021	SYSTEM	(\$10,290.00)		
					6	Sep 16, 2021	SYSTEM	\$6,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					6	Sep 16, 2021	SYSTEM	(\$6,860.00)		
					7	Oct 1, 2021	SYSTEM	\$6,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					7	Oct 1, 2021	SYSTEM	(\$6,860.00)		
					8	Oct 18, 2021	SYSTEM	\$6,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lamonr overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					8	Oct 18, 2021	SYSTEM	(\$6,860.00)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0210	- Total						\$0.00		
	0220	CLASS B-2 CONCRETE	Material		4	Aug 16, 2021	SYSTEM	\$18,268.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user lamonr overridding Payment Estimate Exception 1 on the current Payment Estimate.	
						4	Aug 16, 2021	SYSTEM	(\$18,268.20)	
					5	Sep 1, 2021	SYSTEM	\$27,402.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lamonr overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					5	Sep 1, 2021	SYSTEM	(\$27,402.30)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
		- Total						\$0.00		
	0320	MISC. REMOVALS	Material		10	Nov 16,	SYSTEM	\$10,062.00	This adjustment offsets the original system-generated Material Payment	
						2021			Estimate Item Adjustment (0006) due to user lamonr overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					10	Nov 16, 2021	SYSTEM	(\$10,062.00)		
					10	Nov 16,				
						Nov 16, 2021 Dec 2,	SYSTEM SYSTEM	(\$10,062.00)	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment	
					11	Nov 16, 2021 Dec 2, 2021	SYSTEM SYSTEM	(\$10,062.00) \$10,062.00	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment	
					11	Nov 16, 2021 Dec 2, 2021 Dec 2, 2021 Dec 16,	SYSTEM SYSTEM	(\$10,062.00) \$10,062.00 (\$10,062.00)	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment	
					11 11 12	Nov 16, 2021 Dec 2, 2021 Dec 2, 2021 Dec 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,062.00) \$10,062.00 (\$10,062.00) \$20,124.00	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment	
					11 11 12	Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,062.00) \$10,062.00 (\$10,062.00) \$20,124.00 (\$20,124.00)	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment	
					11 11 12 12 13	Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,062.00) \$10,062.00 (\$10,062.00) \$20,124.00 (\$20,124.00) \$20,124.00	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment	
					11 11 12 12 13 13 13	Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Mar 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,062.00) \$10,062.00 (\$10,062.00) \$20,124.00 (\$20,124.00) \$20,124.00 (\$20,124.00)	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment	
				- Total	11 11 12 12 13 13 14	Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Mar 16, 2022 Mar 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,062.00) \$10,062.00 (\$10,062.00) \$20,124.00 (\$20,124.00) \$20,124.00 (\$20,124.00) \$20,124.00	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment	
			Material - Tota		11 11 12 12 13 13 14	Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Mar 16, 2022 Mar 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,062.00) \$10,062.00 (\$10,062.00) \$20,124.00 (\$20,124.00) \$20,124.00 (\$20,124.00) \$20,124.00 (\$20,124.00)	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment	
	0320	·Total	Material - Tota		11 11 12 12 13 13 14	Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Mar 16, 2022 Mar 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,062.00) \$10,062.00) (\$10,062.00) \$20,124.00 (\$20,124.00) \$20,124.00 (\$20,124.00) \$20,124.00 (\$20,124.00)	Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment	



5 .		5	A 11	6			0		
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3399	0330	CONCRETE	Material	7,		2021			Estimate Item Adjustment (0007) due to user lamonr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$26,485.90)	
					11	Dec 2, 2021	SYSTEM	\$26,485.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user lamonr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$26,485.90)	
					12	Dec 16, 2021	SYSTEM	\$52,971.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$52,971.80)	,
					13	Jan 3, 2022	SYSTEM	\$52,971.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$52,971.80)	
					14	Mar 16, 2022	SYSTEM	\$52,971.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Mar 16, 2022	SYSTEM	(\$52,971.80)	Estimate Exception 4 on the editority dynamic Estimate.
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0330 -	Total						\$0.00	
	0350	PROTECTIVE COATING - CONCRETE BENTS AND	Material		9	Nov 2, 2021	SYSTEM	\$4,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$4,280.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0350 -	Total						\$0.00	
	0360	REHABILITATE BEARING			9	Nov 2, 2021	SYSTEM	\$31,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user lamonr overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$31,200.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0360 -	Total						\$0.00	
	0380	FIELD APPLICATION OF INORGANIC ZINC	Material		8	Oct 18, 2021	SYSTEM	\$5,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user lamonr overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Oct 18, 2021	SYSTEM	(\$5,400.00)	
					9	Nov 2, 2021	SYSTEM	\$5,124.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user lamonr overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$5,124.35)	
				- Total				\$0.00	
			Material - Tota	l e				\$0.00	
	0380 -	Total						\$0.00	
	5001	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		14	Mar 16, 2022	SYSTEM	\$8,554.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Mar 16, 2022	SYSTEM	(\$8,554.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	

Jul 6, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3399	5001 -	· Total						\$0.00	
	5002	TUBULAR MARKER	Material		14	Mar 16, 2022	SYSTEM	\$20,124.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Mar 16, 2022	SYSTEM	(\$20,124.00)	
				- Total				\$0.00	
			Material - Tota	l e				\$0.00	
	5002 -	· Total						\$0.00	
J5P3399	Total							\$0.00	
Overall -	Total							\$0.00	