

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 15, 2021

Progress Estimate Number	Contract ID	210122-H05	Pay Period Start	November 2, 2021	Original Contract Amount	\$2,798,726.11
14	Prime Contractor	N.B. West Contracting Company	Pay Period End	November 15, 2021	Net Change Order Amount Current Contract Amount	\$57,077.89 \$2,855,804,00
					Carront Contract / another	Ψ2,000,001.00

Approval Date		By User
November 15, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	REEDV1
November 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	dowdyd
November 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
September 30, 2021	October 11, 2021	October 8, 2021	96.03%

	Contract Informational Dat	tes	Milestones
Date Description	No Milestones Exist for Contract		
Acceptance Date			
Awarded Date	February 3, 2021	February 3, 2021	
Letting Date	January 22, 2021	January 22, 2021	
Notice to Proceed Date	April 5, 2021	April 5, 2021	
Work Began Date			

Contract Total Pa	y For Estimate No. 14				
		This Estimate	Previous	To Date	
210122-H05					
	Total Posted Items Pay	\$0.00	\$2,742,542.57	\$2,742,542.57	
	Gross Item Adjustments	\$0.00	\$96,630.88	\$96,630.88	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$2,839,173.45	\$2,839,173.45	
Contract Total Pa	yable This Estimate:	\$0.00			

#### Items Paid This Estimate Period

No Data Available

#### Contract Adjustments This Estimate

		tments Exist on Contract nents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3340	0075	MISC.	Material			-1,759.31	\$47.10	(\$82,863.50)
	0075	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,759.31	\$47.10	\$82,863.50
Total								\$0.00

Revision 4/1/2020 Page 1 of 13



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Co	ntract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9S3340	FAS S702(59)	Pavement and shoulder improvements	J	MADISON	from Rte. 72 to Rte. 51		
Γotals by J	Job Numbe	ers					
J9S3340					This Estimate	Previous	To Date
		d Item Pay			\$0.00	\$2,742,542.57	\$2,742,542.57
	Gross	Item Adjustme			\$0.00	\$96,630.88	\$96,630.88
			Gross I	Item Pay	\$0.00	\$2,839,173.45	\$2,839,173.45
	Incent	tive			\$0.00	\$0.00	\$0.00
		centive			\$0.00	\$0.00	\$0.00
	Liquid	dated Damages			\$0.00	\$0.00	\$0.00
	Other	<b>Contract Adjus</b>	tments		\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 2 of 13



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3340, Item 4019910, Project Item Line Number 0075, Material Set 401991096, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	Still waiting on the Rap AC QA and Rap QA test to be entered.	REEDV1	Overridden
Estimate Exception Type: Item Overrun: Contract 210122-H05, Contract Project J9S3340, Project Item Line Number 0340, Contract Line Item Number 0340, Item 8061005, Minor Item.	This is for the Type 2 Rock Ditch checks, this will be resolved when change order 005 is approved.	REEDV1	Overridden

Revision 4/1/2020 Page 3 of 13



## Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Project Category Line Item Description Bild Net Total Unit Total Unit Price Total Value POSTED

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210122-H05	J9S3340	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$32,650.00	\$32,650.00
		0001	0020	2063500	CULVERT CLEANOUT	2.00	0.00	2.00	EA	2.00	\$1,000.00	\$2,000.00
		0001	0030	2129900	MISC.MISC. SHOULDER GRADING	1,873.00	0.00	1,873.00	100F	1,873.00	\$298.50	\$559,090.50
		0001	0040	3049907	MISC.TYPE 1 AGGREGATE FOR BASE	210.00	-45.60	164.40	CUYD	164.40	\$25.50	\$4,192.20
		0001	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	194.00	510.00	704.00	TONS	703.81	\$58.50	\$41,172.88
		0001	0060	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	93.70	-17.70	76.00	TONS	76.00	\$201.25	\$15,295.00
		0001	0075	4019910	MISC.OPTIONAL SHOULDER	10,802.90	-43.59	10,759.31	TONS	10,759.31	\$47.10	\$506,763.50
		0001	0800	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	17,460.10	-21.90	17,438.20	TONS	17,438.20	\$49.70	\$866,678.54
		0001	0090	4071005	TACK COAT	21,212.00	-519.50	20,692.50	GAL	16,017.00	\$1.97	\$31,553.49
		0001	0095	6044011	PIPE COLLAR, TYPE A	18.00	-1.00	17.00	EA	17.00	\$825.00	\$14,025.00
		0001	0100	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	200.00	0.00	200.00	CUYD	93.00	\$31.00	\$2,883.00
		0001	0110	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	312.00	0.00	312.00	CUYD	66.00	\$31.00	\$2,046.00
		0001	0120	6096041	PLACING TYPE 1 ROCK DITCH LINER	200.00	0.00	200.00	CUYD	93.00	\$39.00	\$3,627.00
		0001	0130	6096042	PLACING TYPE 2 ROCK DITCH LINER	353.00	0.00	353.00	CUYD	66.00	\$39.00	\$2,574.00
		0001	0140	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0150	6161005	CONSTRUCTION SIGNS	1,825.00	0.00	1,825.00	SQFT	1,615.00	\$6.50	\$10,497.50
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	50.00	\$20.00	\$1,000.00
		0001	0170	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$10.00	\$0.00
		0001	0180	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,200.00	\$4,400.00
		0001	0190	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$306,150.00	\$306,150.00
		0001	0200	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0210	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	188,306.00	0.00	188,306.00	LF	150,645.00	\$0.11	\$16,570.95
		0001	0220	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	171,517.00	0.00	171,517.00	LF	169,339.00	\$0.11	\$18,627.29
		0001	0225	6214600A	FLOWABLE BACKFILL	3.00	1.50	4.50	CUYD	4.50	\$335.00	\$1,507.50
		0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,771.00	-1,023.00	748.00	SQYD	747.20	\$4.50	\$3,362.40
		0001	0240	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,867.70	0.00	1,867.70	STA	1,545.40	\$11.00	\$16,999.40
		0001	0250	7034041	CLASS B-1 CONCRETE (CULVERTS)	3.20	-0.40	2.80	CUYD	2.80	\$4,450.00	\$12,460.00
		0001	0260	7250312A	12 IN. PIPE GROUP B	51.00	-51.00	0.00	LF	0.00	\$105.00	\$0.00
		0001	0270	7250315A	15 IN. PIPE GROUP B	146.00	260.00	406.00	LF	406.00	\$107.00	\$43,442.00
		0001	0280	7250318A	18 IN. PIPE GROUP B	301.00	157.00	458.00	LF	458.00	\$111.75	\$51,181.50
		0001	0290	7250324A	24 IN. PIPE GROUP B	120.00	-30.00	90.00	LF	90.00	\$118.50	\$10,665.00
		0001	0300	7250336A	36 IN. PIPE GROUP B	43.00	0.00	43.00	LF	43.00	\$137.00	\$5,891.00
		0001	0310	7350001	PIPE LINER FOR EXISTING CULVERT	48.00	56.00	104.00	LF	104.00	\$114.00	\$11,856.00
		0001	0320	8051000A	SEEDING - COOL SEASON MIXTURES	43.20	0.00	43.20	ACRE	27.49	\$2,000.00	\$54,980.00
		0001	0325	8061017	TEMPORARY SEEDING AND MULCHING	5.00	0.00	5.00	ACRE	0.00	\$1,900.00	\$0.00
		0001	0330	8061004	SEDIMENT TRAP ROCK	259.00	0.00	259.00	CUYD	70.00	\$68.00	\$4,760.00
		0001	0340	8061005	ROCK DITCH CHECK	5,350.00	0.00	5,350.00	LF	5,456.15	\$12.75	\$69,565.91
		0001	0350	8061006	ALTERNATE DITCH CHECK	200.00	0.00	200.00	LF	0.00	\$14.25	\$0.00
		0001	0360	8061016	SEDIMENT REMOVAL	1,119.00	0.00	1,119.00	CUYD	207.50	\$2.00	\$415.00
		0001	0370	8061019	SILT FENCE	4,636.00	0.00	4,636.00	LF	1,860.00	\$2.30	\$4,278.00
		0040	0380	9031260	WOOD POST, 4 IN. BY 4 IN.	120.00	0.00	120.00	LF	0.00	\$15.00	\$0.00
		0040	0390		2 IN. PSST POST - 12 GA.	152.00	0.00	152.00	LF	152.00	\$24.00	\$3,648.00
		0040	0400	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	72.00	0.00	72.00	LF	72.00	\$40.00	\$2,880.00
		0040	0410		SHF-FLAT SHEET FLUORESCENT	72.00	0.00	72.00	SQFT	72.00	\$36.00	\$2,592.00
210122-H05 Ovo					late as of Report Generated Date							\$2,743,280.57 \$2,743,280.57
Davidia - 4/4/000		- ulue FUSI	ou to Da	to as or iteh	STATE OF THE STATE							VZ,140,200.37

Revision 4/1/2020 Page 4 of 13



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

The info	rmation	below this	line are details for	Construction Sign	ns (if applicable	<u>).</u>							
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Info	rmation	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9S3340	0150	October 5, 2021	1615	WO20-1 48x48 16 ROAD/BRIDGE/RAM			.598	Right	1.00	16			16
				WO8-11 48x48 16	6.00 UNEVEN		0.000	Left	1.00	16			16
				WO8-12 48x48 16	6.00 NO CENTER		0.000	Right	1.00	16			16
				WO8-15 48x48 16 PAVEMENT	3.00 GROOVED		0.000	Right	1.00	16			16
				WO20-1 48x48 16 ROAD/BRIDGE/RAM			0.000	Right	1.00	16			16
				GO20-4 36x18 4. FOLLOW ME	.50 PILOT CAR		0.000	Left	1.00	4.5			4.5
				WO8-15p 30x24 5 MOTORCYCLE (PLA			0.000	Right	1.00	5			5
				GO20-4a 42x30 8 FOR PILOT CAR	3.75 PLEASE WAIT		0.000	Left	1.00	8.75			8.75
				WO20-1 48x48 16 ROAD/BRIDGE/RAM			0.028	Left	1.00	16			16
				GO20-2 48x24 8. WORK	.00 END ROAD		0.028	Right	1.00	8			8
				CONST-7 48x24 8 WORK ZONE	8.00 RATE OUR		0.028	Right	1.00	8			8
				WO3-4 8x48 16. PREPARED TO STO			0.075	Left	1.00	16			16
				GO20-1 60x24 10 NEXT XX MILES	0.00 ROAD WORK		0.123	Right	1.00	10			10
				WO20-4 48x48 16 ROAD AHEAD	3.00 ONE LANE		0.123	Right	1.00	16			16
				CONST-8 48x36 1 ZONE NO PHONE ZO			0.218	Right	1.00	12			12
				WO20-7 48x48 16 (SYMBOL) WITH FLA			0.218	Left	1.00	16			16
				WO21-5 48x48 16 WORK AHEAD	3.00 SHOULDER		0.315	Left	1.00	16			16
				WO5-1 48x48 16 ROAD/BRIDGE/RAM			0.568	Right	1.00	16			16
				WO5-1 48x48 16 ROAD/BRIDGE/RAM			0.588	Left	1.00	16			16
				WO20-1 48x48 16 ROAD/BRIDGE/RAM			0.598	Right	1.00	16			16
				WO8-15 48x48 16 PAVEMENT	6.00 GROOVED		0.825	Right	1.00	16			16
				WO8-15p 30x24 5 MOTORCYCLE (PLA			0.825	Right	1.00	5			5
				GO20-4a 42x30 8 FOR PILOT CAR	3.75 PLEASE WAIT		0.825	Left	1.00	8.75			8.75
				WO8-11 48x48 16 LANES	6.00 UNEVEN		1.000	Right	1.00	16			16
				WO8-12 48x48 16 LINE	6.00 NO CENTER		1.000	Left	1.00	16			16
				WO20-1 48x48 16 ROAD/BRIDGE/RAM			1.028	Left	1.00	16			16
				WO3-4 8x48 16. PREPARED TO STO			1.075	Right	1.00	16			16
				WO20-4 48x48 16 ROAD AHEAD	6.00 ONE LANE		1.123	Right	1.00	16			16
				WO20-7 48x48 16 (SYMBOL) WITH FLA			1.218	Right	1.00	16			16
				WO21-5 48x48 16 WORK AHEAD	6.00 SHOULDER		1.3189	Right	1.00	16			16
				WO8-11 48x48 16 LANES	6.00 UNEVEN		10.000	Left	1.00	16			16
				WO8-12 48x48 16 LINE	6.00 NO CENTER		10.000	Right	1.00	16			16
	4/4/0000												

Revision 4/1/2020 Page 5 of 13



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign In	formation	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post											
9S3340	0150	October 5, 2021	1615	WO8-11 48x48 LANES	16.00 UNEVEN		11.000	Right	1.00	16	Sigil	Special Sign	10 F051											
		3, 2021			16.00 NO CENTER		11.000	Left	1.00	16			1											
					16.00 UNEVEN		12.000	Left	1.00	16			1											
					16.00 NO CENTER		12.000	Right	1.00	16			1											
				WO20-7 48x48	16.00 FLAGGER		12.411	Left	1.00	16			1											
				(SYMBOL) WITH F WO20-7 48x48 (SYMBOL) WITH F	16.00 FLAGGER		12.411	Right	1.00	16														
				, ,	16.00 BUMP		12.928	Left	1.00	16														
					16.00 BUMP		12.928	Right	1.00	16														
				WO8-11 48x48 LANES	16.00 UNEVEN		13.000	Right	1.00	16														
				WO8-12 48x48 LINE	16.00 NO CENTER		13.000	Left	1.00	16														
				WO8-15 48x48 PAVEMENT	16.00 GROOVED		13.219	Right	1.00	16														
				WO8-15p 30x24 MOTORCYCLE (PI			13.219	Right	1.00	5														
				GO20-4a 42x30 FOR PILOT CAR	8.75 PLEASE WAIT		13.219	Left	1.00	8.75			8.											
				WO8-15 48x48 PAVEMENT	16.00 GROOVED		13.368	Right	1.00	16														
				WO8-15p 30x24 MOTORCYCLE (PI			13.368	Right	1.00	5														
				GO20-4a 42x30 FOR PILOT CAR	8.75 PLEASE WAIT		13.368	Left	1.00	8.75			8											
				WO8-11 48x48 LANES	16.00 UNEVEN		14.000	Left	1.00	16														
				WO8-12 48x48 LINE	16.00 NO CENTER		14.000	Right	1.00	16														
								WO8-1 48x48	16.00 BUMP		14.535	Left	1.00	16										
															WO8-1 48x48	16.00 BUMP		14.535	Right	1.00	16			
															WO8-11 48x48 LANES	16.00 UNEVEN		15.000	Right	1.00	16			
				WO8-12 48x48 LINE	16.00 NO CENTER		15.000	Left	1.00	16														
				GO20-4a 42x30 FOR PILOT CAR	8.75 PLEASE WAIT		15.90	Left	1.00	8.75			8											
				WO8-15 48x48 PAVEMENT	16.00 GROOVED		15.900	Right	1.00	16														
				WO8-15p 30x24 MOTORCYCLE (PI			15.900	Right	1.00	5														
				WO8-11 48x48 LANES	16.00 UNEVEN		16.000	Left	1.00	16														
											WO8-15 48x48 PAVEMENT	16.00 GROOVED		16.000	Right	1.00	16							
					CONST-7 48x24 WORK ZONE	8.00 RATE OUR		17804	Left	1.00	8													
						V L V		WO8-11 48x48 LANES	16.00 UNEVEN		17.000	Right	1.00	16										
							WO8-15 48x48 PAVEMENT	16.00 GROOVED		17.000	Left	1.00	16											
				CONST-8 48x36 ZONE NO PHONE			17.614	Left	1.00	12														
				GO20-1 60x24 NEXT XX MILES	10.00 ROAD WORK		17.709	Left	1.00	10														
				GO20-2 48x24 WORK	8.00 END ROAD		17.804	Left	1.00	8														

Revision 4/1/2020 Page 6 of 13



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post				
S3340	0150	October 5, 2021	1615	WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		17.823	Left	1.00	16			1				
				GO20-4 36x18 4.50 PILOT CAR FOLLOW ME		17.823	Right	1.00	4.5			4.				
				WO8-11 48x48 16.00 UNEVEN LANES		17.832	Left	1.00	16			1				
				WO8-15 48x48 16.00 GROOVED PAVEMENT		17.832	Left	1.00	16			1				
				WO8-15 48x48 16.00 GROOVED PAVEMENT		17.832	Right	1.00	16			1				
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		17.832	Left	1.00	5							
				GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		17.832	Left	1.00	8.75			8.7				
				WO8-11 48x48 16.00 UNEVEN LANES		2.000	Left	1.00	16							
				WO8-12 48x48 16.00 NO CENTER LINE		2.000	Right	1.00	16			1				
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		2.028	Right	1.00	16							
				WO3-4 8x48 16.00 BE PREPARED TO STOP		2.075	Left	1.00	16							
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		2.123	Left	1.00	16							
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS		2.218	Left	1.00	16							
				WO8-1 48x48 16.00 BUMP		2.681	Left	1.00	16							
				WO8-1 48x48 16.00 BUMP		2.681	Right	1.00	16							
				WO8-11 48x48 16.00 UNEVEN LANES		3.000	Right	1.00	16							
				WO8-12 48x48 16.00 NO CENTER LINE		3.000	Left	1.00	16							
				WO8-12 48x48 16.00 NO CENTER LINE		3.028	Right	1.00	16							
				WO3-4 8x48 16.00 BE PREPARED TO STOP		3.075	Right	1.00	16							
								WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		3.123	Right	1.00	16			
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS		3.218	Right	1.00	16							
				WO8-11 48x48 16.00 UNEVEN LANES		4.000	Left	1.00	16							
				WO8-12 48x48 16.00 NO CENTER LINE		4.000	Right	1.00	16							
				WO8-15 48x48 16.00 GROOVED PAVEMENT		4.375	Right	1.00	16							
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		4.375	Right	1.00	5							
				GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		4.375	Left	1.00	8.75			8.				
				WO8-15 48x48 16.00 GROOVED PAVEMENT		4.475	Right	1.00	16							
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		4.475	Right	1.00	5							
								GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		4.475	Left	1.00	8.75			8.
				WO8-1 48x48 16.00 BUMP		4.888	Left	1.00	16							
				WO8-1 48x48 16.00 BUMP		4.888	Right	1.00	16							
				WO8-11 48x48 16.00 UNEVEN LANES		5.000	Right	1.00	16							
				WO8-12 48x48 16.00 NO CENTER LINE		5.000	Left	1.00	16							

Revision 4/1/2020 Page 7 of 13



The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

he info	rmation	below this	s line are details for	Construction Signs (if applicable	<u>e).</u>																
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post									
J9S3340	9S3340 0150	October 5, 2021	1615	WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS		5.487	Left	1.00	16			16									
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS		5.487	Right	1.00	16			16									
				WO8-15 48x48 16.00 GROOVED PAVEMENT		5.575	Right	1.00	16			16									
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		5.575	Right	1.00	5			5									
				GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		5.575	Left	1.00	8.75			8.75									
				WO8-11 48x48 16.00 UNEVEN LANES		6.000	Left	1.00	16			16									
				WO8-12 48x48 16.00 NO CENTER LINE		6.000	Right	1.00	16			16									
									WO8-15 48x48 16.00 GROOVED PAVEMENT		6.95	Right	1.00	16			16				
										WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		6.95	Right	1.00	5			5			
											GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		6.950	Left	1.00	8.75			8.75		
					WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		6.975	Right	1.00	16			16								
				WO8-11 48x48 16.00 UNEVEN LANES		7.000	Right	1.00	16			16									
							WO8-12 48x48 16.00 NO CENTER LINE		7.000	Left	1.00	16			16						
													WO8-11 48x48 16.00 UNEVEN LANES		8.000	Left	1.00	16			16
																	WO8-12 48x48 16.00 NO CENTER LINE		8.000	Right	1.00
				WO8-1 48x48 16.00 BUMP		8.812	Left	1.00	16			16									
				WO8-1 48x48 16.00 BUMP		8.812	Right	1.00	16			16									
				WO8-11 48x48 16.00 UNEVEN LANES		9.000	Right	1.00	16			16									
				WO8-12 48x48 16.00 NO CENTER LINE		9.000	Left	1.00	16			16									
	0150 - To	otal										1614.5									

Revision 4/1/2020 Page 8 of 13



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3340	0040	MISC. AGGREGATE FOR BASE	Material		3	Jun 2, 2021	SYSTEM	\$3,340.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jun 2, 2021	SYSTEM	(\$3,340.50)	
					4	Jun 16, 2021	SYSTEM	\$4,192.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 16, 2021	SYSTEM	(\$4,192.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0040 -	Total						\$0.00	
	0050	GRAVEL (A) OR CRUSHED STONE (B)	Material		3	Jun 2, 2021	SYSTEM	\$5,686.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jun 2, 2021	SYSTEM	(\$5,686.20)	
					4	Jun 16, 2021	SYSTEM	\$10,845.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Jun 16, 2021	SYSTEM	(\$10,845.90)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	10	Sep 16, 2021	SYSTEM	(\$2,138.76)	
					11	Oct 1, 2021	SYSTEM	\$19,745.51	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Oct 1, 2021	SYSTEM	\$7,939.62	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user reedv1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Oct 1, 2021	SYSTEM	(\$27,685.13)	
					12	Oct 18, 2021	SYSTEM	(\$27,685.13)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					12	Oct 18, 2021	SYSTEM	\$27,685.13	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Nov 2, 2021	SYSTEM	\$2,138.76	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',58.50000 - 58.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0050 -	Total						\$0.00	
	0075	MISC.	Material		9	Sep 1, 2021	SYSTEM	\$82,863.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Sep 1, 2021	SYSTEM	(\$82,863.50)	
					10	Sep 16, 2021	SYSTEM	\$82,863.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 16, 2021	SYSTEM	(\$82,863.50)	
					11	Oct 1, 2021	SYSTEM	\$82,863.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Oct 1, 2021	SYSTEM	(\$82,863.50)	
					12	Oct 18, 2021	SYSTEM	\$82,863.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Property   1										
13   Nov.2   2011	Project	Line	Description		Adjustment				Amount	Remarks
2021	J9S3340	0075	MISC.	Material		12		SYSTEM	(\$82,863.50)	
14   Nov 16   2011   15   2011   15   2011   15   2011   15   2011   15   2011   15   2011   15   2011   15   2011   20						13		SYSTEM	\$82,863.50	Estimate Item Adjustment (0003) due to user reedv1 overridding Payment
ACAD - Total						13		SYSTEM	(\$82,863.50)	
Total						14		SYSTEM	\$82,863.50	Estimate Item Adjustment (0001) due to user reedv1 overridding Payment
Material - Total						14		SYSTEM	(\$82,863.50)	
Chies team					- Total				\$0.00	
Adjustment   2021				Material - To	otal				\$0.00	
Other Item Adjustment - Total					ACAD	9		REEDV1	\$35,061.90	the current factor is $4\overline{9}3.75$ for a difference of 98.75, the virgin AC is 4.0%% for this mix
					ACAD - Tot	al			\$35,061.90	
DRIVEN   D				Other Item	Adjustment -	Total			\$35,061.90	
PAYEMENT   MIXTURE   9   Sep 1,   SYSTEM   \$414,898.08		0075 -	Total						\$35,061.90	
Sep 1, SYSTEM   SVSTEM   SVS		0800	PAVEMENT MIXTURE	Material		9		SYSTEM	\$414,898.08	Estimate Item Adjustment (0005) due to user reedv1 overridding Payment
Material - Total			PG04-22 (SUR			9		SYSTEM	(\$414,898.08)	
Other Item   ACAD   9   Sep 1,   700   7					- Total				\$0.00	
Adjustment				Material - Total					\$0.00	
2021   2021						9		REEDV1	\$32,974.80	the current factor is 493.75 for a difference of 98.75, the virgin AC is 4.0%% for this mix
2021   31, the quantity was under reported by 93.71 tons and on 91/12021 the quantity was under reported by 156.43 tons. Asphalt laid in this period was adjusted based on an original factor of 395 with the current factor of 493.75 for a difference of 98.75 with a virgin AC of 496.   11						10		REEDV1	\$35,024.08	0010. There was 8756.02 tons of asphalt laid with a virgin AC of 4% and the original factor was 395 with the current factor being 495 for a difference of
2021   2021, the base factor was 395 and the current index was 495 for a difference of 100, the virgin AC was 4.0% 10/01/2021 Estimate 011						10		REEDV1	\$988.05	31, the quantity was under reported by 93.71 tons and on 9/1/2021 the quantity was under reported by 156.43 tons. Asphalt laid in this period was adjusted based on an original factor of 395 with the current factor of 493.75 for
Other Item Adjustment - Total  S69,322.89  O090 TACK COAT Material  9 Sep 1, 2021 SYSTEM \$13,730.90 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  9 Sep 1, 2021 SYSTEM (\$13,730.90)  - Total S0.00  Material - Total S0.00  O090 - Total S0.00  O095 PIPE COLLAR, TYPE A Material S221 SYSTEM \$13,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  2 May 17, SYSTEM (\$13,200.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.  2 May 17, SYSTEM (\$13,200.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payme						11		REEDV1	\$335.96	2021, the base factor was 395 and the current index was 495 for a dilfference
Sep 1, 2021   SYSTEM   \$13,730.90   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.					ACAD - Tota	al			\$69,322.89	
TACK COAT Material  9 Sep 1, 2021 \$\frac{1}{2021}\$ \$\frac				Other Item	Adjustment -	Total			\$69,322.89	
Sep 1, 2021   Estimate Item Adjustment (0006) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		0080 -	Total						\$69,322.89	
Total  So.00  Material - Total  So.00  PIPE COLLAR, TYPE A  Material  A  Discrete A  Discr		0090		Material		9		SYSTEM	\$13,730.90	Estimate Item Adjustment (0006) due to user reedv1 overridding Payment
Material - Total   \$0.00						9		SYSTEM	(\$13,730.90)	
Solution					- Total	- Total			\$0.00	
PIPE COLLAR, TYPE A  Material  2 May 17, 2021  SYSTEM \$13,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  Material  2 May 17, 2021  SYSTEM (\$13,200.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  3 Jun 2, SYSTEM (\$13,200.00)				Material - To	otal				\$0.00	
TYPE A  2021  Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  May 17, 2021  May 17, 2021  Jun 2, 2021  SYSTEM \$13,200.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  Jun 2, SYSTEM \$13,200.00)		0090 -	Total						\$0.00	
2021  3 Jun 2, 2021  \$13,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  3 Jun 2, SYSTEM (\$13,200.00)		0095		Material	erial	2		SYSTEM	\$13,200.00	Estimate Item Adjustment (0003) due to user reedv1 overridding Payment
Estimate Item Adjustment (0004) dué to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  3 Jun 2, SYSTEM (\$13,200.00)						2		SYSTEM	(\$13,200.00)	
						3		SYSTEM	\$13,200.00	Estimate Item Adjustment (0004) due to user reedv1 overridding Payment
						3		SYSTEM	(\$13,200.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9S3340	0095	PIPE COLLAR,	Material	- Total				\$0.00		
		TYPE A	Material - To	otal				\$0.00		
			Other Item Adjustment	OTHR	2	May 17, 2021	REEDV1	(\$13,200.00)	This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021	
					3	Jun 2, 2021	SYSTEM	\$13,200.00	This adjustment removes the pay for the Type A pipe collars due to the testing not being completed. The testing for the concrete should be completed around June 9, 2021	
				OTHR - Tota	il			\$0.00		
			Other Item	Adjustment -	Total			\$0.00		
	0095 -	Total						\$0.00		
	0150	CONSTRUCTION SIGNS	Material		1	May 3, 2021	SYSTEM	\$494.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					1	May 3, 2021	SYSTEM	(\$494.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
			Other Item Adjustment	OTHR	1	May 3, 2021	REEDV1	(\$494.00)	This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001 05/03/2021.	
					2	May 17, 2021	SYSTEM	\$494.00	This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001 05/03/2021.	
				OTHR - Tota	ıl			\$0.00		
			Other Item /	Adjustment -	Total			\$0.00		
	0150 -	Total						\$0.00		
	0180	CMS W/O COMMUNICATION INTERFACE, CONT F/	N <u>=</u> ,	Material		1	May 3, 2021	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	May 3, 2021	SYSTEM	(\$4,400.00)		
				- Total				\$0.00		
			Material - To					\$0.00		
			Other Item Adjustment	OTHR	1	May 3, 2021	REEDV1	(\$4,400.00)	This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001 05/03/2021.	
					2	May 17, 2021	SYSTEM	\$4,400.00	This adjustment is due to a missing certification for the sample 21SEVTR002, this adjustment will be reversed on a future estimate. Estimate 001 05/03/2021.	
				OTHR - Tota	il			\$0.00		
			Other Item /	Adjustment -	Total			\$0.00		
	0180 -	Total						\$0.00		
	0210	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		12	Oct 18, 2021	SYSTEM	\$16,570.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					12	Oct 18, 2021	SYSTEM	(\$16,570.95)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0210 -							\$0.00		
	0220	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Material		12	Oct 18, 2021	SYSTEM	\$18,627.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					12	Oct 18, 2021	SYSTEM	(\$18,627.29)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0220 -							\$0.00		
	0225	FLOWABLE BACKFILL	Overrun	Overrun	9	Sep 1, 2021	SYSTEM	(\$502.50)		



ject Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3340 0225	FLOWABLE BACKFILL	Overrun	Overrun	13	Nov 2, 2021	SYSTEM	\$502.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',335.00000 - 335.00000, 'is applied (if non-zero).
			Overrun - To	otal			\$0.00	
		Overrun - T	otal				\$0.00	
0225	- Total						\$0.00	
0250	CLASS B-1 CONCRETE (CULVERTS)	Material		4	Jun 16, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				4	Jun 16, 2021	SYSTEM	(\$12,460.00)	
				5	Jul 1, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user reedv1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				5	Jul 1, 2021	SYSTEM	(\$12,460.00)	
				9	Sep 1, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user reedv1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				9	Sep 1, 2021	SYSTEM	(\$12,460.00)	
				11	Oct 1, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				11	Oct 1, 2021	SYSTEM	(\$12,460.00)	
				12	Oct 18, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user reedv1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				12	Oct 18, 2021	SYSTEM	(\$12,460.00)	
				13	Nov 2, 2021	SYSTEM	\$12,460.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
				13	Nov 2, 2021	SYSTEM	(\$12,460.00)	
			- Total				\$0.00	
		Material - T	otal				\$0.00	
0250	- Total						\$0.00	
0270	15 IN. PIPE CULVERT GROUP B	Overrun	verrun Overrun	4	Jun 16, 2021	SYSTEM	(\$7,490.00)	
				9	Sep 1, 2021	SYSTEM	(\$12,198.00)	
				11	Oct 1, 2021	SYSTEM	\$19,688.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',107.00000 - 107.00000, 'is applied (if non-zero).
			Overrun - Total					
		Overrun - T	otal				\$0.00	
0270	- Total						\$0.00	
0280	18 IN. PIPE CULVERT GROUP B	Overrun	Overrun	9	Sep 1, 2021	SYSTEM	(\$5,475.75)	
	В			11	Oct 1, 2021	SYSTEM	\$5,475.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',111.75000 - 111.75000, 'is applied (if non-zero).
			Overrun - Total				\$0.00	
		Overrun - T	otal				\$0.00	
0280	- Total						\$0.00	
0320	SEEDING - COOL SEASON MIXTURES	Material		11	Oct 1, 2021	SYSTEM	\$44,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user reedv1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
				11	Oct 1,	SYSTEM	(\$44,000.00)	
					2021			

Nov 18, 2021



#### Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J9S3340	0320	SEEDING - COOL SEASON MIXTURES	Material			2021			Estimate Item Adjustment (0006) due to user reedv1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
		MIXTURES			12	Oct 18, 2021	SYSTEM	(\$54,980.00)		
				- Total				\$0.00		
			Material - To	otal				\$0.00		
	0320 -	Total						\$0.00		
	0330	SEDIMENT TRAP ROCK	Material		2	May 17, 2021	SYSTEM	\$2,516.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user reedv1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					2	May 17, 2021	SYSTEM	(\$2,516.00)		
				- Total						
			Material - To	otal				\$0.00		
	0330 - Total							\$0.00		
	0340	ROCK DITCH CHECK	Other Item Adjustment		OTHR	9	Sep 1, 2021	REEDV1	\$6,400.50	compensate the contractor when the rock ditch checks are removed. Estimate 009 20210901
					10	Sep 17, 2021	REEDV1	(\$12,801.00)	This removes an adjustment from Estimate 0009 that was made to hold pay until the contractor removed the rock ditch check on highway J, the original adjustment was positive in error and this adjustment corrects the original adjustment6400.50 to remove the original adjustment and -6400.50 to correct the adjustment to hold pay to provide compensation to the contractor once the rock ditch checks have been removed.	
				OTHR - Total						
			Other Item	Adjustment -	Total			(\$6,400.50)		
			Overrun	Overrun	10	Sep 16, 2021	SYSTEM	(\$1,353.41)		
				Overrun - Total				(\$1,353.41)		
			Overrun - Total					(\$1,353.41)		
	0340 -	Total						(\$7,753.91)		
J9S3340 -	- Total							\$96,630.88		
Overall -	Total							\$96,630.88		