

Pay Estimate Created Date: October 1, 2021

Progress Estimate I	Progress Estimate Number 10		210219-C04 or Ideker, Inc.	Pay Perio Pay Perio		September 16, September 30,	2021 <b>N</b>	riginal Contract Amount et Change Order Amount current Contract Amount	\$4,357,163.79 \$188,165.38 \$4,545,329.17
Approval Date									By User
October 1, 2021			Generated and	Approved (	and sho	uld be considered	d Draft) at	the Project Office Level by	warrem1
October 1, 2021		Re	eviewed and Appr	oved (and s	should be	e considered Dra	ft) at the l	Resident Engineer Level by	warrem1
October 4, 2021				Reviewed a	and App	roved at the Cent	tral Office	Controllers Office Level by	ramses1
Original Completion Date Current Co			mpletion Date Actual Completion Date			letion Date	%	nt Complete	
December 1, 202	21	Decembe	er 1, 2021		76.0			76.04%	
	Contract	Informational Dat	tes	es Milesto					
Date Description	Original	Completion Date	Current Comple	etion Date	No Milestones Exist for Contract				
Acceptance Date									
Awarded Date	March 3,	2021	March 3, 2021						
Letting Date	February	19, 2021	February 19, 202	21					
Notice to Proceed Date	May 3, 20	21	May 3, 2021						
Work Began Date									

Contract Total Pay	y For Estimate No. 10			
		This Estimate	Previous	To Date
210219-C04				
	Total Posted Items Pay	\$238,453.00	\$3,217,689.40	\$3,456,142.40
	Gross Item Adjustments	\$7,063.32	\$77,858.46	\$84,921.78
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	•		\$3,295,547.86	\$3,541,064.18
<b>Contract Total Pay</b>	/able This Estimate:	\$245,516.32		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J4P3275	0030	2031000	CLASS A EXCAVATION	CUYD	\$12.000	33	\$396.00			
	0120	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$10.500	100	\$1,050.00			
	0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$11.650	3,120	\$36,348.00			
	0150	4019905	MISC.OPTIONAL PAVEMENT	SQYD	\$45.490	3,120	\$141,928.80			
	0160	4019905	MISC.OPTIONAL TEMPORARY PAVEMENT	SQYD	\$28.490	100	\$2,849.00			
	0260	6091052	CURB AND GUTTER TYPE B	LF	\$29.900	238	\$7,116.20			
	0330	6122030	IMPACT ATTENUATOR (RELOCATION)	EA	\$400.000	1	\$400.00			
	0370	6161025	CHANNELIZER (TRIM LINE)	EA	\$23.000	30	\$690.00			
	0390	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	EA	\$4,900.000	3	\$14,700.00			
	0430	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	LF	\$13.000	2,474	\$32,162.00			
	0440	6175020A	RELOCATING TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	EA	\$400.000	2	\$800.00			
Project J4P3275 - Total										
J4S3278	1190	6161025	CHANNELIZER (TRIM LINE)	EA	\$1.000	13	\$13.00			
Project J4S3278 - Total										
Overall - Total										

# Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 42



Pay Estimate Created Date: October 1, 2021

Progress Estimate Number 10 Contract ID Prime Contractor Ideker, Inc. Pay Period Start September 16, 2021 Original Contract Amount September 30, 2021 Original Contract Amount Net Change Order Amount Current Contract Amount Current Contract Amount S4,357,163.79

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3275	0030	CLASS A EXCAVATION	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	33	\$0.10	\$3.37
	0040	EMBANKMENT IN PLACE	Material			-39,371	\$20.00	(\$787,420.00)
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	39,371	\$20.00	\$787,420.00
	0050	COMPACTING EMBANKMENT	Material			-839	\$2.00	(\$1,678.00)
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	839	\$2.00	\$1,678.00
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	100	\$0.08	\$7.65
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-5,262.2	\$10.50	(\$55,253.10)
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	5,262.2	\$10.50	\$55,253.10
	0130	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	3,120	\$0.12	\$365.98
	0130	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-7,205.1	\$11.65	(\$83,939.42)
	0130	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	7,205.1	\$11.65	\$83,939.42
	0150	MISC.	Material			-6,272.9	\$45.49	(\$285,354.22)
	0150	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	6,272.9	\$45.49	\$285,354.22
	0150	MISC.	Other Item Adjustment		3,120 SQYD of 10.25" SP190 21-13 with 3.10% Virgin AC			\$4,362.07
	0150	MISC.	Other Item Adjustment	Asphalt Cement Price Adjustment	3,120 SQYD of 1.75" SP125 21-14 with 3.4% Virgin AC.			\$816.82
	0160	MISC.	Overrun			-100	\$28.49	(\$2,849.00)
	0160	MISC.	Material			-4,721.5	\$28.49	(\$134,515.54)
C	0160	MISC.	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 42 on the current Payment Estimate. Material Insufficiency Quantity 4721.500; Overrun Quantity Balance 100.00.	100	\$28.49	\$2,849.00
	0160	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user schnod1	4,721.5	\$28.49	\$134,515.54

Revision 4/1/2020 Page 2 of 42



Pay Estimate Created Date: October 1, 2021

Progress Estimate Number					Original Contract Amount Net Change Order Amount	\$4,357,163.79 \$188,165,38
10	Trime Contractor	ideker, irio.	r ay r enou Liiu	Deptember 30, 2021	Current Contract Amount	\$4,545,329.17

Project umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
P3275					overridding Payment Estimate Exception 10 on the current Payment Estimate.			
	0160	MISC.	Other Item Adjustment	Asphalt Cement Price Adjustment	100.0 SQYD of 6.25" SP190 21-13 with 3.1% Virgin AC.			\$85.2
	0160	MISC.	Other Item Adjustment	Asphalt Cement Price Adjustment	100 SQYD of 1.75" SP125 21-14 with 3.4% Virgin AC.			\$26.1
	0160	MISC.	Other Item Adjustment	Overrun	Overrun/material adjustment.			(\$2,849.0
	0210	PAVED APPROACH, 8 IN.	Material			-189.8	\$62.70	(\$11,900.4
	0210	PAVED APPROACH, 8 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	189.8	\$62.70	\$11,900.46
	0240	CONCRETE GUTTER TYPE A	Material			-20	\$96.25	(\$1,925.00
	0240	CONCRETE GUTTER TYPE A	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.	20	\$96.25	\$1,925.00
	0260	CURB AND GUTTER TYPE B	Material			-919.4	\$29.90	(\$27,490.00
	0260	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	919.4	\$29.90	\$27,490.00
	0300	ROCK LINING	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-11	\$225.00	(\$2,475.0
	0320	REPLACEMENT SAND BARREL	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-4	\$330.00	(\$1,320.0
	0320	REPLACEMENT SAND BARREL	Other Item Adjustment	Overrun	Return of adjustment from estimate 0009.			\$1,320.0
	0480	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-1,748	\$1.00	(\$1,748.0
	0480	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material			-14,879	\$1.00	(\$14,879.0
	0480	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 45 on the current Payment Estimate. Material Insufficiency Quantity 14879.000; Overrun Quantity Balance 1748.00.	1,748	\$1.00	\$1,748.0
	0480	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	14,879	\$1.00	\$14,879.0
	0490	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material			-22,738	\$1.00	(\$22,738.0

Revision 4/1/2020 Page 3 of 42



Pay Estimate Created Date: October 1, 2021

\$4,357,163.79	Original Contract Amount	September 16, 2021	Pay Period Start	210219-C04	Contract ID	Progress Estimate Number
\$188,165.38 \$4.545.329.17	<b>9</b>	September 30, 2021	Pay Period End	Ideker, Inc.	Prime Contractor	10
	Current Contract Amount					10

								· · ·
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3275	0490	YELLOW TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	22,738	\$1.00	\$22,738.00
	0570	18 IN. PIPE GROUP C	Material			-14	\$100.00	(\$1,400.00
	0570	18 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	14	\$100.00	\$1,400.00
	0590	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material			-2	\$606.00	(\$1,212.00)
	0590	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	2	\$606.00	\$1,212.00
	0600	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material			-2	\$606.00	(\$1,212.00
	0600	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	2	\$606.00	\$1,212.00
	0640	ROCK DITCH CHECK	Other Item Adjustment	Overrun	Return of adjustment from estimate 0009.			\$6,720.00
	0650	ALTERNATE DITCH CHECK	Material			-100	\$13.00	(\$1,300.00
	0650	ALTERNATE DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	100	\$13.00	\$1,300.00
	0740	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material			-600	\$25.00	(\$15,000.00
	0740	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	600	\$25.00	\$15,000.00
	5002	PAVEMENT EDGE TREATMENT	Material			-370	\$7.10	(\$2,627.00
	5002	PAVEMENT EDGE TREATMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.	370	\$7.10	\$2,627.00
J4S3278	1120	GRAVEL (A)	Material			-118	\$87.92	(\$10,374.56
	1120	GRAVEL (A)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	118	\$87.92	\$10,374.56
	1150	3 IN. CONCRETE MEDIAN STRIP	Material			-11.3	\$298.60	(\$3,374.18)
Revision 4	/1/2020							Page 4 of

Revision 4/1/2020 Page 4 of 42

\$58.85 (\$139,327.38)

\$58.85 \$139,327.38

\$7,063.32

-2,367.5

2,367.5



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 1, 2021

1420

1420

Total

BITUMINOUS PAVEMENT

BITUMINOUS PAVEMENT

MIXTURE PG64-22 (SURFACE LEVELING)

MIXTURE PG64-22

(SURFACE LEVELING)

Material

Material

1 rogroco Ecumato Itamboi		Contract I Prime Cor	act ID 210219-C04 Contractor Ideker, Inc.		Pay Period End September 30, 2021 Net		Net Cha	t Change Order Amount		\$4,357,163.79 \$188,165.38 \$4,545,329.17	
Project Number	Line No.	Item Descrip	otion	Adjustment Type	Other Item Adjustmen Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3278	1150	3 IN. CONCRET	Material		generated I Adjustm overridding I	nent offsets the original Material Payment Estim ent (0003) due to user Payment Estimate Exce I the current Payment E	schnod1	11.3	\$298.60	\$3,374.18	
1	1320	12 IN. PIPE	GROUP C	Material					-50	\$54.00	(\$2,700.00)
	1320	12 IN. PIPE	GROUP C	Material		generated I Adjustm overridding I	nent offsets the original Material Payment Estim ent (0004) due to user Payment Estimate Exce I the current Payment E	nate Item schnod1 eption 36	50	\$54.00	\$2,700.00
	1330	18 IN. PIPE	GROUP C	Material					-50	\$65.00	(\$3,250.00)
	1330	18 IN. PIPE GROUP C		Material		generated I Adjustm overridding I	nent offsets the original Material Payment Estim ent (0005) due to user Payment Estimate Exce I the current Payment E	nate Item schnod1 eption 37	50	\$65.00	\$3,250.00

This adjustment offsets the original systemgenerated Material Payment Estimate Item

overridding Payment Estimate Exception 11 on the current Payment Estimate.

Adjustment (0006) due to user schnod1

Revision 4/1/2020 Page 5 of 42



					Co	ontract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4P3275	FAF 92-1(35)	Intersection improvements	92	PLATTE	at intersection of Rte. 45 Sp	pur	
J4S3278	FAS S302(80)	Resurface	45	PLATTE	from Route 92 to Route 45		
Totals by .	Job Numbe	rs					
J4P3275		Posted Item Pay Gross Item Adjustments Gross Item Pay			This Estimate \$238,440.00 \$7,063.32 <b>\$245,503.32</b>	Previous \$2,193,153.26 \$31,069.54 \$2,224,222.80	To Date \$2,431,593.26 \$38,132.86 \$2,469,726.12
	Disino Liquio	Incentive Disincentive Liquidated Damages Other Contract Adjustments			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00
J4S3278		Posted Item Pay Gross Item Adjustments Gross Item Pay		This Estimate \$13.00 \$0.00 <b>\$13.00</b>	Previous \$1,024,536.14 \$46,788.92 \$1,071,325.06	To Date \$1,024,549.14 \$46,788.92 \$1,071,338.06	
	Liquid	tive centive lated Damages Contract Adius	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 6 of 42



#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 3040504, Project Item Line Number 0120, Material Set 304050496, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 3040506, Project Item Line Number 0130, Material Set 304050696, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 3101002, Project Item Line Number 1120, Material Set 310100296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4019905, Project Item Line Number 0150, Material Set 401990596, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4019905, Project Item Line Number 0150, Material Set 401990596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4019905, Project Item Line Number 0150, Material Set 401990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4019905, Project Item Line Number 0150, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4019905, Project Item Line Number 0160, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4020520, Project Item Line Number 1420, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is Insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6061061, Project Item Line Number 0740, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1057JMFRPF - Preformed Fiber Expansion Joint Matl @, Acceptance Action Generic 1057JMFRPF is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6085008, Project Item Line Number 0210, Material Set 608500896, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 1005FACCNSCA - Natural Sand for Conc Class A,	No Remark was entered by Engineer	schnod1	Overridden

Revision 4/1/2020 Page 7 of 42



**Exceptions (Discrepancies) This Estimate Period** 

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 1005FACCNSCA is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091041, Project Item Line Number 0240, Material Set 609104196, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6091052, Project Item Line Number 0260, Material Set 609105296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6191000, Project Item Line Number 5002, Material Set 619100096, Material 0619PET - Material for Pavement Edge Treatment, Acceptance Action Generic 0619PET is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6205301B, Project Item Line Number 0480, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6205303B, Project Item Line Number 0490, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 7250412, Project Item Line Number 1320, Material Set 725041296, Material 1020CPCSZC.012 - CulvPipe Zn Ctd Corrug Stl 12" 300mm, Acceptance Action Generic 1020CPCSZC.012 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 7250418, Project Item Line Number 1330, Material Set 725041896, Material 1020CPCSZC.018 - CulvPipe Zn Ctd Corrug Stl 18" 450mm, Acceptance Action Generic 1020CPCSZC.018 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 7250418, Project Item Line Number 0570, Material Set 725041896, Material 1020CPCSZC.018 - CulvPipe Zn Ctd Corrug Stl 18" 450mm, Acceptance Action Generic 1020CPCSZC.018 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 7320618A, Project Item Line Number 0590, Material Set 7320618A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 7320818A, Project Item Line Number 0600, Material Set 7320818A96, Material 1020ESZN - Flared End Section Zinc galvanized steel, Acceptance Action Generic 1020ESZN is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 8061006, Project Item Line Number 0650, Material Set 806100696, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0160, Contract Line Item Number 0160, Item 4019905, Minor Item.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0300, Contract Line Item Number 0300, Item 6097000, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0320, Contract Line Item Number 0320, Item 6122020, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0480, Contract Line Item Number 0480, Item 6205301B, Minor Item.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4S3278, Project Item Line Number 1200, Contract Line Item Number 1200, Item 6161031, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0010, Contract Line Item Number 0010, Item 2013000, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0070, Contract Line Item Number 0070, Item 2071000, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0640, Contract Line Item Number 0640, Item 8061005, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged

Revision 4/1/2020 Page 8 of 42



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4P3275	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	3.00	\$9,000.00	\$27,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.80	\$69,665.00	\$55,732.00
		0001	0030	2031000	CLASS A EXCAVATION	8,110.00	0.00	8,110.00	CUYD	1,206.00	\$12.00	\$14,472.00
		0001	0040	2035500	EMBANKMENT IN PLACE	29,876.00	13,000.00	42,876.00	CUYD	39,371.00	\$20.00	\$787,420.00
		0001	0050	2036000	COMPACTING EMBANKMENT	6,758.00	0.00	6,758.00	CUYD	839.00	\$2.00	\$1,678.00
		0001	0060	2063000	CLASS 3 EXCAVATION	75.00	0.00	75.00	CUYD	75.00	\$12.00	\$900.00
		0001	0070	2071000	LINEAR GRADING CLASS 1	30.90	0.00	30.90	STA	35.90	\$550.00	\$19,745.00
		0001	0090	2142000	FURNISHING ROCK FILL	2,040.00	0.00	2,040.00	CUYD	907.00	\$19.20	\$17,414.40
		0001	0100	2143000	PLACING ROCK FILL	2,040.00	0.00	2,040.00	CUYD	907.00	\$11.00	\$9,977.00
		0001	0110	3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	1,500.00	0.00	1,500.00	SQYD	1,500.00	\$10.50	\$15,750.00
		0001	0120	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	6,498.00	0.00	6,498.00	SQYD	5,262.20	\$10.50	\$55,253.10
		0001	0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	13,671.00	0.00	13,671.00	SQYD	7,205.10	\$11.65	\$83,939.42
		0001	0140	4010150	TYPE A2 SHOULDER	2,303.80	0.00	2,303.80	SQYD	963.50	\$23.34	\$22,488.09
		0001	0150	4019905	MISC.OPTIONAL PAVEMENT	10,728.50	0.00	10,728.50	SQYD	6,272.90	\$45.49	\$285,354.22
		0001	0160	4019905	MISC.OPTIONAL TEMPORARY PAVEMENT	4,621.50	0.00	4,621.50	SQYD	4,721.50	\$28.49	\$134,515.54
		0001	0170	5029905	MISC.TINTED CONCRETE PAVEMENT (8 IN. NON-REINFORCED)	576.60	0.00	576.60	SQYD	0.00	\$90.25	\$0.00
		0001	0180	6072010	WOVEN WIRE FENCE	987.00	0.00	987.00	LF	0.00	\$18.75	\$0.00
		0001	0190	6079902	MISC.US BOP Drive Gate	1.00	0.00	1.00	EA	0.00	\$2,910.00	\$0.00
		0001	0200	6083006	6 IN. CONCRETE MEDIAN STRIP	976.80	0.00	976.80	SQYD	0.00	\$55.35	\$0.00
		0001	0210	6085008	PAVED APPROACH, 8 IN.	763.40	0.00	763.40	SQYD	189.80	\$62.70	\$11,900.46
		0001	0220	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	21.00	0.00	21.00	LF	0.00	\$52.00	\$0.00
		0001	0230	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	39.00	0.00	39.00	LF	0.00	\$45.90	\$0.00
		0001	0240	6091041	CONCRETE GUTTER TYPE A	127.00	0.00	127.00	LF	20.00	\$96.25	\$1,925.00
		0001	0250	6091051	CURB AND GUTTER TYPE A	192.00	0.00	192.00	LF	0.00	\$34.85	\$0.00
		0001	0260	6091052	CURB AND GUTTER TYPE B	1,413.00	0.00	1,413.00	LF	919.40	\$29.90	\$27,490.06
		0001	0270	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	267.00	0.00	267.00	LF	0.00	\$7.70	\$0.00
		0001	0280	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	192.00	0.00	192.00	LF	0.00	\$8.90	\$0.00
		0001	0290	6092031	CONCRETE CURB LOW PROFILE TYPE E	355.00	0.00	355.00	LF	0.00	\$27.20	\$0.00
		0001	0300	6097000	ROCK LINING	6.00	0.00	6.00	CUYD	17.00	\$225.00	\$3,825.00
		0001	0310	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	5.00	0.00	5.00	EA	5.00	\$2,000.00	\$10,000.00
		0001	0320	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	12.00	\$330.00	\$3,960.00
		0001	0330	6122030	IMPACT ATTENUATOR (RELOCATION)	10.00	0.00	10.00	EA	6.00	\$400.00	\$2,400.00
		0001	0340	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0350	6161005	CONSTRUCTION SIGNS	637.00	0.00	637.00	SQFT	440.00	\$5.00	\$2,200.00
		0001	0360	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	3.00	\$50.00	\$150.00
		0001	0370	6161025	CHANNELIZER (TRIM LINE)	141.00	0.00	141.00	EA	125.00	\$23.00	\$2,875.00
		0001	0380	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	2.00	\$50.00	\$100.00
		0001	0390	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	7.00	0.00	7.00	EA	6.00	\$4,900.00	\$29,400.00
		0001	0400	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	4.00	\$900.00	\$3,600.00
		0001	0410	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	7,925.00	0.00	7,925.00	LF	6,658.50	\$33.00	\$219,730.50
		0001	0420	6174000A	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	2.00	0.00	2.00	EA	2.00	\$850.00	\$1,700.00
		0001	0430	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	7,200.00	0.00	7,200.00	LF	6,720.00	\$13.00	\$87,360.00
		0001	0440	6175020A	RELOCATING TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	5.00	0.00	5.00	EA	4.00	\$400.00	\$1,600.00
		0001	0450	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$343,077.28	\$0.00
		0001	0451	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$318,927.28	\$318,927.28

Revision 4/1/2020 Page 9 of 42



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
10219-C04	J4P3275	0001	0460	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0470	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	48.00	0.00	48.00	EA	0.00	\$50.00	\$0.00
		0001	0480	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	13,131.00	0.00	13,131.00	LF	14,879.00	\$1.00	\$14,879.00
		0001	0490	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	24,834.00	0.00	24,834.00	LF	22,738.00	\$1.00	\$22,738.00
		0001	0500	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,679.00	0.00	5,679.00	LF	0.00	\$0.15	\$0.00
		0001	0510	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,125.00	0.00	8,125.00	LF	0.00	\$0.18	\$0.0
		0001	0520	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,107.00	0.00	2,107.00	LF	0.00	\$0.18	\$0.0
		0001	0530	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	432.00	0.00	432.00	LF	0.00	\$3.00	\$0.0
		0001	0540	6207001	PAVEMENT MARKING REMOVAL	32,031.00	0.00	32,031.00	LF	18,795.00	\$0.25	\$4,698.7
		0001	0550	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,205.00	0.00	1,205.00	SQYD	642.00	\$3.35	\$2,150.7
		0001	0560	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$5,000.00	\$2,500.0
		0001	0570	7250418	18 IN. PIPE GROUP C	35.00	0.00	35.00	LF	14.00	\$100.00	\$1,400.0
		0001	0580	7261018	18 IN. PIPE GROUP A	74.00	0.00	74.00	LF	74.00	\$73.00	\$5,402.0
		0001	0590	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$606.00	\$1,212.0
		0001	0600	7320818A	18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END SECTION	4.00	0.00	4.00	EA	2.00	\$606.00	\$1,212.0
		0001	0610	8051000A	SEEDING - COOL SEASON MIXTURES	7.40	0.00	7.40	ACRE	3.50	\$1,605.00	\$5,617.5
		0001	0620	8061003	SEDIMENT TRAP EXCAVATION	191.00	0.00	191.00	CUYD	0.00	\$8.45	\$0.0
		0001	0630	8061004	SEDIMENT TRAP ROCK	51.00	0.00	51.00	CUYD	0.00	\$90.00	\$0.
		0001	0640	8061005	ROCK DITCH CHECK	63.00	0.00	63.00	LF	231.00	\$40.00	\$9,240.
		0001	0650	8061006	ALTERNATE DITCH CHECK	189.00	0.00	189.00	LF	100.00	\$13.00	\$1,300.
		0001	0660	8061016	SEDIMENT REMOVAL	105.00	0.00	105.00	CUYD	0.00	\$13.00	\$0.
		0001	0670	8061017	TEMPORARY SEEDING AND MULCHING	0.70	2.30	3.00	ACRE	3.00	\$1,605.00	\$4,815.
		0001	0680	8061019	SILT FENCE	5,955.00	0.00	5,955.00	LF	4,879.00	\$3.00	\$14,637.
		0001	0690	8064134	TYPE 1D EROSION CONTROL BLANKET	8,624.00	0.00	8,624.00	SQYD	4,117.00	\$1.46	\$6,010.
		0001	0700	8064135	TYPE 2A EROSION CONTROL BLANKET	2,123.00	0.00	2,123.00	SQYD	1,016.00	\$1.39	\$1,412.
		0001	0710	8064137	TYPE 2C EROSION CONTROL BLANKET	14,850.00	0.00	14,850.00	SQYD	7,064.00	\$1.39	\$9,818.
		0001	0720	8064138	TYPE 2D EROSION CONTROL BLANKET	9,964.00	0.00	9,964.00	SQYD	4,732.00	\$1.46	\$6,908.
		0010	0730	6061060	MGS GUARDRAIL	1,238.00	0.00	1,238.00	LF	0.00	\$21.00	\$0
		0010	0740	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	2,113.00	0.00	2,113.00	LF	600.00	\$25.00	\$15,000
		0010	0750	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	0.00	\$800.00	\$0
		0010	0760	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	9.00	0.00	9.00	EA	4.00	\$2,433.00	\$9,732.
		0020	0770	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	7.00	0.00	7.00	EA	0.00	\$1,793.00	\$0.
		0020	0780	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	3.00	0.00	3.00	EA	0.00	\$2,987.50	\$0
		0020	0790	9011115	BRACKET ARM, 15 FT. OR 4.6 M	10.00	0.00	10.00	EA	0.00	\$852.50	\$0
		0020	0800	9011311	LUMINAIRE, LED-A	7.00	0.00	7.00	EA	0.00	\$473.00	\$0
		0020	0810	9011312	LUMINAIRE, LED-B	3.00	0.00	3.00	EA	0.00	\$205.00	\$0
		0020	0820	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	0.00	\$7,838.00	\$0
		0020	0830	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$13.56	\$0
		0020	0840	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	190.00	0.00	190.00	LF	0.00	\$15.00	\$0
		0020	0850	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	20.00	0.00	20.00	LF	0.00	\$15.52	\$0.
		0020	0860	9015010	TRENCHING TYPE I	92.00	0.00	92.00	LF	0.00	\$10.05	\$0
		0020	0870	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	0.00	\$513.40	\$0
		0020	0880	9017002	CABLE, 2 AWG 1 CONDUCTOR	330.00	0.00	330.00	LF	0.00	\$3.30	\$0.
		0020	0890	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	990.00	0.00	990.00	LF	0.00	\$1.76	\$0.
		0020	0900	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	2,300.00	0.00	2,300.00	LF	0.00	\$3.27	\$0.0

Revision 4/1/2020 Page 10 of 42



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values an	e hased on Report	Generated date an	d can differ from the posted an	nount at the time the Estimate was Generated	

Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4P3275	0020	0910	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	7.00	0.00	7.00	EA	0.00	\$970.00	\$0.00
		0020	0920	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	3.00	0.00	3.00	EA	0.00	\$970.00	\$0.00
		0020	0930	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE,	1.00	0.00	1.00	EA	0.00	\$5,434.00	\$0.00
		0040	0940	9031010	LIGHTING ONLY  CONCRETE FOOTINGS, EMBEDDED	0.40	0.00	0.40	CUYD	0.00	\$1,650.00	\$0.00
		0040	0950	9031210	STRUCTURAL STEEL POSTS	190.00	0.00	190.00	LB	0.00	\$4.00	\$0.00
		0040	0960	9031220	PIPE POSTS	692.00	0.00	692.00	LB	0.00	\$5.00	\$0.00
		0040	0970	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	6.00	0.00	6.00	EA	0.00	\$225.00	\$0.00
		0040	0980	9031270A	TUBE) 2 IN. PSST POST - 12 GA.	277.00	0.00	277.00	LF	0.00	\$11.00	\$0.00
		0040	0990	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	48.00	0.00	48.00	LF	0.00	\$19.00	\$0.00
		0040	1000	9031272	2.25 IN. PSST POST - 12 GA.	36.00	0.00	36.00	LF	0.00	\$11.00	\$0.00
		0040	1010	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	0.00	\$47.00	\$0.00
		0040	1020	9031280	2.5 IN. PSST POST - 12 GA.	227.00	0.00	227.00	LF	0.00	\$12.00	\$0.00
		0040	1030	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	42.00	0.00	42.00	LF	0.00	\$51.00	\$0.00
		0040	1040	9035004A	SH-FLAT SHEET	313.00	0.00	313.00	SQFT	0.00	\$20.00	\$0.00
		0040	1050	9035011A	ST-STRUCTURAL	66.00	0.00	66.00	SQFT	0.00	\$23.00	\$0.00
		0040	1060	9035069A	SHF-FLAT SHEET FLUORESCENT	75.00	0.00	75.00	SQFT	0.00	\$23.00	\$0.00
		0040	1070	9039902	MISC.EACH	10.00	0.00	10.00	EA	0.00	\$50.00	\$0.00
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$24,150.00	\$24,150.00
		0001	5002	6191000	PAVEMENT EDGE TREATMENT	0.00	370.00	370.00	LF	370.00	\$7.10	\$2,627.00
		0001	5003	6139901	MISC.CONCRETE PATCH FOR STORM SEWER CROSSING	0.00	1.00	1.00	LS	1.00	\$3,349.50	\$3,349.50
	Project J4	4P3275 - To	tal Value	Posted to D	ate as of Report Generated Date							\$2,431,593.25
	J4S3278	0001	1080	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,904.00	\$2,904.00
		0001	1090	2031000	CLASS A EXCAVATION	120.00	0.00	120.00	CUYD	0.00	\$88.00	\$0.00
		0001	1100	2035500	EMBANKMENT IN PLACE	370.00	0.00	370.00	CUYD	0.00	\$48.00	\$0.00
		0001	1110	2063000	CLASS 3 EXCAVATION	24.00	0.00	24.00	CUYD	24.00	\$12.00	\$288.00
		0001	1110	2063000 3101002	CLASS 3 EXCAVATION  GRAVEL (A)	24.00 396.00	0.00	24.00 118.00	CUYD	24.00 118.00	\$12.00 \$87.92	\$288.00 \$10,374.56
		0001	1120	3101002	GRAVEL (A)	396.00	-278.00	118.00	TONS	118.00	\$87.92	\$10,374.56
		0001	1120 1130	3101002 4011209	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	396.00 124.30	-278.00 0.00	118.00 124.30	TONS	118.00 124.30	\$87.92 \$87.19	\$10,374.56 \$10,837.72
		0001 0001 0001	1120 1130 1140	3101002 4011209 4071005	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT	396.00 124.30 93.00	-278.00 0.00 0.00	118.00 124.30 93.00	TONS TONS GAL	118.00 124.30 93.00	\$87.92 \$87.19 \$2.50	\$10,374.56 \$10,837.72 \$232.50
		0001 0001 0001 0001	1120 1130 1140 1150	3101002 4011209 4071005 6083003	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP	396.00 124.30 93.00 11.30	-278.00 0.00 0.00 0.00	118.00 124.30 93.00 11.30	TONS TONS GAL SQYD	118.00 124.30 93.00 11.30	\$87.92 \$87.19 \$2.50 \$298.60	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18
		0001 0001 0001 0001 0001	1120 1130 1140 1150 1160	3101002 4011209 4071005 6083003 6161005	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS	396.00 124.30 93.00 11.30 393.00	-278.00 0.00 0.00 0.00 0.00	118.00 124.30 93.00 11.30 393.00	TONS TONS GAL SQYD SQFT	118.00 124.30 93.00 11.30 220.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00
		0001 0001 0001 0001 0001	1120 1130 1140 1150 1160 1170	3101002 4011209 4071005 6083003 6161005 6161009	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY	396.00 124.30 93.00 11.30 393.00 5.00	-278.00 0.00 0.00 0.00 0.00 0.00	118.00 124.30 93.00 11.30 393.00 5.00	TONS TONS GAL SQYD SQFT EA	118.00 124.30 93.00 11.30 220.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$25.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00
		0001 0001 0001 0001 0001 0001	1120 1130 1140 1150 1160 1170	3101002 4011209 4071005 6083003 6161005 6161009 6161024	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT	396.00 124.30 93.00 11.30 393.00 5.00 7.00	-278.00 0.00 0.00 0.00 0.00 0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00	TONS TONS GAL SQYD SQFT EA	118.00 124.30 93.00 11.30 220.00 2.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$25.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00
		0001 0001 0001 0001 0001 0001 0001	1120 1130 1140 1150 1160 1170 1180	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE)	396.00 124.30 93.00 11.30 393.00 5.00 7.00	-278.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00	TONS TONS GAL SQYD SQFT EA EA	118.00 124.30 93.00 11.30 220.00 2.00 0.00 93.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$25.00 \$1.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$93.00
		0001 0001 0001 0001 0001 0001 0001 000	1120 1130 1140 1150 1160 1170 1180 1190	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR	396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00	-278.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00	TONS TONS GAL SQYD SQFT EA EA EA	118.00 124.30 93.00 11.30 220.00 2.00 0.00 93.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$93.00
		0001 0001 0001 0001 0001 0001 0001 000	1120 1130 1140 1150 1160 1170 1180 1190 1200	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A	GRAVEL (A)  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  TACK COAT  3 IN. CONCRETE MEDIAN STRIP  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE) WITH LIGHT  CHANNELIZER (TRIM LINE)  TYPE III MOVEABLE BARRICADE WITH LIGHTS  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R	396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00	-278.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00	TONS TONS GAL SQYD SQFT EA EA EA EA	118.00 124.30 93.00 11.30 220.00 2.00 0.00 93.00 22.00 3.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1,000.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$93.00 \$1,650.00
		0001 0001 0001 0001 0001 0001 0001 000	1120 1130 1140 1150 1160 1170 1180 1190 1200 1210	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION	396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00	-278.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00	TONS TONS GAL SQYD SQFT EA EA EA LS	118.00 124.30 93.00 11.30 220.00 2.00 0.00 93.00 22.00 3.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1,000.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$93.00 \$1,650.00 \$3,000.00
		0001 0001 0001 0001 0001 0001 0001 000	1120 1130 1140 1150 1160 1170 1180 1190 1200 1210	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 6200033 6206000C	GRAVEL (A) BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) TACK COAT 3 IN. CONCRETE MEDIAN STRIP CONSTRUCTION SIGNS FLAG ASSEMBLY CHANNELIZER (TRIM LINE) WITH LIGHT CHANNELIZER (TRIM LINE) TYPE III MOVEABLE BARRICADE WITH LIGHTS CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED MOBILIZATION PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00	-278.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00	TONS TONS GAL SQYD SQFT EA EA EA EA EA EA	118.00 124.30 93.00 11.30 220.00 2.00 0.00 93.00 22.00 3.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1,000.00 \$12,551.00 \$800.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$93.00 \$1,650.00 \$3,000.00 \$12,551.00
		0001 0001 0001 0001 0001 0001 0001 000	1120 1130 1140 1150 1160 1170 1180 1190 1210 1220 1230	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 6200033 6206000C	GRAVEL (A)  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  TACK COAT  3 IN. CONCRETE MEDIAN STRIP  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE) WITH LIGHT  CHANNELIZER (TRIM LINE)  TYPE III MOVEABLE BARRICADE WITH LIGHTS  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00	-278.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00	TONS TONS GAL SQYD SQFT EA EA LS EA LS EA	118.00 124.30 93.00 11.30 220.00 2.00 0.00 93.00 22.00 3.00 1.00 1.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1,000.00 \$1,000.00 \$10.00 \$0.10	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$93.00 \$1,650.00 \$3,000.00 \$12,551.00 \$800.00
		0001 0001 0001 0001 0001 0001 0001 000	1120 1130 1140 1150 1160 1170 1180 1200 1210 1220 1230 1240	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 6200033 6206000C	GRAVEL (A)  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  TACK COAT  3 IN. CONCRETE MEDIAN STRIP  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE) WITH LIGHT  CHANNELIZER (TRIM LINE)  TYPE III MOVEABLE BARRICADE WITH LIGHTS  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R  CROSSING MARKER  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	396.00 124.30 93.00 11.30 393.00 7.00 93.00 17.00 3.00 1.00 1.00 19,047.00 7,377.00	-278.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00 19,047.00	TONS TONS GAL SQYD SQFT EA EA LS EA LS EA LF	118.00 124.30 93.00 11.30 220.00 0.00 93.00 22.00 3.00 1.00 19,047.00 7,377.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1,000.00 \$1,000.00 \$1000.00 \$0.10	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$93.00 \$1,650.00 \$3,000.00 \$12,551.00 \$800.00 \$11,904.70
		0001 0001 0001 0001 0001 0001 0001 000	1120 1130 1140 1150 1160 1170 1180 1200 1210 1220 1220 1240 1250 1260 1270	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 62000033 6206000C 6206001C 6206108A 6206124A 6221001	GRAVEL (A)  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  TACK COAT  3 IN. CONCRETE MEDIAN STRIP  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE) WITH LIGHT  CHANNELIZER (TRIM LINE)  TYPE III MOVEABLE BARRICADE WITH LIGHTS  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R  CROSSING MARKER  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00 7,377.00 112.00 24.00	-278.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00 1.00 1.00 1.00 1.00 24.00 871.00	TONS TONS GAL SQYD SQFT EA EA EA LS EA LS EA LF LF LF SQYD	118.00 124.30 93.00 11.30 220.00 2.00 0.00 93.00 22.00 3.00 1.00 1.00 19.047.00 7,377.00 112.00 24.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1,000.00 \$1,000.00 \$10,000	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$93.00 \$1,650.00 \$12,551.00 \$800.00 \$1,904.70 \$737.70 \$56.00 \$120.00
		0001 0001 0001 0001 0001 0001 0001 000	1120 1130 1140 1150 1160 1170 1180 1200 1210 1220 1230 1240 1250 1260	3101002 4011209 4071005 6083003 6161005 6161009 6161024 6161025 6161031 6161098A 6181000 6200033 6206000C 6206001C 6206108A 6206124A	GRAVEL (A)  BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)  TACK COAT  3 IN. CONCRETE MEDIAN STRIP  CONSTRUCTION SIGNS  FLAG ASSEMBLY  CHANNELIZER (TRIM LINE) WITH LIGHT  CHANNELIZER (TRIM LINE)  TYPE III MOVEABLE BARRICADE WITH LIGHTS  CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED  MOBILIZATION  PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R  CROSSING MARKER  4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS  COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	396.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00 7,377.00 112.00 24.00	-278.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00  0.00	118.00 124.30 93.00 11.30 393.00 5.00 7.00 93.00 17.00 3.00 1.00 1.00 19,047.00 7,377.00	TONS TONS GAL SQYD SQFT EA EA EA LS EA LF LF LF	118.00 124.30 93.00 11.30 220.00 0.00 93.00 22.00 3.00 1.00 19,047.00 7,377.00 112.00	\$87.92 \$87.19 \$2.50 \$298.60 \$4.00 \$1.00 \$1.00 \$1,000.00 \$1,000.00 \$0.10 \$0.10 \$5.00	\$10,374.56 \$10,837.72 \$232.50 \$3,374.18 \$880.00 \$50.00 \$0.00 \$1,650.00 \$12,551.00 \$800.00 \$1,904.70 \$737.70 \$56.00

Revision 4/1/2020 Page 11 of 42



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4S3278	0001	1310	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0001	1320	7250412	12 IN. PIPE GROUP C	50.00	0.00	50.00	LF	50.00	\$54.00	\$2,700.00
		0001	1330	7250418	18 IN. PIPE GROUP C	50.00	0.00	50.00	LF	50.00	\$65.00	\$3,250.00
		0001	1340	8051000A	SEEDING - COOL SEASON MIXTURES	0.50	-0.30	0.20	ACRE	0.20	\$5,940.00	\$1,188.00
		0001	1350	8061005	ROCK DITCH CHECK	98.00	-14.00	84.00	LF	84.00	\$40.00	\$3,360.00
		0001	1360	8061016	SEDIMENT REMOVAL	21.00	-21.00	0.00	CUYD	0.00	\$13.00	\$0.00
		0001	1370	8061019	SILT FENCE	792.00	-752.00	40.00	LF	40.00	\$4.70	\$188.00
		0001	1380	9031010	CONCRETE FOOTINGS, EMBEDDED	0.10	0.00	0.10	CUYD	0.10	\$1,650.00	\$165.00
		0001	1390	9031220	PIPE POSTS	70.00	0.00	70.00	LB	70.00	\$5.00	\$350.00
		0002	1400	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	5,419.50	399.90	5,819.40	TONS	5,819.40	\$59.61	\$346,894.43
		0002	1410	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	8,564.20	-1,045.40	7,518.80	TONS	7,518.80	\$56.21	\$422,631.75
		0002	1420	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	2,280.50	87.00	2,367.50	TONS	2,367.50	\$58.85	\$139,327.38
		0002	1430	4071005	TACK COAT	17,393.00	-8,443.00	8,950.00	GAL	8,950.00	\$2.50	\$22,375.00
		0010	1460	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,175.00	0.00	1,175.00	LF	0.00	\$25.00	\$0.00
		0010	1470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,433.00	\$0.00
	Project J	4S3278 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,024,549.12
210219-C04 Ove	erall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$3,456,142.38

Revision 4/1/2020 Page 12 of 42



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3275

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2031000	CLASS A EXCAVATION	9/24/21	10/1/21	33.00	CUYD	For the additional optional pavement in the truck apron for EB traffic in phase 4.	62+34		63+45		
0120	3040504	TYPE 5 AGGREGATE FOR BASE	9/24/21	10/1/21	100.00	SQYD	For the additional optional pavement in the truck apron for EB traffic in phase 4.	62+34		63+45		
0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	9/28/21	10/1/21	1,476.60	SQYD	Phase 3 Construction	63+62		71+37.5		
				10/1/21	1,643.40	SQYD	Phase 3 Construction	54+00		62+12		
0150	4019905	MISC.	9/28/21	10/1/21	1,476.60	SQYD	Phase 3 Paving	63+62		71+37.5		
				10/1/21	1,643.40	SQYD	Phase 3 Paving	54+00		62+12		
0160	4019905	MISC.	9/28/21	10/1/21	100.00	SQYD	Additional temp paving in the truck apron roundabout for EB traffic during phase 4 traffic configuration.	62+34		63+45		
0260	6091052	CURB AND GUTTER TYPE B	9/22/21	10/1/21	89.00	LF	EB 92 Phase 3 Partial Run	61+04	5' Rt	61+90	4' rt	
				10/1/21	149.00	LF	EB 92 Phase 3 Partial Run East of Roundabout	64+00	CL existing	65+47	2.5' RT	
0330	6122030	IMPACT ATTENUATOR (RELOCATION)	9/30/21	10/1/21	1.00	EA	For Phase 4 Traffic	72+80		72+80		
0370	6161025	CHANNELIZER (TRIM LINE)	9/20/21	10/1/21	30.00	EA		54+00		71+37.5		
0390	6161098A	CMS W/O COMMUNICATION INTERFACE, CONT F/	9/22/21	10/1/21	3.00	EA	One on the Kansas side of the Bridge	MO 45 N 10.446		MO 45 N 16.337		3 total were set out for this phase of traffic control
0430	6175011B	RELOC TEMPORARY TRAFFIC BARRIER ANCHORED	9/30/21	10/1/21	370.00	LF	Phase 4	63+25		66+97		
				10/1/21	510.00	LF	Phase 4	67+58		72+80		
				10/1/21	1,594.00	LF	Phase 4	46+59		62+53		
0440	6175020A	RELOCATING TEMP. TRAFF BARR HEIGHT TRANS	9/30/21	10/1/21	1.00	EA	Phase 4	66+77		66+97		
				10/1/21	1.00	EA	Phase 4	72+60		72+80		

Project: J4S3278

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1190	6161025	CHANNELIZER (TRIM LINE)	9/20/21	10/1/21	13.00	EA		69+61		183+52		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 13 of 42



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0010	CLEARING AND GRUBBING	Overrun	Overrun	3	Jun 16, 2021	SYSTEM	(\$9,000.00)	
				Overrun - T	otal			(\$9,000.00)	
			Overrun - To	tal				(\$9,000.00)	
	0010 -							(\$9,000.00)	
	0030	CLASS A EXCAVATION	Price FUEL		6	Aug 2, 2021	SYSTEM	\$104.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 2, 2021	SYSTEM	\$5.52	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Sep 16, 2021	SYSTEM	\$12.24	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Oct 1, 2021	SYSTEM	\$3.37	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$125.86	
			Price FUEL -	Total				\$125.86	
	0030 -							\$125.86	
	0040	EMBANKMENT IN PLACE	Material		3	Jun 16, 2021	SYSTEM	\$279,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$279,620.00)	
					4	Jul 1, 2021	SYSTEM	\$316,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$316,020.00)	
					5	Jul 16, 2021	SYSTEM	\$562,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$562,220.00)	
					6	Aug 2, 2021	SYSTEM	\$713,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$713,020.00)	
					7	Aug 16, 2021	SYSTEM	\$787,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$787,420.00)	
					8	Sep 2, 2021	SYSTEM	\$787,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$787,420.00)	
					9	Sep 16, 2021	SYSTEM	\$787,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$787,420.00)	
					10	Oct 1, 2021	SYSTEM	\$787,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$787,420.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	OVRN	6	Aug 2, 2021	schnod1	(\$115,500.00)	Payment held until quantity is verified by contractor/MoDOT.
				OVRN - Tota	al			(\$115,500.00)	
			Other Item A	djustment - T	otal			(\$115,500.00)	
			Overrun	Overrun	6	Aug 2, 2021	SYSTEM	(\$116,551.05)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0040	EMBANKMENT IN PLACE	Overrun	Overrun	6	Aug 2, 2021	SYSTEM	\$31,887.56	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.
					6	Aug 2, 2021	SYSTEM	\$33,098.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.
					6	Aug 2, 2021	SYSTEM	\$35,116.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.
					6	Aug 2, 2021	SYSTEM	\$16,448.33	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.
					7	Aug 16, 2021	SYSTEM	(\$116,533.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.17890' is applied (if non-zero).
					7	Aug 16, 2021	schnod1	(\$74,400.00)	Overrun withheld for estimate 0007.
					7	Aug 16, 2021	SYSTEM	(\$75,181.20)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Aug 16, 2021	SYSTEM	\$75,181.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 28 on the current Payment Estimate. Material Insufficiency Quantity 39371.000; Overrun Quantity Balance 9495.00.
					7	Aug 16, 2021	SYSTEM	\$116,533.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 28 on the current Payment Estimate. Material Insufficiency Quantity 39371.000; Overrun Quantity Balance 9495.00.
					8	Sep 2, 2021	schnod1	\$189,900.00	Quantity updated on CO 3, overrun negative adjustments are being paid back. \$189,900
				Overrun - To	otal			\$115,500.00	
			Overrun - To	tal				\$115,500.00	
			Price FUEL		3	Jun 16, 2021	SYSTEM	\$2,446.67	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 1, 2021	SYSTEM	\$318.50	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Jul 16, 2021	SYSTEM	\$2,240.42	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Aug 2, 2021	SYSTEM	\$1,372.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Aug 16,	SYSTEM	0704.00	
						2021		\$781.20	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total		2021		\$781.20	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Price FUEL -			2021		, , ,	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0040 -	- Total	Price FUEL -			2021		\$7,159.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
	0040 - 0050	-Total  COMPACTING EMBANKMENT	Price FUEL -		6	Aug 2, 2021	SYSTEM	\$7,159.07 \$7,159.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		COMPACTING			6	Aug 2,		\$7,159.07 \$7,159.07 \$7,159.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment
		COMPACTING				Aug 2, 2021	SYSTEM	\$7,159.07 \$7,159.07 \$7,159.07 \$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment
		COMPACTING			6	Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM	\$7,159.07 \$7,159.07 \$7,159.07 \$1,678.00 (\$1,678.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
		COMPACTING			6	Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM	\$7,159.07 \$7,159.07 \$7,159.07 \$1,678.00 (\$1,678.00) \$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
		COMPACTING			6 7 7	Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM	\$7,159.07 \$7,159.07 \$7,159.07 \$1,678.00 (\$1,678.00) \$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment
		COMPACTING			7 7 8	Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$7,159.07 \$7,159.07 \$7,159.07 \$1,678.00 (\$1,678.00) \$1,678.00 (\$1,678.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0050	COMPACTING EMBANKMENT	Material		10	Oct 1, 2021	SYSTEM	\$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$1,678.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050 -	· Total						\$0.00	
	0070	LINEAR GRADING CLASS 1	Overrun	Overrun	4	Jul 1, 2021	SYSTEM	(\$1,650.00)	
					9	Sep 16, 2021	SYSTEM	(\$1,100.00)	
				Overrun - T	otal			(\$2,750.00)	
			Overrun - To	tal				(\$2,750.00)	
	0070 -	- Total						(\$2,750.00)	
	0110	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	Material		8	Sep 2, 2021	SYSTEM	\$15,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		micky			8	Sep 2, 2021	SYSTEM	(\$15,750.00)	
					9	Sep 16, 2021	SYSTEM	\$15,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$15,750.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		8	Sep 2, 2021	SYSTEM	\$270.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$270.00	
			Price FUEL -	Total				\$270.00	
	0110 -	· Total						\$270.00	
	0120	TYPE 5 AGGREGATE FOR BASE	Material		4	Jul 1, 2021	SYSTEM	\$48,687.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment
		FOR BASE							Estimate Exception 2 on the current Payment Estimate.
		FOR BASE			4	Jul 1, 2021	SYSTEM	(\$48,687.45)	
		FOR BASE			5		SYSTEM	(\$48,687.45) \$48,687.45	
		FUN BASE				2021 Jul 16,			Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment
		FUN BASE			5	Jul 16, 2021 Jul 16,	SYSTEM	\$48,687.45	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment
		FUN BASE			5	Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM	\$48,687.45 (\$48,687.45)	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment
		FUN BASE			5 6	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM	\$48,687.45 (\$48,687.45) \$48,687.45	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment
		FUN BASE			5 5 6	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM	\$48,687.45 (\$48,687.45) \$48,687.45	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment
		FUN BASE			5 5 6 6 7	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$48,687.45 (\$48,687.45) \$48,687.45 (\$48,687.45)	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment
		FUN BASE			5 5 6 7	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$48,687.45 (\$48,687.45) \$48,687.45 (\$48,687.45) \$48,687.45	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment
		FUN BASE			5 5 6 7 7 8	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$48,687.45 (\$48,687.45) \$48,687.45 (\$48,687.45) \$48,687.45 (\$48,687.45) \$54,203.10	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment
		FOR BASE			5 5 6 7 7 8	2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$48,687.45 (\$48,687.45) \$48,687.45 (\$48,687.45) \$48,687.45 (\$48,687.45) \$54,203.10	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3275	0120	TYPE 5 AGGREGATE	Material						Estimate Exception 3 on the current Payment Estimate.
		FOR BASE			10	Oct 1, 2021	SYSTEM	(\$55,253.10)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		4	Jul 1, 2021	SYSTEM	\$347.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 2, 2021	SYSTEM	\$47.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Oct 1, 2021	SYSTEM	\$7.65	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$402.70	
			Price FUEL -	Total				\$402.70	
	0120 -	Total						\$402.70	
	0130	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		7	Aug 16, 2021	SYSTEM	\$5,463.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		THICK)			7	Aug 16, 2021	SYSTEM	(\$5,463.85)	
					8	Sep 2, 2021	SYSTEM	\$47,591.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$47,591.42)	
					9	Sep 16, 2021	SYSTEM	\$47,591.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$47,591.42)	
					10	Oct 1, 2021	SYSTEM	\$83,939.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$83,939.42)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		7	Aug 16, 2021	SYSTEM	\$64.72	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 2, 2021	SYSTEM	\$499.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Oct 1, 2021	SYSTEM	\$365.98	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$929.72	
			Price FUEL -	Total				\$929.72	
	0130 -	Total						\$929.72	
	0140	TYPE A2 SHOULDER	Material		8	Sep 2, 2021	SYSTEM	\$22,488.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$22,488.09)	
					9	Sep 16, 2021	SYSTEM	\$22,488.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$22,488.09)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0140 -	Total						\$0.00	
	0150	MISC.	Material		10	Oct 1, 2021	SYSTEM	\$285,354.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Oct 1,	SYSTEM	(\$285,354.22)	Examate Exception of the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J4P3275	0150	MISC.	Material			2021							
				- Total				\$0.00					
			Material - To	tal				\$0.00					
			Other Item Adjustment	ACAD	8	Sep 2, 2021	schnod1	\$3,693.73	2,683.9 SQYD of SP190 21-13				
					8	Sep 2, 2021	schnod1	\$691.67	2,683.90 SQYD of SP125 21-14.				
					10	Oct 1, 2021	schnod1	\$816.82	3,120 SQYD of 1.75" SP125 21-14 with 3.4% Virgin AC.				
					10	Oct 1, 2021	schnod1	\$4,362.07	3,120 SQYD of 10.25" SP190 21-13 with 3.10% Virgin AC				
				ACAD - Tota	al			\$9,564.29					
			Other Item A	djustment - T	otal			\$9,564.29					
	0150 -	· Total						\$9,564.29					
	0160	MISC.	Material		4	Jul 1, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					4	Jul 1, 2021	SYSTEM	(\$125,903.01)					
					5	Jul 16, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					5	Jul 16, 2021	SYSTEM	(\$125,903.01)					
									6	Aug 2, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
											6	Aug 2, 2021	SYSTEM
					7	Aug 16, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					7	Aug 16, 2021	SYSTEM	(\$125,903.01)					
					8	Sep 2, 2021	SYSTEM	\$131,666.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					8	Sep 2, 2021	SYSTEM	(\$131,666.54)					
					9	Sep 16, 2021	SYSTEM	\$131,666.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					9	Sep 16, 2021	SYSTEM	(\$131,666.54)					
								10	Oct 1, 2021	SYSTEM	\$134,515.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					10	Oct 1, 2021	SYSTEM	(\$134,515.54)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
			Other Item Adjustment	ACAD	10	Oct 1, 2021	schnod1	\$26.18	100 SQYD of 1.75" SP125 21-14 with 3.4% Virgin AC.				
					10	Oct 1, 2021	schnod1	\$85.25	100.0 SQYD of 6.25" SP190 21-13 with 3.1% Virgin AC.				
				ACAD - Tota				\$111.43					
				OVRN	10	Oct 1, 2021	schnod1	(\$2,849.00)	Overrun/material adjustment.				
				OVRN - Tota	al			(\$2,849.00)					
			Other Item A	djustment - T	otal			(\$2,737.57)					
			Overrun	Overrun	10	Oct 1, 2021	SYSTEM	\$2,849.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 42 on the current Payment Estimate. Material Insufficiency Quantity 4721.500; Overrun Quantity Balance 100.00.				



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
275	0160	MISC.	Overrun	Overrun	10	Oct 1, 2021	SYSTEM	(\$2,849.00)															
				Overrun - To	otal			\$0.00															
			Overrun - To	tal				\$0.00															
	0160 -	Total						(\$2,737.57)															
	0210	PAVED APPROACH, 8 IN.	Material		8	Sep 2, 2021	SYSTEM	\$11,900.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
					8	Sep 2, 2021	SYSTEM	(\$11,900.46)															
					9	Sep 16, 2021	SYSTEM	\$11,900.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Paymen Estimate Exception 22 on the current Payment Estimate.														
					9	Sep 16, 2021	SYSTEM	(\$11,900.46)															
									10	Oct 1, 2021	SYSTEM	\$11,900.46	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Paymen Estimate Exception 17 on the current Payment Estimate.										
					10	Oct 1, 2021	SYSTEM	(\$11,900.46)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
			Price FUEL		8	Sep 2, 2021	SYSTEM	\$68.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL														
			- Tota					\$68.33															
			Price FUEL -	Total				\$68.33															
	0210 -							\$68.33															
024	0240	CONCRETE GUTTER TYPE A	NCRETE Material TYPE A		8	Sep 2, 2021	SYSTEM	\$1,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Paymer Estimate Exception 29 on the current Payment Estimate.														
					8	Sep 2, 2021	SYSTEM	(\$1,925.00)															
														9	Sep 16, 2021	SYSTEM	\$1,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Paymer Estimate Exception 30 on the current Payment Estimate.					
														9	Sep 16, 2021	SYSTEM	(\$1,925.00)						
												1	10	Oct 1, 2021	SYSTEM	\$1,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Paymer Estimate Exception 24 on the current Payment Estimate.						
					10	Oct 1, 2021	SYSTEM	(\$1,925.00)															
				- Total				\$0.00															
			Material - To	tal				\$0.00															
	0240 -							\$0.00															
	0260	CURB AND GUTTER TYPE B	Material		8	Sep 2, 2021	SYSTEM	\$20,373.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Paymer Estimate Exception 37 on the current Payment Estimate.														
					8	Sep 2, 2021	SYSTEM	(\$20,373.86)															
																			9	Sep 16, 2021	SYSTEM	\$20,373.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$20,373.86)															
					10	Oct 1, 2021	SYSTEM	\$27,490.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.														
					10	Oct 1, 2021	SYSTEM	(\$27,490.06)															
				- Total				\$0.00															
		Material	Material - To	tal				\$0.00															
	0260 -	Total						\$0.00															





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0320	REPLACEMENT SAND BARREL	Material		4	Jul 1, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$990.00)	
					5	Jul 16, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$990.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	OVRN	9	Sep 16, 2021	schnod1	(\$1,320.00)	Overrun adjustment until change order completion.
					10	Oct 1, 2021	schnod1	\$1,320.00	Return of adjustment from estimate 0009.
				OVRN - Tota	al			\$0.00	
			Other Item A	djustment - T				\$0.00	
			Overrun	Overrun		Sep 16, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$1,320.00)	
					10	Oct 1, 2021	SYSTEM	(\$1,320.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$1,320.00)	
			Overrun - To	tal				(\$1,320.00)	
	0320 -	Total						(\$1,320.00)	
	0350	CONSTRUCTION SIGNS	Material		1	May 17, 2021	SYSTEM	\$2,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$2,040.00)	
					2	Jun 2, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user woodwj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$2,200.00)	
					3	Jun 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$2,200.00)	
					4	Jul 1, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$2,200.00)	
					5	Jul 16, 2021	SYSTEM	\$2,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$2,200.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0350 -	Total						\$0.00	
	0360	ADVANCED WARNING RAIL SYSTEM	Material		1	May 17, 2021	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$150.00)	
					2	Jun 2, 2021	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0360	ADVANCED WARNING RAIL	Material		2	Jun 2, 2021	SYSTEM	(\$150.00)	
		SYSTEM			3	Jun 16, 2021	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$150.00)	
					4	Jul 1, 2021	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$150.00)	
					5	Jul 16, 2021	SYSTEM	\$150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$150.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0360 -	Total						\$0.00	
	0370	CHANNELIZER (TRIM LINE)	Material		1	May 17, 2021	SYSTEM	\$1,472.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$1,472.00)	
					2	Jun 2, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user woodwj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$2,185.00)	
					3	Jun 16, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$2,185.00)	
					4	Jul 1, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$2,185.00)	
					5	Jul 16, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$2,185.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0370 -	Total						\$0.00	
	0400	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		1	May 17, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$3,600.00)	
					2	Jun 2, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user woodwj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$3,600.00)	
					3	Jun 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$3,600.00)	
					4	Jul 1, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0400	TEMPORARY LONG-TERM	Material		4	Jul 1, 2021	SYSTEM	(\$3,600.00)	
		RUMBLE STRIPS			5	Jul 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$3,600.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0400 -	Total						\$0.00	
	0410	TEMP. TRAFFIC BARRIER ANCHORED., CONT	Material		1	May 17, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		CONT			1	May 17, 2021	SYSTEM	(\$96,937.50)	
					2	Jun 2, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user woodwj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$96,937.50)	
					3	Jun 16, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$96,937.50)	
					4	Jul 1, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$96,937.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0410 -	Total						\$0.00	
	0420	TEMP. TRAFFIC BARRIER HEIGHT TRANSITION	Material		1	May 17, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$1,700.00)	
					2	Jun 2, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user woodwj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$1,700.00)	
					3	Jun 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$1,700.00)	
					4	Jul 1, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,700.00)	
					5	Jul 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$1,700.00)	
					6	Aug 2, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,700.00)	
					7	Aug 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Fioject	Line	Description	Туре	Adjustment Type	Number	Date	By	Amount	IVEIIIAINS
J4P3275	0420	TEMP. TRAFFIC BARRIER HEIGHT	Material		7	Aug 16, 2021	SYSTEM	(\$1,700.00)	
		TRANSITION			8	Sep 2, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$1,700.00)	
					9	Sep 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$1,700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0420 -	Total						\$0.00	
	0480	TEMPORARY REMOVABLE MARKING TAPE 4	Material		1	May 17, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		IN.,			1	May 17, 2021	SYSTEM	(\$4,314.00)	
					2	Jun 2, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$4,314.00)	
					3	Jun 16, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$4,314.00)	
					4	Jul 1, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$4,314.00)	
					5	Jul 16, 2021	SYSTEM	\$11,794.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$11,794.00)	
					6	Aug 2, 2021	SYSTEM	\$11,794.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$11,794.00)	
					7	Aug 16, 2021	SYSTEM	\$11,794.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$11,794.00)	
					8	Sep 2, 2021	SYSTEM	\$11,794.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$11,794.00)	
					9	Sep 16, 2021	SYSTEM	\$14,879.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$14,879.00)	
					10	Oct 1, 2021	SYSTEM	\$14,879.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$14,879.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0480	TEMPORARY	Material - To	tal				\$0.00	
		REMOVABLE MARKING TAPE 4 IN.,	Other Item Adjustment	OVRN	9	Sep 16, 2021	schnod1	(\$1,748.00)	Overrun adjustment until change order completion.
				OVRN - Tota	al			(\$1,748.00)	
			Other Item A	djustment - T	otal			(\$1,748.00)	
			Overrun	Overrun	9	Sep 16, 2021	SYSTEM	\$1,748.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0026) overridding Payment Estimate Exception 64 on the current Payment Estimate. Material Insufficiency Quantity 14879.000; Overrun Quantity Balance 1748.00.
					9	Sep 16, 2021	SYSTEM	(\$1,748.00)	
					10	Oct 1, 2021	SYSTEM	(\$1,748.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Oct 1, 2021	SYSTEM	\$1,748.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0021) overridding Payment Estimate Exception 45 on the current Payment Estimate. Material Insufficiency Quantity 14879.000; Overrun Quantity Balance 1748.00.
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0480 -	Total						(\$1,748.00)	
	0490	TEMPORARY REMOVABLE MARKING TAPE	Material		1	May 17, 2021	SYSTEM	\$7,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$7,428.00)	
					2	Jun 2, 2021	SYSTEM	\$7,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user woodwj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$7,428.00)	
					3	Jun 16, 2021	SYSTEM	\$7,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$7,428.00)	
					4	Jul 1, 2021	SYSTEM	\$7,428.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$7,428.00)	
					5	Jul 16, 2021	SYSTEM	\$14,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$14,884.00)	
					6	Aug 2, 2021	SYSTEM	\$14,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$14,884.00)	
					7	Aug 16, 2021	SYSTEM	\$14,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$14,884.00)	
					8	Sep 2, 2021	SYSTEM	\$14,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$14,884.00)	
					9	Sep 16, 2021	SYSTEM	\$22,738.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$22,738.00)	
					10	Oct 1,	SYSTEM	\$22,738.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0490	TEMPORARY REMOVABLE	Material			2021			Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
		MARKING TAPE			10	Oct 1, 2021	SYSTEM	(\$22,738.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0490 -	Total						\$0.00	
	0570	18 IN. PIPE CULVERT GROUP C	Material		8	Sep 2, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$1,400.00)	
					9	Sep 16, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$1,400.00)	
					10	Oct 1, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$1,400.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
	0570 -	Total						\$0.00	
	0590	18 IN. GROUP A FLARED END SECT	Material		3	Jun 16, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$1,212.00)	
					4	Jul 1, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,212.00)	
					5	Jul 16, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$1,212.00)	
					6	Aug 2, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,212.00)	
					7	Aug 16, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$1,212.00)	
					8	Sep 2, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$1,212.00)	
					9	Sep 16, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$1,212.00)	
					10	Oct 1, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					10	Oct 1,	SYSTEM	(\$1,212.00)	
						2021			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0590	18 IN. GROUP A FLARED END	Material	- Total				\$0.00	
		SECT	Material - To	tal				\$0.00	
	0590 -	· Total						\$0.00	
	0600	18 IN. GROUP C FLARED END SEC	Material		8	Sep 2, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$1,212.00)	
					9	Sep 16, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$1,212.00)	
					10	Oct 1, 2021	SYSTEM	\$1,212.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$1,212.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0600 -	· Total						\$0.00	
	0610	SEEDING - COOL SEASON MIXTURES	Material		9	Sep 16, 2021	SYSTEM	\$5,617.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schnod1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$5,617.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0610 -	· Total						\$0.00	
	0640	ROCK DITCH CHECK	Material		3	Jun 16, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$1,600.00)	
					4	Jul 1, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$5,600.00)	
					5	Jul 16, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$5,600.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment	OVRN	4	Jul 1, 2021	schnod1	(\$3,080.00)	Payment held for overrun exception.
					6	Aug 2, 2021	schnod1	\$3,080.00	Manual negative adjustment from estimate 0004 paid for now.
					9	Sep 16, 2021	schnod1	(\$6,720.00)	Overrun adjustment until change order completion.
					10	Oct 1, 2021	schnod1	\$6,720.00	Return of adjustment from estimate 0009.
				OVRN - Tot	al			\$0.00	
			Other Item A	djustment - T	otal			\$0.00	
			Overrun	Overrun	4	Jul 1, 2021	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 62 on the current Payment Estimate. Material Insufficiency Quantity 140.000; Overrun Quantity Balance 77.00.
					4	Jul 1, 2021	SYSTEM	(\$3,080.00)	
					5	Jul 16,	SYSTEM	(\$3,080.00)	Averaged Price Adjustment from this item on all previous payment estimates



Material   Topic   T										
CHECK	Project	Line	Description	Adjustment Type		Est. Number	Created Date	Created By	Amount	Remarks
S	J4P3275	0640	ROCK DITCH	Overrun	Overrun		2021			of '0.00000' is applied (if non-zero).
2021   Sep 16   SYSTEM   (\$1,880.00)			CHECK			5		SYSTEM	\$3,080.00	Estimate Item Adjustment (0044) overridding Payment Estimate Exception 54 on the current Payment Estimate. Material Insufficiency Quantity 140.000;
Page						6		SYSTEM	(\$3,080.00)	
Covernum - Total						8		SYSTEM	(\$1,480.00)	
						9		SYSTEM	(\$2,160.00)	
					Overrun - T	otal			(\$6,720.00)	
				Overrun - To	tal				(\$6,720.00)	
Natural		0640 -	Total						(\$6,720.00)	
Sep 2, 2021   SYSTEM   (\$208.00)		0650		Material		8		SYSTEM		Estimate Item Adjustment (0036) due to user schnod1 overridding Payment
9						8		SYSTEM	(\$208.00)	Estimate Exception of the current ayrıcın Estimate.
9						9	Sep 16,	SYSTEM	\$1,300.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Payment
10						9		SYSTEM	(\$1,300.00)	
Total   S0.00						10	Oct 1,	SYSTEM	\$1,300.00	Estimate Item Adjustment (0027) due to user schnod1 overridding Payment
Material - Total   S0.00						10		SYSTEM	(\$1,300.00)	
School   S					- Total				\$0.00	
TEMPORARY SEEDING AND MULCHING  Material  Mate				Material - To	tal				\$0.00	
TEMPORARY SEEDING AND MULCHING  Material  Mate		0650 -	Total							
2021  5 Jul 16, 2021  5 System (\$4,815.00)  - Total  So.00  Material - Total  Solution (\$3,691.50) Payment held for overrun exception.  Adjustment  OVRN 4 Jul 1, 2021  6 Aug 2, 2021  Solution (\$3,691.50) Manual negative adjustment from estimate 0004 paid for now.  Other Item Adjustment - Total  Solution (\$3,691.50) Manual negative adjustment from estimate 0004 paid for now.		0670	SEEDING AND	Material		4		SYSTEM	\$4,815.00	Estimate Item Adjustment (0047) due to user schnod1 overridding Payment
Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 46 on the current Payment Estimate.  5 Jul 16, 2021 \$0.00  Material - Total \$0.00  Other Item Adjustment OVRN 4 Jul 1, 2021 6 Aug 2, 2021 \$3,691.50 Manual negative adjustment from estimate 0004 paid for now.  OVRN - Total \$0.00  Other Item Adjustment - Total \$0.00  Other Item Adjustment - Total \$0.00						4		SYSTEM	(\$4,815.00)	
Column						5		SYSTEM	\$4,815.00	Estimate Item Adjustment (0047) due to user schnod1 overridding Payment
Material - Total  Other Item Adjustment  OVRN   4   Jul 1, 2021   schnod1 (\$3,691.50) Payment held for overrun exception.  Adjustment   6   Aug 2, 2021   schnod1   \$3,691.50   Manual negative adjustment from estimate 0004 paid for now.  OVRN - Total   \$0.00						5		SYSTEM	(\$4,815.00)	
Other Item Adjustment  OVRN 4 Jul 1, 2021 (\$3,691.50) Payment held for overrun exception.  6 Aug 2, 2021 Schnod1 \$3,691.50 Manual negative adjustment from estimate 0004 paid for now.  OVRN - Total \$0.00  Other Item Adjustment - Total \$0.00					- Total				\$0.00	
Adjustment 2021				Material - To	tal				\$0.00	
					OVRN	4		schnod1	(\$3,691.50)	Payment held for overrun exception.
Other Item Adjustment - Total \$0.00						6		schnod1	\$3,691.50	Manual negative adjustment from estimate 0004 paid for now.
					OVRN - Tota	al			\$0.00	
				Other Item A	djustment - T	otal			\$0.00	
Overrun Overrun 4 Jul 1, 2021 \$3,691.50 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) overridding Payment Estimate Exception 63 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 2.30.				Overrun	Overrun	4		SYSTEM	\$3,691.50	Estimate Item Adjustment (0046) overridding Payment Estimate Exception 63 on the current Payment Estimate. Material Insufficiency Quantity 3.000;
4 Jul 1, 2021 (\$3,691.50)						4		SYSTEM	(\$3,691.50)	
5 Jul 16, 2021 (\$3,691.50) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						5		SYSTEM	(\$3,691.50)	
5 Jul 16, SYSTEM \$3,691.50 This adjustment offsets the original system-generated Overrun Payment						5	Jul 16, 2021	SYSTEM	\$3,691.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) overridding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 2.30.
on the current Payment Estimate. Material Insufficiency Quantity 3.000;						6	Aug 2, 2021	SYSTEM	(\$3,691.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0670	TEMPORARY SEEDING AND MULCHING	Overrun	Overrun	8	Sep 2, 2021	SYSTEM	\$3,691.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1605.00000 - 1605.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0670 -	· Total						\$0.00	
	0680	SILT FENCE	Material		2	Jun 2, 2021	SYSTEM	\$10,641.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user woodwj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$10,641.00)	
					3	Jun 16, 2021	SYSTEM	\$10,641.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$10,641.00)	
					4	Jul 1, 2021	SYSTEM	\$14,637.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schnod1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$14,637.00)	
					5	Jul 16, 2021	SYSTEM	\$14,637.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$14,637.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0680 -	· Total						\$0.00	
	0730	MGS GUARDRAIL	Construction Stockpile STMI		2	Jun 2, 2021	SYSTEM	\$16,625.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$16,625.00	
			Construction	Stockpile S	TMI - Tota			\$16,625.00	
		· Total						\$16,625.00	
	0740	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile		9	Sep 16, 2021	SYSTEM	(\$9,252.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$9,252.00)	
				i Stockpile - 1			0) (0 === 1	(\$9,252.00)	
			Construction Stockpile STMI		2	Jun 2, 2021	SYSTEM	\$32,582.46	Payment Estimate Item Adjustment generated Stockpile Transaction
			O - marking a tile of	- Total	FAUL Todal			\$32,582.46	
			Construction	Stockpile S			CVCTEA	\$32,582.46	This adjustment effects the original quature are set of Material Day
			Material		9	Sep 16, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$15,000.00)	
					10	Oct 1, 2021	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$15,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0740 -	· Total						\$23,330.46	
	0750	MGS END ANCHOR	Construction Stockpile STMI		2	Jun 2, 2021	SYSTEM	\$1,158.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,158.00	
			Construction	Stockpile S	TMI - Tota			\$1,158.00	
		· Total						\$1,158.00	
	0760	TYPE A	Construction		9	Sep 16,	SYSTEM	(\$6,180.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J4P3275	0760	CRASHWORTHY	Stockpile			2021												
		END TERMINAL (MASH)		- Total				(\$6,180.00)										
			Construction	Stockpile -	Total			(\$6,180.00)										
			Construction Stockpile		2	Jun 2, 2021	SYSTEM	\$13,905.00	Payment Estimate Item Adjustment generated Stockpile Transaction									
			STMI	- Total				\$13,905.00										
			Construction	Stockpile S	ΓΜΙ - Total			\$13,905.00										
	0760 -	· Total						\$7,725.00										
	5002	PAVEMENT EDGE TREATMENT	Material		8	Sep 2, 2021	SYSTEM	\$2,627.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.									
					8	Sep 2, 2021	SYSTEM	(\$2,627.00)										
					9	Sep 16, 2021	SYSTEM	\$2,627.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 46 on the current Payment Estimate.									
					9	Sep 16, 2021	SYSTEM	(\$2,627.00)										
					10	Oct 1, 2021	SYSTEM	\$2,627.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.									
					10	Oct 1, 2021	SYSTEM	(\$2,627.00)										
				- Total		2021		\$0.00										
			Material - To					\$0.00										
	5002 -	· Total						\$0.00										
J4P3275 -	Total							\$38,132.86										
J4S3278	1120	GRAVEL (A)	Material		3	Jun 16, 2021	SYSTEM	\$10,402.69	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					3	Jun 16, 2021	SYSTEM	(\$10,402.69)										
					4	Jul 1, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					4	Jul 1, 2021	SYSTEM	(\$10,374.56)										
																	(\$10,011.00)	
					5	Jul 16, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					5	2021 Jul 16,	SYSTEM SYSTEM	, , ,	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment									
						2021		\$10,374.56	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment									
					5	2021 Jul 16, 2021 Aug 2,	SYSTEM	\$10,374.56 (\$10,374.56)	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment									
					5	Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM	\$10,374.56 (\$10,374.56) \$10,374.56	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment									
					5 6	2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM	\$10,374.56 (\$10,374.56) \$10,374.56 (\$10,374.56)	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment									
					5 6 6 7	2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$10,374.56 (\$10,374.56) \$10,374.56 (\$10,374.56) \$10,374.56	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment									
					5 6 6 7	2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,374.56 (\$10,374.56) \$10,374.56 (\$10,374.56) \$10,374.56	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment									
					5 6 7 7 8	2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,374.56 (\$10,374.56) \$10,374.56 (\$10,374.56) \$10,374.56 (\$10,374.56) \$10,374.56	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment									
					5 6 7 7 8	2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$10,374.56 (\$10,374.56) \$10,374.56 (\$10,374.56) \$10,374.56 (\$10,374.56) \$10,374.56	Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1120	GRAVEL (A)	Material						Estimate Exception 5 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$10,374.56)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1120 -	Total						\$0.00	
	1130	BIT. PAVEMENT MIXTURE	Price FUEL		2	Jun 2, 2021	SYSTEM	\$202.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		PG64-22 (BP-1)		- Total				\$202.21	
			Price FUEL -	Total				\$202.21	
	1130 -	Total						\$202.21	
	1140	TACK COAT	Material		2	Jun 2, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$232.50)	
					3	Jun 16, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$232.50)	
					4	Jul 1, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$232.50)	
					5	Jul 16, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$232.50)	
					6	Aug 2, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$232.50)	
					7	Aug 16, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$232.50)	
					8	Sep 2, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$232.50)	
					9	Sep 16, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$232.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1140 -	Total						\$0.00	
	1150	3 IN. CONCRETE MEDIAN STRIP	Material		2	Jun 2, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$3,374.18)	
					3	Jun 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$3,374.18)	
						2021			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1150	3 IN. CONCRETE MEDIAN STRIP	Material		4	Jul 1, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$3,374.18)	
					5	Jul 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$3,374.18)	
					6	Aug 2, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schood1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$3,374.18)	
					7	Aug 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$3,374.18)	
					8	Sep 2, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$3,374.18)	
					9	Sep 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schood1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$3,374.18)	
					10	Oct 1, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$3,374.18)	
				- Total				\$0.00	
	1150 -	- Total	Material - To	tal				\$0.00 \$0.00	
	1160	CONSTRUCTION SIGNS	Material		1	May 17, 2021	SYSTEM	\$256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$256.00)	
					2	Jun 2, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodwj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$880.00)	
					3	Jun 16, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$880.00)	
					3		SYSTEM	(\$880.00) \$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
						2021 Jul 1,			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment
					4	2021 Jul 1, 2021 Jul 1,	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment
					4	2021 Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment
				- Total	4 5	2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM	\$880.00 (\$880.00) \$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment
			Material - To		4 5	2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM	\$880.00 (\$880.00) \$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1170	FLAG ASSEMBLY	Material		2	Jun 2, 2021	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$50.00)	
					3	Jun 16, 2021	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$50.00)	
					4	Jul 1, 2021	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$50.00)	
					5	Jul 16, 2021	SYSTEM	\$50.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$50.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1170 -							\$0.00	
	1190	CHANNELIZER (TRIM LINE)	Material		1	May 17, 2021	SYSTEM	\$41.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$41.00)	
					2	Jun 2, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodwj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$80.00)	
					3	Jun 16, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$80.00)	
					4	Jul 1, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$80.00)	
					5	Jul 16, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$80.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1190 -	Total						\$0.00	
	1200	TYPE III MOVEABLE BARRICADE WITH	Material		2	Jun 2, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodwj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		LIGHTS			2	Jun 2, 2021	SYSTEM	(\$1,650.00)	
					3	Jun 16, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$1,650.00)	
					4	Jul 1, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,650.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1200	TYPE III MOVEABLE BARRICADE WITH	Material		5	Jul 16, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
		LIGHTS			5	Jul 16, 2021	SYSTEM	(\$1,650.00)	
				- Total		2021		\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment	OVRN	6	Aug 2, 2021	schnod1	\$375.00	Manual negative adjustment from estimate 0002 paid for now.
				OVRN - Total	al			\$375.00	
			Other Item A	.djustment - T	otal			\$375.00	
			Overrun	Overrun	2	Jun 2, 2021	woodwj1	(\$375.00)	Manual adjustment for the overrun with material exceptions. This will be removed once they are resolved
					2	Jun 2, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 35 on the current Payment Estimate. Material Insufficiency Quantity 22.000;
					2	Jun 2,	SYSTEM	(\$375.00)	Overrun Quantity Balance 5.00.
					3	Jun 16, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Jun 16, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 54 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.
					4	Jul 1, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	Jul 1, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 59 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.
					5	Jul 16, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Jul 16, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 52 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.
					6	Aug 2, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$750.00)	
			Overrun - To	tal				(\$750.00)	
	1200 -	· Total						(\$375.00)	
	1210	CMS W/O COMMUNICATION INTERFACE,	Material		1	May 17, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		CONT F/			1	May 17, 2021	SYSTEM	(\$3,000.00)	
					2	Jun 2, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodwj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$3,000.00)	
					3	Jun 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$3,000.00)	
					4	Jul 1, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$3,000.00)	
					5	Jul 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					5	Jul 16,	SYSTEM	(\$3,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1210	CMS W/O COMMUNICATION	Material			2021			
		INTERFACE,		- Total				\$0.00	
		CONT F/	Material - To	tal				\$0.00	
	1210 -	Total						\$0.00	
	1230	PREF THERMO PVMT MARK, R/R XING	Material		3	Jun 16, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$800.00)	
					4	Jul 1, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$800.00)	
					5	Jul 16, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$800.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	1230 -	Total						\$0.00	
	1240	4 IN. WHITE WATERBORNE PAVEMENT	Material		3	Jun 16, 2021	SYSTEM	\$1,904.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
		MARKING			3	Jun 16, 2021	SYSTEM	(\$1,904.70)	
					4	Jul 1, 2021	SYSTEM	\$1,904.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,904.70)	
					5	Jul 16, 2021	SYSTEM	\$1,904.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$1,904.70)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1240 -	Total						\$0.00	
	1250	4 IN. YELLOW WATERBORNE PAVEMENT	Material		3	Jun 16, 2021	SYSTEM	\$737.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
		MARKING			3	Jun 16, 2021	SYSTEM	(\$737.70)	
					4	Jul 1, 2021	SYSTEM	\$737.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$737.70)	
					5	Jul 16, 2021	SYSTEM	\$737.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$737.70)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1250 -	Total						\$0.00	
	1260	8 IN. WHITE WATERBORNE PAVEMENT	Material		3	Jun 16, 2021	SYSTEM	\$56.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
		MARKING			3	Jun 16, 2021	SYSTEM	(\$56.00)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1260	8 IN. WHITE WATERBORNE PAVEMENT	Material		4	Jul 1, 2021	SYSTEM	\$56.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
		MARKING			4	Jul 1, 2021	SYSTEM	(\$56.00)	
					5	Jul 16, 2021	SYSTEM	\$56.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$56.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1260 -	- Total						\$0.00	
	1270	WATERBORNE PAVEMENT	Material		3	Jun 16, 2021	SYSTEM	\$120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
		MARKING			3	Jun 16, 2021	SYSTEM	(\$120.00)	
					4	Jul 1, 2021	SYSTEM	\$120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$120.00)	
					5	Jul 16, 2021	SYSTEM	\$120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$120.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1270 -	· Total						\$0.00	
	1320	12 IN. PIPE	Material		1	May 17,	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment
		CULVERT GROUP C				2021			Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$2,700.00)	
					1 2	May 17,	SYSTEM SYSTEM	(\$2,700.00)	
						May 17, 2021 Jun 2,			Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment
					2	May 17, 2021 Jun 2, 2021 Jun 2,	SYSTEM	\$2,700.00	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment
					2	May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM	\$2,700.00	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment
					2 2 3	May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM	\$2,700.00 (\$2,700.00) \$2,700.00	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment
					2 2 3 3	May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021 Jun 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00)	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment
					2 2 3 3 4	May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00) \$2,700.00	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment
					2 2 3 3 4	May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00)	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment
					2 2 3 3 4 4 5	May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00)	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment
					2 2 3 3 4 4 5	May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00) \$2,700.00	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.
					2 2 3 3 4 4 5 5	May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM	\$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00) \$2,700.00 (\$2,700.00) (\$2,700.00) \$2,700.00	Estimate Exception 14 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1320	12 IN. PIPE CULVERT GROUP C	Material		8	Sep 2, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$2,700.00)	
					9	Sep 16, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schood1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$2,700.00)	
					10	Oct 1, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$2,700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		Total						\$0.00	
	1330	18 IN. PIPE CULVERT GROUP C	Material		1	May 17, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$3,250.00)	
					2	Jun 2, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$3,250.00)	
					3	Jun 16, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$3,250.00)	
					4	Jul 1, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$3,250.00)	
					5	Jul 16, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$3,250.00)	
					6	Aug 2, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$3,250.00)	
					7	Aug 16, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$3,250.00)	
					8	Sep 2, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$3,250.00)	
					9	Sep 16, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$3,250.00)	
					10	Oct 1, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					10	Oct 1,	SYSTEM	(\$3,250.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1330	18 IN. PIPE CULVERT GROUP	Material			2021			
		С		- Total				\$0.00	
	4220	Total	Material - To	tal				\$0.00	
	1340	Total  SEEDING - COOL SEASON MIXTURES	Material		1	May 17, 2021	SYSTEM	\$0.00 \$1,051.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$1,051.38)	
					2	Jun 2, 2021	SYSTEM	\$1,051.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodwj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$1,051.38)	
					3	Jun 16, 2021	SYSTEM	\$1,051.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$1,051.38)	
					4	Jul 1, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,188.00)	
					5	Jul 16, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$1,188.00)	
					6	Aug 2, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,188.00)	
					7	Aug 16, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$1,188.00)	
					8	Sep 2, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$1,188.00)	
					9	Sep 16, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$1,188.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		Total						\$0.00	
	1350	ROCK DITCH CHECK	Material		1	May 17, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$3,360.00)	
					2	Jun 2, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$3,360.00)	
					3	Jun 16, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1350	ROCK DITCH CHECK	Material		3	Jun 16, 2021	SYSTEM	(\$3,360.00)	
					4	Jul 1, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$3,360.00)	
					5	Jul 16, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$3,360.00)	
					6	Aug 2, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$3,360.00)	
					7	Aug 16, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$3,360.00)	
					8	Sep 2, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$3,360.00)	
					9	Sep 16, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$3,360.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1350 -						01/0==1/	\$0.00	
	1370	SILT FENCE	Material		3	Jun 16, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$188.00)	
					4	Jul 1, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$188.00)	
					5	Jul 16, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$188.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1370 -							\$0.00	
	1380	CONCRETE FOOTINGS, EMBEDDED	Material		3	Jun 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$165.00)	
					4	Jul 1, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$165.00)	
					5	Jul 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1380	CONCRETE FOOTINGS,	Material		5	Jul 16, 2021	SYSTEM	(\$165.00)	
		EMBEDDED			6	Aug 2, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$165.00)	
					7	Aug 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$165.00)	
					8	Sep 2, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$165.00)	
					9	Sep 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$165.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	1380 -	Total						\$0.00	
	1400	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Overrun	Overrun	3	Jun 16, 2021	SYSTEM	(\$24,504.32)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		. 55 . 22 (51)			4	Jul 1, 2021	SYSTEM	\$2.45	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.26999 - 59.61000, 'is applied (if non-zero).
					6	Aug 2, 2021	SYSTEM	\$24,501.87	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.26999 - 59.61000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
			Price FUEL		2	Jun 2, 2021	SYSTEM	\$8,375.96	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Jun 16, 2021	SYSTEM	\$1,113.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 1, 2021	SYSTEM	(\$0.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$9,489.27	
			Price FUEL -	Total				\$9,489.27	
	1400 -							\$9,489.27	
	1410	BITUMINOUS PAVEMENT MIXTURE	Price FUEL		2	Jun 2, 2021	SYSTEM	\$12,227.43	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		PG64-22 (BAS			4	Jul 1, 2021	SYSTEM	\$0.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$12,227.45	
		Tetal	Price FUEL -	Total				\$12,227.45	
	1410 -		Metarial		2	lue 0	ever:	\$12,227.45	This adjustment effects the adjust a second of the second
	1420	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		2	Jun 2, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		1 307-22 (001)			2	Jun 2, 2021	SYSTEM	(\$139,327.38)	
					3	Jun 16, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$139,327.38)	
					4	Jul 1, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
-,		-	Туре	Adjustment Type	Number	Date	Ву		
J4S3278	1420	BITUMINOUS PAVEMENT	Material		4	Jul 1, 2021	SYSTEM	(\$139,327.38)	
		MIXTURE PG64-22 (SUR			5	Jul 16, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$139,327.38)	
					6	Aug 2, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$139,327.38)	
					7	Aug 16, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$139,327.38)	·
					8	Sep 2, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$139,327.38)	
					9	Sep 16, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$139,327.38)	
					10	Oct 1, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$139,327.38)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Other Item Adjustment	OVRN	6	Aug 2, 2021	schnod1	\$5,261.48	Manual negative adjustment from estimate 0002 paid for now.
				OVRN - Tota				\$5,261.48	
				djustment - T				\$5,261.48	
			Overrun	Overrun	2	Jun 2, 2021	woodwj1	(\$5,261.48)	Manual adjustment for the overrun with material exceptions. This will be removed once they are resolved
					2	Jun 2, 2021	SYSTEM	(\$5,261.48)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					2	Jun 2, 2021	SYSTEM	\$5,261.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 2367.500; Overrun Quantity Balance 87.00.
					3	Jun 16, 2021	SYSTEM	(\$5,261.48)	Averaged Price Adjustment from this item on all previous payment estimates of '1.62680' is applied (if non-zero).
					3	Jun 16, 2021	SYSTEM	\$5,261.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) overridding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 2367.500; Overrun Quantity Balance 87.00.
					4	Jul 1, 2021	SYSTEM	(\$5,261.48)	Averaged Price Adjustment from this item on all previous payment estimates of '1.62680' is applied (if non-zero).
					4		SYSTEM	(\$5,261.48) \$5,261.48	
						2021 Jul 1,			of '1.62680' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) overridding Payment Estimate Exception 60 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;
					4	Jul 1, 2021 Jul 16,	SYSTEM	\$5,261.48	of '1.62680' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) overridding Payment Estimate Exception 60 on the current Payment Estimate. Material Insufficiency Quantity 2367.500; Overrun Quantity Balance 87.00.  Averaged Price Adjustment from this item on all previous payment estimates
				Overrun - T	5 5	Jul 16, 2021 Jul 16, 2021 Jul 16,	SYSTEM	\$5,261.48 (\$5,261.48)	of '1.62680' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) overridding Payment Estimate Exception 60 on the current Payment Estimate. Material Insufficiency Quantity 2367.500; Overrun Quantity Balance 87.00.  Averaged Price Adjustment from this item on all previous payment estimates of '1.62680' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 53 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;
			Overrun - To		5 5	Jul 16, 2021 Jul 16, 2021 Jul 16,	SYSTEM	\$5,261.48 (\$5,261.48) \$5,261.48	of '1.62680' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) overridding Payment Estimate Exception 60 on the current Payment Estimate. Material Insufficiency Quantity 2367.500; Overrun Quantity Balance 87.00.  Averaged Price Adjustment from this item on all previous payment estimates of '1.62680' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 53 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;



					7	Aug 2, 2021 Aug 16,	SYSTEM SYSTEM	(\$22,375.00) \$22,375.00	This adjustment offsets the original system-generated Material Payment
					7	2021 Aug 16,	SYSTEM	\$22,375.00 (\$22,375.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	2021 Sep 2, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$22,375.00)	·
					9	Sep 16, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$22,375.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1430 -	- Total						\$0.00	
					2	Jun 2,	SYSTEM	\$18,303.54	Payment Estimate Item Adjustment generated Stockpile Transaction
					0	Jun 2	SYSTEM	\$18.303.54	
					0	Jun 2	SYSTEM	\$18,303,54	
	1430 -	- I Otal			0	lun 2	QVQTEM4		
	1430 -	- Total						\$0.00	
	1430 -	- Total							
			Material - To	tal				\$0.00	
			Material Te						
				- Total				\$0.00	
				Total			S. STEIVI	,	
					9		SYSTEM	(\$22,375.00)	Estimate Exception 14 on the current Fayment Estimate.
						2021			Estimate Item Adjustment (0011) due to user schnod1 overridding Payment
					9	Sep 16,	SYSTEM	\$22,375.00	
					8		SYSTEM	(\$22,375.00)	
					8		SVSTEM	(\$22.375.00)	
					8	Sep 2,	SYSTEM	\$22,375.00	Estimate Item Adjustment (0012) due to user schnod1 overridding Payment
					7		SYSTEM	(\$22,375.00)	
					7		SYSTEM	\$22,375.00	Estimate Item Adjustment (0014) due to user schnod1 overridding Payment
						2021			This adjustment offsets the original system-generated Material Payment
					6	2021	SYSTEM	(\$22.375.00)	Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	2021 Aug 2,	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment
					5	2021 Jul 16,	SYSTEM	(\$22,375.00)	Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	2021 Jul 16,	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment
					4	2021 Jul 1,	SYSTEM	(\$22,375.00)	Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	2021 Jul 1,	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment
					3	2021 Jun 16,	SYSTEM	(\$22,375.00)	Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	2021 Jun 16,	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment
					2	Jun 2,	SYSTEM	(\$21,587.50)	Estimate Exception 4 on the current Payment Estimate.
	1430	TACK COAT	Material		2	Jun 2, 2021	SYSTEM	\$21,587.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodwj1 overridding Paymen
	1420 -	- Total						\$3,851.45	
		,	Price FUEL -	Total				\$3,851.45	
		PAVEMENT MIXTURE PG64-22 (SUR		- Total		2021		\$3,851.45	
3278	1420	BITUMINOUS	Price FUEL	Туре	2	Jun 2,	SYSTEM	\$3,851.45	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks