

Pay Estimate Created Date: August 2, 2021

Progress Estimate 6	Number	Contract ID Prime Contrac	210219-C04 ctor Ideker, Inc.		riod Start riod End	July 16, 202 August 1, 20	21 Net	ginal Contract Amount Change Order Amount rent Contract Amount	\$4,357,163.79 (\$81,502.62) \$4,275,661.17
Approval Date									By User
August 2, 2021			Generated and A	Generated and Approved (and should be considered Draft) at the Project Office Level by					
August 2, 2021		Re	eviewed and Appro	ved (and s	should be co	onsidered Draf	t) at the F	Resident Engineer Level by	warrem1
August 3, 2021			F	Reviewed	and Approv	ed at the Cent	ral Office	Controllers Office Level by	ramses1
Original Completio	Current Con	npletion Date Actual Complet			ion Date	%	of Current Contract Amou	nt Complete	
December 1, 20	21	Decembe	er 1, 2021				62.24%		
	Contract I	nformational Dat	tes			Milestones			
Date Description	Original C	ompletion Date	Current Complet	ion Date	No Milest	ones Exist for	Contract		
Acceptance Date									
Awarded Date	March 3, 2	021	March 3, 2021						
Letting Date	February 1	9, 2021	February 19, 2021						
Notice to Proceed Date	otice to Proceed Date May 3, 2021								
Work Began Date									

Contract Total Pay For Estimate No. 6											
		This Estimate	Previous	To Date							
210219-C04											
	Total Posted Items Pay	\$589,600.88	\$2,071,411.40	\$2,661,012.28							
	Gross Item Adjustments	(\$84,259.64)	\$69,227.89	(\$15,031.75)							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
	•		\$2,140,639.29	\$2,645,980.53							
Contract Total Pag	yable This Estimate:	\$505,341.24									

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3275	0020	2022010	REMOVAL OF IMPROVEMENTS	LS	\$69,665.000	0.3	\$20,899.50
	0030	2031000	CLASS A EXCAVATION	CUYD	\$12.000	1,007	\$12,084.00
	0040	2035500	EMBANKMENT IN PLACE	CUYD	\$20.000	7,540	\$150,800.00
	0050	2036000	COMPACTING EMBANKMENT	CUYD	\$2.000	839	\$1,678.00
	0090	2142000	FURNISHING ROCK FILL	CUYD	\$19.200	907	\$17,414.40
	0100	2143000	PLACING ROCK FILL	CUYD	\$11.000	907	\$9,977.00
	0310	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	EA	\$2,000.000	2	\$4,000.00
	0410	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	LF	\$33.000	1,490	\$49,170.00
	0451	6181000	MOBILIZATION	LS	\$318,927.280	1	\$318,927.28
	0550	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$3.350	642	\$2,150.70
	0560	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$5,000.000	0.5	\$2,500.00
Project J4	P3275 - To	tal					\$589,600.88

Project J4P3275 - Total \$589,600.88

Overall - Total \$589,600.88

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3275	0030	CLASS A EXCAVATION	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,007	\$0.10	\$104.73

Revision 4/1/2020 Page 1 of 32



Pay Estimate Created Date: August 2, 2021

Progress Estimate Number
6
Contract ID 210219-C04 Pay Period Start July 16, 2021 Original Contract Amount (\$4,357,163.79\$)
Prime Contractor Ideker, Inc. Pay Period End August 1, 2021 Original Contract Amount Current Contract Amount (\$81,502.62)
Current Contract Amount Current Contract Amount Current Contract Amount Current Contract Amount (\$4,275,661.17\$)

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3275	0040	EMBANKMENT IN PLACE	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,580	\$0.18	\$287.56
	0040	EMBANKMENT IN PLACE	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,640	\$0.18	\$298.48
	0040	EMBANKMENT IN PLACE	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,740	\$0.18	\$316.68
	0040	EMBANKMENT IN PLACE	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	1,920	\$0.18	\$349.44
	0040	EMBANKMENT IN PLACE	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	660	\$0.18	\$120.12
	0040	EMBANKMENT IN PLACE	Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-1,580	\$20.18	(\$31,887.56)
	0040	EMBANKMENT IN PLACE	Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-1,640	\$20.18	(\$33,098.48)
	0040	EMBANKMENT IN PLACE	Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-1,740	\$20.18	(\$35,116.68)
	0040	EMBANKMENT IN PLACE	Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-815	\$20.18	(\$16,448.33)
	0040	EMBANKMENT IN PLACE	Material			-35,651	\$20.00	(\$713,020.00)
	0040	0040 EMBANKMENT IN PLACE Ov			This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.	1,580	\$20.18	\$31,887.56
(0040	EMBANKMENT IN PLACE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.	1,640	\$20.18	\$33,098.48
	0040	EMBANKMENT IN PLACE	Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.	1,740	\$20.18	\$35,116.68
	0040	EMBANKMENT IN PLACE	BANKMENT IN PLACE Overrun		This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.	815	\$20.18	\$16,448.33
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	35,651	\$20.00	\$713,020.00
	0040	EMBANKMENT IN PLACE	Other Item Adjustment	Overrun	Payment held until quantity is verified by contractor/MoDOT.			(\$115,500.00)
	0050	COMPACTING EMBANKMENT	Material				\$2.00	(\$1,678.00)
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user schnod1	839	\$2.00	\$1,678.00



Pay Estimate Created Date: August 2, 2021

Prog	ress E	6 Contract Prime Co		210219-C04 deker, Inc.	Pay Period End August 1, 2021 Net Char	Contract Am nge Order An Contract Am	nount (\$8	,357,163.79 31,502.62) ,275,661.17
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3275					overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-4,636.9	\$10.50	(\$48,687.45
	0120	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	4,636.9	\$10.50	\$48,687.45
	0160	MISC.	Material			-4,419.2	\$28.49	(\$125,903.01)
	0160	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	4,419.2	\$28.49	\$125,903.01
	0420 TEMPORARY TRAFFION BARRIER HEIGH TRANSITION		Material			-2	\$850.00	(\$1,700.00)
	0420	TEMPORARY TRAFFIC BARRIER HEIGHT TRANSITION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	2	\$850.00	\$1,700.00
	0480	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material			-11,794	\$1.00	(\$11,794.00)
	0480	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0028) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	11,794	\$1.00	\$11,794.00
	0490	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material			-14,884	\$1.00	(\$14,884.00)
	0490	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	14,884	\$1.00	\$14,884.00
	0590	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material			-2	\$606.00	(\$1,212.00)
	0590	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	2	\$606.00	\$1,212.00
	0640	ROCK DITCH CHECK	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-77	\$40.00	(\$3,080.00)
	0640	ROCK DITCH CHECK	Other Item Adjustment	Overrun	Manual negative adjustment from estimate 0004 paid for now.			\$3,080.00
	0670	TEMPORARY SEEDING AND MULCHING	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-2.3	\$1,605.00	(\$3,691.50)
	0670	TEMPORARY SEEDING AND MULCHING	Other Item Adjustment	Overrun	Manual negative adjustment from estimate 0004 paid for now.			\$3,691.50
J4S3278	1120	GRAVEL (A)	Material			-118	\$87.92	(\$10,374.56)

Revision 4/1/2020 Page 3 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 2, 2021

Prog	gress Es	6 Contract Prime Co		10219-C04 deker, Inc.	Pay Period End August 1, 2021 Net Cha	Contract Amonge Order Amonge Order Amonge Contract Amonge Cont	nount (\$8	357,163.79 1,502.62) 275,661.17
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3278	1120	GRAVEL (A)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		\$87.92	\$10,374.56
	1140	TACK COAT	Material			-93	\$2.50	(\$232.50)
	1140	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		\$2.50	\$232.50
	1150	3 IN. CONCRETE MEDIAN STRIP	Material			-11.3	\$298.60	(\$3,374.18)
	1150	3 IN. CONCRETE MEDIAN STRIP	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		\$298.60	\$3,374.18
	1200	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		\$75.00	(\$375.00)
	1200	TYPE III MOVEABLE BARRICADE WITH LIGHTS	Other Item Adjustment	Overrun	Manual negative adjustment from estimate 0002 paid for now.			\$375.00
	1320	12 IN. PIPE GROUP C	Material			-50	\$54.00	(\$2,700.00)
	1320	12 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.		\$54.00	\$2,700.00
	1330	18 IN. PIPE GROUP C	Material			-50	\$65.00	(\$3,250.00)
	1330	18 IN. PIPE GROUP C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		\$65.00	\$3,250.00
	1340	SEEDING - COOL SEASON MIXTURES	Material			-0.2	\$5,940.00	(\$1,188.00)
	1340	SEEDING - COOL SEASON MIXTURES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.		\$5,940.00	\$1,188.00
	1350	ROCK DITCH CHECK	Material			-84	\$40.00	(\$3,360.00)
	1350	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.		\$40.00	\$3,360.00
	1380	CONCRETE FOOTINGS, EMBEDDED	Material			-0.1	\$1,650.00	(\$165.00)
	1380	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.		\$1,650.00	\$165.00
	1400	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.26999 - 59.61000, 'is		\$61.27	\$24,501.87

Page 4 of 32 Revision 4/1/2020



Pay Estimate Created Date: August 2, 2021

Prog	jress Es	timate Number 6				Pay Period Start Pay Period End	July 16, 2021 August 1, 2021	Net Char	Original Contract Amount \$4, Net Change Order Amount (\$8 Current Contract Amount \$4,			
Project Number	Line No.	Item Descript	ion	Adjustment Type Other Item Comments Type Type					Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J4S3278							applied (if	non-zero).				
	1420	BITUMINOUS PA MIXTURE (SURFACE LE	PG64-22	Material					-2,367.5	\$58.85	(\$139,327.38)	
-	1420	BITUMINOUS PA MIXTURE (SURFACE LE	PG64-22	Material		generated Ma Adjustmen overridding Paym	nt offsets the origir terial Payment Est t (0021) due to use nent Estimate Exce le current Paymen	imate Item er schnod1 eption 6 on	2,367.5	\$58.85	\$139,327.38	
	1420	BITUMINOUS PA MIXTURE (SURFACE LE	PG64-22	Other Item Adjustment	Overrun	Manual negat	ive adjustment froi 0002 pa	m estimate iid for now.			\$5,261.48	
	1430	TA	CK COAT	Material					-8,950	\$2.50	(\$22,375.00)	
	generated M Adjustme overridding Pay					generated Ma Adjustmen overridding Payn	nt offsets the origir terial Payment Est t (0022) due to use nent Estimate Exce le current Paymen	imate Item er schnod1 eption 9 on	8,950	\$2.50	\$22,375.00	
Total											(\$84,259.64)	

Revision 4/1/2020 Page 5 of 32



					Co	ontract Project Information	1				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J4P3275	FAF 92-1(35)	Intersection improvements	92	PLATTE	at intersection of Rte. 45 S	pur					
J4S3278	FAS S302(80)	Resurface	45	PLATTE	from Route 92 to Route 45	from Route 92 to Route 45					
Γotals by .	Job Numbe	rs									
J4P3275		d Item Pay Item Adjustme		Item Pay	This Estimate \$589,600.88 (\$114,022.99) \$475,577.89	Previous \$1,046,875.26 \$52,202.32 \$1,099,077.58	To Date \$1,636,476.14 (\$61,820.67) \$1,574,655.47				
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J4S3278		d Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$29,763.35 \$29,763.35	Previous \$1,024,536.14 \$17,025.57 \$1,041,561.71	To Date \$1,024,536.14 \$46,788.92 \$1,071,325.06				
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 6 of 32



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 3040504, Project Item Line Number 0120, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 3101002, Project Item Line Number 1120, Material Set 310100296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 4019905, Project Item Line Number 0160, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4020520, Project Item Line Number 1420, Material Set 402052096, Material 0402SLPMSL - Plant Mix for Surface Leveling, Acceptance Action Generic AspSL is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4071005, Project Item Line Number 1140, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4071005, Project Item Line Number 1140, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4071005, Project Item Line Number 1430, Material Set 407100596, Material 1015EASS1 - Emulsified Asphalt SS-1, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 4071005, Project Item Line Number 1430, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 6083003, Project Item Line Number 1150, Material Set 608300396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6174000A, Project Item Line Number 0420, Material Set 6174000A96, Material 0617MBPKBT.1PC - One Piece Barrier Height-Transition Sect, Acceptance Action Generic 0617MBPKBT.1PC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6205301B, Project Item Line Number 0480, Material Set 6205301B96, Material 1048PMRPMTWH - Marking Tape Removable White, Acceptance Action Generic 1048PMRPMTWH is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 6205303B, Project Item Line Number 0490, Material Set 6205303B96, Material 1048PMRPMTYL - Marking Tape Removable Yellow, Acceptance Action Generic 1048PMRPMTYL is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 7250412, Project Item Line Number 1320, Material Set 725041296, Material 1020CPCSZC.012 - CulvPipe Zn Ctd Corrug Stl 12" 300mm, Acceptance Action Generic 1020CPCSZC.012 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 7250418, Project Item Line Number 1330, Material Set 725041896, Material 1020CPCSZC.018 - CulvPipe Zn Ctd Corrug Stl 18" 450mm, Acceptance Action Generic 1020CPCSZC.018 is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3275, Item 7320618A, Project Item Line Number 0590, Material Set 7320618A96, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 8051000A, Project Item Line Number 1340, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action	No Remark was entered by Engineer	schnod1	Overridden

Revision 4/1/2020 Page 7 of 32



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 0805SD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 8061005, Project Item Line Number 1350, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3278, Item 9031010, Project Item Line Number 1380, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0010, Contract Line Item Number 0010, Item 2013000, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0070, Contract Line Item Number 0070, Item 2071000, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0040, Contract Line Item Number 0040, Item 2035500, Minor Item.	No Remark was entered by Engineer	schnod1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4S3278, Project Item Line Number 1200, Contract Line Item Number 1200, Item 6161031, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0640, Contract Line Item Number 0640, Item 8061005, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-C04, Contract Project J4P3275, Project Item Line Number 0670, Contract Line Item Number 0670, Item 8061017, Minor Item.	No Remark was entered by Engineer	schnod1	Acknowledged

Revision 4/1/2020 Page 8 of 32



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4P3275	0001	0010	2013000	CLEARING AND GRUBBING	2.00	0.00	2.00	ACRE	3.00	\$9,000.00	\$27,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.65	\$69,665.00	\$45,282.25
		0001	0030	2031000	CLASS A EXCAVATION	8,110.00	0.00	8,110.00	CUYD	1,007.00	\$12.00	\$12,084.00
		0001	0040	2035500	EMBANKMENT IN PLACE	29,876.00	0.00	29,876.00	CUYD	35,651.00	\$20.00	\$713,020.00
		0001	0050	2036000	COMPACTING EMBANKMENT	6,758.00	0.00	6,758.00	CUYD	839.00	\$2.00	\$1,678.00
		0001	0060	2063000	CLASS 3 EXCAVATION	75.00	0.00	75.00	CUYD	66.40	\$12.00	\$796.80
		0001	0070	2071000	LINEAR GRADING CLASS 1	30.90	0.00	30.90	STA	33.90	\$550.00	\$18,645.00
		0001	0090	2142000	FURNISHING ROCK FILL	2,040.00	0.00	2,040.00	CUYD	907.00	\$19.20	\$17,414.40
		0001	0100	2143000	PLACING ROCK FILL	2,040.00	0.00	2,040.00	CUYD	907.00	\$11.00	\$9,977.00
		0001	0110	3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	1,500.00	0.00	1,500.00	SQYD	0.00	\$10.50	\$0.00
		0001	0120	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	6,498.00	0.00	6,498.00	SQYD	4,636.90	\$10.50	\$48,687.45
		0001	0130	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	13,671.00	0.00	13,671.00	SQYD	0.00	\$11.65	\$0.00
		0001	0140	4010150	TYPE A2 SHOULDER	2,303.80	0.00	2,303.80	SQYD	0.00	\$23.34	\$0.00
		0001	0150	4019905	MISC.OPTIONAL PAVEMENT	10,728.50	0.00	10,728.50	SQYD	0.00	\$45.49	\$0.00
		0001	0160	4019905	MISC.OPTIONAL TEMPORARY PAVEMENT	4,621.50	0.00	4,621.50	SQYD	4,419.20	\$28.49	\$125,903.01
		0001	0170	5029905	MISC.TINTED CONCRETE PAVEMENT (8 IN. NON-	576.60	0.00	576.60	SQYD	0.00	\$90.25	\$0.00
		0001	0180	6072010	REINFORCED) WOVEN WIRE FENCE	987.00	0.00	987.00	LF	0.00	\$18.75	\$0.00
		0001	0190	6079902	MISC.US BOP Drive Gate	1.00	0.00	1.00	EA	0.00	\$2,910.00	\$0.00
		0001	0200	6083006	6 IN. CONCRETE MEDIAN STRIP	976.80	0.00	976.80	SQYD	0.00	\$55.35	\$0.00
		0001	0210	6085008	PAVED APPROACH, 8 IN.	763.40	0.00	763.40	SQYD	0.00	\$62.70	\$0.00
		0001	0220	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	21.00	0.00	21.00	LF	0.00	\$52.00	\$0.00
		0001	0230	6091011	CONCRETE CURB (OVER 6 IN. HEIGHT) TYPE S	39.00	0.00	39.00	LF	0.00	\$45.90	\$0.00
		0001	0240	6091041	CONCRETE GUTTER TYPE A	127.00	0.00	127.00	LF	0.00	\$96.25	\$0.00
		0001	0250	6091051	CURB AND GUTTER TYPE A	192.00	0.00	192.00	LF	0.00	\$34.85	\$0.00
		0001	0260	6091052	CURB AND GUTTER TYPE B	1,413.00	0.00	1,413.00	LF	0.00	\$29.90	\$0.00
		0001	0270	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	267.00	0.00	267.00	LF	0.00	\$7.70	\$0.00
		0001	0280	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	192.00	0.00	192.00	LF	0.00	\$8.90	\$0.00
		0001	0290	6092031	CONCRETE CURB LOW PROFILE TYPE E	355.00	0.00	355.00	LF	0.00	\$27.20	\$0.00
		0001	0300	6097000	ROCK LINING	6.00	0.00	6.00	CUYD	2.00	\$225.00	\$450.00
		0001	0310	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	5.00	0.00	5.00	EA	5.00	\$2,000.00	\$10,000.00
		0001	0320	6122020	REPLACEMENT SAND BARREL	8.00	0.00	8.00	EA	3.00	\$330.00	\$990.00
		0001	0330	6122030	IMPACT ATTENUATOR (RELOCATION)	10.00	0.00	10.00	EA	3.00	\$400.00	\$1,200.00
		0001	0340	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.00
		0001	0350	6161005	CONSTRUCTION SIGNS	637.00	0.00	637.00	SQFT	440.00	\$5.00	\$2,200.00
		0001	0360	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	3.00	\$50.00	\$150.00
		0001	0370	6161025	CHANNELIZER (TRIM LINE)	141.00	0.00	141.00	EA	95.00	\$23.00	\$2,185.00
		0001	0380	6161040	FLASHING ARROW PANEL	4.00	0.00	4.00	EA	0.00	\$50.00	\$0.00
		0001	0390	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	7.00	0.00	7.00	EA	0.00	\$4,900.00	\$0.00
		0001	0000	01010001	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	1.00	0.00	1.00	2,	0.00	ψ1,000.00	Q 0.00
		0001	0400	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	4.00	\$900.00	\$3,600.00
		0001	0410	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	7,925.00	0.00	7,925.00	LF	4,427.50	\$33.00	\$146,107.50
		0001	0420	6174000A		2.00	0.00	2.00	EA	2.00	\$850.00	\$1,700.00
		0001	0430	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	7,200.00	0.00	7,200.00	LF	2,792.00	\$13.00	\$36,296.00
		0001	0440	6175020A	RELOCATING TEMPORARY TRAFFIC BARRIER HEIGHT	5.00	0.00	5.00	EA	2.00	\$400.00	\$800.00
		0001	0450	6181000	TRANSITION MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$343,077.28	\$0.00
		0001	0450	6181000	MOBILIZATION	0.00	1.00	1.00	LS		\$318,927.28	\$318,927.28
		0001	0.01	3.3.000		0.00	1.00	1.00	20	1.00	-5.0,027.20	ψ310,021.20

Page 9 of 32 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4P3275	0001	0460	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0470	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	48.00	0.00	48.00	EA	0.00	\$50.00	\$0.00
		0001	0480	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	13,131.00	0.00	13,131.00	LF	11,794.00	\$1.00	\$11,794.00
		0001	0490	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	24,834.00	0.00	24,834.00	LF	14,884.00	\$1.00	\$14,884.00
		0001	0500	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,679.00	0.00	5,679.00	LF	0.00	\$0.15	\$0.00
		0001	0510	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,125.00	0.00	8,125.00	LF	0.00	\$0.18	\$0.00
		0001	0520	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,107.00	0.00	2,107.00	LF	0.00	\$0.18	\$0.00
		0001	0530	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	432.00	0.00	432.00	LF	0.00	\$3.00	\$0.00
		0001	0540	6207001	MARKING PAINT, TYPE L BEADS PAVEMENT MARKING REMOVAL	32,031.00	0.00	32,031.00	LF	16,951.00	\$0.25	\$4,237.75
		0001	0550	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,205.00	0.00	1,205.00	SQYD	642.00	\$3.35	\$2,150.70
		0001	0560	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$5,000.00	\$2,500.00
		0001	0570	7250418	18 IN. PIPE GROUP C	35.00	0.00	35.00	LF	0.00	\$100.00	\$0.00
		0001	0580	7261018	18 IN. PIPE GROUP A	74.00	0.00	74.00	LF	74.00	\$73.00	\$5.402.00
		0001	0590	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	2.00	0.00	2.00	EA	2.00	\$606.00	\$1,212.00
		0001	0600	7320818A	SECTION 18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END	4.00	0.00	4.00	EA	0.00	\$606.00	\$0.00
		0001	0610	8051000A	SECTION SEEDING - COOL SEASON MIXTURES	7.40	0.00	7.40	ACRE	0.00	\$1.605.00	\$0.00
		0001	0620	8061003	SEDIMENT TRAP EXCAVATION	191.00	0.00	191.00	CUYD	0.00	\$8.45	\$0.00
		0001	0630	8061004	SEDIMENT TRAP ROCK	51.00	0.00	51.00	CUYD	0.00	\$90.00	\$0.00
		0001	0640	8061005	ROCK DITCH CHECK	63.00	0.00	63.00	LF	140.00	\$40.00	\$5,600.00
		0001	0650	8061006	ALTERNATE DITCH CHECK	189.00	0.00	189.00	LF	0.00	\$13.00	\$0.00
		0001	0660	8061016	SEDIMENT REMOVAL	105.00	0.00	105.00	CUYD	0.00	\$13.00	\$0.00
		0001	0670	8061017	TEMPORARY SEEDING AND MULCHING	0.70	0.00	0.70	ACRE	3.00	\$1,605.00	\$4,815.00
		0001	0680	8061019	SILT FENCE	5,955.00	0.00	5,955.00	LF	4,879.00	\$3.00	\$14,637.00
		0001	0690	8064134	TYPE 1D EROSION CONTROL BLANKET	8,624.00	0.00	8,624.00	SQYD	0.00	\$1.46	\$0.00
			0700	8064135	TYPE 2A EROSION CONTROL BLANKET	2,123.00	0.00	2,123.00	SQYD	0.00	\$1.39	\$0.00
		0001	0710	8064137	TYPE 2C EROSION CONTROL BLANKET	14,850.00	0.00	14,850.00	SQYD	0.00	\$1.39	\$0.00
		0001	0720		TYPE 2D EROSION CONTROL BLANKET		0.00		SQYD	0.00		\$0.00
		0001	0730	8064138 6061060	MGS GUARDRAIL	9,964.00	0.00	9,964.00	LF	0.00	\$1.46 \$21.00	\$0.00
		0010	0740	6061061	MGS GUARDRAIL MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,238.00 2,113.00	0.00	2,113.00	LF	0.00	\$25.00	\$0.00
		0010	0750	6061080	MGS END ANCHOR	2,113.00	0.00	2,113.00	EA	0.00	\$800.00	\$0.00
		0010					0.00					
		0010	0760	9011030	TYPE A CRASHWORTHY END TERMINAL (MASH) LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	9.00		9.00	EA	0.00	\$2,433.00 \$1,793.00	\$0.00 \$0.00
		0020	0770	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	7.00	0.00	7.00	EA EA	0.00	\$2,987.50	\$0.00
		0020	0790	9011115	BRACKET ARM, 15 FT. OR 4.6 M	10.00	0.00	10.00	EA	0.00	\$852.50	\$0.00
		0020	0800	9011113	LUMINAIRE. LED-A	7.00	0.00	7.00	EA	0.00	\$473.00	\$0.00
		0020	0810	9011311	LUMINAIRE, LED-B	3.00	0.00	3.00	EA	0.00	\$205.00	\$0.00
		0020			BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT						\$7,838.00	
		0020	0820	9012230		1.00	0.00	1.00	EA	0.00		\$0.00
		0020	0830	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$13.56	\$0.00
		0020	0840	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	190.00	0.00	190.00	LF	0.00	\$15.00	\$0.00
		0020	0850	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	20.00	0.00	20.00	LF	0.00	\$15.52	\$0.00
		0020	0860	9015010	TRENCHING TYPE I	92.00	0.00	92.00	LF	0.00	\$10.05	\$0.00
		0020	0870	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	0.00	\$513.40	\$0.00
		0020	0880	9017002	CABLE, 2 AWG 1 CONDUCTOR	330.00	0.00	330.00	LF	0.00	\$3.30	\$0.00
		0020	0890	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	990.00	0.00	990.00	LF	0.00	\$1.76	\$0.00
		0020	0900	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	2,300.00	0.00	2,300.00	LF	0.00	\$3.27	\$0.00

Revision 4/1/2020 Page 10 of 32



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10219-C04	J4P3275				NEUTRAL, 8 AWG					,		
		0020	0910	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	7.00	0.00	7.00	EA	0.00	\$970.00	\$0.00
		0020	0920	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	3.00	0.00	3.00	EA	0.00	\$970.00	\$0.00
		0020	0930	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY	1.00	0.00	1.00	EA	0.00	\$5,434.00	\$0.00
		0040	0940	9031010	CONCRETE FOOTINGS, EMBEDDED	0.40	0.00	0.40	CUYD	0.00	\$1,650.00	\$0.00
		0040	0950	9031210	STRUCTURAL STEEL POSTS	190.00	0.00	190.00	LB	0.00	\$4.00	\$0.00
		0040	0960	9031220	PIPE POSTS	692.00	0.00	692.00	LB	0.00	\$5.00	\$0.00
		0040	0970	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	6.00	0.00	6.00	EA	0.00	\$225.00	\$0.00
		0040	0980	9031270A	2 IN. PSST POST - 12 GA.	277.00	0.00	277.00	LF	0.00	\$11.00	\$0.00
		0040	0990	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	48.00	0.00	48.00	LF	0.00	\$19.00	\$0.00
		0040	1000	9031272	2.25 IN. PSST POST - 12 GA.	36.00	0.00	36.00	LF	0.00	\$11.00	\$0.00
		0040	1010	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	0.00	\$47.00	\$0.00
		0040	1020	9031280	2.5 IN. PSST POST - 12 GA.	227.00	0.00	227.00	LF	0.00	\$12.00	\$0.00
		0040	1030	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	42.00	0.00	42.00	LF	0.00	\$51.00	\$0.00
		0040	1040	9035004A	SH-FLAT SHEET	313.00	0.00	313.00	SQFT	0.00	\$20.00	\$0.00
		0040	1050	9035011A	ST-STRUCTURAL	66.00	0.00	66.00	SQFT	0.00	\$23.00	\$0.00
		0040	1060	9035069A	SHF-FLAT SHEET FLUORESCENT	75.00	0.00	75.00	SQFT	0.00	\$23.00	\$0.00
		0040	1070	9039902	MISC.EACH	10.00	0.00	10.00	EA	0.00	\$50.00	\$0.00
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$24,150.00	\$24,150.00
	Project J4			Posted to D	Pate as of Report Generated Date							\$1,636,476.14
	J4S3278	0001	1080	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$2,904.00	\$2,904.00
		0001	1090	2031000	CLASS A EXCAVATION	120.00	0.00	120.00	CUYD	0.00	\$88.00	\$0.00
		0001	1100	2035500	EMBANKMENT IN PLACE	370.00	0.00	370.00	CUYD	0.00	\$48.00	\$0.00
		0001	1110	2063000	CLASS 3 EXCAVATION	24.00	0.00	24.00	CUYD	24.00	\$12.00	\$288.00
		0001	1120	3101002	GRAVEL (A)	396.00	-278.00	118.00	TONS	118.00	\$87.92	\$10,374.56
		0001	1130	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	124.30	0.00	124.30	TONS	124.30	\$87.19	\$10,837.72
		0001	1140	4071005	TACK COAT	93.00	0.00	93.00	GAL	93.00	\$2.50	\$232.50
		0001	1150	6083003	3 IN. CONCRETE MEDIAN STRIP	11.30	0.00	11.30	SQYD	11.30	\$298.60	\$3,374.18
		0001	1160	6161005	CONSTRUCTION SIGNS	393.00	0.00	393.00	SQFT	220.00	\$4.00	\$880.00
		0001	1170	6161009	FLAG ASSEMBLY	5.00	0.00	5.00	EA	2.00	\$25.00	\$50.00
		0001	1180	6161024	CHANNELIZER (TRIM LINE) WITH LIGHT	7.00	0.00	7.00	EA	0.00	\$1.00	\$0.00
		0001	1190	6161025	CHANNELIZER (TRIM LINE)	93.00	0.00	93.00	EA	80.00	\$1.00	\$80.00
		0001	1200	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	17.00	0.00	17.00	EA	22.00	\$75.00	\$1,650.00
		0001	1210	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	3.00	\$1,000.00	\$3,000.00
		0001	1220	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$12,551.00	\$12,551.00
		0001	1230	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	1.00	0.00	1.00	EA	1.00	\$800.00	\$800.00
		0001	1240	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	19,047.00	0.00	19,047.00	LF	19,047.00	\$0.10	\$1,904.7
		0001	1250	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	7,377.00	0.00	7,377.00	LF	7,377.00	\$0.10	\$737.7
		0001	1260	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	112.00	0.00	112.00	LF	112.00	\$0.50	\$56.0
		0001	1270	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	24.00	0.00	24.00	LF	24.00	\$5.00	\$120.0
		0001	1280	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	871.00	0.00	871.00	SQYD	871.00	\$13.65	\$11,889.15
		0001	1290	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	295.00	0.00	295.00	SQYD	295.00	\$16.19	\$4,776.0
		0001	1300	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	213.30	0.00	213.30	STA	213.30	\$49.70	\$10,601.01
		0001	1310	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00

Revision 4/1/2020 Page 11 of 32



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210219-C04	J4S3278	0001	1320	7250412	12 IN. PIPE GROUP C	50.00	0.00	50.00	LF	50.00	\$54.00	\$2,700.00
		0001	1330	7250418	18 IN. PIPE GROUP C	50.00	0.00	50.00	LF	50.00	\$65.00	\$3,250.00
		0001	1340	8051000A	SEEDING - COOL SEASON MIXTURES	0.50	-0.30	0.20	ACRE	0.20	\$5,940.00	\$1,188.00
		0001	1350	8061005	ROCK DITCH CHECK	98.00	-14.00	84.00	LF	84.00	\$40.00	\$3,360.00
		0001	1360	8061016	SEDIMENT REMOVAL	21.00	-21.00	0.00	CUYD	0.00	\$13.00	\$0.00
		0001	1370	8061019	SILT FENCE	792.00	-752.00	40.00	LF	40.00	\$4.70	\$188.00
		0001	1380	9031010	CONCRETE FOOTINGS, EMBEDDED	0.10	0.00	0.10	CUYD	0.10	\$1,650.00	\$165.00
		0001	1390	9031220	PIPE POSTS	70.00	0.00	70.00	LB	70.00	\$5.00	\$350.00
		0002	1400	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	5,419.50	399.90	5,819.40	TONS	5,819.40	\$59.61	\$346,894.43
		0002	1410	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	8,564.20	-1,045.40	7,518.80	TONS	7,518.80	\$56.21	\$422,631.75
		0002	1420	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	2,280.50	87.00	2,367.50	TONS	2,367.50	\$58.85	\$139,327.38
		0002	1430	4071005	TACK COAT	17,393.00	-8,443.00	8,950.00	GAL	8,950.00	\$2.50	\$22,375.00
		0010	1460	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,175.00	0.00	1,175.00	LF	0.00	\$25.00	\$0.00
		0010	1470	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,433.00	\$0.00
	Project J	4S3278 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,024,536.12
210219-C04 Ove	erall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$2,661,012.26

Revision 4/1/2020 Page 12 of 32



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3275

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	2022010	REMOVAL OF IMPROVEMENTS	7/29/21	8/2/21	0.30	LS		53+00		77+00		Removal of 92 asphalt and concrete
0030	2031000	CLASS A EXCAVATION	7/23/21	8/2/21	404.10	CUYD	For Rock Fill 92 LT	68+70		69+34		
				8/2/21	602.90	CUYD	For Rock Fill 92 LT.	69+80		70+43		
0040	2035500	EMBANKMENT IN PLACE	7/19/21	8/2/21	1,580.00	CUYD		64+00		68+50		
			7/20/21	8/2/21	1,640.00	CUYD		64+00		68+50		
			7/21/21	8/2/21	1,740.00	CUYD		64+00		68+50		
			7/22/21	8/2/21	1,920.00	CUYD		57+50		68+50		
			7/29/21	8/2/21	660.00	CUYD		57+50		68+50		
0050	2036000	COMPACTING EMBANKMENT	7/23/21	8/2/21	335.60	CUYD	From rock fill area. 83.3% of Class A. 92 LT.	68+70		69+34		
				8/2/21	503.40	CUYD	From Rock Fill. 83.3%. 92 LT	69+80		70+43		
0090	2142000	FURNISHING ROCK FILL	7/29/21	8/2/21	352.00	CUYD	Rt. 92 Left Side	69+85		70+43		
				8/2/21	555.00	CUYD	Rt. 92 Left Side	68+70		69+65		
0100	2143000	PLACING ROCK FILL	7/29/21	8/2/21	352.00	CUYD	Rt. 92 Left Side	69+85		70+43		
				8/2/21	555.00	CUYD	Rt. 92 Left Side	68+70		69+65		
0310	6122012	IMPACT ATTENUATOR 55 MPH (SAND BARREL ARRAY)	7/26/21	8/2/21	2.00	EA	Rt. 92 Left side	57+80		72+65		
0410	6173700B	TEMP. TRAFFIC BARRIER ANCHORED., CONT	7/28/21	8/2/21	1,490.00	LF	Rt. 92 Left Side	57+80		72+65		
0451	6181000	MOBILIZATION	7/28/21	8/2/21	0.25	LS		0+00		0+00		10%
				8/2/21	0.25	LS		0+00		0+00		5%
			7/29/21	8/2/21	0.50	LS		0		0		
0550	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	7/26/21	8/2/21	281.00	SQYD	Rt. 92 Left	68+70		69+34		
				8/2/21	361.00	SQYD	Rt. 92 Left	69+80		70+43		
0560	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	7/26/21	8/2/21	0.25	LS		0+00		0+00		Phase 1 Stage 1 and Stage 2
				8/2/21	0.25	LS		0+00		0+00		Phase 2

The information below this line are details for Construction Signs (if applicable).

No Data Available

No Data Available

Revision 4/1/2020 Page 13 of 32



D		Б		011		0	0		ъ .
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0010	CLEARING AND GRUBBING	Overrun	Overrun	3	Jun 16, 2021	SYSTEM	(\$9,000.00)	
				Overrun - T	otal			(\$9,000.00)	
			Overrun - To	tal				(\$9,000.00)	
	0010 -	- Total						(\$9,000.00)	
	0030	CLASS A EXCAVATION	Price FUEL		6	Aug 2, 2021	SYSTEM	\$104.73	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$104.73	
			Price FUEL -	· Total				\$104.73	
	0030 -	- Total						\$104.73	
	0040	EMBANKMENT IN PLACE	Material		3	Jun 16, 2021	SYSTEM	\$279,620.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$279,620.00)	Estimate Exception 1 on the eurone 1 aymon Estimate.
					4	Jul 1, 2021	SYSTEM	\$316,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$316,020.00)	
					5	Jul 16, 2021	SYSTEM	\$562,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$562,220.00)	
					6	Aug 2, 2021	SYSTEM	\$713,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$713,020.00)	
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
			Material - To Other Item Adjustment		6	Aug 2, 2021	schnod1		Payment held until quantity is verified by contractor/MoDOT.
			Other Item	tal			schnod1	\$0.00	Payment held until quantity is verified by contractor/MoDOT.
			Other Item Adjustment	tal OVRN	al		schnod1	\$0.00 (\$115,500.00)	Payment held until quantity is verified by contractor/MoDOT.
			Other Item Adjustment	OVRN - Tot	al otal		schnod1	\$0.00 (\$115,500.00) (\$115,500.00)	Payment held until quantity is verified by contractor/MoDOT. Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Other Item Adjustment	OVRN OVRN - Tot djustment - T	al otal	2021 Aug 2,		\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00)	
			Other Item Adjustment	OVRN OVRN - Tot djustment - T	al otal	Aug 2, 2021 Aug 2,	SYSTEM	\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00) (\$116,551.05)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000;
			Other Item Adjustment	OVRN OVRN - Tot djustment - T	al fotal 6	Aug 2, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM	\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00) (\$116,551.05) \$31,887.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000;
			Other Item Adjustment	OVRN OVRN - Tot djustment - T	6 6	Aug 2, 2021	SYSTEM SYSTEM	\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00) (\$116,551.05) \$31,887.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000;
			Other Item Adjustment	OVRN OVRN - Tot djustment - T	6 6 6	Aug 2, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00) (\$116,551.05) \$31,887.56 \$33,098.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000;
			Other Item Adjustment	OVRN - Tot djustment - T Overrun	6 6 6	Aug 2, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00) (\$116,551.05) \$31,887.56 \$33,098.48 \$35,116.68	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000;
			Other Item Adjustment Other Item A Overrun	OVRN - Tot djustment - T Overrun	6 6 6	Aug 2, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00) (\$116,551.05) \$31,887.56 \$33,098.48 \$35,116.68	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000;
			Other Item Adjustment Other Item A Overrun Overrun	OVRN - Tot djustment - T Overrun	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	Aug 2, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00) (\$116,551.05) \$31,887.56 \$33,098.48 \$35,116.68 \$16,448.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.
			Other Item Adjustment Other Item A Overrun Overrun	OVRN - Tot djustment - T Overrun	6 6 6 6 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Jun 16, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 (\$115,500.00) (\$115,500.00) (\$115,500.00) (\$116,551.05) \$31,887.56 \$33,098.48 \$35,116.68 \$16,448.33 \$0.00 \$0.00 \$2,446.67	Reference Item Price Adjustment Index Adjustment Type applied is FUEL This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 35651.000; Overrun Quantity Balance 5775.00.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I4P3275	0040	EMBANKMENT IN	Price FUEL	- Total				\$6,377.87	
		PLACE	Price FUEL -	· Total				\$6,377.87	
	0040 -	Total						(\$109,122.13)	
	0050	COMPACTING EMBANKMENT	Material		6	Aug 2, 2021	SYSTEM	\$1,678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,678.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0050 -	Total						\$0.00	
	0070	LINEAR GRADING	Overrun	Overrun	4	Jul 1,	SYSTEM	(\$1,650.00)	
		CLASS 1				2021		(, ,,	
				Overrun - T	otal			(\$1,650.00)	
			Overrun - To	tal				(\$1,650.00)	
	0070 -	Total						(\$1,650.00)	
	0120	TYPE 5 AGGREGATE FOR BASE	Material		4	Jul 1, 2021	SYSTEM	\$48,687.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$48,687.45)	
					5	Jul 16, 2021	SYSTEM	\$48,687.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$48,687.45)	
					6	Aug 2, 2021	SYSTEM	\$48,687.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$48,687.45)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		4	Jul 1, 2021	SYSTEM	\$347.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$347.77	
			Price FUEL -	Total				\$347.77	
	0120 -	Total						\$347.77	
	0160	MISC.	Material		4	Jul 1, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$125,903.01)	
					5	Jul 16, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$125,903.01)	
					6	Aug 2, 2021	SYSTEM	\$125,903.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$125,903.01)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
	0300	ROCK LINING	Material		3	Jun 16, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$450.00)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3275	0300	ROCK LINING	Material		4	Jul 1, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$450.00)	
					5	Jul 16, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schnod1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$450.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0300 -	· Total						\$0.00	
	0310	IMPACT ATTENUATOR 55 MPH (SAND	Material		1	May 17, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
		BARREL ARRAY)			1	May 17, 2021	SYSTEM	(\$6,000.00)	
					2	Jun 2, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user woodwj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$6,000.00)	
					3	Jun 16, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schnod1 overridding Paymer Estimate Exception 14 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$6,000.00)	
					4	Jul 1, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schnod1 overridding Paymer Estimate Exception 16 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$6,000.00)	
					5	Jul 16, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Paymer Estimate Exception 16 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$6,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0310 -	· Total						\$0.00	
	0320	REPLACEMENT SAND BARREL	Material		3	Jun 16, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schnod1 overridding Paymer Estimate Exception 15 on the current Payment Estimate.
					3	Jun 16,	SYSTEM	(\$990.00)	
						2021		(ψ330.00)	
					4	Jul 1, 2021	SYSTEM	\$990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schnod1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					4	Jul 1,	SYSTEM	,	Estimate Item Adjustment (0034) due to user schnod1 overridding Paymer
						Jul 1, 2021 Jul 1,		\$990.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Paymer
					4	Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM	\$990.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Paymer Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment
				- Total	5	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	\$990.00 (\$990.00) \$990.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Paymer Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment
			Material - To		5	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	\$990.00 (\$990.00) \$990.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Paymer Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment
	0320 -	· Total	Material - To		5	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	\$990.00 (\$990.00) \$990.00 (\$990.00)	Estimate Item Adjustment (0034) due to user schnod1 overridding Paymer Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment
	0320 - 0350	-Total CONSTRUCTION SIGNS	Material - To		5	Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM	\$990.00 (\$990.00) \$990.00 (\$990.00) \$0.00	Estimate Item Adjustment (0034) due to user schnod1 overridding Paymer Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schnod1 overridding Payment



APPENT COST CONSTRUCTION Material	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2011 3 2.01 0 2.01 0 2.00 0 1 1 2.00 0 1 2.00 0 1 2.00 0 1 2.00 0 1 2.00 0 0 2.00 0 1 2.00 0 1 2.00 0 2.00 2.00 0 2.00 0 2.00 0 2.00 0 2.00 0 2.00 0 2.00 0 2.00 0 2.00 0 2.00 0 2.00 0 2.00 2.00 0 2.0	J4P3275	0350		Material		2		SYSTEM	\$2,200.00	Estimate Item Adjustment (0028) due to user woodwj1 overridding Payment
2021						2		SYSTEM	(\$2,200.00)	
4						3		SYSTEM	\$2,200.00	Estimate Item Adjustment (0041) due to user schnod1 overridding Payment
2021						3		SYSTEM	(\$2,200.00)	
2021 S						4		SYSTEM	\$2,200.00	Estimate Item Adjustment (0035) due to user schnod1 overridding Payment
1						4		SYSTEM	(\$2,200.00)	
Total						5		SYSTEM	\$2,200.00	Estimate Item Adjustment (0036) due to user schnod1 overridding Payment
						5		SYSTEM	(\$2,200.00)	
					- Total				\$0.00	
1				Material - To	tal				\$0.00	
WARNING FAIL SYSTEM		0350 -	Total						\$0.00	
2021 2		0360	WARNING RAIL	Material		1		SYSTEM	\$150.00	Estimate Item Adjustment (0010) due to user schnod1 overridding Payment
2021 Estimate Rem Adjustment (0029) due to user woodyl overridding Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Exception 14 on the current Payment Estimate Payment Estimate Rem Adjustment (0042) due to user schood overridding Payment Estimate Rem Adjustment (0042) due to user schood overridding Payment						1		SYSTEM	(\$150.00)	
2021 3						2		SYSTEM	\$150.00	Estimate Item Adjustment (0029) due to user woodwj1 overridding Payment
2021 Estimate Exception 18 on the current Payment Estimate.						2		SYSTEM	(\$150.00)	
2021 4						3		SYSTEM	\$150.00	Estimate Item Adjustment (0042) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0036) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.						3		SYSTEM	(\$150.00)	
2021 5 Jul 16, SYSTEM \$150.00 Estimate Item Adjustment (0037) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. 5 Jul 16, SYSTEM 2021 \$0.00						4		SYSTEM	\$150.00	Estimate Item Adjustment (0036) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0037) due to user schood1 overridding Payment Estimate Exception 20 on the current Payment Estimate. Total Total S0.00 Material - Total S7000 CHANNELIZER (TRIM LINE) Material May 17, 2021 May 17, 2021 May 17, 2021 SYSTEM (\$1,472.00) 2 Jun 2, 2021 SYSTEM (\$2,185.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. SYSTEM (\$2,185.00) This adjustment (0037) due to user schood1 overridding Payment Estimate Exception 17 on the current Payment Estimate. SYSTEM (\$2,185.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. SYSTEM (\$2,185.00) This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. SYSTEM (\$2,185.00)						4		SYSTEM	(\$150.00)	
CHANNELIZER (TRIM LINE)						5		SYSTEM	\$150.00	Estimate Item Adjustment (0037) due to user schnod1 overridding Payment
Material - Total \$0.00						5		SYSTEM	(\$150.00)	
Solution Solution					- Total				\$0.00	
CHANNELIZER (TRIM LINE) Material 1 May 17, 2021 SYSTEM \$1,472.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 1 May 17, 2021 2 Jun 2, 2021 SYSTEM \$2,185.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user woodwj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 2 Jun 2, 2021 SYSTEM \$2,185.00 (\$2,185.00) 3 Jun 16, 2021 This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate. 3 Jun 16, SYSTEM \$2,185.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				Material - To	tal				\$0.00	
(TRIM LINE) 2021 Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate. 1 May 17, 2021 2 Jun 2, 2021 SYSTEM \$2,185.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user woodwj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 2 Jun 2, 2021 3 Jun 16, 2021 \$2,185.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 3 Jun 16, SYSTEM (\$2,185.00)		0360 -	Total						\$0.00	
2 Jun 2, 2021 SYSTEM \$2,185.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user woodwj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 2 Jun 2, 2021 SYSTEM (\$2,185.00) 3 Jun 16, 2021 SYSTEM \$2,185.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		0370		Material		1		SYSTEM	\$1,472.00	Estimate Item Adjustment (0011) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0030) due to user woodwj1 overridding Payment Estimate Exception 17 on the current Payment Estimate. 2 Jun 2, 2021 3 Jun 16, 2021 \$2,185.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 3 Jun 16, SYSTEM (\$2,185.00)						1		SYSTEM	(\$1,472.00)	
2021 3 Jun 16, 2021 \$2,185.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 3 Jun 16, SYSTEM (\$2,185.00)						2		SYSTEM	\$2,185.00	Estimate Item Adjustment (0030) due to user woodwj1 overridding Payment
2021 Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 3 Jun 16, SYSTEM (\$2,185.00)						2		SYSTEM	(\$2,185.00)	
						3		SYSTEM	\$2,185.00	Estimate Item Adjustment (0043) due to user schnod1 overridding Payment
						3		SYSTEM	(\$2,185.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3275	0370	CHANNELIZER (TRIM LINE)	Material		4	Jul 1, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$2,185.00)	
					5	Jul 16, 2021	SYSTEM	\$2,185.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$2,185.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0370 -	· Total						\$0.00	
	0400	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		1	May 17, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$3,600.00)	
					2	Jun 2, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user woodwj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$3,600.00)	
					3	Jun 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$3,600.00)	
					4	Jul 1, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$3,600.00)	
					5	Jul 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$3,600.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0400 -	Total						\$0.00	
	0410	TEMP. TRAFFIC BARRIER ANCHORED.,	Material		1	May 17, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		CONT			1	May 17, 2021	SYSTEM	(\$96,937.50)	
					2	Jun 2, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user woodwj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$96,937.50)	
					3	Jun 16, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$96,937.50)	
					4	Jul 1, 2021	SYSTEM	\$96,937.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$96,937.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0410 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3275	0420	TEMP. TRAFFIC BARRIER HEIGHT TRANSITION	Material		1	May 17, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$1,700.00)	
					2	Jun 2, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user woodwj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$1,700.00)	
					3	Jun 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$1,700.00)	
					4	Jul 1, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,700.00)	, ,
					5	Jul 16, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schnod1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$1,700.00)	
					6	Aug 2, 2021	SYSTEM	\$1,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		· Total						\$0.00	
	0480	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		1	May 17, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		,			1	May 17, 2021	SYSTEM	(\$4,314.00)	
					_				
					2	Jun 2, 2021	SYSTEM	\$4,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					2		SYSTEM	\$4,314.00 (\$4,314.00)	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment
						2021 Jun 2,			Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment
					2	Jun 2, 2021 Jun 16,	SYSTEM	(\$4,314.00)	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment
					2	Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM SYSTEM	(\$4,314.00) \$4,314.00	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
					3	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM	(\$4,314.00) \$4,314.00 (\$4,314.00)	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment
					2 3 3 4	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,314.00) \$4,314.00 (\$4,314.00) \$4,314.00	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment
					2 3 3 4	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,314.00) \$4,314.00 (\$4,314.00) \$4,314.00	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment
					2 3 3 4 4 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,314.00) \$4,314.00 (\$4,314.00) \$4,314.00 (\$4,314.00) \$11,794.00	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment
					2 3 3 4 4 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,314.00) \$4,314.00 (\$4,314.00) \$4,314.00 (\$4,314.00) \$11,794.00	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.
				- Total	2 3 3 4 4 5 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,314.00) \$4,314.00 (\$4,314.00) \$4,314.00 (\$4,314.00) \$11,794.00 (\$11,794.00)	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.
			Material - To		2 3 3 4 4 5 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$4,314.00) \$4,314.00 (\$4,314.00) \$4,314.00 (\$4,314.00) \$11,794.00 (\$11,794.00) (\$11,794.00)	Estimate Item Adjustment (0034) due to user woodwj1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schnod1 overridding Payment Estimate Exception 29 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 29 on the current Payment Estimate.



March Marc	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2	J4P3275	0490	REMOVABLE	Material		1		SYSTEM	\$7,428.00	Estimate Item Adjustment (0016) due to user schnod1 overridding Payment
2011 2014 2016 2016 2017						1		SYSTEM	(\$7,428.00)	
2021 3						2		SYSTEM	\$7,428.00	Estimate Item Adjustment (0035) due to user woodwj1 overridding Payment
2021 Section Page Page						2		SYSTEM	(\$7,428.00)	
A						3		SYSTEM	\$7,428.00	Estimate Item Adjustment (0048) due to user schnod1 overridding Payment
Sectional Enternational International Education (Security Description 32 on the current Payment Education (Security Description 33 on the Current Payment Education (Security Description 34						3		SYSTEM	(\$7,428.00)	
2021 5 34 ft, 2021 5						4		SYSTEM	\$7,428.00	Estimate Item Adjustment (0042) due to user schnod1 overridding Payment
Section Sect						4		SYSTEM	(\$7,428.00)	
2021 6						5		SYSTEM	\$14,884.00	Estimate Item Adjustment (0042) due to user schnod1 overridding Payment
2021						5		SYSTEM	(\$14,884.00)	
170tal 170tal 180,000 181 181 182 182 183 183 184						6		SYSTEM	\$14,884.00	Estimate Item Adjustment (0029) due to user schnod1 overridding Payment
						6		SYSTEM	(\$14,884.00)	
					- Total				\$0.00	
18 IN. GROUP A FLARED END SECT SECT				Material - To	tal				\$0.00	
SECT		0490 -	Total						\$0.00	
2021			40 IN ODOLID 4							
2021 Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.		0590	FLARED END	Material		3		SYSTEM	\$1,212.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment
2021		0590	FLARED END	Material			2021 Jun 16,			Estimate Item Adjustment (0049) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate.		0590	FLARED END	Material		3	Jun 16, 2021 Jul 1,	SYSTEM	(\$1,212.00)	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment
2021		0590	FLARED END	Material		3	Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM	(\$1,212.00) \$1,212.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.		0590	FLARED END	Material		3 4	Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16,	SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00)	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment
Total S0.00 Material - Total \$0.00 Material - Total \$0.00		0590	FLARED END	Material		3 4 4 5	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment
Material - Total \$0.00		0590	FLARED END	Material		3 4 4 5 5 5	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment
Solution Solution		0590	FLARED END	Material		3 4 4 5 5 6 6	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00)	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment
ROCK DITCH CHECK System		0590	FLARED END	Material	- Total	3 4 4 5 5 6 6	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment
CHECK 2021 Estimate Item Adjustment (0050) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate. 3 Jun 16, 2021 4 Jul 1, SYSTEM (\$1,600.00) SYSTEM \$5,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate. 4 Jul 1, SYSTEM (\$5,600.00)			FLARED END SECT			3 4 4 5 5 6 6	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00)	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment
2021 4 Jul 1, SYSTEM \$5,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate. 4 Jul 1, SYSTEM (\$5,600.00)			FLARED END SECT			3 4 4 5 5 6 6	2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00) \$0.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate. 4 Jul 1, SYSTEM (\$5,600.00)		0590 -	FLARED END SECT Total ROCK DITCH	Material - To		3 4 4 5 5 6 6 6	2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00) \$0.00 \$0.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
		0590 -	FLARED END SECT Total ROCK DITCH	Material - To		3 4 4 5 5 6 6	2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 \$0.00 \$0.00 \$1,600.00	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
		0590 -	FLARED END SECT Total ROCK DITCH	Material - To		3 4 4 5 5 6 6 6 3 3 3	2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 (\$1,212.00) \$1,212.00 \$0.00 \$0.00 \$0.00 \$1,600.00 (\$1,600.00)	Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schnod1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate.



Desired	I to a	December	A -15	O41	F-4	0	041	A	Dawada
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0640	ROCK DITCH CHECK	Material		5	Jul 16, 2021	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schnod1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$5,600.00)	
				- Total				\$0.00	
			Material - Tot					\$0.00	
			Other Item Adjustment	OVRN	4	Jul 1, 2021	schnod1	(\$3,080.00)	Payment held for overrun exception.
			,		6	Aug 2, 2021	schnod1	\$3,080.00	Manual negative adjustment from estimate 0004 paid for now.
				OVRN - Tota	al			\$0.00	
			Other Item Ad					\$0.00	
				Overrun		Jul 1,	SYSTEM		This adjustment affects the original quotem generated Overrun Dayment
			Overrun	Overrun	4	2021	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 62 on the current Payment Estimate. Material Insufficiency Quantity 140.000; Overrun Quantity Balance 77.00.
					4	Jul 1, 2021	SYSTEM	(\$3,080.00)	
					5	Jul 16, 2021	SYSTEM	(\$3,080.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Jul 16, 2021	SYSTEM	\$3,080.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0044) overridding Payment Estimate Exception 54 on the current Payment Estimate. Material Insufficiency Quantity 140.000; Overrun Quantity Balance 77.00.
					6	Aug 2, 2021	SYSTEM	(\$3,080.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$3,080.00)	
			Overrun - Tot	tal				(\$3,080.00)	
	0640 -	Total						(\$3,080.00)	
	0670	TEMPORARY SEEDING AND MULCHING	Material		4	Jul 1, 2021	SYSTEM	\$4,815.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$4,815.00)	
					5	Jul 16, 2021	SYSTEM	\$4,815.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schnod1 overridding Payment
					5	Jul 16,	SYSTEM	(\$4,815.00)	Estimate Exception 46 on the current Payment Estimate.
						2021			
				- Total				\$0.00	
			Material - Tot					\$0.00	
			Other Item Adjustment	OVRN	4	Jul 1, 2021	schnod1	(\$3,691.50)	Payment held for overrun exception.
					6	Aug 2, 2021	schnod1	\$3,691.50	Manual negative adjustment from estimate 0004 paid for now.
				OVRN - Tota	al			\$0.00	
			Other Item Ad	djustment - T	otal			\$0.00	
			Overrun	Overrun	4	Jul 1, 2021	SYSTEM	\$3,691.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) overridding Payment Estimate Exception 63 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 2.30.
					4	Jul 1, 2021	SYSTEM	(\$3,691.50)	
					5	Jul 16, 2021	SYSTEM	(\$3,691.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Jul 16, 2021	SYSTEM	\$3,691.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0046) overridding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 2.30.
					6	Aug 2, 2021	SYSTEM	(\$3,691.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$3,691.50)	
			Overrun - Tot					(\$3,691.50)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3275	0670 -	· Total						(\$3,691.50)	
	0680	SILT FENCE	Material		2	Jun 2, 2021	SYSTEM	\$10,641.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user woodwj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$10,641.00)	
					3	Jun 16, 2021	SYSTEM	\$10,641.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$10,641.00)	
					4	Jul 1, 2021	SYSTEM	\$14,637.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schnod1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$14,637.00)	
					5	Jul 16, 2021	SYSTEM	\$14,637.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$14,637.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0680 -	· Total						\$0.00	
	0730	MGS GUARDRAIL	Construction Stockpile		2	Jun 2, 2021	SYSTEM	\$16,625.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$16,625.00	
			Construction	Stockpile S	TMI - Tota	ı		\$16,625.00	
	0730 -	· Total						\$16,625.00	
	0740	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN			2	Jun 2, 2021	SYSTEM	\$32,582.46	Payment Estimate Item Adjustment generated Stockpile Transaction
		113114	STMI	- Total				\$32,582.46	
			Construction	Stockpile S	TMI - Tota	ı		\$32,582.46	
	0740 -	· Total						\$32,582.46	
	0750	MGS END ANCHOR	Construction Stockpile STMI		2	Jun 2, 2021	SYSTEM	\$1,158.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			O T WIII	- Total				\$1,158.00	
			Construction	Stockpile S	TMI - Tota	<u> </u>		\$1,158.00	
	0750 -	· Total						\$1,158.00	
	0760	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI		2	Jun 2, 2021	SYSTEM	\$13,905.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)	O T WII	- Total				\$13,905.00	
			Construction	Stockpile S	TMI - Tota			\$13,905.00	
		· Total						\$13,905.00	
J4P3275 -								(\$61,820.67)	
J4S3278	1120	GRAVEL (A)	Material		3	Jun 16, 2021	SYSTEM	\$10,402.69	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$10,402.69)	
					4	Jul 1, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$10,374.56)	
					5	Jul 16, 2021	SYSTEM	\$10,374.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$10,374.56)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J4S3278	1120	GRAVEL (A)	Material			2021			Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.								
					6	Aug 2, 2021	SYSTEM	(\$10,374.56)	Estimate Estapation 1 Strate Surface algorithms and a surface and a surf								
				- Total		2021		\$0.00									
			Material - To	tal				\$0.00									
	1120 -	Total						\$0.00									
	1130	BIT. PAVEMENT MIXTURE	Price FUEL		2	Jun 2, 2021	SYSTEM	\$202.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL								
		PG64-22 (BP-1)		- Total				\$202.21									
			Price FUEL -	Total	Γotal .			\$202.21									
	1130 -	Total						\$202.21									
	1140	TACK COAT	CK COAT Material		2	Jun 2, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodwj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					2	Jun 2, 2021	SYSTEM	(\$232.50)									
								3	Jun 16, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
													3	Jun 16, 2021	SYSTEM	(\$232.50)	
										4	Jul 1, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
									4	Jul 1, 2021	SYSTEM	(\$232.50)					
													5	Jul 16, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
																5	Jul 16, 2021
							6	Aug 2, 2021	SYSTEM	\$232.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
					6	Aug 2, 2021	SYSTEM	(\$232.50)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	1140 -	Total						\$0.00									
	1150	3 IN. CONCRETE MEDIAN STRIP	Material		2	Jun 2, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodwj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.								
					2	Jun 2, 2021	SYSTEM	(\$3,374.18)									
					3	Jun 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.								
													3	Jun 16, 2021	SYSTEM	(\$3,374.18)	
					4	Jul 1, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.								
					4	Jul 1, 2021	SYSTEM	(\$3,374.18)									
						5	Jul 16, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
					5	Jul 16, 2021	SYSTEM	(\$3,374.18)									
					6	Aug 2, 2021	SYSTEM	\$3,374.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
					6	Aug 2,	SYSTEM	(\$3,374.18)									



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks									
			Туре	Adjustment Type	Number	Date	Ву											
J4S3278	1150	3 IN. CONCRETE MEDIAN STRIP	Material			2021												
			Material To	- Total				\$0.00										
	1150 -	Total	Material - To	tai				\$0.00										
						14 47	0)/07514	\$0.00	Ti									
	1160	CONSTRUCTION SIGNS	Material		1	May 17, 2021	SYSTEM	\$256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schnod1 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					1	May 17, 2021	SYSTEM	(\$256.00)										
					2	Jun 2, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodwj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					2	Jun 2, 2021	SYSTEM	(\$880.00)										
				3	Jun 16, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.										
					3	Jun 16, 2021	SYSTEM	(\$880.00)										
			- Total		4	Jul 1, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.									
														4	Jul 1, 2021	SYSTEM	(\$880.00)	
										5	Jul 16, 2021	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					5	Jul 16, 2021	SYSTEM	(\$880.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	1160 -	· Total	Material - To	tal				\$0.00 \$0.00										
	1160 - 1170	Total FLAG ASSEMBLY	Material - To	tal	2	Jun 2, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
				tal	2		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment									
				tal		2021 Jun 2,		\$0.00 \$50.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment									
				tal	2	Jun 2, 2021 Jun 16,	SYSTEM	\$0.00 \$50.00 (\$50.00)	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment									
				tal	3	Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment									
				tal	3	Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00)	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment									
				tal	3 3 4	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00)	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment									
				tal	2 3 3 4	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment									
				- Total	2 3 3 4 4 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment									
				- Total	2 3 3 4 4 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00 (\$50.00)	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment									
		FLAG ASSEMBLY	Material	- Total	2 3 3 4 4 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment									
	1170	FLAG ASSEMBLY	Material Material - To	- Total	2 3 3 4 4 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00 \$50.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment									
	1170	FLAG ASSEMBLY Total CHANNELIZER	Material Material - To	- Total	2 3 3 4 4 5 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00 \$0.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate.									
	1170	FLAG ASSEMBLY Total CHANNELIZER	Material Material - To	- Total	2 3 3 4 4 5 5	2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 May 17, 2021 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$50.00 (\$50.00) \$50.00 (\$50.00) \$50.00 (\$50.00) \$0.00 \$0.00 \$41.00	Estimate Item Adjustment (0009) due to user woodwj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment Estimate Item Adjustment (0002) due to user schnod1 overridding Payment									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J4S3278	1190	CHANNELIZER	Material			2021									
		(TRIM LINE)			3	Jun 16, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.						
					3	Jun 16, 2021	SYSTEM	(\$80.00)							
					4	Jul 1, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.						
					4	Jul 1, 2021	SYSTEM	(\$80.00)							
					5	Jul 16, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.						
					5	Jul 16, 2021	SYSTEM	(\$80.00)							
				- Total		2021		\$0.00							
			Material - To					\$0.00							
	1190 -	Total						\$0.00							
	1200	TYPE III MOVEABLE BARRICADE WITH	Material		2	Jun 2, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woodwj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.						
		LIGHTS			2	Jun 2, 2021	SYSTEM	(\$1,650.00)							
					3	Jun 16, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.						
							3	Jun 16, 2021	SYSTEM	(\$1,650.00)					
											4	Jul 1, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
						4	Jul 1, 2021	SYSTEM	(\$1,650.00)						
						5	Jul 16, 2021	SYSTEM	\$1,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 24 on the current Payment Estimate.					
						5	Jul 16, 2021	SYSTEM	(\$1,650.00)						
				- Total				\$0.00							
			Material - To	tal				\$0.00							
			Other Item Adjustment	OVRN	6	Aug 2, 2021	schnod1	\$375.00	Manual negative adjustment from estimate 0002 paid for now.						
				OVRN - Tota	al			\$375.00							
			Other Item A	djustment - T	otal			\$375.00							
			Overrun	Overrun	2	Jun 2, 2021	woodwj1	(\$375.00)	Manual adjustment for the overrun with material exceptions. This will be removed once they are resolved						
					2	Jun 2, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 35 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.						
					2	Jun 2, 2021	SYSTEM	(\$375.00)							
					3	Jun 16, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
					3	Jun 16, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 54 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.						
					4	Jul 1, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).						
					4	Jul 1, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 59 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.						



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks									
				Туре			Í											
J4S3278	1200	TYPE III MOVEABLE BARRICADE WITH	Overrun	Overrun	5	Jul 16, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
		LIGHTS			5	Jul 16, 2021	SYSTEM	\$375.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 52 on the current Payment Estimate. Material Insufficiency Quantity 22.000; Overrun Quantity Balance 5.00.									
					6	Aug 2, 2021	SYSTEM	(\$375.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).									
				Overrun - T	otal			(\$750.00)										
			Overrun - To	tal				(\$750.00)										
	1200 -	Total						(\$375.00)										
	1210	CMS W/O COMMUNICATION INTERFACE,	Material		1	May 17, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schnod1 overridding Payment Estimate Exception 7 on the current Payment Estimate.									
		CONT F/			1	May 17, 2021	SYSTEM	(\$3,000.00)										
					2	Jun 2, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woodwj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.									
					2	Jun 2, 2021	SYSTEM	(\$3,000.00)										
					3	Jun 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schnod1 overridding Payment Estimate Exception 23 on the current Payment Estimate.									
					3	Jun 16, 2021	SYSTEM	(\$3,000.00)										
						4	Jul 1, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
						4	Jul 1, 2021	SYSTEM	(\$3,000.00)									
						5	Jul 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
					5	Jul 16, 2021	SYSTEM	(\$3,000.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	1210 -	Total						\$0.00										
	1230	PREF THERMO PVMT MARK, R/R XING	Material		3	Jun 16, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.									
					3	Jun 16, 2021	SYSTEM	(\$800.00)										
														4	Jul 1, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
										4	Jul 1, 2021	SYSTEM	(\$800.00)					
													5	Jul 16, 2021	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
					5	Jul 16, 2021	SYSTEM	(\$800.00)										
				- Total				\$0.00										
			Material - To	tal				\$0.00										
	1230 -	Total						\$0.00										
	1240	4 IN. WHITE WATERBORNE PAVEMENT	Material		3	Jun 16, 2021	SYSTEM	\$1,904.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schnod1 overridding Payment Estimate Exception 31 on the current Payment Estimate.									
		MARKING				Jun 16, 2021	SYSTEM	(\$1,904.70)										
					4	Jul 1, 2021	SYSTEM	\$1,904.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schnod1 overridding Payment Estimate Exception 33 on the current Payment Estimate.									



Project Tele																							
1200 1200	Project	Line	Description		Adjustment				Amount	Remarks													
MARKING S Aul 16, SYSTEM S1,004 70 This adjustment offends the colgrant system-generated Material Phyment Estimate Exception 31 on the current Phyment Estimate Exception 31 on the current Phyment Estimate State S2,004 70	J4S3278	1240		Material		4		SYSTEM	(\$1,904.70)														
Total						5		SYSTEM	\$1,904.70	Estimate Item Adjustment (0018) due to user schnod1 overridding Payment													
1200 Total 1200						5		SYSTEM	(\$1,904.70)														
Material - Total					- Total				\$0.00														
1260 Total				Material - To	tal																		
1250		1240 -	Total																				
3 Jun 16, SYSTEM (\$737.70)		1250	WATERBORNE	Material		3		SYSTEM		Estimate Item Adjustment (0014) due to user schnod1 overridding Payment													
2021 Estimate Item Agjustment (0015) due le user schood overridding Payment			MARKING			3		SYSTEM	(\$737.70)														
2021 5						4		SYSTEM	\$737.70	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment													
2021 System Estimate Exception 32 on the current Payment Estimate.						4		SYSTEM	(\$737.70)														
1269 - Total 1269							5		SYSTEM	\$737.70	Estimate Item Adjustment (0019) due to user schnod1 overridding Payment												
1250 Total Total S						5		SYSTEM	(\$737.70)														
1250 - Total					- Total				\$0.00														
1260 S.I.N. WHITE WATERBORNE PARENT Material WATERBORNE PARENT Material Value Valu				Material - To					\$0.00														
2021 Estimate Item Adjustment (0015) due to user schood to verridding Payment Estimate.		1250 -	Total						\$0.00														
3		1260	WATERBORNE	NE NT		3		SYSTEM	\$56.00	Estimate Item Adjustment (0015) due to user schnod1 overridding Payment													
2021 Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.			MARKING				3		SYSTEM	(\$56.00)													
2021													4		SYSTEM	\$56.00	Estimate Item Adjustment (0016) due to user schnod1 overridding Payment						
2021 Estimate Item Adjustment (0020) due to user schood 1 overridding Payment Estimate Exception 33 on the current Payment Estimate.									4		SYSTEM	(\$56.00)											
Total S0.00								5		SYSTEM	\$56.00	Estimate Item Adjustment (0020) due to user schnod1 overridding Payment											
1260 - Total 24 IN. WHITE WATERBORNE PAVEMENT MARKING 2021 3							5		SYSTEM	(\$56.00)													
1270 24 IN. WHITE WATERBORNE PAVEMENT MARKING 2021 3 Jun 16, 2021 SYSTEM \$120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 3 Jun 16, 2021 SYSTEM S120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate. 4 Jul 1, 2021 SYSTEM S120.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate. 5 Jul 16, 2021 SYSTEM S120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate. Total					- Total				\$0.00														
1270 24 IN. WHITE WATERBORNE PAVEMENT MARKING 3 Jun 16, 2021 SYSTEM \$120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 3 Jun 16, 2021 4 Jul 1, 2021 SYSTEM \$120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate. 4 Jul 1, 2021 SYSTEM \$120.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate. 5 Jul 16, 2021 SYSTEM \$120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 5 Jul 16, 2021 SYSTEM \$120.00 SYSTEM \$120.				Material - To	tal				\$0.00														
WATERBORNE PAVEMENT MARKING 2021 2021 2021 Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate. 3 Jun 16, 2021 4 Jul 1, 2021 SYSTEM \$120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate. 4 Jul 1, 2021 SYSTEM (\$120.00) 5 Jul 16, 2021 SYSTEM \$120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate. Total SYSTEM (\$120.00) Attended The Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate. **Total*** **O.00*** **Material - Total** **O.00** **Do.00** **Material - Total** **O.00** **Do.00** **Do.		1260 -	Total						\$0.00														
System (\$120.00)		1270	WATERBORNE PAVEMENT	Material		3		SYSTEM	\$120.00	Estimate Item Adjustment (0016) due to user schnod1 overridding Payment													
Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate. 4 Jul 1, 2021 5 Jul 16, 2021 \$120.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 5 Jul 16, 2021 \$0.00 Material - Total \$0.00			MARKING			3		SYSTEM	(\$120.00)														
2021 5 Jul 16, 2021 5 Jul 16, 2021 5 Jul 16, 2021 5 Jul 16, 2021 5 SYSTEM (\$120.00) This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate. - Total *0.00 Material - Total \$0.00																			4		SYSTEM	\$120.00	Estimate Item Adjustment (0017) due to user schnod1 overridding Payment
2021 Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 35 on the current Payment Estimate. 5 Jul 16, 2021 \$0.00 -Total \$0.00 Material - Total \$0.00						4		SYSTEM	(\$120.00)														
2021						5		SYSTEM	\$120.00	Estimate Item Adjustment (0021) due to user schnod1 overridding Payment													
Material - Total \$0.00						5		SYSTEM	(\$120.00)														
					- Total				\$0.00														
1270 - Total \$0.00									\$0.00														
		1270 -	Total						\$0.00														



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1320	12 IN. PIPE CULVERT GROUP C	Material		1	May 17, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schnod1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$2,700.00)	
					2	Jun 2, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woodwj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$2,700.00)	
					3	Jun 16, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$2,700.00)	
					4	Jul 1, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$2,700.00)	
					5	Jul 16, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$2,700.00)	
					6	Aug 2, 2021	SYSTEM	\$2,700.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schnod1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$2,700.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
		- Total					0) (0==14	\$0.00	
	1330	18 IN. PIPE CULVERT GROUP	Material		1	May 17, 2021	SYSTEM	\$3,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schnod1 overridding Payment
		С							Estimate Exception 15 on the current Payment Estimate.
		С			1	May 17, 2021	SYSTEM	(\$3,250.00)	
		С			1		SYSTEM SYSTEM	(\$3,250.00) \$3,250.00	
		С				2021 Jun 2,			Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment
		С			2	2021 Jun 2, 2021 Jun 2,	SYSTEM	\$3,250.00	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment
		С			2	Jun 2, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM	\$3,250.00 (\$3,250.00)	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment
		С			2 2 3	Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM	\$3,250.00 (\$3,250.00) \$3,250.00	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment
		С			2 2 3	Jun 2, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00)	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment
		C			2 2 3 3 4	2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00) \$3,250.00	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment
		С			2 2 3 3 4 4	2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00) (\$3,250.00)	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment
		C			2 2 3 4 4 5	2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00)	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment
		C			2 2 3 3 4 4 5	2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00) (\$3,250.00)	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment
		C		- Total	2 2 3 3 4 4 5 5	2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM	\$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00) (\$3,250.00) \$3,250.00	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment
		C	Material - To		2 2 3 3 4 4 5 5	2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM	\$3,250.00 (\$3,250.00) \$3,250.00 (\$3,250.00) (\$3,250.00) (\$3,250.00) (\$3,250.00) (\$3,250.00)	Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woodwj1 overridding Payment Estimate Exception 27 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schnod1 overridding Payment Estimate Exception 42 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 38 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment Estimate Item Adjustment (0016) due to user schnod1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3278	1340	SEEDING - COOL SEASON MIXTURES	Material		1	May 17, 2021	SYSTEM	\$1,051.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schnod1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					1	May 17, 2021	SYSTEM	(\$1,051.38)	
					2	Jun 2, 2021	SYSTEM	\$1,051.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woodwj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					2	Jun 2, 2021	SYSTEM	(\$1,051.38)	
					3	Jun 16, 2021	SYSTEM	\$1,051.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$1,051.38)	
					4	Jul 1, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					4	Jul 1, 2021	SYSTEM	(\$1,188.00)	
					5	Jul 16, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$1,188.00)	
					6	Aug 2, 2021	SYSTEM	\$1,188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schnod1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,188.00)	
			- Total					\$0.00	
			Material - To	tal				\$0.00	
		- Total						\$0.00	
								<u> </u>	
	1350	ROCK DITCH CHECK	Material		1	May 17, 2021		\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		ROCK DITCH	Material		1		SYSTEM SYSTEM	<u> </u>	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment
		ROCK DITCH	Material			2021 May 17,		\$3,360.00	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment
		ROCK DITCH	Material		1	2021 May 17, 2021 Jun 2,	SYSTEM	\$3,360.00 (\$3,360.00)	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment
		ROCK DITCH	Material		1 2	2021 May 17, 2021 Jun 2, 2021	SYSTEM SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment
		ROCK DITCH	Material		1 2 2	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16,	SYSTEM SYSTEM SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00)	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment
		ROCK DITCH	Material		1 2 2 3	2021 May 17, 2021 Jun 2, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00)	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment
		ROCK DITCH	Material		1 2 2 3 3 3	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jun 16, 2021 Jun 17,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) \$3,360.00	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment
		ROCK DITCH	Material		1 2 2 3 3 4	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00)	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment
		ROCK DITCH	Material		1 2 2 3 3 4 4 4	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 3021 Jul 16, 3021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) (\$3,360.00) (\$3,360.00)	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 50 on the current Payment Estimate.
		ROCK DITCH	Material		1 2 2 3 3 4 4 5 5	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) (\$3,360.00) \$3,360.00	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 50 on the current Payment Estimate.
		ROCK DITCH	Material		1 2 2 3 3 4 4 5 5 5	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00)	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 44 on the current Payment Estimate.
		ROCK DITCH	Material	- Total	1 2 2 3 3 4 4 5 5 5 6 6	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) (\$3,360.00) (\$3,360.00) (\$3,360.00) (\$3,360.00) \$3,360.00	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 44 on the current Payment Estimate.
		ROCK DITCH	Material Material - To		1 2 2 3 3 4 4 5 5 5 6 6	2021 May 17, 2021 Jun 2, 2021 Jun 16, 2021 Jun 16, 2021 Jul 1, 2021 Jul 1, 2021 Jul 16, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM	\$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) \$3,360.00 (\$3,360.00) (\$3,360.00)	Estimate Item Adjustment (0007) due to user schnod1 overridding Payment Estimate Exception 20 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user woodwj1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schnod1 overridding Payment Estimate Exception 48 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 44 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 44 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4S3278	1370	SILT FENCE	Material		3	Jun 16, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 50 on the current Payment Estimate.			
					3	Jun 16, 2021	SYSTEM	(\$188.00)				
					4	Jul 1, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 55 on the current Payment Estimate.			
					4	Jul 1, 2021	SYSTEM	(\$188.00)				
					5	Jul 16, 2021	SYSTEM	\$188.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 49 on the current Payment Estimate.			
					5	Jul 16, 2021	SYSTEM	(\$188.00)				
				- Total				\$0.00				
	1370 - Total		Material - To	I - Total								
	1370 -							\$0.00				
	1380	CONCRETE FOOTINGS, EMBEDDED	Material		3	Jun 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 52 on the current Payment Estimate.			
					3	Jun 16, 2021	SYSTEM	(\$165.00)				
					4	Jul 1, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schnod1 overridding Payment Estimate Exception 57 on the current Payment Estimate.			
					4	Jul 1, 2021	SYSTEM	(\$165.00)				
								5	Jul 16, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$165.00)				
								6	Aug 2, 2021	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schnod1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$165.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
		Total						\$0.00				
	1400	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Overrun	Overrun	3	Jun 16, 2021	SYSTEM	(\$24,504.32)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
		1 304 22 (81-1)			4	Jul 1, 2021	SYSTEM	\$2.45	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.26999 - 59.61000, 'is applied (if non-zero).			
					6	Aug 2, 2021	SYSTEM	\$24,501.87	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.26999 - 59.61000, 'is applied (if non-zero).			
				Overrun - T	otal			\$0.00				
			Overrun - To	tal				\$0.00				
			Price FUEL		2	Jun 2, 2021	SYSTEM	\$8,375.96	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					3	Jun 16, 2021	SYSTEM	\$1,113.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
					4		SYSTEM	(\$0.07)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$9,489.27				
			Price FUEL -	Total				\$9,489.27				
	1400 -	Total						\$9,489.27				
	1410	BITUMINOUS PAVEMENT	Price FUEL		2	Jun 2, 2021	SYSTEM	\$12,227.43	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
		MIXTURE PG64-22 (BAS			4	Jul 1, 2021	SYSTEM	\$0.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4S3278	1410	BITUMINOUS PAVEMENT	Price FUEL	- Total				\$12,227.45			
		MIXTURE PG64-22 (BAS	Price FUEL -	·Total				\$12,227.45			
	1410 -	- Total						\$12,227.45			
	1420	BITUMINOUS PAVEMENT MIXTURE	Material		2	Jun 2, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodwj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
		PG64-22 (SUR			2	Jun 2, 2021	SYSTEM	(\$139,327.38)			
					3	Jun 16, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schnod1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					3	Jun 16, 2021	SYSTEM	(\$139,327.38)			
					4	Jul 1, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					4	Jul 1, 2021	SYSTEM	(\$139,327.38)			
					5	Jul 16, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schnod1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					5	Jul 16, 2021	SYSTEM	(\$139,327.38)			
							6	Aug 2, 2021	SYSTEM	\$139,327.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$139,327.38)			
				- Total				\$0.00			
			Material - To	tal				\$0.00			
			Other Item Adjustment	OVRN	6	Aug 2, 2021	schnod1	\$5,261.48	Manual negative adjustment from estimate 0002 paid for now.		
				OVRN - Tot	al			\$5,261.48			
			Other Item A	djustment - 1	otal			\$5,261.48			
			Overrun	Overrun	2	Jun 2, 2021	woodwj1	(\$5,261.48)	Manual adjustment for the overrun with material exceptions. This will be removed once they are resolved		
					2	Jun 2, 2021	SYSTEM	(\$5,261.48)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					2	Jun 2, 2021	SYSTEM	\$5,261.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 2367.500; Overrun Quantity Balance 87.00.		
					3	Jun 16, 2021	SYSTEM	(\$5,261.48)	Averaged Price Adjustment from this item on all previous payment estimates of '1.62680' is applied (if non-zero).		
					3	Jun 16, 2021	SYSTEM	\$5,261.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0023) overridding Payment Estimate Exception 55 on the current Payment Estimate. Material Insufficiency Quantity 2367.500; Overrun Quantity Balance 87.00.		
					4	Jul 1, 2021	SYSTEM	(\$5,261.48)	Averaged Price Adjustment from this item on all previous payment estimates of '1.62680' is applied (if non-zero).		
						4	Jul 1, 2021	SYSTEM	\$5,261.48	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0025) overridding Payment Estimate Exception 60 on the current Payment Estimate. Material Insufficiency Quantity 2367.500; Overrun Quantity Balance 87.00.	
						11.40	SYSTEM	(\$5,261.48)	Averaged Price Adjustment from this item on all previous payment estimates		
					5	Jul 16, 2021	OTOTEM		of '1.62680' is applied (if non-zero).		
					5		SYSTEM	\$5,261.48			
				Overrun - T	5	2021 Jul 16,		\$5,261.48 (\$5,261.48)	of '1.62680' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 53 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;		
			Overrun - To		5	2021 Jul 16,			of '1.62680' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0028) overridding Payment Estimate Exception 53 on the current Payment Estimate. Material Insufficiency Quantity 2367.500;		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J4S3278	1420	BITUMINOUS PAVEMENT	Price FUEL	- Total				\$3,851.45											
		MIXTURE PG64-22 (SUR	Price FUEL -	Total				\$3,851.45											
	1420 -	Total						\$3,851.45											
	1430	TACK COAT	Material		2	Jun 2, 2021	SYSTEM	\$21,587.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user woodwj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
					2	Jun 2, 2021	SYSTEM	(\$21,587.50)											
					3	Jun 16, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schnod1 overridding Payment Estimate Exception 6 on the current Payment Estimate.										
					3	Jun 16, 2021	SYSTEM	(\$22,375.00)											
					4	Jul 1, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.										
															4	Jul 1, 2021	SYSTEM	(\$22,375.00)	
													5	Jul 16, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schnod1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
									5	Jul 16, 2021	SYSTEM	(\$22,375.00)							
						6	Aug 2, 2021	SYSTEM	\$22,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schnod1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
						Aug 2, 2021	SYSTEM	(\$22,375.00)											
				- Total				\$0.00											
			Material - To	tal				\$0.00											
	1430 -	Total						\$0.00											
	1460	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile STMI		2	Jun 2, 2021	SYSTEM	\$18,303.54	Payment Estimate Item Adjustment generated Stockpile Transaction										
		113114	OTIVII	- Total				\$18,303.54											
			Construction	Stockpile S	ГМI - Total			\$18,303.54											
	1460 -	Total						\$18,303.54											
	1470	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI		2	Jun 2, 2021	SYSTEM	\$3,090.00	Payment Estimate Item Adjustment generated Stockpile Transaction										
		(MASH)		- Total				\$3,090.00											
			Construction	Stockpile S	ΓΜΙ - Total			\$3,090.00											
		Total						\$3,090.00											
J4S3278 -								\$46,788.92											
Overall -	Total							(\$15,031.75)											