

#### Pay Estimate Created Date: September 16, 2021

Progress Estimate 5	Number	Contract ID Prime Contractor	210219-D03 r Magruder Paving		ay Period Start ay Period End			Original Contract Amount Net Change Order Amoun Current Contract Amount	t \$34,870.92		
Approval Date									By User		
September 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by										
September 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by										
September 21, 2021	Reviewed and Approved at the Central Office Controllers Office Level by										
Original Complet	ion Date	Current Cor	npletion Date	Act	tual Completion Date % of Current Contract Amount Complete						
November 1, 2	2021	Novemb	er 1, 2021					87.23%			
	Contract	Informational Dat	es		Mil	estones					
Date Description	Original	Completion Date	Current Completi	on Date	No Milestone	s Exist for	Contract				
Acceptance Date											
Awarded Date	March 3,	2021	March 3, 2021								
Letting Date	February	19, 2021	February 19, 2021								
Notice to Proceed Da	te April 5, 2	021	April 5, 2021								

Contract Total Pa	y For Estimate No. 5				
		This Estimate	Previous	To Date	
210219-D03					
	Total Posted Items Pay	\$8,815.48	\$433,009.23	\$441,824.71	
	Gross Item Adjustments	\$28,218.65	(\$19,818.90)	\$8,399.75	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$413,190.33	\$450,224.46	
Contract Total Pa	yable This Estimate:	\$37,034.13			

## Items Paid This Estimate Period

Work Began Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J5P3387	0040	2142000	FURNISHING ROCK FILL	CUYD	\$21.660	164	\$3,552.24		
	0050	2143000	PLACING ROCK FILL	\$5,397.24					
	0100	4019910	MISC.MODIFIED BITUMINOUS PAVEMENT MIXTURE (BP-2) PG64-22	TONS	\$67.000	-2	(\$134.00)		
Project J5P3387 - Total									
Overall - Total									

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3387	0040	FURNISHING ROCK FILL	Material			-239	\$21.66	(\$5,176.74)
	0040	FURNISHING ROCK FILL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	239	\$21.66	\$5,176.74
	0090	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING)	Other Item Adjustment	Asphalt Cement Price Adjustment	2 tons / 3% Virgin / BP-2 21-6			\$4.73
	0100	MISC.	Price		Reference Item Price Adjustment Index	-2	\$1.69	(\$3.39)



### Pay Estimate Created Date: September 16, 2021

Progr	ess Es	timate Number 5	Contract ID Prime Cont	210219- ractor Magrude		Pay Period End September 15, 2021 No.	riginal Contract et Change Orde urrent Contract	er Amount	\$471,641.79 \$34,870.92 \$506,512.71
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
5P3387						Adjustment Type applied is FUE	EL		
	0100		MISC.	Other Item Adjustment	Asphalt Cement Price Adjustment	3,339.1 tons / 3% Virgin / BP-2 21	-6		\$7,888.63
	0100		MISC.	Other Item Adjustment		-2124.90 tons / 3% Virgin / BP-2 21	-6		(\$2,870.20
	0200		REFORMED MOPLASTIC RKING, 6 IN. WHITE	Overrun		Averaged Price Adjustment from this item of all previous payment estimates of '0.00000' applied (if non-zero	is	\$13.50	(\$1,876.50
	0200		REFORMED MOPLASTIC RKING, 6 IN. WHITE	MaterialCredit			697	\$13.50	\$9,409.50
	0200		REFORMED MOPLASTIC RKING, 6 IN. WHITE	Material			-697	\$13.50	(\$9,409.50
	0200		REFORMED MOPLASTIC RKING, 6 IN. WHITE	Overrun		This adjustment offsets the original syster generated Overrun Payment Estimate Ite Adjustment (0003) overridding Payme Estimate Exception 11 on the current Payme Estimate. Material Insufficiency Quanti 697.000; Overrun Quantity Balance 139.0	m nt nt ty	\$13.50	\$1,876.50
	0200		REFORMED MOPLASTIC RKING, 6 IN. WHITE	Material		This adjustment offsets the original syster generated Material Payment Estimate Ite Adjustment (0005) due to user stokez overridding Payment Estimate Exception 3 o the current Payment Estimat	m z1 on	\$13.50	\$9,409.50
	0210		REFORMED MOPLASTIC IARKING, 24 IN. WHITE	MaterialCredit			293	\$13.50	\$3,955.50
	0210		REFORMED MOPLASTIC IARKING, 24 IN. WHITE	Material			-293	\$13.50	(\$3,955.50
	0210		REFORMED MOPLASTIC IARKING, 24 IN. WHITE	Material		This adjustment offsets the original syster generated Material Payment Estimate Ite Adjustment (0007) due to user stokez overridding Payment Estimate Exception 4 o the current Payment Estimat	m z1 on	\$13.50	\$3,955.50
	0220	THER PAVEMEN	REFORMED MOPLASTIC T MARKING, GHT ARROW	MaterialCredit			20	\$150.00	\$3,000.00
	0220	0 PREFORMED Material THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW			-20	\$150.00	(\$3,000.00		
	0220	THER PAVEMEN	REFORMED MOPLASTIC T MARKING, GHT ARROW	Material		This adjustment offsets the original syster generated Material Payment Estimate Ite Adjustment (0009) due to user stokez overridding Payment Estimate Exception 5 o the current Payment Estimat	m z1 on	\$150.00	\$3,000.00
	0230	THER	REFORMED MOPLASTIC T MARKING,	MaterialCredit			2	\$150.00	\$300.00



## Pay Estimate Created Date: September 16, 2021

Progr		5 Contract I Prime Con			Pay Period End September 15, 2021 Net	jinal Contract Change Orde rent Contract	er Amount	\$471,641.79 \$34,870.92 \$506,512.71
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3387		STRAIGHT ARROV	/					
	0230 PREFORM THERMOPLAS PAVEMENT MARKII STRAIGHT ARR 0230 PREFORM THERMOPLAS PAVEMENT MARKII STRAIGHT ARR		<b>)</b>			-2	\$150.00	(\$300.00
			<b>)</b>		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	2	\$150.00	\$300.00
	0240	4 IN. WHITE STANDARI WATERBORNE PAVEMEN MARKING PAINT, TYPE I BEAD			Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-119.2	\$0.20	(\$23.84)
	0240	4 IN. WHITE STANDARI WATERBORNE PAVEMEN MARKING PAINT, TYPE I BEAD				15,915.2	\$0.20	\$3,183.04
	0250 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS					14,991.2	\$0.15	\$2,248.68
	0260	8 IN. WHITE STANDARI WATERBORNE PAVEMEN MARKING PAINT, TYPE I BEAD				42	\$3.00	\$126.00
	0270	MISC	. MaterialCredit			2	\$500.00	\$1,000.00
	0270	MISC	. Material			-2	\$500.00	(\$1,000.00
	0270	MISC	. Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	2	\$500.00	\$1,000.00
	0310	ROCK DITCH CHEC	K Material			-8	\$18.00	(\$144.00)
	0310	ROCK DITCH CHEC	K Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	8	\$18.00	\$144.00
	0350	MGS GUARDRAIL, 8 FT POSTS, 6 FT 3 IN SPACING				-912.5	\$27.00	(\$24,637.50)
	0350	MGS GUARDRAIL, 8 FT POSTS, 6 FT 3 IN SPACING			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	912.5	\$27.00	\$24,637.50
Fotal								\$28,218.65



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J5P3387	FAS S402(21)	Pavement improvements	19,100	GASCONADE	from Missouri Rive	r bridge to 0.1 mile south of F	Rte. H and on Rte. 100 from Rte. 19				
fotals by .	Job Numbe	rs									
J5P3387	Poste	d Item Pay			This Estimate \$8.815.48	Previous \$433,009.23	<b>To Date</b> \$441,824.71				
		Item Adjustme		tem Pay	\$28,218.65 \$37,034.13	(\$19,818.90) <b>\$413,190.33</b>	\$8,399.75 <b>\$450,224.46</b>				
	Incent				\$0.00	\$0.00	\$0.00				
	Liquid	centive lated Damages Contract Adjus			\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00				



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 2142000, Project Item Line Number 0040, Material Set 214200096, Material 0214STRF - Stone for Rock Fill, Acceptance Action Generic 0214STRF is insufficient.	Stokez1 Materials test needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 6061061, Project Item Line Number 0350, Material Set 606106196, Material 1065DE - Delineators, Acceptance Action Generic 1065DE is insufficient.	stokez1 Delineator certification is needed	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 6200009, Project Item Line Number 0200, Material Set 620000996, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Stokez1 Materials test needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 6200015, Project Item Line Number 0210, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Stokez1 Materials test needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 6200021, Project Item Line Number 0220, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Stokez1 Materials test needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 6200024, Project Item Line Number 0230, Material Set 620002496, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Stokez1 Materials test needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 6206108A, Project Item Line Number 0260, Material Set 6206108A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Stokez1 Error no High build set up on project	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 6209902, Project Item Line Number 0270, Material Set 6209902, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Stokez1 Materials test needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 6240104A, Project Item Line Number 0290, Material Set 6240104A96, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient.	Stokez1 Materials test needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3387, Item 8061005, Project Item Line Number 0310, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Stokez1 Materials test needs to be entered by MoDOT	stokez1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-D03, Contract Project J5P3387, Project Item Line Number 0200, Item 6200009, Minor Item.	Stokez1 Change order is needed	stokez1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-D03, Contract Project J5P3387, Project Item Line Number 0240, Contract Line Item Number 0240, Item 6206000C, Minor Item.	Stokez1 Change order is needed	stokez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-D03, Contract Project J5P3387, Project Item Line Number 0380, Contract Line Item Number 0380, Item 6063014, Minor Item.	Stokez1 Change order is needed	stokez1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210219-D03, Contract Project J5P3387, Project Item Line Number 5001, Contract Line Item Number 5001, Item 6221001, Minor Item.	Stokez1 Change order is needed	stokez1	Acknowledged



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

I otal Pater All refins / All Estimates (including unit Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
9-D03	J5P3387	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$2,581.50	\$2,581.5
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$9,769.78	\$9,769.7
		0001	0030	2035000	UNCLASSIFIED EXCAVATION	520.00	0.00	520.00	CUYD	239.00	\$39.10	\$9,344.9
		0001	0040	2142000	FURNISHING ROCK FILL	520.00	0.00	520.00	CUYD	239.00	\$21.66	\$5,176.7
		0001	0050	2143000	PLACING ROCK FILL	520.00	0.00	520.00	CUYD	239.00	\$32.91	\$7,865.4
		0001	0060	2153000	SHAPING SLOPES, CLASS III	4.00	0.00	4.00	100F	4.00	\$1,200.00	\$4,800.0
		0001	0070	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	46.00	0.00	46.00	SQYD	10.00	\$49.71	\$497.1
		0001	0080	3105002	GRAVEL (A) OR CRUSHED STONE (B)	25.00	0.00	25.00	TONS	0.00	\$195.34	\$0.0
		0001	0090	4013010	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE WIDENING)	20.20	0.00	20.20	TONS	2.00	\$168.33	\$336.6
		0001	0100	4019910	MISC.MODIFIED BITUMINOUS PAVEMENT MIXTURE (BP-2) PG64-22	3,422.90	0.00	3,422.90	TONS	3,339.10	\$67.00	\$223,719.7
		0001	0110	4079912	MISC.LOW TRACKING OR NON-TRACKING TACK	4,073.00	0.00	4,073.00	GAL	3,074.00	\$2.78	\$8,545.7
		0001	0120	6049902	MISC.ADJUST MANHOLES AND VALVES	22.00	-22.00	0.00	EA	0.00	\$79.52	\$0.0
		0001	0130	6161005	CONSTRUCTION SIGNS	1,133.00	0.00	1,133.00	SQFT	320.00	\$4.50	\$1,440.0
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$55.00	\$0.0
		0001	0150	6161009	FLAG ASSEMBLY	10.00	0.00	10.00	EA	6.00	\$10.25	\$61.5
		0001	0160	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	25.00	\$15.00	\$375.0
		0001	0170	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.0
		0001	0180	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	EA	3.00	\$1,500.00	\$4,500.0		
		0001	0190	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$25,350.00	\$25,350.
		0001	0200	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	558.00	0.00	558.00	LF	697.00	\$13.50	\$9,409.
		0001	0210	6200009 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE   6200015 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE		373.00	0.00	373.00	LF	293.00	\$13.50	\$3,955.
		0001	0220	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	22.00	0.00	22.00	EA	20.00	\$150.00	\$3,000.
		0001	0230	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	5.00	0.00	5.00	EA	2.00	\$150.00	\$300.
		0001	0240	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	15,796.00	0.00	15,796.00	LF	15,915.20	\$0.20	\$3,183
		0001	0250	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	17,918.00	0.00	17,918.00	LF	14,991.20	\$0.15	\$2,248
		0001	0260	6206108A	8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	42.00	0.00	42.00	LF	42.00	\$3.00	\$126
		0001	0270	6209902	MISC. LANE REDUCTION ARROWS, PREFORMED THERMOPLASTIC	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000
		0001	0280	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	3,551.00	-3,551.00	0.00	SQYD	0.00	\$3.60	\$0
		0001	0290	6240104A	SEPARATION GEOTEXTILE	247.00	0.00	247.00	SQYD	151.00	\$3.00	\$453
		0001	0300	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.50	\$2,500.00	\$1,250
		0001	0310	8061005	ROCK DITCH CHECK	100.00	0.00	100.00	LF	8.00	\$18.00	\$144
		0001	0320	8061050	TYPE C BERM	220.00	0.00	220.00	LF	0.00	\$38.50	\$0
		0010	0330	6061010	GUARDRAIL TYPE A	138.00	0.00	138.00	LF	137.50	\$24.00	\$3,300
		0010	0340	6061060	MGS GUARDRAIL	125.00	0.00	125.00	LF	125.00	\$25.00	\$3,125
		0010	0350	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	913.00	0.00	913.00	LF	912.50	\$27.00	\$24,637
		0010	0360	6062100	BRIDGE ANCHOR SECTION (CURB TYPE)	1.00	0.00	1.00	EA	1.00	\$2,100.00	\$2,100
		0010	0370	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	3.00	0.00	3.00	EA	3.00	\$700.00	\$2,100
		0010	0380	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	9.00	\$2,800.00	\$25,200
		0010	0390	6063015	TYPE A CRASHWORTHY END TERMINAL	3.00	0.00	3.00	EA	0.00	\$2,700.00	\$0
		0040	0400	9031020	CONCRETE FOOTINGS, BOLT DOWN	0.70	0.00	0.70	CUYD	0.00	\$2,100.00	\$0
		0040	0410	9031220	PIPE POSTS	350.00	0.00	350.00	LB	0.00	\$6.00	\$0
		0001	5001	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	0.00	37,712.95	37,712.95	SQYD	39,640.00	\$1.31	\$51,928
					· · · · · · · · · · · · · · · · · · ·							



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail. location and quantity of work.

Project: J5P3387

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	2142000	FURNISHING ROCK FILL	9/15/21	9/16/21	164.00	CUYD	Rte.19 from LM 74.617 to LM 74.622 Lt					
0050	2143000	PLACING ROCK FILL	9/15/21	9/16/21	164.00	CUYD	Rte.19 from LM 74.617 to LM 74.622 Lt					
0100	4019910	MISC.	9/15/21	9/16/21	-2.00	TONS	Deducted for asphalt placed for Line #0090					

The information below this line are details for Construction Signs (if applicable). No Data Available



Sep 22, 2021

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J5P3387	0030	UNCLASSIFIED EXCAVATION	Price FUEL	Туре	3	Aug 17, 2021	SYSTEM	\$42.94	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		EXCAVATION			4	Sep 2, 2021	SYSTEM	\$0.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total		2021		\$43.02	
			Price FUEL - 1					\$43.02	
	0030 -	Total						\$43.02	
	0040	FURNISHING ROCK FILL	Material		3	Aug 17, 2021	SYSTEM	\$1,615.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 17, 2021	SYSTEM	(\$1,615.40)	
					4	Sep 2, 2021	SYSTEM	\$1,624.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment
					4	Sep 2,	SYSTEM	(\$1,624.50)	Estimate Exception 1 on the current Payment Estimate.
						2021			
					5	Sep 16, 2021	SYSTEM	\$5,176.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$5,176.74)	
				- Total				\$0.00	
		Material -		ıl				\$0.00	
	0040 -	Total						\$0.00	
	0070	) TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Material		3	Aug 17, 2021	SYSTEM	\$497.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Aug 17, 2021	SYSTEM	(\$497.10)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
			Price FUEL		3	Aug 17, 2021	SYSTEM	\$0.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$0.90	
			Price FUEL - 1	lotal				\$0.90	
	0070 -	Total						\$0.90	
	0090	BITUMINOUS PAVEMENT MIXTURE	Other Item Adjustment	ACAD		Sep 16, 2021	stokez1	\$4.73	2 tons / 3% Virgin / BP-2 21-6
		PG64-22 (BAS		ACAD - Tota				\$4.73	
			Other Item Ad	justment - To				\$4.73	
			Price FUEL		3	Aug 17, 2021	SYSTEM	\$3.98	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$3.98	
			Price FUEL - 1	otal				\$3.98	
	0090 -		0.11 I					\$8.71	
	0100	MISC.	Other Item Adjustment	ACAD	3	Aug 17, 2021	stokez1	\$2,870.20	1214.9 tons / 3% Virgin / BP-2 21-6
					5	Sep 16, 2021	stokez1	(\$2,870.20)	-2124.90 tons / 3% Virgin / BP-2 21-6
				ACAD - Tota	5	Sep 16, 2021	stokez1	\$7,888.63	3,339.1 tons / 3% Virgin / BP-2 21-6
			Other Item An					\$7,888.63	
			Other Item Ad Price FUEL	<del>justinent -</del> 10	3	Aug 17,	SYSTEM	\$7,888.63 \$6,655.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				5	2021 Sep 16,	SYSTEM	(\$3.39)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
						2021			
				- Total				\$6,652.08	
			Price FUEL - 1	otal				\$6,652.08	



Sep 22, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3387	0100 -	Total						\$14,540.71	
	0110	MISC. NON STANDARD TACK COAT	Material		3	Aug 17, 2021	SYSTEM	\$8,545.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Aug 17, 2021	SYSTEM	(\$8,545.72)	
				- Total	1	1		\$0.00	
			Material - Tota					\$0.00	
	0110 -	Total						\$0.00	
	0130	CONSTRUCTION SIGNS	Material		1	Jun 1, 2021	SYSTEM	\$576.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user stokez1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 1, 2021	SYSTEM	(\$576.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0130 -	Total						\$0.00	
	0150	FLAG ASSEMBLY	Material		1	Jun 1, 2021	SYSTEM	\$61.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jun 1, 2021	SYSTEM	(\$61.50)	
				- Total		1		\$0.00	
			Material - Tota	erial - Total				\$0.00	
	0150 -	Total						\$0.00	
	0180	CMS WITH COMMUNICATION INTERFACE,	Material		1	Jun 1, 2021	SYSTEM	\$4,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		CONT F			1	Jun 1, 2021	SYSTEM	(\$4,500.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0180 -	· Total						\$0.00	
	0200	PREF THERMO PAVMT MARKING, 6 IN WHITE	Material		4	Sep 2, 2021	SYSTEM	(\$9,409.50)	
		0 IN WHITE			5	Sep 16, 2021	SYSTEM	\$9,409.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user stokez1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$9,409.50)	
				- Total				(\$9,409.50)	
			Material - Tota					(\$9,409.50)	
			MaterialCredit		5	Sep 16, 2021	SYSTEM	\$9,409.50	
				- Total				\$9,409.50	
			MaterialCredit					\$9,409.50	
			Overrun	Overrun	4	Sep 2, 2021	SYSTEM	\$972.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 697.000; Overrun Quantity Balance 139.00.
					4	Sep 2, 2021	SYSTEM	\$904.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 697.000; Overrun Quantity Balance 139.00.
					4	Sep 2, 2021	SYSTEM	(\$1,876.50)	
					5	Sep 16, 2021	SYSTEM	(\$1,876.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Sep 16, 2021	SYSTEM	\$1,876.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 11 on the current Payment Estimate. Material Insufficiency Quantity 697.000; Overrun Quantity Balance 139.00.



Sep 22, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I5P3387	0200	PREF THERMO	Overrun	Overrun - T	otal			\$0.00	
		PAVMT MARKING, 6 IN WHITE	Overrun - Tota	ıl				\$0.00	
	0200 -	0200 - Total							
	0210	PREF THERMO PVMT MARK, 24 IN WHIT	Material		4	Sep 2, 2021	SYSTEM	(\$3,955.50)	
					5	Sep 16, 2021	SYSTEM	\$3,955.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user stokez1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$3,955.50)	
				- Total				(\$3,955.50)	
			Material - Total					(\$3,955.50)	
			MaterialCredit		5	Sep 16, 2021	SYSTEM	\$3,955.50	
				- Total				\$3,955.50	
			MaterialCredit - Total					\$3,955.50	
	0210 -	Total						\$0.00	
	0220	PREF THERMO PV/MT MARK, LT/RT ARROW	Material		4	Sep 2, 2021	SYSTEM	(\$3,000.00)	
					5	Sep 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$3,000.00)	
				- Total				(\$3,000.00)	
			Material - Total					(\$3,000.00)	
			MaterialCredit		5	Sep 16, 2021	SYSTEM	\$3,000.00	
				- Total				\$3,000.00	
	MaterialCredit - Total							\$3,000.00	
	0220 -	Total						\$0.00	
	0230	PVMT MRKG, STRIAGHT ARROW			4	Sep 2, 2021	SYSTEM	(\$300.00)	
					5	Sep 16, 2021	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user stokez1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$300.00)	
				- Total				(\$300.00)	
			Material - Tota MaterialCredit	I				(\$300.00)	
					5	Sep 16, 2021	SYSTEM	\$300.00	
				- Total				\$300.00	
			MaterialCredit	- Total				\$300.00	
	0230 -	Total						\$0.00	
	0240	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		4	Sep 2, 2021	SYSTEM	(\$3,183.04)	
				- Total					
			Material - Tota	tal				(\$3,183.04)	
			MaterialCredit		5	Sep 16, 2021	SYSTEM	\$3,183.04	
				- Total				\$3,183.04	
			MaterialCredit					\$3,183.04	
			Overrun	Overrun	4	Sep 2, 2021	SYSTEM	\$23.84	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 15915.200; Overrun Quantity Balance 119.20.
					4	Sep 2,	SYSTEM	(\$23.84)	
						2021			



Sep 22, 2021

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5P3387	0240	4 IN. WHITE WATERBORNE	Overrun	Overrun	5	Sep 16, 2021	SYSTEM	(\$23.84)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
		PAVEMENT MARKING		Overrun - T	otal			(\$23.84)	
			Overrun - Tota	ıl				(\$23.84)	
	0240 -	Total						(\$23.84)	
	0250	4 IN. YELLOW WATERBORNE	Material		4	Sep 2, 2021	SYSTEM	(\$2,248.68)	
		PAVEMENT MARKING		- Total				(\$2,248.68)	
			Material - Total					(\$2,248.68)	
			MaterialCredit		5	Sep 16, 2021	SYSTEM	\$2,248.68	
				- Total				\$2,248.68	
			MaterialCredit	terialCredit - Total					
	0250 -	Total						\$2,248.68 \$0.00	
	0260	8 IN. WHITE WATERBORNE	Material		4	Sep 2, 2021	SYSTEM	(\$126.00)	
		PAVEMENT		- Total				(\$126.00)	
		MARKING	- I Otal Material - Total					(\$126.00)	
			MaterialCredit		5	Sep 16,	SYSTEM	\$126.00	
			MaterialCredit	Total	5	2021	OTOTEM		
			MatarialOvadi	- Total				\$126.00	
	0000	<b>T</b> -4-1	MaterialCredit - Total					\$126.00	
	0260 -							\$0.00	
	0270	MISC. PAVEMENT MARKINGS	Material		4	Sep 2, 2021	SYSTEM	(\$1,000.00)	
					5	Sep 16, 2021	SYSTEM	\$1,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user stokez1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$1,000.00)	
				- Total				(\$1,000.00)	
			Material - Tota	I				(\$1,000.00)	
			MaterialCredit		5	Sep 16, 2021	SYSTEM	\$1,000.00	
				- Total				\$1,000.00	
			MaterialCredit	- Total				\$1,000.00	
	0270 -	Total						\$0.00	
	0290	SEPARATION GEOTEXTILE	Material		3	Aug 17, 2021	SYSTEM	\$453.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Aug 17, 2021	SYSTEM	(\$453.30)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0290	Total						\$0.00	
	0310	ROCK DITCH CHECK	Material		4	Sep 2, 2021	SYSTEM	\$144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user stokez1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$144.00)	
					5	Sep 16, 2021	SYSTEM	\$144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$144.00)	
				- Total	- Total				
			Material - Total					\$0.00	
	0310	Total						\$0.00	
	0330	GUARDRAIL	Construction		4	Sep 2,	SYSTEM	(\$1,834.25)	Payment Estimate Item Adjustment generated Stockpile Transaction



Sep 22, 2021

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3387	0330	TYPE A	Stockpile			2021			
				- Total			1	(\$1,834.25)	
			Construction Stockpile - Total					(\$1,834.25)	
			Construction Stockpile STMI		2	Jun 30, 2021	SYSTEM	\$1,840.92	Payment Estimate Item Adjustment generated Stockpile Transaction
			0 TIVII	- Total				\$1,840.92	
			Construction S	Stockpile STMI - Total				\$1,840.92	
	0330 - Total							\$6.67	
	0340	MGS GUARDRAIL	Construction Stockpile		4	Sep 2, 2021	SYSTEM	(\$1,768.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,768.75)	
			Construction \$	Stockpile - To				(\$1,768.75)	
			Construction Stockpile STMI	Tetal	2	Jun 30, 2021	SYSTEM	\$1,768.75	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,768.75	
			Construction Stockpile STMI - Total					\$1,768.75	
	0340 - 0350	MGS GUARDRAIL, 8 FT. POSTS, 6	Construction Stockpile		4	Sep 2, 2021	SYSTEM	\$0.00 (\$14,627.37)	Payment Estimate Item Adjustment generated Stockpile Transaction
		8 FT. POSTS, 6 FT 3 IN	Stockpile	- Total		2021		(\$14,627.37)	
			Construction S					(\$14,627.37)	
			Construction	Stockpile - T	2	Jun 30,	SYSTEM	\$14,635.39	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile		2	2021	OTOTEM	¢14,000.00	a griorit Estimate tem registrinon generated eteoriphe transaction
			- Total					\$14,635.39	
			Construction Stockpile STMI - Total					\$14,635.39	
			Material		4	Sep 2, 2021	SYSTEM	\$24,637.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$24,637.50)	
					5	Sep 16, 2021	SYSTEM	\$24,637.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user stokez1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$24,637.50)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0350 - Total							\$8.02	
	0360	BRIDGE ANCHOR SECTION (CURB TYPE)	Construction Stockpile		4	Sep 2, 2021	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,161.00)	
			Construction S	Stockpile - Total				(\$1,161.00)	
			Construction Stockpile STMI		2	Jun 30, 2021	SYSTEM	\$1,161.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,161.00	
			Construction Stockpile STMI - Total					\$1,161.00	
	0360 -	Total						\$0.00	
	0370	ASYMMETRICAL TRNS. SEC., 6.5 FT. POSTS	Construction Stockpile		4	Sep 2, 2021	SYSTEM	(\$507.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$507.00)	
			Construction S	Stockpile - To				(\$507.00)	
			Construction Stockpile STMI	Tetal	2	Jun 30, 2021	SYSTEM	\$507.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total				\$507.00	
	0070	T-4-1	Construction Stockpile STMI - Total					\$507.00	
	0370 -							\$0.00	
	0380	TYPE A	Construction		4	Sep 2,	SYSTEM	(\$9,480.00)	Payment Estimate Item Adjustment generated Stockpile Transaction



Sep 22, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3387	0380	CRASHWORTHY END TERMINAL (MASH)	Stockpile			2021			
				- Total				(\$9,480.00)	
			Construction Stockpile - Total					(\$9,480.00)	
			Construction Stockpile STMI		2	Jun 30, 2021	SYSTEM	\$9,480.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$9,480.00	
			Construction Stockpile STMI - Total					\$9,480.00	
			Overrun	Overrun	4	Sep 2, 2021	SYSTEM	(\$8,400.00)	
				Overrun - Total				(\$8,400.00)	
			Overrun - Tota	al				(\$8,400.00)	
	0380 -	Total						(\$8,400.00)	
	0390	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile STMI		2	Jun 30, 2021	SYSTEM	\$4,740.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			31101	- Total				\$4,740.00	
			Construction	Stockpile STN	/II - Total			\$4,740.00	
	0390 -	Total						\$4,740.00	
	5001	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	3	Aug 17, 2021	SYSTEM	(\$2,524.44)	
				Overrun - Total				(\$2,524.44)	
			Overrun - Tota					(\$2,524.44)	
	5001 - Total								
J5P3387 -	5P3387 - Total								
Overall -	Total					\$8,399.75			