Pay Estimate Created Date: June 16, 2022

Progress Estimate N 24	annoon	Contract ID Prime Contractor	210219-D05 S & A Equipment &	Builders,			2 Original Contract Amount 22 Net Change Order Amount Current Contract Amount	\$47,437.58
Approval Date								By User
June 16, 2022			Generated and	Approve	ed (and should be considere	ed Draft) at	the Project Office Level by	schaua1
June 16, 2022			Reviewed and Appr	oved (ar	nd should be considered Dra	aft) at the I	Resident Engineer Level by	oeschd1
June 17, 2022				Reviewe	ed and Approved at the Cer	ntral Office	Controllers Office Level by	ramses1
Original Completio	n Date	Current Co	mpletion Date	Act	tual Completion Date	%	of Current Contract Amount	Complete
November 1, 20	21	March	15, 2022		March 14, 2022		97.67%	
	Contract	Informational Da	tes		Milestones			
Date Description	Original	Completion Date	Current Completion	on Date	No Milestones Exist for C	ontract		
Acceptance Date								
Awarded Date	March 3,	2021	March 3, 2021					
Letting Date	February	19, 2021	February 19, 2021					
Notice to Proceed Date	April 5, 2	021	April 5, 2021					
Work Began Date	April 21,	2021	April 21, 2021					

Contract Total Pay For Estimate No. 24				
	This Estimate	Previous	To Date	
210219-D05				
Total Posted Items Pay	\$1,334.78	\$4,361,009.00	\$4,362,343.78	
Gross Item Adjustments	\$1,128.84	\$7,437.68	\$8,566.52	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		<mark>\$4,368,446.68</mark>	\$4,370,910.30	
Contract Total Payable This Estimate:	\$2,463.62			

Contract Total Payable This Estimate:

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5P3195	0630	8061007A	CURB INLET CHECK	EA	\$197.930	2	\$395.86
	0850	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$1,108.410	-1	(\$1,108.41)
	0980	9031210	STRUCTURAL STEEL POSTS	LB	\$11.540	-1	(\$11.54)
	1010	9031270A	2 IN. PSST POST - 12 GA.	LF	\$11.590	-0.41	(\$4.75)
	1030	9031280	2.5 IN. PSST POST - 12 GA.	LF	\$13.230	0.02	\$0.26
	1050	9035004A	SH-FLAT SHEET	SQFT	\$26.400	0.164	\$4.33
	1190	6039903	WATER	LF	\$43.520	49	\$2,132.48
	1220	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	CUYD	\$1,140.040	0.7	\$798.03
	1230	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	LB	\$4.780	87	\$415.86
	5005	1099902		EA	(\$1.000)	5,979.33	(\$5,979.33)
	5006	7279901		LS	\$3,872.660	1	\$3,872.66
	5007	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$49.150	16.67	\$819.33
Project J5P3	195 - Total						\$1,334.78
Overall - Tot	al						\$1,334.78

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line item /	Adjusti	<u>ments This Estimate</u>						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3195	0630	CURB INLET CHECK	Material			-2	\$197.93	(\$395.86)
	0630	CURB INLET CHECK	Material		This adjustment offsets the original system-	2	\$197.93	\$395.86



Pay Estimate Created Date: June 16, 2022

Progre	ess Esti 2	mate Number 4	Contract ID Prime Contra	210219 actor S & A E		Pay Period Start April 2, 2022 (Builders, LLC Pay Period End June 15, 2022 (rder Amount	
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5P3195						generated Material Payment Estimate Item Adjustment (0003) due to user schaua1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
	0650		PAVEMENT (8 NFORCED, 15 FT. JOINTS)	Material			-34,184.878	\$49.15	(\$1,680,186.75
	0650		PAVEMENT (8 NFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	34,184.878	\$49.15	\$1,680,186.75
	0850	PULL BOX,	PREFORMED CLASS 1	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1108.41000 - 1108.41000, 'is applied (if non-zero).	1	\$1,108.41	\$1,108.41
	0980	STRUC	TURAL STEEL POSTS	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.54000 - 11.54000, 'is applied (if non-zero).	1	\$11.54	\$11.54
	1010	2 IN. PSST F	POST - 12 GA.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.59000 - 11.59000, 'is applied (if non-zero).	0.41	\$11.59	\$4.75
	1030	2.5 IN. PSST F	POST - 12 GA.	Overrun			-0.02	\$13.23	(\$0.20
	5003		MISC.	Material			-1	\$5,817.90	(\$5,817.9
	5003		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$5,817.90	\$5,817.90
	5004		MISC.	Material			-1	\$80.00	(\$80.00
	5004		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user schaua1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1	\$80.00	\$80.00
	5007		PAVEMENT (8 NFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	16.67	\$0.26	\$4.4
	5007		PAVEMENT (8 NFORCED, 15 FT. JOINTS)	Material			-16.67	\$49.15	(\$819.33
	5007		PAVEMENT (8 NFORCED, 15 FT. JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	16.67	\$49.15	\$819.33
Fotal									\$1,128.84



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Informatic	on
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5P3195	FAF-63-3(110)	Intersection improvements	63	BOONE	from Rte. Y and Rte	. M to Rte. H	
Totals by J	Job Numbers						
J5P3195					This Estimate	Previous	To Date
	Posted Iten Gross Item	n Pay Adjustments			\$1,334.78 \$1,128.84	\$4,361,009.00 \$7,437.68	\$4,362,343.78 \$8,566.52
		Gro	ss Item F	Pay	\$2,463.62	\$4,368,446.68	\$4,370,910.30
	Incentive				\$0.00	\$0.00	\$0.00
	Disincentiv	e			\$0.00	\$0.00	\$0.00
	Liquidated				\$0.00	\$0.00	\$0.00
	Other Cont	ract Adjustment	ts		\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 5021308, Project Item Line Number 0650, Material Set 502130896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to resolve.	schaua1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 5021308, Project Item Line Number 5007, Material Set 502130896, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Working with materials to resolve.	schaua1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 5021308, Project Item Line Number 5007, Material Set 502130896, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to resolve.	schaua1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 5021308, Project Item Line Number 5007, Material Set 502130896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to resolve.	schaua1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 8061007A, Project Item Line Number 0630, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Working with materials to resolve.	schaua1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 9039901, Project Item Line Number 5003, Material Set 9039901, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Working with materials to resolve.	schaua1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 9039901, Project Item Line Number 5004, Material Set 9039901, Material 0903HSXX - Highway Signing Material, Acceptance Action Generic 0903HSXX is insufficient.	Working with materials to resolve.	schaua1	Overridden
Estimate Exception Type: Item Overrun: Contract 210219-D05, Contract Project J5P3195, Project Item Line Number 1030, Contract Line Item Number 1030, Item 9031280, Minor Item.	Working on Change Order to resolve.	schaua1	Acknowledged



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

date and can differ from the posted amount at the time the Estimate was Generated N

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
0219-D05	J5P3195	0001	0010	2013000	CLEARING AND GRUBBING	15.00	0.00	15.00	ACRE	15.00	\$4,062.43	\$60,936.4
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$175,733.11	\$175,733.1
		0001	0030	2031000	CLASS A EXCAVATION	18,603.00	0.00	18,603.00	CUYD	18,603.00	\$13.99	\$260,255.9
		0001	0040	2035500	EMBANKMENT IN PLACE	135.00	0.00	135.00	CUYD	135.00	\$15.88	\$2,143.8
		0001	0050	2036000	COMPACTING EMBANKMENT	11,536.00	0.00	11,536.00	CUYD	11,536.00	\$4.09	\$47,182.2
		0001	0060	2037075	COMPACTING IN CUT	239.20	0.00	239.20	STA	239.20	\$107.58	\$25,733.
		0001	0070	2071000	LINEAR GRADING CLASS 1	20.20	0.00	20.20	STA	20.20	\$537.52	\$10,857.
		0001	0080	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	47,626.00	0.00	47,626.00	SQYD	47,624.00	\$8.62	\$410,662.
		0001	0090	3101003	GRAVEL (A)	77.00	0.00	77.00	SQYD	77.00	\$30.07	\$2,315.
		0001	0100	4019905	MISC.VEGETATIVE BARRIER 3 IN.	3,492.00	0.00	3,492.00	SQYD	3,492.00	\$7.44	\$25,980.
		0001	0110	6044011	PIPE COLLAR, TYPE A	8.00	0.00	8.00	EA	8.00	\$612.56	\$4,900.
		0001	0120	6083003	3 IN. CONCRETE MEDIAN STRIP	281.90	0.00	281.90	SQYD	221.30	\$180.96	\$40,046.
		0001	0130	6085008	PAVED APPROACH, 8 IN.	54.20	0.00	54.20	SQYD	54.20	\$257.87	\$13,976.
		0001	0140	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	188.00	109.00	297.00	CUYD	297.00	\$61.08	\$18,140.
		0001	0150	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	48.00	-48.00	0.00	CUYD	0.00	\$61.08	\$0.
		0001	0160	6096041	PLACING TYPE 1 ROCK DITCH LINER	188.00	109.00	297.00	CUYD	297.00	\$12.40	\$3,682.
		0001	0170	6096042	PLACING TYPE 2 ROCK DITCH LINER	48.00	-48.00	0.00	CUYD	0.00	\$46.23	\$0.
		0001	0180	6097000	ROCK LINING	49.00	0.00	49.00	CUYD	32.00	\$91.89	\$2,940
		0001	0190	6113010	FURNISHING TYPE 1 ROCK BLANKET	289.00	40.00	329.00	CUYD	329.00	\$62.89	\$20,690.
		0001	0200	6113030	PLACING TYPE 1 ROCK BLANKET	289.00	40.00	329.00	CUYD	329.00	\$18.32	\$6,027
		0001	0210	6117000A	GABIONS	129.00	0.00	129.00	CUYD	129.00	\$271.45	\$35,017
		0001	0220	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM)	2.00	0.00	2.00	EA	2.00	\$2,622.28	\$5,244
		0001	0230	6161005	CONSTRUCTION SIGNS	964.00	0.00	964.00	SQFT	796.00	\$7.92	\$6,304
		0001	0240	6161010	RELOCATED SIGNS	1,114.00	0.00	1,114.00	SQFT	496.00	\$7.92	\$3,928
		0001	0250	6161025	CHANNELIZER (TRIM LINE)	145.00	100.00	245.00	EA	245.00	\$27.14	\$6,649
		0001	0260	6161031	TYPE III MOVEABLE BARRICADE WITH LIGHTS	3.00	4.00	7.00	EA	7.00	\$339.31	\$2,375
		0001	0270	6161033	DIRECTIONAL INDICATOR BARRICADE	76.00	0.00	76.00	EA	58.00	\$113.10	\$6,559
		0001	0280	6161040	FLASHING ARROW PANEL	5.00	0.00	5.00	EA	2.00	\$2,827.57	\$5,655
		0001	0290	6161055	SEQUENTIAL FLASHING WARNING LIGHT	76.00	0.00	76.00	EA	0.00	\$282.76	\$0
		0001	0300	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	3.00	0.00	3.00	EA	3.00	\$7,351.68	\$22,055
		0001	0310	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	8.00	\$7,351.68	\$58,813
		0001	0320	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$239,065.66	\$239,065
		0001	0330	6191000	PAVEMENT EDGE TREATMENT	23,180.00	0.00	23,180.00	LF	23,180.00	\$2.11	\$48,909
		0001	0340	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	12.00	0.00	12.00	LF	12.00	\$33.93	\$407
		0001	0350	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	27.00	0.00	27.00	EA	27.00	\$395.86	\$10,68
		0001	0360	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	3.00	0.00	3.00	EA	3.00	\$735.17	\$2,20
		0001	0370	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	41,366.00	0.00	41,366.00	LF	41,366.00	\$0.23	\$9,51
		0001	0380	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	23,658.00	0.00	23,658.00	LF	23,658.00	\$0.23	\$5,44
		0001	0390	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,504.00	0.00	1,504.00	LF	1,504.00	\$0.45	\$67
		0001	0400	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,005.00	0.00	2,005.00	LF	2,005.00	\$0.17	\$34
		0001	0410	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	3,129.00	0.00	3,129.00	LF	3,129.00	\$0.17	\$53
		0001	0420	6207001	PAVEMENT MARKING REMOVAL	5,795.00	7,794.00	13,589.00	LF	13,589.00	\$1.13	\$15,355
		0001	0430	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.95	\$52,932.06	\$50,285
		0001	0440	7261012	12 IN. PIPE GROUP A	122.00	0.00	122.00	LF	122.00	\$47.86	\$5,838



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

date and can differ from the posted amount at the time the Estimate was Generated N

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
0219-D05	J5P3195	0001	0450	7261015	15 IN. PIPE GROUP A	128.00	0.00	128.00	LF	128.00	\$45.88	\$5,872.0
		0001	0460	7261018	18 IN. PIPE GROUP A	87.00	-37.00	50.00	LF	37.00	\$62.78	\$2,322.
		0001	0470	7261024	24 IN. PIPE GROUP A	71.00	0.00	71.00	LF	71.00	\$58.17	\$4,130.
		0001	0480	7261030	30 IN. PIPE GROUP A	17.00	0.00	17.00	LF	17.00	\$122.87	\$2,088.
		0001	0490	7261048	48 IN. PIPE GROUP A	14.00	0.00	14.00	LF	14.00	\$190.88	\$2,672.
		0001	0500	7261060	60 IN. PIPE GROUP A	49.00	0.00	49.00	LF	41.00	\$200.06	\$8,202.
		0001	0510	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	9.00	0.00	9.00	FT	9.00	\$695.97	\$6,263.
		0001	0520	7320612A	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$11,136.86	\$22,273
		0001	0530	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$735.20	\$1,470
		0001	0540	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	4.00	-2.00	2.00	EA	2.00	\$774.90	\$1,549
		0001	0550	7320624A	SECTION 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	4.00	0.00	4.00	EA	4.00	\$860.41	\$3,441
		0001	0560	7320630A	SECTION 30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	3.00	0.00	3.00	EA	2.00	\$1,274.68	\$2,549
					SECTION							
		0001	0570	7320648A	48 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$2,875.76	\$2,875
		0001	0580	7320660A	60 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$4,177.01	\$8,354
		0001	0590	8051000A	SEEDING - COOL SEASON GRASSES	10.00	0.00	10.00	ACRE	9.00	\$2,431.71	\$21,885
		0001	0600	8061003	SEDIMENT TRAP EXCAVATION	24.00	0.00	24.00	CUYD	8.00	\$39.59	\$316
		0001	0610	8061004	SEDIMENT TRAP ROCK	35.00	0.00	35.00	CUYD	12.00	\$73.52	\$88
		0001	0620	8061005	ROCK DITCH CHECK	341.00	0.00	341.00	LF	341.00	\$12.16	\$4,14
		0001	0630	8061007A	CURB INLET CHECK	3.00	0.00	3.00	EA	2.00	\$197.93	\$39
		0001	0640	8061019	SILT FENCE	7,268.00	0.00	7,268.00	LF	7,090.00	\$2.38	\$16,87
		0002	0650	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	36,434.90	0.00	36,434.90	SQYD	36,434.90	\$49.15	\$1,790,77
		0002	0660	6262000A	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	22.20	0.00	22.20	STA	22.20	\$738.74	\$16,40
		0004	0690	5021340	TYPE A2 SHOULDER	7,458.80	0.00	7,458.80	SQYD	7,458.80	\$34.42	\$256,73
		0010	0710	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	63.00	0.00	63.00	LF	63.00	\$33.37	\$2,10
		0010	0720	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	113.00	0.00	113.00	LF	113.00	\$28.84	\$3,25
		0010	0730	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$3,749.70	\$7,49
		0010	0740	6064100	MEDIAN GUARD CABLE 3 - STRAND	5,115.00	0.00	5,115.00	LF	4,190.00	\$16.41	\$68,75
		0010	0750	6064110	ANCHOR ASSEMBLY, GUARD CABLE 3-STRAND	14.00	0.00	14.00	EA	8.00	\$3,902.04	\$31,21
		0020	0760	9011062	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2	8.00	0.00	8.00	EA	8.00	\$3,110.32	\$24,88
		0020	0770	9011106	BRACKET ARM, 6 FT. OR 1.8 M	8.00	0.00	8.00	EA	8.00	\$481.82	\$3,85
		0020	0780	9011313	LUMINAIRE, LED-C	8.00	0.00	8.00	EA	8.00	\$506.70	\$4,05
		0020	0790	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	3.00	0.00	3.00	EA	3.00	\$6,559.96	\$19,67
		0020	0800	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	54.00	214.00	268.00	LF	268.00	\$11.31	\$3,03
		0020	0810	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	460.00	0.00	460.00	LF	287.00	\$12.44	\$3,57
		0020	0820	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	114.00	0.00	114.00	LF	114.00	\$14.70	\$1,67
		0020	0830	9014004	CONDUIT, 4 IN. RIGID, PUSHED	949.00	0.00	949.00	LF	925.00	\$32.80	\$30,34
		0020	0840	9015010	TRENCHING TYPE I	2,926.00	0.00	2,926.00	LF	2,925.00	\$3.96	\$11,58
		0020	0850	9016110	PULL BOX, PREFORMED CLASS 1	10.00	0.00	10.00	EA	10.00	\$1,108.41	\$11,08
		0020	0860	9016112	PULL BOX, PREFORMED CLASS 3	3.00	0.00	3.00	EA	3.00	\$1,866.19	\$5,59
		0020	0870	9017002	CABLE, 2 AWG 1 CONDUCTOR	580.00	305.00	885.00	LF	885.00	\$2.83	\$2,50
		0020	0880	9017008	CABLE, 8 AWG 1 CONDUCTOR	4,090.00	0.00	4,090.00	LF	4,090.00	\$1.41	\$5,76
		0020	0890	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	450.00	0.00	450.00	LF	450.00	\$0.96	\$43
		0020	0900	9017202	WIRE, 2 AWG, BARE NEUTRAL	290.00	153.00	443.00	LF	443.00	\$2.71	\$1,20
		0020	0910	9017208	WIRE, 8 AWG, BARE NEUTRAL	2,060.00	0.00	2,060.00	LF	2,060.00	\$1.35	\$2,78



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

0020 093 0020 094 0020 095 0020 096 0020 097 0040 098 0040 100 0040 101 0040 102 0040 101 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 103 0040 104 0040 105 0040 104 0040 105 0040 104 0040 104 0060 111 0060 112 0060 114 0060 114 0060 124 0060 124 0070 124 0040 500		oject Catego lo.	ry Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See repor generated date)
0020 094 0020 095 0020 096 0020 096 0020 096 0040 098 0040 098 0040 100 0040 101 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 104 0040 104 0040 106 0040 107 0060 111 0060 112 0060 113 0060 114 0060 116 0060 117 0060 118 0060 120 0060 121 0070 122 0070 123	9-D05 J5P	3195 0020	0920	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	2,360.00	0.00	2,360.00	LF	2,360.00	\$3.39	\$8,000.4
0020 095 0020 096 0020 097 0040 098 0040 100 0040 101 0040 101 0040 102 0040 101 0040 102 0040 103 0040 104 0040 104 0040 104 0040 104 0040 104 0040 104 0040 104 0040 104 0040 104 0040 104 0040 104 0040 104 0040 104 0040 107 0060 114 0060 114 0060 114 0060 115 0060 116 0060 117 0060 118 0060 124 0060 124 0070 122 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500		0020	0930	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	8.00	\$1,244.13	\$9,953.0
0020 096 0020 097 0040 099 0040 100 0040 101 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 102 0040 103 0040 104 0040 105 0040 106 0040 106 0040 107 0060 109 0060 111 0060 112 0060 113 0060 114 0060 117 0060 118 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 120		0020	0940	9018610	POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY	3.00	0.00	3.00	EA	3.00	\$1.13	\$3.3
0200 097 0040 098 0040 100 0040 101 0040 102 0040 102 0040 102 0040 102 0040 103 0040 103 0040 106 0040 107 0040 108 0040 109 0040 109 0040 109 0040 109 0040 109 0060 119 0060 110 0060 111 0060 112 0060 113 0060 116 0060 117 0060 118 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500		0020	0950	9028500	CABLE, LOOP DETECTOR, IN DUCT	420.00	-420.00	0.00	LF	0.00	\$5.09	\$0.0
0400 098 0400 100 0400 100 0400 101 0400 102 0400 103 0400 104 0400 104 0400 104 0400 104 0400 104 0400 104 0400 105 0400 106 0400 108 0400 108 0400 108 0400 108 0400 108 0400 108 0400 110 0600 111 0600 111 0600 113 0600 114 0600 115 0600 116 0600 117 0600 118 0600 121 0700 122 0060 121 0070 122 0070 123 0070 124		0020	0960	9028510	CABLE, LOOP DETECTOR, LEAD-IN	400.00	-400.00	0.00	LF	0.00	\$1.47	\$0.
0400 099 0400 100 0400 102 0400 103 0400 104 0400 103 0400 104 0400 104 0400 104 0400 105 0400 106 0400 106 0400 106 0400 108 0400 108 0400 109 0600 109 0600 111 0600 112 0600 113 0600 114 0600 115 0600 116 0600 117 0600 118 0600 119 0600 119 0600 119 0600 119 0600 119 0600 119 0600 119 0600 119 0600 119 0600 119		0020	0970	9105020	CONDUIT, 1 IN., LOOP DETECTOR	30.00	-30.00	0.00	LF	0.00	\$9.05	\$0.
0040 100 0040 102 0040 103 0040 103 0040 104 0040 105 0040 106 0040 106 0040 106 0040 106 0040 106 0040 107 0060 109 0060 111 0060 112 0060 113 0060 116 0060 116 0060 117 0060 118 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 120 0070 123 0070 124 0040 500 0040 500 0040 500		0040	0980	9031210	STRUCTURAL STEEL POSTS	780.00	0.00	780.00	LB	780.00	\$11.54	\$9,001.
0040 101 0040 102 0040 103 0040 104 0040 105 0040 106 0040 107 0040 106 0040 107 0040 107 0040 107 0040 107 0060 110 0060 111 0060 112 0060 113 0060 116 0060 116 0060 117 0060 118 0060 120 0060 120 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0040	0990	9031242	36 IN. SURFACE-MOUNT DELINEATOR POST	18.00	0.00	18.00	EA	18.00	\$122.86	\$2,211.
0040 102 0040 103 0040 103 0040 105 0040 105 0040 106 0040 107 0060 108 0060 109 0060 111 0060 111 0060 113 0060 114 0060 115 0060 116 0060 117 0060 118 0060 119 0060 119 0060 111 0060 113 0060 116 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 120 0070 123 0070 124 0040 500 0040 500		0040	1000	9031256	7 FT. CHANNEL POST DELINEATOR, WHITE	28.00	0.00	28.00	EA	28.00	\$54.45	\$1,524.
0040 103 0040 104 0040 105 0040 106 0040 106 0040 106 0040 107 0060 109 0060 111 0060 112 0060 113 0060 114 0060 115 0060 116 0060 116 0060 116 0060 117 0060 118 0060 119 0060 119 0060 119 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0040	1010	9031270A	2 IN. PSST POST - 12 GA.	1,043.00	214.00	1,257.00	LF	1,257.00	\$11.59	\$14,568.
040 104 040 105 040 105 040 107 060 109 0600 109 0600 110 0600 111 0600 112 0600 114 0600 115 0600 116 0600 117 0600 116 0060 116 0060 116 0060 116 0060 117 0060 116 0060 117 0060 118 0060 120 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0040	1020	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	327.00	-3.00	324.00	LF	321.00	\$10.70	\$3,434.
0040 105 0040 107 0040 107 0060 108 0060 109 0060 111 0060 111 0060 112 0060 113 0060 114 0060 115 0060 116 0060 117 0060 118 0060 120 0060 121 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0040	1030	9031280	2.5 IN. PSST POST - 12 GA.	202.00	63.00	265.00	LF	281.00	\$13.23	\$3,717.
040 106 040 107 060 108 060 109 0660 110 0660 111 0060 111 0060 113 0060 114 0060 115 0060 116 0060 117 0060 118 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0040	1040	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	54.00	6.00	60.00	LF	60.00	\$51.39	\$3,083.
0040 107 0060 109 0060 110 0060 111 0060 112 0060 113 0060 114 0060 116 0060 116 0060 116 0060 117 0060 118 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0040	1050	9035004A	SH-FLAT SHEET	932.00	39.00	971.00	SQFT	971.00	\$26.40	\$25,634.
0060 108 0060 109 0060 110 0060 111 0060 112 0060 113 0060 114 0060 115 0060 116 0060 117 0060 118 0060 120 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0001 500		0040	1060	9035011A	ST-STRUCTURAL	120.00	0.00	120.00	SQFT	120.00	\$41.44	\$4,972.
0060 109 0060 110 0060 111 0060 111 0060 113 0060 114 0060 115 0060 116 0060 117 0060 118 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0040	1070	9035069A	SHF-FLAT SHEET FLUORESCENT	175.00	-9.00	166.00	SQFT	166.00	\$35.02	\$5,813.
0060 110 0060 111 0060 112 0060 113 0060 114 0060 115 0060 116 0060 117 0060 118 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0060	1080	2079909	MISC.FINE GRADING AND SEEDING (WATER LINE RELOCATION)	7.30	0.00	7.30	STA	7.30	\$2,047.11	\$14,943
0060 111 0060 112 0060 113 0060 114 0060 115 0060 116 0060 117 0060 117 0060 117 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0060	1090	3109910	MISC.GRAVEL (WATER LINE RELOCATION)	250.00	0.00	250.00	TONS	250.00	\$51.76	\$12,940
0060 112 0060 113 0060 114 0060 115 0060 116 0060 117 0060 118 0060 119 0060 120 0060 121 0070 123 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0060	1100	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$7,199.49	\$7,199
0060 113 0060 114 0060 115 0060 116 0060 118 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0041 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0001 500		0060	1110	6039901	WATER	1.00	0.00	1.00	LS	1.00	\$3,176.76	\$3,176
0060 114 0060 115 0060 117 0060 117 0060 119 0060 120 0060 120 0060 121 0070 122 0070 123 0040 500 0040 500 0040 500 0040 500 0040 500 0001 500		0060	1120	6039902	WATER	3.00	0.00	3.00	EA	3.00	\$1,937.86	\$5,813
0060 115 0060 117 0060 117 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 00010 500 00010 500		0060	1130	6039902	WATER	6.00	0.00	6.00	EA	6.00	\$2,053.22	\$12,319
0060 116 0060 117 0060 118 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0001 500		0060	1140	6039902	WATER	2.00	0.00	2.00	EA	2.00	\$6,405.41	\$12,810
0060 117 0060 118 0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0001 500		0060	1150	6039902	WATER	10.00	0.00	10.00	EA	10.00	\$891.27	\$8,912
0060 118 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0001 500 0001 500		0060	1160	6039902	WATER	2.00	0.00	2.00	EA	2.00	\$1,451.52	\$2,903
0060 119 0060 120 0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500		0060	1170	6039903	WATER	25.00	0.00	25.00	LF	25.00	\$110.95	\$2,773
0060 120 0060 121 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0001 500		0060	1180	6039903	WATER	55.00	0.00	55.00	LF	55.00	\$145.82	\$8,020
0060 121 0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0001 500 0001 500		0060	1190	6039903	WATER	700.00	49.00	749.00	LF	749.00	\$43.52	\$32,596
0070 122 0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0001 500 0001 500 0001 500		0060	1200	6189901	MISC.MOBILIZATION FOR WATER LINE RELOCATION	1.00	0.00	1.00	LS	1.00	\$3,654.03	\$3,654
0070 123 0070 124 0040 500 0040 500 0040 500 0040 500 0040 500 0040 500 0001 500 0001 500		0060	1210	7032002	CLASS B CONCRETE (MISC)	10.00	0.00	10.00	CUYD	10.00	\$239.84	\$2,398
0070 124 0040 500 0010 500 0040 500 0040 500 00010 500 00011 500 00012 500		0070	1220	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	2.90	0.70	3.60	CUYD	3.60	\$1,140.04	\$4,104
0040 500 0010 500 0040 500 0040 500 0040 500 00010 500 00011 500 00011 500		0070	1230	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	490.00	87.00	577.00	LB	577.00	\$4.78	\$2,758
0010 500 0040 500 0040 500 0001 500 0001 500		0070	1240	7133000	BRIDGE GUARDRAIL (W-BEAM)	29.00	0.00	29.00	LF	29.00	\$265.79	\$7,707
0040 500 0040 500 0001 500 0001 500		0040	5001	9031010	CONCRETE FOOTINGS, EMBEDDED	0.00	1.80	1.80	CUYD	1.80	\$1,057.10	\$1,902
0040 500 0001 500 0001 500		0010	5002	6069901	MISC.Guard Cable	0.00	1.00	1.00	LS	1.00	\$17,460.00	\$17,460
0001 500 0001 500		0040	5003	9039901	MISC.Structural Steel	0.00	1.00	1.00	LS	1.00	\$5,817.90	\$5,817
0001 500		0040	5004	9039901	MISC.Reflective Panels	0.00	1.00	1.00	LS	1.00	\$80.00	\$80
		0001	5005	1099902		0.00	5,979.33	5,979.33	EA	5,979.33	(\$1.00)	(\$5,979
0002 500		0001	5006	7279901		0.00	1.00	1.00	LS	1.00	\$3,872.66	\$3,872
		0002	5007	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS)	0.00	16.67	16.67	SQYD	16.67	\$49.15	\$819
Project J5P3195 - Total V	Proj	ject J5P3195	Total Val	ue Posted to I	Date as of Report Generated Date							\$4,362,343.



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project:	J5P3195											
Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0630	8061007A	CURB INLET CHECK	4/5/22	4/5/22	2.00	EA	US 63					
0850	9016110	PULL BOX, PREFORMED CLASS 1	4/5/22	4/5/22	-1.00	EA	US 63					Extra pull box was added to estimate 19.
0980	9031210	STRUCTURAL STEEL POSTS	4/5/22	4/5/22	-1.00	LB	US 63					Per spec final quantity to be rounded to the nearest 10.
1010	9031270A	2 IN. PSST POST - 12 GA.	4/5/22	4/5/22	-0.41	LF	US 63					Rounding to nearest whole number.
1030	9031280	2.5 IN. PSST POST - 12 GA.	4/5/22	4/5/22	0.02	LF	US 63					Rounding to nearest whole number.
1050	9035004A	SH-FLAT SHEET	4/5/22	4/5/22	0.16	SQFT	US 63					Rounding to nearest whole number.
1190	6039903	WATER - UTILITY ITEM	6/15/22	6/16/22	49.00	LF	East New Salem					
1220	7034040	CLASS B-1 CONCRETE (CULVERTS-BRIDGE)	6/15/22	6/16/22	0.70	CUYD	US 63					
1230	7061020	REINFORCING STEEL (CULVERTS-BRIDGE)	6/15/22	6/16/22	87.00	LB	US 63					
5005	1099902	MISC.	6/15/22	6/16/22	5,979.33	EA	US 63					
5006	7279901	MISC.	6/15/22	6/16/22	1.00	LS	US 63					
5007	5021308	CONCRETE PAVEMENT (8 IN. NON-REINFORCED,	6/15/22	6/16/22	16.67	SQYD	US 63					

The information below this line are details for Construction Signs (if applicable). No Data Available



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3195	0030	CLASS A EXCAVATION	Price FUEL	туре	2	May 3, 2021	SYSTEM	\$32.93	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	May 17, 2021	SYSTEM	\$251.27	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Jun 16, 2021	SYSTEM	\$143.20	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Jul 2, 2021	SYSTEM	\$50.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Jul 15, 2021	SYSTEM	\$52.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Aug 2, 2021	SYSTEM	\$52.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Sep 2, 2021	SYSTEM	\$149.76	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Sep 16, 2021	SYSTEM	\$154.12	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Oct 4, 2021	SYSTEM	\$414.32	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Oct 18, 2021	SYSTEM	\$480.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Nov 2, 2021	SYSTEM	\$445.92	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$2,225.52	
			Price FUEL -	Total				\$2,225.52	
	0030 - 0040	EMBANKMENT	Price FUEL		15	Nov 17,	SYSTEM	\$2,225.52 \$38.74	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		IN PLACE		- Total		2021		\$38.74	
			Price FUEL -	Total				\$38.74	
	0040 -	Total						\$38.74	
	0050	COMPACTING EMBANKMENT	Material		2	May 3, 2021	SYSTEM	\$1,092.03	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$1,092.03)	
					3	May 17, 2021	SYSTEM	\$7,889.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 17,	SYSTEM	(\$7,889.61)	
						2021		(++,)	
					4	Jun 3, 2021	SYSTEM	\$7,889.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jun 3,	SYSTEM SYSTEM		Estimate Item Adjustment (0003) due to user webers1 overridding Payment
						Jun 3, 2021 Jun 3,		\$7,889.61	Estimate Item Adjustment (0003) due to user webers1 overridding Payment
					4	Jun 3, 2021 Jun 3, 2021 Jun 16,	SYSTEM	\$7,889.61 (\$7,889.61)	Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment
					4	Jun 3, 2021 Jun 3, 2021 Jun 16, 2021 Jun 16,	SYSTEM SYSTEM	\$7,889.61 (\$7,889.61) \$12,298.63	Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment
					4 5 5	Jun 3, 2021 Jun 3, 2021 Jun 16, 2021 Jun 16, 2021 Jul 2,	SYSTEM SYSTEM SYSTEM	\$7,889.61 (\$7,889.61) \$12,298.63 (\$12,298.63)	Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment
					4 5 5 6	Jun 3, 2021 Jun 3, 2021 Jun 16, 2021 Jun 16, 2021 Jul 2, 2021 Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$7,889.61 (\$7,889.61) \$12,298.63 (\$12,298.63) \$14,343.63	Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment
					4 5 5 6 6	Jun 3, 2021 Jun 3, 2021 Jun 16, 2021 Jun 2, 2021 Jul 2, 2021 Jul 2, 2021 Jul 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,889.61 (\$7,889.61) \$12,298.63 (\$12,298.63) \$14,343.63 (\$14,343.63)	Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.
					4 5 5 6 7	Jun 3, 2021 Jun 3, 2021 Jun 16, 2021 Jun 16, 2021 Jul 2, 2021 Jul 2, 2021 Jul 15, 2021 Jul 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,889.61 (\$7,889.61) \$12,298.63 (\$12,298.63) \$14,343.63 (\$14,343.63) \$16,388.63	Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3195	0050	COMPACTING EMBANKMENT	Material		9	Aug 16, 2021	SYSTEM	\$18,433.63	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$18,433.63)	
					10	Sep 2, 2021	SYSTEM	\$21,075.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$21,075.77)	
					11	Sep 16, 2021	SYSTEM	\$23,178.03	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Sep 16, 2021	SYSTEM	(\$23,178.03)	
					12	Oct 4, 2021	SYSTEM	\$25,836.53	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Oct 4, 2021	SYSTEM	(\$25,836.53)	
					13	Oct 18, 2021	SYSTEM	\$38,106.53	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$38,106.53)	
				- Total				\$0.00	
			Material - Tota	il .				\$0.00	
	0050 -	Total			_			\$0.00	
	0060	COMPACTING IN CUT	Material		2	May 3, 2021	SYSTEM	\$258.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	May 3, 2021	SYSTEM	(\$258.19)	
					3	May 17, 2021	SYSTEM	\$5,744.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 17, 2021	SYSTEM	(\$5,744.77)	
					4	Jun 3, 2021	SYSTEM	\$5,744.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Jun 3, 2021	SYSTEM	(\$5,744.77)	
					5	Jun 16, 2021	SYSTEM	\$5,744.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$5,744.77)	
					6	Jul 2, 2021	SYSTEM	\$5,744.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jul 2, 2021	SYSTEM	(\$5,744.77)	
					7	Jul 15, 2021	SYSTEM	\$5,744.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jul 15, 2021	SYSTEM	(\$5,744.77)	
					8	Aug 2, 2021	SYSTEM	\$5,744.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$5,744.77)	
					9	Aug 16, 2021	SYSTEM	\$5,744.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 16,	SYSTEM	(\$5,744.77)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3195	0060	COMPACTING	Material			2021			
		IN CUT			10	Sep 2, 2021	SYSTEM	\$8,638.67	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$8,638.67)	
					11	Sep 16, 2021	SYSTEM	\$8,638.67	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Sep 16, 2021	SYSTEM	(\$8,638.67)	
					12	Oct 4, 2021	SYSTEM	\$18,837.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Oct 4, 2021	SYSTEM	(\$18,837.26)	
					13	Oct 18, 2021	SYSTEM	\$18,837.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$18,837.26)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0060 -	Total						\$0.00	
	0080	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		2	May 3, 2021	SYSTEM	\$7,717.59	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		IN. THORY			2	May 3, 2021	SYSTEM	(\$7,717.59)	
					3	May 17, 2021	SYSTEM	\$53,040.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	May 17, 2021	SYSTEM	(\$53,040.13)	
					4	Jun 3, 2021	SYSTEM	\$94,352.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jun 3, 2021	SYSTEM	(\$94,352.98)	
					5	Jun 16, 2021	SYSTEM	\$82,073.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jun 16, 2021	SYSTEM	(\$82,073.81)	
					6	Jul 2, 2021	SYSTEM	\$93,283.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Jul 2, 2021	SYSTEM	(\$93,283.72)	
					7	Jul 15, 2021	SYSTEM	\$119,652.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Jul 15, 2021	SYSTEM	(\$119,652.89)	
					8	Aug 2, 2021	SYSTEM	\$164,337.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$164,337.32)	
					9	Aug 16, 2021	SYSTEM	\$155,714.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$155,714.31)	
					10	Sep 2, 2021	SYSTEM	\$184,135.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3195	0080	TYPE 5 AGGREGATE	Material		10	Sep 2, 2021	SYSTEM	(\$184,135.76)	
		FOR BASE (6 IN. THICK)			11	Sep 16, 2021	SYSTEM	\$198,639.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Sep 16, 2021	SYSTEM	(\$198,639.66)	
					12	Oct 4, 2021	SYSTEM	\$245,695.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Oct 4, 2021	SYSTEM	(\$245,695.42)	
					13	Oct 18, 2021	SYSTEM	\$271,262.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$271,262.65)	
					14	Nov 2, 2021	SYSTEM	\$262,639.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$262,639.64)	
					15	Nov 17, 2021	SYSTEM	\$262,639.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$262,639.64)	
					16	Dec 2, 2021	SYSTEM	\$228,147.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Dec 2, 2021	SYSTEM	(\$228,147.60)	
					17	Dec 16, 2021	SYSTEM	\$233,959.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Dec 16, 2021	SYSTEM	(\$233,959.51)	
					18	Jan 4, 2022	SYSTEM	\$233,959.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Jan 4, 2022	SYSTEM	(\$233,959.51)	
			Material - Tota	- Total				\$0.00 \$0.00	
			Price FUEL		2	May 3,	SYSTEM	\$67.93	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	2021 May 17, 2021	SYSTEM	\$592.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jun 3, 2021	SYSTEM	\$539.95	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Jun 16, 2021	SYSTEM	\$411.24	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Jul 2, 2021	SYSTEM	\$264.50	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Jul 15, 2021	SYSTEM	\$485.34	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Aug 2, 2021	SYSTEM	\$858.97	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Sep 2, 2021	SYSTEM	\$730.85	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Sep 16, 2021	SYSTEM	\$197.30	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Oct 4, 2021	SYSTEM	\$640.11	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Oct 18, 2021	SYSTEM	\$913.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J5P3195	0080	TYPE 5 AGGREGATE	Price FUEL	51	17	Dec 16, 2021	SYSTEM	\$124.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
		FOR BASE (6 IN. THICK)			19	Jan 18, 2022	SYSTEM	\$247.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL							
				- Total				\$6,073.20								
			Price FUEL - 1	fotal				\$6,073.20								
	0080 -	Total						\$6,073.20								
	0100	MISC.	Material		15	Nov 17, 2021	SYSTEM	\$25,980.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
					15	Nov 17, 2021	SYSTEM	(\$25,980.48)								
				- Total				\$0.00								
			Material - Tota	al				\$0.00								
			Other Item Adjustment	ACAD	15	Nov 17, 2021	schaua1	\$1,944.61	AC adjustment for 3492 SQYDs of vegetative barrier at 4.5% VAC 05BP2R2.							
				ACAD - Tota	al			\$1,944.61								
				FUEL	15	Nov 17, 2021	schaua1	\$1,568.59	Fuel adjustment for 3492 SQYDs, converted based on 1.98 tons per cubic yard, of vegetative barrier at Fuel Usage Factor 3.32 05BP2R2.							
				FUEL - Tota				\$1,568.59								
			Other Item Ad	justment - To	tal			\$3,513.20								
	0100 -							\$3,513.20								
	0110	PIPE COLLAR, TYPE A	Material		5	Jun 16, 2021	SYSTEM	\$612.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					5	Jun 16, 2021	SYSTEM	(\$612.56)								
					6	Jul 2, 2021	SYSTEM	\$612.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					6	Jul 2, 2021	SYSTEM	(\$612.56)								
				- Total				\$0.00								
			Material - Total					\$0.00								
	0110 -	Total						\$0.00								
	0120	3 IN. CONCRETE MEDIAN STRIP	Material		7	Jul 15, 2021	SYSTEM	\$12,866.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.							
						7	Jul 15, 2021	SYSTEM	(\$12,866.26)							
					8	Aug 2, 2021	SYSTEM	\$12,866.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
											٤	8	Aug 2, 2021	SYSTEM	(\$12,866.26)	
					9	Aug 16, 2021	SYSTEM	(\$12,866.26)								
					10	Sep 2, 2021	SYSTEM	\$12,866.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.							
					10	Sep 2, 2021	SYSTEM	(\$12,866.26)								
					11	11	Sep 16, 2021	SYSTEM	\$12,866.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					11	Sep 16, 2021	SYSTEM	(\$12,866.26)								
												12	Oct 4, 2021	SYSTEM	\$12,866.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Oct 4,	SYSTEM	(\$12,866.26)								



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3195	0120	3 IN.	Material			2021			
		CONCRETE MEDIAN STRIP			13	Oct 18, 2021	SYSTEM	\$40,046.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$40,046.45)	
					14	Nov 2, 2021	SYSTEM	\$40,046.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schaua1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$40,046.45)	
					15	Nov 17, 2021	SYSTEM	\$40,046.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schaua1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$40,046.45)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0120 -	Total						\$0.00	
	0130	PAVED APPROACH, 8 IN.	Material		13	Oct 18, 2021	SYSTEM	\$13,976.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$13,976.55)	
					14	Nov 2, 2021	SYSTEM	\$13,976.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schaua1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$13,976.55)	
					15	Nov 17, 2021	SYSTEM	\$13,976.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schaua1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$13,976.55)	
				- Total				\$0.00	
			Material - Tota	d				\$0.00	
			Price FUEL		13	Oct 18, 2021	SYSTEM	\$26.02	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$26.02	
			Price FUEL - 1	otal				\$26.02	
	0130 - 0140	FURNISHING	Overrun	Overrun	16	Dec 2,	SYSTEM	\$26.02 (\$6,291.24)	
		TYPE 1 ROCK DITCH LINER			17	2021 Dec 16,	SYSTEM	(\$366.48)	
					19	2021 Jan 18,	SYSTEM	\$6,657.72	Unit price based on averaged overrun adjustments for installed quantity on all
				A	- 4 - 1	2022		60.00	previous payment estimates. Price Adjustments of ',61.08000 - 61.08000, 'is applied (if non-zero).
			Overrun - Tota	Overrun - T	otai			\$0.00 \$0.00	
	0140 -	Total	overrun - Tota						
	0140 -	PLACING TYPE	Overrun	Overrun	16	Dec 2,	SYSTEM	\$0.00 (\$1.277.20)	
	0100	1 ROCK DITCH LINER	Ovenull	Ovenull	10	Dec 2, 2021 Dec 16,	SYSTEM	(\$1,277.20)	
					17	2021 Jan 18,	SYSTEM	(\$74.40)	Unit price based on averaged overrun adjustments for installed quantity on all
						2022	C. CILIVI		previous payment estimates. Price Adjustments of ',12.40000 - 12.40000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0160 -							\$0.00	
	0180	ROCK LINING	Material		16	Dec 2, 2021	SYSTEM	\$1,562.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment



t	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре			_,		
95	0180	ROCK LINING	Material						Estimate Exception 3 on the current Payment Estimate.
					16	Dec 2, 2021	SYSTEM	(\$1,562.13)	
					17	Dec 16, 2021	SYSTEM	\$1,562.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schaua1 overridding Paymen Estimate Exception 3 on the current Payment Estimate.
					17	Dec 16, 2021	SYSTEM	(\$1,562.13)	
					18	Jan 4, 2022	SYSTEM	\$1,562.13	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schaua1 overridding Paymen Estimate Exception 3 on the current Payment Estimate.
					18	Jan 4, 2022	SYSTEM	(\$1,562.13)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0180 -	Total						\$0.00	
ſ	0190	FURNISHING TYPE 1 ROCK BLANKET	Material		11	Sep 16, 2021	SYSTEM	\$12,011.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Paymen Estimate Exception 8 on the current Payment Estimate.
					11	Sep 16, 2021	SYSTEM	(\$12,011.99)	
					12	Oct 4, 2021	SYSTEM	\$12,011.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Paymen Estimate Exception 9 on the current Payment Estimate.
					12	Oct 4, 2021	SYSTEM	(\$12,011.99)	
					13	Oct 18, 2021	SYSTEM	\$12,011.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payme Estimate Exception 14 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$12,011.99)	
					14	Nov 2, 2021	SYSTEM	\$12,011.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schaua1 overridding Payme Estimate Exception 13 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$12,011.99)	
					15	Nov 17, 2021	SYSTEM	\$12,011.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schaua1 overridding Payme Estimate Exception 15 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$12,011.99)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Overrun	Overrun	16	Dec 2, 2021	SYSTEM	(\$1,320.69)	
					19	Jan 18, 2022	SYSTEM	\$1,320.69	Unit price based on averaged overrun adjustments for installed quantity o previous payment estimates. Price Adjustments of ',62.89000 - 62.89000, applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0190 -	Total						\$0.00	
	0200	PLACING TYPE 1 ROCK	Overrun	Overrun	16	Dec 2, 2021	SYSTEM	(\$384.72)	
		BLANKET			19	Jan 18, 2022	SYSTEM	\$384.72	Unit price based on averaged overrun adjustments for installed quantity o previous payment estimates. Price Adjustments of ',18.32000 - 18.32000, applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0200 -	Total						\$0.00	
	0210	GABIONS	Material		4	Jun 3, 2021	SYSTEM	\$20,087.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payme
	0210								Estimate Exception 10 on the current Payment Estimate.



Jun 18, 2022

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
P3195	0210	GABIONS	Material	- Total				\$0.00		
			Material - Tota	I				\$0.00		
	0210 -	Total				_		\$0.00		
	0330	PAVEMENT EDGE TREATMENT	Material		3	May 17, 2021	SYSTEM	\$6,100.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					3	May 17, 2021	SYSTEM	(\$6,100.01)		
				- Total				\$0.00		
			Material - Tota	ıl				\$0.00		
	0330 -	Total						\$0.00		
	0350	PREF THERMO PVMT MARK, LT/RT ARROW	Material		19	Jan 18, 2022	SYSTEM	\$10,688.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					19	Jan 18, 2022	SYSTEM	(\$10,688.22)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	0350 -	Total						\$0.00		
	0360	PREF THERMO PVMT MARK, WORD (ONLY)	Material		19	Jan 18, 2022	SYSTEM	\$2,205.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schaua1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					19	Jan 18, 2022	SYSTEM	(\$2,205.51)		
				- Total				\$0.00		
			Material - Tota	I				\$0.00		
	0360 -	Total						\$0.00		
	0370		0 6 IN. WHITE HIGH BUILD WATERBORNE	Material		17	Dec 16, 2021	SYSTEM	\$4,757.09	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					17	Dec 16, 2021	SYSTEM	(\$4,757.09)		
				- Total				\$0.00		
			Material - Tota	I				\$0.00		
			Other Item Adjustment	REFL	19	Jan 18, 2022	schaua1	\$338.56	Bonus for Retro reflectivity results, calculated using worksheet.	
				REFL - Tota				\$338.56		
			Other Item Ad	justment - To	tal			\$338.56		
	0370 -	Total						\$338.56		
	0380	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		17	Dec 16, 2021	SYSTEM	\$2,720.67	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schaua1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					17	Dec 16, 2021	SYSTEM	(\$2,720.67)		
				- Total				\$0.00		
			Material - Tota	I				\$0.00		
			Other Item Adjustment	REFL	19	Jan 18, 2022	schaua1	\$260.72	Bonus for Retro reflectivity results, calculated using worksheet.	
				REFL - Tota	I			\$260.72		
			Other Item Ad	justment - To	tal			\$260.72		
	0380 -	Total						\$260.72		
	0400	4 IN. WHITE WATERBORNE PAVEMENT	Other Item Adjustment	REFL		Apr 4, 2022	schaua1	(\$68.17)	20% withheld pending retro results.	
		MARKING		REFL - Tota				(\$68.17)		
			Other Item Ad	justment - To	tal			(\$68.17)		
	0400 -							(\$68.17)		
	0410	4 IN. YELLOW WATERBORNE PAVEMENT	Other Item Adjustment	REFL		Apr 4, 2022	schaua1	(\$106.39)	20% withheld pending retro results.	
		MARKING		REFL - Tota				(\$106.39)		



Jun 18, 2022

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	By		
J5P3195	0410	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	Other Item Ad	justment - To	tal			(\$106.39)	
	0410 -	Total						(\$106.39)	
	0510	PRECAST CONCRETE DROP INLET 5	Material		19	Jan 18, 2022	SYSTEM	\$6,263.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schaua1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		FT X 3 FT			19	Jan 18, 2022	SYSTEM	(\$6,263.73)	
					20	Feb 2, 2022	SYSTEM	\$6,263.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					20	Feb 2, 2022	SYSTEM	(\$6,263.73)	
					21	Feb 16, 2022	SYSTEM	\$6,263.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					21	Feb 16, 2022	SYSTEM	(\$6,263.73)	
					22	Mar 2, 2022	SYSTEM	\$6,263.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					22	Mar 2, 2022	SYSTEM	(\$6,263.73)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0510 -	Total						\$0.00	
	0590	SEEDING - COOL SEASON GRASSES	Material		12	Oct 4, 2021	SYSTEM	\$4,863.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Oct 4, 2021	SYSTEM	(\$4,863.42)	
					13	Oct 18, 2021	SYSTEM	\$4,863.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$4,863.42)	
					14	Nov 2, 2021	SYSTEM	\$4,863.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$4,863.42)	
				15	15	Nov 17, 2021	SYSTEM	\$4,863.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schaua1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$4,863.42)	
				- Total				\$0.00	
			Material - Tota	d				\$0.00	
			Other Item Adjustment	OTHR	21	Feb 16, 2022	webers1	(\$4,377.00)	Withholding 20% till proper seed growth is established per EPG
				OTHR - Tota				(\$4,377.00)	
			Other Item Ad	justment - To	tal			(\$4,377.00)	
	0590 -							(\$4,377.00)	
	0630	CURB INLET CHECK	Material		24	Jun 16, 2022	SYSTEM	\$395.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schaua1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					24	Jun 16, 2022	SYSTEM	(\$395.86)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0630 -	Total						\$0.00	
	0640	SILT FENCE	Material		2	May 3,	SYSTEM	\$2,058.70	This adjustment offsets the original system-generated Material Payment



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J5P3195	0640	SILT FENCE	Material			2021			Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					2	May 3, 2021	SYSTEM	(\$2,058.70)			
				- Total				\$0.00			
			Material - Tota					\$0.00			
	0640 -	Total						\$0.00			
	0650	CONCRETE PAVEMENT (8 IN. NON- REINFORCED,	Material		2	May 3, 2021	SYSTEM	\$16,214.58	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
		REINFORCED,			2	May 3, 2021	SYSTEM	(\$16,214.58)			
					3	May 17, 2021	SYSTEM	\$146,059.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					3	May 17, 2021	SYSTEM	(\$146,059.06)			
					4	Jun 3, 2021	SYSTEM	\$233,211.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					4	Jun 3, 2021	SYSTEM	(\$233,211.84)			
					5	Jun 16, 2021	SYSTEM	\$398,144.49	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					5	Jun 16, 2021	SYSTEM	(\$398,144.49)			
						6	Jul 2, 2021	SYSTEM	\$508,496.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
									6	Jul 2, 2021	SYSTEM
					7	Jul 15, 2021	SYSTEM	\$617,668.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					7	Jul 15, 2021	SYSTEM	(\$617,668.05)			
					8	Aug 2, 2021	SYSTEM	\$772,298.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		
					8	Aug 2, 2021	SYSTEM	(\$772,298.86)			
					9	Aug 16, 2021	SYSTEM	\$885,407.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					9	Aug 16, 2021	SYSTEM	(\$885,407.76)			
					10	Sep 2, 2021	SYSTEM	\$1,027,736.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					10	Sep 2, 2021	SYSTEM	(\$1,027,736.33)			
					11	Sep 16, 2021	SYSTEM	\$1,249,225.89	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					11	Sep 16, 2021	SYSTEM	(\$1,249,225.89)			
					12	Oct 4, 2021	SYSTEM	\$1,446,592.63	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					12	Oct 4, 2021	SYSTEM	(\$1,446,592.63)			
					13	Oct 18, 2021	SYSTEM	\$1,498,902.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					13	Oct 18, 2021	SYSTEM	(\$1,498,902.98)			



Project J5P3195	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
J5P3195			Туре	Adjustment Type	Number	Date	Ву	, unoun	
	0650	PAVEMENT (8 IN. NON-	Material		14	Nov 2, 2021	SYSTEM	\$1,678,256.24	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		REINFORCED,			14	Nov 2, 2021	SYSTEM	(\$1,678,256.24)	
					15	Nov 17, 2021	SYSTEM	\$1,684,326.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schaua1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$1,684,326.26)	
					16	Dec 2, 2021	SYSTEM	\$1,684,326.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Dec 2, 2021	SYSTEM	(\$1,684,326.26)	
					17	Dec 16, 2021	SYSTEM	\$1,668,096.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Dec 16, 2021	SYSTEM	(\$1,668,096.05)	
					18	Jan 4, 2022	SYSTEM	\$1,647,084.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					18	Jan 4, 2022	SYSTEM	(\$1,647,084.23)	
					19	Jan 18, 2022	SYSTEM	\$1,680,186.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	Jan 18, 2022	SYSTEM	(\$1,680,186.75)	
					20	Feb 2, 2022	SYSTEM	\$1,680,186.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Feb 2, 2022	SYSTEM	(\$1,680,186.75)	
					21	Feb 16, 2022	SYSTEM	\$1,680,186.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	Feb 16, 2022	SYSTEM	(\$1,680,186.75)	
					22	Mar 2, 2022	SYSTEM	\$1,680,186.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					22	Mar 2, 2022	SYSTEM	(\$1,680,186.75)	
					23	Apr 4, 2022	SYSTEM	\$1,680,186.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					23	Apr 4, 2022	SYSTEM	(\$1,680,186.75)	
					24	Jun 16, 2022	SYSTEM	\$1,680,186.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schaua1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					24	Jun 16, 2022	SYSTEM	(\$1,680,186.75)	
				- Total				\$0.00	
			Material - Tota Other Item	OTHR	19	Jan 18,	schaua1	\$0.00 (\$7,099.23)	20% deduction for Concrete due to cure not being placed. Refer to Order
			Adjustment			2022	Sonaua I		Record 002 for detailed breakdown.
				OTHR - Tota		las de		(\$7,099.23)	
				SUBI		Jan 18, 2022	schaua1	(\$442.35)	20% concrete deduction for high air. Refer to NCR 002 for breakdown.
				SUBI - Total				(\$442.35)	
			Other Item Ad	justment - To				(\$7,541.58)	
			Price FUEL		2	May 3, 2021	SYSTEM	\$65.32	Reference Item Price Adjustment Index Adjustment Type applied is FUEL



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3195	0650	CONCRETE PAVEMENT (8	Price FUEL	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	3	May 17, 2021	SYSTEM	\$776.69	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		IN. NON- REINFORCED,			4	Jun 3, 2021	SYSTEM	\$521.32	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Jun 16, 2021	SYSTEM	\$1,006.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Jul 2, 2021	SYSTEM	\$673.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Jul 15, 2021	SYSTEM	\$693.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Aug 2, 2021	SYSTEM	\$981.58	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Aug 16, 2021	SYSTEM	\$828.47	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Sep 2, 2021	SYSTEM	\$1,042.49	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Sep 16, 2021	SYSTEM	\$1,378.96	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Oct 4, 2021	SYSTEM	\$1,228.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Oct 18, 2021	SYSTEM	\$510.86	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Nov 2, 2021	SYSTEM	\$1,751.57	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					15	Nov 17, 2021 Dec 16,	SYSTEM	\$60.76	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					17	2021 Jan 18,	SYSTEM	\$716.30	Reference Item Price Adjustment Index Adjustment Type applied is FUEL Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total	19	2022	STOTEM	\$12,527.32	
			Price FUEL - 1						
	0650 -	Total	FIICE FUEL - I	Utal				\$12,527.32 \$4,985.74	
	0690	TYPE A2 SHOULDER	Material		3	May 17, 2021	SYSTEM	\$15,960.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	May 17, 2021	SYSTEM	(\$15,960.55)	
					4	Jun 3, 2021	SYSTEM	\$33,005.34	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Jun 3, 2021	SYSTEM	(\$33,005.34)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
			Other Item Adjustment	OTHR	19	Jan 18, 2022	schaua1	(\$1,147.56)	20% deduction for A2 shoulder due to cure not being placed. Refer to Order Record 002 for detailed breakdown.
				OTHR - Tota	al			(\$1,147.56)	
			Other Item Ad	justment - To	tal			(\$1,147.56)	
	0690 -	Total						(\$1,147.56)	
	0710	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Material		13	Oct 18, 2021	SYSTEM	\$2,102.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		i i 5 IN			13	Oct 18, 2021	SYSTEM	(\$2,102.31)	
					14	Nov 2, 2021	SYSTEM	\$2,102.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schaua1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$2,102.31)	
					15	Nov 17, 2021	SYSTEM	\$2,102.31	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schaua1 overridding Payment Estimate Exception 7 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3195	0710	MGS GUARDRAIL, 8	Material		15	Nov 17, 2021	SYSTEM	(\$2,102.31)	
		FT. POSTS, 6 FT 3 IN		- Total				\$0.00	
			Material - Tota					\$0.00	
	0710 -	Total						\$0.00	
	0720	MGS GUARDRAIL, 6 FT. POSTS, 3	Material		13	Oct 18, 2021	SYSTEM	\$3,258.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		FT 1.5			13	Oct 18, 2021	SYSTEM	(\$3,258.92)	
					14	Nov 2, 2021	SYSTEM	\$3,258.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schaua1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$3,258.92)	
					15	Nov 17, 2021	SYSTEM	\$3,258.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schaua1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$3,258.92)	
				- Total				\$0.00	
		Material - Tota					\$0.00		
	0720 -	Total						\$0.00	
	0780	LUMINAIRE, LED-C	Material		18	Jan 4, 2022	SYSTEM	\$4,053.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schaua1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					18	Jan 4, 2022	SYSTEM	(\$4,053.60)	
				- Total				\$0.00	
			Material - Tota	d.				\$0.00	
	0780 -	Total						\$0.00	
	0790	BASE MOUNTED CONTROL STATION	Material		18	Jan 4, 2022	SYSTEM	\$19,679.88	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schaua1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		on minor			18	Jan 4, 2022	SYSTEM	(\$19,679.88)	
				- Total				\$0.00	
			Material - Tota	l		\$0.00			
	0790 -	Total						\$0.00	
	0800	CONDUIT, 2 IN. RIGID, IN TRENCH	Overrun	Overrun	8	Aug 2, 2021	SYSTEM	\$893.49	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Aug 2, 2021	SYSTEM	(\$893.49)	
					9	Aug 16, 2021	SYSTEM	(\$893.49)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Aug 16, 2021	SYSTEM	\$893.49	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Sep 2, 2021	SYSTEM	(\$893.49)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					10	Sep 2, 2021	SYSTEM	\$893.49	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Sep 16, 2021	SYSTEM	(\$893.49)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					11	Sep 16, 2021	SYSTEM	\$893.49	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					12	Oct 4, 2021	SYSTEM	(\$893.49)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					12	Oct 4, 2021	SYSTEM	\$893.49	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 16 on the current Payment Estimate.



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type		Date	Ву		
J5P3195	0800	CONDUIT, 2 IN. RIGID, IN TRENCH	Overrun	Overrun	13	Oct 18, 2021	SYSTEM	(\$893.49)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
		menon			19	Jan 18, 2022	SYSTEM	(\$1,526.85)	
					23	Apr 4, 2022	SYSTEM	\$2,420.34	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.31000 - 11.31000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Tota	al				\$0.00	
	0800 -	Total						\$0.00	
	0850	PULL BOX, PREFORMED CLASS 1	Overrun	Overrun	19	Jan 18, 2022	SYSTEM	(\$1,108.41)	
		CLASS T			24	Jun 16, 2022	SYSTEM	\$1,108.41	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1108.41000 - 1108.41000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0850 -	Total						\$0.00	
	0870	CABLE, 2 AWG 1 CONDUCTOR	Material		19	Jan 18, 2022	SYSTEM	(\$2,504.55)	
				- Total				(\$2,504.55)	
			Material - Tota					(\$2,504.55)	
			MaterialCredit		20	Feb 2, 2022	SYSTEM	\$2,504.55	
				- Total				\$2,504.55	
			MaterialCredit	- Total				\$2,504.55	
			Overrun	Overrun	19	Jan 18, 2022	SYSTEM	\$863.15	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 885.000; Overrun Quantity Balance 305.00.
					19	Jan 18, 2022	SYSTEM	(\$863.15)	
					20	Feb 2, 2022	SYSTEM	(\$863.15)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					23	Apr 4, 2022	SYSTEM	\$863.15	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.83000 - 2.83000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0870 -	Total						\$0.00	
	0880	CABLE, 8 AWG 1 CONDUCTOR	Material		18	Jan 4, 2022	SYSTEM	\$5,766.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					18	Jan 4, 2022	SYSTEM	(\$5,766.90)	
					19	Jan 18, 2022	SYSTEM	\$5,766.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schaua1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					19	Jan 18, 2022	SYSTEM	(\$5,766.90)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
	0880 -							\$0.00	
	0890	CABLE, 10 AWG 1 CONDUCTOR, POLE &	Material		18	Jan 4, 2022	SYSTEM	\$432.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schaua1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		BRACKE			18	Jan 4, 2022	SYSTEM	(\$432.00)	
					19	Jan 18, 2022	SYSTEM	\$432.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schaua1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					19	Jan 18, 2022	SYSTEM	(\$432.00)	



Jun 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J5P3195	0890	CABLE, 10 AWG 1	Material	- Total				\$0.00				
		CONDUCTOR, POLE & BRACKE	Material - Tota	l				\$0.00				
	0890 -	Total						\$0.00				
	0900	WIRE, 2 AWG, BARE			19	Jan 18, 2022	SYSTEM	(\$1,200.53)				
		NEUTRAL		- Total				(\$1,200.53)				
			Material - Total MaterialCredit	l				(\$1,200.53)				
			MaterialCredit		20	Feb 2, 2022	SYSTEM	\$1,200.53				
				- Total				\$1,200.53				
			MaterialCredit	- Total				\$1,200.53				
			Overrun	Overrun	19	Jan 18, 2022	SYSTEM	\$414.63	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 443.000; Overrun Quantity Balance 153.00.			
					19	Jan 18, 2022	SYSTEM	(\$414.63)				
					20	Feb 2, 2022	SYSTEM	(\$414.63)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).			
					23	Apr 4, 2022	SYSTEM	\$414.63	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.71000 - 2.71000, 'is applied (if non-zero).			
				Overrun - T	otal			\$0.00				
			Overrun - Tota	ıl				\$0.00				
	0900 -	Total						\$0.00				
	0910	WIRE, 8 AWG, BARE NEUTRAL	E		18	Jan 4, 2022	SYSTEM	\$2,781.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schaua1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					18	Jan 4, 2022	SYSTEM	(\$2,781.00)				
					19	Jan 18, 2022	SYSTEM	\$2,781.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schaua1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					19	Jan 18, 2022	SYSTEM	(\$2,781.00)				
				- Total				\$0.00				
			Material - Tota	I				\$0.00				
	0910 -	Total						\$0.00				
	0920	CABLE- CONDUIT, 1 IN., 2 CONDUCTORS	Material		8	Aug 2, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
		CONDUCTORS	RS					8	Aug 2, 2021	SYSTEM	(\$7,593.60)	
								9	Aug 16, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Aug 16, 2021	SYSTEM	(\$7,593.60)				
					10	Sep 2, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user webers1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					10	Sep 2, 2021	SYSTEM	(\$7,593.60)				
					11	Sep 16, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					11	Sep 16, 2021	SYSTEM	(\$7,593.60)				
					12	Oct 4, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
					12	Oct 4,	SYSTEM	(\$7,593.60)				



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3195	0920	CABLE-	Material			2021			
		CONDUIT, 1 IN., 2 CONDUCTORS			13	Oct 18, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user webers1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$7,593.60)	
					14	Nov 2, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schaua1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$7,593.60)	
					15	Nov 17, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schaua1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$7,593.60)	
					16	Dec 2, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schaua1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					16	Dec 2, 2021	SYSTEM	(\$7,593.60)	
					17	Dec 16, 2021	SYSTEM	\$7,593.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schaua1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					17	Dec 16, 2021	SYSTEM	(\$7,593.60)	
					18	Jan 4, 2022	SYSTEM	\$8,000.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schaua1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					18	Jan 4, 2022	SYSTEM	(\$8,000.40)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	0920 -	Total						\$0.00	
	0920 - 0930	POLE FOUNDATION (45 FT. OR 13.5	Material		6	Jul 2, 2021	SYSTEM	\$0.00 \$2,488.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		POLE FOUNDATION			6		SYSTEM		Estimate Item Adjustment (0009) due to user webers1 overridding Payment
		POLE FOUNDATION (45 FT. OR 13.5				2021 Jul 2,		\$2,488.26	Estimate Item Adjustment (0009) due to user webers1 overridding Payment
		POLE FOUNDATION (45 FT. OR 13.5			6	2021 Jul 2, 2021 Jul 15,	SYSTEM	\$2,488.26 (\$2,488.26)	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment
		POLE FOUNDATION (45 FT. OR 13.5			6 7	2021 Jul 2, 2021 Jul 15, 2021 Jul 15,	SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment
		POLE FOUNDATION (45 FT. OR 13.5			6 7 7	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26)	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment
		POLE FOUNDATION (45 FT. OR 13.5			6 7 7 8	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment
		POLE FOUNDATION (45 FT. OR 13.5			6 7 7 8 8	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) (\$2,488.26)	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.
		POLE FOUNDATION (45 FT. OR 13.5		- Total	6 7 7 8 8 9	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.
		POLE FOUNDATION (45 FT. OR 13.5		- Total	6 7 7 8 8 9	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26)	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.
	0930	POLE FOUNDATION (45 FT. OR 13.5	Material	- Total	6 7 7 8 8 9	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 \$2,488.26	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.
	0930	POLE FOUNDATION (45 FT. OR 13.5 M	Material Material - Tota	- Total	6 7 7 8 8 9	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.
	0930 -	POLE FOUNDATION (45 FT. OR 13.5 M	Material Material - Tota	- Total	6 7 7 8 8 9 9	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jun 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$0.00 \$0.00	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	0930 -	POLE FOUNDATION (45 FT. OR 13.5 M SUPPLY ASSEMBLY, TYPE 1,	Material Material - Tota	- Total	6 7 7 8 8 9 9 9	2021 Jul 2, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Jan 4, 2022 Jan 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26 (\$2,488.26) \$2,488.26) \$2,488.26 (\$2,488.26) \$0.00 \$0.00 \$3.39	Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



Jun 18, 2022

JPS710 040 POVM POVEN Material Total Vertex 54.00 Interval Section 2000 Section 2000 Section 2000 <td co<="" th=""><th></th></td>	<th></th>	
ASSRUE, 20170 Total Interface Total Interface Interface Interface <thinterface< th=""> <thinterface< th=""> Interface<</thinterface<></thinterface<>		
1000 Control Control Second		
0800 STELE POSTS STELE POSTS STELE POSTS STELE POSTS STELE POSTS STELE POSTS STELE POSTS Overrun - Total 0verrun - Total SYSTEM (1) (1) (2) plob based on averaged overrun edjustments of 11.0300 - popled (1) ren-zero). 0000 Overrun - Total 50.00 0000 SHELT 130.00 c. popled (1) movero). 00000 Overrun - Total 50.00 00000 Overrun - Total 50.00 00000 SHELT 130.00 c. popled (1) mov		
$ \begin{array}{c c c c c c } \hline Field POSTS have been been been been been been been be$		
Image: Contraining the second of th		
900 - Total900 - Vertun900 - Vertun100 -		
OSD - Total Overun 19 Jan 16, 2022 SYSTEN (64.77) 1010 2 N. PSST POST - 12 GA Overun 19 Jan 16, 2022 SYSTEN (64.77) 0000 Overun - Total Overun 1000 SYSTEN (64.77) 0000 0000 Overun - Total 0000 SYSTEN 0000 spinol (fram-con) spinol (fram-con) 1030 2.5 N. POST POST - 12 GA Overun - Total 00000 SYSTEN (6211.42) 1030 2.5 N. POST POST - 12 GA Overun - Total 000000 SYSTEN (60.20) 1030 2.5 N. POST POST - 12 GA Overun - Total (5311.60) Total 000000000000000000000000000000000000		
1010 21N POST 12 24 Jan 10. Jan 10. 2022 SYSTEN (44.70) 0verun 0verun 12 24 Jan 10. Jan 10. 2022 SYSTEN 34.75 Unlt price based on averaged overun adjustments for installed applied (if non-zeru). 0 0verun 0verun 0 50.00 0		
POST-12 GA POST-12		
Image: state in the		
Overrun - Total 50.00 1010 - Total 0 Jan 18, 3 SYSTEM (\$211.42) 1030 251 PST - 12 GA, 2002 0 SYSTEM (\$211.42) 0 0 Jun 18, 3 SYSTEM (\$20.20) (\$211.42) 0 0 0 SYSTEM (\$20.20) (\$211.42) 0 0 0 (\$211.42) (\$211.42) (\$211.42) 0 0 0 (\$211.42) (\$211.42) (\$211.42) 0 0 0 (\$211.42) (\$211.42) (\$211.42) 0 0 0 (\$211.42) (\$211.42) (\$211.42) 0 0 0 (\$211.42) (\$211.42) (\$211.42) 0 0 0 (\$211.42) (\$211.42) (\$211.42) 0 0 0 0 (\$211.42) (\$211.42) 0 0 0 0 0 0 0 0 0 0 0 0		
1010-Total Overrun 19 Jan 18, 2022 SYSTEM (S211.42) 1030 2.5 N. RSST POST-12 GA Overrun - Total (S211.42) (S211.63) 0verrun - Total Overrun - Total (S211.63) (S211.63) 1030 - Total Overrun - Total (S211.63) 1030 - Total Overrun - Total (S211.63) 1030 - Total Overrun - Total (S211.63) 1050 SH-FLAT Material Ocerrun - Total 1050 SH-FLAT Material Ocerrun - Total (S211.63) 1050 SH-FLAT Material Oce1.6, SYSTEM SYSTEM S4.202.56 This adjustment offsets the original system-generated Material Estimate Exception 19 on the current Payment Estimate. 14 Nov 2, SYSTEM S4.202.56 This adjustment offsets the original system-generated Material Estimate Exception 19 on the current Payment Estimate. 15 Nov 17, SYSTEM S25.433.13 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 1060 STRUCTURAL Material - Total SYSTEM S1.964.80 1060 <td></td>		
1030 2.5 N, POST - 12 GA, POST		
POST - 12 GA. Image: Control image: Contr		
Image: Control		
Image: constraint of the second sec		
1030 - Total (\$211.68) 1050 SH-FLAT SHEET Material 2021 SYSTEM \$4,202.56 This adjustment offsets the original system-generated Material Estimate Exception 20 on the current Payment Estimate. 13 Oct 18, 2021 SYSTEM \$4,202.56 This adjustment offsets the original system-generated Material Estimate Exception 20 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$4,202.56 This adjustment offsets the original system-generated Material Estimate Exception 19 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$4,202.56 This adjustment offsets the original system-generated Material Estimate Exception 19 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM \$25,433.13 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 1060 1070 1080 STRUCTURAL 13 Oct 18, 2021 SYSTEM \$1,864.80 Total 1080 STRUCTURAL 13 Oct 18, 2021 SYSTEM \$1,864.80 This adjustment o		
1050 SH-FLAT SHEET Material 13 Oct 18, 2021 SYSTEM \$4,202.56 This adjustment offsets the original system-generated Material Estimate Encopion 20 on the current Payment Estimate. 13 Oct 18, 2021 SYSTEM \$4,202.56 This adjustment offsets the original system-generated Material Estimate Encopion 20 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$4,202.56 This adjustment offsets the original system-generated Material Estimate Encopion 10 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$4,202.56 This adjustment offsets the original system-generated Material Estimate Encopion 21 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM \$25,433.13 This adjustment offsets the original system-generated Material Estimate Encopion 21 on the current Payment Estimate. 1050 Total • Total \$0,017 SYSTEM \$(\$25,433.13) 1050 Total • Total \$0,001 This adjustment offsets the original system-generated Material Estimate Encopion 21 on the current Payment Estimate. 1060 STRUCTURAL Material 13 Oct 18, 2021 SYSTEM \$(\$1,864.80) 1070 STRUCTURAL Material 14 Nov 2, 2021 SYSTEM \$(\$1,864.80) 1080 STRUCTURAL Material 10 Oct 18, 2021 SYSTEM		
No. 17. System		
Image: bit is adjustment offsets the original system-generated Material Estimate Exception 19 on the current Payment Estimate. Image: bit is adjustment offsets the original system-generated Material Estimate Exception 19 on the current Payment Estimate. 14 Nov 2, Nov 17, SYSTEM S25,433.13 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 15 Nov 17, SYSTEM S25,433.13 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 150 - Total Total SYSTEM S25,433.13 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 1060 ST. Material - Total Total SYSTEM SYSTEM S18,864.80 1060 ST. STRUCTURAL Meterial Oct 18, SYSTEM SYSTEM S1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 130 Oct 18, SYSTEM S1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 14 Nov 2, SYSTEM S1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 20 on the current Payment Estimate. 132 O		
1000 STRUCTURAL Material 1 0 0 SYSTEM (\$4,202.60) 14 Nov 2, 2021 SYSTEM (\$4,202.60) 1 <t< td=""><td></td></t<>		
Image: bit is adjustment offsets the original system-generated Material isotance (013) due to user schauari overriddi isotance (013) due to user schauari overriddi isotance (014) due to user schauari overriddi isotance (015) Image: bit isotance (015) <th< td=""><td></td></th<>		
1060 2021 2021 SYSTEM Estimate tem Adjustment (0014) due to user schaual overidid Estimate Exception 21 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM (\$25,433.13) •••••••••••••••••••••••••••••••••••		
Image:		
Material - Total \$0.00 1050 - Total \$0.00 1060 ST. STRUCTURAL Material 11 0 ct 18, 2021 SYSTEM \$1.864.80 This adjustment (0018) due to user webers1 overriddi Estimate Item Adjustment (0018) due to user webers1 overriddi Estimate Item Adjustment (0018) due to user webers1 overriddi Estimate Item Adjustment (0013) due to user schaua1 overriddi Estimate Item Adjustment (0015) due to user schaua1 overriddi Estimate Item Adjustmen		
1050 - Total \$0.00 1060 ST. STRUCTURAL Material 13 Oct 18, 2021 SYSTEM \$1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 13 Oct 18, 2021 SYSTEM \$1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$1,864.80 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0013) due to user schaual overriddi Estimate Exception 20 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$1,864.80 15 Nov 17, 2021 SYSTEM \$4,972.80 This adjustment offsets the original system-generated Material Estimate Exception 22 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM \$4,972.80		
1060 ST. STRUCTURAL Material 13 Oct 18, 2021 SYSTEM \$1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 13 Oct 18, 2021 SYSTEM \$\$1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 21 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$\$1,864.80 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0013) due to user schauard overriddi Estimate Exception 20 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$\$\$1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 20 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$		
STRUCTURAL 2021 2021 Estimate ltem Adjustment (0018) due to user webers1 overriddi Estimate Exception 21 on the current Payment Estimate. 13 Oct 18, 2021 SYSTEM (\$1,864.80) 14 Nov 2, 2021 SYSTEM \$1,864.80 14 Nov 2, 2021 SYSTEM (\$1,864.80) 14 Nov 2, 2021 SYSTEM \$(\$1,864.80) 14 Nov 2, 2021 SYSTEM (\$1,864.80) 15 Nov 17, 2021 SYSTEM \$4,972.80 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0015) due to user schaua1 overriddi Estimate Item Adjustment (0015) due to user schaua1 overriddi Estimate Exception 20 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM \$4,972.80 This adjustment offsets the original system-generated Material Estimate Exception 22 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM \$(\$4,972.80) This adjustment (0015) due to user schaua1 overriddi Estimate Exception 22 on the current Payment Estimate.		
2021 2021 2021 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0013) due to user schaua1 overriddi Estimate Exception 20 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$1,864.80 This adjustment offsets the original system-generated Material Estimate Exception 20 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM \$(\$1,864.80) 15 Nov 17, 2021 SYSTEM \$4,972.80 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0015) due to user schaua1 overriddi Estimate Exception 22 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM \$(\$4,972.80)		
2021 2021 Estimate Item Adjustment (0013) due to user schaua1 overriddi Estimate Exception 20 on the current Payment Estimate. 14 Nov 2, 2021 SYSTEM (\$1,864.80) 15 Nov 17, 2021 SYSTEM \$4,972.80 This adjustment offsets the original system-generated Material Estimate Exception 22 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM (\$4,972.80)		
2021 2021 2021 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0015) due to user schaua1 overriddi Estimate Exception 22 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM \$4,972.80 This adjustment offsets the original system-generated Material Estimate Exception 22 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM \$(\$4,972.80)		
2021 Estimate Item Adjustment (0015) due to user schaua1 overriddi Estimate Exception 22 on the current Payment Estimate. 15 Nov 17, 2021 SYSTEM (\$4,972.80)		
2021		
- Total \$0.00		
Material - Total \$0.00		



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
95	1060 -	Total						\$0.00	
	1070	SHF-FLAT SHEET FLUORESCENT	Material		13	Oct 18, 2021	SYSTEM	\$1,751.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user webers1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$1,751.00)	
					14	Nov 2, 2021	SYSTEM	\$1,751.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schaua1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$1,751.00)	
					15	Nov 17, 2021	SYSTEM	\$5,813.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schaua1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$5,813.32)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	1070 -	Total						\$0.00	
	1080	MISC. GRADING	Other Item Adjustment	OTHR	19	Jan 18, 2022	schaua1	(\$2,988.78)	20% withheld for seed growth.
				OTHR - Tot	al			(\$2,988.78)	
			Other Item Ad	ljustment - To	otal			(\$2,988.78)	
	1080 -	Total						(\$2,988.78)	
	1100	WATER - UTILITY ITEM	Other Item Adjustment	OTHR		Dec 3, 2021	schaua1	(\$7,199.49)	Pay taken off due to waterline installation issues.
					19	Jan 18, 2022	schaua1	\$7,199.49	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tot				\$0.00	
			Other Item Ad	ljustment - To	otal			\$0.00	
	1100 -	Total						\$0.00	
	1110	WATER - UTILITY ITEM	Other Item Adjustment	OTHR		Dec 3, 2021	schaua1	(\$3,176.76)	Pay taken off due to waterline installation issues.
					19	Jan 18, 2022	schaua1	\$3,176.76	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tot				\$0.00	
	4440	Total	Other Item Ad	ijustment - 10	otai			\$0.00	
- 5	1110 - 1120	WATER - UTILITY ITEM	Other Item Adjustment	OTHR	16	Dec 3, 2021	schaua1	\$0.00 (\$5,813.58)	Pay taken off due to waterline installation issues.
		0.12111112.00	, lajaounone		19	Jan 18, 2022	schaua1	\$5,813.58	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tot	al			\$0.00	
			Other Item Ad	liustment - To	otal			\$0.00	
				justinent re					
	1120 -	Total						\$0.00	
- 5	1120 - 1130	Total WATER - UTILITY ITEM	Other Item Adjustment	OTHR	16	Dec 3, 2021	schaua1		Pay taken off due to waterline installation issues.
- 5		WATER -	Other Item		16 19		schaua1 schaua1	\$0.00	Pay taken off due to waterline installation issues. This adjustment offsets pay being taken away on estimate 16.
- 5		WATER -	Other Item		19	2021 Jan 18,		\$0.00 (\$12,319.32)	-
- 5		WATER -	Other Item	OTHR	19 al	2021 Jan 18,		\$0.00 (\$12,319.32) \$12,319.32	-
	1130	WATER -	Other Item Adjustment	OTHR	19 al	2021 Jan 18,		\$0.00 (\$12,319.32) \$12,319.32 \$0.00	-
	1130	WATER - UTILITY ITEM	Other Item Adjustment	OTHR	19 al otal 16	2021 Jan 18, 2022 Dec 3, 2021	schaua1	\$0.00 (\$12,319.32) \$12,319.32 \$0.00 \$0.00 \$0.00 (\$12,810.82)	This adjustment offsets pay being taken away on estimate 16. Pay taken off due to waterline installation issues.
	1130 1130 -	WATER - UTILITY ITEM	Other Item Adjustment Other Item Ad	OTHR OTHR - Tot ljustment - To	19 al otal 16 19	2021 Jan 18, 2022 Dec 3, 2021 Jan 18, 2022	schaua1 schaua1 schaua1	\$0.00 (\$12,319.32) \$12,319.32 \$0.00 \$0.00 \$0.00 (\$12,810.82) \$12,812.82	This adjustment offsets pay being taken away on estimate 16. Pay taken off due to waterline installation issues. This adjustment offsets pay being taken away on estimate 16.
	1130 1130 -	WATER - UTILITY ITEM	Other Item Adjustment Other Item Ad	OTHR OTHR - Tot Justment - To OTHR	19 al tal 16 19 23	2021 Jan 18, 2022 Dec 3, 2021 Jan 18,	schaua1	\$0.00 (\$12,319.32) \$12,319.32 \$0.00 \$0.00 (\$12,810.82) \$12,812.82 (\$2.00)	This adjustment offsets pay being taken away on estimate 16. Pay taken off due to waterline installation issues.
	1130 1130 -	WATER - UTILITY ITEM	Other Item Adjustment Other Item Ad	OTHR - Tot OTHR - Tot OTHR OTHR - Tot	19 al ttal 16 19 23 al	2021 Jan 18, 2022 Dec 3, 2021 Jan 18, 2022 Apr 4,	schaua1 schaua1 schaua1	\$0.00 (\$12,319.32) \$12,319.32 \$0.00 \$0.00 \$0.00 (\$12,810.82) \$12,812.82	This adjustment offsets pay being taken away on estimate 16. Pay taken off due to waterline installation issues. This adjustment offsets pay being taken away on estimate 16. This adjustment is to correct mistake made on estimate 19. On estimate 19



Jun 18, 2022

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
195	1140 -	Total						\$0.00	
	1150	WATER - UTILITY ITEM	Other Item Adjustment	OTHR	16	Dec 3, 2021	schaua1	(\$8,912.70)	Pay taken off due to waterline installation issues.
					19	Jan 18, 2022	schaua1	\$8,912.70	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tota	al			\$0.00	
			Other Item Ad	ljustment - To	tal			\$0.00	
	1150 -	Total						\$0.00	
	1160	WATER - UTILITY ITEM	Other Item Adjustment	OTHR	16	Dec 3, 2021	schaua1	(\$2,903.04)	Pay taken off due to waterline installation issues.
					19	Jan 18, 2022	schaua1	\$2,903.04	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tota	al			\$0.00	
			Other Item Ad	- ljustment - To	tal			\$0.00	
	1160 -	Total						\$0.00	
	1170	WATER - UTILITY ITEM	Other Item Adjustment	OTHR	16	Dec 3, 2021	schaua1	(\$2,773.75)	Pay taken off due to waterline installation issues.
					19	Jan 18, 2022	schaua1	\$2,773.75	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Total			\$0.00		
			Other Item Ad	- ljustment - To	tal			\$0.00	
	1170 -	Total						\$0.00	
	1180	WATER - UTILITY ITEM	Other Item Adjustment	OTHR	16	Dec 3, 2021	schaua1	(\$8,020.10)	Pay taken off due to waterline installation issues.
					19	Jan 18, 2022	schaua1	\$8,020.10	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tota	al			\$0.00	
			Other Item Ad	ljustment - To	tal			\$0.00	
	1180 -	Total						\$0.00	
	1190	WATER - UTILITY ITEM	Other Item Adjustment	OTHR	16	Dec 3, 2021	schaua1	(\$30,464.00)	Pay taken off due to waterline installation issues.
				19		Jan 18, 2022	schaua1	\$30,464.00	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tota	al			\$0.00	
			Other Item Ad	ljustment - To	tal			\$0.00	
	1190 -	Total						\$0.00	
	1200	MISC.	. Other Item Adjustment		16	Dec 3, 2021	schaua1	(\$3,654.03)	Pay taken off due to waterline installation issues.
				19		Jan 18, 2022	schaua1	\$3,654.03	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tota	al			\$0.00	
			Other Item Ad	ljustment - To	tal			\$0.00	
	1200 -	Total						\$0.00	
	1210	CONCRETE	Other Item Adjustment	OTHR	16	Dec 3, 2021	schaua1	(\$2,398.40)	Pay taken off due to waterline installation issues.
		(MISC)			19	Jan 18, 2022	schaua1	\$2,398.40	This adjustment offsets pay being taken away on estimate 16.
				OTHR - Tota	al			\$0.00	
			Other Item Ad	ljustment - To	tal			\$0.00	
	1210 -	Total						\$0.00	
	1220	CLASS B-1 CONCRETE (CULVERTS-	Material		10	Sep 2, 2021	SYSTEM	\$3,306.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
		BRIDGE)			10	Sep 2, 2021	SYSTEM	(\$3,306.12)	
					11	Sep 16, 2021	SYSTEM	\$3,306.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user webers1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					11	Sep 16,	SYSTEM	(\$3,306.12)	,
					11	Sep 16,	SISIEM	(\$3,306.12)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3195	1220	CLASS B-1 CONCRETE (CULVERTS- BRIDGE)	Material			2021			
					12	Oct 4, 2021	SYSTEM	\$3,306.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user webers1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	Oct 4, 2021	SYSTEM	(\$3,306.12)	
					13	Oct 18, 2021	SYSTEM	\$3,306.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user webers1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$3,306.12)	
					14	Nov 2, 2021	SYSTEM	\$3,306.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schaua1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$3,306.12)	
					15	Nov 17, 2021	SYSTEM	\$3,306.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schaua1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$3,306.12)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1220 -	Total						\$0.00	
	5001	CONCRETE	Material		13	Oct 18,	SYSTEM	\$570.83	This adjustment offsets the original system-generated Material Payment
		FOOTINGS, EMBEDDED				2021			Estimate Item Adjustment (0021) due to user webers1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					13	Oct 18, 2021	SYSTEM	(\$570.83)	
					14	Nov 2, 2021	SYSTEM	\$570.83	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schaua1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					14	Nov 2, 2021	SYSTEM	(\$570.83)	
					15	Nov 17, 2021	SYSTEM	\$1,902.78	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schaua1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					15	Nov 17, 2021	SYSTEM	(\$1,902.78)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	5001 -	Total						\$0.00	
	5003	MISC. HIGHWAY SIGNING	Material		19	Jan 18, 2022	SYSTEM	\$5,817.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schaua1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					19	Jan 18, 2022	SYSTEM	(\$5,817.90)	
					20	Feb 2, 2022	SYSTEM	\$5,817.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					20	Feb 2, 2022	SYSTEM	(\$5,817.90)	
					21	Feb 16, 2022	SYSTEM	\$5,817.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					21	Feb 16, 2022	SYSTEM	(\$5,817.90)	
					22	Mar 2, 2022	SYSTEM	\$5,817.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schaua1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					22	Mar 2, 2022	SYSTEM	(\$5,817.90)	
					23	Apr 4, 2022	SYSTEM	\$5,817.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					23	Apr 4,	SYSTEM	(\$5,817.90)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5P3195	5003	MISC.	Material			2022			
		HIGHWAY SIGNING			24	Jun 16, 2022	SYSTEM	\$5,817.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					24	Jun 16, 2022	SYSTEM	(\$5,817.90)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
	5003 -	Total						\$0.00	
	5004	MISC. HIGHWAY SIGNING	Material		19	Jan 18, 2022	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schaua1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					19	Jan 18, 2022	SYSTEM	(\$80.00)	
					20	Feb 2, 2022	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					20	Feb 2, 2022	SYSTEM	(\$80.00)	
					21	Feb 16, 2022	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					21	Feb 16, 2022	SYSTEM	(\$80.00)	
					22	Mar 2, 2022	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schaua1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					22	Mar 2, 2022	SYSTEM	(\$80.00)	
					23	Apr 4, 2022	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schaua1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					23	Apr 4, 2022	SYSTEM	(\$80.00)	
					24	Jun 16, 2022	SYSTEM	\$80.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schaua1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					24	Jun 16, 2022	SYSTEM	(\$80.00)	
				- Total		2022		\$0.00	
			Material - Tota					\$0.00	
	5004 -	Total						\$0.00	
	5007	CONCRETE PAVEMENT (8 IN. NON-	Material		24	Jun 16, 2022	SYSTEM	\$819.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schaua1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		REINFORCED,			24	Jun 16, 2022	SYSTEM	(\$819.33)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
			Price FUEL		24	Jun 16, 2022	SYSTEM	\$4.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$4.40	
			Price FUEL - T	otal				\$4.40	
		Total						\$4.40	
J5P3195								\$8,566.52	
Overall -	Total							\$8,566.52	