

Pay Estimate Created Date: June 16, 2021

| Progress Estimate N 5 | annoon | | 210219-D05 S & A Equipment & | Builders, I | | | 1 Original Contract Amount 21 Net Change Order Amoun Current Contract Amount | t \$0.00 |
|--------------------------|------------|-------------------|---------------------------------|-------------|---------------------------|--------------|--|----------|
| Approval Date | | | | | | | | By User |
| June 16, 2021 | | | Generated and A | Approved (| and should be considered | d Draft) at | the Project Office Level by | webers1 |
| June 17, 2021 | | R | eviewed and Appro | oved (and s | should be considered Drat | ft) at the F | Resident Engineer Level by | niemej1 |
| June 21, 2021 | | | ł | Reviewed a | and Approved at the Cent | ral Office | Controllers Office Level by | greggd1 |
| Original Completio | n Date | Current Con | npletion Date | Actua | al Completion Date | % | of Current Contract Amount | Complete |
| November 1, 20 | 21 | Novembe | er 1, 2021 | | | | 22.77% | |
| | Contract | Informational Dat | tes | | Milestones | | | |
| Date Description | Original | Completion Date | Current Complet | tion Date | No Milestones Exist for | Contract | | |
| Acceptance Date | | | | | | | | |
| Awarded Date | March 3, | 2021 | March 3, 2021 | | | | | |
| Letting Date | February | 19, 2021 | February 19, 202 | 1 | | | | |
| Notice to Proceed Date | April 5, 2 | 021 | April 5, 2021 | | | | | |
| Work Began Date | April 21, | 2021 | April 21, 2021 | | | | | |

| Contract Total Pay For Estimate No. 5 | | | | |
|---------------------------------------|------------------------------|---------------------------|----------------|--|
| | This Estimate | Previous | To Date | |
| 210219-D05 | | | | |
| Total Posted Items P | ay <mark>\$362,908.35</mark> | \$643,452.59 | \$1,006,360.94 | |
| Gross Item Adjustme | ents \$1,561.15 | \$2,847.76 | \$4,408.91 | |
| Incentive | \$0.00 | \$0.00 | \$0.00 | |
| Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| Other Contract Adjus | stments <mark>\$0.00</mark> | \$0.00 | \$0.00 | |
| | | <mark>\$646,300.35</mark> | \$1,010,769.85 | |
| Contract Total Payable This Estimate: | \$364,469.50 | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|--|------|---------------|--------------------------|-----------------------------|
| J5P3195 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | LS | \$175,733.110 | 0.05 | \$8,786.66 |
| | 0030 | 2031000 | CLASS A EXCAVATION | CUYD | \$13.990 | 1,432 | \$20,033.68 |
| | 0050 | 2036000 | COMPACTING EMBANKMENT | CUYD | \$4.090 | 1,078 | \$4,409.02 |
| | 0080 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | SQYD | \$8.623 | 3,576 | \$30,835.88 |
| | 0110 | 6044011 | PIPE COLLAR, TYPE A | EA | \$612.560 | 1 | \$612.56 |
| | 0140 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | CUYD | \$61.080 | 27 | \$1,649.16 |
| | 0160 | 6096041 | PLACING TYPE 1 ROCK DITCH LINER | CUYD | \$12.400 | 27 | \$334.80 |
| | 0210 | 6117000A | GABIONS | CUYD | \$271.450 | 55 | \$14,929.75 |
| | 0240 | 6161010 | RELOCATED SIGNS | SQFT | \$7.920 | 132 | \$1,045.44 |
| | 0320 | 6181000 | MOBILIZATION | LS | \$239,065.660 | 0.25 | \$59,766.42 |
| | 0330 | 6191000 | PAVEMENT EDGE TREATMENT | LF | \$2.110 | 2,885 | \$6,087.35 |
| | 0490 | 7261048 | 48 IN. PIPE GROUP A | LF | \$190.880 | 14 | \$2,672.32 |
| | 0570 | 7320648A | 48 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | EA | \$2,875.760 | 1 | \$2,875.76 |
| | 0600 | 8061003 | SEDIMENT TRAP EXCAVATION | CUYD | \$39.590 | 8 | \$316.72 |
| | 0610 | 8061004 | SEDIMENT TRAP ROCK | CUYD | \$73.520 | 12 | \$882.24 |
| | 0620 | 8061005 | ROCK DITCH CHECK | LF | \$12.160 | 73 | \$887.68 |
| | 0640 | 8061019 | SILT FENCE | LF | \$2.380 | 1,810 | \$4,307.80 |
| | 0650 | 5021308 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | SQYD | \$49.150 | 3,355.7 | \$164,932.66 |
| | 0690 | 5021340 | TYPE A2 SHOULDER | SQYD | \$34.420 | 890.6 | \$30,654.45 |



Pay Estimate Created Date: June 16, 2021

| Progress E | Estimate Nur 5 | nber | Contract ID Prime Contract | 210219-D05 tor S & A Equipment & Builders, LL0 | | ne 15, 2021 Net | Change Order Am | bunt\$4,418,755.87bount\$0.00bunt\$4,418,755.87 |
|-------------------|-------------------|-------------|-------------------------------|---|------|-----------------|--------------------------|---|
| Project Number | Line Number | Iten Cod | | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
| J5P3195 | 0830 | 90140 | 004 CONDUIT, | 4 IN. RIGID, PUSHED | LF | \$32.800 | 210 | \$6,888.00 |
| Project J5P | 3195 - Total | | | | | | | \$362,908.35 |
| Overall - To | tal | | | | | | | \$362,908.35 |
| ontract Adju | stments Thi | s Estim | late | | | | | |

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|---|--------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| 5P3195 | 0030 | CLASS A EXCAVATION | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 1,432 | \$0.10 | \$143.20 |
| | 0050 | COMPACTING EMBANKMENT | Material | | | -3,007 | \$4.09 | (\$12,298.63 |
| | 0050 | COMPACTING EMBANKMENT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 3,007 | \$4.09 | \$12,298.63 |
| | 0060 | COMPACTING IN CUT | Material | | | -53.4 | \$107.58 | (\$5,744.77 |
| | 0060 | COMPACTING IN CUT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 53.4 | \$107.58 | \$5,744.77 |
| | 0080 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 3,576 | \$0.12 | \$411.24 |
| | 0080 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | | -9,518 | \$8.62 | (\$82,073.81 |
| | 0080 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 9,518 | \$8.62 | \$82,073.81 |
| | 0110 | PIPE COLLAR, TYPE A | Material | | | -1 | \$612.56 | (\$612.56 |
| | 0110 | PIPE COLLAR, TYPE A | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | 1 | \$612.56 | \$612.56 |
| | 0650 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 3,355.7 | \$0.30 | \$1,006.71 |
| | 0650 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | Material | | | -8,100.6 | \$49.15 | (\$398,144.49) |
| | 0650 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 8,100.6 | \$49.15 | \$398,144.49 |
| otal | | | | | | | | \$1,561.15 |



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Informati | on |
|-------------------|--|------------------------------|-----------|--------|--|---|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J5P3195 | FAF-63-3(110) | Intersection improvements | 63 | BOONE | from Rte. Y and Rte | . M to Rte. H | |
| Totals by | Job Numbers | | | | | | |
| J5P3195 | Posted Iten Gross Item | Adjustments | ss Item F | Pay | This Estimate \$362,908.35 \$1,561.15 \$364,469.50 | Previous \$643,452.59 \$2,847.76 \$646,300.35 | To Date \$1,006,360.94 \$4,408.91 \$1,010,769.85 |
| | Incentive Disincentiv Liquidated Other Cont | | ts | | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 | \$0.00 \$0.00 \$0.00 \$0.00 |



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|--|---------------|------------|
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 2037075, Project Item Line Number 0060, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 3040506, Project Item Line Number 0080, Material Set 304050696, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 5021308, Project Item Line Number 0650, Material Set 502130896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J5P3195, Item 6044011, Project Item Line Number 0110, Material Set 604401196, Material 1036RSDFPL42M16 - Reinforcing Steel No. 5/M16 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. | Working with Contractor and Materials to resolve | webers1 | Overridden |



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 10219-D05 | J5P3195 | 0001 | 0010 | 2013000 | CLEARING AND GRUBBING | 15.00 | 0.00 | 15.00 | ACRE | 0.80 | \$4,062.43 | \$3,249.94 |
| | | 0001 | 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 0.15 | \$175,733.11 | \$26,359.97 |
| | | 0001 | 0030 | 2031000 | CLASS A EXCAVATION | 18,603.00 | 0.00 | 18,603.00 | CUYD | 4,495.00 | \$13.99 | \$62,885.05 |
| | | 0001 | 0040 | 2035500 | EMBANKMENT IN PLACE | 135.00 | 0.00 | 135.00 | CUYD | 0.00 | \$15.88 | \$0.00 |
| | | 0001 | 0050 | 2036000 | COMPACTING EMBANKMENT | 11,536.00 | 0.00 | 11,536.00 | CUYD | 3,007.00 | \$4.09 | \$12,298.63 |
| | | 0001 | 0060 | 2037075 | COMPACTING IN CUT | 239.20 | 0.00 | 239.20 | STA | 53.40 | \$107.58 | \$5,744.7 |
| | | 0001 | 0070 | 2071000 | LINEAR GRADING CLASS 1 | 20.20 | 0.00 | 20.20 | STA | 0.00 | \$537.52 | \$0.00 |
| | | 0001 | 0080 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 47,626.00 | 0.00 | 47,626.00 | SQYD | 14,518.00 | \$8.62 | \$125,188.8 |
| | | 0001 | 0090 | 3101003 | GRAVEL (A) | 77.00 | 0.00 | 77.00 | SQYD | 0.00 | \$30.07 | \$0.0 |
| | | 0001 | 0100 | 4019905 | MISC.VEGETATIVE BARRIER 3 IN. | 3,492.00 | 0.00 | 3,492.00 | SQYD | 0.00 | \$7.44 | \$0.0 |
| | | 0001 | 0110 | 6044011 | PIPE COLLAR, TYPE A | 8.00 | 0.00 | 8.00 | EA | 1.00 | \$612.56 | \$612.5 |
| | | 0001 | 0120 | 6083003 | 3 IN. CONCRETE MEDIAN STRIP | 281.90 | 0.00 | 281.90 | SQYD | 0.00 | \$180.96 | \$0.0 |
| | | 0001 | 0130 | 6085008 | PAVED APPROACH, 8 IN. | 54.20 | 0.00 | 54.20 | SQYD | 0.00 | \$257.87 | \$0.0 |
| | | 0001 | 0140 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | 188.00 | 0.00 | 188.00 | CUYD | 27.00 | \$61.08 | \$1,649.1 |
| | | 0001 | 0150 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 48.00 | 0.00 | 48.00 | CUYD | 0.00 | \$61.08 | \$0.0 |
| | | 0001 | 0160 | 6096041 | PLACING TYPE 1 ROCK DITCH LINER | 188.00 | 0.00 | 188.00 | CUYD | 27.00 | \$12.40 | \$334.8 |
| | | 0001 | 0170 | 6096042 | PLACING TYPE 2 ROCK DITCH LINER | 48.00 | 0.00 | 48.00 | CUYD | 0.00 | \$46.23 | \$0.0 |
| | | 0001 | 0180 | 6097000 | ROCK LINING | 49.00 | 0.00 | 49.00 | CUYD | 0.00 | \$91.89 | \$0.0 |
| | | 0001 | 0190 | 6113010 | FURNISHING TYPE 1 ROCK BLANKET | 289.00 | 0.00 | 289.00 | CUYD | 0.00 | \$62.89 | \$0.0 |
| | | 0001 | 0200 | 6113030 | PLACING TYPE 1 ROCK BLANKET | 289.00 | 0.00 | 289.00 | CUYD | 0.00 | \$18.32 | \$0.0 |
| | | 0001 | 0210 | 6117000A | GABIONS | 129.00 | 0.00 | 129.00 | CUYD | 129.00 | \$271.45 | \$35,017.0 |
| | | 0001 | 0220 | 6141024 | GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914 MM) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$2,622.28 | \$0.0 |
| | | 0001 | 0230 | 6161005 | CONSTRUCTION SIGNS | 964.00 | 0.00 | 964.00 | SQFT | 760.00 | \$7.92 | \$6,019.2 |
| | | 0001 | 0240 | 6161010 | RELOCATED SIGNS | 1,114.00 | 0.00 | 1,114.00 | SQFT | 132.00 | \$7.92 | \$1,045.4 |
| | | 0001 | 0250 | 6161025 | CHANNELIZER (TRIM LINE) | 145.00 | 0.00 | 145.00 | EA | 145.00 | \$27.14 | \$3,935.3 |
| | | 0001 | 0260 | 6161031 | TYPE III MOVEABLE BARRICADE WITH LIGHTS | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$339.31 | \$0.0 |
| | | 0001 | 0270 | 6161033 | DIRECTIONAL INDICATOR BARRICADE | 76.00 | 0.00 | 76.00 | EA | 30.00 | \$113.10 | \$3,393.0 |
| | | 0001 | 0280 | 6161040 | FLASHING ARROW PANEL | 5.00 | 0.00 | 5.00 | EA | 2.00 | \$2,827.57 | \$5,655.1 |
| | | 0001 | 0290 | 6161055 | SEQUENTIAL FLASHING WARNING LIGHT | 76.00 | 0.00 | 76.00 | EA | 0.00 | \$282.76 | \$0.0 |
| | | 0001 | 0300 | 6161099 | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$7,351.68 | \$22,055.0 |
| | | 0001 | 0310 | 6162004 | TEMPORARY SHORT-TERM RUMBLE STRIPS | 8.00 | 0.00 | 8.00 | EA | 8.00 | \$7,351.68 | \$58,813.4 |
| | | 0001 | 0320 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 0.50 | \$239,065.66 | \$119,532.8 |
| | | 0001 | 0330 | 6191000 | PAVEMENT EDGE TREATMENT | 23,180.00 | 0.00 | 23,180.00 | LF | 8,325.00 | \$2.11 | \$17,565.7 |
| | | 0001 | 0340 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 12.00 | 0.00 | 12.00 | LF | 0.00 | \$33.93 | \$0.0 |
| | | 0001 | 0350 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 27.00 | 0.00 | 27.00 | EA | 0.00 | \$395.86 | \$0.0 |
| | | 0001 | 0360 | 6200030 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY) | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$735.17 | \$0.0 |
| | | 0001 | 0370 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 41,366.00 | 0.00 | 41,366.00 | LF | 0.00 | \$0.23 | \$0.0 |
| | | 0001 | 0380 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 23,658.00 | 0.00 | 23,658.00 | LF | 0.00 | \$0.23 | \$0.0 |
| | | 0001 | 0390 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 1,504.00 | 0.00 | 1,504.00 | LF | 0.00 | \$0.45 | \$0.0 |
| | | 0001 | 0400 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 2,005.00 | 0.00 | 2,005.00 | LF | 0.00 | \$0.17 | \$0.0 |
| | | 0001 | 0410 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 3,129.00 | 0.00 | 3,129.00 | LF | 0.00 | \$0.17 | \$0.0 |
| | | 0001 | 0420 | 6207001 | PAVEMENT MARKING REMOVAL | 5,795.00 | 0.00 | 5,795.00 | LF | 0.00 | \$1.13 | \$0.0 |
| | | 0001 | 0430 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$52,932.06 | \$0.0 |



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

date and can differ from the posted amount at the time the Estimate was Generated.

| Contract m.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTE To Date (See repor generated date) |
|------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 10219-D05 | J5P3195 | 0001 | 0440 | 7261012 | 12 IN. PIPE GROUP A | 122.00 | 0.00 | 122.00 | LF | 0.00 | \$47.86 | \$0.0 |
| | | 0001 | 0450 | 7261015 | 15 IN. PIPE GROUP A | 128.00 | 0.00 | 128.00 | LF | 0.00 | \$45.88 | \$0.0 |
| | | 0001 | 0460 | 7261018 | 18 IN. PIPE GROUP A | 87.00 | 0.00 | 87.00 | LF | 0.00 | \$62.78 | \$0.0 |
| | | 0001 | 0470 | 7261024 | 24 IN. PIPE GROUP A | 71.00 | 0.00 | 71.00 | LF | 0.00 | \$58.17 | \$0.0 |
| | | 0001 | 0480 | 7261030 | 30 IN. PIPE GROUP A | 17.00 | 0.00 | 17.00 | LF | 0.00 | \$122.87 | \$0.0 |
| | | 0001 | 0490 | 7261048 | 48 IN. PIPE GROUP A | 14.00 | 0.00 | 14.00 | LF | 14.00 | \$190.88 | \$2,672.3 |
| | | 0001 | 0500 | 7261060 | 60 IN. PIPE GROUP A | 49.00 | 0.00 | 49.00 | LF | 0.00 | \$200.06 | \$0.0 |
| | | 0001 | 0510 | 7311053 | PRECAST CONCRETE DROP INLET 5 FT X 3 FT | 9.00 | 0.00 | 9.00 | FT | 0.00 | \$695.97 | \$0.0 |
| | | 0001 | 0520 | 7320612A | 12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$11,136.86 | \$0.0 |
| | | 0001 | 0530 | 7320615A | 15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$735.20 | \$0.0 |
| | | 0001 | 0540 | 7320618A | 18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$774.90 | \$0. |
| | | 0001 | 0550 | 7320624A | SECTION 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END | 4.00 | 0.00 | 4.00 | EA | 0.00 | \$860.41 | \$0.0 |
| | | | | | SECTION | | | | | | | |
| | | 0001 | 0560 | 7320630A | 30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1,274.68 | \$0.0 |
| | | 0001 | 0570 | 7320648A | 48 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$2,875.76 | \$2,875. |
| | | 0001 | 0580 | 7320660A | 60 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$4,177.01 | \$0.0 |
| | | 0001 | 0590 | 8051000A | SEEDING - COOL SEASON MIXTURES | 10.00 | 0.00 | 10.00 | ACRE | 0.00 | \$2,431.71 | \$0. |
| | | 0001 | 0600 | 8061003 | SEDIMENT TRAP EXCAVATION | 24.00 | 0.00 | 24.00 | CUYD | 8.00 | \$39.59 | \$316. |
| | | 0001 | 0610 | 8061004 | SEDIMENT TRAP ROCK | 35.00 | 0.00 | 35.00 | CUYD | 12.00 | \$73.52 | \$882 |
| | | 0001 | 0620 | 8061005 | ROCK DITCH CHECK | 341.00 | 0.00 | 341.00 | LF | 73.00 | \$12.16 | \$887 |
| | | 0001 | 0630 | 8061007A | CURB INLET CHECK | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$197.93 | \$0 |
| | | 0001 | 0640 | 8061019 | SILT FENCE | 7,268.00 | 0.00 | 7,268.00 | LF | 4,940.00 | \$2.38 | \$11,757 |
| | | 0002 | 0650 | 5021308 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED, 15 FT. JOINTS) | 36,434.90 | 0.00 | 36,434.90 | SQYD | 8,100.60 | \$49.15 | \$398,144 |
| | | 0002 | 0660 | 6262000A | PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP | 22.20 | 0.00 | 22.20 | STA | 0.00 | \$738.74 | \$0 |
| | | 0004 | 0690 | 5021340 | TYPE A2 SHOULDER | 7,458.80 | 0.00 | 7,458.80 | SQYD | 1,849.50 | \$34.42 | \$63,659 |
| | | 0010 | 0710 | 6061061 | MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING | 63.00 | 0.00 | 63.00 | LF | 0.00 | \$33.37 | \$0 |
| | | 0010 | 0720 | 6061063 | MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING | 113.00 | 0.00 | 113.00 | LF | 0.00 | \$28.84 | \$0 |
| | | 0010 | 0730 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$3,749.70 | \$0 |
| | | 0010 | 0740 | 6064100 | MEDIAN GUARD CABLE 3 - STRAND | 5,115.00 | 0.00 | 5,115.00 | LF | 0.00 | \$16.41 | \$0. |
| | | 0010 | 0750 | 6064110 | ANCHOR ASSEMBLY, GUARD CABLE 3-STRAND | 14.00 | 0.00 | 14.00 | EA | 0.00 | \$3,902.04 | \$0. |
| | | 0020 | 0760 | 9011062 | LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 2 | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$3,110.32 | \$0. |
| | | 0020 | 0770 | 9011106 | BRACKET ARM, 6 FT. OR 1.8 M | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$481.82 | \$0 |
| | | 0020 | 0780 | 9011313 | LUMINAIRE, LED-C | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$506.70 | \$0 |
| | | 0020 | 0790 | 9012230 | BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$6,559.96 | \$0 |
| | | 0020 | 0800 | 9013002 | CONDUIT, 2 IN. RIGID, IN TRENCH | 54.00 | 0.00 | 54.00 | LF | 0.00 | \$11.31 | \$0 |
| | | 0020 | 0810 | 9013003 | CONDUIT, 3 IN. RIGID, IN TRENCH | 460.00 | 0.00 | 460.00 | LF | 102.00 | \$12.44 | \$1,268 |
| | | 0020 | 0820 | 9013004 | CONDUIT, 4 IN. RIGID, IN TRENCH | 114.00 | 0.00 | 114.00 | LF | 0.00 | \$14.70 | \$0 |
| | | 0020 | 0830 | 9014004 | CONDUIT, 4 IN. RIGID, PUSHED | 949.00 | 0.00 | 949.00 | LF | 370.00 | \$32.80 | \$12,136 |
| | | 0020 | 0840 | 9015010 | TRENCHING TYPE I | 2,926.00 | 0.00 | 2,926.00 | LF | 102.00 | \$3.96 | \$403 |
| | | 0020 | 0850 | 9016110 | PULL BOX, PREFORMED CLASS 1 | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$1,108.41 | \$0 |
| | | 0020 | 0860 | 9016112 | PULL BOX, PREFORMED CLASS 3 | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1,866.19 | \$0 |
| | | 0020 | 0870 | 9017002 | CABLE, 2 AWG 1 CONDUCTOR | 580.00 | 0.00 | 580.00 | LF | 0.00 | \$2.83 | \$0 |
| | | 0020 | 0880 | 9017008 | CABLE, 8 AWG 1 CONDUCTOR | 4,090.00 | 0.00 | 4,090.00 | LF | 0.00 | \$1.41 | \$0 |
| | | 0020 | 0890 | 9017110 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | 450.00 | 0.00 | 450.00 | LF | 0.00 | \$0.96 | \$0 |
| | | | 0900 | 9017202 | WIRE, 2 AWG, BARE NEUTRAL | 290.00 | 0.00 | 290.00 | LF | 0.00 | \$2.71 | \$0. |



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Note: Posted Q | uantities | and Valu | es are b | ased on R | eport Generated date and can differ from the posted ame | ount at the | time the | Estimate wa | as Gene | rated. | | |
|-------------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|---------|------------------------------------|------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 210219-D05 | J5P3195 | 0020 | 0910 | 9017208 | WIRE, 8 AWG, BARE NEUTRAL | 2,060.00 | 0.00 | 2,060.00 | LF | 0.00 | \$1.35 | \$0.00 |
| | | 0020 | 0920 | 9017407 | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG | 2,360.00 | 0.00 | 2,360.00 | LF | 0.00 | \$3.39 | \$0.00 |
| | | 0020 | 0930 | 9018245 | POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT) | 8.00 | 0.00 | 8.00 | EA | 0.00 | \$1,244.13 | \$0.00 |
| | | 0020 | 0940 | 9018610 | POWER SUPPLY ASSEMBLY, TYPE 1, 240/120 VOLT SERVICE, LIGHTING ONLY | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1.13 | \$0.00 |
| | | 0020 | 0950 | 9028500 | CABLE, LOOP DETECTOR, IN DUCT | 420.00 | 0.00 | 420.00 | LF | 0.00 | \$5.09 | \$0.00 |
| | | 0020 | 0960 | 9028510 | CABLE, LOOP DETECTOR, LEAD-IN | 400.00 | 0.00 | 400.00 | LF | 0.00 | \$1.47 | \$0.00 |
| | | 0020 | 0970 | 9105020 | CONDUIT, 1 IN., LOOP DETECTOR | 30.00 | 0.00 | 30.00 | LF | 0.00 | \$9.05 | \$0.00 |
| | | 0040 | 0980 | 9031210 | STRUCTURAL STEEL POSTS | 780.00 | 0.00 | 780.00 | LB | 0.00 | \$11.54 | \$0.00 |
| | | 0040 | 0990 | 9031242 | 36 IN. SURFACE-MOUNT DELINEATOR POST | 18.00 | 0.00 | 18.00 | EA | 0.00 | \$122.86 | \$0.00 |
| | | 0040 | 1000 | 9031256 | 7 FT. CHANNEL POST DELINEATOR, WHITE | 28.00 | 0.00 | 28.00 | EA | 0.00 | \$54.45 | \$0.00 |
| | | 0040 | 1010 | 9031270A | 2 IN. PSST POST - 12 GA. | 1,043.00 | 0.00 | 1,043.00 | LF | 0.00 | \$11.59 | \$0.00 |
| | | 0040 | 1020 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 327.00 | 0.00 | 327.00 | LF | 0.00 | \$10.70 | \$0.00 |
| | | 0040 | 1030 | 9031280 | 2.5 IN. PSST POST - 12 GA. | 202.00 | 0.00 | 202.00 | LF | 0.00 | \$13.23 | \$0.00 |
| | | 0040 | 1040 | 9031281 | POST ANCHOR FOR 2.5 IN. PSST - 7 GA. | 54.00 | 0.00 | 54.00 | LF | 0.00 | \$51.39 | \$0.00 |
| | | 0040 | 1050 | 9035004A | SH-FLAT SHEET | 932.00 | 0.00 | 932.00 | SQFT | 0.00 | \$26.40 | \$0.00 |
| | | 0040 | 1060 | 9035011A | ST-STRUCTURAL | 120.00 | 0.00 | 120.00 | SQFT | 0.00 | \$41.44 | \$0.00 |
| | | 0040 | 1070 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 175.00 | 0.00 | 175.00 | SQFT | 0.00 | \$35.02 | \$0.00 |
| | | 0060 | 1080 | 2079909 | MISC.FINE GRADING AND SEEDING (WATER LINE RELOCATION) | 7.30 | 0.00 | 7.30 | STA | 0.00 | \$2,047.11 | \$0.00 |
| | | 0060 | 1090 | 3109910 | MISC.GRAVEL (WATER LINE RELOCATION) | 250.00 | 0.00 | 250.00 | TONS | 0.00 | \$51.76 | \$0.00 |
| | | 0060 | 1100 | 6039901 | WATER | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$7,199.49 | \$0.00 |
| | | 0060 | 1110 | 6039901 | WATER | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,176.76 | \$0.00 |
| | | 0060 | 1120 | 6039902 | WATER | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$1,937.86 | \$0.00 |
| | | 0060 | 1130 | 6039902 | WATER | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$2,053.22 | \$0.00 |
| | | 0060 | 1140 | 6039902 | WATER | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$6,405.41 | \$0.00 |
| | | 0060 | 1150 | 6039902 | WATER | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$891.27 | \$0.00 |
| | | 0060 | 1160 | 6039902 | WATER | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$1,451.52 | \$0.00 |
| | | 0060 | 1170 | 6039903 | WATER | 25.00 | 0.00 | 25.00 | LF | 0.00 | \$110.95 | \$0.00 |
| | | 0060 | 1180 | 6039903 | WATER | 55.00 | 0.00 | 55.00 | LF | 0.00 | \$145.82 | \$0.00 |
| | | 0060 | 1190 | 6039903 | WATER | 700.00 | 0.00 | 700.00 | LF | 0.00 | \$43.52 | \$0.00 |
| | | 0060 | 1200 | 6189901 | MISC.MOBILIZATION FOR WATER LINE RELOCATION | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,654.03 | \$0.00 |
| | | 0060 | 1210 | 7032002 | CLASS B CONCRETE (MISC) | 10.00 | 0.00 | 10.00 | CUYD | 0.00 | \$239.84 | \$0.00 |
| | | 0070 | 1220 | 7034040 | CLASS B-1 CONCRETE (CULVERTS-BRIDGE) | 2.90 | 0.00 | 2.90 | CUYD | 0.00 | \$1,140.04 | \$0.00 |
| | | 0070 | 1230 | 7061020 | REINFORCING STEEL (CULVERTS-BRIDGE) | 490.00 | 0.00 | 490.00 | LB | 0.00 | \$4.78 | \$0.00 |
| | | 0070 | 1240 | 7133000 | BRIDGE GUARDRAIL (W-BEAM) | 29.00 | 0.00 | 29.00 | LF | 0.00 | \$265.79 | \$0.00 |
| | Project J | 5P3195 - To | otal Value | Posted to D | Date as of Report Generated Date | | | | | | | \$1,006,360.93 |
| 210219-D05 Ove | rall - Total | Value Pos | ted to Dat | te as of Repo | ort Generated Date | | | | | | | \$1,006,360.93 |

210219-D05 Overall - Total Value Posted to Date as of Report Gene



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5P3195

| Line lumber | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|--|------------------------------|---------------------|----------------------------|---------------------|----------|
| 0020 | 2022010 | REMOVAL OF IMPROVEMENTS | 6/15/21 | 6/15/21 | 0.05 | LS | US 63 Stage 1 and 2 5% Partial Payment | | | | | |
| 0030 | 2031000 | CLASS A EXCAVATION | 6/15/21 | 6/15/21 | 95.00 | CUYD | SB US 63 | 631+50 | | 632+53.74 | | |
| | | | | 6/15/21 | 337.00 | CUYD | East New Salem Lane (East) | | | | | |
| | | | | 6/15/21 | 1,000.00 | CUYD | US 63 NB Stage 2 | | | | | |
| 0050 | 2036000 | COMPACTING EMBANKMENT | 6/15/21 | 6/15/21 | 37.00 | CUYD | | 631+50 | | 632+53.74 | | |
| | | | | 6/15/21 | 41.00 | CUYD | East New Salem Lane (East) | | | | | |
| | | | | 6/15/21 | 1,000.00 | CUYD | NB US 63 Stage 2 | | | | | |
| 0080 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 6/15/21 | 6/15/21 | 366.00 | SQYD | NB 63 | 672+00 | | 674+39.20 | | |
| | | | | 6/15/21 | 586.00 | SQYD | East New Salem Lane (East) | 10+68 | | 11+94.20 | | |
| | | | | 6/15/21 | 2,624.00 | SQYD | NB US 63 | 672+00 | | 658+00 | | |
| 0110 | 6044011 | PIPE COLLAR, TYPE A | 6/15/21 | 6/15/21 | 1.00 | EA | US 63 89.0 LT | 623+95 | | | | 01-01 |
| 0140 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | 6/15/21 | 6/15/21 | 8.00 | CUYD | US 63 LT | 624+10 | | 624+34 | | |
| | | | | 6/15/21 | 19.00 | CUYD | US 63 LT | 624+13 | | 625+38 | | |
| 0160 | 6096041 | PLACING TYPE 1 ROCK DITCH LINER | 6/15/21 | 6/15/21 | 8.00 | CUYD | US 63 LT | 624+10 | | 624+34 | | |
| | | | | 6/15/21 | 19.00 | CUYD | | 624+13 | | 625+38 | | |
| 0210 | 6117000A | GABIONS | 6/15/21 | 6/15/21 | 55.00 | CUYD | East Gabion at Minor Hill Road | 3+49.19 | | 3+98.47 | | |
| 0240 | 6161010 | RELOCATED SIGNS | 6/15/21 | 6/15/21 | 132.00 | SQFT | US 63 NB Stage 2 Daily High Count 6/15 | | | | | |
| 0320 | 6181000 | MOBILIZATION | 6/15/21 | 6/15/21 | 0.25 | LS | 25% Partial Payment for Reaching 10% of Contract | | | | | |
| 0330 | 6191000 | PAVEMENT EDGE TREATMENT | 6/15/21 | 6/15/21 | 2,885.00 | LF | US 63 NB Stage 2 | 645+54.54 | | 674+39.20 | | |
| 0490 | 7261048 | 48 IN. PIPE GROUP A | 6/15/21 | 6/15/21 | 14.00 | LF | US 63 89.3 LT | 623+96 | | | | 01-01 |
| 0570 | 7320648A | 48 IN. GROUP A FLARED END SECT | 6/15/21 | 6/15/21 | 1.00 | EA | US 63 103.1 LT | 624+09 | | | | 01-01 |
| 0600 | 8061003 | SEDIMENT TRAP EXCAVATION | 6/15/21 | 6/15/21 | 4.00 | CUYD | | 604+30 | 94 LT | | | |
| | | | | 6/15/21 | 4.00 | CUYD | | 624+12 | 105 LT | | | |
| 0610 | 8061004 | SEDIMENT TRAP ROCK | 6/15/21 | 6/15/21 | 6.00 | CUYD | | 604+30 | 94 LT | | | |
| | | | | 6/15/21 | 6.00 | CUYD | | 624+12 | 105 LT | | | |
| 0620 | 8061005 | ROCK DITCH CHECK | 6/15/21 | 6/15/21 | 3.00 | LF | US 63 RT 84' | 632+22 | | | | |
| | | | | 6/15/21 | 10.00 | LF | US 63 LT | 675+00 | | | | |
| | | | | 6/15/21 | 60.00 | LF | US 63 LT | 605+88 | | 613+50 | | |
| 0640 | 8061019 | SILT FENCE | 6/15/21 | 6/15/21 | 130.00 | | SB Stage 1 | | | | | |
| | | | | 6/15/21 | 1,680.00 | | SB Stage 2A | 675+00 | | 690+00 | | |
| 0650 | 5021308 | CONCRETE PAVEMENT (8 IN. NON-REINFORCED. | 6/15/21 | 6/15/21 | 3,355.70 | SQYD | SB 63 | 614+52.83 | | 639+87.12 | | |
| 0690 | | TYPE A2 SHOULDER | | 6/15/21 | 289.20 | | | 614+37.83 | | 622+07.83 | | |
| | | | | 6/15/21 | 601.40 | | | 623+45.35 | | 639+87.12 | | |
| 0830 | 9014004 | CONDUIT, 4 IN, RIGID, PUSHED | 6/15/21 | 6/15/21 | 210.00 | | PS to CS Stage 1 | | | | | |

The information below this line are details for Construction Signs (if applicable). No Data Available

NO Data Availabi



Line Item Adjustments by Estimate

Jun 21, 2021

Contract ID:190621-F01

| ect | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|-----|--------|--------------------------|---------------|--------------------|----------------------------|---|--|--|---|
| | LING | Description | Туре | Adjustment Type | | Date | By | , inount | , concine |
| 195 | 0030 | CLASS A EXCAVATION | Price FUEL | | 2 | May 3, 2021 | SYSTEM | \$32.93 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$251.27 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$143.20 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$427.40 | |
| | | | Price FUEL | - Total | | | | \$427.40 | |
| - 1 | 0030 - | Total | | | | | | \$427.40 | |
| | 0050 | COMPACTING EMBANKMENT | Material | | 2 | May 3, 2021 | SYSTEM | \$1,092.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$1,092.03) | |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$7,889.61 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$7,889.61) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$7,889.61 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$7,889.61) | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$12,298.63 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$12,298.63) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0050 - | Total | | | | | | | |
| | 0050 - | · Total | | | | | | \$0.00 | |
| | 0060 | COMPACTING IN CUT | Material | | 2 | May 3, 2021 | SYSTEM | \$0.00 \$258.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | COMPACTING | Material | | 2 | | SYSTEM SYSTEM | | Estimate Item Adjustment (0003) due to user webers1 overridding Payment |
| | | COMPACTING | Material | | | 2021 May 3, | | \$258.19 | Estimate Item Adjustment (0003) due to user webers1 overridding Payment |
| | | COMPACTING | Material | | 2 | 2021 May 3, 2021 May 17, | SYSTEM | \$258.19 (\$258.19) | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment |
| | | COMPACTING | Material | | 2 3 | 2021 May 3, 2021 May 17, 2021 May 17, | SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment |
| | | COMPACTING | Material | | 2 3 3 | 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 3, | SYSTEM SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 (\$5,744.77) | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment |
| | | COMPACTING | Material | | 2 3 3 4 | 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 3, 2021 Jun 3, | SYSTEM SYSTEM SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 (\$5,744.77) \$5,744.77 | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment |
| | | COMPACTING | Material | | 2 3 3 4 4 | 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 3, 2021 Jun 3, 2021 Jun 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
| | | COMPACTING | Material | - Total | 2 3 3 4 4 5 | 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 3, 2021 Jun 3, 2021 Jun 16, Jun 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77 | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
| | | COMPACTING | Material | | 2 3 3 4 4 5 | 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 3, 2021 Jun 3, 2021 Jun 16, Jun 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
| | 0060 | COMPACTING | | | 2 3 3 4 4 5 | 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 3, 2021 Jun 3, 2021 Jun 16, Jun 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77 | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
| | 0060 | COMPACTING IN CUT | | | 2 3 3 4 4 5 | 2021 May 3, 2021 May 17, 2021 May 17, 2021 Jun 3, 2021 Jun 3, 2021 Jun 16, Jun 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77) \$0.00 | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |
| | 0060 - | COMPACTING IN CUT | Material - To | | 2 3 3 4 5 5 | 2021 May 3, 2021 May 17, 2021 Jun 3, 2021 Jun 3, 2021 Jun 16, 2021 Jun 16, 2021 May 3, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$258.19 (\$258.19) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$5,744.77 (\$5,744.77) \$0.00 | Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user webers1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |



Line Item Adjustments by Estimate

Contract ID:190621-F01

| ct | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|----|--------|--|------------------|--------------------|--------|-----------------|---------|---------------|---|
| | | · | Туре | Adjustment Type | Number | Date | Ву | | |
| 95 | 0080 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | 3 | May 17, 2021 | SYSTEM | (\$53,040.13) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$94,352.98 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user webers1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$94,352.98) | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$82,073.81 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Paymen Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$82,073.81) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | | | Price FUEL | | 2 | May 3, 2021 | SYSTEM | \$67.93 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$592.35 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$539.95 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$411.24 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$1,611.47 | |
| | | | Price FUEL | - Total | | | | \$1,611.47 | |
| | 0080 - | Total | | | | | | \$1,611.47 | |
| | 0110 | PIPE COLLAR, TYPE A | Material | | 5 | Jun 16, 2021 | SYSTEM | \$612.56 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$612.56) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 0110 - | Total | | | | | | \$0.00 | |
| | 0210 | GABIONS | Material | | 4 | Jun 3, 2021 | SYSTEM | \$20,087.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user webers1 overridding Payme Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$20,087.30) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0210 - | Total | | | | | \$0.00 | | |
| | 0330 | PAVEMENT EDGE TREATMENT | Material | | 3 | May 17, 2021 | SYSTEM | \$6,100.01 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$6,100.01) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0330 - | 0330 - Total | | | | | | \$0.00 | |
| | 0640 | SILT FENCE | Material | | 2 | May 3, 2021 | SYSTEM | \$2,058.70 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user webers1 overridding Payme Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 2 | May 3, 2021 | SYSTEM | (\$2,058.70) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0640 - | Total | | | | | | \$0.00 | |
| 1 | 0650 | CONCRETE PAVEMENT (8 | Material | | 2 | May 3, 2021 | SYSTEM | \$16,214.58 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payme |



Line Item Adjustments by Estimate

Contract ID:190621-F01

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------------|--------------|---------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|--|
| J5P3195 | 0650 | REINFORCED, | Material | | 2 | May 3, 2021 | SYSTEM | (\$16,214.58) | |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$146,059.06 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$146,059.06) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$233,211.84 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user webers1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$233,211.84) | |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$398,144.49 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | (\$398,144.49) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | | | Price FUEL | | 2 | May 3, 2021 | SYSTEM | \$65.32 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 3 | May 17, 2021 | SYSTEM | \$776.69 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$521.32 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 5 | Jun 16, 2021 | SYSTEM | \$1,006.71 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$2,370.04 | |
| | | | Price FUEL - Total | | | | | \$2,370.04 | |
| | 0650 - Total | | | | | | | \$2,370.04 | |
| | 0690 | TYPE A2 SHOULDER | Material | | 3 | May 17, 2021 | SYSTEM | \$15,960.55 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user webers1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 3 | May 17, 2021 | SYSTEM | (\$15,960.55) | |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | \$33,005.34 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user webers1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 4 | Jun 3, 2021 | SYSTEM | (\$33,005.34) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 0690 - Total | | | | | | | | |
| J5P3195 - Total | | | | | | | | | |
| - ··· | Total | | | | | | | \$4,408.91 | |