

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2022

Progress Es	stimate Number 16	Contract ID Prime Contractor	210319-C02 Emery Sapp & So	ons, Inc.	Pay Period Sta Pay Period En			Net Change	ntract Amount Order Amount ntract Amount	\$96,	76,874.20 079.94 72,954.14	
Approval Date	е									Е	By User	
May 2, 2022			Generated and	d Approve	ed (and should be	considere	d Draft) a	at the Project C	Office Level by		kennec2	
May 3, 2022		Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by										
May 4, 2022				Reviewe	ed and Approved	at the Cer	ntral Offic	e Controllers C	Office Level by		ramses1	
Original Co	ompletion Date	Current Con	npletion Date	Act	ual Completion	Date	9/	6 of Current C	Contract Amoun	t Com	plete	
Decem	ber 1, 2021	Decembe	er 21, 2021 December 21, 202			99.16%						
Con	tract Information	al Dates				Mile	stones					
Date Description	Original Completion Date	Current Completion Date	Date	Description	on	Original Completion Date		Current Completion Date	Days Remaini on Milestone		Diary Charge Days	
Acceptance Date			Milestone - Comp Completion Date,		te, JSP B -	June 6, 20	21 Ju	ine 28, 2021	-	310		
Awarded Date	April 7, 2021	April 7, 2021										
Letting Date	March 19, 2021	March 19, 2021										
Notice to Proceed Date	April 22, 2021	April 22, 2021										
Work Began	June 21, 2021	June 21, 2021										

Contract Total Pa	y For Estimate No. 16				
		This Estimate	Previous	To Date	
210319-C02					
	Total Posted Items Pay	\$0.00	\$2,452,144.37	\$2,452,144.37	
	Gross Item Adjustments	\$1,749.80	\$710.22	\$2,460.02	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$2,452,854.59	\$2,454,604.39	
Contract Total Page	yable This Estimate:	\$1,749.80			

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

		tments Exist on Contract						
Line Item /	<u>Adjustr</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4I3436	0040	MISC.	Other Item Adjustment	Fuel Price	Item is non-standard concrete pavement, so system did not automatically add a fuel adjustment to the item. This adjustment is to add a fuel adjustment for the 206.4 SQYD of pavement placed on the project in accordance with guidance from the construction liaison.			\$23.28
	0060	OUTLET PIPES AND SPLASH PADS	Material			-1	\$2,500.00	(\$2,500.00)
	0060	OUTLET PIPES AND SPLASH PADS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$2,500.00	\$2,500.00
J4S3386	0240	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material			-2,233	\$15.00	(\$33,495.00)
	0240	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,233	\$15.00	\$33,495.00
	0250	MISC.	Material			-2,175	\$44.40	(\$96,570.00)

Revision 4/1/2020 Page 1 of 38



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2022

Progress Estimate Number
16
Contract ID 210319-C02 Pay Period Start March 16, 2022 Original Contract Amount \$2,376,874.20
Prime Contractor Emery Sapp & Sons, Inc. Pay Period End May 1, 2022 Net Change Order Amount Current Contract Amount \$2,472,954.14

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3386	0250	MISC.	Material	.,,,,	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	2,175	\$44.40	\$96,570.00
	0250	MISC.	Other Item Adjustment	Asphalt Cement Price Adjustment	Asphalt Cement Price Adjustment for Hot Mix Asphalt (Square Yards) Adjustment was selected in the contract and documentation for the adjustment uploaded in Eprojects.			\$1,807.50
	0280	MODIFIED CONCRETE GUTTER TYPE B	Material			-173	\$60.00	(\$10,380.00
	0280	MODIFIED CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	173	\$60.00	\$10,380.00
	0550	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Other Item Adjustment	Retroreflectivity Adjustment	Adjustment for retroreflectivity readings, documentation uploaded in Eprojects.			\$2.05
	0560	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS		Retroreflectivity Adjustment	Adjustment for retroreflectivity readings, documentation uploaded in Eprojects.			(\$83.03
	0890	BRIDGE APPROACH SLAB (MINOR ROAD)	Material			-169	\$250.00	(\$42,250.00
	0890	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	169	\$250.00	\$42,250.00
	0910	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material			-52	\$1,200.00	(\$62,400.0
	0910	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.	52	\$1,200.00	\$62,400.00
	0920	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material			-28	\$350.00	(\$9,800.0
	0920	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.	28	\$350.00	\$9,800.00
	0980	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-83.1	\$850.00	(\$70,635.00
	0980	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	83.1	\$850.00	\$70,635.00
	0990	TYPE D BARRIER	Material			-403	\$185.00	(\$74,555.00
	0990	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	403	\$185.00	\$74,555.0
	1000	SLAB ON CONCRETE BEAM	Material			-848	\$400.00	(\$339,200.00
	1000	SLAB ON CONCRETE BEAM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	848	\$400.00	\$339,200.00

Revision 4/1/2020 Page 2 of 38



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 2, 2022

Progress Estimate Number	Contract ID	210319-C02	Pay Period Start	March 16, 2022	Original Contract Amount	\$2,376,874.20
16	Prime Contractor	Emery Sapp & Sons, Inc.	Pay Period End	May 1, 2022	Net Change Order Amount	\$96,079.94
10					Current Contract Amount	\$2,472,954.14

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3386					Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.			
	1010	SIDEWALK (BRIDGES)	Material			-1,391	\$15.00	(\$20,865.00)
	1010	SIDEWALK (BRIDGES)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.	1,391	\$15.00	\$20,865.00
	1120	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-1,800	\$65.45	(\$117,810.00)
	1120	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 17 on the current Payment Estimate.	1,800	\$65.45	\$117,810.00
	1150	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-1,766	\$65.45	(\$115,584.70)
	1150	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.	1,766	\$65.45	\$115,584.70
	5003	CURB INLET	Material			-1	\$6,665.12	(\$6,665.12)
	5003	CURB INLET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	1	\$6,665.12	\$6,665.12
Total								\$1,749.80

Revision 4/1/2020 Page 3 of 38



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J4I3436	l 435-1(332)	improvements								
J4S3386	FAS S302(91)	Bridge replacement	53rd Ter	CLAY	over I-435, 0.8 miles south of Rte. 69 and 0.7 miles north of 48th Street					
Totals by	Job Number	S								
J4I3436					This Estimate	Previous	To Date			
		Item Pay tem Adjustment	nts Gross Item Pay		\$0.00 \$23.28 \$23.28	\$77,761.50 \$0.00 \$77,761.50	\$77,761.50 \$23.28 \$77,784.78			
	Incenti Disince Liquida				\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00			
		Contract Adjustn	nents		\$0.00	\$0.00	\$0.00			
J4S3386		Item Pay tem Adjustment	ts Gross Ite	em Pay	This Estimate \$0.00 \$1,726.52 \$1,726.52	Previous \$2,374,382.87 \$710.22 \$2,375,093.09	To Date \$2,374,382.87 \$2,436.74 \$2,376,819.61			
			nents		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 4 of 38



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Feriod			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 3040506, Project Item Line Number 0240, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 4039905, Project Item Line Number 0250, Material Set 403990596, Material 0401BPPMBP1 - Plant Mix for Bit Pavement BP-1, Acceptance Action Generic AspLow is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 4039905, Project Item Line Number 0250, Material Set 403990596, Material 0401BPPMBB - Plant Mix Bituminous Base, Acceptance Action Generic AspLow is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 5031011A, Project Item Line Number 0890, Material Set 5031011A96, Material 1058PSBB - Polyethylene Sheeting for Bond Breaker, Acceptance Action Generic 1058PSBB is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 5031011A, Project Item Line Number 0890, Material Set 5031011A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3436, Item 6054020, Project Item Line Number 0060, Material Set 605402096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4l3436, Item 6054020, Project Item Line Number 0060, Material Set 605402096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 6071102, Project Item Line Number 0280, Material Set 607110296, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 6071102, Project Item Line Number 0280, Material Set 607110296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 6143020, Project Item Line Number 5003, Material Set 614302096, Material 1033DIRCPK - Precast Conc Drop Inlet, Acceptance Action Generic 1033DIRCPK is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7011106, Project Item Line Number 0910, Material Set 701110696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7011205, Project Item Line Number 0920, Material Set 701120596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7032003, Project Item Line Number 0980, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7034219A, Project Item Line Number 0990, Material Set 7034219A96, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7034222, Project Item Line Number 1000, Material Set 703422296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7034430, Project Item Line Number 1010, Material Set 703443096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7201000, Project Item Line Number 1120, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	No Remark was entered by Engineer	kennec2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3386, Item 7201000, Project Item Line Number 1150, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	No Remark was entered by Engineer	kennec2	Overridden

Revision 4/1/2020 Page 5 of 38



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category		Item Code	teport Generated date and can differ from the posted amo Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
10319-C02	J4I3436	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$7,500.00	\$7,500.0
		0001	0020	3030600	FURNISHING ROCK BASE MATERIAL	193.00	13.00	206.00	SQYD	206.00	\$40.00	\$8,240.0
		0001	0030	3030610A	PLACING ROCK BASE	193.00	13.00	206.00	SQYD	206.00	\$30.00	\$6,180.0
		0001	0040	5029905	MISC.CONCRETE PAVEMENT (16 IN, NON-REINFORCED, 15 FT JOINTS)	193.30	13.00	206.30	SQYD	206.30	\$150.00	\$30,945.0
		0001	0050	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	15.00	0.00	15.00	LF	15.00	\$50.00	\$750.0
		0001	0060	6054020	OUTLET PIPES AND SPLASH PADS	1.00	0.00	1.00	EA	1.00	\$2,500.00	\$2,500.0
		0001	0070	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.0
		0001	0800	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	38.00	7.00	45.00	LF	0.00	\$2.00	\$0.0
		0001	0090	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	75.00	4.50	79.50	LF	0.00	\$2.00	\$0.0
		0001	0100	6240104A	SEPARATION GEOTEXTILE	253.00	16.00	269.00	SQYD	269.00	\$5.00	\$1,345.0
		0001	0110	6262000A	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	0.90	0.00	0.90	STA	0.90	\$12,000.00	\$10,800.0
		0001	0120	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$2,925.00	\$2,925.0
		0001	0130	8061006	ALTERNATE DITCH CHECK	40.00	-10.00	30.00	LF	30.00	\$25.00	\$750.0
		0001	0140	8061016	SEDIMENT REMOVAL	9.00	0.00	9.00	CUYD	0.00	\$35.00	\$0.0
		0001	0150	8061019	SILT FENCE	43.00	0.00	43.00	LF	0.00	\$6.50	\$0.0
		0010	0160	6061010	GUARDRAIL TYPE A	38.00	0.00	38.00	LF	38.00	\$21.75	\$826.5
		0040	0170	9039902	MISC.RELOCATION OF EXISTING SIGN ASSEMBLIES	1.00	-1.00	0.00	EA	0.00	\$1,100.00	\$0.0
	Project J	413436 - To	tal Value	Posted to Da	ate as of Report Generated Date							\$77,761.5
	J4S3386	0001	0180	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$10,000.00	\$10,000.0
		0001	0190	2022010	REMOVAL OF IMPROVEMENTS	\$34,000.00	\$34,000.0					
		0001	0200	2031000	CLASS A EXCAVATION	1,766.00	\$20.00	\$35,320.0				
		0001	0210	2035500	EMBANKMENT IN PLACE	2,250.00	-101.00	2,149.00	CUYD	2,149.00	\$25.00	\$53,725.0
		0001	0220	2036000	COMPACTING EMBANKMENT	1,454.00	12.00	1,466.00	CUYD	1,466.00	\$5.00	\$7,330.0
		0001	0230	2063000	CLASS 3 EXCAVATION	305.00	162.00	467.00	CUYD	467.00	\$100.00	\$46,700.0
		0001	0240	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	2,233.00	0.00	2,233.00	SQYD	2,233.00	\$15.00	\$33,495.0
		0001	0250	4039905	MISC.OPTIONAL PAVEMENT	2,142.00	33.00	2,175.00	SQYD	2,175.00	\$44.40	\$96,570.
		0001	0260	6071012A	CHAIN-LINK FENCE (60 IN.)	686.00	0.00	686.00	LF	686.00	\$18.50	\$12,691.
		0001		007 1012A								
		0001	0270	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	173.00	0.00	173.00	LF	173.00	\$55.00	\$9,515.0
					` '	173.00 173.00	0.00	173.00 173.00	LF LF	173.00 173.00	\$55.00 \$60.00	
		0001	0270	6071050	CHAIN-LINK FENCE (RETAINING WALLS)							\$10,380.0
		0001	0270	6071050 6071102	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B	173.00	0.00	173.00	LF	173.00	\$60.00	\$10,380.0 \$9,889.8
		0001 0001 0001	0270 0280 0290	6071050 6071102 6086004 6091051	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN.	173.00 104.10	0.00	173.00 104.10	LF SQYD	173.00 104.10	\$60.00 \$95.00	\$10,380.1 \$9,889.3 \$9,945.1
		0001 0001 0001 0001	0270 0280 0290 0300	6071050 6071102 6086004 6091051	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A	173.00 104.10 252.00	0.00 0.00 -99.00	173.00 104.10 153.00	LF SQYD LF	173.00 104.10 153.00	\$60.00 \$95.00 \$65.00	\$10,380.0 \$9,889.9 \$9,945.0 \$220.0
		0001 0001 0001 0001 0001	0270 0280 0290 0300 0310	6071050 6071102 6086004 6091051 6096010A	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER	173.00 104.10 252.00 4.00	0.00 0.00 -99.00 0.00	173.00 104.10 153.00 4.00	LF SQYD LF CUYD	173.00 104.10 153.00 4.00	\$60.00 \$95.00 \$65.00 \$55.00	\$10,380.1 \$9,889.1 \$9,945.1 \$220.1
		0001 0001 0001 0001 0001	0270 0280 0290 0300 0310 0320	6071050 6071102 6086004 6091051 6096010A 6096041	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER	173.00 104.10 252.00 4.00 4.00	0.00 0.00 -99.00 0.00	173.00 104.10 153.00 4.00 4.00	LF SQYD LF CUYD	173.00 104.10 153.00 4.00	\$60.00 \$95.00 \$65.00 \$55.00	\$10,380.0 \$9,889.5 \$9,945.0 \$220.0 \$700.0
		0001 0001 0001 0001 0001 0001	0270 0280 0290 0300 0310 0320	6071050 6071102 6086004 6091051 6096010A 6096041 6097000	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING	173.00 104.10 252.00 4.00 4.00	0.00 0.00 -99.00 0.00 0.00	173.00 104.10 153.00 4.00 4.00	LF SQYD LF CUYD CUYD	173.00 104.10 153.00 4.00 4.00 4.00	\$60.00 \$95.00 \$65.00 \$55.00 \$175.00	\$10,380.1 \$9,889. \$9,945.1 \$220.1 \$700.1 \$4,800.1
		0001 0001 0001 0001 0001 0001 0001	0270 0280 0290 0300 0310 0320 0330	6071050 6071102 6086004 6091051 6096010A 6096041 6097000 6113020	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING FURNISHING TYPE 2 ROCK BLANKET	173.00 104.10 252.00 4.00 4.00 4.00 24.00	0.00 0.00 -99.00 0.00 0.00 0.00	173.00 104.10 153.00 4.00 4.00 4.00 96.00	LF SQYD LF CUYD CUYD CUYD CUYD	173.00 104.10 153.00 4.00 4.00 4.00 96.00	\$60.00 \$95.00 \$65.00 \$55.00 \$175.00 \$100.00	\$10,380.1 \$9,889.1 \$9,945.1 \$220.1 \$700.1 \$400.1 \$1,900.1
		0001 0001 0001 0001 0001 0001 0001 000	0270 0280 0290 0300 0310 0320 0330 0340	6071050 6071102 6086004 6091051 6096010A 6096010A 6097000 6113020 6113040	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET	173.00 104.10 252.00 4.00 4.00 4.00 24.00	0.00 0.00 -99.00 0.00 0.00 72.00	173.00 104.10 153.00 4.00 4.00 4.00 96.00	LF SQYD LF CUYD CUYD CUYD CUYD	173.00 104.10 153.00 4.00 4.00 4.00 96.00	\$60.00 \$95.00 \$65.00 \$175.00 \$100.00 \$50.00	\$10,380.1 \$9,889. \$9,945.1 \$220.1 \$700.1 \$400.1 \$1,920.1 \$6,000.1
		0001 0001 0001 0001 0001 0001 0001 000	0270 0280 0290 0300 0310 0320 0330 0340 0350	6071050 6071102 6086004 6091051 6096010A 6096041 6097000 6113020 6113040 6122017	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY)	173.00 104.10 252.00 4.00 4.00 4.00 24.00 24.00	0.00 0.00 -99.00 0.00 0.00 72.00 72.00	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00	LF SQYD LF CUYD CUYD CUYD CUYD CUYD	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00 3.00	\$60.00 \$95.00 \$65.00 \$55.00 \$175.00 \$100.00 \$20.00	\$10,380.0 \$9,889.5 \$9,945.0 \$220.0 \$700.0 \$4,800.0 \$1,920.0 \$6,000.0
		0001 0001 0001 0001 0001 0001 0001 000	0270 0280 0290 0300 0310 0320 0330 0340 0350 0360	6071050 6071102 6086004 6091051 6096010A 6096041 6097000 6113020 6113040 6122017 6122020	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) REPLACEMENT SAND BARREL	173.00 104.10 252.00 4.00 4.00 24.00 24.00 2.00	0.00 0.00 -99.00 0.00 0.00 72.00 72.00 1.00	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00 3.00 2.00	LF SQYD LF CUYD CUYD CUYD CUYD CUYD CUYD EA EA	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00 3.00	\$60.00 \$95.00 \$65.00 \$175.00 \$100.00 \$50.00 \$20.00 \$300.00	\$10,380.1 \$9,889.1 \$9,945.1 \$220.1 \$700.1 \$4,800.1 \$1,920.1 \$6,000.1 \$800.1
		0001 0001 0001 0001 0001 0001 0001 000	0270 0280 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380	6071050 6071102 6086004 6091051 6096010A 6096041 6097000 6113020 6112017 6122020 6122030	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) REPLACEMENT SAND BARREL IMPACT ATTENUATOR (RELOCATION)	173.00 104.10 252.00 4.00 4.00 24.00 24.00 2.00 2.00	0.00 0.00 -99.00 0.00 0.00 72.00 72.00 1.00 0.00	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00 3.00 2.00	LF SQYD LF CUYD CUYD CUYD CUYD CUYD EA EA	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00 3.00 0.00	\$60.00 \$95.00 \$65.00 \$175.00 \$100.00 \$20.00 \$2,000.00 \$300.00	\$10,380.1 \$9,889.3 \$9,945.1 \$220.1 \$700.1 \$4,800.1 \$1,920.1 \$6,000.1 \$800.1
		0001 0001 0001 0001 0001 0001 0001 000	0270 0280 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380	6071050 6071102 6086004 6091051 6096010A 6096041 6097000 6113020 6113040 6122017 6122020 6122030 6123000A	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) REPLACEMENT SAND BARREL IMPACT ATTENUATOR (RELOCATION) TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	173.00 104.10 252.00 4.00 4.00 24.00 24.00 2.00 2.00 3.00	0.00 0.00 -99.00 0.00 0.00 72.00 1.00 0.00 0.00	173.00 104.10 153.00 4.00 4.00 96.00 96.00 3.00 2.00 3.00	LF SQYD LF CUYD CUYD CUYD CUYD EA EA EA	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00 3.00 0.00 1.00	\$60.00 \$95.00 \$65.00 \$175.00 \$100.00 \$20.00 \$300.00 \$800.00	\$10,380.0 \$9,889.5 \$9,945.0 \$700.0 \$4,800.0 \$1,920.0 \$6,000.0 \$3,000.0 \$5,356.0
		0001 0001 0001 0001 0001 0001 0001 000	0270 0280 0290 0300 0310 0320 0340 0350 0360 0370 0380 0390	6071050 6071102 6086004 6091051 6096010A 6096041 6097000 6113020 6113040 6122017 6122020 6122030 6123000A 6161005	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) REPLACEMENT SAND BARREL IMPACT ATTENUATOR (RELOCATION) TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS	173.00 104.10 252.00 4.00 4.00 24.00 24.00 2.00 2.00 3.00 996.00	0.00 0.00 -99.00 0.00 0.00 72.00 1.00 0.00 0.00 0.00 0.00	173.00 104.10 153.00 4.00 4.00 96.00 96.00 2.00 2.00 3.00 996.00	LF SQYD LF CUYD CUYD CUYD CUYD EA EA EA SQFT	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00 3.00 0.00 1.00 3.00	\$60.00 \$95.00 \$65.00 \$175.00 \$100.00 \$50.00 \$20.00 \$300.00 \$800.00 \$1,000.00	\$10,380.0 \$9,889.6 \$9,945.0 \$220.0 \$700.0 \$4,800.0 \$1,920.0 \$6,000.0 \$800.0 \$3,000.0 \$5,356.0 \$140.0
		0001 0001 0001 0001 0001 0001 0001 000	0270 0280 0290 0300 0310 0320 0330 0340 0350 0360 0370 0380 0390 04400	6071050 6071102 6086004 6091051 6096010A 6096041 6097000 6113020 6113040 6122017 6122020 6122030 6123000A 6161005	CHAIN-LINK FENCE (RETAINING WALLS) MODIFIED CONCRETE GUTTER TYPE B CONCRETE SIDEWALK, 4 IN. CURB AND GUTTER TYPE A FURNISHING TYPE 1 ROCK DITCH LINER PLACING TYPE 1 ROCK DITCH LINER ROCK LINING FURNISHING TYPE 2 ROCK BLANKET PLACING TYPE 2 ROCK BLANKET IMPACT ATTENUATOR 65 MPH (SAND BARREL ARRAY) REPLACEMENT SAND BARREL IMPACT ATTENUATOR (RELOCATION) TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) CONSTRUCTION SIGNS ADVANCED WARNING RAIL SYSTEM	173.00 104.10 252.00 4.00 4.00 24.00 24.00 2.00 2.00 3.00 996.00	0.00 0.00 -99.00 0.00 0.00 72.00 1.00 0.00 0.00 0.00 0.00 0.00	173.00 104.10 153.00 4.00 4.00 96.00 96.00 3.00 2.00 2.00 3.00 996.00	LF SQYD LF CUYD CUYD CUYD CUYD EA EA EA SQFT	173.00 104.10 153.00 4.00 4.00 4.00 96.00 96.00 3.00 0.00 1.00 3.00 824.00	\$60.00 \$95.00 \$65.00 \$175.00 \$100.00 \$20.00 \$2,000.00 \$300.00 \$1,000.00 \$6.50	\$9,515.0 \$10,380.0 \$9,889.5 \$9,945.0 \$220.0 \$700.0 \$400.0 \$4,800.0 \$1,920.0 \$6,000.0 \$3,000.0 \$5,356.0 \$140.0 \$0.0 \$7,710.0

Page 6 of 38 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
10319-C02	J4S3386	0001	0450	6161033	DIRECTIONAL INDICATOR BARRICADE	42.00	0.00	42.00	EA	28.00	\$40.00	\$1,120.0
		0001	0460	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	2.00	\$900.00	\$1,800.0
		0001	0470	6161055	SEQUENTIAL FLASHING WARNING LIGHT	42.00	0.00	42.00	EA	28.00	\$40.00	\$1,120.0
		0001	0480	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	31.00	3.00	34.00	EA	34.00	\$2,000.00	\$68,000.0
		0001	0490	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	10.00	-10.00	0.00	EA	0.00	\$1,600.00	\$0.0
		0001	0500	6173600D	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	700.00	440.00	1,140.00	LF	1,140.00	\$22.50	\$25,650.0
		0001	0510	6175010A	RELOCATING TEMPORARY TRAFFIC BARRIER	575.00	0.00	575.00	LF	287.50	\$8.00	\$2,300.0
		0001	0520	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$145,000.00	\$145,000.0
		0001	0530	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	1.00	\$600.00	\$600.
		0001	0540	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,975.00	0.00	1,975.00	LF	1,975.00	\$0.45	\$888.
		0001	0550	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	1,275.00	0.00	1,275.00	LF	1,275.00	\$0.45	\$573.
		0001	0560	6206000C	MARKING PAINT, TYPE L BEADS 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	918.00	0.00	918.00	LF	918.00	\$0.45	\$413.1
		0001	0570	6206001C	PAINT, TYPE P BEADS 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	1,466.00	0.00	1,466.00	LF	1,466.00	\$0.45	\$659.7
		0001	0580	6206124A	MARKING PAINT, TYPE P BEADS 24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING	40.00	0.00	40.00	LF	40.00	\$3.00	\$120.0
					PAINT, TYPE P BEADS				LF	8,189.00		
		0001	0590	6207001	PAVEMENT MARKING REMOVAL	11,005.00		11,005.00				\$3,930.
		0001	0600	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	7,755.00		0.00 7,735.00	LF	6,851.00	\$0.50	\$3,425.
		0001	0610	6214600A	FLOWABLE BACKFILL	7.00			CUYD	7.00	\$300.00	\$2,100
		0001	0620	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	64.00	75.00	139.00	SQYD	139.00	\$5.00	\$695
		0001	0630	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000
		0001	0640	7250330A	30 IN. PIPE GROUP B	119.00	42.00	161.00	LF	161.00	\$100.00	\$16,100
		0001	0650	7320030A	30 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.
		0001	0660	8051000A	SEEDING - COOL SEASON GRASSES	1.10	0.00	1.10	ACRE	1.00	\$5,000.00	\$5,000.
		0001	0670	8061005	ROCK DITCH CHECK	60.00	0.00	60.00	LF	60.00	\$15.00	\$900
		0001	0680	8061006	ALTERNATE DITCH CHECK	600.00	0.00	600.00	LF	304.00	\$10.50	\$3,192
		0001	0690	8061016	SEDIMENT REMOVAL	47.00	0.00	47.00	CUYD	47.00	\$35.00	\$1,645
		0001	0700	8061017	TEMPORARY SEEDING	1.10	0.00	1.10	ACRE	0.00	\$3,000.00	\$0
		0001	0710	8061019	SILT FENCE	1,095.00	0.00	1,095.00	LF	53.00	\$2.30	\$121
		0010	0720	6061010	GUARDRAIL TYPE A	188.00	0.00	188.00	LF	188.00	\$21.50	\$4,042
		0010	0730	6061060	MGS GUARDRAIL	350.00	0.00	350.00	LF	350.00	\$22.50	\$7,875
		0010	0740	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	400.00	0.00	400.00	LF	400.00	\$25.50	\$10,200.
		0010	0750	6062204A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (NEW CONSTRUCTION ONLY)	4.00	0.00	4.00	EA	4.00	\$1,850.00	\$7,400
		0010	0760	6062303	ASYMMETRICAL TRANSITION SECTION, 6.5 FT. POSTS	4.00	0.00	4.00	EA	4.00	\$500.00	\$2,000
		0010	0770	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$2,650.00	\$5,300
		0010	0780	6063015	TYPE A CRASHWORTHY END TERMINAL	4.00	0.00	4.00	EA	4.00	\$2,650.00	\$10,600
		0010	0790	6063016	TYPE B CRASHWORTHY END TERMINAL	2.00	0.00	2.00	EA	2.00	\$4,250.00	\$8,500
		0010	0800	6069901	MISC.REMOVAL AND REINSTALL GUARD CABLE	1.00	0.00	1.00	LS	1.00	\$13,000.00	\$13,000
		0040	0810	9031010	CONCRETE FOOTINGS, EMBEDDED	1.90	0.00	1.90	CUYD	1.90	\$1,050.00	\$1,995
		0040	0820	9031210	STRUCTURAL STEEL POSTS	600.00	0.00	600.00	LB	600.00	\$4.50	\$2,700
		0040	0830	9031270A	2 IN. PSST POST - 12 GA.	63.00	0.00	63.00	LF	63.00	\$13.00	\$819
		0040	0840	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	18.00	0.00	18.00	LF	18.00	\$47.50	\$855
		0040	0850	9031280	2.5 IN. PSST POST - 12 GA.	38.00	0.00	38.00	LF	38.00	\$14.00	\$532
		0040	0860	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	9.00	0.00	9.00	LF	9.00	\$50.50	\$454.
		0070	0870	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	22.00	0.00	22.00	SQFT	22.00	\$250.00	\$5,500.
		0070	0880	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$120,000.00	\$120,000.

Page 7 of 38 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description		Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210319-C02	J4S3386	0070	0890	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	169.00	0.00	169.00	SQYD	169.00	\$250.00	\$42,250.00
		0070 0900 6079903 MISC.48 IN. ORNAMENTAL PEDESTRIAN FENCE		MISC.48 IN. ORNAMENTAL PEDESTRIAN FENCE	372.00	0.00	372.00	LF	372.00	\$160.00	\$59,520.00	
		0070	0910	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	28.00	24.00	52.00	LF	52.00	\$1,200.00	\$62,400.00
		0070	0920	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	45.00	-17.00	28.00	LF	28.00	\$350.00	\$9,800.00
		0070	0930	7011300	VIDEO CAMERA INSPECTION	2.00	0.00	2.00	EA	2.00	\$600.00	\$1,200.00
		0070	0940	7011400	FOUNDATION INSPECTION HOLES	65.00	0.00	65.00	LF	65.00	\$150.00	\$9,750.00
		0070	0950	7011600	SONIC LOGGING TESTING	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0070	0960	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	372.00	186.00	558.00	LF	558.00	\$75.00	\$41,850.00
		0070	0970	7027000	PILE POINT REINFORCEMENT	12.00	0.00	12.00	EA	12.00	\$110.00	\$1,320.00
		0070	0980	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	83.10	0.00	83.10	CUYD	83.10	\$850.00	\$70,635.00
		0070	0990	7034219A	TYPE D BARRIER	403.00	0.00	403.00	LF	403.00	\$185.00	\$74,555.00
		0070	1000	7034222	SLAB ON CONCRETE BEAM	848.00	0.00	848.00	SQYD	848.00	\$400.00	\$339,200.00
		0070	1010	7034430	SIDEWALK (BRIDGES)	1,391.00	0.00	1,391.00	SQFT	1,391.00	\$15.00	\$20,865.00
		0070	1020	7034620	FORM LINERS	118.00	0.00	118.00	SQYD	118.00	\$40.00	\$4,720.00
		0070	1030	7056051A	33 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	1,105.00	0.00	1,105.00	LF	1,105.00	\$350.00	\$386,750.00
		0070	1040	7071000	CONDUIT SYSTEM ON STRUCTURE	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000.00
		0070	1050	7101000	REINFORCING STEEL (EPOXY COATED)	18,160.00	0.00	18,160.00	LB	18,160.00	\$1.55	\$28,148.00
		0070	1060	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,750.00	\$3,500.00
		0070	1070	7161000	PLAIN NEOPRENE BEARING PAD	12.00	0.00	12.00	EA	12.00	\$250.00	\$3,000.00
		0070	1080	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	12.00	0.00	12.00	EA	12.00	\$350.00	\$4,200.00
		0070	1090	7201300	PIPE PILE SPACERS	12.00	0.00	12.00	EA	12.00	\$1,000.00	\$12,000.00
		0071	1100	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,656.00	\$1,656.00
		0071	1110	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,656.00	\$1,656.00
		0071	1120	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	1,800.00	0.00	1,800.00	SQFT	1,800.00	\$65.45	\$117,810.00
		0072	1130	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,656.00	\$1,656.00
		0072	1140	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,656.00	\$1,656.00
		0072	1150	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	1,766.00	0.00	1,766.00	SQFT	1,766.00	\$65.45	\$115,584.70
		0001	5001	7250318A	18 IN. PIPE GROUP B	0.00	89.00	89.00	LF	89.00	\$138.13	\$12,293.57
		0001	5002	7320018A	18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION	0.00	1.00	1.00	EA	1.00	\$798.61	\$798.61
		0001	5003	6143020	CURB INLET	0.00	1.00	1.00	EA	1.00	\$6,665.12	\$6,665.12
		0001	5004	7339901	MISC.4 Ft. x 4 Ft. Junction Box	0.00	1.00	1.00	LS	1.00	\$10,335.10	\$10,335.10
		0001	5005	7339901	MISC.Relocating Flared End Section	0.00	1.00	1.00	LS	1.00	\$500.00	\$500.00
		0001	5006	6049901	MISC.Locating Existing Utilities	0.00	1.00	1.00	LS	1.00	\$3,374.34	\$3,374.34
	Project J	4S3386 - To	tal Value	Posted to D	ate as of Report Generated Date							\$2,374,382.86
210319-C02 Ove	erall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$2,452,144.36

Page 8 of 38 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 9 of 38



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J4I3436	0020	FURNISHING ROCK BASE	Material		1	Jun 30, 2021	SYSTEM	(\$8,240.00)											
		MATERIAL			2	Jul 16, 2021	SYSTEM	(\$7,720.00)											
				- Total				(\$15,960.00)											
			Material - Tota					(\$15,960.00)											
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$8,240.00											
					3	Aug 2, 2021	SYSTEM	\$7,720.00											
				- Total				\$15,960.00											
			MaterialCredit	- Total				\$15,960.00											
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$520.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 34 on the current Payment Estimate. Material Insufficiency Quantity 206.000; Overrun Quantity Balance 13.00.										
					1	Jun 30, 2021	SYSTEM	(\$520.00)											
				Overrun - T	otal			\$0.00											
			Overrun - Tota	ıl				\$0.00											
	0020 -	Total						\$0.00											
	0030	PLACING ROCK BASE	Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$390.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user caseyj overridding Payment Estimate Exception 35 on the current Payment Estimate.										
					1	Jun 30, 2021	SYSTEM	(\$390.00)											
				Overrun - T	otal			\$0.00											
			Overrun - Tota	ıl				\$0.00											
	0030 -	Total						\$0.00											
	0040	MISC.	Material		1	Jun 30, 2021	SYSTEM	(\$30,960.00)											
								2	Jul 16, 2021	SYSTEM	(\$28,995.00)								
							3	Aug 2, 2021	SYSTEM	\$28,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user marshp3 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
															3	Aug 2, 2021	SYSTEM	(\$28,995.00)	
					4	Aug 16, 2021	SYSTEM	\$28,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					4	Aug 16, 2021	SYSTEM	(\$28,995.00)											
					5	Sep 1, 2021	SYSTEM	\$28,995.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user marshp3 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					5	Sep 1, 2021	SYSTEM	(\$28,995.00)											
					6	Sep 17, 2021	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					6	Sep 17, 2021	SYSTEM	(\$30,945.00)											
											7	Oct 1, 2021	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user marshp3 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					7	Oct 1, 2021	SYSTEM	(\$30,945.00)											
									8	Oct 15, 2021	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					8	Oct 15, 2021	SYSTEM	(\$30,945.00)											
					9	Nov 2, 2021	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user marshp3 overridding Payment										



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1412426	0040	MICO	Material	Туре					Cating the Constition 2 on the government December Cating the
J4I3436	0040	MISC.	Material		9	Nov 2,	SYSTEM	(\$30,945.00)	Estimate Exception 2 on the current Payment Estimate.
					3	2021	OTOTEW	(ψου,σ-σ.σο)	
					10	Nov 16, 2021	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user marshp3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$30,945.00)	
					11	Dec 2, 2021	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user marshp3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$30,945.00)	
					12	Dec 16, 2021	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user caseyj overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$30,945.00)	
					13	Jan 3, 2022	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user kennec2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$30,945.00)	
					14	Feb 1, 2022	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$30,945.00)	
					15	Mar 16, 2022	SYSTEM	\$30,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$30,945.00)	
				- Total				(\$59,955.00)	
			Material - Tota					(\$59,955.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$30,960.00	
					3	Aug 2, 2021	SYSTEM	\$28,995.00	
				- Total				\$59,955.00	
			MaterialCredit	- Total				\$59,955.00	
			Other Item Adjustment	FUEL	16	May 2, 2022	kennec2	\$23.28	Item is non-standard concrete pavement, so system did not automatically add a fuel adjustment to the item. This adjustment is to add a fuel adjustment for the 206.4 SQYD of pavement placed on the project in accordance with guidance from the construction liaison.
				FUEL - Tota				\$23.28	
			Other Item Adj					\$23.28	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$1,965.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 36 on the current Payment Estimate. Material Insufficiency Quantity 206.400; Overrun Quantity Balance 13.10.
					1	Jun 30, 2021	SYSTEM	(\$1,965.00)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ı				\$0.00	
	0040 -	Total						\$23.28	
	0050	PIPE AGGREGATE PAVEMENT EDGE DRAIN	Material		1	Jun 30, 2021	SYSTEM	(\$1,000.00)	
		DRAIN			2	Jul 16, 2021	SYSTEM	(\$750.00)	
					3	Aug 2, 2021	SYSTEM	(\$750.00)	
					4	Aug 16, 2021	SYSTEM	(\$750.00)	
					5	Sep 1,	SYSTEM	(\$750.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3436	0050	PIPE AGGREGATE PAVEMENT EDGE	Material			2021			
		DRAIN			6	Sep 17, 2021	SYSTEM	(\$750.00)	
					7	Oct 1, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marshp3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Oct 1, 2021	SYSTEM	(\$750.00)	,
					8	Oct 15, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marshp3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Oct 15, 2021	SYSTEM	(\$750.00)	
					9	Nov 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user marshp3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$750.00)	
					10	Nov 16, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user marshp3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$750.00)	
					11	Dec 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user marshp3 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$750.00)	
					12	Dec 16, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user caseyj overridding Payment Estimate Exception 10 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$750.00)	
					13	Jan 3, 2022	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$750.00)	
					14	Feb 1, 2022	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$750.00)	
					15	Mar 16, 2022	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$750.00)	
				- Total				(\$4,750.00)	
			Material - Tota MaterialCredit		2	Jul 16, 2021	SYSTEM	(\$4,750.00) \$1,000.00	
					3	Aug 2, 2021	SYSTEM	\$750.00	
					4	Aug 16, 2021	SYSTEM	\$750.00	
					5	Sep 1, 2021	SYSTEM	\$750.00	
					6	Sep 17, 2021	SYSTEM	\$750.00	
					7	Oct 1, 2021	SYSTEM	\$750.00	
				- Total				\$4,750.00	
			MaterialCredit	- Total				\$4,750.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$250.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 37



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3436	0050	PIPE AGGREGATE PAVEMENT EDGE	Overrun	Overrun					on the current Payment Estimate. Material Insufficiency Quantity 20.000; Overrun Quantity Balance 5.00.
		DRAIN			1	Jun 30, 2021	SYSTEM	(\$250.00)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0050 -	· Total						\$0.00	
	0060	OUTLET PIPES AND SPLASH PADS	Material		1	Jun 30, 2021	SYSTEM	(\$2,500.00)	
		FADS			2	Jul 16, 2021	SYSTEM	(\$2,500.00)	
					3	Aug 2, 2021	SYSTEM	(\$2,500.00)	
					4	Aug 16, 2021	SYSTEM	(\$2,500.00)	
					5	Sep 1, 2021	SYSTEM	(\$2,500.00)	
					6	Sep 17, 2021	SYSTEM	(\$2,500.00)	
					7	Oct 1, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user marshp3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Oct 1, 2021	SYSTEM	(\$2,500.00)	
					8	Oct 15, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user marshp3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Oct 15, 2021	SYSTEM	(\$2,500.00)	
					9	Nov 2, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user marshp3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$2,500.00)	
					10	Nov 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user marshp3 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$2,500.00)	
					11	Dec 2, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user marshp3 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$2,500.00)	
					12	Dec 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user caseyj overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$2,500.00)	
					13	Jan 3, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$2,500.00)	
					14	Feb 1, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$2,500.00)	
					15	Mar 16, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kennec2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$2,500.00)	
					16	May 2, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3436	0060	OUTLET PIPES AND SPLASH PADS	Material		16	May 2, 2022	SYSTEM	(\$2,500.00)	
		1 ADO		- Total				(\$15,000.00)	
			Material - Tota	I				(\$15,000.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$2,500.00	
					3	Aug 2, 2021	SYSTEM	\$2,500.00	
					4	Aug 16, 2021	SYSTEM	\$2,500.00	
					5	Sep 1, 2021	SYSTEM	\$2,500.00	
					6	Sep 17, 2021	SYSTEM	\$2,500.00	
				Total	7	Oct 1, 2021	SYSTEM	\$2,500.00	
				- Total				\$15,000.00	
	0000	T-4-1	MaterialCredit	- Total				\$15,000.00	
	0060 -	6 IN. WHITE HIGH	Material		1	Jun 30,	SYSTEM	\$0.00 (\$90.00)	
		BUILD WATERBORNE PAINT			2	Jul 16, 2021	SYSTEM	(\$76.00)	
				- Total		2021		(\$166.00)	
			Material - Tota					(\$166.00)	
			MaterialCredit	•	2	Jul 16,	SYSTEM	\$90.00	
			Waterlarorout		3	2021 Aug 2,	SYSTEM	\$76.00	
						2021			
				- Total				\$166.00	
			MaterialCredit					\$166.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$14.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0018) overridding Payment Estimate Exception 38 on the current Payment Estimate. Material Insufficiency Quantity 45.000; Overrun Quantity Balance 7.00.
					1	Jun 30, 2021	SYSTEM	(\$14.00)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0080 -							\$0.00	
	0090	6 IN. YELLOW HIGH BUILD WATERBORNE	Material		1	Jun 30, 2021	SYSTEM	(\$159.00)	
		PAINT			2	Jul 16, 2021	SYSTEM	(\$150.00)	
				- Total				(\$309.00)	
			Material - Tota					(\$309.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$159.00	
				Total	3	Aug 2, 2021	SYSTEM	\$150.00	
			MaterialCredit	- Total				\$309.00 \$309.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$9.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0020) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 79.500;
					1	Jun 30, 2021	SYSTEM	(\$9.00)	Overrun Quantity Balance 4.50.
				Overrun - T	otal			\$0.00	
			Overrun - Tota					\$0.00	
	0090 -	Total	Oroman - Tota					\$0.00	
	-0030 -	Total						φυ.υυ	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4I3436	0100	SEPARATION GEOTEXTILE	Material		1	Jun 30, 2021	SYSTEM	(\$1,345.00)	
					2	Jul 16, 2021	SYSTEM	(\$1,265.00)	
				- Total				(\$2,610.00)	
			Material - Tota	ı				(\$2,610.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$1,345.00	
					3	Aug 2, 2021	SYSTEM	\$1,265.00	
				- Total				\$2,610.00	
			MaterialCredit	- Total				\$2,610.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$80.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0022) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 269.000; Overrun Quantity Balance 16.00.
					1	Jun 30, 2021	SYSTEM	(\$80.00)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0100 -	Total						\$0.00	
	0130	ALTERNATE DITCH CHECK	Material		3	Aug 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user marshp3 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$750.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0130 -							\$0.00	
	0160	GUARDRAIL TYPE A	Material		1	Jun 30, 2021	SYSTEM	(\$826.50)	
					2	Jul 16, 2021	SYSTEM	(\$826.50)	
					3	Aug 2, 2021	SYSTEM	(\$826.50)	
					4	Aug 16, 2021	SYSTEM	\$826.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$826.50)	
				- Total				(\$2,479.50)	
			Material - Tota	I				(\$2,479.50)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$826.50	
					3	Aug 2, 2021	SYSTEM	\$826.50	
					4	Aug 16, 2021	SYSTEM	\$826.50	
				- Total				\$2,479.50	
			MaterialCredit	- I otal				\$2,479.50	
	0160 -	Total						\$0.00	
J4I3436 -								\$23.28	
J4S3386	0200	CLASS A EXCAVATION	Price FUEL		10	Nov 16, 2021	SYSTEM	\$132.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total	12	Dec 16, 2021	SYSTEM	\$22.34	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			Duine FUEL - T					\$154.34	
	0000		Price FUEL - T	otal				\$154.34	
	0200 -						a.va===	\$154.34	
	0210	EMBANKMENT IN PLACE	Material		10	Nov 16, 2021	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user marshp3 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0210	EMBANKMENT IN	Material	.,,,,,					Estimate Exception 1 on the current Payment Estimate.
		PLACE			10	Nov 16, 2021	SYSTEM	(\$50,000.00)	
					11	Dec 2, 2021	SYSTEM	\$50,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user marshp3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$50,000.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Price FUEL		10	Nov 16, 2021	SYSTEM	\$308.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Dec 16, 2021	SYSTEM	\$21.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$329.90	
			Price FUEL - T	otal				\$329.90	
	0210 -	Total						\$329.90	
	0240	AGGREGATE FOR BASE (6 IN.	Material		11	Dec 2, 2021	SYSTEM	\$33,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user marshp3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		THICK)			11	Dec 2, 2021	SYSTEM	(\$33,495.00)	
					12	Dec 16, 2021	SYSTEM	\$33,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user caseyj overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$33,495.00)	
					13	Jan 3, 2022	SYSTEM	\$33,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$33,495.00)	
					14	Feb 1, 2022	SYSTEM	\$33,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$33,495.00)	
					15	Mar 16, 2022	SYSTEM	\$33,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$33,495.00)	
					16	May 2, 2022	SYSTEM	\$33,495.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user kennec2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$33,495.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Price FUEL		11	Dec 2, 2021	SYSTEM	\$225.98	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$225.98	
			Price FUEL - T	otal				\$225.98	
	0240 -	Total						\$225.98	
	0250	MISC.	Material		11	Dec 2, 2021	SYSTEM	\$95,104.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$95,104.80)	
					14	Feb 1, 2022	SYSTEM	\$96,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$96,570.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0250	MISC.	Material		15	Mar 16, 2022	SYSTEM	\$96,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$96,570.00)	
					16	May 2, 2022	SYSTEM	\$96,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$96,570.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Other Item Adjustment	ACAD	16	May 2, 2022	kennec2	\$1,807.50	Asphalt Cement Price Adjustment for Hot Mix Asphalt (Square Yards) Adjustment was selected in the contract and documentation for the adjustment uploaded in Eprojects.
				ACAD - Tota	al			\$1,807.50	
			Other Item Ad	justment - To	tal			\$1,807.50	
	0250 -	Total						\$1,807.50	
	0260	CHAIN-LINK FENCE (60 IN.)	Material		13	Jan 3, 2022	SYSTEM	\$12,691.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$12,691.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0260 -	Total						\$0.00	
	0270	CHAIN-LINK FENCE (RETAINING	Material		12	Dec 16, 2021	SYSTEM	\$9,509.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user caseyj overridding Payment Estimate Exception 14 on the current Payment Estimate.
		WALLS)			12	Dec 16, 2021	SYSTEM	(\$9,509.50)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0270 -	Total						\$0.00	
	0280	MODIFIED CONCRETE GUTTER TYPE B	Material		9	Nov 2, 2021	SYSTEM	\$10,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user marshp3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$10,380.00)	
					10	Nov 16, 2021	SYSTEM	\$10,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$10,380.00)	
					11	Dec 2, 2021	SYSTEM	\$10,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$10,380.00)	
					12	Dec 16, 2021	SYSTEM	\$10,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user caseyj overridding Payment Estimate Exception 15 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$10,380.00)	
					13	Jan 3, 2022	SYSTEM	\$10,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$10,380.00)	
					14	Feb 1, 2022	SYSTEM	\$10,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$10,380.00)	
					15	Mar 16,	SYSTEM	\$10,380.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0280	MODIFIED CONCRETE	Material			2022			Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		GUTTER TYPE B			15	Mar 16, 2022	SYSTEM	(\$10,380.00)	
					16	May 2, 2022	SYSTEM	\$10,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user kennec2 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$10,380.00)	
				- Total				\$0.00	
	0200	Total	Material - Tota	ıl				\$0.00	
	0280 -		Matarial		44	D O	OVOTEM	\$0.00	This adjustment off at the critical part of Material December
	0290	CONCRETE SIDEWALK, 4 IN.	Material		11	Dec 2, 2021	SYSTEM	\$7,486.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$7,486.00)	
					12	Dec 16, 2021	SYSTEM	\$9,889.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user caseyj overridding Payment Estimate Exception 19 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$9,889.50)	
					13	Jan 3, 2022	SYSTEM	\$9,889.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$9,889.50)	
					14	Feb 1, 2022	SYSTEM	\$9,889.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$9,889.50)	
					15	Mar 16, 2022	SYSTEM	\$9,889.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$9,889.50)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0290 -	Total						\$0.00	
	0300	CURB AND GUTTER TYPE A	Material		11	Dec 2, 2021	SYSTEM	\$11,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user marshp3 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$11,050.00)	
					12	Dec 16, 2021	SYSTEM	\$11,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user caseyj overridding Payment Estimate Exception 21 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$11,050.00)	
					13	Jan 3, 2022	SYSTEM	\$11,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$11,050.00)	
					14	Feb 1, 2022	SYSTEM	\$9,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$9,945.00)	
					15	Mar 16, 2022	SYSTEM	\$9,945.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$9,945.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0300	CURB AND GUTTER TYPE A	Material - Tota					\$0.00	
	0300 -	· Total						\$0.00	
	0310	FURNISHING TYPE 1 ROCK DITCH LINER	Material		12	Dec 16, 2021	SYSTEM	\$220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user caseyj overridding Payment Estimate Exception 23 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$220.00)	
					13	Jan 3, 2022	SYSTEM	\$220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$220.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0310 -	· Total						\$0.00	
	0360	IMPACT ATTENUATOR 65	Material		1	Jun 30, 2021	SYSTEM	(\$6,000.00)	
		MPH (SAND BARREL ARRAY)			2	Jul 16, 2021	SYSTEM	(\$4,000.00)	
				- Total				(\$10,000.00)	
			Material - Tota	ı				(\$10,000.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$6,000.00	
					3	Aug 2, 2021	SYSTEM	\$4,000.00	
				- Total				\$10,000.00	
			MaterialCredit					\$10,000.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.
					1	Jun 30, 2021	SYSTEM	(\$2,000.00)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0360 -	Total						\$0.00	
	0390	TRUCK OR TRAILER MOUNTED ATTEN	Material		1	Jun 30, 2021	SYSTEM	(\$2,000.00)	
		(TMA)			2	Jul 16, 2021	SYSTEM	(\$2,000.00)	
					3	Aug 2, 2021 Aug 16,	SYSTEM	(\$2,000.00)	
					·	2021	0.0.2	(ψΣ,000.00)	
				- Total				(\$8,000.00)	
			Material - Tota	l				(\$8,000.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$2,000.00	
					3	Aug 2, 2021	SYSTEM	\$2,000.00	
					4	Aug 16, 2021	SYSTEM	\$2,000.00	
				- Total	5	Sep 1, 2021	SYSTEM	\$2,000.00	
			MaterialCredit					\$8,000.00	
	0390 -	Total	atoriaroreuit	Total				\$0.00	
	0400	CONSTRUCTION	Material		1	Jun 30,	SYSTEM	(\$5,148.00)	
	U#UU	SIGNS	wawiai		2	Jul 16,	SYSTEM	(\$5,148.00)	
					_	2021	STOTEW	(ψυ, 1πυ.υυ)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0400	CONSTRUCTION	Material	- Total				(\$10,296.00)	
		SIGNS	Material - Tota					(\$10,296.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$5,148.00	
					3	Aug 2, 2021	SYSTEM	\$5,148.00	
				- Total				\$10,296.00	
			MaterialCredit	- Total				\$10,296.00	
	0400 -	Total						\$0.00	
	0430	CHANNELIZER (TRIM LINE)	Material		1	Jun 30, 2021	SYSTEM	(\$7,710.00)	
					2	Jul 16, 2021	SYSTEM	(\$4,620.00)	
				- Total				(\$12,330.00)	
			Material - Tota					(\$12,330.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$7,710.00	
					3	Aug 2, 2021	SYSTEM	\$4,620.00	
				- Total				\$12,330.00	
			MaterialCredit	- Total				\$12,330.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$3,090.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 30 on the current Payment Estimate. Material Insufficiency Quantity 257.000; Overrun Quantity Balance 103.00.
					1	Jun 30, 2021	SYSTEM	(\$3,090.00)	
				Overrun - To	otal			\$0.00	
			Overrun - Tota					\$0.00	
	0430 -	Total						\$0.00	
	0440	TYPE III	Material		1	Jun 30,	SYSTEM	(\$6,000.00)	
		MOVEABLE BARRICADE			2	2021 Jul 16,	SYSTEM	(\$5,250.00)	
				- Total		2021		(\$11,250.00)	
			Material - Tota					(\$11,250.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$6,000.00	
					3	Aug 2, 2021	SYSTEM	\$5,250.00	
				- Total				\$11,250.00	
			MaterialCredit					\$11,250.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 31 on the current Payment Estimate. Material Insufficiency Quantity 40.000; Overrun Quantity Balance 5.00.
					1	Jun 30, 2021	SYSTEM	(\$750.00)	
				Overrun - To	otal			\$0.00	
			Overrun - Tota					\$0.00	
	0440 -	Total						\$0.00	
	0450	DIRECTIONAL INDICATOR	Material		1	Jun 30, 2021	SYSTEM	(\$1,120.00)	
		BARRICADE			2	Jul 16, 2021	SYSTEM	(\$1,120.00)	
				- Total				(\$2,240.00)	
			Material - Tota					(\$2,240.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$1,120.00	
					3	Aug 2,	SYSTEM	\$1,120.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0450	DIRECTIONAL	MaterialCredit	.,,,,,		2021			
		INDICATOR BARRICADE		- Total				\$2,240.00	
			MaterialCredit	- Total				\$2,240.00	
	0450 -	Total						\$0.00	
	0460	FLASHING ARROW PANEL	Material		1	Jun 30, 2021	SYSTEM	(\$1,800.00)	
					2	Jul 16, 2021	SYSTEM	(\$1,800.00)	
				- Total				(\$3,600.00)	
			Material - Tota	l				(\$3,600.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$1,800.00	
					3	Aug 2, 2021	SYSTEM	\$1,800.00	
			M (1.10 III	- Total				\$3,600.00	
			MaterialCredit	- Total				\$3,600.00	
	0460 -		Matarial		4	h 00	OVOTEL	\$0.00	
	0470	SEQUENTIAL FLASHING WARNING LIGHT	Material		1	Jun 30, 2021	SYSTEM	(\$1,120.00)	
					2	Jul 16, 2021	SYSTEM	(\$1,120.00)	
				- Total				(\$2,240.00)	
			Material - Tota	1				(\$2,240.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$1,120.00	
					3	Aug 2, 2021	SYSTEM	\$1,120.00	
				- Total				\$2,240.00	
			MaterialCredit	- Total				\$2,240.00	
	0470 -							\$0.00	
	0480	CMS WITH COMMUNICATION INTERFACE,	Material		1	Jun 30, 2021	SYSTEM	(\$68,000.00)	
		CONT F			2	Jul 16, 2021	SYSTEM	(\$62,000.00)	
				- Total				(\$130,000.00)	
			Material - Tota	l				(\$130,000.00)	
			MaterialCredit		2	Jul 16, 2021	SYSTEM	\$68,000.00	
					3	Aug 2, 2021	SYSTEM	\$62,000.00	
				- Total				\$130,000.00	
			MaterialCredit	- Total				\$130,000.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 32 on the current Payment Estimate. Material Insufficiency Quantity 34.000; Overrun Quantity Balance 3.00.
					1	Jun 30, 2021	SYSTEM	(\$6,000.00)	
				Overrun - T	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0480 -	Total						\$0.00	
	0500	TEMPORARY TRAFFIC BARRIER, CONT.	Material		1	Jun 30, 2021	SYSTEM	(\$25,650.00)	
		FURN/RE			2	Jul 16, 2021	SYSTEM	(\$15,750.00)	
					3	Aug 2, 2021	SYSTEM	(\$15,750.00)	
					4	Aug 16, 2021	SYSTEM	(\$15,750.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0500	TEMPORARY	Material	- Total				(\$72,900.00)	
		TRAFFIC BARRIER, CONT.	Material - Tota					(\$72,900.00)	
		FURN/RE	MaterialCredit		2	Jul 16, 2021	SYSTEM	\$25,650.00	
					3	Aug 2, 2021	SYSTEM	\$15,750.00	
					4	Aug 16, 2021	SYSTEM	\$15,750.00	
					5	Sep 1, 2021	SYSTEM	\$15,750.00	
				- Total		2021		\$72,900.00	
			MaterialCredit					\$72,900.00	
			Overrun	Overrun	1	Jun 30, 2021	SYSTEM	\$9,900.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 1140.000; Overrun Quantity Balance 440.00.
					1	Jun 30,	SYSTEM	(\$9,900.00)	Overfull Quantity Balance 440.00.
				Overrun - To	otal	2021		\$0.00	
			Overrun - Tota	ı				\$0.00	
	0500 -	Total						\$0.00	
	0540	6 IN. WHITE HIGH BUILD WATERBORNE	Material		12	Dec 16, 2021	SYSTEM	\$888.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user caseyj overridding Payment Estimate Exception 24 on the current Payment Estimate.
		PAINT			12	Dec 16, 2021	SYSTEM	(\$888.75)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0540 -	· Total						\$0.00	
	0550	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		12	Dec 16, 2021	SYSTEM	\$573.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user caseyj overridding Payment Estimate Exception 26 on the current Payment Estimate.
		FAIIVI			12	Dec 16, 2021	SYSTEM	(\$573.75)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
			Other Item Adjustment	REFL	16	May 2, 2022	kennec2	\$2.05	Adjustment for retroreflectivity readings, documentation uploaded in Eprojects.
				REFL - Tota				\$2.05	
			Other Item Ad					\$2.05	
	DEED		Other Item Au	ustment - To	tal			\$2.05	
		Total						\$2.05 \$2.05	
	0560	4 IN. WHITE WATERBORNE		REFL	16	May 2, 2022	kennec2	\$2.05 \$2.05 (\$83.03)	Adjustment for retroreflectivity readings, documentation uploaded in Eprojects.
		4 IN. WHITE	Other Item Adjustment	REFL - Tota	16		kennec2	\$2.05 \$2.05 (\$83.03) (\$83.03)	Adjustment for retroreflectivity readings, documentation uploaded in Eprojects.
	0560	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Other Item	REFL - Tota	16		kennec2	\$2.05 \$2.05 (\$83.03) (\$83.03) (\$83.03)	Adjustment for retroreflectivity readings, documentation uploaded in Eprojects.
	0560	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Other Item Adjustment Other Item Ad	REFL - Tota	16 I	2022		\$2.05 \$2.05 (\$83.03) (\$83.03) (\$83.03)	
	0560	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Other Item Adjustment	REFL - Tota	16		kennec2	\$2.05 \$2.05 (\$83.03) (\$83.03) (\$83.03)	Adjustment for retroreflectivity readings, documentation uploaded in Eprojects. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
	0560	4 IN. WHITE WATERBORNE PAVEMENT MARKING Total FLOWABLE	Other Item Adjustment Other Item Ad	REFL - Tota	16 I	2022 Sep 1,		\$2.05 \$2.05 (\$83.03) (\$83.03) (\$83.03)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment
	0560	4 IN. WHITE WATERBORNE PAVEMENT MARKING Total FLOWABLE	Other Item Adjustment Other Item Ad	REFL - Tota	16 I tal	Sep 1, 2021	SYSTEM	\$2.05 \$2.05 (\$83.03) (\$83.03) (\$83.03) (\$83.03) \$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment
	0560	4 IN. WHITE WATERBORNE PAVEMENT MARKING Total FLOWABLE	Other Item Adjustment Other Item Ad	REFL - Tota	16 I 5 5 5	Sep 1, 2021 Sep 1, 2021 Nov 2,	SYSTEM	\$2.05 \$2.05 (\$83.03) (\$83.03) (\$83.03) (\$83.03) \$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user marshp3 overridding Payment
	0560	4 IN. WHITE WATERBORNE PAVEMENT MARKING Total FLOWABLE	Other Item Adjustment Other Item Ad	REFL - Tota	16 I I I I I I I I I I I I I I I I I I I	Sep 1, 2021 Sep 1, 2021 Nov 2, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM	\$2.05 \$2.05 (\$83.03) (\$83.03) (\$83.03) (\$83.03) \$2,100.00 (\$2,100.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user marshp3 overridding Payment
	0560	4 IN. WHITE WATERBORNE PAVEMENT MARKING Total FLOWABLE	Other Item Adjustment Other Item Ad	REFL - Tota	16 I I I I I I I I I I I I I I I I I I I	Sep 1, 2021 Sep 1, 2021 Sep 1, 2021 Nov 2, 2021 Nov 2, 2021	SYSTEM SYSTEM SYSTEM	\$2.05 \$2.05 (\$83.03) (\$83.03) (\$83.03) (\$83.03) \$2,100.00 (\$2,100.00) (\$2,100.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user marshp3 overridding Payment Estimate Exception 21 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0610	FLOWABLE BACKFILL	Material			2021			Estimate Item Adjustment (0008) due to user marshp3 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$2,100.00)	
					12	Dec 16, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user caseyj overridding Payment Estimate Exception 28 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$2,100.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0610 -	Total						\$0.00	
	0620	PERMANENT EROSION CONTROL	Material		12	Dec 16, 2021	SYSTEM	\$320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user caseyj overridding Payment Estimate Exception 29 on the current Payment Estimate.
		GEOTEXTILE			12	Dec 16, 2021	SYSTEM	(\$320.00)	
					13	Jan 3, 2022	SYSTEM	\$320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$320.00)	
					14	Feb 1, 2022	SYSTEM	\$695.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$695.00)	
					15	Mar 16, 2022	SYSTEM	\$695.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$695.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0620 -	Total						\$0.00	
	0650	30 IN. GROUP B FLARED END SEC	Material		5	Sep 1, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					5	Sep 1, 2021	SYSTEM	(\$4,000.00)	
					6	Sep 17, 2021	SYSTEM	(\$4,000.00)	
					7	Oct 1, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user marshp3 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					7	Oct 1, 2021	SYSTEM	(\$4,000.00)	
					8	Oct 15, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user marshp3 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					8	Oct 15, 2021	SYSTEM	(\$4,000.00)	
					9	Nov 2, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user marshp3 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$4,000.00)	
					10	Nov 16, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$4,000.00)	·
					11	Dec 2, 2021	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					11	Dec 2,	SYSTEM	(\$4,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
4S3386	0650	30 IN. GROUP B	Material			2021			
		FLARED END SEC			13	Jan 3, 2022	SYSTEM	\$4,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$4,000.00)	
				- Total				(\$4,000.00)	
			Material - Tota					(\$4,000.00)	
			MaterialCredit		7	Oct 1, 2021	SYSTEM	\$4,000.00	
				- Total				\$4,000.00	
			MaterialCredit	- Total				\$4,000.00	
	0650 -	Total						\$0.00	
	0660	SEEDING - COOL SEASON GRASSES	Material		12	Dec 16, 2021	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user caseyj overridding Payment Estimate Exception 50 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$5,000.00)	
					13	Jan 3, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$5,000.00)	
			- Total				\$0.00		
			Material - Tota	1				\$0.00	
	0660 -	Total						\$0.00	
	0670	ROCK DITCH CHECK			2	Jul 16, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kennem2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					2	Jul 16, 2021	SYSTEM	(\$750.00)	
					3	Aug 2, 2021	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user marshp3 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					3	Aug 2, 2021	SYSTEM	(\$750.00)	
				- Total				\$0.00	
			Material - Tota	<u>'</u>				\$0.00	
	0670 -		Material		0	A 5	OVOTELL	\$0.00	
	0710	SILT FENCE	Material		3	Aug 2, 2021	SYSTEM	(\$121.90)	
					4	Aug 16, 2021	SYSTEM	\$121.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$121.90)	
				- Total				(\$121.90)	
			Material - Tota		,		0)/0==:	(\$121.90)	
			MaterialCredit		4	Aug 16, 2021	SYSTEM	\$121.90	
				- Total				\$121.90	
			MaterialCredit	- Total				\$121.90	
	0710 -						2).(2)	\$0.00	
	0720	GUARDRAIL TYPE A	Construction Stockpile	Total	12	Dec 16, 2021	SYSTEM	(\$2,620.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total	tal			(\$2,620.00)	
			Construction Stockpile	Stockpile - To	5	Sep 1, 2021	SYSTEM	(\$2,620.00) \$2,620.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		S	STMI	- Total				\$2,620.00	
			Construction S		/II - <u>Total</u>			\$2,620.00	
			- July a ottoff (,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
3386	0720 -	Total		Туро				\$0.00		
	0730	MGS GUARDRAIL	Construction Stockpile		11	Dec 2, 2021	SYSTEM	(\$5,190.50)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$5,190.50)		
			Construction	Stockpile - To	otal			(\$5,190.50)		
			Construction Stockpile STMI	Total	5	Sep 1, 2021	SYSTEM	\$5,190.50	Payment Estimate Item Adjustment generated Stockpile Transaction	
			0 1 11	- Total				\$5,190.50		
	0730 -	Total	Construction	Stockpile STI	vii - Totai			\$5,190.50		
	0740	MGS GUARDRAIL, 8 FT. POSTS, 6 FT.	Construction Stockpile		12	Dec 16, 2021	SYSTEM	\$0.00 (\$6,684.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		- 3 IN		- Total				(\$6,684.00)		
			Construction	Stockpile - To	otal			(\$6,684.00)		
			Construction Stockpile		5	Sep 1, 2021	SYSTEM	\$6,684.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$6,684.00		
			Construction	Stockpile STI	VII - Total			\$6,684.00		
	0740 -	Total						\$0.00		
	0750	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS	Construction Stockpile		12	Dec 16, 2021	SYSTEM	(\$4,672.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		F0313		- Total				(\$4,672.00)		
			Construction	Stockpile - To	otal			(\$4,672.00)		
			Construction Stockpile STMI		5	Sep 1, 2021	SYSTEM	\$4,672.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$4,672.00		
			Construction	Stockpile STI	VII - Total			\$4,672.00		
	0750 -							\$0.00		
	0760	ASYMMETRICAL TRNS. SEC., 6.5 FT. POSTS	TRNS. SEC., 6.5	Construction Stockpile		12	Dec 16, 2021	SYSTEM	(\$712.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			O a mark muse the mark	- Total	4-1			(\$712.00)		
			Construction	Stockpile - 10		0 1	OVOTEM	(\$712.00)	Down and Father the News Adjustment are control Otrachelle Transaction	
			Construction Stockpile STMI	- Total	5	Sep 1, 2021	SYSTEM	\$712.00 \$712.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction		MI - Total			\$712.00		
	0760 -	Total						\$0.00		
	0770	TYPE A CRASHWORTHY	Construction Stockpile		12	Dec 16, 2021	SYSTEM	(\$3,244.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		END TERMINAL (MASH)		- Total				(\$3,244.00)		
			Construction	Stockpile - To	otal			(\$3,244.00)		
			Construction Stockpile STMI		5	Sep 1, 2021	SYSTEM	\$3,244.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$3,244.00		
			Construction	Stockpile STI	VII - Total			\$3,244.00		
	0770 -							\$0.00		
	0780	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile	Total	12	Dec 16, 2021	SYSTEM	(\$6,032.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			- Total					(\$6,032.00)		
			Construction	Stockpile - To		Carr d	CVOTELL	(\$6,032.00)	Designant Estimate Hom Adjustment account of Ch. 1, 17	
			Construction Stockpile STMI	- Total	5	Sep 1, 2021	SYSTEM	\$6,032.00 \$6,032.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Construction		MI - Total			\$6,032.00		
	0780 -	Total	Construction	Stockpile STI	m - Total			\$6,032.00		
	0790		Construction		11	Dec 2	SYSTEM		Payment Estimate Item Adjustment generated Steelinile Transaction	
	0780	TYPE B CRASHWORTHY	Stockpile		11	Dec 2, 2021	JIJIEW	(\$6,028.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0790	END TERMINAL	Construction Stockpile	- Total				(\$6,028.00)	
			Construction S	Stockpile - To	otal			(\$6,028.00)	
			Construction Stockpile		5	Sep 1, 2021	SYSTEM	\$6,028.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$6,028.00	
			Construction S	Stockpile STI	/II - Total			\$6,028.00	
	0790 -	Total						\$0.00	
	0810	CONCRETE	Material		12	Dec 16,	SYSTEM	\$1,995.00	This adjustment offsets the original system-generated Material Payment
		FOOTINGS, EMBEDDED				2021			Estimate Item Adjustment (0020) due to user caseyj overridding Payment Estimate Exception 52 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$1,995.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0810 -	Total						\$0.00	
	0830	2 IN. PSST POST - 12 GA.	Material		12	Dec 16, 2021	SYSTEM	\$819.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user caseyj overridding Payment Estimate Exception 53 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$819.00)	
					13	Jan 3, 2022	SYSTEM	\$819.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$819.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0830	Total	material rota					\$0.00	
	0830 - 0840		Material		12	Dec 16, 2021	SYSTEM	\$855.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user caseyj overridding Payment Estimate Exception 54 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$855.00)	
					13	Jan 3, 2022	SYSTEM	\$855.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$855.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0840 -	Total						\$0.00	
	0850	2.5 IN. PSST POST - 12 GA.	Material		12	Dec 16, 2021	SYSTEM	\$532.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user caseyj overridding Payment Estimate Exception 55 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$532.00)	
					13	Jan 3, 2022	SYSTEM	\$532.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$532.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0850 -	Total						\$0.00	
	0860	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material		12	Dec 16, 2021	SYSTEM	\$454.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user caseyj overridding Payment Estimate Exception 56 on the current Payment Estimate.
		. 3/11			12	Dec 16, 2021	SYSTEM	(\$454.50)	
					13	Jan 3, 2022	SYSTEM	\$454.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 48 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0860	POST ANCHOR FOR 2.5 IN. PSST -	Material	,	13	Jan 3, 2022	SYSTEM	(\$454.50)	
		7 GA.		- Total				\$0.00	
			Material - Tota					\$0.00	
	0860 -	Total						\$0.00	
	0890	BRIDGE APPROACH SLAB (MINOR ROAD)	Material		9	Nov 2, 2021	SYSTEM	\$21,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$21,125.00)	
					10	Nov 16, 2021	SYSTEM	\$42,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user marshp3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$42,250.00)	
					11	Dec 2, 2021	SYSTEM	\$42,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user marshp3 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$42,250.00)	
					12	Dec 16, 2021	SYSTEM	\$42,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user caseyj overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$42,250.00)	
					13	Jan 3, 2022	SYSTEM	\$42,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$42,250.00)	
					14	Feb 1, 2022	SYSTEM	\$42,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$42,250.00)	
					15	Mar 16, 2022	SYSTEM	\$42,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$42,250.00)	
					16	May 2, 2022	SYSTEM	\$42,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user kennec2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$42,250.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0890 -	Total						\$0.00	
	0910	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		5	Sep 1, 2021	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 1, 2021	SYSTEM	(\$33,600.00)	
					6	Sep 17, 2021	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user marshp3 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Sep 17, 2021	SYSTEM	(\$33,600.00)	
					7	Oct 1, 2021	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Oct 1, 2021	SYSTEM	(\$33,600.00)	
					8	Oct 15, 2021	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user marshp3 overridding Payment Estimate Exception 9 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0910	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		8	Oct 15, 2021	SYSTEM	(\$33,600.00)	
					9	Nov 2, 2021	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$33,600.00)	
					10	Nov 16, 2021	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user marshp3 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$33,600.00)	
					11	Dec 2, 2021	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$33,600.00)	
					12	Dec 16, 2021	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user caseyj overridding Payment Estimate Exception 30 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$33,600.00)	
					13	Jan 3, 2022	SYSTEM	\$33,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kennec2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$33,600.00)	
					14	Feb 1, 2022	SYSTEM	\$62,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$62,400.00)	
					15	Mar 16, 2022	SYSTEM	\$62,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$62,400.00)	
					16	May 2, 2022	SYSTEM	\$62,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user kennec2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$62,400.00)	
				- Total				\$0.00	
	0910 -	Total	Material - Tota	ıl				\$0.00 \$0.00	
	0920	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		5	Sep 1, 2021	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marshp3 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Sep 1, 2021	SYSTEM	(\$9,450.00)	
					6	Sep 17, 2021	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user marshp3 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					6	Sep 17, 2021	SYSTEM	(\$9,450.00)	
					7	Oct 1, 2021	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Oct 1, 2021	SYSTEM	(\$9,450.00)	
					8	Oct 15, 2021	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user marshp3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Oct 15, 2021	SYSTEM	(\$9,450.00)	
					9	Nov 2, 2021	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 26 on the current Payment Estimate.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3386	0920	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		9	Nov 2, 2021	SYSTEM	(\$9,450.00)	
					10	Nov 16, 2021	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$9,450.00)	
					11	Dec 2, 2021	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marshp3 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$9,450.00)	
					12	Dec 16, 2021	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user caseyj overridding Payment Estimate Exception 32 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$9,450.00)	
					13	Jan 3, 2022	SYSTEM	\$9,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kennec2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$9,450.00)	
					14	Feb 1, 2022	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$9,800.00)	
					15	Mar 16, 2022	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$9,800.00)	
					16	May 2, 2022	SYSTEM	\$9,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user kennec2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$9,800.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0920 - 0960	GALVANIZED STRUCTURAL STEEL PILES (12	Material		4	Aug 16, 2021	SYSTEM	\$0.00 \$27,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
		İN			4	Aug 16, 2021	SYSTEM	(\$27,900.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00 \$0.00	
	0960 -	Total	Material - Tota						
	0960 -	Total PILE POINT REINFORCEMENT			4	Aug 16, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		PILE POINT			4		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0006) due to user marshp3 overridding Payment
		PILE POINT	Material	ıl - Total		2021 Aug 16,		\$0.00 \$0.00 \$1,320.00	Estimate Item Adjustment (0006) due to user marshp3 overridding Payment
	0970	PILE POINT REINFORCEMENT		ıl - Total		2021 Aug 16,		\$0.00 \$0.00 \$1,320.00 (\$1,320.00) \$0.00	Estimate Item Adjustment (0006) due to user marshp3 overridding Payment
	0970	PILE POINT REINFORCEMENT	Material Material - Tota	ıl - Total	4	2021 Aug 16, 2021	SYSTEM	\$0.00 \$0.00 \$1,320.00 (\$1,320.00) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user marshp3 overridding Payment
	0970	PILE POINT REINFORCEMENT	Material	ıl - Total	4	2021 Aug 16, 2021 Aug 16, 2021	SYSTEM	\$0.00 \$0.00 \$1,320.00 (\$1,320.00) \$0.00 \$0.00 (\$14,705.00)	Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 13 on the current Payment Estimate.
	0970	PILE POINT REINFORCEMENT Total CLASS B CONCRETE	Material Material - Tota	ıl - Total	4	2021 Aug 16, 2021	SYSTEM	\$0.00 \$0.00 \$1,320.00 (\$1,320.00) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user marshp3 overridding Payment
	0970	PILE POINT REINFORCEMENT Total CLASS B CONCRETE	Material Material - Tota	ıl - Total	4	Aug 16, 2021 Aug 16, 2021 Sep 1,	SYSTEM	\$0.00 \$0.00 \$1,320.00 (\$1,320.00) \$0.00 \$0.00 (\$14,705.00)	Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user marshp3 overridding Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3386	0980	CLASS B	Material						Estimate Exception 17 on the current Payment Estimate.
		CONCRETE (SUBSTRUCTURE)			6	Sep 17, 2021	SYSTEM	(\$70,040.00)	
					7	Oct 1, 2021	SYSTEM	\$70,040.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Oct 1, 2021	SYSTEM	(\$70,040.00)	Estimate Estapaton III on the standard application and the standard applic
					8	Oct 15, 2021	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user marshp3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Oct 15, 2021	SYSTEM	(\$70,635.00)	
					9	Nov 2, 2021	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user marshp3 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$70,635.00)	
					10	Nov 16, 2021	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user marshp3 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$70,635.00)	
					11	Dec 2, 2021	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user marshp3 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$70,635.00)	
					12	Dec 16, 2021	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user caseyj overridding Payment Estimate Exception 34 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$70,635.00)	
					13	Jan 3, 2022	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kennec2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$70,635.00)	
					14	Feb 1, 2022	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$70,635.00)	
					15	Mar 16, 2022	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$70,635.00)	
					16	May 2, 2022	SYSTEM	\$70,635.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user kennec2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$70,635.00)	
				- Total				(\$14,705.00)	
			Material - Tota				a.v.=	(\$14,705.00)	
			MaterialCredit		5	Sep 1, 2021	SYSTEM	\$14,705.00	
				- Total				\$14,705.00	
			MaterialCredit	- Total				\$14,705.00	
	0980 -	Total						\$0.00	
	0990	TYPE D BARRIER	Material		9	Nov 2, 2021	SYSTEM	\$54,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user marshp3 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$54,575.00)	
					10	Nov 16,	SYSTEM	\$74,555.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	0990	TYPE D BARRIER	Material			2021			Estimate Item Adjustment (0011) due to user marshp3 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$74,555.00)	
					11	Dec 2, 2021	SYSTEM	\$74,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user marshp3 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$74,555.00)	
					12	Dec 16, 2021	SYSTEM	\$74,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user caseyj overridding Payment Estimate Exception 36 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$74,555.00)	
					13	Jan 3, 2022	SYSTEM	\$74,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user kennec2 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$74,555.00)	
					14	Feb 1, 2022	SYSTEM	\$74,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$74,555.00)	
					15	Mar 16, 2022	SYSTEM	\$74,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$74,555.00)	
					16	May 2, 2022	SYSTEM	\$74,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user kennec2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$74,555.00)	
				- Total				\$0.00	
	nggn	· Total	Material - Tota	ıl				\$0.00 \$0.00	
	1000	SLAB ON CONCRETE BEAM	Material		8	Oct 15, 2021	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Oct 15, 2021	SYSTEM	(\$339,200.00)	
					9	Nov 2, 2021	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$339,200.00)	
					10	Nov 16, 2021	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user marshp3 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$339,200.00)	
					11	Dec 2, 2021	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user marshp3 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$339,200.00)	
					12	Dec 16, 2021	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user caseyj overridding Payment Estimate Exception 39 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$339,200.00)	
					13	Jan 3, 2022	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user kennec2 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$339,200.00)	



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3386 1	1000	SLAB ON CONCRETE BEAM	Material		14	Feb 1, 2022	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$339,200.00)	
					15	Mar 16, 2022	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$339,200.00)	
					16	May 2, 2022	SYSTEM	\$339,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user kennec2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$339,200.00)	
				- Total				\$0.00	
			Material - Tota	l .				\$0.00	
	1000 -							\$0.00	
1	1010	SIDEWALK (BRIDGES)	Material		9	Nov 2, 2021	SYSTEM	\$18,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user marshp3 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$18,720.00)	
					10	Nov 16, 2021	SYSTEM	\$18,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user marshp3 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$18,720.00)	
					11	Dec 2, 2021	SYSTEM	\$18,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user marshp3 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$18,720.00)	
					12	Dec 16, 2021	SYSTEM	\$20,865.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user caseyj overridding Payment Estimate Exception 42 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$20,865.00)	
					13	Jan 3, 2022	SYSTEM	\$20,865.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user kennec2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$20,865.00)	
					14	Feb 1, 2022	SYSTEM	\$20,865.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$20,865.00)	
					15	Mar 16, 2022	SYSTEM	\$20,865.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$20,865.00)	
					16	May 2, 2022	SYSTEM	\$20,865.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user kennec2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$20,865.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1010 -	Total						\$0.00	
1	1020	FORM LINERS	Material		9	Nov 2, 2021	SYSTEM	\$3,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user marshp3 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$3,540.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	1020	FORM LINERS	Material		10	Nov 16, 2021	SYSTEM	\$4,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user marshp3 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$4,720.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1020 -	Total						\$0.00	
	1030	33 IN., PRESTRESSED CONC SPREAD	Material		6	Sep 17, 2021	SYSTEM	\$386,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user marshp3 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		BOX BM			6	Sep 17, 2021	SYSTEM	(\$386,750.00)	
					7	Oct 1, 2021	SYSTEM	\$386,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Oct 1, 2021	SYSTEM	(\$386,750.00)	
					8	Oct 15, 2021	SYSTEM	\$386,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Oct 15, 2021	SYSTEM	(\$386,750.00)	
					9	Nov 2, 2021	SYSTEM	\$386,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user marshp3 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$386,750.00)	
					10	Nov 16, 2021	SYSTEM	\$386,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user marshp3 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$386,750.00)	
					11	Dec 2, 2021	SYSTEM	\$386,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user marshp3 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$386,750.00)	
					12	Dec 16, 2021	SYSTEM	\$386,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user caseyj overridding Payment Estimate Exception 45 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$386,750.00)	
					13	Jan 3, 2022	SYSTEM	\$386,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user kennec2 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$386,750.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1030 -	Total						\$0.00	
	1050	REINFORCING STEEL (EPOXY COATED)	Material		4	Aug 16, 2021	SYSTEM	\$2,963.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user marshp3 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$2,963.14)	
					5	Sep 1, 2021	SYSTEM	\$7,682.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user marshp3 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					5	Sep 1, 2021	SYSTEM	(\$7,682.26)	
					6	Sep 17, 2021	SYSTEM	\$14,106.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user marshp3 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Sep 17, 2021	SYSTEM	(\$14,106.86)	



SERVICEORING Material	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2021 8	J4S3386	1050	STEEL (EPOXY	Material		7		SYSTEM	\$14,106.86	Estimate Item Adjustment (0007) due to user marshp3 overridding Payment
2021 SYSTEM SZ-0, 67-007 SYSTEM SZ-0, 68-007						7		SYSTEM	(\$14,106.86)	
100 Total						8		SYSTEM	\$25,987.92	Estimate Item Adjustment (0007) due to user marshp3 overridding Payment
2021 Estimate Item Adjustment (DOTs) use to user manatys overridding Payment Estimate Exception 47 on the current Payment Estimate Payment Estimate Exception 67 on the current Payment Estimate Payment Estimate Exception 67 on the current Payment Estimate Payment Estimate Estimate Item Adjustment (DOTs) due to user manatys overridding Payment Estimate Exception 55 on the current Payment Estimate Exception 50 on the current Payment Estimate Estima						8		SYSTEM	(\$25,987.92)	
10						9		SYSTEM	\$28,148.00	Estimate Item Adjustment (0013) due to user marshp3 overridding Payment
2021 Estimable Enception 43 on the outer maniph3 overridding Payment Estimable Exception 43 on the outered Payment Estimable (2021) 2021						9		SYSTEM	(\$28,148.00)	
10						10		SYSTEM	\$28,148.00	Estimate Item Adjustment (0016) due to user marshp3 overridding Payment
11						10		SYSTEM	(\$28,148.00)	
1050 - Total 1050						11	Dec 2,	SYSTEM	\$28,148.00	Estimate Item Adjustment (0020) due to user marshp3 overridding Payment
1950 - Total						11		SYSTEM	(\$28,148.00)	
1050 VERTICAL DRAIN Material 8					- Total				\$0.00	
1060 VERTICAL DRAIN Material				Material - Tota					\$0.00	
AT END BENTS		1050 -	Total						\$0.00	
2021 9		1060		Material		8		SYSTEM	\$1,750.00	Estimate Item Adjustment (0008) due to user marshp3 overridding Payment
2021 SySTEM Estimate Item Adjustment (0014) due to user marshp3 overridding Payment Estimate Exception 52 on the current Payment Estimate.						8		SYSTEM	(\$1,750.00)	
2021						9		SYSTEM	\$3,500.00	Estimate Item Adjustment (0014) due to user marshp3 overridding Payment
Estimate Item Adjustment (0017) due to user marshp3 overridding Payment Estimate Exception 53 on the current Payment Estimate. 10 Nov 16, 2021 11 Dec 2, SYSTEM \$3,500.00 2021 11 Dec 2, SYSTEM \$3,500.00 2021 11 Dec 2, SYSTEM \$3,500.00 2021 2						9		SYSTEM	(\$3,500.00)	
2021 11						10		SYSTEM	\$3,500.00	Estimate Item Adjustment (0017) due to user marshp3 overridding Payment
2021 Estimate Item Adjustment (0021) due to user marshp3 overridding Payment Estimate Exception 60 on the current Payment Estimate.						10		SYSTEM	(\$3,500.00)	
Total S0.00						11		SYSTEM	\$3,500.00	Estimate Item Adjustment (0021) due to user marshp3 overridding Payment
Material - Total \$0.00						11		SYSTEM	(\$3,500.00)	
This adjustment offsets the original system-generated Material Payment Estimate Exception 24 on the current Payment Estimate Estimate Item Adjustment (0008) due to user marshp3 overridding Payment Estimate Exception 24 on the current Payment Estimate Exception 24 on the current Payment Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Exception 30 on the current Payment Estimate. A					- Total				\$0.00	
This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user marshp3 overridding Payment Estimate Exception 24 on the current Payment Estimate Exception 24 on the current Payment Estimate. 7 Oct 1, 2021 8 Oct 15, 2021 8 Oct 15, 2021 8 Oct 15, 2021 9 Nov 2, 2021 9 Nov 2, 2021 9 Nov 2, 2021 1 SYSTEM \$1,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate. 8 This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate. 8 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user marshp3 overridding Payment				Material - Tota	1				\$0.00	
MASONRY PROTECTION SYSTEM 2021 Cot 1, 2021 8 Oct 15, 2021 SYSTEM 1,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate. 8 Oct 15, 2021 9 Nov 2, SYSTEM \$1,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate. 8 Doct 15, 2021 9 Nov 2, SYSTEM \$1,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 30 on the current Payment Estimate.		1060 -	Total						\$0.00	
7 Oct 1, 2021 SYSTEM (\$1,656.00) 8 Oct 15, 2021 SYSTEM \$1,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Exception 30 on the current Payment Estimate. 8 Oct 15, 2021 SYSTEM (\$1,656.00) 9 Nov 2, SYSTEM \$1,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user marshp3 overridding Payment		1100	MASONRY PROTECTION	Material		7		SYSTEM	\$1,656.00	Estimate Item Adjustment (0008) due to user marshp3 overridding Payment
2021 Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Exception 30 on the current Payment Estimate. 8 Oct 15, 2021 9 Nov 2, SYSTEM \$1,656.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user marshp3 overridding Payment			SISIEM			7		SYSTEM	(\$1,656.00)	
9 Nov 2, SYSTEM \$1,656.00 This adjustment offsets the original system-generated Material Payment 2021 Estimate Item Adjustment (0015) due to user marshp3 overridding Payment						8		SYSTEM	\$1,656.00	Estimate Item Adjustment (0009) due to user marshp3 overridding Payment
2021 Estimate Item Adjustment (0015) due to user marshp3 overridding Payment						8		SYSTEM	(\$1,656.00)	
						9		SYSTEM	\$1,656.00	Estimate Item Adjustment (0015) due to user marshp3 overridding Payment
9 Nov 2, 2021 (\$1,656.00)						9		SYSTEM	(\$1,656.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4S3386	1100	CONCRETE AND MASONRY PROTECTION SYSTEM	Material		10	Nov 16, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user marshp3 overridding Payment Estimate Exception 51 on the current Payment Estimate.													
					10	Nov 16, 2021	SYSTEM	(\$1,656.00)														
					11	Dec 2, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user marshp3 overridding Payment Estimate Exception 58 on the current Payment Estimate.													
					11	Dec 2, 2021	SYSTEM	(\$1,656.00)														
				- Total				\$0.00														
			Material - Tota	ı				\$0.00														
	1100 -	Total						\$0.00														
	1120	MECHANICALLY STABILIZED EARTH WALL SYS	Material		3	Aug 2, 2021	SYSTEM	\$106,029.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user marshp3 overridding Payment Estimate Exception 14 on the current Payment Estimate.													
					3	Aug 2, 2021	SYSTEM	(\$106,029.00)														
					4	Aug 16, 2021	SYSTEM	\$106,029.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user marshp3 overridding Payment Estimate Exception 21 on the current Payment Estimate.													
					4	Aug 16, 2021	SYSTEM	(\$106,029.00)														
					5	Sep 1, 2021	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user marshp3 overridding Payment Estimate Exception 26 on the current Payment Estimate.													
					5	Sep 1, 2021	SYSTEM	(\$117,810.00)														
								6	Sep 17, 2021	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user marshp3 overridding Payment Estimate Exception 24 on the current Payment Estimate.										
					6	Sep 17, 2021	SYSTEM	(\$117,810.00)														
					7	Oct 1, 2021	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user marshp3 overridding Payment Estimate Exception 26 on the current Payment Estimate.													
					7	Oct 1, 2021	SYSTEM	(\$117,810.00)														
					8	Oct 15, 2021	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user marshp3 overridding Payment Estimate Exception 33 on the current Payment Estimate.													
					8	Oct 15, 2021	SYSTEM	(\$117,810.00)														
							9	Nov 2, 2021	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user marshp3 overridding Payment Estimate Exception 53 on the current Payment Estimate.											
									9	Nov 2, 2021	SYSTEM	(\$117,810.00)										
																10	Nov 16, 2021	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user marshp3 overridding Payment Estimate Exception 54 on the current Payment Estimate.		
																		10	Nov 16, 2021	SYSTEM	(\$117,810.00)	
																11	Dec 2, 2021	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user marshp3 overridding Payment Estimate Exception 61 on the current Payment Estimate.		
					11	Dec 2, 2021	SYSTEM	(\$117,810.00)														
					12	Dec 16, 2021	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user caseyj overridding Payment Estimate Exception 46 on the current Payment Estimate.													
					12	Dec 16, 2021	SYSTEM	(\$117,810.00)														
					13	Jan 3, 2022	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user kennec2 overridding Payment Estimate Exception 39 on the current Payment Estimate.													
					13	Jan 3, 2022	SYSTEM	(\$117,810.00)														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J4S3386	1120	MECHANICALLY STABILIZED EARTH WALL SYS	Material		14	Feb 1, 2022	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 39 on the current Payment Estimate.					
					14	Feb 1, 2022	SYSTEM	(\$117,810.00)						
					15	Mar 16, 2022	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user kennec2 overridding Payment Estimate Exception 25 on the current Payment Estimate.					
					15	Mar 16, 2022	SYSTEM	(\$117,810.00)						
					16	May 2, 2022	SYSTEM	\$117,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user kennec2 overridding Payment Estimate Exception 17 on the current Payment Estimate.					
					16	May 2, 2022	SYSTEM	(\$117,810.00)						
				- Total				\$0.00						
			Material - Total					\$0.00						
	1120 -	· Total						\$0.00						
	1130	CONCRETE AND MASONRY PROTECTION SYSTEM	Material		7	Oct 1, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user marshp3 overridding Payment Estimate Exception 25 on the current Payment Estimate.					
					7	Oct 1, 2021	SYSTEM	(\$1,656.00)						
					8	Oct 15, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user marshp3 overridding Payment Estimate Exception 31 on the current Payment Estimate.					
					8	Oct 15, 2021	SYSTEM	(\$1,656.00)						
					9	Nov 2, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user marshp3 overridding Payment Estimate Exception 51 on the current Payment Estimate.					
					9	Nov 2, 2021	SYSTEM	(\$1,656.00)						
					10	Nov 16, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user marshp3 overridding Payment Estimate Exception 52 on the current Payment Estimate.					
					10	Nov 16, 2021	SYSTEM	(\$1,656.00)						
					11	Dec 2, 2021	SYSTEM	\$1,656.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user marshp3 overridding Payment Estimate Exception 59 on the current Payment Estimate.					
					11	Dec 2, 2021	SYSTEM	(\$1,656.00)						
				- Total				\$0.00						
			Material - Tota	ıl				\$0.00						
	1130 -	· Total						\$0.00						
	1150	MECHANICALLY STABILIZED EARTH WALL SYS	Material	Material	Material	Material	Material	Material	3	Aug 2, 2021	SYSTEM	\$104,026.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user marshp3 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
						3	Aug 2, 2021	SYSTEM	(\$104,026.23)					
										4	Aug 16, 2021	SYSTEM	\$104,026.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user marshp3 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					4	Aug 16, 2021	SYSTEM	(\$104,026.23)						
					5	Sep 1, 2021	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user marshp3 overridding Payment Estimate Exception 28 on the current Payment Estimate.					
					5	Sep 1, 2021	SYSTEM	(\$115,584.70)						
					6	Sep 17, 2021	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user marshp3 overridding Payment Estimate Exception 26 on the current Payment Estimate.					
					6	Sep 17, 2021	SYSTEM	(\$115,584.70)						



1	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
6 1	1150	MECHANICALLY STABILIZED EARTH WALL SYS	Material		7	Oct 1, 2021	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user marshp3 overridding Paymer Estimate Exception 28 on the current Payment Estimate.
					7	Oct 1, 2021	SYSTEM	(\$115,584.70)	
					8	Oct 15, 2021	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user marshp3 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					8	Oct 15, 2021	SYSTEM	(\$115,584.70)	
					9	Nov 2, 2021	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user marshp3 overridding Payme Estimate Exception 55 on the current Payment Estimate.
					9	Nov 2, 2021	SYSTEM	(\$115,584.70)	
					10	Nov 16, 2021	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user marshp3 overridding Payme Estimate Exception 56 on the current Payment Estimate.
					10	Nov 16, 2021	SYSTEM	(\$115,584.70)	
					11	Dec 2, 2021	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user marshp3 overridding Payme Estimate Exception 63 on the current Payment Estimate.
					11	Dec 2, 2021	SYSTEM	(\$115,584.70)	
					12	Dec 16, 2021	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user caseyj overridding Payment Estimate Exception 48 on the current Payment Estimate.
					12	Dec 16, 2021	SYSTEM	(\$115,584.70)	
					13	Jan 3, 2022	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user kennec2 overridding Payme Estimate Exception 41 on the current Payment Estimate.
					13	Jan 3, 2022	SYSTEM	(\$115,584.70)	
							14	Feb 1, 2022	SYSTEM
					14	Feb 1, 2022	SYSTEM	(\$115,584.70)	
					15	Mar 16, 2022	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user kennec2 overridding Payme Estimate Exception 26 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$115,584.70)	
					16	May 2, 2022	SYSTEM	\$115,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user kennec2 overridding Payme Estimate Exception 18 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$115,584.70)	
				- Total				\$0.00	
	1150	Total	Material - Tota					\$0.00 \$0.00	
	5002		Material		14	Feb 1, 2022	SYSTEM	\$0.00 \$798.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user kennec2 overridding Payme Estimate Exception 41 on the current Payment Estimate.
					14	Feb 1, 2022	SYSTEM	(\$798.61)	Exemple Execution 41 on the current rayment Estimate.
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
5	5002 -	Total						\$0.00	
5	5003	CURB INLET	Material		14	Feb 1, 2022	SYSTEM	\$6,665.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kennec2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					14	Feb 1,	SYSTEM	(\$6,665.12)	

May 5, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3386	5003	CURB INLET	Material		15	Mar 16, 2022	SYSTEM	\$6,665.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user kennec2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$6,665.12)	
					16	May 2, 2022	SYSTEM	\$6,665.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user kennec2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$6,665.12)	
				- Total				\$0.00	
	Material - Total							\$0.00	
5003 - Total								\$0.00	
J4S3386 - Total									
Overall - Total									