

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 16, 2022

| Progress Estimate Number | Contract ID | 210319-F07 | Pay Period Start | February 2, 2022 | Original Contract Amount | \$2,956,107.23 |
|-----------------------------|---------------------|-----------------------------------|---------------------|------------------|---|-------------------------------|
| 19 | Prime Contractor | Gershenson Construction Co., Inc. | Pay Period End | 2022 | Net Change Order Amount Current Contract Amount | \$13,729.09 \$2,969,836.32 |

| Approval Date | | By User |
|-------------------|--|---------|
| February 16, 2022 | Generated and Approved (and should be considered Draft) at the Project Office Level by | sandeb2 |
| February 16, 2022 | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | lewisj1 |
| February 17, 2022 | Reviewed and Approved at the Central Office Controllers Office Level by | ramses1 |

| Original Completion Date | · | | % of Current Contract Amount Complete |
|--------------------------|--------------|--|---------------------------------------|
| June 1, 2022 | June 1, 2022 | | 72.85% |

| | Milestones | | |
|------------------------|--------------------------|--------------------------------|----------------------------------|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract |
| Acceptance Date | | | |
| Awarded Date | April 7, 2021 | April 7, 2021 | |
| Letting Date | March 19, 2021 | March 19, 2021 | |
| Notice to Proceed Date | May 10, 2021 | May 10, 2021 | |
| Work Began Date | | | |

| Contract Total Pay For Estimate No. 19 | | | | | | | | | | |
|--|----------------------------|---------------|----------------|----------------|--|--|--|--|--|--|
| | | This Estimate | Previous | To Date | | | | | | |
| 210319-F07 | | | | | | | | | | |
| | Total Posted Items Pay | \$141,734.17 | \$2,021,784.90 | \$2,163,519.07 | | | | | | |
| | Gross Item Adjustments | \$1,149.07 | \$12,178.00 | \$13,327.07 | | | | | | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | | | | | | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | | | | | | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | | | | | | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | | | | | | |
| | • | | \$2,033,962.90 | \$2,176,846.14 | | | | | | |
| Contract Total Page 1 | avable This Estimate | \$142 883 24 | | | | | | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount |
|-------------------|----------------|--------------|--|------|------------|--------------------------|-----------------------------|
| J6S3408 | 0140 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | SQYD | \$10.000 | 2,028 | \$20,280.00 |
| | 0150 | 3049905 | MISC.RIGID GEOGRID TO ENHANCE AGGREGATE OR ROCK BASE | SQYD | \$3.250 | 2,028 | \$6,591.00 |
| | 0240 | 5021309 | CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS) | SQYD | \$54.000 | 2,028 | \$109,512.00 |
| | 0700 | 6240104A | SEPARATION GEOTEXTILE | SQYD | \$2.000 | 2,028 | \$4,056.00 |
| | 1020 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | CUYD | \$631.370 | 0.49 | \$309.37 |
| | 1050 | 9031220 | PIPE POSTS | LB | \$3.180 | 310 | \$985.80 |
| Project ISS3 | 400 Total | | | | | | \$1.41.73.4.17 |

 Project J6S3408 - Total
 \$141,734.17

 Overall - Total
 \$141,734.17

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

| Line Item | Adjust | ments This Estimate | | | | | | |
|-------------------|-------------|--|--------------------|----------------------------------|--|------------------------|---------------------------------------|-------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J6S3408 | 0140 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 2,028 | \$0.08 | \$158.59 |
| | 0240 | CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS) | Price | | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | 2,028 | \$0.49 | \$990.48 |
| | 0250 | MISC. | Material | | | -53.7 | \$105.00 | (\$5,638.50) |

Revision 4/1/2020 Page 1 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 16, 2022

Progress Estimate Number
19 Contract ID 210319-F07 Pay Period Start February 2, 2022 Original Contract Amount \$2,956,107.23
Prime Contractor Inc. Pay Period End February 15, 2022 Net Change Order Amount \$13,729.09
Current Contract Amount \$2,969,836.32

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment | Comments | Adjustment Quantity | Line Item Adjustment | Adjustment amount |
|-------------------|-------------|---|--------------------|--------------------------|--|------------------------|-------------------------|-------------------|
| J6S3408 | 0250 | MISC. | Material | Туре | This adjustment offsets the original system- | 53.7 | Unit Price \$105.00 | \$5,638.50 |
| | | | | | generated Material Payment Estimate Item Adjustment (0003) due to user sandeb2 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | ******* | **,***** |
| | 0430 | MISC. | Overrun | | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). | -0.4 | \$30.00 | (\$12.00 |
| | 0430 | MISC. | Material | | | -129.4 | \$30.00 | (\$3,882.00) |
| | 0430 | MISC. | Overrun | | This adjustment offsets the original system- generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40. | 0.4 | \$30.00 | \$12.00 |
| | 0430 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user sandeb2 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 129.4 | \$30.00 | \$3,882.00 |
| | 0740 | MECHANICALLY STABILIZED EARTH WALL SYSTEMS | Material | | | -2,393 | \$65.00 | (\$155,545.00) |
| (| 0740 | MECHANICALLY STABILIZED EARTH WALL SYSTEMS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user sandeb2 overridding Payment Estimate Exception 7 on the current Payment Estimate. | 2,393 | \$65.00 | \$155,545.00 |
| | 0920 | LUMINAIRE, LED-A | Material | | | -15 | \$400.00 | (\$6,000.00) |
| | 0920 | LUMINAIRE, LED-A | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user sandeb2 overridding Payment Estimate Exception 9 on the current Payment Estimate. | 15 | \$400.00 | \$6,000.00 |
| | 0980 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | Material | | | -1,080 | \$0.50 | (\$540.00) |
| | 0980 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user sandeb2 overridding Payment Estimate Exception 10 on the current Payment Estimate. | 1,080 | \$0.50 | \$540.00 |
| | 1010 | MISC. | Material | | | -1 | \$8,840.00 | (\$8,840.00) |
| | 1010 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user sandeb2 overridding Payment Estimate Exception 11 on the current Payment Estimate. | 1 | \$8,840.00 | \$8,840.00 |
| | 1020 | CONCRETE FOOTINGS, EMBEDDED | Material | | | -3 | \$631.37 | (\$1,894.11) |
| | 1020 | CONCRETE FOOTINGS, EMBEDDED | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user sandeb2 overridding Payment Estimate Exception 12 on the current Payment Estimate. | 3 | \$631.37 | \$1,894.11 |
| | 1070 | SH-FLAT SHEET | Material | | | -30.2 | \$23.74 | (\$716.95) |
| | 1070 | SH-FLAT SHEET | Material | | This adjustment offsets the original system- | 30.2 | \$23.74 | \$716.95 |

Revision 4/1/2020 Page 2 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: February 16, 2022

Progress Estimate Number 19
Contract ID 210319-F07 Start February 2, 2022 Original Contract Amount \$2,956,107.23
Prime Gershenson Construction Co., Inc.
Pay Period Start February 15, Net Change Order Amount \$13,729.09
Contractor Start February 15, 2022 Original Contract Amount \$2,956,107.23
Current Contract Amount \$2,956,307.23

| | Current Contract Amount \$2,909,650.52 | | | | | | | | | | |
|-------------------|--|--------------------------------|--------------------|----------------------------------|--|------------------------|---------------------------------------|----------------------|--|--|--|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount | | | |
| J6S3408 | | | | | generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Exception 13 on the current Payment Estimate. | | | | | | |
| | 1080 | ST-STRUCTURAL | Material | | | -360 | \$17.59 | (\$6,332.40) | | | |
| | 1080 | ST-STRUCTURAL | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user sandeb2 overridding Payment Estimate Exception 14 on the current Payment Estimate. | 360 | \$17.59 | \$6,332.40 | | | |
| | 1090 | SHF-FLAT SHEET FLUORESCENT | Material | | | -32 | \$24.41 | (\$781.12) | | | |
| | 1090 | SHF-FLAT SHEET FLUORESCENT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user sandeb2 overridding Payment Estimate Exception 15 on the current Payment Estimate. | 32 | \$24.41 | \$781.12 | | | |
| | 5001 | CONDUIT SYSTEM ON STRUCTURE | Material | | | -1 | \$4,872.00 | (\$4,872.00) | | | |
| | 5001 | CONDUIT SYSTEM ON STRUCTURE | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user sandeb2 overridding Payment Estimate Exception 3 on the current Payment Estimate. | 1 | \$4,872.00 | \$4,872.00 | | | |
| Total | | | | | | | | \$1,149.07 | | | |

Revision 4/1/2020 Page 3 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | Contract Project Information | | | | | | | | | | |
|-------------------|------------------------------|---------------------------|----------|---------------|--|--|--|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | Location of Work | | | | | | |
| J6S3408 | FAS S502(17) | Intersection improvements | OR 70 | ST CHARLES | at the intersection of Lake St. Louis, Veterans Memorial Parkway, and I-70 eastbound ramps | | | | | | |

| Totals by Job Numbers | Standard By Job Numbers | Totals By Job Numbers | Standard By Job Numbers | Stan

Revision 4/1/2020 Page 4 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions / Discrepencies | Explanation | Entered By | Status |
|--|--|---------------|--------------|
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 5029905, Project Item Line Number 0250, Material Set 502990596, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient. | Working with materials to approved PAL | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 6099903, Project Item Line Number 0430, Material Set 609990396, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient. | Waiting for 28 day cylinder maturity | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7071000, Project Item Line Number 5001, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. | Working with materials for acceptance material code MC1062JBHL | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7071000, Project Item Line Number 5001, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient. | Working with materials for acceptance of material code 1060EC | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7071000, Project Item Line Number 5002, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient. | Working with materials for acceptance material code MC1062JBHL | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7071000, Project Item Line Number 5002, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient. | Working with materials for acceptance of material code 1060EC | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7201000, Project Item Line Number 0740, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient. | Working with Bridge division to approve MSE Wall design | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7201000, Project Item Line Number 0740, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient. | Working with materials to accept select granular fill | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9011311, Project Item Line Number 0920, Material Set 9011311, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. | Working with materials for approval of material code 0901LHXX | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9017110, Project Item Line Number 0980, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. | Working with materials for sufficient certification for material code 0901LHXX | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9019902, Project Item Line Number 1010, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient. | Working with materials for sufficient certification for material code 0901LHXX | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9031010, Project Item Line Number 1020, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. | Waiting for 28 day maturity | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9035004A, Project Item Line Number 1070, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient. | Working with materials to resolve testing requirement | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9035011A, Project Item Line Number 1080, Material Set 9035011A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient. | Working with materials for acceptance of material 1042SM | sandeb2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9035069A, Project Item Line Number 1090, Material Set 9035069A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient. | Working with materials for acceptance | sandeb2 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 210319-F07, Contract Project J6S3408, Project Item Line Number 0430, Contract Line Item Number 0430, Item 6099903, Minor Item. | No Remark was entered by Engineer | sandeb2 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 210319-F07, Contract Project J6S3408, Project Item Line Number 0930, Contract Line Item Number 0930, Item 9013003, Minor Item. | Working on change order | sandeb2 | Acknowledged |

Revision 4/1/2020 Page 5 of 33



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 210319-F07 | J6S3408 | 0001 | 0010 | 1041000 | TEMPORARY SURFACING | 235.00 | 0.00 | 235.00 | CUYD | 18.00 | \$5.00 | \$90.00 |
| | | 0001 | 0020 | 2013000 | CLEARING AND GRUBBING | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$15,000.00 | \$15,000.00 |
| | | 0001 | 0030 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 0.95 | \$235,000.00 | \$223,250.00 |
| | | 0001 | 0040 | 2031000 | CLASS A EXCAVATION | 6,592.00 | 0.00 | 6,592.00 | CUYD | 6,385.00 | \$12.00 | \$76,620.00 |
| | | 0001 | 0050 | 2035500 | EMBANKMENT IN PLACE | 9,181.00 | 0.00 | 9,181.00 | CUYD | 3,437.00 | \$12.00 | \$41,244.00 |
| | | 0001 | 0060 | 2036000 | COMPACTING EMBANKMENT | 5,606.00 | 0.00 | 5,606.00 | CUYD | 5,389.00 | \$10.00 | \$53,890.00 |
| | | 0001 | 0070 | 2037075 | COMPACTING IN CUT | 23.60 | 0.00 | 23.60 | STA | 20.20 | \$100.00 | \$2,020.00 |
| | | 0001 | 0800 | 2039901 | MISC.UTILITY LOCATION VERIFICATION | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$10,000.00 | \$0.00 |
| | | 0001 | 0090 | 2063000 | CLASS 3 EXCAVATION | 132.00 | 0.00 | 132.00 | CUYD | 132.00 | \$30.00 | \$3,960.00 |
| | | 0001 | 0100 | 2072000 | LINEAR GRADING CLASS 2 | 9.30 | 0.00 | 9.30 | STA | 3.05 | \$1,200.00 | \$3,660.00 |
| | | 0001 | 0110 | 2169901 | MISC.REMOVE AND RESET FIRST BANK SIGN | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$12,000.00 | \$12,000.00 |
| | | 0001 | 0120 | 3040143 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | 686.00 | 0.00 | 686.00 | SQYD | 0.00 | \$7.00 | \$0.00 |
| | | 0001 | 0130 | 3040504 | TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) | 1,056.00 | 0.00 | 1,056.00 | SQYD | 422.70 | \$8.00 | \$3,381.60 |
| | | 0001 | 0140 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 14,772.00 | 0.00 | 14,772.00 | SQYD | 13,794.15 | \$10.00 | \$137,941.50 |
| | | 0001 | 0150 | 3049905 | MISC.RIGID GEOGRID TO ENHANCE AGGREGATE OR ROCK BASE | 14,771.50 | 0.00 | 14,771.50 | SQYD | 13,654.94 | \$3.25 | \$44,378.56 |
| | | 0001 | 0160 | 4010101 | 8 INCHES, BITUMINOUS PAVEMENT | 1,195.20 | -809.20 | 386.00 | SQYD | 385.99 | \$50.00 | \$19,299.50 |
| | | 0001 | 0170 | 4010150 | TYPE A2 SHOULDER | 2,115.70 | 0.00 | 2,115.70 | SQYD | 1,867.02 | \$40.00 | \$74,680.80 |
| | | 0001 | 0180 | 4019905 | MISC.OPTIONAL PAVEMENT | 5,100.50 | 0.00 | 5,100.50 | SQYD | 5,100.10 | \$54.00 | \$275,405.40 |
| | | 0001 | 0190 | 4030109 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX) | 95.00 | 0.00 | 95.00 | TONS | 0.00 | \$165.00 | \$0.00 |
| | | 0001 | 0200 | 4030306 | ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP250C MIX) | 45.40 | 0.00 | 45.40 | TONS | 0.00 | \$130.00 | \$0.00 |
| | | 0001 | 0210 | 4030308 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP250C MIX) | 23.70 | 0.00 | 23.70 | TONS | 0.00 | \$130.00 | \$0.00 |
| | | 0001 | 0220 | 4039905 | MISC.OPTIONAL TEMPORARY PAVEMENT | 1,055.90 | 0.00 | 1,055.90 | SQYD | 787.70 | \$44.52 | \$35,068.40 |
| | | 0001 | 0230 | 4071005 | TACK COAT | 100.00 | 0.00 | 100.00 | GAL | 0.00 | \$5.00 | \$0.00 |
| | | 0001 | 0240 | 5021309 | CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS) | 5,711.90 | 0.00 | 5,711.90 | SQYD | 5,709.78 | \$54.00 | \$308,328.12 |
| | | 0001 | 0250 | 5029905 | MISC.MODIFIED COLORED CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS) | 502.20 | 0.00 | 502.20 | SQYD | 53.70 | \$105.00 | \$5,638.50 |
| | | 0001 | 0260 | 6042020 | ADJUSTING BASIN OR INLET | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$500.00 | \$500.00 |
| | | 0001 | 0270 | 6049902 | MISC.ADJUSTING MANHOLES AND VALVES | 4.00 | 0.00 | 4.00 | EA | 3.00 | \$350.00 | \$1,050.00 |
| | | 0001 | 0280 | 6049902 | MISC.REMOVE AND REPLACE INLET STONE | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$700.00 | \$1,400.00 |
| | | 0001 | 0290 | 6071050 | CHAIN-LINK FENCE (RETAINING WALLS) | 240.00 | 0.00 | 240.00 | LF | 0.00 | \$31.57 | \$0.00 |
| | | 0001 | 0300 | 6081012 | TRUNCATED DOMES | 32.00 | 0.00 | 32.00 | SQFT | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 0310 | 6085008 | PAVED APPROACH, 8 IN. | 137.90 | 0.00 | 137.90 | SQYD | 137.90 | \$54.00 | \$7,446.60 |
| | | 0001 | 0320 | 6086004 | CONCRETE SIDEWALK, 4 IN. | 685.80 | 0.00 | 685.80 | SQYD | 0.00 | \$35.00 | \$0.00 |
| | | 0001 | 0330 | 6089902 | MISC.ADA CONCRETE CURB RAMP | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$1,600.00 | \$0.00 |
| | | 0001 | 0340 | 6089905 | MISC.MODIFIED COLORED 6" CONCRETE MEDIAN STRIP | 671.00 | 0.00 | 671.00 | SQYD | 0.00 | \$90.00 | \$0.00 |
| | | 0001 | 0350 | 6091010 | CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S | 620.00 | 0.00 | 620.00 | LF | 0.00 | \$30.00 | \$0.00 |
| | | 0001 | 0360 | 6091041 | CONCRETE GUTTER TYPE A | 85.00 | 0.00 | 85.00 | LF | 34.70 | \$101.00 | \$3,504.70 |
| | | 0001 | 0370 | 6091042 | CONCRETE GUTTER TYPE B | 237.00 | 0.00 | 237.00 | LF | 237.00 | \$50.00 | \$11,850.00 |
| | | 0001 | 0380 | 6091052 | CURB AND GUTTER TYPE B | 1,821.00 | 0.00 | 1,821.00 | LF | 1,478.60 | \$30.00 | \$44,358.00 |
| | | 0001 | 0390 | 6092011 | INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A | 122.00 | 0.00 | 122.00 | LF | 121.90 | \$17.00 | \$2,072.30 |
| | | 0001 | 0400 | 6092021 | INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A | 451.00 | 0.00 | 451.00 | LF | 0.00 | \$18.00 | \$0.00 |
| | | 0001 | 0410 | 6097000 | ROCK LINING | 24.00 | 0.00 | 24.00 | CUYD | 24.00 | \$70.00 | \$1,680.00 |
| | | 0001 | 0420 | 6099903 | MISC.MODIFIED CURB AND GUTTER TYPE A (1' GUTTER PAN) | 504.00 | 0.00 | 504.00 | LF | 0.00 | \$30.00 | \$0.00 |
| | | 0001 | 0430 | 6099903 | MISC.MODIFIED CURB AND GUTTER TYPE A (2.5' GUTTER PAN) | 129.00 | 0.00 | 129.00 | LF | 129.40 | \$30.00 | \$3,882.00 |
| | | 0001 | 0440 | 6141120 | CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM) | 5.00 | 0.00 | 5.00 | EA | 3.00 | \$800.00 | \$2,400.00 |
| | | 0001 | 0450 | 6143011 | MANHOLE FRAME AND COVER, TYPE 1-B | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$360.00 | \$360.00 |

Page 6 of 33 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| iote: Posted Q | uantities | and valu | es are t | pased on R | eport Generated date and can differ from the posted am | ount at the | time the | Estimate wa | is Gener | rated. | | |
|-------------------------|----------------|----------|-------------|--------------|---|-----------------|------------------------|------------------------------|----------|------------------------------------|--------------|--|
| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
| 210319-F07 | J6S3408 | 0001 | 0460 | 6161099 | CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 5.00 | 0.00 | 5.00 | EA | 4.00 | \$9,000.00 | \$36,000.00 |
| | | 0001 | 0470 | 6169901 | MISC.TEMPORARY TRAFFIC CONTROL | 1.00 | 0.00 | 1.00 | LS | 0.91 | \$40,000.00 | \$36,400.00 |
| | | 0001 | 0480 | 6169901 | MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$30,720.00 | \$30,720.00 |
| | | 0001 | 0490 | 6169902 | MISC.SPECIAL ST. CHARLES COUNTY ROAD BOARD SIGN, POSTS, AND INSTALLATION | 5.00 | 0.00 | 5.00 | EA | 4.00 | \$350.00 | \$1,400.00 |
| | | 0001 | 0500 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$205,000.00 | \$205,000.00 |
| | | 0001 | 0510 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | 7.00 | 0.00 | 7.00 | EA | 2.00 | \$600.00 | \$1,200.00 |
| | | 0001 | 0520 | 6200009 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE | 54.00 | 0.00 | 54.00 | LF | 0.00 | \$6.25 | \$0.00 |
| | | 0001 | 0530 | 6200012 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE | 90.00 | 0.00 | 90.00 | LF | 0.00 | \$12.50 | \$0.00 |
| | | 0001 | 0540 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 85.00 | 0.00 | 85.00 | LF | 0.00 | \$25.00 | \$0.00 |
| | | 0001 | 0550 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 14.00 | 0.00 | 14.00 | EA | 0.00 | \$350.00 | \$0.00 |
| | | 0001 | 0560 | 6200024 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | 9.00 | 0.00 | 9.00 | EA | 0.00 | \$300.00 | \$0.00 |
| | | 0001 | 0570 | 6200027 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$650.00 | \$0.00 |
| | | 0001 | 0580 | 6200036 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$200.00 | \$0.00 |
| | | 0001 | 0590 | 6200042 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES | 58.00 | 0.00 | 58.00 | EA | 0.00 | \$35.00 | \$0.00 |
| | | 0001 | 0600 | 6200045 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$1,200.00 | \$0.00 |
| | | 0001 | 0610 | 6200051 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$1,200.00 | \$0.00 |
| | | 0001 | 0620 | 6205901A | 4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 4,117.00 | 0.00 | 4,117.00 | LF | 0.00 | \$0.45 | \$0.00 |
| | | 0001 | 0630 | 6205902A | 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 7,867.00 | 0.00 | 7,867.00 | LF | 0.00 | \$0.45 | \$0.00 |
| | | 0001 | 0640 | 6205903A | 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 2,210.00 | 0.00 | 2,210.00 | LF | 0.00 | \$0.45 | \$0.00 |
| | | 0001 | 0650 | 6207001 | PAVEMENT MARKING REMOVAL | 20,202.00 | 0.00 | 20,202.00 | LF | 5,871.00 | \$0.75 | \$4,403.25 |
| | | 0001 | 0660 | 6207002 | PAVEMENT MARKING REMOVAL (SYMBOLS) | 20.00 | 0.00 | 20.00 | EA | 11.00 | \$100.00 | \$1,100.00 |
| | | 0001 | 0670 | 6209903 | MISC."24 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS" | 115.00 | 0.00 | 115.00 | LF | 0.00 | \$10.00 | \$0.00 |
| | | 0001 | 0680 | 6209903 | MISC."24 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS" | 262.00 | 0.00 | 262.00 | LF | 0.00 | \$10.00 | \$0.00 |
| | | 0001 | 0690 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 869.00 | 0.00 | 869.00 | SQYD | 0.00 | \$4.00 | \$0.00 |
| | | 0001 | 0700 | 6240104A | SEPARATION GEOTEXTILE | 14,772.00 | 0.00 | 14,772.00 | SQYD | 13,819.00 | \$2.00 | \$27,638.00 |
| | | 0001 | 0710 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 0.55 | \$20,000.00 | \$11,000.00 |
| | | 0001 | 0720 | 7110300 | CONCRETE AND MASONRY PROTECTION SYSTEM | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,200.00 | \$0.00 |
| | | 0001 | 0730 | 7110400 | SACRIFICIAL GRAFFITI PROTECTION SYSTEM | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$3,200.00 | \$0.00 |
| | | 0001 | 0740 | 7201000 | MECHANICALLY STABILIZED EARTH WALL SYSTEMS | 2,393.00 | 0.00 | 2,393.00 | SQFT | 2,393.00 | \$65.00 | \$155,545.00 |
| | | 0001 | 0750 | 7261012 | 12 IN. PIPE GROUP A | 200.00 | 0.00 | 200.00 | LF | 200.00 | \$60.00 | \$12,000.00 |
| | | 0001 | 0760 | 7310048 | PRECAST CONCRETE MANHOLE - 48 IN. | 6.00 | 0.00 | 6.00 | FT | 6.00 | \$400.00 | \$2,400.00 |
| | | 0001 | 0770 | 7311022 | PRECAST CONCRETE DROP INLET 2 FT X 2 FT | 28.00 | 0.00 | 28.00 | FT | 28.00 | \$260.00 | \$7,280.00 |
| | | 0001 | 0780 | 7320612A | 12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$600.00 | \$600.00 |
| | | 0001 | 0790 | 8031000A | TURF TYPE TALL FESCUE SODDING | 5,958.00 | 0.00 | 5,958.00 | SQYD | 880.00 | \$6.00 | \$5,280.00 |
| | | 0001 | 0800 | 8051000A | SEEDING - COOL SEASON MIXTURES | 2.30 | 0.00 | 2.30 | ACRE | 0.98 | \$12,100.00 | \$11,858.00 |
| | | 0001 | 0810 | 8061005 | ROCK DITCH CHECK | 480.00 | 0.00 | 480.00 | LF | 186.00 | \$15.00 | \$2,790.00 |
| | | 0001 | 0820 | 8061007A | CURB INLET CHECK | 19.00 | 0.00 | 19.00 | EA | 1.00 | \$125.00 | \$125.00 |
| | | 0001 | 0830 | 8061016 | SEDIMENT REMOVAL | 98.00 | 0.00 | 98.00 | CUYD | 3.00 | \$20.00 | \$60.00 |
| | | 0001 | 0840 | 8061017 | TEMPORARY SEEDING AND MULCHING | 2.40 | 0.00 | 2.40 | ACRE | 0.00 | \$1,500.00 | \$0.00 |
| | | 0001 | 0850 | 8061019 | SILT FENCE | 4,027.00 | 0.00 | 4,027.00 | LF | 3,131.00 | \$2.85 | \$8,923.35 |
| | | 0010 | 0860 | 6061060 | MGS GUARDRAIL | 600.00 | 0.00 | 600.00 | LF | 275.00 | \$20.85 | \$5,733.75 |
| | | | | | MGS HEIGHT AND BLOCK TRANSITION | 4.00 | 0.00 | 4.00 | EA | 2.00 | \$768.21 | \$1,536.42 |

Page 7 of 33 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract n.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|------------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|-------------|--|
| 0319-F07 | J6S3408 | 0010 | 0880 | 6061080 | MGS END ANCHOR | 4.00 | 0.00 | 4.00 | EA | 1.00 | \$956.20 | \$956.20 |
| | | 0010 | 0890 | 6063014 | TYPE A CRASHWORTHY END TERMINAL (MASH) | 6.00 | 0.00 | 6.00 | EA | 1.00 | \$2,311.40 | \$2,311.40 |
| | | 0020 | 0900 | 9011030 | LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT | 15.00 | 0.00 | 15.00 | EA | 15.00 | \$2,176.00 | \$32,640.00 |
| | | 0020 | 0910 | 9011106 | BRACKET ARM, 6 FT. OR 1.8 M | 15.00 | 0.00 | 15.00 | EA | 15.00 | \$550.00 | \$8,250.0 |
| | | 0020 | 0920 | 9011311 | LUMINAIRE, LED-A | 15.00 | 0.00 | 15.00 | EA | 15.00 | \$400.00 | \$6,000.0 |
| | | 0020 | 0930 | 9013003 | CONDUIT, 3 IN. RIGID, IN TRENCH | 12.00 | 0.00 | 12.00 | LF | 128.00 | \$18.00 | \$2,304.0 |
| | | 0020 | 0940 | 9014003 | CONDUIT, 3 IN. RIGID, PUSHED | 340.00 | 0.00 | 340.00 | LF | 212.00 | \$22.00 | \$4,664.0 |
| | | 0020 | 0950 | 9015010 | TRENCHING TYPE I | 1,234.00 | 0.00 | 1,234.00 | LF | 1,234.00 | \$7.00 | \$8,638.0 |
| | | 0020 | 0960 | 9016110 | PULL BOX, PREFORMED CLASS 1 | 9.00 | 0.00 | 9.00 | EA | 9.00 | \$1,217.00 | \$10,953.0 |
| | | 0020 | 0970 | 9016112 | PULL BOX, PREFORMED CLASS 3 | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,470.00 | \$1,470.0 |
| | | 0020 | 0980 | 9017110 | CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET | 1,080.00 | 0.00 | 1,080.00 | LF | 1,080.00 | \$0.50 | \$540.0 |
| | | 0020 | 0990 | 9017407 | CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG | 1,930.00 | 0.00 | 1,930.00 | LF | 1,837.00 | \$3.00 | \$5,511.0 |
| | | 0020 | 1000 | 9018230 | POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT) | 15.00 | 0.00 | 15.00 | EA | 15.00 | \$990.00 | \$14,850.0 |
| | | 0020 | 1010 | 9019902 | MISC.240/480V MULTI-CIRCUIT PAD MOUNTED POWER SUPPLY | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$8,840.00 | \$8,840.0 |
| | | 0040 | 1020 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 12.29 | 0.00 | 12.29 | CUYD | 3.00 | \$631.37 | \$1,894.1 |
| | | 0040 | 1030 | 9031020 | CONCRETE FOOTINGS, BOLT DOWN | 20.00 | 0.00 | 20.00 | CUYD | 0.00 | \$1,762.49 | \$0.0 |
| | | 0040 | 1040 | 9031210 | STRUCTURAL STEEL POSTS | 1,842.00 | 0.00 | 1,842.00 | LB | 0.00 | \$3.88 | \$0.0 |
| | | 0040 | 1050 | 9031220 | PIPE POSTS | 6,920.00 | 0.00 | 6,920.00 | LB | 1,989.00 | \$3.18 | \$6,325.0 |
| | | 0040 | 1060 | 9031242 | 36 IN. SURFACE-MOUNT DELINEATOR POST | 12.00 | 0.00 | 12.00 | EA | 0.00 | \$76.10 | \$0.0 |
| | | 0040 | 1070 | 9035004A | SH-FLAT SHEET | 383.60 | 0.00 | 383.60 | SQFT | 30.20 | \$23.74 | \$716.9 |
| | | 0040 | 1080 | 9035011A | ST-STRUCTURAL | 753.00 | 0.00 | 753.00 | SQFT | 360.00 | \$17.59 | \$6,332.4 |
| | | 0040 | 1090 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 225.50 | 0.00 | 225.50 | SQFT | 32.00 | \$24.41 | \$781. |
| | | 0040 | 1100 | 9039901 | MISC.TUBULAR SUPPORT, TYPE S - 27718, 52 FT. (TWO TUBES) | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$43,008.45 | \$0.0 |
| | | 0040 | 1110 | 9039901 | MISC.TUBULAR SUPPORT, TYPE S - 27718, 55 FT. (TWO TUBES) | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$43,596.45 | \$0.0 |
| | | 0050 | 1120 | 8089901 | MISC.IRRIGATION SYSTEM | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$41,387.50 | \$0. |
| | | 0050 | 1130 | 8089901 | MISC.LANDSCAPE LIGHTING | 1.00 | 0.00 | 1.00 | LS | 0.00 | \$2,940.00 | \$0.0 |
| | | 0050 | 1140 | 8089902 | MISC.BLACK-EYED SUSAN | 106.00 | 0.00 | 106.00 | EA | 0.00 | \$45.00 | \$0.0 |
| | | 0050 | 1150 | 8089902 | MISC.JADE PILLAR BOXWOOD | 40.00 | 0.00 | 40.00 | EA | 0.00 | \$56.00 | \$0.0 |
| | | 0050 | 1160 | 8089902 | MISC.JAPANESE BARBERRY | 104.00 | 0.00 | 104.00 | EA | 0.00 | \$53.00 | \$0. |
| | | 0050 | 1170 | 8089902 | MISC.REDOSIER DOGWOOD | 24.00 | 0.00 | 24.00 | EA | 0.00 | \$53.00 | \$0.0 |
| | | 0050 | 1180 | 8089902 | MISC.SHAMROCK INKBERRY | 82.00 | 0.00 | 82.00 | EA | 0.00 | \$53.00 | \$0.0 |
| | | 0050 | 1190 | 8089902 | MISC.SPARTAN JUNIPER | 10.00 | 0.00 | 10.00 | EA | 0.00 | \$390.00 | \$0.0 |
| | | 0050 | 1200 | 8089902 | MISC.TUFTED HAIR GRASS | 104.00 | 0.00 | 104.00 | EA | 0.00 | \$14.00 | \$0.0 |
| | | 0050 | 1210 | 8089907 | MISC.SHREDDED HARDWOOD MULCH | 62.00 | 0.00 | 62.00 | CUYD | 0.00 | \$58.00 | \$0.0 |
| | | 0020 | 5001 | 7071000 | CONDUIT SYSTEM ON STRUCTURE | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$4,872.00 | \$4,872. |
| | | 0020 | 5002 | 7071000 | CONDUIT SYSTEM ON STRUCTURE | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$5,357.10 | \$5,357. |
| | | 0001 | 5003 | 5021307 | CONCRETE PAVEMENT (7 IN. NON-REINFORCED, 15 FT. JOINTS) | 0.00 | 809.20 | 809.20 | SQYD | 809.20 | \$50.00 | \$40,460. |
| | | 0001 | 5004 | 6191000 | PAVEMENT EDGE TREATMENT | 0.00 | 1,000.00 | 1,000.00 | LF | 1,000.00 | \$3.50 | \$3,500.0 |
| | Project J | 6S3408 - To | otal Value | Posted to D | late as of Report Generated Date | | | | | | | \$2,163,519.0 |
| 319-F07 Ove | rall - Total | Value Pos | ted to Da | te as of Repo | ort Generated Date | | | | | | | \$2,163,519.0 |

Page 8 of 33 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S3408

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | Quantity Posted | Units | Location | From Station/ Log Mile | Offset/ Distance | To Station/ Log Mile | Offset/ Distance | Comments |
|----------------|--------------|--|-------------|-------------------------|--------------------|-------|-----------------------------------|---------------------------------|---------------------|-------------------------------|---------------------|----------|
| 0140 | 3040506 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | 2/7/22 | 2/16/22 | 2,028.00 | SQYD | RAB, Circulatory Roadway Pavement | 00+00 LT | | 5+11 LT | | |
| 0150 | 3049905 | MISC. AGGREGATE FOR BASE | 2/7/22 | 2/16/22 | 2,028.00 | SQYD | RAB, Circulatory Roadway Pavement | 00+00 LT | | 5+11 LT | | |
| 0240 | 5021309 | CONCRETE PAVEMENT (9 IN. NON-REINFORCED, | 2/7/22 | 2/16/22 | 2,028.00 | SQYD | RAB, Circulatory Roadway Pavement | 0+00 LT | | 5+11 LT | | |
| 0700 | 6240104A | SEPARATION GEOTEXTILE | 2/7/22 | 2/16/22 | 2,028.00 | SQYD | RAB, Circulatory Roadway Pavement | 0+00 LT | | 5+11 LT | | |
| 1020 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 2/7/22 | 2/16/22 | 0.13 | CUYD | LSL BLVD south, sign No. 12 | 109+45 | | | | |
| | | | | 2/16/22 | 0.36 | CUYD | LSL BLVD south, sign No. 11 | 109+16 | | | | |
| 1050 | 9031220 | PIPE POSTS | 2/7/22 | 2/16/22 | 127.00 | LB | LSL BLVD south, sign No. 12 | 109+45 | | | | |
| | | | | 2/16/22 | 183.00 | LB | LSL BLVD south, sign No. 11 | 109+16 | | | | |

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 9 of 33



| 2 Jun 2 SYSTEM \$70.40 Reference tem Pice Adjustment type applied in FUEL \$2.00 \$ | Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---|---------|--------|-------------|--------------------|-----------------------------|----------------|-----------------|---------------|------------|---|
| Sep 16, SYSTEM Sep 50, SYSTEM Sep | 6S3408 | 0040 | | Price FUEL | | 2 | | SYSTEM | \$70.40 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| 10 | | | | | | 2 | | SYSTEM | \$44.24 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| 1 | | | | | | 9 | | SYSTEM | \$6.50 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| 1 | | | | | | 10 | | SYSTEM | \$1.95 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| 2021 15 20-e1 5 20-e | | | | | | 11 | | SYSTEM | \$19.15 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| Total | | | | | | 14 | | SYSTEM | \$5.81 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| Price FUEL - Total | | | | | | 15 | | SYSTEM | \$46.62 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| 11 Oct 18 SYSTEM S189.34 Reference item Price Adjustment index Adjustment Type applied is PUEL 14 Dec. 2 SYSTEM S72.35 Reference item Price Adjustment index Adjustment Type applied is PUEL 20/21 SYSTEM S246.81 Reference item Price Adjustment index Adjustment Type applied is PUEL Total S509.53 SOS SO | | | | | - Total | | | | \$194.67 | |
| System 1 | | | | Price FUEL - | Total | | | | \$194.67 | |
| N PLACE | | 0040 - | Total | | | | | | \$194.67 | |
| 2021 15 | | 0050 | | Price FUEL | | 11 | | SYSTEM | \$189.34 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| 1-Total 1-To | | | | | | 14 | | SYSTEM | \$72.38 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | | 15 | | SYSTEM | \$246.81 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | - Total | | | | \$508.53 | |
| Material Compacting EMBANKMENT | | | | Price FUEL - | Total | | | | \$508.53 | |
| EMBANKMENT | | 0050 - | Total | | | | | | \$508.53 | |
| 2021 | | 0060 | | Material | | 3 | | SYSTEM | \$780.00 | Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment |
| 2021 Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | 3 | | SYSTEM | (\$780.00) | |
| 2021 5 Jul 16, 2021 5 | | | | | | 4 | | SYSTEM | \$780.00 | Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment |
| 2021 Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | | | 4 | | SYSTEM | (\$780.00) | |
| Total S0.00 | | | | | | 5 | | SYSTEM | \$780.00 | Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment |
| Material - Total \$0.00 | | | | | | 5 | | SYSTEM | (\$780.00) | |
| Solid System Sys | | | | | - Total | | | | \$0.00 | |
| COMPACTING IN CUT Material SYSTEM September System System September System System September System System System September System | | | | Material - To | tal | | | | \$0.00 | |
| IN CUT 2021 Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Jun 16, 2021 \$\frac{1}{2}\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$\$ \$\frac{1}{2}\$\$\$\$\$ \$\frac{1}{2}\$ | | 0060 - | Total | | | | | | \$0.00 | |
| 2021 4 Jul 2, 2021 \$\frac{1}{2}\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$ \$\frac{1}{2}\$\$\$\$\$ \$\frac{1}{2}\$ | | 0070 | | Material | | 3 | | SYSTEM | \$675.00 | Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment |
| Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 4 Jul 2, 2021 5 Jul 16, 2021 \$ SYSTEM \$675.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate Exception 2 on the current Payment Estimate. 5 Jul 16, 2021 \$ SYSTEM \$ (\$675.00) - Total \$ 0.00 | | | | | | 3 | | SYSTEM | (\$675.00) | |
| 2021 5 Jul 16, 2021 5 Jul 16, 2021 5 Jul 16, 2021 5 Jul 16, 2021 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 Jul 16, 2021 System (\$675.00) - Total \$0.00 | | | | | | 4 | | SYSTEM | \$675.00 | Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment |
| Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 5 Jul 16, 2021 \$ \$9.00 \$ \$0.00 \$ \$0.00 | | | | | | 4 | | SYSTEM | (\$675.00) | |
| 2021 | | | | | | 5 | | SYSTEM | \$675.00 | Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment |
| Material - Total \$0.00 | | | | | | 5 | | SYSTEM | (\$675.00) | |
| | | | | | - Total | | | | \$0.00 | |
| 0070 - Total \$0.00 | | | | Material - To | tal | | | | \$0.00 | |
| | | 0070 - | Total | | | | | | \$0.00 | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|--|--|--|---|
| J6S3408 | 0130 | TYPE 5 AGGREGATE FOR BASE | Material | | 5 | Jul 16, 2021 | SYSTEM | \$1,874.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$1,874.40) | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$1,874.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$1,874.40) | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | \$1,874.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$1,874.40) | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$2,261.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$2,261.60) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Price FUEL | | 5 | Jul 16, 2021 | SYSTEM | \$4.92 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$1.60 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | \$5.67 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$2.55 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$14.74 | |
| | | | Price FUEL - | Total | | | | \$14.74 | |
| | 0130 - | | | | - | | | \$14.74 | |
| | 0140 | TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) | Material | | 3 | Jun 16, 2021 | SYSTEM | \$11,160.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | THION | | | 3 | Jun 16, 2021 | SYSTEM | (\$11,160.00) | |
| | | | | | | | | | |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | \$37,937.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 4 | | SYSTEM | \$37,937.00 (\$37,937.00) | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment |
| | | | | | | 2021 Jul 2, | | | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment |
| | | | | | 4 | 2021 Jul 2, 2021 Jul 16, | SYSTEM | (\$37,937.00) | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment |
| | | | | | 5 | Jul 2, 2021 Jul 16, 2021 Jul 16, | SYSTEM SYSTEM | (\$37,937.00) \$37,937.00 | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment |
| | | | | | 5 | Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, | SYSTEM SYSTEM SYSTEM | (\$37,937.00) \$37,937.00 (\$37,937.00) | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment |
| | | | | | 4 5 5 | 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM | (\$37,937.00) \$37,937.00 (\$37,937.00) \$43,614.00 | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment |
| | | | | | 4 5 5 6 6 6 | 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, | SYSTEM SYSTEM SYSTEM SYSTEM | (\$37,937.00) \$37,937.00 (\$37,937.00) \$43,614.00 | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment |
| | | | | | 4 5 5 6 6 7 7 | 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$37,937.00) \$37,937.00 (\$37,937.00) \$43,614.00 (\$43,614.00) \$49,373.00 | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment |
| | | | | | 4 5 5 6 6 7 7 | 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$37,937.00) \$37,937.00 (\$37,937.00) \$43,614.00 (\$43,614.00) \$49,373.00 | Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | | | | |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|----------------|----------------|--|---|--|---|--|---|---|----|-----------------|-----------------|----------|---|
| J6S3408 | 0140 | TYPE 5 | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | |
| | | AGGREGATE FOR BASE (6 IN. THICK) | Price FUEL | | 3 | Jun 16, 2021 | SYSTEM | \$30.80 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | \$73.91 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$18.28 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | \$29.14 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$17.03 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$2.06 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$6.58 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$95.00 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$47.60 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$40.43 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | | |
| | | | | | | 14 | Dec 2, 2021 | SYSTEM | \$104.40 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 15 | Dec 16, 2021 | SYSTEM | \$240.36 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | | | | 16 | Jan 3, 2022 | SYSTEM | \$19.24 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | | | | | | 17 | Jan 18, 2022 | SYSTEM | \$39.10 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | |
| | | | | | | | | | | | 18 | Feb 1, 2022 | SYSTEM | \$8.51 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | |
| | | | | | | | | | | | | | ı | | | 19 | Feb 16, 2022 | SYSTEM | \$158.59 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$931.03 | | | | | | | | | | | | |
| | | | Price FUEL - | Total | | | | \$931.03 | | | | | | | | | | | | |
| | 0140 - | Total | | Matarial | Material | Material | Matarial | | | | | | \$931.03 | | | | | | | |
| | 0150 | MISC. AGGREGATE FOR BASE | Material | | 4 | Jul 2, 2021 | SYSTEM | \$12,329.33 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | | | | | | | 4 | Jul 2, 2021 | SYSTEM | (\$12,329.33) | | | | | | |
| | | | | | | | | | | | | | | | | | 5 | Jul 16, 2021 | SYSTEM | \$12,329.33 |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$12,329.33) | | | | | | | | | | | | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$14,174.03 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | | | | | | | | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$14,174.03) | | | | | | | | | | | | |
| | | | | | | | | | | | | \$16,045.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | | | | |
| | | | | 7 | 7 | Aug 16, 2021 | SYSTEM | (\$16,045.38) | | | | | | | | | | | | |
| | | | | 3 | | 8 | 8 | Sep 2, 2021 | SYSTEM | \$16,914.43 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | | | | | | | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$16,914.43) | | | | | | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J6S3408 | 0150 - | Total | | | | | | \$0.00 | |
| | 0160 | 8 INCHES, BITUMINOUS | Other Item Adjustment | ACAD | 6 | Aug 2, 2021 | brinkr1 | \$91.53 | 170.50 Sq.Yds BB20-3, 5th Estimate period, enterance to Haddock Lane |
| | | PAVEMENT | | | 6 | Aug 2, 2021 | brinkr1 | \$95.74 | 215.50 Sq.Yds BB20-2 215.50 Sq. Yds BP120-8 Location entrance to Rue Petit |
| | | | | ACAD - Tot | al | | | \$187.27 | |
| | | | Other Item A | djustment - T | otal | | | \$187.27 | |
| | | | Price FUEL | | 4 | Jul 2, 2021 | SYSTEM | \$37.77 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | \$34.88 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$72.65 | |
| | | | Price FUEL - | Total | | | | \$72.65 | |
| | 0160 - | · Total | | | | | | \$259.92 | |
| | 0170 | TYPE A2 SHOULDER | Material | | 4 | Jul 2, 2021 | SYSTEM | \$17,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | (\$17,840.00) | |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | \$26,828.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$26,828.80) | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$27,920.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$27,920.80) | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | \$27,920.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$27,920.80) | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$28,220.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$28,220.80) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$28,220.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$28,220.80) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$28,220.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$28,220.80) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$28,220.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$28,220.80) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$32,960.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$32,960.80) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0170 - | · Total | | | | | | \$0.00 | |
| | 0180 | MISC. | Material | | 7 | Aug 16, | SYSTEM | \$147,555.00 | This adjustment offsets the original system-generated Material Payment |



| ect | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----|--------|-------------|--------------------------|-----------------------------|----------------|-----------------|---------------|------------------------------|--|
| 408 | 0180 | MISC. | Material | | | 2021 | | | Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$147,555.00) | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$153,100.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$153,100.80) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$153,100.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$153,100.80) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$153,100.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$153,100.80) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$153,100.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$153,100.80) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$163,074.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$163,074.60) | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$184,642.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$184,642.20) | |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | \$165,304.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | (\$165,304.80) | |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | \$167,405.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$167,405.40) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$59,405.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$59,405.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | | | | | \$0.00 | |
| | | | Other Item Adjustment | ACAD | | Aug 2, 2021 | brinkr1 | \$56.01 | 167.00 Sq.Yds BB20-2 167.00 Sq.Yds BP120-8 Location VMP shoulder RT from Rue Petit to STA 507+75 |
| | | | | ACAD - Tot | | | | \$56.01 | |
| | | | Other Item A | djustment - T | otal | | | \$56.01 | |
| | 0480 - | Total | | | - | Jul 16, | SYSTEM | \$56.01 \$10,431.04 | This adjustment offsets the original system-generated Material Payment |
| | 0220 | MISC. | Material | | 5 | 2021 | | | Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment |
| | | MISC. | Material | | 5 | | SYSTEM | (\$10,431.04) | |
| | | MISC. | Material | | | 2021 | | (\$10,431.04) \$10,431.04 | Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | |
|---------|--------|--|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|--|----|----------------|---------|-------------|--|
| J6S3408 | 0220 | MISC. | Material | | 6 | Aug 2, 2021 | SYSTEM | (\$10,431.04) | | | | | | | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | \$10,431.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | | | | | | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$10,431.04) | | | | | | | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$12,585.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$12,585.80) | | | | | | | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$12,585.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | | | | | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$12,585.80) | | | | | | | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$12,585.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | | | | | | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$12,585.80) | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | |
| | | | Material - To | tal | | | | \$0.00 | | | | | | | |
| | 0220 - | | | | - | | | \$0.00 | | | | | | | |
| | 0240 | CONCRETE PAVEMENT (9 IN. NON- REINFORCED, | Material | | 3 | Jun 16, 2021 | SYSTEM | \$20,034.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | | | | |
| | | ,, | | | 3 | Jun 16, 2021 | SYSTEM | (\$20,034.00) | | | | | | | |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | \$35,143.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | (\$35,143.20) | | | | | | | |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | \$45,558.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | | | | | | |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$45,558.72) | | | | | | | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$60,511.32 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$60,511.32) | | | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | | | |
| | | | Material - Tot | | | | | \$0.00 | | | | | | | |
| | | | Other Item Adjustment | PCCS | 6 | Aug 2, 2021 | brinkr1 | (\$8,403.99) | Location VMP east LT, and center lane Lot 1 | | | | | | |
| | | | | | 10 | Oct 1, 2021 | brinkr1 | (\$11,386.66) | Location LSL BLVD south, LOT 2 cores | | | | | | |
| | | | | | 14 | Dec 2, 2021 | brinkr1 | \$8,403.99 | Lot #1 concrete strength adjustment, Estimate #6 QTY changed to a positive amount due to a 3rd party vender strength test of the same concrete roadway | | | | | | |
| | | | 14 | | | | | 14 | 1 | | 14 | Dec 2, 2021 | brinkr1 | \$11,386.66 | Lot #2 concrete strength adjustment, Estimate #10 QTY changed to a positive amount, due to a 3rd party vender strength test of the same concrete roadway |
| | | | | | 14 | Dec 2, 2021 | brinkr1 | \$1,150.20 | Lot #3 concrete strength adjustment | | | | | | |
| | | | | PCCS - Tota | al | | | \$1,150.20 | | | | | | | |
| | | | | PCCT | 6 | Aug 2, 2021 | brinkr1 | \$1,210.95 | Location VMP east left lane and center lane, Lot 1 | | | | | | |
| | | | | | 10 | Oct 1, 2021 | brinkr1 | \$993.60 | Location LSL BLVD south, Lot 2 cores | | | | | | |
| | | | | | 14 | Dec 2, 2021 | brinkr1 | \$1,150.20 | Lot #3 concrete thickness adjustment | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | | | | | |
|---------|--------|-------------------------|--------------------------|-----------------------------|----------------|--|---------------|----------------------------|---|---|-----------------|--------|-----------------|--------|--------------|--|--|
| J6S3408 | 0240 | CONCRETE PAVEMENT (9 | Other Item Adjustment | PCCT - Tota | ul | | | \$3,354.75 | | | | | | | | | |
| | | IN. NON- REINFORCED, | Other Item A | .djustment - T | otal | | | \$4,504.95 | | | | | | | | | |
| | | | Price FUEL | | 3 | Jun 16, 2021 | SYSTEM | \$29.38 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | \$22.16 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | \$17.82 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$25.59 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$17.93 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$18.88 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$123.58 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$52.53 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | \$275.43 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$107.71 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$24.41 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$990.48 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | | | | | |
| | | | | - Total | | | | \$1,705.90 | | | | | | | | | |
| | | | Price FUEL - | Total | | | | \$1,705.90 | | | | | | | | | |
| | 0240 - | - Total | | | | | | \$6,210.85 | | | | | | | | | |
| | 0250 | MISC. | Material | | 8 | Sep 2, 2021 | SYSTEM | \$3,538.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. | | | | | | | | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$3,538.50) | | | | | | | | | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$3,538.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate. | | | | | | | | |
| | | | | | | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$3,538.50) | | | | |
| | | | | | | | | | | | | | | | | | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$3,538.50) | | | | | | | | | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$3,538.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. | | | | | | | | |
| | | | | | | | | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$3,538.50) | | |
| | | | | | | | | | | | | | | | | | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$3,538.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | | | |
| | | | | | 12 | | SYSTEM | \$3,538.50 (\$3,538.50) | Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment | | | | | | | | |
| | | | | | | 2021 Nov 2, | | | Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment | | | | | | | | |
| | | | | | 12 | 2021 Nov 2, 2021 Nov 16, | SYSTEM | (\$3,538.50) | Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment | | | | | | | | |
| | | | | | 12 | Nov 2, 2021 Nov 16, 2021 Nov 16, | SYSTEM SYSTEM | (\$3,538.50) \$3,538.50 | Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-----------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J6S3408 | 0250 | MISC. | Material | | | 2021 | | | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$5,638.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$5,638.50) | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$5,638.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandeb2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$5,638.50) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$5,638.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandeb2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$5,638.50) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0250 - | Total | | | | | | \$0.00 | |
| | 0310 | PAVED APPROACH, 8 IN. | Material | | 8 | Sep 2, 2021 | SYSTEM | \$3,720.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$3,720.60) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$7,446.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$7,446.60) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$7,446.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$7,446.60) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$7,446.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$7,446.60) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$7,446.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$7,446.60) | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$7,446.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$7,446.60) | |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | \$7,446.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | (\$7,446.60) | |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | \$7,446.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | (\$7,446.60) | |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | \$7,446.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$7,446.60) | |
| | | | | - Total | | | | \$0.00 | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|----------------|--------------|---|---|
| J6S3408 | 0310 | PAVED | Material - Tot | tal | | | | \$0.00 | | |
| | | APPROACH, 8 IN. | Price FUEL | | 8 | Sep 2, 2021 | SYSTEM | \$9.09 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$5.38 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | |
| | | | | - Total | | | | \$14.47 | | |
| | | | Price FUEL - | Total | | | | \$14.47 | | |
| | 0310 - | Total | | | | | | \$14.47 | | |
| | 0350 | CONCRETE CURB (6 IN. HEIGHT AND | Material | | 10 | Oct 1, 2021 | SYSTEM | \$3,360.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | |
| | | UNDER) | | | 10 | Oct 1, 2021 | SYSTEM | (\$3,360.00) | | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$3,360.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 24 on the current Payment Estimate. | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$3,360.00) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - Tot | tal | | | | \$0.00 | | |
| | 0350 - | Total | | | | | | \$0.00 | | |
| | 0360 | CONCRETE GUTTER TYPE A | Material | | 6 | Aug 2, 2021 | SYSTEM | \$1,121.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$1,121.10) | | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | \$2,009.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate. | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$2,009.90) | | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$2,009.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 23 on the current Payment Estimate. | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$2,009.90) | | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$2,009.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$2,009.90) | | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$2,009.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user brinkr1 overridding Payment Estimate Exception 22 on the current Payment Estimate. | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$2,009.90) | | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$2,009.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate. | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$2,009.90) | | |
| | | | | | 1 | 12 | Nov 2, 2021 | SYSTEM | \$2,009.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$2,009.90) | | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$2,009.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate. | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$2,009.90) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - Tot | tal | | | | \$0.00 | | |
| | 0360 - | Total | | | | | | \$0.00 | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J6S3408 | 0370 | CONCRETE GUTTER TYPE B | Material | | 11 | Oct 18, 2021 | SYSTEM | \$11,850.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$11,850.00) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$11,850.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$11,850.00) | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$11,850.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$11,850.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0370 - | Total | | | | | | \$0.00 | |
| | 0380 | CURB AND GUTTER TYPE B | Material | | 4 | Jul 2, 2021 | SYSTEM | \$4,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | (\$4,320.00) | |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | \$4,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$4,320.00) | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$4,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$4,320.00) | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | \$4,320.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$4,320.00) | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$7,962.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$7,962.00) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$7,962.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$7,962.00) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$9,558.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user brinkr1 overridding Payment Estimate Exception 25 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$9,558.00) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$14,967.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 34 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$14,967.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0380 - | Total | | | | | | \$0.00 | |
| | 0390 | INTEGRAL CURB (6 IN. HEIGHT AND | Material | | 8 | Sep 2, 2021 | SYSTEM | \$1,286.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate. |
| | | UNDER) | | | 8 | Sep 2, | SYSTEM | (\$1,286.90) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J6S3408 | 0390 | INTEGRAL | Material | | | 2021 | | | |
| | | CURB (6 IN. HEIGHT AND UNDER) | | | 9 | Sep 16, 2021 | SYSTEM | \$1,286.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$1,286.90) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$1,286.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$1,286.90) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$1,286.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 36 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$1,286.90) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0390 - | Total | | | | | | \$0.00 | |
| | 0410 | ROCK LINING | Material | | 17 | Jan 18, 2022 | SYSTEM | \$1,680.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$1,680.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0410 - | Total | | | | | | \$0.00 | |
| | 0430 | MISC. PAVED DRAINAGE | Material | | 9 | Sep 16, 2021 | SYSTEM | \$2,475.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$2,475.00) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$2,475.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$2,475.00) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$2,475.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 39 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$2,475.00) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$2,475.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$2,475.00) | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$2,475.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$2,475.00) | |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | \$3,882.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$3,882.00) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$3,882.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$3,882.00) | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$3,882.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandeb2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |



| ct L | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|------|------------------------|---|-----------------------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 08 0 | 0430 | MISC. PAVED DRAINAGE | Material | | 18 | Feb 1, 2022 | SYSTEM | (\$3,882.00) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$3,882.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandeb2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$3,882.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Overrun | Overrun | 16 | Jan 3, 2022 | SYSTEM | \$12.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$12.00) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$12.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$12.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$12.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero). |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$12.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$12.00) | Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$12.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40. |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - To | tal | | | | \$0.00 | |
| 0 | 0430 - | | | | | | | \$0.00 | |
| 0 | 0450 | MANHOLE FRAME AND COVER, TYPE 1- | Material | | 3 | Jun 16, 2021 | SYSTEM | \$360.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | В | | | 3 | Jun 16, 2021 | SYSTEM | (\$360.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0450 - | | | | | | | \$0.00 | |
| 0 | 0520 | PREF THERMO PAVMT MARKING, 6 IN | Stockpile | | 15 | Dec 16, 2021 | SYSTEM | \$260.10 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | WHITE | | - Total | | | | \$260.10 | |
| | 0500 | Total | Construction | Stockpile S | MI - Total | | | \$260.10 | |
| | 0520 - | | Com-t " | | 45 | De - 40 | ever: | \$260.10 | Deument Fetimete Hem Adjustuset source de Ch. 1. 7. T. |
| 0 | 0530 | PREF THERMO PAVMT MARKING, 12 IN | Construction Stockpile STMI | Total | 15 | Dec 16, 2021 | SYSTEM | \$294.70 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | WHITE | Construction | - Total | IMI Total | | | \$294.70 | |
| | | | Construction | Stockpile S | IVII - Total | | | \$294.70 | |
| ٥ | 0520 | Total . | | | | | | \$294.70 | |
| | 0 530 - 0540 | PREF THERMO | Construction Stocknile | | 15 | Dec 16, 2021 | SYSTEM | \$588.92 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | Construction Stockpile STMI | - Total | 15 | Dec 16, 2021 | SYSTEM | · | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | PREF THERMO PVMT MARK, 24 | Stockpile STMI | - Total | | 2021 | SYSTEM | \$588.92 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| 0 | | PREF THERMO PVMT MARK, 24 IN WHIT | Stockpile STMI | - Total Stockpile S | | 2021 | SYSTEM | · | Payment Estimate Item Adjustment generated Stockpile Transaction |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|-----------------------------------|-----------------------------|----------------|--|----------------------|--|---|
| J6S3408 | 0550 | PREF THERMO PVMT MARK, LT/RT ARROW | Construction Stockpile STMI | - Total | | | | \$1,390.90 | |
| | | | Construction | Stockpile S | ГМI - Total | | | \$1,390.90 | |
| | 0550 - | · Total | | | | | | \$1,390.90 | |
| | 0560 | PREF THERMO PVMT MRKG, | Construction Stockpile | | 15 | Dec 16, 2021 | SYSTEM | \$874.65 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | STRIAGHT ARROW | STMI | - Total | | | | \$874.65 | |
| | | | Construction | Stockpile S | ΓΜΙ - Total | | | \$874.65 | |
| | 0560 - | - Total | | | | | | \$874.65 | |
| | 0570 | PREF THERMO PVMT | Construction Stockpile | | 15 | Dec 16, 2021 | SYSTEM | \$180.92 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | MARKING, COMBO | STMI | - Total | | | | \$180.92 | |
| | | | Construction | Stockpile S | ГМI - Total | | | \$180.92 | |
| | 0570 - | · Total | | | | | | \$180.92 | |
| | 0590 | PREF THERMO PVMT MARK, | Construction Stockpile | | 15 | Dec 16, 2021 | SYSTEM | \$319.20 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | YIELD TRIAN | STMI | - Total | | | | \$319.20 | |
| | | | Construction | Stockpile S | ΓΜΙ - Total | | | \$319.20 | |
| | 0590 - | - Total | | | | | | \$319.20 | |
| | 0600 | PREF THERMO PVMT MARK, | Construction Stockpile | | 15 | Dec 16, 2021 | SYSTEM | \$1,613.22 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | LT/RT FISH | STMI | - Total | | | | \$1,613.22 | |
| | | | Construction | Stockpile S | FML Total | | | \$1,613.22 | |
| | 0000 | T-4-1 | Construction | 1 Stockpile 3 | iwii - i Otai | | | | |
| | 0600 - | | | | | 5 10 | 0) (0==14 | \$1,613.22 | |
| | 0610 | PREF THERMO PVMT MARK, COMBO FISH | Construction Stockpile STMI | | 15 | Dec 16, 2021 | SYSTEM | \$1,613.22 | Payment Estimate Item Adjustment generated Stockpile Transaction |
| | | | 0 1 1 | - Total | | | | \$1,613.22 | |
| | | | Construction | Stockpile S | IMI - I otal | | | \$1,613.22 | |
| | 0610 - | | | | | | | \$1,613.22 | |
| | 0700 | SEPARATION GEOTEXTILE | Material | | 4 | Jul 2, 2021 | SYSTEM | \$7,587.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | (\$7,587.40) | |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | \$7,587.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$7,587.40) | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$8,722.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, | SYSTEM | (\$8,722.80) | |
| | | | | | | 2021 | | (40,122.00) | |
| | | | | | 7 | | SYSTEM | \$9,874.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | | 2021 Aug 16, | SYSTEM | | Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment |
| | | | | | 7 | 2021 Aug 16, 2021 Aug 16, | | \$9,874.60 | Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment |
| | | | | | 7 | 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, | SYSTEM | \$9,874.60 (\$9,874.60) | Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment |
| | | | | | 7 7 8 | 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, | SYSTEM SYSTEM | \$9,874.60 (\$9,874.60) \$10,409.60 | Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment |
| | | | | | 7 7 8 8 | 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, | SYSTEM SYSTEM SYSTEM | \$9,874.60 (\$9,874.60) \$10,409.60 (\$10,409.60) | Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|---|
| J6S3408 | 0700 | SEPARATION GEOTEXTILE | Material | | | 2021 | | | Estimate Item Adjustment (0037) due to user brinkr1 overridding Payment Estimate Exception 35 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$10,849.60) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$12,816.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$12,816.60) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$13,802.20 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$13,802.20) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0700 - | Total | | | | | | \$0.00 | |
| | 0740 | MECHANICALLY STABILIZED EARTH WALL SYS | Material | | 10 | Oct 1, 2021 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user brinkr1 overridding Payment Estimate Exception 40 on the current Payment Estimate. |
| | | 313 | | | 10 | Oct 1, 2021 | SYSTEM | (\$155,545.00) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 49 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$155,545.00) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$155,545.00) | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$155,545.00) | |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | (\$155,545.00) | |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | (\$155,545.00) | |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$155,545.00) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$155,545.00) | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandeb2 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$155,545.00) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$155,545.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandeb2 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, | SYSTEM | (\$155,545.00) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J6S3408 | 0740 | MECHANICALLY | Material | | | 2022 | | | |
| | | STABILIZED EARTH WALL | | - Total | | | | \$0.00 | |
| | | SYS | Material - To | tal | | | | \$0.00 | |
| | 0740 - | | | | | | | \$0.00 | |
| | 0780 | 12 IN. GROUP A FLARED END SECT | Material | | 8 | Sep 2, 2021 | SYSTEM | \$600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 42 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$600.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0780 - | · Total | | | | | | \$0.00 | |
| | 0790 | TURF TYPE TALL FESCUE SODDING | Material | | 9 | Sep 16, 2021 | SYSTEM | \$5,280.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 43 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$5,280.00) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$5,280.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user brinkr1 overridding Payment Estimate Exception 47 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$5,280.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0790 - | · Total | | | | | | \$0.00 | |
| | 0800 | SEEDING - COOL SEASON MIXTURES | Material | | 10 | Oct 1, 2021 | SYSTEM | \$11,858.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user brinkr1 overridding Payment Estimate Exception 48 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$11,858.00) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$11,858.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 56 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$11,858.00) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$11,858.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$11,858.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0800 - | · Total | | | | | | \$0.00 | |
| | 0810 | ROCK DITCH CHECK | Material | | 5 | Jul 16, 2021 | SYSTEM | \$570.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$570.00) | |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | \$570.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$570.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0810 - | Total | | | | | | \$0.00 | |
| | 0820 | CURB INLET CHECK | Material | | 5 | Jul 16, 2021 | SYSTEM | \$125.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$125.00) | |



| Project | Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---------------------------------------|--------------------|---------------------|----------------|-----------------|---------------|--------------|---|
| J6S3408 | 0820 | CURB INLET | Material | Туре | 6 | Aug 2, | SYSTEM | \$125.00 | This adjustment offsets the original system-generated Material Payment |
| | | CHECK | | | | 2021 | | Ţ0.00 | Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$125.00) | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | \$125.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$125.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0820 - | Total | | | | | | \$0.00 | |
| | 0840 | TEMPORARY SEEDING AND MULCHING | Material | | 9 | Sep 16, 2021 | SYSTEM | \$1,470.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$1,470.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0840 - | Total | | | | | | \$0.00 | |
| | 0860 | MGS GUARDRAIL | Material | | 8 | Sep 2, 2021 | SYSTEM | \$3,127.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$3,127.50) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$3,127.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$3,127.50) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$3,127.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$3,127.50) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$3,127.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$3,127.50) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0860 - | Total | | | | | | \$0.00 | |
| | 0870 | MGS HEIGHT AND BLOCK TRANSITION | Material | | 8 | Sep 2, 2021 | SYSTEM | \$768.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brinkr1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$768.21) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$768.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$768.21) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$768.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$768.21) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$768.21 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$768.21) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|--|
| 6S3408 | 0870 | MGS HEIGHT AND BLOCK | Material | - Total | | | | \$0.00 | |
| | | TRANSITION | Material - To | tal | | | | \$0.00 | |
| | 0870 - | | | | | | | \$0.00 | |
| | 0890 | TYPE A CRASHWORTHY END TERMINAL (MASH) | Material | | 8 | Sep 2, 2021 | SYSTEM | \$2,311.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | (IVIASH) | | | 8 | Sep 2, 2021 | SYSTEM | (\$2,311.40) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$2,311.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$2,311.40) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$2,311.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$2,311.40) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$2,311.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$2,311.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0890 - | Total | | | | | | \$0.00 | |
| | 0920 | LUMINAIRE, LED-A | Material | | 16 | Jan 3, 2022 | SYSTEM | \$2,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$2,000.00) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$5,200.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$5,200.00) | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$6,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandeb2 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$6,000.00) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$6,000.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandeb2 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$6,000.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0920 - | · Total | | | | | | \$0.00 | |
| | 0930 | CONDUIT, 3 IN. RIGID, IN TRENCH | Material | | 6 | Aug 2, 2021 | SYSTEM | \$2,304.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$2,304.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | | | Overrun | Overrun | 6 | Aug 2, 2021 | SYSTEM | \$2,088.00 | This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 24 on the current Payment Estimate. Material Insufficiency Quantity 128.000; Overrun Quantity Balance 116.00. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$2,088.00) | |
| | | | | | 7 | Aug 16, | SYSTEM | (\$2,088.00) | Averaged Price Adjustment from this item on all previous payment estimates |
| | | | | | ′ | Aug 10, | SIGILIVI | (ΨΣ,000.00) | Avoragos i noc Aujustinoni inon tino iteni on ali previous payment estimates |



| Project | Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------|---------------------|----------------|-----------------|---------------|--------------|---|
| | | | | Type | Number | | Бу | | |
| J6S3408 | 0930 | CONDUIT, 3 IN. RIGID, IN | Overrun | Overrun - T | otol | 2021 | | /\$2.000.00\ | of '0.00000' is applied (if non-zero). |
| | | TRENCH | Overrun - To | | otai | | | (\$2,088.00) | |
| | 0930 - | Total | Overruit - 10 | Lai | | | | (\$2,088.00) | |
| | 0960 | PULL BOX, PREFORMED CLASS 1 | Material | | 6 | Aug 2, 2021 | SYSTEM | \$2,434.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$2,434.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0960 - | Total | | | | | | \$0.00 | |
| | 0970 | PULL BOX, PREFORMED CLASS 3 | Material | | 6 | Aug 2, 2021 | SYSTEM | \$1,470.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 22 on the current Payment Estimate. |
| | | | | | 6 | Aug 2, 2021 | SYSTEM | (\$1,470.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0970 - | Total | | | | | | \$0.00 | |
| | 0980 | CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE | Material | | 16 | Jan 3, 2022 | SYSTEM | \$180.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | BRACKE | | | 16 | Jan 3, 2022 | SYSTEM | (\$180.00) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$468.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$468.00) | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$540.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandeb2 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$540.00) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$540.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandeb2 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$540.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 0980 - | Total | | | | | | \$0.00 | |
| | 0990 | CABLE- CONDUIT, 1 IN., 2 | Material | | 6 | Aug 2, 2021 | SYSTEM | \$645.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | CONDUCTORS | | | 6 | Aug 2, 2021 | SYSTEM | (\$645.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 0990 - | Total | | | | | | \$0.00 | |
| | 1000 | POLE FOUNDATION (30 FT. OR 9.0 M | Material | | 7 | Aug 16, 2021 | SYSTEM | \$2,970.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 24 on the current Payment Estimate. |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$2,970.00) | |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | \$3,960.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user brinkr1 overridding Payment Estimate Exception 43 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$3,960.00) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J6S3408 | 1000 | POLE FOUNDATION (30 FT. OR 9.0 M | Material | | 9 | Sep 16, 2021 | SYSTEM | \$4,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 47 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$4,950.00) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$4,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user brinkr1 overridding Payment Estimate Exception 53 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$4,950.00) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$4,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user brinkr1 overridding Payment Estimate Exception 61 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$4,950.00) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$4,950.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 31 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$4,950.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1000 - | | | | | | | \$0.00 | |
| | 1010 | MISC. HIGHWAY LIGHTING | Material | | 13 | Nov 16, 2021 | SYSTEM | \$8,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$8,840.00) | |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | \$8,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | (\$8,840.00) | |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | \$8,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | (\$8,840.00) | |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | \$8,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$8,840.00) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$8,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$8,840.00) | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$8,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandeb2 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$8,840.00) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$8,840.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandeb2 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$8,840.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tot | tal | | | | \$0.00 | |
| | 1010 - | Total | | | | | | \$0.00 | |
| | 1020 | CONCRETE FOOTINGS, EMBEDDED | Material | | 8 | Sep 2, 2021 | SYSTEM | \$82.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, | SYSTEM | (\$82.08) | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-----------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| 6S3408 | 1020 | CONCRETE | Material | | | 2021 | | | |
| | | FOOTINGS, EMBEDDED | | | 9 | Sep 16, 2021 | SYSTEM | \$82.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 48 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$82.08) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$82.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user brinkr1 overridding Payment Estimate Exception 54 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$82.08) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$82.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user brinkr1 overridding Payment Estimate Exception 62 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$82.08) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$82.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$82.08) | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$82.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$82.08) | |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | \$82.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | (\$82.08) | |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | \$82.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate. |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | (\$82.08) | |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | \$947.06 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$947.06) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$947.06 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$947.06) | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$1,584.74 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandeb2 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$1,584.74) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$1,894.11 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandeb2 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$1,894.11) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1020 - | | | | | 0 0 | 0)(0777) | \$0.00 | |
| | 1050 | PIPE POSTS | Material | | 8 | Sep 2, 2021 | SYSTEM | \$248.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user brinkr1 overridding Payment Estimate Exception 47 on the current Payment Estimate. |
| | | | | | 8 | Sep 2, 2021 | SYSTEM | (\$248.04) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$248.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brinkr1 overridding Payment |



| | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|----|--------|---------------|--------------------|-----------------------------|----------------------------|---|---|--|--|
| 80 | 1050 | PIPE POSTS | Material | | | | | | Estimate Exception 51 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$248.04) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$248.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user brinkr1 overridding Payment Estimate Exception 57 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$248.04) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$248.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user brinkr1 overridding Payment Estimate Exception 65 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$248.04) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$248.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 33 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$248.04) | |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | \$248.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 13 | Nov 16, 2021 | SYSTEM | (\$248.04) | |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | \$248.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | | 14 | Dec 2, 2021 | SYSTEM | (\$248.04) | |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | \$248.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | (\$248.04) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 40E0 | Total | | | | | | \$0.00 | |
| | 1050 - | | | | 4.0 | | | | This adjustment effects the original quature generated Material Dayment |
| | 1070 | SH-FLAT SHEET | Material | | 16 | Jan 3, 2022 | SYSTEM | \$360.85 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | SH-FLAT SHEET | Material | | 16 | | SYSTEM | \$360.85 (\$360.85) | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment |
| | | SH-FLAT SHEET | Material | | 16 17 | Jan 3, 2022 Jan 18, 2022 | SYSTEM SYSTEM | (\$360.85) \$360.85 | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment |
| | | SH-FLAT SHEET | Material | | 16 | Jan 3, 2022 Jan 18, | SYSTEM | (\$360.85) | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment |
| | | SH-FLAT SHEET | Material | | 16 17 | Jan 3, 2022 Jan 18, 2022 Jan 18, | SYSTEM SYSTEM | (\$360.85) \$360.85 | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment |
| | | SH-FLAT SHEET | Material | | 16 17 | Jan 3, 2022 Jan 18, 2022 Jan 18, 2022 Feb 1, | SYSTEM SYSTEM SYSTEM | (\$360.85) \$360.85 (\$360.85) | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment |
| | | SH-FLAT SHEET | Material | | 16 17 17 18 | 2022 Jan 3, 2022 Jan 18, 2022 Jan 2022 Feb 1, 2022 | SYSTEM SYSTEM SYSTEM SYSTEM | (\$360.85) \$360.85 (\$360.85) \$716.95 | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate. |
| | | SH-FLAT SHEET | Material | | 16 17 17 18 18 | 2022 Jan 3, 2022 Jan 18, 2022 Jan 18, 2022 Feb 1, 2022 Feb 1, 2022 | SYSTEM SYSTEM SYSTEM SYSTEM | (\$360.85) \$360.85 (\$360.85) \$716.95 | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment |
| | | SH-FLAT SHEET | Material | - Total | 16 17 17 18 18 | 2022 Jan 3, 2022 Jan 18, 2022 Jan 18, 2022 Feb 1, 2022 Feb 1, 2022 Feb 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$360.85) \$360.85 (\$360.85) \$716.95 (\$716.95) | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment |
| | | SH-FLAT SHEET | Material - To | | 16 17 17 18 18 | 2022 Jan 3, 2022 Jan 18, 2022 Jan 18, 2022 Feb 1, 2022 Feb 1, 2022 Feb 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$360.85) \$360.85 (\$360.85) \$716.95 (\$716.95) | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment |
| | | | | | 16 17 17 18 18 | 2022 Jan 3, 2022 Jan 18, 2022 Jan 18, 2022 Feb 1, 2022 Feb 1, 2022 Feb 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$360.85) \$360.85 (\$360.85) \$716.95 (\$716.95) \$716.95 | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment |
| | 1070 | | | | 16 17 17 18 18 | 2022 Jan 3, 2022 Jan 18, 2022 Jan 18, 2022 Feb 1, 2022 Feb 1, 2022 Feb 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | (\$360.85) \$360.85 (\$360.85) \$716.95 (\$716.95) \$716.95 \$0.00 | Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payme Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|-----------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|---|
| J6S3408 | 1080 | ST- STRUCTURAL | Material | | 17 | Jan 18, 2022 | SYSTEM | \$4,221.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$4,221.60) | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$6,332.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandeb2 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$6,332.40) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$6,332.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandeb2 overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$6,332.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1080 - | · Total | | | | | | \$0.00 | |
| | 1090 | SHF-FLAT SHEET FLUORESCENT | Material | | 18 | Feb 1, 2022 | SYSTEM | \$781.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandeb2 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | (\$781.12) | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$781.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandeb2 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$781.12) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 1090 - | · Total | | | | | | \$0.00 | |
| | 5001 | CONDUIT SYSTEM ON STRUCTURE | Material | | 4 | Jul 2, 2021 | SYSTEM | \$4,872.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | (\$4,872.00) | |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | \$4,872.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$4,872.00) | |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | \$4,872.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 7 | Aug 16, 2021 | SYSTEM | (\$4,872.00) | |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | \$4,872.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 15 | Dec 16, 2021 | SYSTEM | (\$4,872.00) | |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | \$4,872.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 16 | Jan 3, 2022 | SYSTEM | (\$4,872.00) | |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | \$4,872.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 17 | Jan 18, 2022 | SYSTEM | (\$4,872.00) | |
| | | | | | | 2022 | | | |
| | | | | | 18 | Feb 1, 2022 | SYSTEM | \$4,872.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user sandeb2 overridding Payment Estimate Exception 3 on the current Payment Estimate. |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|--|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|---|
| J6S3408 | 5001 | CONDUIT SYSTEM ON STRUCTURE | Material | | | 2022 | | | |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | \$4,872.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user sandeb2 overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 19 | Feb 16, 2022 | SYSTEM | (\$4,872.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | 5001 - | Total | | | | | | \$0.00 | |
| | 5002 | CONDUIT SYSTEM ON STRUCTURE | Material | | 4 | Jul 2, 2021 | SYSTEM | \$5,357.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 4 | Jul 2, 2021 | SYSTEM | (\$5,357.10) | |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | \$5,357.10 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | 5 | Jul 16, 2021 | SYSTEM | (\$5,357.10) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 5002 - | Total | | | | | | \$0.00 | |
| | 5003 | CONCRETE PAVEMENT (7 IN. NON- REINFORCED, | Material | | 11 | Oct 18, 2021 | SYSTEM | \$26,885.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$26,885.00) | |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$40,460.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | (\$40,460.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | tal | | | | \$0.00 | |
| | | | Price FUEL | | 11 | Oct 18, 2021 | SYSTEM | \$59.15 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 12 | Nov 2, 2021 | SYSTEM | \$29.87 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$89.02 | |
| | | | Price FUEL - Total | | | | | \$89.02 | |
| | 5003 - | Total | | | | | | \$89.02 | |
| | 5004 | PAVEMENT EDGE TREATMENT | Material | | 8 | Sep 2, 2021 | SYSTEM | \$3,311.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user brinkr1 overridding Payment Estimate Exception 36 on the current Payment Estimate. |
| | | | | 9 1 1 1 1 | 8 | Sep 2, 2021 | SYSTEM | (\$3,311.00) | |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | \$3,311.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brinkr1 overridding Payment Estimate Exception 37 on the current Payment Estimate. |
| | | | | | 9 | Sep 16, 2021 | SYSTEM | (\$3,311.00) | |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | \$3,311.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user brinkr1 overridding Payment Estimate Exception 34 on the current Payment Estimate. |
| | | | | | 10 | Oct 1, 2021 | SYSTEM | (\$3,311.00) | |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | \$3,311.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user brinkr1 overridding Payment Estimate Exception 43 on the current Payment Estimate. |
| | | | | | 11 | Oct 18, 2021 | SYSTEM | (\$3,311.00) | |
| | | | | - Total | | | | \$0.00 | |

Feb 25, 2022



Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------------|---|-------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------|---------|
| J6S3408 | S 5004 PAVEMENT EDGE TREATMENT Material - Total | | | | | | | \$0.00 | |
| | 5004 - Total | | | | | | | \$0.00 | |
| J6S3408 - Total | | | | | | | | | |
| Overall - Total | | | | | | | | | |