

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 4, 2022

Progress Estimate Number	Contract ID	210319-F07		Pay Period Start March 16, 2022	2 Original Contract Amount \$2,956,107.23
22	Prime Contractor	Gershenson Construction Co.,	Inc	. Pay Period End April 1, 2022	Net Change Order Amount \$13,729.09
22					Current Contract Amount \$2,969,836.32

Approval Date		By User
April 4, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	brinkr1
April 4, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	lewisj1
April 5, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
June 1, 2022	June 1, 2022		76.66%

	Contract Informational Dates									
Date Description	Date Description Original Completion Date Current Completion Date									
Acceptance Date										
Awarded Date	April 7, 2021	April 7, 2021								
Letting Date	March 19, 2021	March 19, 2021								
Notice to Proceed Date	May 10, 2021	May 10, 2021								
Work Began Date										

Contract Total Pa	ay For Estimate No. 22			
		This Estimate	Previous	To Date
210319-F07				
	Total Posted Items Pay	\$50,908.29	\$2,225,671.52	\$2,276,579.81
	Gross Item Adjustments	(\$690.02)	\$13,393.31	\$12,703.29
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$2,239,064.83	\$2,289,283.10
Contract Total Pa	avable This Estimate:	\$50.218.27		

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3408	0040	2031000	CLASS A EXCAVATION	CUYD	\$12.000	190	\$2,280.00
	0060	2036000	COMPACTING EMBANKMENT	CUYD	\$10.000	202	\$2,020.00
	0070	2037075	COMPACTING IN CUT	STA	\$100.000	3.1	\$310.00
	0120	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$7.000	100	\$700.00
	0320	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$35.000	100	\$3,500.00
	0550	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$350.000	6	\$2,100.00
	0590	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	EA	\$35.000	24	\$840.00
	0680	6209903	MISC."24 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS"	LF	\$10.000	65	\$650.00
	0710	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	LS	\$20,000.000	0.4	\$8,000.00
	0720	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	LS	\$3,200.000	1	\$3,200.00
	0730	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	LS	\$3,200.000	1	\$3,200.00
	0860	6061060	MGS GUARDRAIL	LF	\$20.850	275	\$5,733.75
	0870	6061074	MGS HEIGHT AND BLOCK TRANSITION	EA	\$768.210	1	\$768.21
	0880	6061080	MGS END ANCHOR	EA	\$956.200	2	\$1,912.40
	0890	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	EA	\$2,311.400	5	\$11,557.00
	1070	9035004A	SH-FLAT SHEET	SQFT	\$23.740	97.4	\$2,312.28
	1090	9035069A	SHF-FLAT SHEET FLUORESCENT	SQFT	\$24.410	74.75	\$1,824.65
Project J6	S3408 - To	tal					\$50,908.29
Overall - T	otal						\$50,908.29

Revision 4/1/2020 Page 1 of 36



#### **Missouri Department of Transportation** Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 4, 2022

Pay Period Start March 16, 2022 Original Contract Amount \$2,956,107.23 **Progress Estimate Number** 210319-F07 Prime Contractor Gershenson Construction Co., Inc. Pay Period End April 1, 2022 Net Change Order Amount \$13,729.09 Current Contract Amount \$2,969,836.32 22

#### Contract Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S3408	0040	CLASS A EXCAVATION	Price	Турс	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	190	\$0.14	\$27.36
	0120	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	100	\$0.11	\$10.80
	0320	CONCRETE SIDEWALK, 4 IN.	Material			-100	\$35.00	(\$3,500.00)
	0320	CONCRETE SIDEWALK, 4 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	100	\$35.00	\$3,500.00
	0340	MISC.	Material			-200	\$90.00	(\$18,000.00)
	0340	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	200	\$90.00	\$18,000.00
	0550	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$596.10)
	0550	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-6	\$350.00	(\$2,100.00)
	0550	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	6	\$350.00	\$2,100.00
	0590	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$132.08)
	0590	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material			-24	\$35.00	(\$840.00)
	0590	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	24	\$35.00	\$840.00
	0680	MISC.	Material			-65	\$10.00	(\$650.00)
	0680	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	65	\$10.00	\$650.00
	0740	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-2,393	\$65.00	(\$155,545.00)
	0740	MECHANICALLY STABILIZED EARTH WALL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	2,393	\$65.00	\$155,545.00

Page 2 of 36 Revision 4/1/2020



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: April 4, 2022

Progress Estimate Number
22 Contract ID 210319-F07 Pay Period Start March 16, 2022 Original Contract Amount \$2,956,107.23 Prime Contractor Gershenson Construction Co., Inc. Pay Period End April 1, 2022 Net Change Order Amount \$13,729.09 Current Contract Amount \$2,969,836.32

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
J6S3408		SYSTEMS		Туре	Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		Unit Price	
	1020	CONCRETE FOOTINGS, EMBEDDED	Material		on the danont rayment Estimate.	-4.11	\$631.37	(\$2,594.93
	1020	CONCRETE FOOTINGS, EMBEDDED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	4.11	\$631.37	\$2,594.93
	1030	CONCRETE FOOTINGS, BOLT DOWN	Material			-5.2	\$1,762.49	(\$9,164.95
	1030	CONCRETE FOOTINGS, BOLT DOWN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	5.2	\$1,762.49	\$9,164.95
	1070	SH-FLAT SHEET	Material			-133.6	\$23.74	(\$3,171.66
	1070	SH-FLAT SHEET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.	133.6	\$23.74	\$3,171.66
	1080	ST-STRUCTURAL	Material			-360	\$17.59	(\$6,332.40)
	1080	ST-STRUCTURAL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	360	\$17.59	\$6,332.40
	1090	SHF-FLAT SHEET FLUORESCENT	Material			-118.75	\$24.41	(\$2,898.69
	1090	SHF-FLAT SHEET FLUORESCENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	118.75	\$24.41	\$2,898.69
	5001	CONDUIT SYSTEM ON STRUCTURE	Material			-1	\$4,872.00	(\$4,872.00)
	5001	CONDUIT SYSTEM ON STRUCTURE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	1	\$4,872.00	\$4,872.00
Total								(\$690.02)

Revision 4/1/2020 Page 3 of 36



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J6S3408	FAS S502(17)	Intersection improvements	OR 70	ST CHARLES	at the intersection of Lake St. Louis, Veterans Memorial Parkway, and I-70 eastbound ramps							

#### 

Revision 4/1/2020 Page 4 of 36



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Feriou			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 6086004, Project Item Line Number 0320, Material Set 608600496, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with Materials to remove Class B W/Air did not use	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 6089905, Project Item Line Number 0340, Material Set 6089905, Material 1056TM - Tinting Material for Concrete, Acceptance Action Generic 1056TM is insufficient.	waiting for 28 day break to complete concrete tests	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 6200021, Project Item Line Number 0550, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Working with contractor to obtain thermoplastic marking CERTs	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 6200042, Project Item Line Number 0590, Material Set 620004296, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Working with contractor to obtain thermoplastic marking CERTs	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 6209903, Project Item Line Number 0680, Material Set 620990396, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	Working with contractor to obtain white paint CERTs	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 6209903, Project Item Line Number 0680, Material Set 620990396, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Working with contractor to obtain glass beads CERTs	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7071000, Project Item Line Number 5001, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient.	Working with Materials need CERTs for Junction Box	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7071000, Project Item Line Number 5001, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with Materials need CERTs for electrical conduit	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7071000, Project Item Line Number 5002, Material Set 707100096, Material 1062JBHL - Junction Boxes for Highway Lighting, Acceptance Action Generic 1062JBHL is insufficient.	Working with Materials to remove Junction box was not installed	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7071000, Project Item Line Number 5002, Material Set 707100096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Working with Materials to remove, conduit was not installed	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 7201000, Project Item Line Number 0740, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Working with Materials and Jeff City Materials to complete T99 Compaction QA	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9031010, Project Item Line Number 1020, Material Set 903101096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting for 28 day break to complete test	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9031020, Project Item Line Number 1030, Material Set 903102096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting for 28 day concrete break test to complete	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9035004A, Project Item Line Number 1070, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Working with contractor need CERTs	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9035011A, Project Item Line Number 1080, Material Set 9035011A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	working with contractor need CERTs	brinkr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3408, Item 9035069A, Project Item Line Number 1090, Material Set 9035069A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	working with contractor need CERTs	brinkr1	Overridden
Estimate Exception Type: Item Overrun: Contract 210319-F07, Contract Project J6S3408, Project Item Line Number 0930, Contract Line Item Number 0930, Item 9013003, Minor Item.	Overrun will be paid for on next Change Order	brinkr1	Acknowledged

Revision 4/1/2020 Page 5 of 36



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	ased on R	eport Generated date and can differ from the posted amo	ount at the	time the	Estimate wa	is Gene	rated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210319-F07	J6S3408	0001	0010	1041000	TEMPORARY SURFACING	235.00	0.00	235.00	CUYD	18.00	\$5.00	\$90.00
		0001	0020	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$15,000.00	\$15,000.00
		0001	0030	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.95	\$235,000.00	\$223,250.00
		0001	0040	2031000	CLASS A EXCAVATION	6,592.00	0.00	6,592.00	CUYD	6,575.00	\$12.00	\$78,900.00
		0001	0050	2035500	EMBANKMENT IN PLACE	9,181.00	0.00	9,181.00	CUYD	3,437.00	\$12.00	\$41,244.00
		0001	0060	2036000	COMPACTING EMBANKMENT	5,606.00	0.00	5,606.00	CUYD	5,591.00	\$10.00	\$55,910.00
		0001	0070	2037075	COMPACTING IN CUT	23.60	0.00	23.60	STA	23.30	\$100.00	\$2,330.00
		0001	0080	2039901	MISC.UTILITY LOCATION VERIFICATION	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0001	0090	2063000	CLASS 3 EXCAVATION	132.00	0.00	132.00	CUYD	132.00	\$30.00	\$3,960.00
		0001	0100	2072000	LINEAR GRADING CLASS 2	9.30	0.00	9.30	STA	3.05	\$1,200.00	\$3,660.00
		0001	0110	2169901	MISC.REMOVE AND RESET FIRST BANK SIGN	1.00	0.00	1.00	LS	1.00	\$12,000.00	\$12,000.00
		0001	0120	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	686.00	0.00	686.00	SQYD	100.00	\$7.00	\$700.00
		0001	0130	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,056.00	0.00	1,056.00	SQYD	422.70	\$8.00	\$3,381.60
		0001	0140	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	14,772.00	0.00	14,772.00	SQYD	14,194.15	\$10.00	\$141,941.50
		0001	0150	3049905	MISC.RIGID GEOGRID TO ENHANCE AGGREGATE OR ROCK BASE	14,771.50	0.00	14,771.50	SQYD	14,054.94	\$3.25	\$45,678.56
		0001	0160	4010101	8 INCHES, BITUMINOUS PAVEMENT	1,195.20	-809.20	386.00	SQYD	385.99	\$50.00	\$19,299.50
		0001	0170	4010150	TYPE A2 SHOULDER	2,115.70	0.00	2,115.70	SQYD	1,867.02	\$40.00	\$74,680.80
		0001	0180	4019905	MISC.OPTIONAL PAVEMENT	5,100.50	0.00	5,100.50	SQYD	5,100.10	\$54.00	\$275,405.40
		0001	0190	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	95.00	0.00	95.00	TONS	0.00	\$165.00	\$0.00
	0001	0200	4030306	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP250C MIX)	45.40	0.00	45.40	TONS	0.00	\$130.00	\$0.00	
		0001	0210	4030308	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP250C MIX)	23.70	0.00	23.70	TONS	0.00	\$130.00	\$0.00
		0001	0220	4039905	MISC.OPTIONAL TEMPORARY PAVEMENT	1,055.90	0.00	1,055.90	SQYD	787.70	\$44.52	\$35,068.40
		0001	0230	4071005	TACK COAT	100.00	0.00	100.00	GAL	0.00	\$5.00	\$0.00
		0001 0240 0001 0250	0240	5021309	CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	5,711.90	0.00	5,711.90	SQYD	5,709.78	\$54.00	\$308,328.12
			0250	5029905	MISC.MODIFIED COLORED CONCRETE PAVEMENT (9 IN. NON-REINFORCED 15 FT. JOINTS)	502.20	0.00	502.20	SQYD	153.70	\$105.00	\$16,138.50
		0001	0260	6042020	ADJUSTING BASIN OR INLET	1.00	0.00	1.00	EA	1.00	\$500.00	\$500.00
		0001	0270	6049902	MISC.ADJUSTING MANHOLES AND VALVES	4.00	0.00	4.00	EA	3.00	\$350.00	\$1,050.00
		0001	0280	6049902	MISC.REMOVE AND REPLACE INLET STONE	2.00	0.00	2.00	EA	2.00	\$700.00	\$1,400.00
		0001	0290	6071050	CHAIN-LINK FENCE (RETAINING WALLS)	240.00	0.00	240.00	LF	0.00	\$31.57	\$0.00
		0001	0300	6081012	TRUNCATED DOMES	32.00	0.00	32.00	SQFT	0.00	\$25.00	\$0.00
		0001	0310	6085008	PAVED APPROACH, 8 IN.	137.90	0.00	137.90	SQYD	137.90	\$54.00	\$7,446.60
		0001	0320	6086004	CONCRETE SIDEWALK, 4 IN.	685.80	0.00	685.80	SQYD	100.00	\$35.00	\$3,500.00
		0001	0330	6089902	MISC.ADA CONCRETE CURB RAMP	10.00	0.00	10.00	EA	0.00	\$1,600.00	\$0.00
		0001	0340	6089905	MISC.MODIFIED COLORED 6" CONCRETE MEDIAN STRIP	671.00	0.00	671.00	SQYD	200.00	\$90.00	\$18,000.00
		0001	0350	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	620.00	0.00	620.00	LF	0.00	\$30.00	\$0.00
		0001	0360	6091041	CONCRETE GUTTER TYPE A	85.00	0.00	85.00	LF	34.70	\$101.00	\$3,504.70
		0001	0370	6091042	CONCRETE GUTTER TYPE B	237.00	0.00	237.00	LF	237.00	\$50.00	\$11,850.00
		0001	0380	6091052	CURB AND GUTTER TYPE B	1,821.00	0.00	1,821.00	LF	1,478.60	\$30.00	\$44,358.00
		0001	0390	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	122.00	0.00	122.00	LF	121.90	\$17.00	\$2,072.30
		0001	0400	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	451.00	0.00	451.00	LF	0.00	\$18.00	\$0.00
		0001	0410	6097000	ROCK LINING	24.00	0.00	24.00	CUYD	24.00	\$70.00	\$1,680.00
		0001	0420	6099903	MISC.MODIFIED CURB AND GUTTER TYPE A (1' GUTTER PAN)	504.00	0.00	504.00	LF	504.00	\$30.00	\$15,120.00
		0001	0430	6099903	MISC.MODIFIED CURB AND GUTTER TYPE A (2.5' GUTTER PAN)	129.00	0.00	129.00	LF	129.00	\$30.00	\$3,870.00
		0001	0440	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	5.00	0.00	5.00	EA	3.00	\$800.00	\$2,400.00
		0001	0450	6143011	MANHOLE FRAME AND COVER, TYPE 1-B	1.00	0.00	1.00	EA	1.00	\$360.00	\$360.00

Revision 4/1/2020 Page 6 of 36



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

iote: Posted Q	uantities	and valu	es are t	pased on R	eport Generated date and can differ from the posted am	ount at the	time the	Estimate wa	is Gene	rated.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210319-F07	J6S3408	0001	0460	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	5.00	0.00	5.00	EA	4.00	\$9,000.00	\$36,000.00
		0001	0470	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.91	\$40,000.00	\$36,400.00
		0001	0480	6169901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	1.00	\$30,720.00	\$30,720.00
		0001	0490	6169902	MISC.SPECIAL ST. CHARLES COUNTY ROAD BOARD SIGN, POSTS, AND INSTALLATION	5.00	0.00	5.00	EA	4.00	\$350.00	\$1,400.00
		0001	0500	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$205,000.00	\$205,000.00
		0001	0510	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	7.00	0.00	7.00	EA	2.00	\$600.00	\$1,200.00
		0001	0520	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	54.00	0.00	54.00	LF	0.00	\$6.25	\$0.00
		0001	0530	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	90.00	0.00	90.00	LF	0.00	\$12.50	\$0.00
		0001	0540	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	85.00	0.00	85.00	LF	0.00	\$25.00	\$0.00
		0001	0550	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	14.00	0.00	14.00	EA	6.00	\$350.00	\$2,100.00
		0001	0560	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	9.00	0.00	9.00	EA	0.00	\$300.00	\$0.00
		0001	0570	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	1.00	0.00	1.00	EA	0.00	\$650.00	\$0.00
		0001	0580	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	10.00	0.00	10.00	EA	0.00	\$200.00	\$0.00
		0001	0590	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	58.00	0.00	58.00	EA	24.00	\$35.00	\$840.00
		0001	0600	6200045	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW	6.00	0.00	6.00	EA	0.00	\$1,200.00	\$0.00
		0001	0610	6200051	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT FISH HOOK ARROW	6.00	0.00	6.00	EA	0.00	\$1,200.00	\$0.00
		0001	0620	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,117.00	0.00	4,117.00	LF	0.00	\$0.45	\$0.00
		0001	0630	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,867.00	0.00	7,867.00	LF	0.00	\$0.45	\$0.00
		0001	0640	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,210.00	0.00	2,210.00	LF	0.00	\$0.45	\$0.00
		0001	0650	6207001	PAVEMENT MARKING REMOVAL	20,202.00	0.00	20,202.00	LF	5,871.00	\$0.75	\$4,403.25
		0001	0660	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	20.00	0.00	20.00	EA	11.00	\$100.00	\$1,100.00
		0001	0670	6209903	MISC."24 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS"	115.00	0.00	115.00	LF	0.00	\$10.00	\$0.00
		0001	0680	6209903	MISC."24 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS"	262.00	0.00	262.00	LF	65.00	\$10.00	\$650.00
		0001	0690	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	869.00	0.00	869.00	SQYD	0.00	\$4.00	\$0.00
		0001	0700	6240104A	SEPARATION GEOTEXTILE	14,772.00	0.00	14,772.00	SQYD	14,219.00	\$2.00	\$28,438.00
		0001	0710	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.95	\$20,000.00	\$19,000.00
		0001	0720	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,200.00	\$3,200.00
		0001	0730	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,200.00	\$3,200.00
		0001	0740	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	2,393.00	0.00	2,393.00	SQFT	2,393.00	\$65.00	\$155,545.00
		0001	0750	7261012	12 IN. PIPE GROUP A	200.00	0.00	200.00	LF	200.00	\$60.00	\$12,000.00
		0001	0760	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	6.00	0.00	6.00	FT	6.00	\$400.00	\$2,400.00
		0001	0770	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	28.00	0.00	28.00	FT	28.00	\$260.00	\$7,280.00
		0001	0780	7320612A	12 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$600.00	\$600.00
		0001	0790	8031000A	TURF TYPE TALL FESCUE SODDING	5,958.00	0.00	5,958.00	SQYD	880.00	\$6.00	\$5,280.00
		0001	0800	8051000A	SEEDING - COOL SEASON MIXTURES	2.30	0.00	2.30	ACRE	0.98	\$12,100.00	\$11,858.00
		0001	0810	8061005	ROCK DITCH CHECK	480.00	0.00	480.00	LF	186.00	\$15.00	\$2,790.00
		0001	0820	8061007A	CURB INLET CHECK	19.00	0.00	19.00	EA	1.00	\$125.00	\$125.00
		0001	0830	8061016	SEDIMENT REMOVAL	98.00	0.00	98.00	CUYD	3.00	\$20.00	\$60.00
		0001	0840	8061017	TEMPORARY SEEDING AND MULCHING	2.40	0.00	2.40	ACRE	0.00	\$1,500.00	\$0.00
		0001	0850	8061019	SILT FENCE	4,027.00	0.00	4,027.00	LF	3,131.00	\$2.85	\$8,923.35
		0010	0860	6061060	MGS GUARDRAIL	600.00	0.00	600.00	LF	550.00	\$20.85	\$11,467.50
					MGS HEIGHT AND BLOCK TRANSITION	4.00	0.00	4.00	EA	3.00	\$768.21	\$2,304.63

Page 7 of 36 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210319-F07	J6S3408	0010	0880	6061080	MGS END ANCHOR	4.00	0.00	4.00	EA	3.00	\$956.20	\$2,868.60
		0010	0890	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	6.00	\$2,311.40	\$13,868.40
		0020	0900	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	15.00	0.00	15.00	EA	15.00	\$2,176.00	\$32,640.00
		0020	0910	9011106	BRACKET ARM, 6 FT. OR 1.8 M	15.00	0.00	15.00	EA	15.00	\$550.00	\$8,250.00
		0020	0920	9011311	LUMINAIRE, LED-A	15.00	0.00	15.00	EA	15.00	\$400.00	\$6,000.00
		0020	0930	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	12.00	0.00	12.00	LF	128.00	\$18.00	\$2,304.00
		0020	0940	9014003	CONDUIT, 3 IN. RIGID, PUSHED	340.00	0.00	340.00	LF	212.00	\$22.00	\$4,664.00
		0020	0950	9015010	TRENCHING TYPE I	1,234.00	0.00	1,234.00	LF	1,234.00	\$7.00	\$8,638.00
		0020	0960	9016110	PULL BOX, PREFORMED CLASS 1	9.00	0.00	9.00	EA	9.00	\$1,217.00	\$10,953.00
		0020	0970	9016112	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$1,470.00	\$1,470.00
		0020	0980	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	1,080.00	0.00	1,080.00	LF	1,080.00	\$0.50	\$540.00
		0020	0990	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,930.00	0.00	1,930.00	LF	1,837.00	\$3.00	\$5,511.00
		0020	1000	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	15.00	0.00	15.00	EA	15.00	\$990.00	\$14,850.00
		0020	1010	9019902	MISC.240/480V MULTI-CIRCUIT PAD MOUNTED POWER SUPPLY	1.00	0.00	1.00	EA	1.00	\$8,840.00	\$8,840.00
		0040	1020	9031010	CONCRETE FOOTINGS, EMBEDDED	12.29	0.00	12.29	CUYD	4.11	\$631.37	\$2,594.93
		0040	1030	9031020	CONCRETE FOOTINGS, BOLT DOWN	20.00	0.00	20.00	CUYD	5.20	\$1,762.49	\$9,164.95
		0040	1040	9031210	STRUCTURAL STEEL POSTS	1,842.00	0.00	1,842.00	LB	0.00	\$3.88	\$0.00
		0040	1050	9031220	PIPE POSTS	6,920.00	0.00	6,920.00	LB	2,663.00	\$3.18	\$8,468.34
		0040	1060	9031242	36 IN. SURFACE-MOUNT DELINEATOR POST	12.00	0.00	12.00	EA	0.00	\$76.10	\$0.00
		0040	1070	9035004A	SH-FLAT SHEET	383.60	0.00	383.60	SQFT	133.60	\$23.74	\$3,171.66
		0040	1080	9035011A	ST-STRUCTURAL	753.00	0.00	753.00	SQFT	360.00	\$17.59	\$6,332.40
		0040	1090	9035069A	SHF-FLAT SHEET FLUORESCENT	225.50	0.00	225.50	SQFT	118.75	\$24.41	\$2,898.69
		0040	1100	9039901	MISC.TUBULAR SUPPORT, TYPE S - 27718, 52 FT. (TWO TUBES)	1.00	0.00	1.00	LS	0.00	\$43,008.45	\$0.00
		0040	1110	9039901	MISC.TUBULAR SUPPORT, TYPE S - 27718, 55 FT. (TWO TUBES)	1.00	0.00	1.00	LS	0.00	\$43,596.45	\$0.00
		0050	1120	8089901	MISC.IRRIGATION SYSTEM	1.00	0.00	1.00	LS	0.00	\$41,387.50	\$0.00
		0050	1130	8089901	MISC.LANDSCAPE LIGHTING	1.00	0.00	1.00	LS	0.00	\$2,940.00	\$0.00
		0050	1140	8089902	MISC.BLACK-EYED SUSAN	106.00	0.00	106.00	EA	0.00	\$45.00	\$0.00
		0050	1150	8089902	MISC.JADE PILLAR BOXWOOD	40.00	0.00	40.00	EA	0.00	\$56.00	\$0.00
		0050	1160	8089902	MISC.JAPANESE BARBERRY	104.00	0.00	104.00	EA	0.00	\$53.00	\$0.00
		0050	1170	8089902	MISC.REDOSIER DOGWOOD	24.00	0.00	24.00	EA	0.00	\$53.00	\$0.00
		0050	1180	8089902	MISC.SHAMROCK INKBERRY	82.00	0.00	82.00	EA	0.00	\$53.00	\$0.00
		0050	1190	8089902	MISC.SPARTAN JUNIPER	10.00	0.00	10.00	EA	0.00	\$390.00	\$0.00
		0050	1200	8089902	MISC.TUFTED HAIR GRASS	104.00	0.00	104.00	EA	0.00	\$14.00	\$0.00
		0050	1210	8089907	MISC.SHREDDED HARDWOOD MULCH	62.00	0.00	62.00	CUYD	0.00	\$58.00	\$0.00
		0020	5001	7071000	CONDUIT SYSTEM ON STRUCTURE	0.00	1.00	1.00	LS	1.00	\$4,872.00	\$4,872.00
		0020	5002	7071000	CONDUIT SYSTEM ON STRUCTURE	0.00	1.00	1.00	LS	1.00	\$5,357.10	\$5,357.10
		0001	5003	5021307	CONCRETE PAVEMENT (7 IN. NON-REINFORCED, 15 FT. JOINTS)	0.00	809.20	809.20	SQYD	809.20	\$50.00	\$40,460.00
		0001	5004	6191000	PAVEMENT EDGE TREATMENT	0.00	1,000.00	1,000.00	LF	1,000.00	\$3.50	\$3,500.00
	Project J	6S3408 - To	otal Value	Posted to D	late as of Report Generated Date							\$2,276,579.78
210319-F07 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$2,276,579.78

Page 8 of 36 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	2031000	CLASS A EXCAVATION	3/22/22	4/4/22	66.00	CUYD	EB I-70 off ramp	297+00		299+23		
				4/4/22	124.00		Roundabout center	106+75		108+75		
0060	2036000	COMPACTING EMBANKMENT	3/22/22	4/4/22	42.00		EB I-70 on ramp	300+92		303+55		
				4/4/22	54.00		EB I-70 off ramp	297+00		299+23		
				4/4/22	106.00		Roundabout center	106+75		108+75		
0070	2037075	COMPACTING IN CUT	3/22/22		1.10	STA		297+00		299+23		
0010	2007070	761116111601	O'LL'LL	4/4/22	2.00	STA		106+75		108+75		
0120	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	4/1/22		100.00		VMP west south side of road just east of Bank entrance	495+66		497+50		
0320		` '		4/4/22	100.00		VMP west south side of road just east of Bank entrance	495+66		497+50		
							,	RT		RT		
0550	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	3/17/22		3.00		LSL BLVD qty 3 locations, 109+96, 110+42, 110+54 RT	109+96 RT		110+42 LT		
				4/4/22	3.00		VMP east, qty 3 LT arrows, location STA 503+20, 504+24, 505+42 RT	503+20 RT		504+24 RT		
0590	6200042	PREF THERMO PVMT MARK, YIELD TRIAN	3/17/22		7.00		East bound I-70 off ramp	299+28 RT				
				4/4/22	8.00	EA	East bound I-70 off ramp	299+26 RT				
				4/4/22	9.00	EA	VMP, east side of roundabout	498+85 RT				
0680	6209903	MISC. PAVEMENT MARKINGS	3/17/22	4/4/22	65.00	LF	VMP east of roundabout, Diagonal hatching	506+00 RT		507+47 RT		
0710	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKI	4/1/22	4/4/22	0.40	LS	LSL BLVD north of I-70 and Islands & Guardrail layouts south of I-70	100+48		110+72		
0720	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	3/24/22	4/4/22	1.00	LS	MSE Wall	495+90		498+07		
0730	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	3/24/22	4/4/22	1.00	LS	MSE Wall	495+90		498+07		
0860	6061060	MGS GUARDRAIL	3/24/22	4/4/22	25.00	LF	EB I-70 off ramp	296+64 LT		297+50 LT		
				4/4/22	25.00	LF	LSL BLVD north of roundabout	106+50 LT		107+33 LT		
				4/4/22	50.00	LF	VMP west of roundabout	492+36 LT		493+83 LT		
			3/25/22	4/4/22	175.00	LF	VMP, west of roundabout, south side of road	495+73 RT		498+01		
0870	6061074	MGS HEIGHT AND BLOCK TRANSITION	3/24/22	4/4/22	1.00	EA	LSL BLVD north of roundabout	106+50 LT		107+33 LT		
0880	6061080	MGS END ANCHOR	3/24/22	4/4/22	1.00	EA	EB I-70 off ramp	296+64 LT		297+50 LT		
			3/25/22	4/4/22	1.00	EA	VMP, west of roundabout, south side of road	495+73 RT		498+01 RT		
0890	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	3/24/22	4/4/22	1.00	EA	EB I-70 off ramp	296+64 LT		297+50 LT		
				4/4/22	1.00	EA	LSL BLVD north of roundabout	106+50 LT		107+33 LT		
				4/4/22	2.00	EA	VMP west of roundabout	492+36 LT		493+83 LT		
			3/25/22	4/4/22	1.00	EA	VMP, west of roundabout, south side of road	495+73 RT		498+01 RT		
1070	9035004A	SH-FLAT SHEET	3/25/22	4/4/22	1.50	SOFT	VMP, Sign #31, qty 1 R7-1	496+80				
.010	_00000474		0,20,22	4/4/22	1.50		VMP, sign #42, qty 1 R7-1	505+00				
				4/4/22	1.50		VMP, sign #42, qty 1 R7-1 VMP, sign #44, qty 1 R7-1	507+50				
				4/4/22	4.40							
				4/4/22			EB I-70 off ramp, sign #60, qty 1 M6-1	107+57				
					4.50		EB I-70 off ramp, sign #60, qty 1 D9-12qp	107+57				
				4/4/22	9.00		EB I-70 off ramp, sign #60, qty 1 D9-2	107+57				
				4/4/22	25.00		LSL BLVD, sign #11 qty 1 yield R1-2	109+16				
				4/4/22	25.00		VMP, sign #34, qty 1 R1-2	498+83				
				4/4/22			VMP, sign #38, qty 1 R1-2	501+04				
1090	9035069A	SHF-FLAT SHEET FLUORESCENT	3/25/22	4/4/22			LSL BLVD, sign #12, qty 1 w16-7p	109+45				
				4/4/22	3.00	SQFT	VMP, sign #43, qty 1 W16-17P	507+00				
				4/4/22	3.75	SQFT	LSL BLVD, sign #15, qty 1 w16-7p	109+55				
				4/4/22	4.00	SQFT	VMP, sign #43, qty 1 w13-1p 24"x24"	507+00				
				4/4/22	9.00	SQFT	EB I-70 off ramp, Sign #22, qty 1 w3-2	298+25				
				4/4/22	9.00	SQFT	LSL BLVD sign #12, qty 1 W11-2	109+45				
				4/4/22	9.00	SQFT	LSL BLVD, sign #15, qty 1 w11-2	109+55				
				4/4/00	0.00	COET	VMP, sign #32, qty 1 w3-2	497+50				
				4/4/22	9.00	SQFI	vivir, sigii #32, qty i w3-2	431130				
				4/4/22	9.00		VMP, sign #39, qty 1 w3-2	502+25				

The information below this line are details for Construction Signs (if applicable), No Data Available

Revision 4/1/2020 Page 9 of 36



Project Line Desc	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408 0040 EXC	CLASS A Price FUEL AVATION		2	Jun 2, 2021	SYSTEM	\$70.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			2	Jun 2, 2021	SYSTEM	\$44.24	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			9	Sep 16, 2021	SYSTEM	\$6.50	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			10	Oct 1, 2021	SYSTEM	\$1.95	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			11	Oct 18, 2021	SYSTEM	\$19.15	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			14	Dec 2, 2021	SYSTEM	\$5.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			15	Dec 16, 2021	SYSTEM	\$46.62	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			22	Apr 4, 2022	SYSTEM	\$27.36	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		- Total				\$222.03	
	Price FUEL	- Total				\$222.03	
0040 - Total						\$222.03	
	NKMENT Price FUEL N PLACE		11	Oct 18, 2021	SYSTEM	\$189.34	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			14	Dec 2, 2021	SYSTEM	\$72.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
			15	Dec 16, 2021	SYSTEM	\$246.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		- Total				\$508.53	
	Price FUEL	- Total				\$508.53	
0050 - Total						\$508.53	
	PACTING Material NKMENT		3	Jun 16, 2021	SYSTEM	\$780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			3	Jun 16, 2021	SYSTEM	(\$780.00)	
			4	Jul 2, 2021	SYSTEM	\$780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			4	Jul 2, 2021	SYSTEM	(\$780.00)	
			5	Jul 16, 2021	SYSTEM	\$780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
			5	Jul 16, 2021	SYSTEM	(\$780.00)	
		- Total				\$0.00	
	Material - T	otal				\$0.00	
0060 - Total						\$0.00	
0070 COM	PACTING Material		3	Jun 16, 2021	SYSTEM	\$675.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment
	IN CUT						Estimate Exception 2 on the current Payment Estimate.
	IN CUT		3	Jun 16, 2021	SYSTEM	(\$675.00)	Estimate Exception 2 on the current Payment Estimate.
	IN CUT		3		SYSTEM	(\$675.00) \$675.00	Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
	IN CUT			2021 Jul 2,		, ,	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment
	IN CUT		4	Jul 2, 2021 Jul 2, Jul 2,	SYSTEM	\$675.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment
	IN CUT		4	Jul 2, 2021 Jul 2, 2021 Jul 2, 2021 Jul 16,	SYSTEM	\$675.00 (\$675.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	0070	COMPACTING IN CUT	Material - To	tal				\$0.00	
	0070 -	· Total						\$0.00	
	0120	TYPE 1 AGGREGATE	Price FUEL		22	Apr 4, 2022	SYSTEM	\$10.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		FOR BASE (4 IN. THICK)		- Total				\$10.80	
			Price FUEL -	Total				\$10.80	
	0120 -	- Total						\$10.80	
	0130	TYPE 5 AGGREGATE FOR BASE	Material		5	Jul 16, 2021	SYSTEM	\$1,874.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$1,874.40)	
					6	Aug 2, 2021	SYSTEM	\$1,874.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,874.40)	
					7	Aug 16, 2021	SYSTEM	\$1,874.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$1,874.40)	
					8	Sep 2, 2021	SYSTEM	\$2,261.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$2,261.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		5	Jul 16, 2021	SYSTEM	\$4.92	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 2, 2021	SYSTEM	\$1.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					16	Jan 3, 2022	SYSTEM	\$5.67	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					17	Jan 18, 2022	SYSTEM	\$2.55	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$14.74	
			Price FUEL -	Total				\$14.74	
	0130	- Total						\$14.74	
	0140	AGGREGATE FOR BASE (6 IN.	Material		3	Jun 16, 2021	SYSTEM	\$11,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		THICK)			3	Jun 16, 2021	SYSTEM	(\$11,160.00)	
					4	Jul 2, 2021	SYSTEM	\$37,937.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jul 2, 2021	SYSTEM	(\$37,937.00)	
					5	Jul 16, 2021	SYSTEM	\$37,937.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$37,937.00)	
					6	Aug 2, 2021	SYSTEM	\$43,614.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$43,614.00)	
					7	Aug 16, 2021	SYSTEM	\$49,373.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	0140	TYPE 5 AGGREGATE	Material		7	Aug 16, 2021	SYSTEM	(\$49,373.00)	
		FOR BASE (6 IN. THICK)			8	Sep 2, 2021	SYSTEM	\$52,737.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$52,737.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Price FUEL		3	Jun 16, 2021	SYSTEM	\$30.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 2, 2021	SYSTEM	\$73.91	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Aug 2, 2021	SYSTEM	\$18.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Aug 16, 2021	SYSTEM	\$29.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 2, 2021	SYSTEM	\$17.03	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Sep 16, 2021	SYSTEM	\$2.06	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Oct 1, 2021	SYSTEM	\$6.58	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Oct 18, 2021	SYSTEM	\$95.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Nov 2, 2021	SYSTEM	\$47.60	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Nov 16, 2021	SYSTEM	\$40.43	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Dec 2, 2021	SYSTEM	\$104.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					15	Dec 16, 2021	SYSTEM	\$240.36	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					16	Jan 3, 2022	SYSTEM	\$19.24	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					17	Jan 18, 2022	SYSTEM	\$39.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					18	Feb 1, 2022	SYSTEM	\$8.51	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					19	Feb 16, 2022	SYSTEM	\$158.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					21	Mar 16, 2022	SYSTEM	\$66.24	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$997.27	
			Price FUEL -	Total				\$997.27	
	0140 -							\$997.27	
	0150	MISC. AGGREGATE FOR BASE	Material		4	Jul 2, 2021	SYSTEM	\$12,329.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Jul 2, 2021	SYSTEM	(\$12,329.33)	
					5	Jul 16, 2021	SYSTEM	\$12,329.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$12,329.33)	
					6	Aug 2, 2021	SYSTEM	\$14,174.03	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$14,174.03)	
					7	Aug 16, 2021	SYSTEM	\$16,045.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	0150	MISC.	Material						Estimate Exception 3 on the current Payment Estimate.
		AGGREGATE FOR BASE			7	Aug 16, 2021	SYSTEM	(\$16,045.38)	
					8	Sep 2, 2021	SYSTEM	\$16,914.43	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$16,914.43)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0150 -	Total						\$0.00	
	0160	8 INCHES, BITUMINOUS	Other Item Adjustment	ACAD	6	Aug 2, 2021	brinkr1	\$91.53	170.50 Sq.Yds BB20-3, 5th Estimate period, enterance to Haddock Lane
		PAVEMENT			6	Aug 2, 2021	brinkr1	\$95.74	215.50 Sq.Yds BB20-2 215.50 Sq. Yds BP120-8 Location entrance to Rue Petit
				ACAD - Tota	al			\$187.27	
			Other Item A	djustment - T	otal			\$187.27	
			Price FUEL		4	Jul 2, 2021	SYSTEM	\$37.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Jul 16, 2021	SYSTEM	\$34.88	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$72.65	
			Price FUEL -	Total				\$72.65	
	0160 -	Total						\$259.92	
	0170	TYPE A2 SHOULDER	Material		4	Jul 2, 2021	SYSTEM	\$17,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	Jul 2, 2021	SYSTEM	(\$17,840.00)	
					5	Jul 16, 2021	SYSTEM	\$26,828.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$26,828.80)	
					6	Aug 2, 2021	SYSTEM	\$27,920.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$27,920.80)	
					7	Aug 16, 2021	SYSTEM	\$27,920.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$27,920.80)	
					8	Sep 2, 2021	SYSTEM	\$28,220.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$28,220.80)	
					9	Sep 16, 2021	SYSTEM	\$28,220.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$28,220.80)	
					10	Oct 1, 2021	SYSTEM	\$28,220.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$28,220.80)	
					11	Oct 18, 2021	SYSTEM	\$28,220.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Oct 18,	SYSTEM	(\$28,220.80)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	0170	TYPE A2	Material			2021			
		SHOULDER			12	Nov 2, 2021	SYSTEM	\$32,960.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$32,960.80)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0170 -	Total						\$0.00	
	0180	MISC.	Material		7	Aug 16, 2021	SYSTEM	\$147,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$147,555.00)	
					8	Sep 2, 2021	SYSTEM	\$153,100.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$153,100.80)	
					9	Sep 16, 2021	SYSTEM	\$153,100.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$153,100.80)	
					10	Oct 1, 2021	SYSTEM	\$153,100.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$153,100.80)	
					11	Oct 18, 2021	SYSTEM	\$153,100.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$153,100.80)	
					12	Nov 2, 2021	SYSTEM	\$163,074.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$163,074.60)	
					13	Nov 16, 2021	SYSTEM	\$184,642.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Nov 16, 2021	SYSTEM	(\$184,642.20)	
					15	Dec 16, 2021	SYSTEM	\$165,304.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Dec 16, 2021	SYSTEM	(\$165,304.80)	
					16	Jan 3, 2022	SYSTEM	\$167,405.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Jan 3, 2022	SYSTEM	(\$167,405.40)	
					17	Jan 18, 2022	SYSTEM	\$59,405.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$59,405.40)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Other Item Adjustment	ACAD	6	Aug 2, 2021	brinkr1	\$56.01	167.00 Sq.Yds BB20-2 167.00 Sq.Yds BP120-8 Location VMP shoulder RT from Rue Petit to STA 507+75
				ACAD - Tota	al			\$56.01	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	0180	MISC.	Other Item A	djustment - T	otal			\$56.01	
	0180 -	- Total						\$56.01	
	0220	MISC.	Material		5	Jul 16, 2021	SYSTEM	\$10,431.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$10,431.04)	
					6	Aug 2, 2021	SYSTEM	\$10,431.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$10,431.04)	
					7	Aug 16, 2021	SYSTEM	\$10,431.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$10,431.04)	
					8	Sep 2, 2021	SYSTEM	\$12,585.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$12,585.80)	
					9	Sep 16, 2021	SYSTEM	\$12,585.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$12,585.80)	
					10	Oct 1, 2021	SYSTEM	\$12,585.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$12,585.80)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0220 -	- Total						\$0.00	
	0240	CONCRETE PAVEMENT (9 IN. NON- REINFORCED.	Material		3	Jun 16, 2021	SYSTEM	\$20,034.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		TILITI OTTOLD,							
					3	Jun 16, 2021	SYSTEM	(\$20,034.00)	
					4		SYSTEM	(\$20,034.00) \$35,143.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
						2021 Jul 2,			Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment
					4 5	Jul 2, 2021 Jul 2, 2021 Jul 2, 2021 Jul 16, 2021	SYSTEM SYSTEM	\$35,143.20 (\$35,143.20) \$45,558.72	Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment
					4 5 5	Jul 2, 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021	SYSTEM SYSTEM SYSTEM	\$35,143.20 (\$35,143.20) \$45,558.72 (\$45,558.72)	Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4 4 5 5 6	2021 Jul 2, 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM	\$35,143.20 (\$35,143.20) \$45,558.72	Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment
					4 5 5	2021 Jul 2, 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	\$35,143.20 (\$35,143.20) \$45,558.72 (\$45,558.72) \$60,511.32 (\$60,511.32)	Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment
				- Total	4 4 5 5 6	2021 Jul 2, 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$35,143.20 (\$35,143.20) \$45,558.72 (\$45,558.72) \$60,511.32 (\$60,511.32)	Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment
			Material - To Other Item		4 4 5 5 6	2021 Jul 2, 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$35,143.20 (\$35,143.20) \$45,558.72 (\$45,558.72) \$60,511.32 (\$60,511.32)	Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment
				tal	4 4 5 5 6	2021 Jul 2, 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021  Aug 2, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$35,143.20 (\$35,143.20) \$45,558.72 (\$45,558.72) \$60,511.32 (\$60,511.32) \$0.00	Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			Other Item	tal	4 4 5 5 6 6 6 6	2021 Jul 2, 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM  SYSTEM	\$35,143.20 (\$35,143.20) \$45,558.72 (\$45,558.72) \$60,511.32 (\$60,511.32) \$0.00 (\$8,403.99)	Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
			Other Item	tal	4 4 5 5 6 6 10	2021 Jul 2, 2021 Jul 2, 2021 Jul 16, 2021 Jul 16, 2021 Aug 2, 2021 Aug 2, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM brinkr1 brinkr1	\$35,143.20 (\$35,143.20) \$45,558.72 (\$45,558.72) \$60,511.32 (\$60,511.32) \$0.00 (\$8,403.99) (\$11,386.66)	Estimate Item Adjustment (0020) due to user brinkr1 overridding Paym Estimate Exception 7 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Paymer Estimate Item Adjustment (0002) due to user brinkr1 overridding Paym Estimate Exception 9 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Paymer Estimate Item Adjustment (0009) due to user brinkr1 overridding Paym Estimate Exception 7 on the current Payment Estimate.  Location VMP east LT, and center lane Lot 1  Location LSL BLVD south, LOT 2 cores



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	0240	CONCRETE	Other Item	PCCS		2021			amount, due to a 3rd party vender strength test of the same concrete roadway
		PAVEMENT (9 IN. NON-	Adjustment		14	Dec 2, 2021	brinkr1	\$1,150.20	Lot #3 concrete strength adjustment
		REINFORCED,		PCCS - Tota	ıl	2021		\$1,150.20	
				PCCT		Aug 2,	brinkr1	\$1,210.95	Location VMP east left lane and center lane, Lot 1
					10	2021 Oct 1, 2021	brinkr1	\$993.60	Location LSL BLVD south, Lot 2 cores
					14	Dec 2, 2021	brinkr1	\$1,150.20	Lot #3 concrete thickness adjustment
				PCCT - Tota	1	2021		\$3,354.75	
			Other Item A	djustment - T				\$4,504.95	
			Price FUEL		3	Jun 16, 2021	SYSTEM	\$29.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Jul 2, 2021	SYSTEM	\$22.16	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Jul 16, 2021	SYSTEM	\$17.82	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Aug 2, 2021	SYSTEM	\$25.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Sep 2, 2021	SYSTEM	\$17.93	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Oct 1, 2021	SYSTEM	\$18.88	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Oct 18, 2021	SYSTEM	\$123.58	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Nov 2, 2021	SYSTEM	\$52.53	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					15	Dec 16, 2021	SYSTEM	\$275.43	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					17	Jan 18, 2022	SYSTEM	\$107.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					18	Feb 1, 2022	SYSTEM	\$24.41	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					19	Feb 16, 2022	SYSTEM	\$990.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$1,705.90	
			Price FUEL -	Total				\$1,705.90	
	0240 -	Total						\$6,210.85	
	0250	MISC.	Material		8	Sep 2, 2021	SYSTEM	\$3,538.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$3,538.50)	•
					9	Sep 16, 2021	SYSTEM	\$3,538.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$3,538.50)	, , , , , , , , , , , , , , , , , , , ,
					10	Oct 1, 2021	SYSTEM	\$3,538.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$3,538.50)	•
					11	Oct 18, 2021	SYSTEM	\$3,538.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$3,538.50)	
					12	Nov 2, 2021	SYSTEM	\$3,538.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Nov 2,	SYSTEM	(\$3,538.50)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	0250	MISC.	Material			2021			
					13	Nov 16, 2021	SYSTEM	\$3,538.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Nov 16, 2021	SYSTEM	(\$3,538.50)	
					14	Dec 2, 2021	SYSTEM	\$3,538.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Dec 2, 2021	SYSTEM	(\$3,538.50)	
					17	Jan 18, 2022	SYSTEM	\$5,638.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$5,638.50)	
					18	Feb 1, 2022	SYSTEM	\$5,638.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandeb2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$5,638.50)	
					19	Feb 16, 2022	SYSTEM	\$5,638.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandeb2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	Feb 16, 2022	SYSTEM	(\$5,638.50)	
					20	Mar 2, 2022	SYSTEM	\$5,638.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$5,638.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0250 -	· Total	Material - To	tal				\$0.00 \$0.00	
	0250 - 0310	PAVED APPROACH, 8 IN.		tal	8	Sep 2, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
		PAVED APPROACH, 8		tal	8		SYSTEM SYSTEM	\$0.00	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment
		PAVED APPROACH, 8		tal		2021 Sep 2,		\$0.00 \$3,720.60	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment
		PAVED APPROACH, 8		tal	8	2021 Sep 2, 2021 Sep 16,	SYSTEM	\$0.00 \$3,720.60 (\$3,720.60)	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment
		PAVED APPROACH, 8		tal	8	2021 Sep 2, 2021 Sep 16, 2021 Sep 16,	SYSTEM SYSTEM	\$0.00 \$3,720.60 (\$3,720.60) \$7,446.60	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment
		PAVED APPROACH, 8		tal	9	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM	\$0.00 \$3,720.60 (\$3,720.60) \$7,446.60	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brinkr1 overridding Payment
		PAVED APPROACH, 8		tal	8 9 9	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,720.60 (\$3,720.60) \$7,446.60 (\$7,446.60)	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brinkr1 overridding Payment
		PAVED APPROACH, 8		tal	9 9 10	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,720.60 (\$3,720.60) \$7,446.60 (\$7,446.60) (\$7,446.60)	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment
		PAVED APPROACH, 8		tal	8 9 9 10 10	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,720.60 (\$3,720.60) \$7,446.60 (\$7,446.60) (\$7,446.60) \$7,446.60	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment
		PAVED APPROACH, 8		tal	8 9 9 10 10 11 11 11	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,720.60 (\$3,720.60) \$7,446.60 (\$7,446.60) \$7,446.60 (\$7,446.60)	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.
		PAVED APPROACH, 8		tal	8 9 9 10 10 11 11 11 12	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Nov 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$3,720.60 (\$3,720.60) \$7,446.60 (\$7,446.60) \$7,446.60 (\$7,446.60) \$7,446.60	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.
		PAVED APPROACH, 8		tal	8 9 9 10 10 11 11 11 12 12	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 18, 2021 Nov 2, 2021 Nov 16, 16, 16, 16, 16, 16, 16, 16, 16, 16,	SYSTEM	\$0.00 \$3,720.60 (\$3,720.60) \$7,446.60 (\$7,446.60) \$7,446.60 (\$7,446.60) \$7,446.60 (\$7,446.60)	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
6S3408	0310	PAVED	Material						Estimate Exception 2 on the current Payment Estimate.
		APPROACH, 8 IN.			14	Dec 2, 2021	SYSTEM	(\$7,446.60)	
					15	Dec 16, 2021	SYSTEM	\$7,446.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Dec 16, 2021	SYSTEM	(\$7,446.60)	
					16	Jan 3, 2022	SYSTEM	\$7,446.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Jan 3, 2022	SYSTEM	(\$7,446.60)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		8	Sep 2, 2021	SYSTEM	\$9.09	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Sep 16, 2021	SYSTEM	\$5.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$14.47	
			Price FUEL -	Total				\$14.47	
	0310 -	Total						\$14.47	
	0320	CONCRETE SIDEWALK, 4 IN.	Material		22	Apr 4, 2022	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$3,500.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0320 -	Total						\$0.00	
	0340	MISC. CONCRETE	Material		21	Mar 16, 2022	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user sandeb2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$18,000.00)	
					22	Apr 4, 2022	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brinkr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$18,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0340 -	Total						\$0.00	
	0350	CONCRETE CURB (6 IN. HEIGHT AND	Material		10	Oct 1, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
		UNDER)			10	Oct 1, 2021	SYSTEM	(\$3,360.00)	
					11	Oct 18, 2021	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$3,360.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0350 -	· Total						\$0.00	
	0360	CONCRETE GUTTER TYPE A	Material		6	Aug 2, 2021	SYSTEM	\$1,121.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$1,121.10)	



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3408	0360	CONCRETE GUTTER TYPE A	Material		7	Aug 16, 2021	SYSTEM	\$2,009.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$2,009.90)	
					8	Sep 2, 2021	SYSTEM	\$2,009.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$2,009.90)	
					9	Sep 16, 2021	SYSTEM	\$2,009.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$2,009.90)	
					10	Oct 1, 2021	SYSTEM	\$2,009.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user brinkr1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$2,009.90)	
					11	Oct 18, 2021	SYSTEM	\$2,009.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$2,009.90)	
					12	Nov 2, 2021	SYSTEM	\$2,009.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$2,009.90)	
					13	Nov 16, 2021	SYSTEM	\$2,009.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					13	Nov 16, 2021	SYSTEM	(\$2,009.90)	
				- Total				\$0.00	
	0360 -	· Total	Material - To	tal				\$0.00 \$0.00	
	0370	CONCRETE	Material		11	Oct 18,	SYSTEM	\$11,850.00	This adjustment offsets the original system-generated Material Payment
		GUTTER TYPE B	iviateriai			2021			Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
		GUTTER TYPE B	Material		11	2021 Oct 18, 2021	SYSTEM	(\$11,850.00)	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment
		GUTTER TYPE B	Waterial		11 12	Oct 18,	SYSTEM	(\$11,850.00) \$11,850.00	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment
		GUTTER TYPE B	waterial			Oct 18, 2021 Nov 2,			Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment
		GUTTER TYPE B	Water lai		12	Oct 18, 2021 Nov 2, 2021 Nov 2,	SYSTEM	\$11,850.00	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment
		GUTTER TYPE B	Water lai		12	Oct 18, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16,	SYSTEM SYSTEM	\$11,850.00 (\$11,850.00)	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment
		GUTTER TYPE B		- Total	12 12 13	Oct 18, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16, 2021	SYSTEM SYSTEM	\$11,850.00 (\$11,850.00) \$11,850.00 (\$11,850.00)	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment
			Material - To		12 12 13	Oct 18, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16, 2021	SYSTEM SYSTEM	\$11,850.00 (\$11,850.00) \$11,850.00 (\$11,850.00) \$0.00	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment
	0370 -				12 12 13	Oct 18, 2021 Nov 2, 2021 Nov 2, 2021 Nov 16, 2021	SYSTEM SYSTEM	\$11,850.00 (\$11,850.00) \$11,850.00 (\$11,850.00)	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment
		Total CURB AND	Material - To		12 12 13	Oct 18, 2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$11,850.00 (\$11,850.00) \$11,850.00 (\$11,850.00) \$0.00 \$0.00	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.
		Total CURB AND	Material - To		12 12 13 13	Oct 18, 2021  Nov 2, 2021  Nov 16, 2021  Nov 16, 2021  Jul 2, 2021  Jul 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$11,850.00 (\$11,850.00) \$11,850.00 (\$11,850.00) \$0.00 \$0.00 \$4,320.00	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3408	0380	CURB AND	Material			2021			
		GUTTER TYPE B			6	Aug 2, 2021	SYSTEM	\$4,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Aug 2, 2021	SYSTEM	(\$4,320.00)	
					7	Aug 16, 2021	SYSTEM	\$4,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$4,320.00)	
					8	Sep 2, 2021	SYSTEM	\$7,962.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$7,962.00)	
					9	Sep 16, 2021	SYSTEM	\$7,962.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
						9	Sep 16, 2021	SYSTEM	(\$7,962.00)
							10	Oct 1, 2021	SYSTEM
					10	Oct 1, 2021	SYSTEM	(\$9,558.00)	
				Total	11	Oct 18, 2021	SYSTEM	\$14,967.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					11	Oct 18,	SYSTEM	(\$14,967.00)	
						2021			
				- Total		2021		\$0.00	
			Material - To			2021		\$0.00 \$0.00	
	0380 -	·Total	Material - To			2021			
	<b>0380</b> -	INTEGRAL CURB (6 IN. HEIGHT AND	Material - To		8	Sep 2, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
		INTEGRAL CURB (6 IN.			8	Sep 2,	SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND				Sep 2, 2021		\$0.00 \$0.00 \$1,286.90	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND			8	Sep 2, 2021 Sep 2, 2021 Sep 16,	SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90)	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND			8	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16,	SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND			9	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1,	SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND			8 9 9	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90)	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND			8 9 9 10	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90)	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND			8 9 9 10 10	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) (\$1,286.90) \$1,286.90	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND		- Total	8 9 9 10 10	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90)	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment
		INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material	- Total	8 9 9 10 10	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90)	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment
	0390	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material	- Total	8 9 9 10 10	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90)	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment
	0390	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material  Material - To	- Total	9 9 10 10 11 11 11	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Oct 18, 2021 Oct 18, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$0.00 \$0.00	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
	0390	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material  Material - To	- Total	8 9 9 10 10 11 11 11 17	Sep 2, 2021 Sep 2, 2021 Sep 16, 2021 Oct 1, 2021 Oct 1, 2021 Oct 18, 2021 Jan 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$1,286.90 (\$1,286.90) \$0.00 \$0.00 \$1,680.00	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user brinkr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6S3408	0410 -	Total						\$0.00														
	0420	MISC. PAVED DRAINAGE	Material		21	Mar 16, 2022	SYSTEM	\$15,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user sandeb2 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
					21	Mar 16, 2022	SYSTEM	(\$15,120.00)														
				- Total				\$0.00														
			Material - To	tal				\$0.00														
	0420 -	Total						\$0.00														
	0430	MISC. PAVED DRAINAGE	Material		9	Sep 16, 2021	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.													
					9	Sep 16, 2021	SYSTEM	(\$2,475.00)														
						10	Oct 1, 2021	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user brinkr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.												
									10	Oct 1, 2021	SYSTEM	(\$2,475.00)										
					11	Oct 18, 2021	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.													
										11	Oct 18, 2021	SYSTEM	(\$2,475.00)									
					12	Nov 2, 2021	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.													
														12	Nov 2, 2021	SYSTEM	(\$2,475.00)					
								13	Nov 16, 2021	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.										
											13	Nov 16, 2021	SYSTEM	(\$2,475.00)								
					16	Jan 3, 2022	SYSTEM	\$3,882.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.													
							16	Jan 3, 2022	SYSTEM	(\$3,882.00)												
							17	Jan 18, 2022	SYSTEM	\$3,882.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.											
																		17	Jan 18, 2022	SYSTEM	(\$3,882.00)	
																						18
					18	Feb 1, 2022	SYSTEM	(\$3,882.00)														
			19 Feb 16, 2022 \$YSTEM \$3,882.00 This adjustment offsets the original sy Estimate Item Adjustment (0005) due Estimate Exception 2 on the current F  19 Feb 16, 2022 \$YSTEM (\$3,882.00)  20 Mar 2, 2022 \$YSTEM \$3,882.00 This adjustment offsets the original sy Estimate Item Adjustment (0002) due Estimate Exception 2 on the current F  20 Mar 2, 2022 \$YSTEM (\$3,882.00)  21 Mar 16, 2022 \$YSTEM \$3,870.00 This adjustment offsets the original sy Estimate Item Adjustment (0014) due Estimate Item Adjustment (0014) due					1	1	1	1	1	19		SYSTEM	\$3,882.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user sandeb2 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
														19		SYSTEM	(\$3,882.00)					
															2		2		20		SYSTEM	\$3,882.00
					21		SYSTEM	\$3,870.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user sandeb2 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					21	Mar 16, 2022	SYSTEM	(\$3,870.00)														
				- Total				\$0.00														



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
408	0430	MISC. PAVED	Material - Tot	tal				\$0.00	
		DRAINAGE	Overrun	Overrun	16	Jan 3, 2022	SYSTEM	\$12.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0006) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40.
					16	Jan 3, 2022	SYSTEM	(\$12.00)	
					17	Jan 18, 2022	SYSTEM	(\$12.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					17	Jan 18, 2022	SYSTEM	\$12.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40.
					18	Feb 1, 2022	SYSTEM	(\$12.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					18	Feb 1, 2022	SYSTEM	\$12.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40.
					19	Feb 16, 2022	SYSTEM	(\$12.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					19	Feb 16, 2022	SYSTEM	\$12.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40.
					20	Mar 2, 2022	SYSTEM	(\$12.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					20	Mar 2, 2022	SYSTEM	\$12.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 129.400; Overrun Quantity Balance 0.40.
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0430 -	Total						\$0.00	
	0450	MANHOLE FRAME AND COVER, TYPE 1- B	Material		3	Jun 16, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					3	Jun 16, 2021	SYSTEM	(\$360.00)	
				- Total					
			Material - Tot	tal				\$0.00	
	0450 -	Total						\$0.00	
	0520	PREF THERMO PAVMT MARKING, 6 IN			15	Dec 16, 2021	SYSTEM	\$260.10	Payment Estimate Item Adjustment generated Stockpile Transaction
		WHITE	OTIVII	- Total				\$260.10	
			Construction	Stockpile S	TMI - Total			\$260.10	
	0520 -	Total						\$260.10	
	0530	PREF THERMO PAVMT	Construction Stockpile STMI		15	Dec 16, 2021	SYSTEM	\$294.70	Payment Estimate Item Adjustment generated Stockpile Transaction
		MARKING, 12 IN WHITE	OTIVII	- Total				\$294.70	
			Construction	Stockpile S	TMI - Total			\$294.70	
	0530 -	Total						\$294.70	
	0540	PREF THERMO PVMT MARK, 24 IN WHIT	Construction Stockpile		15	Dec 16, 2021	SYSTEM	\$588.92	Payment Estimate Item Adjustment generated Stockpile Transaction
		IIM VV MII	STMI	- Total				\$588.92	
			Construction	Stockpile S	TMI - Total			\$588.92	
	0540 -	Total						\$588.92	
	0550	PREF THERMO PVMT MARK,	Construction Stockpile		22	Apr 4, 2022	SYSTEM	(\$596.10)	Payment Estimate Item Adjustment generated Stockpile Transaction
		LT/RT ARROW		- Total				(\$596.10)	
			Construction	Stockpile - 1	Γotal .			(\$596.10)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
408	0550	PREF THERMO PVMT MARK,	Construction Stockpile		15	Dec 16, 2021	SYSTEM	\$1,390.90	Payment Estimate Item Adjustment generated Stockpile Transaction	
		LT/RT ARROW	STMI	- Total				\$1,390.90		
			Construction	Stockpile S	ΓΜΙ - Total			\$1,390.90		
			Material		22	Apr 4, 2022	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					22	Apr 4, 2022	SYSTEM	(\$2,100.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
	0550 -	Total						\$794.80		
	0560	PREF THERMO PVMT MRKG, STRIAGHT	Construction Stockpile STMI		15	Dec 16, 2021	SYSTEM	\$874.65	Payment Estimate Item Adjustment generated Stockpile Transaction	
		ARROW	OTIVII	- Total				\$874.65		
			Construction	Stockpile S	TMI - Total			\$874.65		
	0560 -	Total						\$874.65		
	0570	PREF THERMO PVMT MARKING,	Construction Stockpile STMI		15	Dec 16, 2021	SYSTEM	\$180.92	Payment Estimate Item Adjustment generated Stockpile Transaction	
		COMBO		- Total				\$180.92		
			Construction	Stockpile S	TMI - Total			\$180.92		
	0570 -	Total						\$180.92		
	0590	PREF THERMO PVMT MARK, YIELD TRIAN	Construction Stockpile		22	Apr 4, 2022	SYSTEM	(\$132.08)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		TILLD TRIAIN		- Total				(\$132.08)		
			Construction	Stockpile - 1	Γotal			(\$132.08)		
				Construction Stockpile STMI		15	Dec 16, 2021	SYSTEM	\$319.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$319.20		
			Construction	onstruction Stockpile STMI - Total						
			Material		22	Apr 4, 2022	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					22	Apr 4, 2022	SYSTEM	(\$840.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
	0590 -	Total						\$187.12		
	0600	PREF THERMO PVMT MARK, LT/RT FISH	Stockpile		15	Dec 16, 2021	SYSTEM	\$1,613.22	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$1,613.22		
			Construction	Stockpile S	TMI - Total			\$1,613.22		
	0600 -	Total						\$1,613.22		
	0610	PREF THERMO PVMT MARK, COMBO FISH	Construction Stockpile STMI		15	Dec 16, 2021	SYSTEM	\$1,613.22	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$1,613.22		
			Construction	Stockpile S	TMI - Total			\$1,613.22		
	0610 -	Total						\$1,613.22		
	0680	MISC. PAVEMENT MARKINGS	Material		22	Apr 4, 2022	SYSTEM	\$650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					22	Apr 4, 2022	SYSTEM	(\$650.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
	0680 -	Total						\$0.00		
	0700	SEPARATION	Material		4	Jul 2,	SYSTEM	\$7,587.40	This adjustment offsets the original system-generated Material Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J6S3408	0700	GEOTEXTILE	Material			2021			Estimate Item Adjustment (0022) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.															
					4	Jul 2, 2021	SYSTEM	(\$7,587.40)																
					5	Jul 16, 2021	SYSTEM	\$7,587.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.															
					5	Jul 16, 2021	SYSTEM	(\$7,587.40)																
					6	Aug 2, 2021	SYSTEM	\$8,722.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.															
					6	Aug 2, 2021	SYSTEM	(\$8,722.80)																
					7	Aug 16, 2021	SYSTEM	\$9,874.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
					7	Aug 16, 2021	SYSTEM	(\$9,874.60)																
					8	Sep 2, 2021	SYSTEM	\$10,409.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 37 on the current Payment Estimate.															
					8	Sep 2, 2021	SYSTEM	(\$10,409.60)																
					9	Sep 16, 2021	SYSTEM	\$10,409.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.															
					9	Sep 16, 2021	SYSTEM	(\$10,409.60)																
					10	Oct 1, 2021	SYSTEM	\$10,849.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user brinkr1 overridding Payment Estimate Exception 35 on the current Payment Estimate.															
					10	Oct 1, 2021	SYSTEM	(\$10,849.60)																
					11	Oct 18, 2021	SYSTEM	\$12,816.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.															
					11	Oct 18, 2021	SYSTEM	(\$12,816.60)																
					12	Nov 2, 2021	SYSTEM	\$13,802.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.															
					12	Nov 2, 2021	SYSTEM	(\$13,802.20)																
				- Total				\$0.00																
	0700 -	Total	Material - To	tal				\$0.00 \$0.00																
	0740	MECHANICALLY STABILIZED EARTH WALL	Material											1	1	1	1			10	Oct 1, 2021	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user brinkr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
		SYS			10	Oct 1, 2021	SYSTEM	(\$155,545.00)																
					11	Oct 18, 2021	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 49 on the current Payment Estimate.															
					11	Oct 18, 2021	SYSTEM	(\$155,545.00)																
					12	Nov 2, 2021	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.															
					12	Nov 2, 2021	SYSTEM	(\$155,545.00)																
					13	Nov 16, 2021	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.															
					13	Nov 16,	SYSTEM	(\$155,545.00)																



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
8	0740	MECHANICALLY	Material			2021							
		STABILIZED EARTH WALL SYS			14	Dec 2, 2021	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brinkr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.				
					14	Dec 2, 2021	SYSTEM	(\$155,545.00)					
					15	Dec 16, 2021	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
					15	Dec 16, 2021	SYSTEM	(\$155,545.00)					
					16	Jan 3, 2022	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.				
					16	Jan 3, 2022	SYSTEM	(\$155,545.00)					
					17	Jan 18, 2022	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					17	Jan 18, 2022	SYSTEM	(\$155,545.00)					
					18	Feb 1, 2022	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandeb2 overridding Payme Estimate Exception 7 on the current Payment Estimate.				
					18	Feb 1, 2022	SYSTEM	(\$155,545.00)					
					19	Feb 16, 2022	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandeb2 overridding Payme Estimate Exception 7 on the current Payment Estimate.				
					19	Feb 16, 2022	SYSTEM	(\$155,545.00)					
					20	Mar 2, 2022	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brinkr1 overridding Paymen Estimate Exception 7 on the current Payment Estimate.				
						20	Mar 2, 2022	SYSTEM	(\$155,545.00)				
							21	Mar 16, 2022	SYSTEM	\$155,545.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user sandeb2 overridding Payme Estimate Exception 9 on the current Payment Estimate.		
						21	Mar 16, 2022	SYSTEM	(\$155,545.00)				
								22	2	22	Apr 4, 2022	SYSTEM	\$155,545.00
					22	Apr 4, 2022	SYSTEM	(\$155,545.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0740 -							\$0.00					
	0780	12 IN. GROUP A FLARED END SECT	Material		8	Sep 2, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Paymen Estimate Exception 42 on the current Payment Estimate.				
					8	Sep 2, 2021	SYSTEM	(\$600.00)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0780 -							\$0.00					
	0790				:		9	Sep 16, 2021	SYSTEM	\$5,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.		
	555510			9	Sep 16, 2021	SYSTEM	(\$5,280.00)						
					10	Oct 1, 2021	SYSTEM	\$5,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user brinkr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.				



1	t	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks											
The property color		Line	Description		Adjustment				Amount	remans											
Total   1000	8 (	0790	TALL FESCUE	Material		10		SYSTEM	(\$5,280.00)												
SPECINIC   SPECINIC   SPATEM   STAR   SPATEM   STAR   SPATEM   S			CODDINO		- Total				\$0.00												
SEEDING				Material - To	tal				\$0.00												
COCI, SEASON	0	0790 -	Total						\$0.00												
1	(	0800	COOL SEASON	Material		10		SYSTEM	\$11,858.00	Estimate Item Adjustment (0040) due to user brinkr1 overridding Payment											
2021						10		SYSTEM	(\$11,858.00)												
2021   12						11		SYSTEM	\$11,858.00	Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment											
2021   Estimate Item Adjustment (00 fis) due to user brinks' overridding Playment Estimate.   12 Nov 2, 2021   SYSTEM (\$11,868.00)						11		SYSTEM	(\$11,858.00)												
Total   S0.00						12		SYSTEM	\$11,858.00	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment											
Material - Total						12		SYSTEM	(\$11,858.00)												
Section					- Total				\$0.00												
National				Material - Tot	tal				\$0.00												
CHECK	C	- 0080	Total						\$0.00												
2021   6	(	0810		Material		5		SYSTEM	\$570.00	Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment											
2021   Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.						5		SYSTEM	(\$570.00)												
Solution							6		SYSTEM	\$570.00	Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment										
Naterial - Total   S0.00						6		SYSTEM	(\$570.00)												
CURB INLET CHECK									\$0.00												
CURB INLET CHECK				Material - To	otal				\$0.00												
CHECK									\$0.00												
2021	(	0820		Material		5		SYSTEM	\$125.00	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment											
System   S						5		SYSTEM	(\$125.00)												
2021   7   Aug 16, SYSTEM   \$125.00   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.   7   Aug 16, SYSTEM   \$125.00																	6		SYSTEM	\$125.00	Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment
2021   Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.   7						6		SYSTEM	(\$125.00)												
Total   \$0.00								7		SYSTEM	\$125.00	Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment									
Material - Total  S0.00  TEMPORARY SEEDING AND MULCHING  MULCHING  Page 16, SYSTEM 2021  System \$1,470.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.  System \$1,470.00 This adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.  System \$0.00  Material - Total  System \$0.00						7		SYSTEM	(\$125.00)												
Second					- Total				\$0.00												
TEMPORARY SEEDING AND MULCHING  MULCHING  Material  9 Sep 16, SYSTEM \$1,470.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.  9 Sep 16, SYSTEM (\$1,470.00)  - Total  Material - Total  \$0.00				Material - Tot	tal				\$0.00												
SEEDING AND MULCHING    2021   Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.    9	C	0840 TEMPORARY SEEDING AND						\$0.00													
2021   \$0.00	(		SEEDING AND	Material		9		SYSTEM	\$1,470.00	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment											
Material - Total \$0.00					9		SYSTEM	(\$1,470.00)													
					- Total				\$0.00												
0840 - Total \$0.00							\$0.00														
	0	0840 -	Total						\$0.00												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	0860	MGS GUARDRAIL	Material		8	Sep 2, 2021	SYSTEM	\$3,127.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$3,127.50)	
					9	Sep 16, 2021	SYSTEM	\$3,127.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$3,127.50)	
					10	Oct 1, 2021	SYSTEM	\$3,127.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$3,127.50)	
					11	Oct 18, 2021	SYSTEM	\$3,127.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$3,127.50)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0860 -							\$0.00	
	0870	MGS HEIGHT AND BLOCK TRANSITION	Material		8	Sep 2, 2021	SYSTEM	\$768.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brinkr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$768.21)	
					9	Sep 16, 2021	SYSTEM	\$768.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$768.21)	
					10	Oct 1, 2021	SYSTEM	\$768.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$768.21)	
					11	Oct 18, 2021	SYSTEM	\$768.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$768.21)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	0870 -		Material		0	0- 6	OVETE	\$0.00	This adjustment offset the said of
	0890	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		8	Sep 2, 2021	SYSTEM	\$2,311.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
		(MINOI I)			8	Sep 2, 2021	SYSTEM	(\$2,311.40)	
					9	Sep 16, 2021	SYSTEM	\$2,311.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$2,311.40)	
					10	Oct 1, 2021	SYSTEM	\$2,311.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$2,311.40)	
					11	Oct 18, 2021	SYSTEM	\$2,311.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					11	Oct 18,	SYSTEM	(\$2,311.40)	



CRASHWORTHY   CRUTERININAL (RASH)   Material - Total   \$0.00	ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
PRO TERMINAL	408	0890		Material			2021							
					- Total				\$0.00					
			(MASH)	Material - Tot	tal				\$0.00					
EED-A		0890 -	Total						\$0.00					
17		0920		Material		16		SYSTEM	\$2,000.00	Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment				
2022   17						16		SYSTEM	(\$2,000.00)					
18						17		SYSTEM	\$5,200.00	Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment				
Second   Part						17		SYSTEM	(\$5,200.00)					
19								18		SYSTEM	\$6,000.00	Estimate Item Adjustment (0007) due to user sandeb2 overridding Payment		
2022   SYSTEM   \$6,000.00   SysTEM   \$6,000.00							18		SYSTEM	(\$6,000.00)				
202									19		SYSTEM	\$6,000.00	Estimate Item Adjustment (0007) due to user sandeb2 overridding Payment	
System   System   System   System   System   Standard Exception 8 on the current Payment Estimate Description 10 on the current Payment Estimate Exception 20 on the current Payment Estimate Exception 21 on the current Payment Estimate Exception 21 on the current Payment Estimate Estimate Exception 21 on the current Payment Estimate Exception 21 on the current Payment Estimate Estim										19		SYSTEM	(\$6,000.00)	
2022   21											20		SYSTEM	\$6,000.00
2022   System   Estimate Item Adjustment (0005) due to user sandeb2 overridding Payment								20		SYSTEM	(\$6,000.00)			
						21		SYSTEM	\$6,000.00	Estimate Item Adjustment (0005) due to user sandeb2 overridding Payment				
Material - Total   S0.00						21		SYSTEM	(\$6,000.00)					
Source   S					- Total				\$0.00					
CONDUIT, 3 IN, RIGID, IN TRENCH				Material - Tot	Vaterial - Total				\$0.00					
RIGID, IN TRENCH    2021   SYSTEM   Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.   30.00		0920 -	Total						\$0.00					
Comparison of the current Payment Estimate Image of 10,000		0930	RIGID, IN	Material		6	Aug 2, 2021	SYSTEM	\$2,304.00	Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment				
Material - Total   S0.00						6		SYSTEM	(\$2,304.00)					
Overrun  Ove					- Total				\$0.00					
2021   Estimate Item Adjustment (0015) overridding Payment Estimate Exception 2c on the current Payment Estimate. Material Insufficiency Quantity 128.000; Overrun Quantity Balance 116.00.    6				Material - Tot	tal				\$0.00					
2021 7 Aug 16, 2021 (\$2,088.00)  Overrun - Total (\$2,088.00)  Overrun - To				Overrun	Overrun	Overrun	Overrun 6	6	Aug 2, 2021	SYSTEM	\$2,088.00	Estimate Item Adjustment (0015) overridding Payment Estimate Exception 24 on the current Payment Estimate. Material Insufficiency Quantity 128.000;		
Overrun - Total  Overrun - Total  (\$2,088.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  - Total  So.00						6		SYSTEM	(\$2,088.00)					
Overrun - Total (\$2,088.00)  0930 - Total (\$2,088.00)  PULL BOX, PREFORMED CLASS 1  6 Aug 2, 2021  6 Aug 2, 2021  FORMED CLASS 1						7	Aug 16, 2021	SYSTEM	(\$2,088.00)					
0930 - Total  O960 PULL BOX, PREFORMED CLASS 1  6 Aug 2, 2021 \$YSTEM \$2,434.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  6 Aug 2, 2021 \$YSTEM (\$2,434.00)  - Total \$0.00					Overrun - T	otal			(\$2,088.00)					
PULL BOX, PREFORMED CLASS 1  One of the component of the				Overrun - To	tal				(\$2,088.00)					
PREFORMED CLASS 1  2021 Estimate Item Adjustment (0017) dué to user brinkr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.  6 Aug 2, 2021 (\$2,434.00)  - Total \$0.00		0930 -	Total						(\$2,088.00)					
- Total \$0.00			PREFORMED	Material		6	Aug 2, 2021	SYSTEM	\$2,434.00	Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment				
						6		SYSTEM	(\$2,434.00)					
Material - Total \$0.00					- Total				\$0.00					
				Material - Tot	tal				\$0.00					



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
3408	0960 -	Total						\$0.00								
	0970	PULL BOX, PREFORMED CLASS 3	Material		6	Aug 2, 2021	SYSTEM	\$1,470.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 22 on the current Payment Estimate.							
					6	Aug 2, 2021	SYSTEM	(\$1,470.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0970 -	Total						\$0.00								
	0980	CABLE, 10 AWG 1 CONDUCTOR, POLE &	Material		16	Jan 3, 2022	SYSTEM	\$180.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
		BRACKE			16	Jan 3, 2022	SYSTEM	(\$180.00)								
							17	Jan 18, 2022	SYSTEM	\$468.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
					17	Jan 18, 2022	SYSTEM	(\$468.00)								
					18	Feb 1, 2022	SYSTEM	\$540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandeb2 overridding Payment Estimate Exception 10 on the current Payment Estimate.							
					18	18	Feb 1, 2022	SYSTEM	(\$540.00)							
						1					19	Feb 16, 2022	SYSTEM	\$540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandeb2 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
												19	Feb 16, 2022	SYSTEM	(\$540.00)	
															20	Mar 2, 2022
					20	Mar 2, 2022	SYSTEM	(\$540.00)								
					21	Mar 16, 2022	SYSTEM	\$540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user sandeb2 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
					21	Mar 16, 2022	SYSTEM	(\$540.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0980 -	Total						\$0.00								
	0990	CABLE- CONDUIT, 1 IN.,	Material		6	Aug 2, 2021	SYSTEM	\$645.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.							
		CONDUCTORS			6	Aug 2, 2021	SYSTEM	(\$645.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0990 -	Total						\$0.00								
	1000	POLE FOUNDATION (30 FT. OR 9.0 M	Material		7	Aug 16, 2021	SYSTEM	\$2,970.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.							
					7	Aug 16, 2021	SYSTEM	(\$2,970.00)								
					8	Sep 2, 2021	SYSTEM	\$3,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user brinkr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.							
					8	Sep 2, 2021	SYSTEM	(\$3,960.00)								
					9	Sep 16, 2021	SYSTEM	\$4,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.							
					9	Sep 16,	SYSTEM	(\$4,950.00)								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	1000	POLE	Material			2021			
		FOUNDATION (30 FT. OR 9.0 M			10	Oct 1, 2021	SYSTEM	\$4,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user brinkr1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$4,950.00)	
					11	Oct 18, 2021	SYSTEM	\$4,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user brinkr1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$4,950.00)	
					12	Nov 2, 2021	SYSTEM	\$4,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$4,950.00)	
				- Total		_,_,		\$0.00	
			Material - Tot	tal				\$0.00	
	1000 -	Total						\$0.00	
	1010	MISC. HIGHWAY LIGHTING	Material		13	Nov 16, 2021	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Nov 16, 2021	SYSTEM	(\$8,840.00)	
					14	Dec 2, 2021	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					14	Dec 2, 2021	SYSTEM	(\$8,840.00)	
					15	Dec 16, 2021	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					15	Dec 16, 2021	SYSTEM	(\$8,840.00)	
					16	Jan 3, 2022	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					16	Jan 3, 2022	SYSTEM	(\$8,840.00)	
					17	Jan 18, 2022	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$8,840.00)	
					18	Feb 1, 2022	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandeb2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$8,840.00)	
					19	Feb 16, 2022	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandeb2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					19	Feb 16, 2022	SYSTEM	(\$8,840.00)	
					20	Mar 2, 2022	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$8,840.00)	
					21	Mar 16, 2022	SYSTEM	\$8,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user sandeb2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$8,840.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
J6S3408	1010	MISC. HIGHWAY LIGHTING	Material - To	tal				\$0.00																					
	1010 -	· Total						\$0.00																					
	1020	CONCRETE FOOTINGS, EMBEDDED	Material		8	Sep 2, 2021	SYSTEM	\$82.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user brinkr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																				
					8	Sep 2, 2021	SYSTEM	(\$82.08)																					
					9	Sep 16, 2021	SYSTEM	\$82.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.																				
					9 Sep 16, SYSTEM (\$82.08) 2021																								
					10	Oct 1, 2021	SYSTEM	\$82.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user brinkr1 overridding Payment Estimate Exception 54 on the current Payment Estimate.																				
								10	Oct 1, 2021	SYSTEM	(\$82.08)																		
					11	Oct 18, 2021	SYSTEM	\$82.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user brinkr1 overridding Payment Estimate Exception 62 on the current Payment Estimate.																				
					11	Oct 18, 2021	SYSTEM	(\$82.08)																					
					12	Nov 2, 2021	SYSTEM	\$82.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																				
					12	Nov 2, 2021	SYSTEM	(\$82.08)																					
					13	Nov 16, 2021	SYSTEM	\$82.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																				
					13	Nov 16, 2021	SYSTEM	(\$82.08)																					
					14	Dec 2, 2021	SYSTEM	\$82.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																				
					14	Dec 2, 2021	SYSTEM	(\$82.08)																					
					15	Dec 16, 2021	SYSTEM	\$82.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																				
													15	Dec 16, 2021	SYSTEM	(\$82.08)													
																		16	Jan 3, 2022	SYSTEM	\$947.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					16	Jan 3, 2022	SYSTEM	(\$947.06)																					
					17	Jan 18, 2022	SYSTEM	\$947.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																				
					17	Jan 18, 2022	SYSTEM	(\$947.06)																					
									1	1						18 19		1	1	1	1				18	Feb 1, 2022	SYSTEM	\$1,584.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandeb2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
																								18	Feb 1, 2022	SYSTEM	(\$1,584.74)		
			15																			1				19	Feb 16, 2022	SYSTEM	\$1,894.11
																		19	Feb 16, 2022	SYSTEM	(\$1,894.11)								
																	20	Mar 2, 2022	SYSTEM	\$2,594.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user brinkr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S3408	1020	CONCRETE FOOTINGS, EMBEDDED	Material		20	Mar 2, 2022	SYSTEM	(\$2,594.93)		
					21	Mar 16, 2022	SYSTEM	\$2,594.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user sandeb2 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					21	Mar 16, 2022	SYSTEM	(\$2,594.93)		
					22	Apr 4, 2022	SYSTEM	\$2,594.93	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					22	Apr 4, 2022	SYSTEM	(\$2,594.93)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1020 -	Total						\$0.00		
	1030	CONCRETE FOOTINGS, BOLT DOWN	Material		21	Mar 16, 2022	SYSTEM	\$9,164.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user sandeb2 overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					21	Mar 16, 2022	SYSTEM	(\$9,164.95)		
					22	Apr 4, 2022	SYSTEM	\$9,164.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
					22	Apr 4, 2022	SYSTEM	(\$9,164.95)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	1030 -	· Total						\$0.00		
	1050	PIPE POSTS	S Material	Vaterial	8	Sep 2, 2021	SYSTEM	\$248.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user brinkr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	
					8	Sep 2, 2021	SYSTEM	(\$248.04)		
					9	Sep 16, 2021	SYSTEM	\$248.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user brinkr1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	
					9	Sep 16, 2021	SYSTEM	(\$248.04)		
					10	Oct 1, 2021	SYSTEM	\$248.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user brinkr1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	
					10	Oct 1, 2021	SYSTEM	(\$248.04)		
					11	Oct 18, 2021	SYSTEM	\$248.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user brinkr1 overridding Payment Estimate Exception 65 on the current Payment Estimate.	
					11	Oct 18, 2021	SYSTEM	(\$248.04)		
						12	Nov 2, 2021	SYSTEM	\$248.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					12	Nov 2, 2021	SYSTEM	(\$248.04)		
					13	Nov 16, 2021	SYSTEM	\$248.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					13	Nov 16, 2021	SYSTEM	(\$248.04)		
					14	Dec 2, 2021	SYSTEM	\$248.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					14	Dec 2, 2021	SYSTEM	(\$248.04)		
					15	Dec 16, 2021	SYSTEM	\$248.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user brinkr1 overridding Payment	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	1050	PIPE POSTS	Material						Estimate Exception 11 on the current Payment Estimate.
					15	Dec 16, 2021	SYSTEM	(\$248.04)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1050 -	Total						\$0.00	
	1070	SH-FLAT SHEET	Material		16	Jan 3, 2022	SYSTEM	\$360.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					16	Jan 3, 2022	SYSTEM	(\$360.85)	
					17	Jan 18, 2022	SYSTEM	\$360.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$360.85)	
					18	Feb 1, 2022	SYSTEM	\$716.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$716.95)	
					19	Feb 16, 2022	SYSTEM	\$716.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					19	Feb 16, 2022	SYSTEM	(\$716.95)	
					20	Mar 2, 2022	SYSTEM	\$859.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user brinkr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$859.39)	
					21	Mar 16, 2022	SYSTEM	\$859.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user sandeb2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$859.39)	
					22	Apr 4, 2022	SYSTEM	\$3,171.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$3,171.66)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1070 -	Total						\$0.00	
	1080	ST- STRUCTURAL		1	16	Jan 3, 2022	SYSTEM	\$4,221.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					16	Jan 3, 2022	SYSTEM	(\$4,221.60)	
					17	Jan 18, 2022	SYSTEM	\$4,221.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					17	Jan 18, 2022	SYSTEM	(\$4,221.60)	
					18	Feb 1, 2022	SYSTEM	\$6,332.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandeb2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$6,332.40)	
					19	Feb 16, 2022	SYSTEM	\$6,332.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandeb2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					19	Feb 16, 2022	SYSTEM	(\$6,332.40)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	1080	ST- STRUCTURAL	Material		20	Mar 2, 2022	SYSTEM	\$6,332.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$6,332.40)	
					21	Mar 16, 2022	SYSTEM	\$6,332.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user sandeb2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$6,332.40)	
					22	Apr 4, 2022	SYSTEM	\$6,332.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$6,332.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1080 -	Total						\$0.00	
	1090	SHF-FLAT SHEET FLUORESCENT	Material		18	Feb 1, 2022	SYSTEM	\$781.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandeb2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					18	Feb 1, 2022	SYSTEM	(\$781.12)	
					19	Feb 16, 2022	SYSTEM	\$781.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user sandeb2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					19	Feb 16, 2022	SYSTEM	(\$781.12)	
					20	Mar 2, 2022	SYSTEM	\$1,074.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user brinkr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					20	Mar 2, 2022	SYSTEM	(\$1,074.04)	
					21	Mar 16, 2022	SYSTEM	\$1,074.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user sandeb2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					21	Mar 16, 2022	SYSTEM	(\$1,074.04)	
					22	Apr 4, 2022	SYSTEM	\$2,898.69	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					22	Apr 4, 2022	SYSTEM	(\$2,898.69)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1090 -	Total						\$0.00	
	5001	CONDUIT SYSTEM ON STRUCTURE	Material	iterial	4	Jul 2, 2021	SYSTEM	\$4,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user brinkr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					4	Jul 2, 2021	SYSTEM	(\$4,872.00)	
					5	Jul 16, 2021	SYSTEM	\$4,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					5	Jul 16, 2021	SYSTEM	(\$4,872.00)	
					7	Aug 16, 2021	SYSTEM	\$4,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Aug 16, 2021	SYSTEM	(\$4,872.00)	
					15	Dec 16, 2021	SYSTEM	\$4,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user brinkr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Dec 16,	SYSTEM	(\$4,872.00)	



Application   CONDUIT   Market   10	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
STRUCTURE	J6S3408	5001	SYSTEM ON	Material			2021					
17   2018   979TEM   54,872.00   The adjustment offsets the original system-generated Malerial Payment Estimate Browning on the current Payment Seatman Browning Payment (Estimate Browning on the current Payment Estimate Browning Payment (Estimate Browning on the current Payment Estimate Browning Payment (Estimate Browning Payment)   16						16		SYSTEM	\$4,872.00	Estimate Item Adjustment (0015) due to user brinkr1 overridding Payment		
2022   2022   2023   2024   2024   2025						16		SYSTEM	(\$4,872.00)			
10						17		SYSTEM	\$4,872.00	Estimate Item Adjustment (0018) due to user brinkr1 overridding Payment		
2022   SysTEM   (\$4.872.00)						17		SYSTEM	(\$4,872.00)			
19						18		SYSTEM	\$4,872.00	Estimate Item Adjustment (0014) due to user sandeb2 overridding Payment		
2022   Estimate Item Adjustment (0014) due to user sandeb2 overridding Payment Estimate Exception 3 on the current Payment Estimate Esti						18		SYSTEM	(\$4,872.00)			
2022   2032						19		SYSTEM	\$4,872.00	Estimate Item Adjustment (0014) due to user sandeb2 overridding Payment		
2022   Estimate Item Adjustment (1003) due to user brinkfr toverridding Payment Estimate Exception 3 on the current Payment Estimate Exception 5 on the current Payment Estimate Exception 7 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate Estimate Exception 15 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 18 on the current Payment Estimate Exception 19 on the current Payme						19		SYSTEM	(\$4,872.00)			
2022   21   Mar 16, SYSTEM   \$4,872.00   Estimate lem Adjustment offsets the original system-generated Material Payment Estimate lem Adjustment offsets the original system-generated Material Payment Estimate lem Adjustment offsets the original system-generated Material Payment Estimate lem Adjustment offsets the original system-generated Material Payment Estimate lem Adjustment offsets the original system-generated Material Payment Estimate lem Adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.   \$0.00						20		SYSTEM	\$4,872.00	Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment		
2022   SYSTEM   SASTEM   SAS								20		SYSTEM	(\$4,872.00)	
2022   22						21		SYSTEM	\$4,872.00	Estimate Item Adjustment (0013) due to user sandeb2 overridding Payment		
2022   Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.   2021   S0.00						21		SYSTEM	(\$4,872.00)			
South						22		SYSTEM	\$4,872.00	Estimate Item Adjustment (0016) due to user brinkr1 overridding Payment		
South   Sout						22		SYSTEM	(\$4,872.00)			
Sound					- Total				\$0.00			
SYSTEM ON STRUCTURE				Material - To	tal							
2021   Estimate Item Adjustment (0023) due to user brinkr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.												
2021		5002	SYSTEM ON	Material	Material .	4		SYSTEM	\$5,357.10	Estimate Item Adjustment (0023) due to user brinkr1 overridding Payment		
2021   Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.						4		SYSTEM	(\$5,357.10)			
Total   \$0.00						5		SYSTEM	\$5,357.10	Estimate Item Adjustment (0017) due to user brinkr1 overridding Payment		
Source   S						5		SYSTEM	(\$5,357.10)			
\$0.00  CONCRETE PAVEMENT (7 IN. NON-REINFORCED,  11 Oct 18, 2021  12 Nov 2, 2021  Nov 2, 2021  SYSTEM \$40,460.00  Final payment estimate Exception 4 on the current Payment estimate.  13 Nov 2, 2021  14 Nov 2, 2021  SYSTEM \$40,460.00  Final payment estimate Exception 4 on the current Payment Estimate.  15 Nov 2, 2021  SYSTEM \$40,460.00  Final payment estimate Exception 4 on the current Payment Estimate.  Final payment estimate Exception 4 on the current Payment Estimate.  Final payment estimate Exception 4 on the current Payment Estimate.  Final payment estimate Exception 4 on the current Payment Estimate.  Final payment estimate Exception 4 on the current Payment Estimate.									\$0.00			
CONCRETE PAVEMENT (7 IN. NON-REINFORCED, REINFORCED, A large of the control of the current Payment Estimate Item Adjustment (0027) due to user brinkr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  11 Oct 18, 2021 SYSTEM (\$26,885.00)  12 Nov 2, 2021 SYSTEM \$40,460.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  12 Nov 2, 2021 SYSTEM (\$40,460.00)  13 Nov 2, 2021 SYSTEM (\$40,460.00)  14 Nov 2, 2021 SYSTEM (\$40,460.00)				Material - To	Total							
PAVEMENT (7 IN. NON-REINFORCED,    11		5002 -	Total						\$0.00			
11 Oct 18, 2021 (\$26,885.00)  12 Nov 2, 2021 \$40,460.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  12 Nov 2, 2021 \$9SYSTEM (\$40,460.00)  - Total \$0.00		5003	PAVEMENT (7 IN. NON-	Material		11		SYSTEM	\$26,885.00	Estimate Item Adjustment (0027) due to user brinkr1 overridding Payment		
Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.  12 Nov 2, 2021 (\$40,460.00)  - Total \$0.00						11		SYSTEM	(\$26,885.00)			
- Total \$0.00						12		SYSTEM	\$40,460.00	Estimate Item Adjustment (0003) due to user brinkr1 overridding Payment		
						12		SYSTEM	(\$40,460.00)			
Material - Total \$0.00					- Total				\$0.00			
				Material - Tot	tal				\$0.00			





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3408	5003	CONCRETE PAVEMENT (7 IN. NON- REINFORCED,	Price FUEL		11	Oct 18, 2021	SYSTEM	\$59.15	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Nov 2, 2021	SYSTEM	\$29.87	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$89.02	
			Price FUEL -	Total				\$89.02	
	5003 -	Total						\$89.02	
	5004	PAVEMENT EDGE TREATMENT	Material		8	Sep 2, 2021	SYSTEM	\$3,311.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user brinkr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					8	Sep 2, 2021	SYSTEM	(\$3,311.00)	
					9	Sep 16, 2021	SYSTEM	\$3,311.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user brinkr1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					9	Sep 16, 2021	SYSTEM	(\$3,311.00)	
					10	Oct 1, 2021	SYSTEM	\$3,311.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user brinkr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					10	Oct 1, 2021	SYSTEM	(\$3,311.00)	
					11	Oct 18, 2021	SYSTEM	\$3,311.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user brinkr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					11	Oct 18, 2021	SYSTEM	(\$3,311.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	5004 -	Total						\$0.00	
J6S3408 -	- Total							\$12,703.29	
Overall -	Total							\$12,703.29	