Diary Charge Days

Days Remaining on

Milestone

-434



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 5, 2023

Progress Estimate Number 14	Contract ID 210319-H01 Pay Period StartSeptember 2, 2022 Original Contract Amo Prime Contractor Pace Construction Company, LLC Pay Period End January 5, 2023 Net Change Order Amo Current Contract Amo	ount\$147,627.90
Approval Date		By User

By User		Approval Date
ROTHEL	Generated and Approved (and should be considered Draft) at the Project Office Level by	January 5, 2023
PULLIA	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	January 17, 2023
ramses1	Reviewed and Approved at the Central Office Controllers Office Level by	January 18, 2023

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2021	June 15, 2022		100.00%

Original

Completion Date

November 1,

2021

Contract Informational Dates Milestones

Date Description	Original Completion Date	Current Completion Date	Date Description
Acceptance Date			Milestone - Completion Date
Awarded Date	April 7, 2021	April 7, 2021	
Letting Date	March 19, 2021	March 19, 2021	
Notice to Proceed Date	May 10, 2021	May 10, 2021	
Work Began Date	June 7, 2021	June 7, 2021	

nis Estimate	Previous	To Date	

Current

Completion Date

November 10,

2021

		This Estimate	Previous	To Date
210319-H01				
	Total Posted Items Pay	\$144.90	\$4,947,483.02	\$4,947,627.92
	Gross Item Adjustments	\$8,002.21	\$110,987.07	\$118,989.28
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	(\$40,800.00)	(\$40,800.00)
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$5,017,670.09	\$5,025,817.20
Contract Total Pay	vable This Estimate:	\$8 147 11		

Items Paid This Estimate Period

Contract Total Pay For Estimate No. 14

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J9P3458	0150	4071005	TACK COAT	GAL	\$2.100	69	\$144.90			
Project J9P3458 - To	Project J9P3458 - Total Overall - Total									
Overall - Total										

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9P3458	0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Retroreflectivity Adjustment	This Adjust is being made to add the 20% deduction that was made on Estimate #0012			\$4,777.98
	0290	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Retroreflectivity Adjustment	This Adjustment is being made for reflectivity results performed on 12/14/21			(\$726.61)
	0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Retroreflectivity Adjustment	This Adjust is being made to add the 20% deduction that was made on Estimate #0012			\$4,382.82
	0300	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	Other Item Adjustment	Retroreflectivity Adjustment	This Adjustment is being made for reflectivity results performed on 12/14/21			(\$431.98)

Revision 4/1/2020 Page 1 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 5, 2023

Progres	ss Esti	mate Number 4	Contract ID Prime Contrac	210319-H ctorPace Con		ny, LLCPay Period End January 5, 2023	2Original Contract Amount \$4,800,000.00 Net Change Order Amount \$147,627.90 Current Contract Amount \$4,947,627.90				
Project Number	Line No.	Item De	Item Description		Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount		
Total									\$8,002.21		


Revision 4/1/2020 Page 2 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	ontract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J9P3458	FAF 160-3(20)	Resurface and add rumblestripes	160	OZARK	from Rte. 5 to Rte. 101		
Totals by J	Job Numbe	rs					
J9P3458					This Estimate	Previous	To Date
	Poste	d Item Pay			\$144.90	\$4,947,483.02	\$4,947,627.92
	Gross	Item Adjustme	nts		\$8,002.21	\$110,987.07	\$118,989.28
			Gross	Item Pay	\$8,147.11	\$5,058,470.09	\$5,066,617.20
	Incent	tive			\$0.00	\$0.00	\$0.00
	Disino	entive			\$0.00	\$0.00	\$0.00
	Liquid	lated Damages			\$0.00	(\$40,800.00)	(\$40,800.00)
	041	O 4 4 A 11	4		#0.00	<u> </u>	60.00

Revision 4/1/2020 Page 3 of 21





Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 4 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0319-H01	J9P3458	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	-	\$127,339.95	\$127,339.9
		0001	0020	2031000	CLASS A EXCAVATION	45.00	0.00	45.00	CUYD	45.00	\$100.00	\$4,500.0
		0001	0030	2063500	CULVERT CLEANOUT	6.00	0.00	6.00	EA	6.00	\$2,000.00	\$12,000.0
		0001	0040	2072000	LINEAR GRADING CLASS 2	10.30	0.00	10.30	STA	10.30	\$550.00	\$5,665.0
		0001	0050	2129900	MISC.SHOULDER GRADING	1,995.20	0.00	1,995.20	100F	1,995.20	\$390.00	\$778,128.0
		0001	0060	2142000	FURNISHING ROCK FILL	400.00	0.00	400.00	CUYD	400.00	\$1.00	\$400.0
		0001	0070	2143000	PLACING ROCK FILL	400.00	0.00	400.00	CUYD	400.00	\$20.00	\$8,000.0
		0001	0080	3040163	TYPE 1 AGGREGATE FOR BASE (6 IN. THICK)	1,418.00	405.00	1,823.00	SQYD	1,823.00	\$10.00	\$18,230.0
		0001	0090	3049907	MISC.TYPE 1 AGGREGATE	607.00	0.00	607.00	CUYD	607.00	\$50.00	\$30,350.0
		0001	0100	3105002	GRAVEL (A) OR CRUSHED STONE (B)	684.00	0.00	684.00	TONS	684.00	\$30.00	\$20,520.0
		0001	0110	4011211	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2)	9,369.60	46.00	9,415.60	TONS	9,415.60	\$65.00	\$612,014.0
		0001	0120	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	10,501.60	-1,029.50	9,472.10	TONS	9,472.10	\$59.00	\$558,853.9
		0001	0130	4019905	MISC.OPTIONAL FULL DEPTH PAVEMENT	1,417.80	405.10	1,822.90	SQYD	1,822.90	\$36.00	\$65,624.4
		0001	0140	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	16,444.70	974.30	17,419.00	TONS	17,419.00	\$63.50	\$1,106,106.
		0001	0150	4071005	TACK COAT	29,839.00	4,580.00	34,419.00	GAL	34,419.00	\$2.10	\$72,279.
		0001	0160	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	2,140.00	0.00	2,140.00	CUYD	2,140.00	\$1.00	\$2,140.0
		0001	0170	6096042	PLACING TYPE 2 ROCK DITCH LINER	2,140.00	0.00	2,140.00	CUYD	2,140.00	\$20.00	\$42,800.0
			0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.0
		0001	0190	6161005	CONSTRUCTION SIGNS	2,634.00	-489.00	2,145.00	SQFT	2,145.00	\$4.50	\$9,652.
		0001	0200	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	6.00	\$60.00	\$360.0
		0001	0210	6161009	FLAG ASSEMBLY	8.00	0.00	8.00	EA	8.00	\$10.25	\$82.0
		0001	0220	6161025	CHANNELIZER (TRIM LINE)	200.00	0.00	200.00	EA	200.00	\$18.00	\$3,600.0
		0001	0230	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$5,500.00	\$11,000.0
		0001	0240	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$300,000.00	\$300,000.
		0001	0250	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	4.00	\$600.00	\$2,400.
		0001	0260	6200013	COLD APPLIED TAPE PAVEMENT MARKING, 24 IN. WHITE	48.00	0.00	48.00	LF	48.00	\$20.00	\$960.
		0001	0270	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	11.00	1.00	12.00	EA	12.00	\$270.00	\$3,240.
		0001	0280	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,500.00	2,600.00	4,100.00	LF	4,100.00	\$2.00	\$8,200.0
		0001	0290	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	238,704.00	195.00	238,899.00	LF	238,899.00	\$0.10	\$23,889.9
		0001	0300	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	219,141.00	0.00	219,141.00	LF	219,141.00	\$0.10	\$21,914.
		0001	0310	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT. TYPE P BEADS	343.00	0.00	343.00	LF	343.00	\$5.00	\$1,715.0
		0001	0320	6207001	PAVEMENT MARKING REMOVAL	13,140.00	-6,290.00	6,850.00	LF	6,850.00	\$0.70	\$4,795.0
		0001	0330	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	8,898.00	0.00	8,898.00	SQYD	8,898.00	\$2.85	\$25,359.3
		0001	0340	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	6,126.00	0.00	6,126.00	SQYD	6,126.00	\$2.85	\$17,459.
		0001	0350	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	6,459.00	0.00	6,459.00	SQYD	6,459.00	\$2.00	\$12,918.
		0001	0360	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	1,524.10	0.00	1,524.10	STA	1,524.10	\$20.00	\$30,482.
		0001	0370	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$2,500.00	\$2,500.
		0001	0380	7034001	CLASS B-1 CONCRETE	3.40	0.00	3.40	CUYD	3.40	\$1,000.00	\$3,400.
		0001	0390	7250312A	12 IN. PIPE GROUP B	3.00	0.00	3.00	LF	3.00	\$50.00	\$150.
		0001	0400	7250315A	15 IN. PIPE GROUP B	176.00	0.00	176.00	LF	176.00	\$50.00	\$8,800
		0001	0410	7250318A	18 IN. PIPE GROUP B	264.00	0.00	264.00	LF	264.00	\$60.00	\$15,840.
		0001	0420	7250324A	24 IN. PIPE GROUP B	212.00	0.00	212.00	LF	212.00	\$80.00	\$16,960.
		0001	0430	7250342A	42 IN. PIPE GROUP B	144.00	0.00	144.00	LF	144.00	\$120.00	\$17,280.0
		0001	0440	7250415	15 IN. PIPE GROUP C	1,120.00	-32.00	1,088.00	LF	1,088.00	\$40.00	\$43,520.0

Revision 4/1/2020 Page 5 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210319-H01	J9P3458	0001	0450	7250418	18 IN. PIPE GROUP C	128.00	0.00	128.00	LF	128.00	\$50.00	\$6,400.00
		0001	0460	7350001	PIPE LINER FOR EXISTING CULVERT	202.00	0.00	202.00	LF	202.00	\$200.00	\$40,400.00
		0001	0470	8051000A	SEEDING - COOL SEASON GRASSES	45.40	0.00	45.40	ACRE	45.40	\$2,150.00	\$97,610.00
		0001	0480	8061005	ROCK DITCH CHECK	2,060.00	5,198.00	7,258.00	LF	7,258.00	\$6.25	\$45,362.50
		0001	0490	8061016	SEDIMENT REMOVAL	191.00	-141.00	50.00	CUYD	50.00	\$1.00	\$50.00
		0001	0500	8061019	SILT FENCE	1,900.00	7,943.00	9,843.00	LF	9,843.00	\$2.50	\$24,607.50
		0010	0510	6061060	MGS GUARDRAIL	2,413.00	0.00	2,413.00	LF	2,413.00	\$22.50	\$54,292.50
		0010	0520	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	6.00	0.00	6.00	EA	6.00	\$2,900.00	\$17,400.00
		0010	0530	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	13.00	0.00	13.00	EA	13.00	\$2,700.00	\$35,100.00
		0010	0540	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	1.00	\$28,125.00	\$28,125.00
		0030	0550	9029401	TEMPORARY TRAFFIC SIGNALS AND LIGHTING	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000.00
		0040	0560	9031260	WOOD POST, 4 IN. BY 4 IN.	270.00	0.00	270.00	LF	270.00	\$5.00	\$1,350.00
		0040	0570	9031270A	2 IN. PSST POST - 12 GA.	264.00	0.00	264.00	LF	264.00	\$14.00	\$3,696.00
		0040	0580	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	66.00	0.00	66.00	LF	66.00	\$40.00	\$2,640.00
		0040 0590 903500	9035004A	SH-FLAT SHEET	66.00	0.00	66.00	SQFT	66.00	\$36.00	\$2,376.00	
		0070	0600	2024018	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	1.00	0.00	1.00	LF	1.00	\$1,800.00	\$1,800.00
		0070	0610	2161500	REMOVAL OF SEAL COAT OR POLYMER WEARING SURFACE	16,669.00	0.00	16,669.00	SQFT	16,669.00	\$0.65	\$10,834.85
		0070	0620	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	153.00	0.00	153.00	LF	153.00	\$405.00	\$61,965.00
		0070	0630	2169903	MISC.Remove and Replace Curb	28.00	0.00	28.00	LF	28.00	\$525.00	\$14,700.00
		0070	0640	6233000	EPOXY POLYMER WEARING SURFACE	1,919.00	0.00	1,919.00	SQYD	1,919.00	\$41.75	\$80,118.25
		0070	0650	7034214	CLASS B-2 CONCRETE	68.80	0.00	68.80	CUYD	68.80	\$1,820.00	\$125,216.00
		0070	0660	7034600	CURB BLOCKOUT	775.00	0.00	775.00	LF	775.00	\$87.00	\$67,425.00
		0070	0670	7040104	HALF-SOLE REPAIR	1,000.00	1,455.00	2,455.00	SQFT	2,455.00	\$49.25	\$120,908.75
		0070	0680	7040106	FULL DEPTH REPAIR	100.00	-100.00	0.00	SQFT	0.00	\$62.10	\$0.00
		0070	0690	7040113	CLEANING AND EPOXY COATING	2,769.00	0.00	2,769.00	SQFT	2,769.00	\$6.00	\$16,614.00
		0070	0700	7101000	REINFORCING STEEL (EPOXY COATED)	10,920.00	0.00	10,920.00	LB	10,920.00	\$2.40	\$26,208.00
	Project J9P3458 - Total Value Posted to Date as of Report Generated Date										\$4,947,627.90	
10319-H01 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$4,947,627.90

Revision 4/1/2020 Page 6 of 21



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9P3458

Nu	Line Imber	Item Code	Description	DWR Date	DWR Approval Date		Units	Location	From Station/ Log Mile	Offset/ Distance	Offset/ Distance	Comments
	0150	4071005	TACK COAT	1/5/23	1/5/23	69.00	GAL	Rte. 160	Log Mi. 197.914			

ject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
3458	0190	June 7, 2021	351	CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		192.042 to 215.517		2.0	12			
				CONST-7-48 48x24 8.00 RATE OUR WORK ZONE		192.042 to 215.517		2.00	8			
				GO20-2 48x24 8.00 END ROAD WORK		192.042 to 215.517		2.00	8			
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		192.042 to 215.517		2.00	10			
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		192.042 to 215.517		48.00	1	18x12 Pilot Car in Use Wait and Follow		
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		192.042 to 215.517		4.00	16			
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		192.042 to 215.517		4.00	16			
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS		192.042 to 215.517		4.00	16			
				GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		192.042 to 215.517		4.00	8.75			
		June 15, 2021	188	WO1-4R 48x48 16.00 REVERSE CURVE (SYMBOL RIGHT ARROW)		Log Mi. 192.042 to 215.517		1.00	16			
				WO3-3 48x48 16.00 SIGNAL AHEAD (SYMBOL)		Log Mi. 192.042 to 215.517		2.00	16			
				WO3-1 48x48 16.00 STOP AHEAD (SYMBOL)		Log Mi. 192.042 to Log Mi. 215.517		8.00	16			
				R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW		Log Mi. 192.042 to Log Mi. 215.517		2.00	6			
		November 18, 2021	1241	WO8-15 48x48 16.00 GROOVED PAVEMENT		192.042 - 215.517		12.00	16			1
				WO8-15p 30x24 5.00 MOTORCYCLE (PLAQUE)		192.042 - 215.517		12.00	5			
				WO8-12 48x48 16.00 NO CENTER LINE		192.042 - 215.517		22.00	16			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		192.042 - 215.517		4.00	5			
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		192.042 - 215.517		4.00	16			
				WO8-1 48x48 16.00 BUMP		192.042 -215.517		12.00	16			
				GO22-1 21x15 2.19 WET PAINT (ARROW PIVETS)		192.042 - 215.517		4.00	2.19			8
				WO8-11 48x48 16.00 UNEVEN LANES		192.042 -215.517		22.00	16			

Revision 4/1/2020 Page 7 of 21



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0020	CLASS A EXCAVATION			3	Jul 15, 2021	SYSTEM	\$1.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$1.26	
			Price FUEL	- Total				\$1.26	
	0020 -	Total						\$1.26	
	0800	TYPE 1 AGGREGATE FOR BASE (6 IN.	Overrun	Overrun		Oct 4, 2021	SYSTEM	(\$4,062.11)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		TĤICK)			8	Oct 4, 2021	SYSTEM	\$4,062.11	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 27 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$4,062.11)	Averaged Price Adjustment from this item on all previous payment estimates of '0.02990' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$4,062.11	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user voyleb1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
				Overrun - To	otal			\$0.00	
			Overrun - T	otal				\$0.00	
			Price FUEL		7	Sep 15, 2021	SYSTEM	\$21.20	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Oct 4, 2021	SYSTEM	\$33.31	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$54.51	
			Price FUEL	- Total				\$54.51	
	0080 -	Total						\$54.51	
	0090	MISC. AGGREGATE FOR BASE	Material		1	Jun 16, 2021	SYSTEM	\$14,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$14,800.00)	
					2	Jul 1, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$28,150.00)	
					3	Jul 15, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$28,150.00)	
					4	Aug 2, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$28,150.00)	
					5	Aug 16, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$28,150.00)	
					6	Sep 2, 2021	SYSTEM	\$28,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$28,150.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0090 -	Total						\$0.00	
	0100	GRAVEL (A) OR CRUSHED STONE (B)	Material		1	Jun 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$9,000.00)	
					2	Jul 1,	SYSTEM	\$18,000.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0100	GRAVEL (A) OR CRUSHED STONE	Material			2021			Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
		(B)			2	Jul 1, 2021	SYSTEM	(\$18,000.00)	
					3	Jul 15, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$18,900.00)	
					4	Aug 2, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$18,900.00)	
					5	Aug 16, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$18,900.00)	
					6	Sep 2, 2021	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$18,900.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0100 -							\$0.00	
	0110	BIT. PAVEMENT MIXTURE PG64-22 (BP-2)	Material		9	Oct 18, 2021	SYSTEM	\$602,650.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user voyleb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$602,650.10)	
					10	Nov 2, 2021	SYSTEM	\$27,014.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$27,014.00)	
					11	Nov 16, 2021	SYSTEM	\$27,014.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$27,014.00)	
					12	Dec 2, 2021	SYSTEM	\$27,014.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$27,014.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	1	Jun 16, 2021	ROTHEL	\$279.00	
					2	Jul 1, 2021	ROTHEL	\$276.77	This Adjustment is being made for 148.8 tons of BP-2 mix laid during this estimate period.
					9	Oct 18, 2021	voyleb1	\$18,753.03	Tons : 8,972.74 Virgin AC % : 4.4 Mix ID : BP2 21-60
					10	Nov 2, 2021	ROTHEL	\$301.09	This Adjustment is being made for 144.06 tons of BP-2 installed during this estimate period.
				ACAD - Tota	al			\$19,609.89	
			Other Item	Adjustment -	Total			\$19,609.89	
			Price FUEL		1	Jun 16, 2021	SYSTEM	\$59.76	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					2	Jul 1, 2021	SYSTEM	\$59.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0110	BIT. PAVEMENT MIXTURE	Price FUEL		9	Oct 18, 2021	SYSTEM	\$2,098.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		PG64-22 (BP-2)			9	Oct 18, 2021	SYSTEM	\$10,413.57	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Nov 2, 2021	SYSTEM	\$200.88	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$12,831.51	
			Price FUEL	- Total				\$12,831.51	
	0110 -	Total						\$32,441.40	
	0120	BITUMINOUS PAVEMENT MIXTURE	Material		8	Oct 4, 2021	SYSTEM	\$145,853.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
		PG64-22 (BAS			8	Oct 4, 2021	SYSTEM	(\$145,853.90)	
					9	Oct 18, 2021	SYSTEM	\$86,853.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user voyleb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$86,853.90)	
					10	Nov 2, 2021	SYSTEM	\$86,853.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$86,853.90)	
					11	Nov 16, 2021	SYSTEM	\$86,853.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$86,853.90)	
					12	Dec 2, 2021	SYSTEM	\$86,853.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$86,853.90)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	ACAD	7	Sep 15, 2021	ROTHEL	\$4,597.32	This Adjustment is being made for the total tons of asphalt laid during this estimate period.
					8	Oct 4, 2021	ROTHEL	\$14,296.80	This Adjustment is being made for the total tons of Bit base laid during this estimate period.
					8	Oct 4, 2021	ROTHEL	\$3,607.17	This adjustment is being made to correct for the AC Adjustment deduction on Estimate #0007
				ACAD - Tota	al			\$22,501.29	
				SUBI	7	Sep 15, 2021	ROTHEL	(\$3,607.17)	This Adjustment is being made in accordance with Order Record #1 and Order Record #2 for a total of 611.90 tons equaling - \$1284.99, and 1105.80 tons equaling - \$2322.18 for total Asphalt AC price adjustments.
					7	Sep 15, 2021	ROTHEL	(\$101,344.30)	This adjustment is being made for in accordance with Order Record #1 and #2 for Bit Base laid during this estimate period. 1717.7 tons at contract price of \$59.00.
					8	Oct 4, 2021	ROTHEL	\$101,344.30	This adjustment is being made to correct the adjustment that was made on Estimate #007 for substandard material. Order Record was rescinded and material was accepted.
				SUBI - Total				(\$3,607.17)	
			Other Item /	Adjustment -	Total			\$18,894.12	
			Price FUEL		7	Sep 15, 2021	SYSTEM	\$1,148.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Oct 4, 2021	SYSTEM	\$2,933.70	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$4,081.71	
			Price FUEL	- Total				\$4,081.71	
	0120 -	Total						\$22,975.83	
	0130	MISC.	Other Item Adjustment	ACAD	7	Sep 15, 2021	ROTHEL	\$777.84	This adjustment is being made for the total square yards of asphalt laid during this estimate period.



### ACAD 8 0.44 0.10 0	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
FUEL 2 Sep 16 2071 2	J9P3458	0130	MISC.		ACAD	8		ROTHEL	\$777.84	
Substitute Sub					ACAD - Tota	al			\$1,555.68	
Public Total Supplied Sup					FUEL	7		ROTHEL	\$154.56	
SUBI 7 2021 2022 2021 2021 2021 2021 2021 2021 2021 2021 2022 2021 202						9		voyleb1	\$1,553.36	Quantity: 1114
SUBI 7 Sep 15 ROTHEL (9777-84) This adjustment is brong made in accordance with Order Record 91 This adjustment is constructed with Order Record 91 This adjustment is constructed with Order Record 91 This adjustment is not constructed with Order Record 91 This adjustment is not constructed with Order Record 91 This adjustment is not constructed with Order Record 91 This adjustment is brong made to correct the adjustment that was made on Estimate Bord Order sections growth of the South of Section 1 Section 2 Section 3 Section 2 Section 3 Section 2 Section 3 Section 2 Section 2 Section 3 Section 2 Section 3 Section 2 Section 3 Section 2 Section 3 Secti					FUEL - Tota				\$1.707.92	
2021 7 Sap 15, ROTHEL (S25,520 0) This adjustment is accordance with fortier factor of the SOYDS of Bit Base and during this estimate period. 78th 950 YOS at the contract price of \$50,00							Sen 15	ROTHEL		This adjustment is being made in accordance with Order Record #1. This
2021 Section					ООВІ		2021			adjustment is removing the AC price adjustment.
Substance Subs							2021			laid during this estimate period. 708.9 SQYDS at the contract price of \$36.00
Other Item Adjustment - Total								ROTHEL	\$25,520.00	Estimate #007 for substandard material. Order Record was rescinded and
Overrun					SUBI - Tota				(\$777.84)	
2021 Stystem				Other Item	Adjustment -	Total			\$2,485.76	
				Overrun	Overrun	9		SYSTEM	\$14,583.60	Estimate Item Adjustment (0012) due to user voyleb1 overridding Payment
						9		SYSTEM	(\$14,583.60)	
10					Overrun - T	otal			\$0.00	
Display				Overrun - T	otal				\$0.00	
PAVEMENT MIXTURE PG64-22 (SUR		0130 -	Total						\$2,485.76	
10		0140	PAVEMENT MIXTURE	Material		10		SYSTEM	\$190,976.25	Estimate Item Adjustment (0010) due to user rothel overridding Payment
Estimate Exception 3 on the current Payment Estimate. 11 Nov 16, SYSTEM (\$471,106.50) 2021 \$471,106.50 This adjustment (0006) due to user rothel overridding Payment Estimate. 12 Dec 2, SYSTEM \$471,106.50 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate. 12 Dec 2, SYSTEM (\$471,106.50) 14 Dec 2, SYSTEM (\$471,106.50) 15 Dec 2, SYSTEM (\$471,106.50) 16 Dec 2, SYSTEM (\$471,106.50) 17 Dec 2, SYSTEM (\$471,106.50) 18 Dec 2, SYSTEM (\$471,106.50) 19 Dec 14, SOUND (\$471,106.50) 10 Nov 2, SOUND (\$471,106.50) 2021 This Adjustment is for total tons of Surface Leveling mix placed during this estimate period. 10 Nov 2, SOTHEL \$267,07.26 This Adjustment is being made for 12223.00 tons of Surface Leveling Mix installed during this estimate period. 11 Nov 16, SOTHEL \$9,639.13 This Adjustment is being made for 4411.5 tons of Surface Leveling Mix installed during this estimate period. 11 Nov 16, SOTHEL \$38,202.82 12 Dec 2, SYSTEM (\$63,291.31) Reference Item Price Adjustment Type applied is FUEL Sound (\$471,37702') is applied (if non-zero).			PG64-22 (SUR			10		SYSTEM	(\$190,976.25)	
12						11		SYSTEM	\$471,106.50	Estimate Item Adjustment (0006) due to user rothel overridding Payment
2021 Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.						11		SYSTEM	(\$471,106.50)	
Total S0.00 Material - Total Other Item Adjustment ACAD 8 Oct 4, 2021 9 Oct 18, 2021 10 Nov 2, 2021 11 Nov 16, 2021 ACAD - Total S9,639.13 ACAD - Total ACAD - Total Overrun Overrun Overrun Overrun Payment Estimate Exception 6 on the current Payment Istimate Material Insufficiency Quantity 7419.000; Overrun Quantity Balance 974.30. Overrun Quantity Salance Overrun Payment Estimate Exception 6 on the current Payment Istimate Material Insufficiency Quantity 7419.000; Overrun Quantity Balance 974.30. Overrun Quantity Balance 974.30. Overrun Quantity Balance 974.30. Overrun Quantity Balance 974.30. Overrun Quantity Balance Overrun Overrun Payment Estimates of '1.37702' is applied (if non-zero).						12		SYSTEM	\$471,106.50	Estimate Item Adjustment (0002) due to user rothel overridding Payment
Other Item Adjustment ACAD 8 Oct 4, 2021 S1,494.16 This adjustment is for total tons of Surface Leveling mix placed during this estimate period. 9 Oct 18, 2021 S362.27 Virgin AC % : 4.6 Mix ID : SL 21-26 10 Nov 2, 2021 September 11 Nov 16, 2021 This Adjustment is being made for 12223.00 tons of Surface Leveling Mix installed during this estimate period. 11 Nov 16, 2021 This Adjustment is being made for 12223.00 tons of Surface Leveling Mix installed during this estimate period. ACAD - Total S38,202.82 Other Item Adjustment - Total S38,202.82 Overrun Overrun This Adjustment is possible to set made for 4411.5 tons of Surface Leveling Mix installed during this estimate period. Reference Item Price Adjustment Index Adjustment Type applied is FUEL SYSTEM 2021 This adjustment (0005) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 7419.000; Overrun Quantity Balance 974.30. 12 Dec 2, 2021 SYSTEM (\$63,209.68) Averaged Price Adjustment from this item on all previous payment estimates of 13.7702 is applied (if non-zero).						12		SYSTEM	(\$471,106.50)	
Other Item Adjustment ACAD 8 Oct 4, 2021 S1,494.16 This adjustment is for total tons of Surface Leveling mix placed during this estimate period. 9 Oct 18, 2021 Tons: 165.8 Virgin AC %: 4.6 Mix ID: SL 21-26 10 Nov 2, ROTHEL \$26,707.26 This Adjustment is being made for 12223.00 tons of Surface Leveling Mix installed during this estimate period. 11 Nov 16, 2021 S38,202.82 Other Item Adjustment - Total S38,202.82 Overrun Overrun 1 Nov 16, 2021 This Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment Insufficiency Quantity 7419.000; Overrun Quantity Balance 974.30. 12 Dec 2, 2021 SYSTEM (\$63,299.68) Averaged Price Adjustment from this item on all previous payment estimates of '1.37702' is applied (if non-zero).					- Total				\$0.00	
Adjustment 2021 estimate period. 9				Material - To	otal				\$0.00	
Virgin AC %: 4.6 Mix ID: SL 21-26 10 Nov 2, 2021 Fins Adjustment is being made for 12223.00 tons of Surface Leveling Mix installed during this estimate period. 11 Nov 16, 2021 S38,202.82 Other Item Adjustment - Total S38,202.82 Overrun Overrun II Nov 16, 2021 Fins Adjustment Index Adjustment Type applied is FUEL 11 Nov 16, 2021 Fins Adjustment - Total S38,202.82 Overrun Overrun II Nov 16, 2021 Fins Adjustment Index Adjustment Type applied is FUEL 11 Nov 16, 2021 Fins Adjustment - Total S48,202.82 Overrun Overrun II Nov 16, 2021 Fins Adjustment Index Adjustment Type applied is FUEL Fit adjustment Index Adjustment Index Adjustment Fit adjustment Estimate Item Adjustment Index Adjustment Fit adjustment Estimate Item Adjustment Index Adjustment Fit adjustme					ACAD	8		ROTHEL	\$1,494.16	
2021 Installed during this estimate period. 11 Nov 16, 2021 System Syste						9		voyleb1	\$362.27	Virgin AC % : 4.6
ACAD - Total \$38,202.82						10		ROTHEL	\$26,707.26	
Overrun Nov 16, 2021 11 Nov 16, 2021 Nov 16, 2021 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 7419.000; Overrun Quantity Balance 974.30. Dec 2, 2021 SYSTEM (\$63,209.68) Averaged Price Adjustment from this item on all previous payment estimates of '1.37702' is applied (if non-zero).						11		ROTHEL	\$9,639.13	
Overrun Overrun Overrun Nov 16, 2021 Nov 16, 2021 SYSTEM					ACAD - Tota	al			\$38,202.82	
2021 Nov 16, 2021 SYSTEM \$63,291.31 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 7419.000; Overrun Quantity Balance 974.30. Dec 2, 2021 SYSTEM (\$63,209.68) Averaged Price Adjustment from this item on all previous payment estimates of '1.37702' is applied (if non-zero).				Other Item	Adjustment -	Total			\$38,202.82	
11 Nov 16, 2021 \$\\$ \$63,291.31 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 7419.000; Overrun Quantity Balance 974.30. 12 Dec 2, 2021 \$\\$ \$YSTEM (\$63,209.68) Averaged Price Adjustment from this item on all previous payment estimates of '1.37702' is applied (if non-zero).				Overrun	Overrun	11		SYSTEM	(\$63,291.31)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
2021 of '1.37702' is applied (if non-zero).						11		SYSTEM	\$63,291.31	Estimate Item Adjustment (0005) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 7419.000;
12 Dec 2, SYSTEM \$63,209.68 This adjustment offsets the original system-generated Overrun Payment						12		SYSTEM	(\$63,209.68)	
						12	Dec 2,	SYSTEM	\$63,209.68	This adjustment offsets the original system-generated Overrun Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
				Туре			·		
J9P3458	0140	BITUMINOUS PAVEMENT	Overrun	Overrun		2021			Estimate Item Adjustment (0001) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 7419.000;
		MIXTURE PG64-22 (SUR							Overrun Quantity Balance 974.30.
		FG04-22 (30K		Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
			Price FUEL		8	Oct 4, 2021	SYSTEM	\$267.03	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Oct 18, 2021	SYSTEM	\$231.19	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Nov 2, 2021	SYSTEM	\$17,043.75	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Nov 16,	SYSTEM	\$6,444.32	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
						2021			
				- Total				\$23,986.29	
			Price FUEL	- Total				\$23,986.29	
	0140 -							\$62,189.11	
	0150	TACK COAT	Material		7	Sep 15, 2021	SYSTEM	\$1,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Sep 15, 2021	SYSTEM	(\$1,260.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	11	Nov 16, 2021	SYSTEM	\$4,830.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	\$3,570.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	\$928.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$9,328.20)	
					12	Dec 2, 2021	SYSTEM	(\$9,328.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					12	Dec 2, 2021	SYSTEM	\$9,328.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 22 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T		otui			\$0.00	
	0150 -	Total	Overruit - 1	otai				\$0.00	
	0200	ADVANCED WARNING RAIL SYSTEM	Material		1	Jun 16, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$360.00)	
					2	Jul 1, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$360.00)	
					3	Jul 15, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$360.00)	
					4	Aug 2, 2021	SYSTEM	\$360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$360.00)	
				- Total				\$0.00	



1879-148 2020 ADVANCED	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1	J9P3458	0200	WARNING RAIL	Material - To	otal				\$0.00	
2021 Service Service		0200 -	Total						\$0.00	
2 Jul 1		0210	FLAG ASSEMBLY	Material		1		SYSTEM	\$82.00	Estimate Item Adjustment (0010) due to user rothel overridding Payment
2021 SYSTEM (882.00) 2021 2						1		SYSTEM	(\$82.00)	
3						2		SYSTEM	\$82.00	Estimate Item Adjustment (0012) due to user rothel overridding Payment
2021 Estimate Item Adjustment (0019) due to user rotted overridding Payment Estimate Exception 4 on the current Payment Estimate (1974) and 1974 2021						2		SYSTEM	(\$82.00)	
2021						3		SYSTEM	\$82.00	Estimate Item Adjustment (0019) due to user rothel overridding Payment
2021 SYSTEM S3,000 to System						3		SYSTEM	(\$82.00)	
2021						4		SYSTEM	\$82.00	Estimate Item Adjustment (0013) due to user rothel overridding Payment
Material - Total						4		SYSTEM	(\$82.00)	
1					- Total				\$0.00	
1				Material - To	otal				\$0.00	
CRIM LINE		0210 -	Total						\$0.00	
2021 2		0220		Material		1		SYSTEM	\$3,600.00	Estimate Item Adjustment (0011) due to user rothel overridding Payment
2021 SySTEM Sys						1		SYSTEM	(\$3,600.00)	
2021 3						2		SYSTEM	\$3,600.00	Estimate Item Adjustment (0013) due to user rothel overridding Payment
2021 Estimate Item Adjustment (0020) due to user rothel overridding Payment Estimate Exception 5 on the current Payment Estimate.						2		SYSTEM	(\$3,600.00)	
2021						3		SYSTEM	\$3,600.00	Estimate Item Adjustment (0020) due to user rothel overridding Payment
2021 Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 5 on the current Payment Estimate. 1 Aug 2, 2021 \$9.00 Naterial - Total \$0.00						3		SYSTEM	(\$3,600.00)	
Total \$0.00						4		SYSTEM	\$3,600.00	Estimate Item Adjustment (0014) due to user rothel overridding Payment
Description						4		SYSTEM	(\$3,600.00)	
CMS W/O COMMUNICATION INTERFACE, CONT F/ SYSTEM SYSTEM SYSTEM STI,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. SYSTEM SYSTEM STI,000.00 This adjustment offsets the original system-generated Material Payment SYSTEM SYSTEM STI,000.00 This adjustment offsets the original system-generated Material Payment Stimate Item Adjustment (0014) due to user rothel overridding Payment STI,000.00 STI,000.00 STI,000.00 STI,000.00 STI,000.00 This adjustment offsets the original system-generated Material Payment STI,000.00 ST									\$0.00	
CMS W/O COMMUNICATION INTERFACE, CONT F/ 1 Jun 16, 2021 SYSTEM \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 1 Jun 16, 2021 SYSTEM (\$11,000.00) 2 Jul 1, 2021 SYSTEM \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 2 Jul 1, 2021 SYSTEM (\$11,000.00) 3 Jul 15, SYSTEM \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 3 Jul 15, SYSTEM (\$11,000.00)				Material - To	otal					
COMMUNICATION INTERFACE, CONT F/ 2021 Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate. 1 Jun 16, 2021 2 Jul 1, 2021 SYSTEM \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 2 Jul 1, 2021 SYSTEM \$11,000.00 2 Jul 15, SYSTEM \$11,000.00 This adjustment (0014) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jul 15, SYSTEM \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user rothel overridding Payment Estimate Item Adjustment (0021) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jul 15, SYSTEM (\$11,000.00)										
1 Jun 16, 2021 (\$11,000.00) 2 Jul 1, 2021 SYSTEM \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 2 Jul 1, 2021 SYSTEM (\$11,000.00) 3 Jul 15, 2021 \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jul 15, SYSTEM (\$11,000.00)		0230	COMMUNICATION INTERFACE,	Material		1		SYSTEM	\$11,000.00	Estimate Item Adjustment (0012) due to user rothel overridding Payment
2021 Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 2 Jul 1, 2021 3 Jul 15, 2021 \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jul 15, SYSTEM (\$11,000.00)			CONT F/			1		SYSTEM	(\$11,000.00)	
2021 3 Jul 15, 2021 \$11,000.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate. 3 Jul 15, SYSTEM (\$11,000.00)						2		SYSTEM	\$11,000.00	Estimate Item Adjustment (0014) due to user rothel overridding Payment
2021 Estimate Item Adjustment (0021) dué to user rothel overridding Páyment Estimate Exception 6 on the current Payment Estimate. 3 Jul 15, SYSTEM (\$11,000.00)						2		SYSTEM	(\$11,000.00)	
						3		SYSTEM	\$11,000.00	Estimate Item Adjustment (0021) due to user rothel overridding Payment
						3		SYSTEM	(\$11,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0230	CMS W/O COMMUNICATION INTERFACE,	Material		4	Aug 2, 2021	SYSTEM	\$11,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate.
		CONT F/			4	Aug 2, 2021	SYSTEM	(\$11,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0230 -	· Total						\$0.00	
	0270	PREF THERMO PVMT MARK, LT/RT ARROW	Material		12	Dec 2, 2021	SYSTEM	\$3,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$3,240.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0280	TEMPORARY REMOVABLE MARKING TAPE 4 IN.,	Material		1	Jun 16, 2021	SYSTEM	\$4,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
		114.,			1	Jun 16, 2021	SYSTEM	(\$4,350.00)	
					2	Jul 1, 2021	SYSTEM	\$4,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$4,350.00)	
					3	Jul 15, 2021	SYSTEM	\$4,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$4,350.00)	
					4	Aug 2, 2021	SYSTEM	\$4,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$4,350.00)	
					5	Aug 16, 2021	SYSTEM	\$8,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user rothel overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$8,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	1	Jun 16, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 2175.000; Overrun Quantity Balance 675.00.
					1	Jun 16, 2021	SYSTEM	(\$1,350.00)	
					2	Jul 1, 2021	SYSTEM	(\$1,350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					2	Jul 1, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 2175.000; Overrun Quantity Balance 675.00.
					3	Jul 15, 2021	SYSTEM	(\$1,350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Jul 15, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 2175.000; Overrun Quantity Balance 675.00.
					4	Aug 2, 2021	SYSTEM	(\$1,350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					4	Aug 2, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 39 on the current Payment Estimate. Material Insufficiency Quantity 2175.000;



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0280	TEMPORARY	Overrun	Overrun					Overrun Quantity Balance 675.00.
		REMOVABLE MARKING TAPE 4 IN.,			5	Aug 16, 2021	SYSTEM	(\$1,350.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Aug 16, 2021	SYSTEM	\$3,850.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 4100.000; Overrun Quantity Balance 2600.00.
					5	Aug 16, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 26 on the current Payment Estimate. Material Insufficiency Quantity 4100.000; Overrun Quantity Balance 2600.00.
					5	Aug 16, 2021	SYSTEM	(\$3,850.00)	
					6	Sep 2, 2021	SYSTEM	(\$5,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Sep 2, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user rothel overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Sep 15, 2021	SYSTEM	(\$5,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Sep 15, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$5,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Oct 4, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 28 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$5,200.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) due to user voyleb1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0280 -	Total						\$0.00	
	0290	4 IN. WHITE WATERBORNE PAVEMENT MARKING	Material		12	Dec 2, 2021	SYSTEM	\$23,889.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 7 on the current Payment Estimate.
		WARRING			12	Dec 2, 2021	SYSTEM	(\$23,889.90)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Other Item Adjustment	PPPS	12	Dec 2, 2021	ROTHEL	(\$4,777.98)	This adjustment is being made for 20% deduction until retroreflectivity readings are conducted.
				PPPS - Tota	ıl			(\$4,777.98)	
				REFL	14	Jan 5, 2023	ROTHEL	\$4,777.98	This Adjust is being made to add the 20% deduction that was made on Estimate #0012
					14	Jan 5, 2023	ROTHEL	(\$726.61)	This Adjustment is being made for reflectivity results performed on 12/14/21
								\$4,051.37	
				REFL - Tota	"				
			Other Item	REFL - Tota Adjustment -				(\$726.61)	
	0290 -	·Total	Other Item						
	0290 -	4 IN. YELLOW WATERBORNE PAVEMENT	Other Item A			Dec 2, 2021	SYSTEM	(\$726.61)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 9 on the current Payment Estimate.
		4 IN. YELLOW WATERBORNE		Adjustment -	Total		SYSTEM	(\$726.61) (\$726.61)	Estimate Item Adjustment (0008) due to user rothel overridding Payment
		4 IN. YELLOW WATERBORNE PAVEMENT			Total	2021 Dec 2,		(\$726.61) (\$726.61) \$21,914.10	Estimate Item Adjustment (0008) due to user rothel overridding Payment
		4 IN. YELLOW WATERBORNE PAVEMENT		Adjustment -	Total	2021 Dec 2,		(\$726.61) (\$726.61) \$21,914.10 (\$21,914.10)	Estimate Item Adjustment (0008) due to user rothel overridding Payment
		4 IN. YELLOW WATERBORNE PAVEMENT	Material	Adjustment -	12 12 12	2021 Dec 2,		(\$726.61) (\$726.61) \$21,914.10 (\$21,914.10) \$0.00	Estimate Item Adjustment (0008) due to user rothel overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0300	4 IN. YELLOW WATERBORNE	Other Item Adjustment	REFL	14	Jan 5, 2023	ROTHEL	\$4,382.82	This Adjust is being made to add the 20% deduction that was made on Estimate #0012
		PAVEMENT MARKING			14	Jan 5, 2023	ROTHEL	(\$431.98)	This Adjustment is being made for reflectivity results performed on 12/14/21
				REFL - Tota	ıl			\$3,950.84	
			Other Item	Adjustment -	Total			(\$431.98)	
	0300 -	Total						(\$431.98)	
	0310	24 IN. YELLOW WATERBORNE PAVEMENT MARKIN	Material		12	Dec 2, 2021	SYSTEM	\$1,715.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 11 on the current Payment Estimate.
		IVIARRIN			12	Dec 2, 2021	SYSTEM	(\$1,715.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0310 -	· Total						\$0.00	
	0380	CLASS B-1 CONCRETE	Material		1	Jun 16, 2021	SYSTEM	\$1,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 8 on the current Payment Estimate.
					1	Jun 16, 2021	SYSTEM	(\$1,300.00)	
					2	Jul 1, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user rothel overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$3,400.00)	
					3	Jul 15, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user rothel overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$3,400.00)	
					4	Aug 2, 2021	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user rothel overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$3,400.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0380 -	Total						\$0.00	
	0460	PIPE LINER FOR EXISTING CULVERT	Material		3	Jul 15, 2021	SYSTEM	\$40,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user rothel overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$40,200.00)	
					4	Aug 2, 2021	SYSTEM	\$40,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user rothel overridding Payment Estimate Exception 36 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$40,200.00)	
					5	Aug 16, 2021	SYSTEM	\$40,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$40,200.00)	
					6	Sep 2, 2021	SYSTEM	\$40,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user rothel overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$40,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0460 -	Total						\$0.00	
	0470	SEEDING - COOL SEASON	Material		12	Dec 2, 2021	SYSTEM	\$97,610.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment



	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
1002450	0470	CDACCEC	Meterial	Type					Fatimata Evacation 1C on the aureant Daymont Fatimata
J9P3458	0470	GRASSES	Material		12	Dec 2,	SYSTEM	(\$97,610.00)	Estimate Exception 16 on the current Payment Estimate.
					12	2021	STSTEIN	(\$97,010.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	PPPS	12	Dec 2, 2021	ROTHEL	(\$19,522.00)	This adjustment is being made for 20% deduction until seed growth acceptance.
					13	Sep 1, 2022	ROTHEL	\$19,522.00	This Adjustment is for the remaining 20% that was held on Estimate12 until seed acceptance.
				PPPS - Tota	ıl			\$0.00	
			Other Item	Adjustment -	Total			\$0.00	
	0470 -	- Total						\$0.00	
	0480	ROCK DITCH CHECK	Material		2	Jul 1, 2021	SYSTEM	\$1,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user rothel overridding Payment Estimate Exception 16 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$1,600.00)	
					3	Jul 15, 2021	SYSTEM	\$25,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 17 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$25,950.00)	
					4	Aug 2, 2021	SYSTEM	\$40,243.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 37 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$40,243.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun			LIAE	0)/07514		
			Overruii	Overrun	3	Jul 15, 2021	SYSTEM	\$8,331.25	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00.
			Overruit	Overrun	3		SYSTEM	\$8,331.25 \$2,750.00	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000;
			Overruit	Overrun		2021 Jul 15,			Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000;
			Overruit	Overrun	3	Jul 15, 2021 Jul 15,	SYSTEM	\$2,750.00	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000;
			Overruit	Overrun	3	Jul 15, 2021 Jul 15, 2021 Jul 15,	SYSTEM	\$2,750.00 \$1,993.75 (\$13,075.00)	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000;
			Overruit	Overrun	3	2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2,	SYSTEM SYSTEM	\$2,750.00 \$1,993.75 (\$13,075.00)	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00.
			Overruit	Overrun	3 3 4	2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM	\$2,750.00 \$1,993.75 (\$13,075.00) (\$13,075.00)	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000;
			Overruit	Overrun	3 3 4 4	2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,750.00 \$1,993.75 (\$13,075.00) (\$13,075.00) \$5,981.25	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 40 on the current Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000;
			Overruit	Overrun	3 3 4 4	2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,750.00 \$1,993.75 (\$13,075.00) (\$13,075.00) \$5,981.25 \$8,312.50	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00.
			Overruit	Overrun	3 3 4 4 4	2021 Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,750.00 \$1,993.75 (\$13,075.00) (\$13,075.00) \$5,981.25 \$8,312.50	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00. This adjustment offsets the original system-generated Overrun Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00.
			Overruit	Overrun	3 3 4 4 4	Jul 15, 2021 Jul 15, 2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$2,750.00 \$1,993.75 (\$13,075.00) (\$13,075.00) \$5,981.25 \$8,312.50 \$13,075.00	Estimate Item Adjustment (0009) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 4152.000; Overrun Quantity Balance 2092.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.0000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 40 on the current Payment Estimate. Material Insufficiency Quantity 6439.000; Overrun Quantity Balance 4379.00.



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0480	ROCK DITCH CHECK	Overrun	Overrun	8	Oct 4, 2021	SYSTEM	(\$525.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Oct 4, 2021	SYSTEM	\$4,593.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 29 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	\$525.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 29 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$4,593.75)	
					9	Oct 18, 2021	SYSTEM	(\$5,118.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$5,118.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user voyleb1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	\$27,368.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.25000 - 6.25000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0480 -	Total						\$0.00	
	0500	SILT FENCE	Material		3	Jul 15, 2021	SYSTEM	\$4,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 18 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$4,890.00)	
					4	Aug 2, 2021	SYSTEM	\$8,105.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 38 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$8,105.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Material - To	Overrun	3	Jul 15, 2021	SYSTEM	\$0.00 \$140.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00.
					3		SYSTEM SYSTEM		Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000;
						2021 Jul 15,		\$140.00	Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000;
					3	Jul 15, 2021 Aug 2,	SYSTEM	\$140.00 (\$140.00)	Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates
					3	Jul 15, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM	\$140.00 (\$140.00) (\$140.00)	Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000;
					3 4 4	Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM	\$140.00 (\$140.00) (\$140.00) \$3,215.00	Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000;
					3 4 4 4	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$140.00 (\$140.00) (\$140.00) \$3,215.00	Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000;
					3 4 4 4 4	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$140.00 (\$140.00) (\$140.00) \$3,215.00 (\$3,215.00)	Estimate Item Adjustment (00¹4) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00.
					3 4 4 4 5	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$140.00 (\$140.00) (\$140.00) \$3,215.00 (\$3,215.00) (\$3,355.00)	Estimate Item Adjustment (000 14) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment
					3 4 4 4 5 5 6	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Sep 2, 2021 Sep 2, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$140.00 (\$140.00) (\$140.00) \$3,215.00 (\$3,215.00) (\$3,355.00) \$9,902.50	Estimate Item Adjustment (000 14) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment
					3 4 4 4 5 6	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Sep 2, 2021 Sep 15, 5ep 15,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$140.00 (\$140.00) (\$140.00) \$3,215.00 (\$3,215.00) (\$3,355.00) \$9,902.50	Estimate Item Adjustment (0014) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 28 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates
					3 4 4 4 5 6 6	2021 Jul 15, 2021 Aug 2, 2021 Aug 2, 2021 Aug 2, 2021 Aug 16, 2021 Sep 2, 2021 Sep 15, 2021 Sep 15, 2021	SYSTEM	\$140.00 (\$140.00) (\$140.00) \$3,215.00 (\$3,215.00) (\$3,355.00) (\$9,902.50 (\$9,902.50)	Estimate Item Adjustment (000 14) overridding Payment Estimate Exception 21 on the current Payment Estimate. Material Insufficiency Quantity 1956.000; Overrun Quantity Balance 56.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0007) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 41 on the current Payment Estimate. Material Insufficiency Quantity 3242.000; Overrun Quantity Balance 1342.00. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user rothel overridding Payment Estimate Exception 28 on the current Payment Estimate. Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero). This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (from this item on all previous payment estimates of '0.00000' is applied (if non-zero).



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3458	0500	SILT FENCE	Overrun	Overrun		2021			Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 30 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	\$9,902.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0013) due to user rothel overridding Payment Estimate Exception 30 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$6,600.00)	
					9	Oct 18, 2021	SYSTEM	(\$16,502.50)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$16,502.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) due to user voyleb1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	\$3,355.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2.50000 - 2.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0500 -	Total						\$0.00	
	0560	WOOD POST, 4 IN. BY 4 IN.	Material		12	Dec 2, 2021	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 20 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$1,350.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0560 -	Total						\$0.00	
	0630	MISC. REMOVALS	Material		8	Oct 4, 2021	SYSTEM	\$7,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user rothel overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$7,350.00)	
					9	Oct 18, 2021	SYSTEM	\$7,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user voyleb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$7,350.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0630 -	Total						\$0.00	
	0640	EPOXY POLYMER WEARING SURFACE	Material		12	Dec 2, 2021	SYSTEM	\$40,059.12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user rothel overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$40,059.12)	
				- Total				\$0.00	
			Material - To	- Total				\$0.00	
	0640 -	Total						\$0.00	
	0650	CLASS B-2 CONCRETE	Material		4	Aug 2, 2021	SYSTEM	\$62,608.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user rothel overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$62,608.00)	
				- Total				\$0.00	
		Material - Total						\$0.00	
	0650 -	Total						\$0.00	
	0660	CURB BLOCKOUT	Material		4	Aug 2, 2021	SYSTEM	\$33,756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user rothel overridding Payment Estimate Exception 21 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$33,756.00)	
					5	Aug 16, 2021	SYSTEM	\$33,756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 12 on the current Payment Estimate.





Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0660	CURB BLOCKOUT	Material	Туре	5	Aug 16,	SYSTEM	(\$33,756.00)	
001 0400						2021		(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
					6	Sep 2, 2021	SYSTEM	\$33,756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user rothel overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$33,756.00)	
					7	Sep 15, 2021	SYSTEM	\$33,756.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user rothel overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Sep 15, 2021	SYSTEM	(\$33,756.00)	
					8	Oct 4, 2021	SYSTEM	\$67,425.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user rothel overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$67,425.00)	
					9	Oct 18, 2021	SYSTEM	\$67,425.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user voyleb1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$67,425.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0660 -	Total						\$0.00	
	0670	HALF-SOLE REPAIR	Material		2	Jul 1, 2021	SYSTEM	\$35,952.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user rothel overridding Payment Estimate Exception 15 on the current Payment Estimate.
					2	Jul 1, 2021	SYSTEM	(\$35,952.50)	
					3	Jul 15, 2021	SYSTEM	\$35,952.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user rothel overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	Jul 15, 2021	SYSTEM	(\$35,952.50)	
					4	Aug 2, 2021	SYSTEM	\$35,952.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user rothel overridding Payment Estimate Exception 29 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$35,952.50)	
					6	Sep 2, 2021	SYSTEM	\$120,908.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user rothel overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$120,908.75)	
					7	Sep 15, 2021	SYSTEM	\$120,908.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user rothel overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Sep 15, 2021	SYSTEM	(\$120,908.75)	
					8	Oct 4, 2021	SYSTEM	\$120,908.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user rothel overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Oct 4, 2021	SYSTEM	(\$120,908.75)	
					9	Oct 18, 2021	SYSTEM	\$120,908.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user voyleb1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$120,908.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	6	Sep 2, 2021	SYSTEM	\$71,658.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 29 on the current Payment Estimate. Material Insufficiency Quantity 2455.000; Overrun Quantity Balance 1455.00.





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9P3458	0670	HALF-SOLE REPAIR	Overrun	Overrun	6	Sep 2, 2021	SYSTEM	(\$71,658.75)	
					7	Sep 15, 2021	SYSTEM	(\$71,658.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					7	Sep 15, 2021	SYSTEM	\$71,658.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) overridding Payment Estimate Exception 25 on the current Payment Estimate. Material Insufficiency Quantity 2455.000; Overrun Quantity Balance 1455.00.
					8	Oct 4, 2021	SYSTEM	(\$71,658.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					8	Oct 4, 2021	SYSTEM	\$71,658.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0016) overridding Payment Estimate Exception 31 on the current Payment Estimate. Material Insufficiency Quantity 2455.000; Overrun Quantity Balance 1455.00.
					9	Oct 18, 2021	SYSTEM	(\$71,658.75)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					9	Oct 18, 2021	SYSTEM	\$71,658.75	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) overridding Payment Estimate Exception 33 on the current Payment Estimate. Material Insufficiency Quantity 2455.000; Overrun Quantity Balance 1455.00.
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0670 -	Total						\$0.00	
	0690	CLEANING AND EPOXY COATING	Material		4	Aug 2, 2021	SYSTEM	\$8,310.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user rothel overridding Payment Estimate Exception 30 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$8,310.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0690 -	Total						\$0.00	
	0700	REINFORCING STEEL (EPOXY COATED)	Material		4	Aug 2, 2021	SYSTEM	\$13,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user rothel overridding Payment Estimate Exception 31 on the current Payment Estimate.
					4	Aug 2, 2021	SYSTEM	(\$13,104.00)	
					5	Aug 16, 2021	SYSTEM	\$13,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user rothel overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$13,104.00)	
					6	Sep 2, 2021	SYSTEM	\$13,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user rothel overridding Payment Estimate Exception 21 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$13,104.00)	
				- Total				\$0.00	
								\$0.00	
			Material - To	otal				\$0.00	
	0700 -	Total	Material - To	otal				\$0.00	
J9P3458 -		Total	Material - To	otal					