

# Pay Estimate Created Date: August 2, 2021

Progress Estimate N 3	lumber	Contract ID Prime Contracto	210416-C03 r Boone Construc		Pay Period Start Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	\$849,248.00 \$0.00 \$849,248.00
Approval Date								By User
August 2, 2021			Generated and A	pproved (a	and should be cons	idered Draft) a	the Project Office Level by	vohsr1
August 2, 2021		Rev	viewed and Appro	ved (and sl	hould be considere	ed Draft) at the	Resident Engineer Level by	penner1
August 3, 2021		Controllers Office Level by	ramses1					
Original Completion	n Date	of Current Contract Amount	Amount Complete					
October 29, 202	1	October	29, 2021				19.79%	
	Contrac	t Informational Dat	es		Miles	tones		
Date Description	Original	Completion Date	Current Comple	tion Date	No Milestones E	xist for Contrac	t	
Acceptance Date								
Awarded Date	May 5, 2	021	May 5, 2021					
Letting Date	April 16,	2021	April 16, 2021					
Notice to Proceed Date	June 7, 2	2021	June 7, 2021					
Work Began Date								

Contract Total Pay For Estimate No.	3			
	This Estimate	Previous	To Date	
210416-C03				
Total Posted Iter	ns Pay <mark>\$55,248.40</mark>	\$112,808.50	\$168,056.90	
Gross Item Adjus	stments \$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Dama	age <mark>\$0.00</mark>	\$0.00	\$0.00	
Other Contract A	djustments <mark>\$0.00</mark>	\$0.00	\$0.00	
		<mark>\$112,808.50</mark>	\$168,056.90	
Contract Total Payable This Estimate:	\$55,248.40			

#### Items Paid This Estimate Period

Project Number	Line Number	ltem Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4S3369	0230	6181000	MOBILIZATION	LS	\$46,500.000	0.25	\$11,625.00
	0290	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	LF	\$97.000	182.2	\$17,673.40
	0300	7027000	PILE POINT REINFORCEMENT	EA	\$110.000	5	\$550.00
	0310	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	CUYD	\$1,000.000	25.4	\$25,400.00
Project J4S336	9 - Total						\$55,248.40
<b>Overall - Total</b>							\$55,248.40

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3369	0280	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-213	\$84.00	(\$17,892.00)
	0280	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	213	\$84.00	\$17,892.00
	0290	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material			-182.2	\$97.00	(\$17,673.40)
	0290	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	182.2	\$97.00	\$17,673.40



# Pay Estimate Created Date: August 2, 2021

Progr	ress Estin 3	mate Number	Contract ID Prime Cont		16-C03 e Constructio	n Co. Pay Period End August 1, 2021 Net C	inal Contract Change Orde ent Contract	r Amount	849,248.00 0.00 849,248.00
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3369						Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
	0300		PILE POINT ORCEMENT	Material			-13	\$110.00	(\$1,430.00)
	0300		PILE POINT ORCEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	13	\$110.00	\$1,430.00
	0310		CONCRETE TRUCTURE)	Material			-25.4	\$1,000.00	(\$25,400.00
	0310		CONCRETE TRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	25.4	\$1,000.00	\$25,400.00
Total									\$0.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	ontract Project Informat	ion
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J4S3369	I-49-2(426)	Bridge replacement	49 OR	CASS	over Tennessee Creek		
Totals by .	Job Numbers	6					
J4S3369		Item Pay tem Adjustme		tem Pay	This Estimate \$55,248.40 \$0.00 <b>\$55,248.40</b>	Previous \$112,808.50 \$0.00 \$112,808.50	<b>To Date</b> \$168,056.90 \$0.00 <b>\$168,056.90</b>
			tments		\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

# Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3369, Item 7021212, Project Item Line Number 0280, Material Set 702121296, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Waiting on materials certifications for piles.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3369, Item 7021214, Project Item Line Number 0290, Material Set 702121496, Material 0702PLSSMAZC - Bearing Piles Struct Steel Galvd, Acceptance Action Generic 0702PLSSMAZC is insufficient.	Waiting on materials certification for piling.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3369, Item 7027000, Project Item Line Number 0300, Material Set 702700096, Material 0702PLPT - Pile Point Reinforcement, Acceptance Action Generic 0702PLPT is insufficient.	Waiting on materials certification for pile point reinforcement.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3369, Item 7032003, Project Item Line Number 0310, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Waiting on concrete testing results	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3369, Item 7032003, Project Item Line Number 0310, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Waiting on concrete testing results	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3369, Item 7032003, Project Item Line Number 0310, Material Set 703200396, Material 1005GECMLS - Masonry Grade E LS/DO, Acceptance Action Generic 1005GECMLS is insufficient.	Waiting on concrete testing results	vohsr1	Overridden

### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					eport Generated date and can differ from the posted am	posted amount at the time the Estimate was Generated.						
Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-C03	J4S3369	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$1,000.00	\$1,000.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.30	\$17,500.00	\$5,250.00
		0001	0030	2031000	CLASS A EXCAVATION	562.00	0.00	562.00	CUYD	0.00	\$16.00	\$0.00
		0001	0040	2036000	COMPACTING EMBANKMENT	332.00	0.00	332.00	CUYD	0.00	\$17.50	\$0.00
		0070	0050	2061000	CLASS 1 EXCAVATION	90.00	0.00	90.00	CUYD	90.00	\$33.00	\$2,970.00
		0001	0060	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	4.00	0.00	4.00	100F	0.00	\$900.00	\$0.00
		0001	0070	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	0.00	\$1,550.00	\$0.00
		0070	0080	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$60,000.00	\$60,000.00
		0001	0090	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,175.00	0.00	1,175.00	SQYD	0.00	\$7.00	\$0.00
		0001	0100	4019905	MISC.OPTIONAL PAVEMENT	1,050.00	0.00	1,050.00	SQYD	0.00	\$65.00	\$0.00
		0070	0110	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	129.00	0.00	129.00	SQYD	0.00	\$100.00	\$0.00
		0010	0120	6061060	MGS GUARDRAIL	250.00	0.00	250.00	LF	0.00	\$23.00	\$0.00
		0010	0130	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	0.00	\$2,825.00	\$0.00
		0010	0140	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,700.00	\$0.00
		0001	0150	6113020	FURNISHING TYPE 2 ROCK BLANKET	360.00	0.00	360.00	CUYD	0.00	\$48.00	\$0.00
		0001	0160	6113040	PLACING TYPE 2 ROCK BLANKET	360.00	0.00	360.00	CUYD	0.00	\$29.00	\$0.00
		0001	0170	6161005	CONSTRUCTION SIGNS	501.00	0.00	501.00	SQFT	281.00	\$5.00	\$1,405.00
		0001	0180	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$35.00	\$140.00
		0001	0190	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$10.00	\$0.00
		0001	0200	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	0.00	\$10.00	\$0.00
		0001	0210	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$215.00	\$2,150.00
		0001	0220	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	0230	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$46,500.00	\$23,250.00
		0001	0240	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0250	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	1,120.00	0.00	1,120.00	LF	0.00	\$0.85	\$0.00
		0001	0260	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	540.00	0.00	540.00	SQYD	0.00	\$3.00	\$0.00
		0001	0270	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$3,000.00	\$3,000.00
		0070	0280	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	252.00	0.00	252.00	LF	213.00	\$84.00	\$17,892.00
		0070	0290	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN)	355.00	0.00	355.00	LF	182.20	\$97.00	\$17,673.40
		0070	0300	7027000	PILE POINT REINFORCEMENT	18.00	0.00	18.00	EA	18.00	\$110.00	\$1,980.00
		0070	0310	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	86.00	0.00	86.00	CUYD	25.40	\$1,000.00	\$25,400.00
		0070	0320	7034219A	TYPE D BARRIER	269.00	0.00	269.00	LF	0.00	\$96.00	\$0.00
		0070	0330	7034222	SLAB ON CONCRETE BEAM	421.00	0.00	421.00	SQYD	0.00	\$375.00	\$0.00
		0070	0340	7056065	17 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	474.00	0.00	474.00	LF	0.00	\$330.00	\$0.00
		0070	0350	7061060	REINFORCING STEEL (BRIDGES)	5,860.00	0.00	5,860.00	LB	0.00	\$1.50	\$0.00
		0070	0360	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.00
		0070	0370	7123610	SLAB DRAIN	20.00	0.00	20.00	EA	0.00	\$575.00	\$0.00
		0070	0380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$2,200.00	\$0.00
		0070	0390	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$225.00	\$0.00
		0070	0400	7161002	LAMINATED NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	0.00	\$260.00	\$0.00
		0001	0410	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$3,300.00	\$0.00
		0001	0420	8061004	SEDIMENT TRAP ROCK	14.00	0.00	14.00	CUYD	0.00	\$160.00	\$0.00
		0001	0430	8061006	ALTERNATE DITCH CHECK	111.00	0.00	111.00	LF	0.00	\$8.00	\$0.00
		0001	0440	8061016	SEDIMENT REMOVAL	22.00	0.00	22.00	CUYD	0.00	\$18.00	\$0.00



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Destad O	uontitioo e	and Value	a ara h	and an	Report Generate	ad data and	Loop diffe	r fram tha	neeted a	mount of the	a time a th	a Estimate y	una Can	aratad
Nole. Posled Q	uanuues a	anu value	es are b	aseu on	Report Generate	eu uale and	i can une		e posteu a	imount at the	e unie ui	e Esimale v	vas Gen	erateu.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-C03	J4S3369	0001	0450	8061017	TEMPORARY SEEDING AND MULCHING	1.00	0.00	1.00	ACRE	0.00	\$2,500.00	\$0.00
		0001	0460	8061019	SILT FENCE	1,240.00	0.00	1,240.00	LF	331.00	\$1.50	\$496.50
		0001	0470	8064133	TYPE 1C EROSION CONTROL BLANKET	2,972.00	0.00	2,972.00	SQYD	0.00	\$1.50	\$0.00
	Project J4	4S3369 - To	otal Value	Posted to D	Date as of Report Generated Date							\$168,606.90
210416-C03 Ove	rall - Total	Value Post	ted to Dat	te as of Rep	ort Generated Date							\$168,606.90



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0230	6181000	MOBILIZATION	7/22/21	8/2/21	0.25	LS	Tenn. Creek Bridge	3+98.50		5+20.00		
0290	7021214	GALVANIZED STRUCTURAL STEEL PILES (14 IN	7/29/21	8/2/21	182.20	LF	Bert 3 Piles Pile 10: 35.5 Pile 11: 37.08 Pile 12: 36.58 Pile 13: 37.16 Pile 14: 35.83	4+80.75		4+80.75		
0300	7027000	PILE POINT REINFORCEMENT	7/29/21	8/2/21	5.00	EA	Bent 3 Piles	4+80.75		4+80.75		
0310	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	7/20/21	8/2/21	12.70	CUYD	End Bent 1	3+98.50		3+98.50		
			7/21/21	8/2/21	12.70	CUYD	End Bent 4	5+20.00		5+20.00		

The information below this line are details for Construction Signs (if applicable). No Data Available



# Line Item Adjustments by Estimate

Contract ID:190621-F01

J45339 Q20 Q4VAVADED STRUCTURES Material STRUCTURES Material Participant STRUCTURES Material Participant STRUCTURES Material Participant Participant STRUCTURES Material Participant Partiti Participant Partiti Participant Partitipant Participant	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	J4S3369	0280	STRUCTURAL STEEL PILES (12	Material		2		SYSTEM	\$17,892.00	Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment
Vision     Pile Point Point     Material Total     Second Point			IN			2		SYSTEM	(\$17,892.00)	
View     View     View       0280 - Total     - Total     50.00       0280 - Total     - Total     50.00       0280 - Total     - Total     50.00       0280 - Total     - Total     - S0.00       0280 - Total     - Total     - S0.00       0280 - Total     - Total     - S0.00       0     - Total     - S0.00       - Total     - S0.00     - S0.00       0     - Total     - S0.00       - Total     - Total     - S0.00       0     - S0.00     - S0.00       0 <td< td=""><td></td><td></td><td></td><td></td><td></td><td>3</td><td>Aug 2, 2021</td><td>SYSTEM</td><td>\$17,892.00</td><td>Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment</td></td<>						3	Aug 2, 2021	SYSTEM	\$17,892.00	Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment
View     Material - Total     Statu						3		SYSTEM	(\$17,892.00)	
0280 - Total     STALVANZED STRUCTING     Material N     Auge 2021     SYSTEM     \$17,673.40     This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.       0280 - Total     - Total     3     Aug 2, 3     SYSTEM     \$17,673.40     Stimate Exception 2 on the current Payment Estimate.       0280 - Total     - Total     50.00     - Total     50.00     - Total       0280 - Total     - Total     50.00     Struct Turner     50.00     - Total       0280 - Total     PILE PORCEMENT     Material - Total     SYSTEM     \$880.00     This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user volsr1 voerriding Payment Estimate Item Adjustment (0002) due to user volsr1 voerriding Payment Estimate Item Adjustment (0002) due to user volsr1 voerriding Payment Estimate Item Adjustment (0003) due to user volsr1 voerriding Payment Estimate Item Adjustment (0003) due to user volsr1 voerriding Payment Estimate Item Adjustment (0003) due to user volsr1 voerriding Payment Estimate Item Adjustment (0003) due to user volsr1 voerriding Payment Estimate Item Adjustment (0004) due to user volsr1 voerriding Payment Estimate Item Adjustment (0004) due to user volsr1 voerriding Payment Estimate Item Adjustment (0004) due to user volsr1 voerriding Payment Estimate Item Adjustment (0004) due to user volsr1 voerriding Payment Estimate Item Adjustment (0004) due to user volsr1 voerriding Payment Estimate Item Adjustment (0004) due to user					- Total				\$0.00	
0290     GALVANIZED STRUCTURAL STRUCTURA				Material - To	otal				\$0.00	
STRUCTURAL STELL PLES IN IN     STRUCTURAL STRUCTUR		0280 -	Total						\$0.00	
		0290	STRUCTURAL STEEL PILES (14	Material		3		SYSTEM	\$17,673.40	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment
Output     Vertial - Total     S0.00       0300     PILE POINT REINFORCEMENT     Material - Total     \$0.00     This adjustment offsets the original system-generated Material Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0003) due to user volser1 overridding Payment Estimate Intern Adjustment (0004) due to user volser1 overridding Payment Estimate Intern Adjustment (0004) due to user volser1 overridding Payment Estimate Exception 3 on the current Payment Estimate.       0310     CLASS E VONCRET [SUBSTRUCTURE]     Aug 2, 2021     SYSTEM     \$25,400.00     This adjustment (0004) due to user volser1 overridding Payment Estimate Exception 4 on the current Payment Estimate.       0310     CLASS E VONCRET [SUBSTRUCTURE]     Image: Image			IN			3	Aug 2, 2021	SYSTEM	(\$17,673.40)	
V290 - Total     S0.00       0300     PILE POINT REINFORCEMENT     Material     2     Jul 16, 2021     SYSTEM     S880.00     This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment       2     Jul 16, 2021     SYSTEM     (\$880.00)     This adjustment offsets the original system-generated Material Payment       2     Jul 16, 2021     SYSTEM     (\$880.00)     This adjustment offsets the original system-generated Material Payment       2     Jul 16, 2021     SYSTEM     (\$1,430.00)     This adjustment offsets the original system-generated Material Payment       4     2021     SYSTEM     (\$1,430.00)     This adjustment offsets the original system-generated Material Payment       6     Total     Total     SUSTEM     (\$1,430.00)     SUSTEM       6     CONCRETE (SUBSTRUCTURE)     Material - Total     SUSTEM     SUSTEM     SUSTEM     SUSTEM       6     CONCRETE (SUBSTRUCTURE)     Material - Total     SUSTEM     SUSTEM     SUSTEM     SUSTEM     SUSTEM       6     Aug 2, 2021     SVSTEM     SUSTEM     SUSTEM     SUSTEM     SUSTEM					- Total				\$0.00	
0300     PILE POINT REINFORCEMENT     Material Network     2     Jul 16, 2021     SYSTEM     \$880.00     This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohor1 overridding Payment Estimate Item Adjustment (0002) due to user vohor1 overridding Payment Estimate Item Adjustment (0002) due to user vohor1 overridding Payment Estimate Item Adjustment (0003) due to user vohor1 overridding Payment Estimate Item Adjustment (0003) due to user vohor1 overridding Payment Estimate Item Adjustment (0003) due to user vohor1 overridding Payment Estimate Item Adjustment (0003) due to user vohor1 overridding Payment Estimate Item Adjustment (0003) due to user vohor1 overridding Payment Estimate Exception 3 on the current Payment Estimate.       0300 - Total     - Total     \$1,430.00     Statustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate Item Adjustment (0004) due to user vohor1 overridding Payment Estimate				Material - To	otal				\$0.00	
Value     REINFORCEMENT		0290 -	Total						\$0.00	
		0300		Material		2		SYSTEM	\$880.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment
Auge 2, 2021   SYSTEM   Setimate Item Adjustment (0003) due to user voher1 overridding Payment Estimate.     - Total   - Total   SYSTEM   (\$1,430.0)     0300 - Total   - Total   SUSTEM   SUSTEM     0310   CLASS B CONCRETE (SUBSTRUCTURE)   Material - Total   SUSTEM   SUSTEM   SUSTEM     0310   CLASS B CONCRETE (SUBSTRUCTURE)   Material   Aug 2, 2021   SYSTEM   Sustemate Item Adjustment offsets the original system-generated Material Payment Estimate.     0310   CLASS B CONCRETE (SUBSTRUCTURE)   Material   Aug 2, 2021   SYSTEM   Sustemate Exception 4 on the current Payment Estimate.     0310   CLASS B CONCRETE (SUBSTRUCTURE)   Image: Total   SUSTEM   Sustemate Item Adjustment (0004) due to user voher1 overridding Payment Estimate.     0310   CLASS B CONCRETE (SUBSTRUCTURE)   Image: Total   SUSTEM   SUSTEM   Sustemate Exception 4 on the current Payment Estimate.     0310   Total   Total   SUSTEM   Sustemate Item Adjustment (0004) due to user voher1 overridding Payment Estimate.     0310   Total   Total   SUSTEM   SUSTEM   SUSTEM     0310   Total   SUSTEM   SUSTEM   SUSTEM   SUSTEM						2		SYSTEM	(\$880.00)	
Image: Provide the state of the st						3		SYSTEM	\$1,430.00	Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment
Material - Total     Subscription     Subscript						3		SYSTEM	(\$1,430.00)	
0300 - Total   \$0.00     0310   CLASS B CONCRETE (SUBSTRUCTURE)   Material CONCRETE (SUBSTRUCTURE)   Material -   3   Aug 2, 2021   SYSTEM   \$25,400.00   This adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.     0   -   -   -   3   Aug 2, 2021   SYSTEM   \$25,400.00     0   -   -   -   -   50.00   -     0   -   -   -   -   -     0   -   -   -   -   -     0   -   -   -   -   -     0   -   -   -   -   -     0   -   -   -   -   -     0   -   -   -   -   -     0   -   -   -   -   -     0   -   -   -   -   -     0   -   -   -   -   -   -     0   -   -   -   -   -   -   -					- Total				\$0.00	
0310     CLASS B CONCRETE (SUBSTRUCTURE)     Material P 0     Aug 2, 2021     SYSTEM     \$25,400.00     This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.       3     Aug 2, 2021     SYSTEM     \$25,400.00     This adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.       4     - Total     - Total     \$30.00     \$55,400.00     \$50.00       0310 - Total     - Total     \$50.00     \$50.00     \$50.00     \$50.00       J4S3369 - Total     - Stat     \$50.00     \$50.00     \$50.00     \$50.00				Material - To	otal				\$0.00	
CONCRETE (SUBSTRUCTURE)     CONCRETE (SUBSTRUCTURE)     2021     Concrete 2021     Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.       • Total     • Total     \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$		0300 -	Total						\$0.00	
Aug 2021 \$0.00   - Total \$0.00   Material - Total \$0.00   0310 - Total \$0.00   J4S3369 - Total \$0.00		0310	CONCRETE	Material		3		SYSTEM	\$25,400.00	Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
Material - Total     \$0.00       0310 - Total     \$0.00       J4\$3369 - Total     \$0.00						3		SYSTEM	(\$25,400.00)	
0310 - Total     \$0.00       J4S3369 - Total     \$0.00				- Total						
J4\$3369 - Total \$0.00				Material - T	otal				\$0.00	
		0310 -	Total						\$0.00	
Overall - Total \$0.00	J4S3369 -	Total							\$0.00	
	Overall -	Total							\$0.00	