

#### **Missouri Department of Transportation Contractor's Pay Estimate Summary**

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number	Contract ID	210416-D05	Pay Period Start November 2, 2021 Original Contract Amount \$1,571,075	3.55
44	Prime Contracto	or Sam Gaines Construction, In	ic. Pay Period End November 15, 2021 Net Change Order Amount \$38,718.8	7
''			Current Contract Amount \$1,609,79	2.42

Approval Date		By User
November 16, 2021	Generated and Approved (and should be considered Draft) at the Project Office Level by	burtoc4
November 17, 2021	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	oeschd1
November 17, 2021	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 20, 2021	December 20, 2021		76.10%

	Contract Informational Dates										
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract								
Acceptance Date											
Awarded Date	May 5, 2021	May 5, 2021									
Letting Date	April 16, 2021	April 16, 2021									
Notice to Proceed Date	May 21, 2021	May 21, 2021									
Work Began Date	June 7, 2021	June 7, 2021									

Contract Total Pay For Estimate No. 11										
	This	s Estimate	Previous	To Date						
210416-D05										
Total Posted I	tems Pay \$15	6,454.20	\$1,068,629.10	\$1,225,083.30						
Gross Item Ac	ljustments \$18	,535.45	(\$58,805.79)	(\$40,270.34)						
Incentive	\$0.0	00	\$0.00	\$0.00						
Disincentive	\$0.0	00	\$0.00	\$0.00						
Liquidated Da	mage \$0.0	00	\$0.00	\$0.00						
Other Contract	t Adjustments \$0.0	00	\$0.00	\$0.00						
			\$1,009,823.31	\$1,184,812.96						
<b>Contract Total Payable This Estimat</b>	e: \$17	74,989.65								

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3378	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$7.000	727.5	\$5,092.50
	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$9.000	691	\$6,219.00
	0800	4019905	MISC.OPTIONAL PAVEMENT	SQYD	\$65.000	691	\$44,915.00
	0090	4019905	MISC.TEMPORARY PAVEMENT	SQYD	\$70.000	100	\$7,000.00
	0100	5021306	CONCRETE PAVEMENT (6 IN. NON-REINFORCED, 15 FT. JOINTS)	SQYD	\$70.000	187.6	\$13,132.00
	0160	6081010	CONCRETE CURB RAMP	SQYD	\$120.000	24.2	\$2,904.00
	0180	6085008	PAVED APPROACH, 8 IN.	SQYD	\$85.000	227.1	\$19,303.50
	0190	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$54.000	28.5	\$1,539.00
	0210	6089905	MISC.CONCRETE PAVEMENT ( 8 IN. NON-REINFORCED) TINTED	SQYD	\$95.000	70	\$6,650.00
	0230	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$75.000	545.6	\$40,920.00
	0240	6091052	CURB AND GUTTER TYPE B	LF	\$42.000	67.6	\$2,839.20
	0550	8031000A	TURF TYPE TALL FESCUE SODDING	SQYD	\$18.000	330	\$5,940.00
Project J5S3	378 - Total						\$156,454.20
Overall - Tot	al						\$156,454.20

#### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 20



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number
11 Contract ID 210416-D05 Pay Period Start November 2, 2021 Original Contract Amount \$1,571,073.55
Prime Contractor Sam Gaines Construction, Inc. Pay Period End November 15, 2021 Net Change Order Amount \$38,718.87
Current Contract Amount \$1,609,792.42

oject mber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3378	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	291.2	\$0.07	\$21.40
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	6	\$0.07	\$0.44
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	73.3	\$0.07	\$5.39
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	179	\$0.07	\$13.16
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	24.2	\$0.07	\$1.78
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	76.9	\$0.07	\$5.6
	0060	BASE (4 IN. THICK)  Adjustment Type applied is FUEL					\$0.07	\$5.65
	0070	BASE (6 IN. THICK)  Adjustment Type applied is FUEL				88.9	\$0.11	\$10.02
	0070	770 TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  Price Reference Item Price Adjustment Index Adjustment Type applied is FUEL				253	\$0.11	\$28.5
	0070	0 TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)  Price Reference Item Price Adjustment Index Adjustment Type applied is FUEL				160	\$0.11	\$18.03
	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	56.2	\$0.11	\$6.33
C	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	83.1	\$0.11	\$9.3
	0070	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	49.8	\$0.11	\$5.6
	0800	MISC.	Other Item Adjustment	Fuel Price		281.42	\$65.00	\$18,292.30
	0800	MISC.	Material			-1,994.763	\$65.00	(\$129,659.6
	0800	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1,994.763	\$65.00	\$129,659.60
	0100	CONCRETE PAVEMENT (6 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	127.2	\$0.24	\$30.54
	0100	CONCRETE PAVEMENT (6 IN. NON-REINFORCED, 15 FT. JOINTS)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	60.4	\$0.24	\$14.5
	0180	PAVED APPROACH, 8 IN.	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	73.3	\$0.29	\$21.5
	0180	PAVED APPROACH, 8 IN.	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	76.9	\$0.29	\$22.6
	0180	PAVED APPROACH, 8 IN.	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	76.9	\$0.29	\$22.6
	0250	CONCRETE CURB LOW PROFILE TYPE E	Material			-496	\$35.00	(\$17,360.0
	0250	CONCRETE CURB LOW PROFILE TYPE E	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user burtoc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.	496	\$35.00	\$17,360.0
	0260	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR	Material			-1	\$2,500.00	(\$2,500.00

Revision 4/1/2020 Page 2 of 20



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: November 16, 2021

Progress Estimate Number
11 Contract ID 210416-D05 Pay Period Start November 2, 2021 Original Contract Amount \$1,571,073.55
Prime Contractor Sam Gaines Construction, Inc. Pay Period End November 15, 2021 Net Change Order Amount \$38,718.87
Current Contract Amount \$1,609,792.42

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
I5S3378		600MM X 600MM)						
	0260	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user burtoc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.	1	\$2,500.00	\$2,500.00
	0280	MANHOLE FRAME AND COVER, TYPE 3 Material					\$500.00	(\$3,500.00
	0280	MANHOLE FRAME AND COVER, TYPE 3	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user burtoc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.	7	\$500.00	\$3,500.00
	0550	TURF TYPE TALL FESCUE SODDING	Material			-723.7	\$18.00	(\$13,026.60
	0550	TURF TYPE TALL FESCUE SODDING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user burtoc4 overridding Payment Estimate Exception 5 on the current Payment Estimate.	723.7	\$18.00	\$13,026.60
	0560	CURB INLET CHECK	Material			-10	\$200.00	(\$2,000.00
	0560	CURB INLET CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0025) due to user burtoc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.	10	\$200.00	\$2,000.00
	0580	SILT FENCE	Material			-197	\$4.00	(\$788.00
	0580	SILT FENCE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0026) due to user burtoc4 overridding Payment Estimate Exception 7 on the current Payment Estimate.	197	\$4.00	\$788.00
otal								\$18,535.4

Revision 4/1/2020 Page 3 of 20



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	n					
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work						
J5S3378 FAS- S402(014) Intersection and ADA improvements M BOONE at Henry Clay Boulevard in Ashland												
Totals by J	Job Number	s										
J5S3378		Item Pay tem Adjustmen	ts Gross It	em Pay	This Estimate \$156,454.20 \$18,535.45 \$174,989.65	Previous \$1,068,629.10 (\$58,805.79) \$1,009,823.31	To Date \$1,225,083.30 (\$40,270.34) \$1,184,812.96					
Incentive Disincentive Liquidated Damages Other Contract Adjustments					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 4 of 20



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 4019905, Project Item Line Number 0080, Material Set 401990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 6092031, Project Item Line Number 0250, Material Set 609203196, Material 1057JMTBE42013 - Tie Bar Ep Ctd 12" No. 4/M13 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 6141120, Project Item Line Number 0260, Material Set 614112096, Material 0614DFGTCV - Curved Vane Grate and Frame, Acceptance Action Generic 0614DFGTCV is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 6143013, Project Item Line Number 0280, Material Set 614301396, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance Action Generic 0614DFMNFC is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 8031000A, Project Item Line Number 0550, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 8061007A, Project Item Line Number 0560, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 8061019, Project Item Line Number 0580, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	No Remark was entered by Engineer	burtoc4	Overridden
Estimate Exception Type: Item Overrun: Contract 210416-D05, Contract Project J5S3378, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6044011, Minor Item.	No Remark was entered by Engineer	burtoc4	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210416-D05, Contract Project J5S3378, Project Item Line Number 0470, Contract Line Item Number 0470, Item 7250315A, Minor Item.	No Remark was entered by Engineer	burtoc4	Acknowledged

Revision 4/1/2020 Page 5 of 20



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted amo	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-D05	J5S3378	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS		\$100,000.00	\$100,000.00
		0001	0015	2024013	REMOVAL OF SURFACING ACM (FRIABLE)	960.00	0.00	960.00	SQFT	525.00	\$20.00	\$10,500.00
		0001	0030	2029950	DEMOLITION AND REMOVAL OF BUILDINGS	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0001	0040	2039901	MISC.EARTHWORK	1.00	0.00	1.00	LS	0.50	\$20,000.00	\$10,000.00
		0001	0050	2063000	CLASS 3 EXCAVATION	605.00	0.00	605.00	CUYD	599.00	\$20.00	\$11,980.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	5,493.00	0.00	5,493.00	SQYD	4,643.57	\$7.00	\$32,504.99
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	4,373.00	0.00	4,373.00	SQYD	4,112.42	\$9.00	\$37,011.78
		0001	0080	4019905	MISC.OPTIONAL PAVEMENT	4,373.00	0.00	4,373.00	SQYD	4,112.42	\$65.00	\$267,307.30
		0001	0090	4019905	MISC.TEMPORARY PAVEMENT	1,093.30	0.00	1,093.30	SQYD	214.80	\$70.00	\$15,036.00
		0001	0100	5021306	CONCRETE PAVEMENT (6 IN. NON-REINFORCED, 15 FT. JOINTS)	322.20	0.00	322.20	SQYD	243.20	\$70.00	\$17,024.00
		0001	0110	6039903	WATER	135.00	0.00	135.00	LF	135.00	\$45.00	\$6,075.00
		0001	0120	6039903	WATER	87.00	0.00	87.00	LF	0.00	\$50.00	\$0.00
		0001	0130	6044011	PIPE COLLAR, TYPE A	2.00	0.00	2.00	EA	3.00	\$500.00	\$1,500.00
		0001	0140	6049901	MISC.FIRE HYDRANT RELOCATION	1.00	-1.00	0.00	LS	0.00	\$15,000.00	\$0.00
		0001	0150	6049902	MISC.ADJUSTING MANHOLES, INLETS, AND VALVES	9.00	0.00	9.00	EA	4.00	\$500.00	\$2,000.00
		0001	0160	6081010	CONCRETE CURB RAMP	264.20	0.00	264.20	SQYD	156.50	\$120.00	\$18,780.00
		0001	0170	6081012	TRUNCATED DOMES	269.00	0.00	269.00	SQFT	159.50	\$35.00	\$5,582.50
		0001	0180	6085008	PAVED APPROACH, 8 IN.	1,432.40	0.00	1,432.40	SQYD	1,025.60	\$85.00	\$87,176.00
		0001	0190	6086004	CONCRETE SIDEWALK, 4 IN.	697.30	97.30 0.00	0.00 697.30	SQYD	538.91	\$54.00	\$29,101.14
		0001	0200	6086007	CONCRETE SIDEWALK, 7 IN.	44.60	0.00	44.60	SQYD	13.80	\$62.00	\$855.60
		0001	0210	6089905	MISC.CONCRETE PAVEMENT ( 8 IN. NON-REINFORCED) TINTED	526.30	0.00	526.30	SQYD	341.90	\$95.00	\$32,480.50
		0001	0220	6089905	MISC.CONCRETE PAVEMENT (8 IN. NON-REINFORCED) NON-	217.40	0.00	217.40	SQYD	121.40	\$85.00	\$10,319.00
		0001	0230	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	1,375.00	0.00	1,375.00	LF	792.50	\$75.00	\$59,437.50
		0001	0240	6091052	CURB AND GUTTER TYPE B	1,480.00	0.00	1,480.00	LF	1,119.80	\$42.00	\$47,031.60
		0001	0250	6092031	CONCRETE CURB LOW PROFILE TYPE E	496.00	0.00	496.00	LF	496.00	\$35.00	\$17,360.00
		0001	0260	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	1.00	0.00	1.00	EA	1.00	\$2,500.00	\$2,500.00
			0270	6141121	600MM)  CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM	3.00	0.00	3.00	EA	3.00	\$3,000.00	\$9,000.00
		0001			X 600MM)							
		0001	0280	6143013	MANHOLE FRAME AND COVER, TYPE 3	7.00	0.00	7.00	EA	7.00	\$500.00	\$3,500.00
		0001	0290	6161005	CONSTRUCTION SIGNS	501.00	0.00	501.00	SQFT	230.00	\$5.90	\$1,357.00
		0001	0300	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$50.00	\$0.00
		0001	0310	6161025	CHANNELIZER (TRIM LINE)	44.00	0.00	44.00	EA	44.00	\$17.00	\$748.00
		0001	0320	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	12.00	\$80.00	\$960.00
		0001	0330	6161040	FLASHING ARROW PANEL	1.00	0.00	1.00	EA	0.00	\$1,600.00	\$0.00
		0001	0340	6161052	WARNING LIGHT, TYPE B	6.00	4.00	10.00	EA	10.00	\$45.00	\$450.00
		0001	0350	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$7,800.00	\$15,600.00
		0001	0360	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$75,000.00	\$75,000.00
		0001	0370	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	0.00	\$390.00	\$0.00
		0001	0380	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	35.00	0.00	35.00	EA	0.00	\$160.00	\$0.00
		0001	0390	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	54.00	0.00	54.00	EA	0.00	\$15.00	\$0.00
		0001	0400	6200045	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0001	0410	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	60.00	0.00	60.00	LF	0.00	\$7.50	\$0.00
		0001	0420	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	27.00	0.00	27.00	LF	0.00	\$7.50	\$0.00
		0001	0430	6209903	MISC.4 IN, WHITE HIGHBUILD WATERBORNE PAVEMENT MARKING W/ TYPE L BEADS	2,251.00	0.00	2,251.00	LF	0.00	\$1.25	\$0.00

Page 6 of 20 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-D05	J5S3378	0001	0440	6209903	MISC.4 IN, YELLOW HIGHBUILD WATERBORNE PAVEMENT MARKING W/ TYPE L BEADS	2,677.00	0.00	2,677.00	LF	0.00	\$1.25	\$0.00
		0001	0450	6209903	MISC.8 IN, WHITE HIGHBUILD WATERBORNE PAVEMENT MARKING W/ TYPE L BEADS	82.00	0.00	82.00	LF	0.00	\$3.75	\$0.00
		0001	0460	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0470	7250315A	15 IN. PIPE GROUP B	279.00	0.00	279.00	LF	300.00	\$55.00	\$16,500.00
		0001	0480	7250318A	18 IN. PIPE GROUP B	240.00	0.00	240.00	LF	213.00	\$65.00	\$13,845.00
		0001	0490	7261015	15 IN. PIPE GROUP A	157.00	0.00	157.00	LF	157.00	\$75.00	\$11,775.00
		0001	0500	7261018	18 IN. PIPE GROUP A	91.00	0.00	91.00	LF	91.00	\$80.00	\$7,280.00
		0001	0510	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	10.00	-4.00	6.00	FT	6.00	\$350.00	\$2,100.00
		0001	0520	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	12.00	0.00	12.00	FT	12.00	\$1,000.00	\$12,000.00
		0001	0530	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	28.00	0.00	28.00	FT	28.00	\$1,000.00	\$28,000.00
		0001	0540	7319913	MISC.PRECAST CONCRETE JUNCTION BOX 5 FT. X 3 FT.	7.00	0.00	7.00	FT	7.00	\$700.00	\$4,900.00
		0001	0550	8031000A	TURF TYPE TALL FESCUE SODDING	1,670.00	0.00	1,670.00	SQYD	723.70	\$18.00	\$13,026.60
		0001	0560	8061007A	CURB INLET CHECK	19.00	0.00	19.00	EA	10.00	\$200.00	\$2,000.00
		0001	0570	8061016	SEDIMENT REMOVAL	21.00	0.00	21.00	CUYD	0.00	\$40.00	\$0.00
		0001	0580	8061019	SILT FENCE	213.00	0.00	213.00	LF	197.00	\$4.00	\$788.00
		0001	0590	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	108.00	0.00	108.00	LF	108.00	\$972.00	\$104,976.00
		0020	0600	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	8.00	0.00	8.00	EA	0.00	\$1,990.00	\$0.00
		0020	0610	9011115	BRACKET ARM, 15 FT. OR 4.6 M	8.00	0.00	8.00	EA	0.00	\$936.00	\$0.00
		0020	0620	9011311	LUMINAIRE, LED-A	8.00	0.00	8.00	EA	0.00	\$436.00	\$0.00
		0020	0630	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	0.00	\$5,900.00	\$0.00
		0020	0640	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	310.00	690.00	1,000.00	LF	397.00	\$10.00	\$3,970.00
		0020	0650	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$12.00	\$0.00
		0020	0660	9015010	TRENCHING TYPE I	919.00	-919.00	0.00	LF	0.00	\$4.25	\$0.00
		0020	0670	9016111	PULL BOX, PREFORMED CLASS 2	7.00	0.00	7.00	EA	0.00	\$1,350.00	\$0.00
		0020	0680	9017001	CABLE, 1 AWG 1 CONDUCTOR	190.00	0.00	190.00	LF	0.00	\$2.90	\$0.00
		0020	0690	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	1,080.00	0.00	1,080.00	LF	0.00	\$0.85	\$0.00
		0020	0700	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,000.00	-1,000.00	0.00	LF	0.00	\$4.00	\$0.00
		0020	0710	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	4.00	\$920.00	\$3,680.00
		0020	0720	9019901	MISC.ELECTRIC SERVICE RECONNECTION	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.00
		0040	0730	9031010	CONCRETE FOOTINGS, EMBEDDED	3.60	0.00	3.60	CUYD	0.00	\$250.00	\$0.00
		0040	0740	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	38.00	-38.00	0.00	EA	0.00	\$75.00	\$0.00
		0040	0750	9031270A	2 IN. PSST POST - 12 GA.	608.00	0.00	608.00	LF	0.00	\$3.00	\$0.00
		0040	0760	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	114.00	0.00	114.00	LF	0.00	\$8.00	\$0.00
		0040	0770	9035004A	SH-FLAT SHEET	337.00	0.00	337.00	SQFT	0.00	\$31.00	\$0.00
		0001	5001	6169902	MISC.Pedestrian Barricade	0.00	4.00	4.00	EA	4.00	\$80.00	\$320.00
		0001	5002	7319902	MISC.Precast Concrete Drop Inlet 3 ft x 2 ft Type S2	0.00	1.00	1.00	EA	0.00	\$1,729.83	\$0.00
		0001	5003	7319902	MISC.Misc. Drop Inlet Construction	0.00	1.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0001	5004	1094000	FORCE ACCOUNT	0.00	55,744.79	55,744.79	EA	55,744.79	\$1.00	\$55,744.79
	Project J	5S3378 - <u>T</u> o	otal Value	Posted to D	late as of Report Generated Date							\$1,225,083.30
210416-D05 Ove	erall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$1,225,083.30

Page 7 of 20 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3378

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0060	3040504	TYPE 5 AGGREGATE FOR BASE	11/2/21	11/16/21	291.20	SQYD	Located throughout the project under Lines 0100, 0090, 0210.	384+00		3+63.30		
			11/4/21	11/16/21	6.00	SQYD	Under truck apron	384+00		3+63.30		
			11/5/21	11/16/21	73.30	SQYD	Southernmost Break Time driveway on Henry Clay Blvd.	12+26.32		12+26.32		
			11/9/21	11/16/21	179.00	SQYD	Placed under Lines 0100, 0190, and 0240.	384+00		3+63.30		
			11/10/21	11/16/21	24.20	SQYD	Under the ramps between the two Break Time driveways on Henry Clay Blvd	11+27.04		12+04.95		
			11/12/21	11/16/21	76.90	SQYD	North driveway to Break Time on Henry Clay Blvd.	10+98.18		10+98.18		
			11/15/21	11/16/21	76.90	SQYD	Other half of the north driveway in front of Break Time on Henry Clay Blvd.	10+98.18		10+98.18		
0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	11/2/21	11/16/21	88.90	SQYD	Installed under the optional pavement, Line 0080	384+00		3+63.30		
			11/3/21	11/16/21	253.00	SQYD	East side of roundabout.	384+00		3+63.30		
			11/4/21	11/16/21	160.00	SQYD	Under optional pavement.	384+00		3+63.30		
			11/8/21	11/16/21	56.20	SQYD	46' long piece of optional pavement placed in front of the southernmost Break Time driveway on Henry Clay Blvd.	12+26.32		12+26.32		
			11/12/21	11/16/21	83.10	SQYD	Under optional pavement installed on Henry Clay Blvd in front of Break Time.	384+00		3+63.30		
			11/15/21	11/16/21	49.80	SQYD	Optional pavement installed on Henry Clay Blvd in front of Break Time.	384+00		3+63.30		
0800	4019905	MISC.	11/2/21	11/16/21	88.90	SQYD		384+00		3+63.30		
			11/3/21	11/16/21	253.00	SQYD	East side of roundabout	384+00		3+63.30		
			11/4/21	11/16/21	160.00	SQYD	West of roundabout in the westbound lane.	384+00		385+00		
			11/8/21	11/16/21	56.20	SQYD	46' long piece of optional pavement placed in front of the southernmost Break Time driveway on Henry Clay Blvd.	12+26.32		12+26.32		
			11/12/21	11/16/21	83.10	SQYD	Under optional pavement installed on Henry Clay Blvd in front of Break Time.	384+00		3+63.30		
			11/15/21	11/16/21	49.80	SQYD	Optional pavement installed on Henry Clay Blvd in front of Break Time.	384+00		3+63.30		
0090	4019905	MISC.	11/2/21	11/16/21	100.00	SQYD		384+00		3+63.30		
0100	5021306	CONCRETE PAVEMENT (6 IN. NON-REINFORCED,	11/2/21	11/16/21	127.20	SQYD	Splitter Island on the east side.	384+00		3+63.30		
			11/9/21	11/16/21	60.40	SQYD	West splitter island on Highway M.	385+03.53		386.42.66		
0160	6081010	CONCRETE CURB RAMP	11/10/21	11/16/21	24.20	SQYD	The two curb ramps between the Break Time driveways on Henry Clay Blvd.	11+27.04		12+04.95		
0180	6085008	PAVED APPROACH, 8 IN.	11/5/21	11/16/21	73.30	SQYD	Southernmost Break Time driveway on Henry Clay Blvd.	12+26.32		12+26.32		
			11/12/21	11/16/21	76.90	SQYD	North driveway to Break Time on Henry Clay Blvd.	10+98.18		10+98.18		
			11/15/21	11/16/21	76.90	SQYD	Other half of the north driveway in front of Break Time on Henry Clay Blvd.	10+98.18		10+98.18		
0190	6086004	CONCRETE SIDEWALK, 4 IN.	11/9/21	11/16/21	28.50	SQYD	Between the Break Time driveways on Henry Clay Blvd.	11+47.44		11+90.16		
0210	6089905	MISC. CONCRETE	11/2/21	11/16/21	64.00	SQYD	Truck apron on east side of roundabout.	384+00		3+63.3		
			11/4/21	11/16/21	6.00	SQYD	Truck apron west of the roundabout.	384+00		3+63.30		
0230	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	11/2/21	11/16/21	250.00	LF	Splitter Island on east side of roundabout.	384+00		3+63.30		
			11/9/21	11/16/21	295.60	LF	West splitter island on Highway M.	385+03.03		386+43.09		
0240	6091052	CURB AND GUTTER TYPE B	11/9/21	11/16/21	67.60	LF	Between the Break Time driveways on Henry Clay Blvd.	11+38.10		12+04.95		
0550	8031000A	TURF TYPE TALL FESCUE SODDING	11/9/21	11/16/21	330.00	SQYD	Various locations along Highway M.	384+00		3+63.30		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 8 of 20



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3378	0060	TYPE 5 AGGREGATE FOR BASE	Material		3	Jul 16, 2021	SYSTEM	\$2,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$2,380.00)	
					4	Aug 3, 2021	SYSTEM	\$5,564.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$5,564.30)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Price FUEL		3	Jul 16, 2021	SYSTEM	\$9.69	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Aug 3, 2021	SYSTEM	\$12.96	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Aug 16, 2021	SYSTEM	\$18.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Sep 2, 2021	SYSTEM	\$27.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Sep 16, 2021	SYSTEM	\$4.43	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Oct 1, 2021	SYSTEM	\$36.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Oct 18, 2021	SYSTEM	\$31.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Oct 18, 2021	SYSTEM	\$1.85	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Nov 2, 2021	SYSTEM	\$0.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Nov 16, 2021	SYSTEM	\$21.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Nov 16, 2021	SYSTEM	\$32.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$196.59	
			Price FUEL	- Total				\$196.59	
	0060 -	Total						\$196.59	
	0070	TYPE 5 AGGREGATE FOR BASE (6			5	Aug 16, 2021	SYSTEM	\$26.93	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
		IN. THICK)			6	Sep 2, 2021	SYSTEM	\$60.36	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Sep 16, 2021	SYSTEM	\$19.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Oct 1, 2021	SYSTEM	\$17.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					9	Oct 18, 2021	SYSTEM	\$77.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					10	Nov 2, 2021	SYSTEM	\$43.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Nov 16, 2021	SYSTEM	\$77.87	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$322.98	
			Price FUEL	- Total				\$322.98	
	0070 -	Total						\$322.98	
	0800	MISC.	Material		5	Aug 16, 2021	SYSTEM	\$28,184.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$28,184.00)	
					6	Sep 2, 2021	SYSTEM	\$36,319.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hakej1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3378	0800	MISC.	Material						Estimate Exception 1 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$36,319.20)	
					7	Sep 16, 2021	SYSTEM	\$67,408.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$67,408.70)	
					8	Oct 1, 2021	SYSTEM	\$94,845.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$94,845.20)	
					9	Oct 18, 2021	SYSTEM	\$141,346.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$141,346.20)	
					10	Nov 2, 2021	SYSTEM	\$167,333.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$167,333.20)	
					11	Nov 16, 2021	SYSTEM	\$129,659.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$129,659.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	FUEL	5	Aug 16, 2021	hakej1	\$65.67	For lines 0080 and 0210. See Supporting Documentation for a breakdown.
					6	Sep 2, 2021	hakej1	\$165.37	
					7	Sep 16, 2021	hakej1	\$97.24	
					8	Oct 1, 2021	hakej1	\$47.87	
					9	Oct 18, 2021	hakej1	\$228.94	Fuel Adjustment
					10	Nov 2, 2021	hakej1	(\$18,292.30)	
					11	Nov 16, 2021	SYSTEM	\$18,292.30	
				FUEL - Tota	ıl			\$605.09	
			Other Item /	Adjustment -	Total			\$605.09	
	0080 -	Total MISC.	Other Item	FUEL	6	Sep 2,	hakej1	\$605.09 \$7.54	
			Adjustment	FUEL - Tota	ıl	2021		\$7.54	
			Other Item /	Adjustment -	Total			\$7.54	
	0090 -	Total						\$7.54	
	0100	CONCRETE PAVEMENT (6 IN. NON-	Material		7	Sep 16, 2021	SYSTEM	\$3,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		REINFORCED,			7	Sep 16, 2021	SYSTEM	(\$3,892.00)	
					8	Oct 1, 2021	SYSTEM	\$3,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$3,892.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5S3378	0100	CONCRETE PAVEMENT (6 IN. NON-	Material		9	Oct 18, 2021	SYSTEM	\$3,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		REINFORCED,			9	Oct 18, 2021	SYSTEM	(\$3,892.00)	
					10	Nov 2, 2021	SYSTEM	\$3,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$3,892.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Price FUEL		7	Sep 16, 2021	SYSTEM	\$4.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Nov 16, 2021	SYSTEM	\$45.04	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$49.94	
			Price FUEL	- Total				\$49.94	
	0100	· Total						\$49.94	
	0110	WATER - UTILITY ITEM	Material		4	Aug 3, 2021	SYSTEM	\$6,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$6,075.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0440	· Total	material - 1	Jtai					
					-			\$0.00	
	0130	PIPE COLLAR, TYPE A	Material		3	Jul 16, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$500.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Overrun	Overrun	8	Oct 1, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$500.00)	
					9	Oct 18, 2021	SYSTEM	(\$500.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$500.00)	
			Overrun - T	otal				(\$500.00)	
	0130 -	· Total						(\$500.00)	
	0160	CONCRETE CURB RAMP	Material		4	Aug 3, 2021	SYSTEM	\$1,752.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$1,752.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0160 -	· Total						\$0.00	
	0170	TRUNCATED DOMES	Material		4	Aug 3, 2021	SYSTEM	\$1,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$1,295.00)	
					5	Aug 16, 2021	SYSTEM	\$1,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.



8 013	170	TRUNCATED DOMES	Adjustment Type Material	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
8 01	170		Material								
					5	Aug 16, 2021	SYSTEM	(\$1,295.00)			
					6	Sep 2, 2021	SYSTEM	\$2,555.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					6	Sep 2, 2021	SYSTEM	(\$2,555.00)			
					7	Sep 16, 2021	SYSTEM	\$4,735.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					7	Sep 16, 2021	SYSTEM	(\$4,735.50)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
01	170 - 1	Total						\$0.00			
018	180	PAVED APPROACH, 8 IN.	Material		3	Jul 16, 2021	SYSTEM	\$6,681.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					3	Jul 16, 2021	SYSTEM	(\$6,681.00)			
					4	Aug 3, 2021	SYSTEM	\$20,561.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		
					4	Aug 3, 2021	SYSTEM	(\$20,561.50)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Price FUEL		3	Jul 16, 2021	SYSTEM	\$8.96	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
			TOLL			4	Aug 3, 2021	SYSTEM	\$18.62	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
							5	Aug 16, 2021	SYSTEM	\$25.61	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
						6	Sep 2, 2021	SYSTEM	\$16.44	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
					8	Oct 1, 2021	SYSTEM	\$32.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
					11	Nov 16, 2021	SYSTEM	\$66.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
				- Total				\$168.48			
			Price FUEL	- Total				\$168.48			
01	180 - 1	Total						\$168.48			
019	190	CONCRETE SIDEWALK, 4 IN.	Material		3	Jul 16, 2021	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					3	Jul 16, 2021	SYSTEM	(\$4,860.00)			
					4	Aug 3, 2021	SYSTEM	\$11,982.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.		
					4	Aug 3, 2021	SYSTEM	(\$11,982.60)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
01	190 - 1	Total						\$0.00			
020	200	CONCRETE SIDEWALK, 7 IN.	Material		7	Sep 16, 2021	SYSTEM	\$855.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					7	Sep 16, 2021	SYSTEM	(\$855.60)			
					8	Oct 1,	SYSTEM	\$855.60	This adjustment offsets the original system-generated Material Payment		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3378	0200	CONCRETE SIDEWALK, 7 IN.	Material			2021			Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		IIV.			8	Oct 1, 2021	SYSTEM	(\$855.60)	
					9	Oct 18, 2021	SYSTEM	\$855.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$855.60)	
					10	Nov 2, 2021	SYSTEM	\$855.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$855.60)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0200 -	- Total						\$0.00	
	0210	MISC. CONCRETE	Material		5	Aug 16, 2021	SYSTEM	\$16,558.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$16,558.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	FUEL	6	Sep 2, 2021	hakej1	\$15.81	
				FUEL - Tota	ı			\$15.81	
			Other Item	Adjustment -	Total			\$15.81	
	0210 -	- Total						\$15.81	
	<b>0210 - To</b>								
			Material		6	Sep 2, 2021	SYSTEM	\$8,041.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
	0220		Material		6		SYSTEM	\$8,041.00 (\$8,041.00)	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
	0220		Material			2021 Sep 2,			Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
	0220		Material		6	2021 Sep 2, 2021 Sep 16,	SYSTEM	(\$8,041.00)	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
	0220		Material	- Total	6	2021 Sep 2, 2021 Sep 16, 2021 Sep 16,	SYSTEM SYSTEM	(\$8,041.00) \$9,163.00	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
	0220		Material - To		6	2021 Sep 2, 2021 Sep 16, 2021 Sep 16,	SYSTEM SYSTEM	(\$8,041.00) \$9,163.00 (\$9,163.00)	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
	0220				6 7 7	2021 Sep 2, 2021 Sep 16, 2021 Sep 16,	SYSTEM SYSTEM	(\$8,041.00) \$9,163.00 (\$9,163.00)	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
	0220		Material - To	otal	6 7 7	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM	(\$8,041.00) \$9,163.00 (\$9,163.00) \$0.00	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
	0220		Material - To	otal FUEL	6 7 7 8 8 8	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM hakej1	(\$8,041.00) \$9,163.00 (\$9,163.00) \$0.00 \$15.33	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
	0220		Material - To	otal	6 7 7 8 8 8	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM hakej1 hakej1	(\$8,041.00) \$9,163.00 (\$9,163.00) \$0.00 \$15.33 \$1.43	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
	0220		Material - To Other Item Adjustment	otal FUEL	6 7 7 8 8 I	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM hakej1 hakej1	(\$8,041.00) \$9,163.00 (\$9,163.00) \$0.00 \$15.33 \$1.43	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
			Material - To Other Item Adjustment	FUEL - Tota	6 7 7 8 8 I	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM hakej1 hakej1	(\$8,041.00) \$9,163.00 (\$9,163.00) \$0.00 \$15.33 \$1.43 \$1.47	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
		- Total  CONCRETE CURB (6 IN. HEIGHT AND	Material - To Other Item Adjustment	FUEL - Tota	6 7 7 8 8 I	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 2, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM hakej1 hakej1	(\$8,041.00) \$9,163.00 (\$9,163.00) \$0.00 \$15.33 \$1.43 \$1.47	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
	0220 -	CONCRETE  CONCRETE CURB (6 IN.	Material - To Other Item Adjustment	FUEL - Tota	6 7 7 6 8 I	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021	SYSTEM SYSTEM SYSTEM hakej1 hakej1	(\$8,041.00) \$9,163.00 (\$9,163.00) \$0.00 \$15.33 \$1.43 \$1.47 \$18.23 \$18.23	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment
	0220 -	- Total  CONCRETE CURB (6 IN. HEIGHT AND	Material - To Other Item Adjustment	FUEL - Tota	6 7 7 8 I Total 7	2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021 Sep 16, 2021 Oct 1, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM hakej1 hakej1 SYSTEM	(\$8,041.00) \$9,163.00 (\$9,163.00) \$0.00 \$15.33 \$1.43 \$1.47 \$18.23 \$18.23 \$18.23 \$18,517.50	Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J5S3378	0230	CONCRETE CURB (6 IN. HEIGHT AND	Material		9	Oct 18, 2021	SYSTEM	\$18,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																
		UNDER)			9	Oct 18, 2021	SYSTEM	(\$18,517.50)																	
					10	Nov 2, 2021	SYSTEM	\$18,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																
					10	Nov 2, 2021	SYSTEM	(\$18,517.50)																	
				- Total				\$0.00																	
			Material - T	otal				\$0.00																	
	0230 -	Total						\$0.00																	
	0240	CURB AND GUTTER TYPE B	Material		3	Jul 16, 2021	SYSTEM	\$9,597.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																
					3	Jul 16, 2021	SYSTEM	(\$9,597.00)																	
					4	Aug 3, 2021	SYSTEM	\$16,375.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																
					4	Aug 3, 2021	SYSTEM	(\$16,375.80)																	
				- Total				\$0.00																	
			Material - T	otal				\$0.00																	
	0240 -	Total						\$0.00																	
	0250	CONCRETE CURB LOW PROFILE TYPE E	Material		5	Aug 16, 2021	SYSTEM	\$7,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																
		IIFEE			5	Aug 16, 2021	SYSTEM	(\$7,840.00)																	
					6	Sep 2, 2021	SYSTEM	\$7,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																
					6	Sep 2, 2021	SYSTEM	(\$7,840.00)																	
					7	Sep 16, 2021	SYSTEM	\$7,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					7	Sep 16, 2021	SYSTEM	(\$7,840.00)																	
					8	Oct 1, 2021	SYSTEM	\$9,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																
					8	Oct 1, 2021	SYSTEM	(\$9,100.00)																	
																					9	Oct 18, 2021	SYSTEM	\$9,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$9,100.00)																	
				10												11	10	Nov 2, 2021	SYSTEM	\$17,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					10	Nov 2, 2021	SYSTEM	(\$17,360.00)																	
					11	Nov 16, 2021	SYSTEM	\$17,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user burtoc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
					11	Nov 16, 2021	SYSTEM	(\$17,360.00)																	
								£0.00																	
				- Total				\$0.00																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J5S3378	0250 -	Total						\$0.00																	
	0260	CURVED VANE GRTE AND FRAME(2 FT. X 2 FT)	Material		4	Aug 3, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hakej1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																
		11. 7211)			4	Aug 3, 2021	SYSTEM	(\$2,500.00)																	
					5	Aug 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																
					5	Aug 16, 2021	SYSTEM	(\$2,500.00)																	
					6	Sep 2, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.																
					6	Sep 2, 2021	SYSTEM	(\$2,500.00)																	
					7	Sep 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																
					7	Sep 16, 2021	SYSTEM	(\$2,500.00)																	
					8	Oct 1, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					8	Oct 1, 2021	SYSTEM	(\$2,500.00)																	
					9	Oct 18, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					9	Oct 18, 2021	SYSTEM	(\$2,500.00)																	
					10	Nov 2, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.																
					10	Nov 2, 2021	SYSTEM	(\$2,500.00)																	
					11	Nov 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user burtoc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					11	Nov 16, 2021	SYSTEM	(\$2,500.00)																	
				- Total				\$0.00																	
			Material - T	otal				\$0.00																	
	0260 -	Total						\$0.00																	
	0270	CURVED VANE GRATE AND FRAME(4	E GRATE FRAME(4 -T. X 2 FT	3	ξ 4 7 7					3	3	3 4	3 4	3	3 3	1				aterial	3	Jul 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
		FI. A Z FI															3	Jul 16, 2021	SYSTEM	(\$9,000.00)					
																4	4			4		4	Aug 3, 2021	SYSTEM	\$9,000.00
															4	Aug 3, 2021	SYSTEM	(\$9,000.00)							
															5	5	5	5	5	Aug 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
				Ę			5							Ę	5	5	5	5	5	Aug 16, 2021	SYSTEM	(\$9,000.00)			
											6	Sep 2, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.										
					6	Sep 2,	SYSTEM	(\$9,000.00)																	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
378	0270	CURVED VANE GRATE AND FRAME(4	Material		7	Sep 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.									
		FT. X 2 FT			7	Sep 16, 2021	SYSTEM	(\$9,000.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0270 -	Total						\$0.00										
	0280	MANHOLE FRAME AND COVER, TYPE	Material		3	Jul 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.									
		3			3	Jul 16, 2021	SYSTEM	(\$2,500.00)										
					4	Aug 3, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hakej1 overridding Payment Estimate Exception 21 on the current Payment Estimate.									
					4	Aug 3, 2021	SYSTEM	(\$3,000.00)										
					5	Aug 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					5	Aug 16, 2021	SYSTEM	(\$3,000.00)										
					6	Sep 2, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.									
					6	Sep 2, 2021	SYSTEM	(\$3,000.00)										
										7	Sep 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					7	Sep 16, 2021	SYSTEM	(\$3,000.00)										
					8	Oct 1, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					8	Oct 1, 2021	SYSTEM	(\$3,500.00)										
					9	Oct 18, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					9	Oct 18, 2021	SYSTEM	(\$3,500.00)										
					10	Nov 2, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					10	Nov 2, 2021	SYSTEM	(\$3,500.00)										
														11	Nov 16, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user burtoc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$3,500.00)										
				- Total				\$0.00										
			Material - To	otal				\$0.00										
	0280 -	Total						\$0.00										
	0340	WARNING LIGHT, TYPE B	Overrun	Overrun	2	Jun 30, 2021	SYSTEM	(\$180.00)										
		Б			5	Aug 16, 2021	SYSTEM	\$180.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',45.00000 - 45.00000, 'is applied (if non-zero).									
				Overrun - To	otal			\$0.00										
			Overrun - T	otal				\$0.00										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J5S3378	0340 -	Total						\$0.00											
	0470	15 IN. PIPE CULVERT GROUP B	Overrun	Overrun	8	Oct 1, 2021	SYSTEM	\$1,155.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.										
					8	Oct 1, 2021	SYSTEM	(\$1,155.00)											
					9	Oct 18, 2021	SYSTEM	(\$1,155.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).										
				Overrun - T	otal			(\$1,155.00)											
			Overrun - T	otal				(\$1,155.00)											
	0470 -	Total						(\$1,155.00)											
	0510	PRECAST CONCRETE DROP INLET 2	Material		4	Aug 3, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hakej1 overridding Payment Estimate Exception 22 on the current Payment Estimate.										
		FT X 2 FT			4	Aug 3, 2021	SYSTEM	(\$2,100.00)											
					5	Aug 16, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
					5	Aug 16, 2021	SYSTEM	(\$2,100.00)											
						6	Sep 2, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					6	Sep 2, 2021	SYSTEM	(\$2,100.00)											
					7	Sep 16, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.										
					7	Sep 16, 2021	SYSTEM	(\$2,100.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	0510 -	Total						\$0.00											
	0520	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	Material		2	Jun 30, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
		117211			2	Jun 30, 2021	SYSTEM	(\$2,000.00)											
					3	Jul 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 16 on the current Payment Estimate.										
														3	Jul 16, 2021	SYSTEM	(\$12,000.00)		
									4	Aug 3, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 23 on the current Payment Estimate.						
					4	Aug 3, 2021	SYSTEM	(\$12,000.00)											
											5 Aug 16, SYS						SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$12,000.00)											
					6 S 2 7 S	6	6	Sep 2, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
						Sep 2, 2021	SYSTEM	(\$12,000.00)											
						7	Sep 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					7	Sep 16,	SYSTEM	(\$12,000.00)											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3378	0520	PRECAST	Material			2021			
		CONCRETE DROP INLET 4		- Total				\$0.00	
		FT X 2 FT	Material - T	otal				\$0.00	
	0520 -	· Total						\$0.00	
	0530	PRECAST CONCRETE DROP INLET 5	Material		3	Jul 16, 2021	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
		FT X 3 FT			3	Jul 16, 2021	SYSTEM	(\$24,000.00)	
					4	Aug 3, 2021	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$24,000.00)	
					5	Aug 16, 2021	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$24,000.00)	
						6	Sep 2, 2021	SYSTEM	\$24,000.00
					6	Sep 2, 2021	SYSTEM	(\$24,000.00)	
					7	Sep 16, 2021	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hakej1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$24,000.00)	
				- Total				\$0.00	
				. •				φυ.υυ	
			Material - T					\$0.00	
	0530 -	·Total	Material - T						
	<b>0530</b> - 0540	MISC. MANHOLES AND DROP	Material - T		4	Aug 3, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
		MISC. MANHOLES			4		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment
		MISC. MANHOLES AND DROP				2021 Aug 3,		\$0.00 \$0.00 \$4,900.00	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment
		MISC. MANHOLES AND DROP			4	2021 Aug 3, 2021 Aug 16,	SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00)	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment
		MISC. MANHOLES AND DROP			5	Aug 3, 2021  Aug 16, 2021  Aug 16,	SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) \$4,900.00	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment
		MISC. MANHOLES AND DROP			5	2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) \$4,900.00	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment
		MISC. MANHOLES AND DROP			<ul><li>4</li><li>5</li><li>6</li></ul>	2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) \$4,900.00 (\$4,900.00)	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment
		MISC. MANHOLES AND DROP		otal	<ul><li>4</li><li>5</li><li>5</li><li>6</li><li>6</li></ul>	2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) \$4,900.00 (\$4,900.00) (\$4,900.00) (\$4,900.00)	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
		MISC. MANHOLES AND DROP	Material	otal - Total	4 5 5 6 6 7	Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) (\$4,900.00) (\$4,900.00) (\$4,900.00) (\$4,900.00)	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
	0540	MISC. MANHOLES AND DROP INLETS		otal - Total	4 5 5 6 6 7	Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) \$4,900.00 (\$4,900.00) (\$4,900.00) (\$4,900.00)	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
		MISC. MANHOLES AND DROP INLETS	Material	otal - Total	4 5 5 6 6 7	Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) (\$4,900.00) (\$4,900.00) (\$4,900.00) (\$4,900.00)	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
	0540	MISC. MANHOLES AND DROP INLETS	Material	otal - Total	4 5 5 6 6 7	Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) (\$4,900.00) (\$4,900.00) (\$4,900.00) (\$4,900.00) \$4,900.00	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
	0540	MISC. MANHOLES AND DROP INLETS  Total  TURF TYPE TALL FESCUE	Material  Material - T	otal - Total	4 5 5 6 6 7	2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 16, 2021 Sep 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$4,900.00 (\$4,900.00) \$4,900.00 (\$4,900.00) \$4,900.00 (\$4,900.00) \$0.00 \$0.00	Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 25 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 14 on the current Payment Estimate.



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
S3378	0550	TURF TYPE TALL FESCUE SODDING	Material		11	Nov 16, 2021	SYSTEM	(\$13,026.60)	Estimate Exception 5 on the current Payment Estimate.														
				- Total				\$0.00															
			Material - T	otal				\$0.00															
	0550 -	Total						\$0.00															
	0560	CURB INLET CHECK	Material		2	Jun 30, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.														
					2	Jun 30, 2021	SYSTEM	(\$600.00)															
					3	Jul 16, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 18 on the current Payment Estimate.														
					3	Jul 16, 2021	SYSTEM	(\$600.00)															
					4	Aug 3, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hakej1 overridding Payment Estimate Exception 26 on the current Payment Estimate.														
					4	Aug 3, 2021	SYSTEM	(\$600.00)															
					5	Aug 16, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 13 on the current Payment Estimate.														
					5	Aug 16, 2021	SYSTEM	(\$600.00)															
					6	Sep 2, 2021	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.														
					6	Sep 2, 2021	SYSTEM	(\$1,800.00)															
					7	Sep 16, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					7	Sep 16, 2021	SYSTEM	(\$2,000.00)															
					8	Oct 1, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					8	Oct 1, 2021	SYSTEM	(\$2,000.00)															
					9	Oct 18, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					9	Oct 18, 2021	SYSTEM	(\$2,000.00)															
					10	Nov 2, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					10	Nov 2, 2021	SYSTEM	(\$2,000.00)															
																			11	Nov 16, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user burtoc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$2,000.00)															
				- Total				\$0.00															
			Material - T	otal				\$0.00															
	0560 -	Total						\$0.00															
	0580	SILT FENCE	Material		7	Sep 16, 2021	SYSTEM	\$60.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					7	Sep 16,	SYSTEM	(\$60.00)															





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3378	0580	SILT FENCE	Material			2021			
					8	Oct 1, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$788.00)	
					9	Oct 18, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$788.00)	
					10	Nov 2, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$788.00)	
					11	Nov 16, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user burtoc4 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$788.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0580 - Total							\$0.00	
	0590	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Other Item Adjustment	OTHR	4	Aug 3, 2021	hakej1	(\$40,000.00)	This is to withhold money until they install the tracer wire.
			OTHR - Total					(\$40,000.00)	
			Other Item Adjustment - Total					(\$40,000.00)	
	0590 - Total							(\$40,000.00)	
	0640	CONDUIT, 2 IN. RIGID, IN TRENCH	Overrun	Overrun	6	Sep 2, 2021	SYSTEM	(\$870.00)	
					10	Nov 2, 2021	SYSTEM	\$870.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - T	verrun - Total				\$0.00	
	0640 - Total							\$0.00	
J5S3378 - Total								(\$40,270.34)	
Overall - Total									