

#### Pay Estimate Created Date: December 16, 2021

Progress Estimate N 13			210416-D05 Sam Gaines Constru	uction, In	Pay Period Start Decemic. Pay Period End Decemi		21 Original Contract Amount 21 Net Change Order Amount Current Contract Amount	\$38,718.87	
Approval Date								By User	
December 16, 2021			Generated and	d Approv	ed (and should be considere	d Draft) a	t the Project Office Level by	hakej1	
December 16, 2021									
December 17, 2021				Review	ed and Approved at the Cer	tral Office	e Controllers Office Level by	ramses1	
Original Completio	n Date	Current Co	mpletion Date	Ac	tual Completion Date	%	of Current Contract Amount	Complete	
December 20, 2	021	March	21, 2022			81.28%			
	Contrac	t Informational Dat	es		Milestones				
Date Description	Original	Completion Date	Current Completio	on Date	No Milestones Exist for Co	ntract			
Acceptance Date									
Awarded Date	May 5, 2	2021	May 5, 2021						
Letting Date	April 16,	2021	April 16, 2021						
Notice to Proceed Date	May 21,	2021	May 21, 2021						
Work Began Date	June 7, 2	2021	June 7, 2021						

Contract Total Pay For Estimate No. 13											
		This Estimate	Previous	To Date							
210416-D05											
	Total Posted Items Pay	\$29,816.82	\$1,278,683.10	\$1,308,499.92							
	Gross Item Adjustments	(\$1,184.10)	(\$39,873.45)	(\$41,057.55)							
	Incentive	\$0.00	\$0.00	\$0.00							
	Disincentive	\$0.00	\$0.00	\$0.00							
	Liquidated Damage	\$0.00	\$0.00	\$0.00							
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00							
			<mark>\$1,238,809.65</mark>	\$1,267,442.37							
Contract Total Pa	yable This Estimate:	\$28,632.72									

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3378	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$7.000	315.9	\$2,211.30
	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	SQYD	\$9.000	63.38	\$570.42
	0080	4019905	MISC.OPTIONAL PAVEMENT	SQYD	\$65.000	63.38	\$4,119.70
	0160	6081010	CONCRETE CURB RAMP	SQYD	\$120.000	38.4	\$4,608.00
	0170	6081012	TRUNCATED DOMES	SQFT	\$35.000	16	\$560.00
	0190	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$54.000	73.6	\$3,974.40
	0230	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$75.000	58	\$4,350.00
	0240	6091052	CURB AND GUTTER TYPE B	LF	\$42.000	153.3	\$6,438.60
	0550	8031000A	TURF TYPE TALL FESCUE SODDING	SQYD	\$18.000	165.8	\$2,984.40
Project J5S33	78 - Total						\$29,816.82
<b>Overall - Total</b>							\$29,816.82

#### Contract Adjustments This Estimate

#### No Contract Adjustments Exist on Contract

Line	ltem Ad	justments	This Est	<u>imate</u>

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3378	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	33.6	\$0.07	\$2.37
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	158.8	\$0.07	\$11.20

#### Pay Estimate Created Date: December 16, 2021

38,718.87	ler Amount S		Pay Period Start December 2, 2021 Ori , Inc. Pay Period End December 15, 2021 Net Cur		210416- I <b>ctor</b> Sam Ga	Contract ID Prime Contra	imate Number 3		Progre
Adjustmer amount	Line Item Adjustment Unit Price	Adjustment Quantity	Comments	Other Item Adjustment Type	Adjustment Type	Description	Item Des	Line No.	Project Number
\$6.0	\$0.07	86.2	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		Price	GREGATE FOR SE (4 IN. THICK)		0060	J5S3378
\$2.6	\$0.07	37.3	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		Price	GREGATE FOR SE (4 IN. THICK)		0060	
\$6.8	\$0.11	63.38	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		Price	GREGATE FOR SE (6 IN. THICK)		0070	
(\$267,307.3	\$65.00	-4,112.42			Material	MISC.		0080	
\$18.7				Fuel Price	Other Item Adjustment	MISC.		0080	
\$267,307.3	\$65.00	4,112.42	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		Material	MISC.		0080	
(\$20,629.0	\$70.00	-294.7			Material	E PAVEMENT (6 EINFORCED, 15 FT. JOINTS)		0100	
\$20,629.0	\$70.00	294.7	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		Material	E PAVEMENT (6 EINFORCED, 15 FT. JOINTS)		0100	
(\$855.6	\$62.00	-13.8			Material	TE SIDEWALK, 7 IN.	CONCRETE	0200	
\$855.6	\$62.00	13.8	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.		Material	TE SIDEWALK, 7 IN.	CONCRETE	0200	
(\$76,312.5	\$75.00	-1,017.5			Material	ETE CURB (6 IN. D UNDER) TYPE S		0230	
\$76,312.5	\$75.00	1,017.5	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		Material	ETE CURB (6 IN. D UNDER) TYPE S		0230	
(\$17,360.0	\$35.00	-496			Material	ETE CURB LOW ROFILE TYPE E		0250	
\$17,360.0	\$35.00	496	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		Material	ETE CURB LOW ROFILE TYPE E		0250	
(\$2,500.0	\$2,500.00	-1			Material	NE GRATE AND 2 FT. X 2 FT. OR 00MM X 600MM)	FRAME (2 F	0260	
\$2,500.0	\$2,500.00	1	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.		Material	NE GRATE AND 2 FT. X 2 FT. OR 00MM X 600MM)	FRAME (2 F	0260	
(\$3,500.0	\$500.00	-7			Material	LE FRAME AND COVER, TYPE 3		0280	
\$3,500.0	\$500.00	7	This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.		Material	LE FRAME AND COVER, TYPE 3		0280	
(\$562.7			20% withholding until retro reflectivity results	Retroreflectivity	Other Item	MISC.		0430	



#### Pay Estimate Created Date: December 16, 2021

Progre	ess Esti 1	mate Number 3	Contract ID Prime Contra	210416 Actor Sam Ga		Pay Period Start December 2, 2021 Ori, , Inc. Pay Period End December 15, 2021 Net Cur	Change Ord		38,718.87
Project Number	Line No.	Item Des	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3378				Adjustment	Adjustment	have been tested and meet MoDOT specification			
	0440		MISC.	Other Item Adjustment	,	20% withholding until retro reflectivity results have been tested and meet MoDOT specification			(\$669.25)
	0550	TURF TYPE 1	TALL FESCUE SODDING	Material			-1,132.6	\$18.00	(\$20,386.80
	0550	TURF TYPE T	TALL FESCUE SODDING	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	1,132.6	\$18.00	\$20,386.80
	0560	CURB	INLET CHECK	Material			-10	\$200.00	(\$2,000.00
	0560	CURB	INLET CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	10	\$200.00	\$2,000.00
	0580		SILT FENCE	Material			-197	\$4.00	(\$788.00
	0580		SILT FENCE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	197	\$4.00	\$788.00
Total				· · · · · · · · · · · · · · · · · · ·					(\$1,184.10



Incentive Disincentive Liquidated Damages Other Contract Adjustments

#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5S3378	FAS- S402(014)	Intersection and ADA improvements	М	BOONE	at Henry Clay Boulevard	in Ashland	
Totals by .	Job Number	S					
J5S3378		Item Pay tem Adjustmen	ts <mark>Gross It</mark> e	em Pay	This Estimate \$29,816.82 (\$1,184.10) <b>\$28,632.72</b>	Previous           \$1,278,683.10           (\$39,873.45)           \$1,238,809.65	To Date \$1,308,499.92 (\$41,057.55) \$1,267,442.37

\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00

\$0.00 \$0.00 \$0.00 \$0.00



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 4019905, Project Item Line Number 0080, Material Set 401990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Need Gradation test	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 4019905, Project Item Line Number 0080, Material Set 401990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 4019905, Project Item Line Number 0080, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	I have to enter 1 more test that I have and QC has to enter 3 but I have many Credo Reports to enter. So I probably have the proper tests. Just haven't had time to enter them.	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 5021306, Project Item Line Number 0100, Material Set 502130696, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QC needs to enter tests. Have a bunch of Credo reports to enter. Just haven't had time to go through these	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 6086007, Project Item Line Number 0200, Material Set 608600796, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QC needs to enter tests. Have a bunch of Credo reports to enter. Just haven't had time to go through these.	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 6091010, Project Item Line Number 0230, Material Set 609101096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	QC needs to enter tests. Have a bunch of Credo reports to enter. Just haven't had time to go through these.	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 6092031, Project Item Line Number 0250, Material Set 609203196, Material 1057JMTBE42013 - Tie Bar Ep Ctd 12" No. 4/M13 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Need cure PAL	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 6141120, Project Item Line Number 0260, Material Set 614112096, Material 0614DFGTCV - Curved Vane Grate and Frame, Acceptance Action Generic 0614DFGTCV is insufficient.	I need to enter Free Form test	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 6143013, Project Item Line Number 0280, Material Set 614301396, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance Action Generic 0614DFMNFC is insufficient.	I need to enter Free Form Test	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 8031000A, Project Item Line Number 0550, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is insufficient.	Waiting on Certifications	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 8061007A, Project Item Line Number 0560, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	I Need Certification and put in a Visual Test	hakej1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5S3378, Item 8061019, Project Item Line Number 0580, Material Set 806101996, Material 1011GXT2 - Geotextile Fabric for TempSiltFence (T2), Acceptance Action Generic 1011GXT2 is insufficient.	I need Certification	hakej1	Overridden
Estimate Exception Type: Item Overrun: Contract 210416-D05, Contract Project J5S3378, Project Item Line Number 0130, Contract Line Item Number 0130, Item 6044011, Minor Item.	Waiting on change order to get approved and signed	hakej1	Overridden
Estimate Exception Type: Item Overrun: Contract 210416-D05, Contract Project J5S3378, Project Item Line Number 0470, Contract Line Item Number 0470, Item 7250315A, Minor Item.	Waiting on change order to get approved and signed	hakej1	Overridden



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

and can differ from the posted amount at the time the Estimate was Generated

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See report generated date)
10416-D05	J5S3378	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$100,000.00	\$100,000.00
		0001	0015	2024013	REMOVAL OF SURFACING ACM (FRIABLE)	960.00	0.00	960.00	SQFT	525.00	\$20.00	\$10,500.00
		0001	0030	2029950	DEMOLITION AND REMOVAL OF BUILDINGS	1.00	0.00	1.00	LS	0.00	\$10,000.00	\$0.00
		0001	0040	2039901	MISC.EARTHWORK	1.00	0.00	1.00	LS	0.50	\$20,000.00	\$10,000.00
		0001	0050	2063000	000 CLASS 3 EXCAVATION		0.00	605.00	CUYD	599.00	\$20.00	\$11,980.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	5,493.00	0.00	5,493.00	SQYD	5,255.17	\$7.00	\$36,786.19
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	4,373.00	0.00	4,373.00	SQYD	4,373.00	\$9.00	\$39,357.0
		0001	0080	4019905	MISC.OPTIONAL PAVEMENT	4,373.00	0.00	4,373.00	SQYD	4,373.00	\$65.00	\$284,245.0
		0001	0090	4019905	MISC.TEMPORARY PAVEMENT	1,093.30	0.00	1,093.30	SQYD	214.80	\$70.00	\$15,036.0
		0001	0100	5021306	CONCRETE PAVEMENT (6 IN. NON-REINFORCED, 15 FT. JOINTS)	322.20	0.00	322.20	SQYD	294.70	\$70.00	\$20,629.0
		0001	0110	6039903	WATER	135.00	0.00	135.00	LF	135.00	\$45.00	\$6,075.0
		0001	0120	6039903	WATER	87.00	0.00	87.00	LF	0.00	\$50.00	\$0.0
		0001	0130	6044011	PIPE COLLAR, TYPE A	2.00	0.00	2.00	EA	3.00	\$500.00	\$1,500.0
		0001	0140	6049901	MISC.FIRE HYDRANT RELOCATION	1.00	-1.00	0.00	LS	0.00	\$15,000.00	\$0.0
		0001	0150	6049902	MISC.ADJUSTING MANHOLES, INLETS, AND VALVES	9.00	0.00	9.00	EA	4.00	\$500.00	\$2,000.0
		0001	0160	6081010	CONCRETE CURB RAMP	264.20	0.00	264.20	SQYD	219.80	\$120.00	\$26,376.0
		0001	0170	6081012	TRUNCATED DOMES	269.00	0.00	269.00	SQFT	211.70	\$35.00	\$7,409.5
		0001	0180	6085008	PAVED APPROACH, 8 IN.	1,432.40	0.00	1,432.40	SQYD	1,025.60	\$85.00	\$87,176.0
		0001	0190	6086004	CONCRETE SIDEWALK, 4 IN.	697.30	0.00	697.30	SQYD	652.21	\$54.00	\$35,219.3
		0001	0200	6086007	CONCRETE SIDEWALK, 7 IN.	44.60	0.00	44.60	SQYD	13.80	\$62.00	\$855.6
		0001	0210	6089905	MISC.CONCRETE PAVEMENT ( 8 IN. NON-REINFORCED)	526.30	0.00	526.30	SQYD	408.70	\$95.00	\$38,826.5
		0001	0220	6089905	TINTED MISC.CONCRETE PAVEMENT (8 IN. NON-REINFORCED) NON- TINTED	217.40	0.00	217.40	SQYD	128.70	\$85.00	\$10,939.5
		0001	0230	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	1,375.00	0.00	1,375.00	LF	1,017.50	\$75.00	\$76,312.5
		0001	0240	6091052	CURB AND GUTTER TYPE B	1,480.00	0.00	1,480.00	LF	1,346.10	\$42.00	\$56,536.2
		0001	0250	6092031	CONCRETE CURB LOW PROFILE TYPE E	496.00	0.00	496.00	LF	496.00	\$35.00	\$17,360.0
		0001	0260	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	1.00	0.00	1.00	EA	1.00	\$2,500.00	\$2,500.0
		0001	0270	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	3.00	0.00	3.00	EA	3.00	\$3,000.00	\$9,000.0
		0001	0280	6143013	MANHOLE FRAME AND COVER, TYPE 3	7.00	0.00	7.00	EA	7.00	\$500.00	\$3,500.0
		0001	0290	6161005	CONSTRUCTION SIGNS	501.00	0.00	501.00	SQFT	230.00	\$5.90	\$1,357.0
		0001	0300	6161008	ADVANCED WARNING RAIL SYSTEM	2.00	0.00	2.00	EA	0.00	\$50.00	\$0.0
		0001	0310	6161025	CHANNELIZER (TRIM LINE)	44.00	0.00	44.00	EA	44.00	\$17.00	\$748.0
		0001	0320	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	12.00	\$80.00	\$960.0
		0001	0330	6161040	FLASHING ARROW PANEL	1.00	0.00	1.00	EA	0.00	\$1,600.00	\$0.0
		0001	0340	6161052	WARNING LIGHT, TYPE B	6.00	4.00	10.00	EA	10.00	\$45.00	\$450.0
		0001	0350	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$7,800.00	\$15,600.0
		0001	0360	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$75,000.00	\$75,000.0
		0001	0370	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	1.00	0.00	1.00	EA	0.00	\$390.00	\$0.0
		0001	0380	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	35.00	0.00	35.00	EA	0.00	\$160.00	\$0.0
		0001	0390	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	54.00	0.00	54.00	EA	0.00	\$15.00	\$0.0
		0001	0400	6200045	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LT/RT FISH HOOK ARROW	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.0
		0001	0410	6206124A	24 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	60.00	0.00	60.00	LF	0.00	\$7.50	\$0.0
			24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	27.00	0.00	27.00	LF	0.00	\$7.50	\$0.0		
		0001	0430	6209903	MISC.4 IN, WHITE HIGHBUILD WATERBORNE PAVEMENT MARKING WI TYPE L BEADS	2,251.00	0.00	2,251.00	LF	0.00	\$1.25	\$0.0



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Vote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract	Project	Category	Line	Item	eport Generated date and can differ from the posted ar Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
210416-D05	J5S3378	0001	0440	6209903	MISC.4 IN, YELLOW HIGHBUILD WATERBORNE PAVEMENT MARKING W/ TYPE L BEADS	2,677.00	0.00	2,677.00	LF	0.00	\$1.25	\$0.00
		0001	0450	6209903	MISC.8 IN, WHITE HIGHBUILD WATERBORNE PAVEMENT MARKING W/ TYPE L BEADS	82.00	0.00	82.00	LF	0.00	\$3.75	\$0.00
		0001	0460	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.00
		0001	0470	7250315A	15 IN. PIPE GROUP B	279.00	0.00	279.00	LF	300.00	\$55.00	\$16,500.00
		0001	0480	7250318A	18 IN. PIPE GROUP B	240.00	0.00	240.00	LF	213.00	\$65.00	\$13,845.00
		0001	0490	7261015	15 IN. PIPE GROUP A	157.00	0.00	157.00	LF	157.00	\$75.00	\$11,775.00
		0001	0500	7261018	18 IN. PIPE GROUP A	91.00	0.00	91.00	LF	91.00	\$80.00	\$7,280.00
		0001	0510	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	10.00	-4.00	6.00	FT	6.00	\$350.00	\$2,100.00
		0001	0520	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	12.00	0.00	12.00	FT	12.00	\$1,000.00	\$12,000.00
		0001	0530	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	28.00	0.00	28.00	FT	28.00	\$1,000.00	\$28,000.00
		0001	0540	7319913	MISC.PRECAST CONCRETE JUNCTION BOX 5 FT. X 3 FT.	7.00	0.00	7.00	FT	7.00	\$700.00	\$4,900.00
		0001	0550	8031000A	TURF TYPE TALL FESCUE SODDING	1,670.00	0.00	1,670.00	SQYD	1,132.60	\$18.00	\$20,386.80
		0001	0560	8061007A	CURB INLET CHECK	19.00	0.00	19.00	EA	10.00	\$200.00	\$2,000.00
		0001	0570	8061016	SEDIMENT REMOVAL	21.00	0.00	21.00	CUYD	0.00	\$40.00	\$0.00
		0001	0580	8061019	SILT FENCE	213.00	0.00	213.00	LF	197.00	\$4.00	\$788.00
		0001	0590	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	108.00	0.00	108.00	LF	108.00	\$972.00	\$104,976.00
		0020	0600	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	8.00	0.00	8.00	EA	0.00	\$1,990.00	\$0.00
		0020	0610	9011115	BRACKET ARM, 15 FT. OR 4.6 M	8.00	0.00	8.00	EA	0.00	\$936.00	\$0.00
		0020	0620	9011311	LUMINAIRE, LED-A	8.00	0.00	8.00	EA	0.00	\$436.00	\$0.00
		0020	0630	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	0.00	\$5,900.00	\$0.00
		0020	0640	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	310.00	690.00	1,000.00	LF	397.00	\$10.00	\$3,970.00
		0020	0650	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	100.00	0.00	100.00	LF	0.00	\$12.00	\$0.00
		0020	0660	9015010	TRENCHING TYPE I	919.00	-919.00	0.00	LF	0.00	\$4.25	\$0.00
		0020	0670	9016111	PULL BOX, PREFORMED CLASS 2	7.00	0.00	7.00	EA	0.00	\$1,350.00	\$0.00
		0020	0680	9017001	CABLE, 1 AWG 1 CONDUCTOR	190.00	0.00	190.00	LF	0.00	\$2.90	\$0.00
		0020	0690	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	1,080.00	0.00	1,080.00	LF	0.00	\$0.85	\$0.00
		0020	0700	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	1,000.00	-1,000.00	0.00	LF	0.00	\$4.00	\$0.00
		0020	0710	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	8.00	0.00	8.00	EA	4.00	\$920.00	\$3,680.00
		0020	0720	9019901	MISC.ELECTRIC SERVICE RECONNECTION	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0.00
		0040	0730	9031010	CONCRETE FOOTINGS, EMBEDDED	3.60	0.00	3.60	CUYD	0.00	\$250.00	\$0.00
		0040	0740	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	38.00	-38.00	0.00	EA	0.00	\$75.00	\$0.00
		0040	0750	9031270A	2 IN. PSST POST - 12 GA.	608.00	0.00	608.00	LF	0.00	\$3.00	\$0.00
		0040	0760	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	114.00	0.00	114.00	LF	0.00	\$8.00	\$0.00
		0040	0770	9035004A	SH-FLAT SHEET	337.00	0.00	337.00	SQFT	0.00	\$31.00	\$0.00
		0001	5001	6169902	MISC.Pedestrian Barricade 0.00		4.00	4.00	EA	4.00	\$80.00	\$320.00
		0001	5002	7319902	MISC.Precast Concrete Drop Inlet 3 ft x 2 ft Type S2	0.00	1.00	1.00	EA	0.00	\$1,729.83	\$0.00
		0001	5003	7319902	MISC.Misc. Drop Inlet Construction	0.00	1.00	1.00	EA	1.00	\$1,000.00	\$1,000.00
		0001	5004	1094000	FORCE ACCOUNT	0.00	55,744.79	55,744.79	EA	55,744.79	\$1.00	\$55,744.79
	Project J5	5S3378 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,308,499.92
210416-D05 Ove	rall - Total	Value Post	ted to Dat	te as of Repo	ort Generated Date							\$1,308,499.92



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5S3378

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0060	3040504	TYPE 5 AGGREGATE FOR BASE	12/3/21	12/16/21	33.60	SQYD		22				Curb and Gutter
			12/6/21	12/16/21	19.80	SQYD		385+90.93		386+13.47		Curb Ramp
				12/16/21	139.00	SQYD		385+04.51		384+00.00		Curb and Gutter
			12/7/21	12/16/21	31.30	SQYD		385+26.09		385+04.51		Curb and Gutter
				12/16/21	54.90	SQYD		384+82.35		384+00.00		Sidewalk
			12/14/21	12/16/21	18.60	SQYD		385+31.89		385+03.98		Curb Ramp
				12/16/21	18.70	SQYD		385+03.98		384+82.35		Sidewalk
0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	12/15/21	12/16/21	63.38	SQYD		384+00.00		384+76.40		Optional Pavement - This is withholding 28.22 SY for this posting due to material discrepancies. Withholding this amount allows for pay to be given to the contractor until the discrepancies are resolved.
0080	4019905	MISC.	12/15/21	12/16/21	63.38	SQYD		384+00.00		384.76.40		This is withholding 28.22 SY for this posting due to material discrepancies. Withholding this amount allows for pay to be given to the contractor until the discrepancies are resolved.
0160	6081010	CONCRETE CURB RAMP	12/6/21	12/16/21	19.80	SQYD		385+90.93		386+13.47		
			12/14/21	12/16/21	18.60	SQYD		385+31.89		385+03.98		
0170	6081012	TRUNCATED DOMES	12/6/21	12/16/21	16.00	SQFT		386+09.00				
0190	6086004	CONCRETE SIDEWALK, 4 IN.	12/7/21	12/16/21	54.90	SQYD		384+82.35		384+00		
			12/14/21	12/16/21	18.70	SQYD		385+03.98		384+82.35		
0230	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	12/3/21	12/16/21	18.00	LF		385+74.65		385+91.65		
				12/16/21	40.00	LF	This is on the inside portion of the island and the Breaktime parking lot.	22				
0240	6091052	CURB AND GUTTER TYPE B	12/3/21	12/16/21	25.30	LF		385+73.84		385+99.13		
			12/6/21	12/16/21	104.50	LF		385+04.51		384+00.00		
			12/7/21	12/16/21	23.50	LF		385+26.09		385+04.51		
0550	8031000A	TURF TYPE TALL FESCUE SODDING	12/14/21	12/16/21	9.30	SQYD		385+65.05		10+81.98		
				12/16/21	156.50	SQYD		385+65.05		10+81.98		

The information below this line are details for Construction Signs (if applicable). No Data Available



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J5S3378	0060	TYPE 5 AGGREGATE FOR BASE	Material		3	Jul 16, 2021	SYSTEM	\$2,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					3	Jul 16, 2021	SYSTEM	(\$2,380.00)												
					4	Aug 3, 2021	SYSTEM	\$5,564.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					4	Aug 3, 2021	SYSTEM	(\$5,564.30)												
				- Total				\$0.00												
			Material - T	otal				\$0.00												
			Price FUEL		3	Jul 16, 2021	SYSTEM	\$9.69	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					4	Aug 3, 2021	SYSTEM	\$12.96	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					5	Aug 16, 2021	SYSTEM	\$18.10	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					6	Sep 2, 2021	SYSTEM	\$27.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					7	Sep 16, 2021	SYSTEM	\$4.43	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					8	Oct 1, 2021	SYSTEM	\$36.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					9	Oct 18, 2021	SYSTEM	\$31.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					9	Oct 18, 2021	SYSTEM	\$1.85	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
																10	Nov 2, 2021	SYSTEM	\$0.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					11	Nov 16, 2021	SYSTEM	\$21.40	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					11	Nov 16, 2021	SYSTEM	\$32.07	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					12	Dec 2, 2021	SYSTEM	\$21.74	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					13	Dec 16, 2021	SYSTEM	\$22.28	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
				- Total				\$240.61												
			Price FUEL	- Total				\$240.61												
	0060 -	Total						\$240.61												
	0070	TYPE 5 AGGREGATE FOR BASE (6	Price FUEL		5	Aug 16, 2021	SYSTEM	\$26.93	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
		IN. THICK)			6	Sep 2, 2021	SYSTEM	\$60.36	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					7	Sep 16, 2021	SYSTEM	\$19.80	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					8	Oct 1, 2021	SYSTEM	\$17.48	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					9	Oct 18, 2021	SYSTEM	\$77.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					10	Nov 2, 2021	SYSTEM	\$43.21	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					11	Nov 16, 2021	SYSTEM	\$77.87	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					12	Dec 2, 2021	SYSTEM	\$22.22	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					13	Dec 16, 2021	SYSTEM	\$6.85	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
				- Total				\$352.05												
			Price FUEL					\$352.05												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J5S3378	0070 -	Total						\$352.05							
	0080	MISC.	Material		5	Aug 16, 2021	SYSTEM	\$28,184.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					5	Aug 16, 2021	SYSTEM	(\$28,184.00)							
					6	Sep 2, 2021	SYSTEM	\$36,319.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					6	Sep 2, 2021	SYSTEM	(\$36,319.20)							
					7	Sep 16, 2021	SYSTEM	\$67,408.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
					7	Sep 16, 2021	SYSTEM	(\$67,408.70)							
					8	Oct 1, 2021	SYSTEM	\$94,845.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					8	Oct 1, 2021	SYSTEM	(\$94,845.20)							
					9	Oct 18, 2021	SYSTEM	\$141,346.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					9	Oct 18, 2021	SYSTEM	(\$141,346.20)							
					10	Nov 2, 2021	SYSTEM	\$167,333.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					10	Nov 2, 2021	SYSTEM	(\$167,333.20)							
					11	Nov 16, 2021	SYSTEM	\$129,659.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user burtoc4 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
								11	Nov 16, 2021	SYSTEM	(\$129,659.60)				
					12	Dec 2, 2021	SYSTEM	\$267,307.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hakej1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
												12	Dec 2, 2021	SYSTEM	(\$267,307.30)
					13	Dec 16, 2021	SYSTEM	\$267,307.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					13	Dec 16, 2021	SYSTEM	(\$267,307.30)							
				- Total				\$0.00							
			Material - To Other Item	otal FUEL	5	Aug 16,	hakej1	\$0.00 \$65.67	For lines 0080 and 0210. See Supporting Documentation for a breakdown.						
			Adjustment		6	2021 Sep 2,	hakej1	\$165.37							
					7	2021 Sep 16,	, hakej1	\$97.24							
										8	2021 Oct 1,	hakej1	\$47.87		
															9
					10	2021 Nov 2,	hakej1	(\$18,292.30)							
					11	2021 Nov 16,	SYSTEM	\$18,292.30							
					12	2021 Dec 2,	hakej1	\$60.88	This is for this Estimate						
						2021									



Dec 29, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
5\$3378	0080	MISC.	Other Item Adjustment	FUEL	12	Dec 2, 2021	hakej1	\$213.31	This is the adjustment for Estimate 0011 for the period of Nov. 1 - 15.										
					13	Dec 16, 2021	hakej1	\$18.77											
				FUEL - Tota	d .			\$898.05											
			Other Item	Adjustment -	Total			\$898.05											
	0080 -	Total						\$898.05											
	0090	MISC.	Other Item Adjustment	FUEL	6	Sep 2, 2021	hakej1	\$7.54											
					12	Dec 2, 2021	hakej1	\$24.01	Fuel Adjustment for Estimate 0011										
				FUEL - Tota	ıl			\$31.55											
			Other Item	Adjustment -	Total			\$31.55											
				Augustinent	Total														
	0090 -							\$31.55											
	0100	CONCRETE PAVEMENT (6 IN. NON- REINFORCED,	Material		7	Sep 16, 2021	SYSTEM	\$3,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
		,			7	Sep 16, 2021	SYSTEM	(\$3,892.00)											
					8	Oct 1, 2021	SYSTEM	\$3,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
					8	Oct 1, 2021	SYSTEM	(\$3,892.00)											
															9	Oct 18, 2021	SYSTEM	\$3,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
							9	Oct 18, 2021	SYSTEM	(\$3,892.00)									
												10	Nov 2, 2021	SYSTEM	\$3,892.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					10	Nov 2, 2021	SYSTEM	(\$3,892.00)											
					13	Dec 16, 2021	SYSTEM	\$20,629.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.										
					13	Dec 16, 2021	SYSTEM	(\$20,629.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
			Price FUEL		7	Sep 16, 2021	SYSTEM	\$4.90	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					11	Nov 16, 2021	SYSTEM	\$45.04	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
					12	Dec 2, 2021	SYSTEM	\$12.36	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
				- Total				\$62.30											
			Price FUEL	- Total				\$62.30											
	0100 -	Total						\$62.30											
	0110	WATER - UTILITY ITEM	Material		4	Aug 3, 2021	SYSTEM	\$6,075.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					4	Aug 3, 2021	SYSTEM	(\$6,075.00)											
				- Total				\$0.00											
			M-4																
			Material - T	otal				\$0.00											
	0110 -	Total						\$0.00											
	0130	PIPE COLLAR, TYPE A	Material		3	Jul 16, 2021	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user hakej1 overridding Payment										



Dec 29, 2021

Alton         PARE COLLS, TYPE A Material Topic T	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
TPEEA         TPEEA         TPEEA         Starting - Total         Starting - Starti				Туре	Adjustment Type	Number	Date	Ву		
Image: Second	5S3378	0130		Material						Estimate Exception 2 on the current Payment Estimate.
Image: state in the s			IYPE A			3		SYSTEM	(\$500.00)	
Vertur         0         Overtur         0         Overtur         0					- Total				\$0.00	
Image: Provide a control of the control of				Material - To	otal				\$0.00	
Image: Provide and the second seco				Overrun	Overrun	8		SYSTEM	\$500.00	Estimate Item Adjustment (0008) due to user hakej1 overridding Payment
Image: state in the im						8		SYSTEM	(\$500.00)	
Overnue.rotat         (3500.00)           7130 - Total         (3500.00)           01000         CONCRETE CUBB RAMP Aug.3, SYSTEM         81,752.00         This adjustment offsets the original system-penerated Material Payment Estimate lism. Adjustment (000) due to user hales) coveriding Payment Estimate lism. Adjustment (000) due to user hales) coveriding Payment Estimate lism. Adjustment (000) due to user hales) coveriding Payment Estimate lism. Adjustment offsets the original system-penerated Material Payment Estimate lism. Adjustment offsets the original system-penerated Material Payment Estimate Exception 7 on the current Payment Estimate.           01700         TRUNCATED DOMES         Material.         4         Aug.3, 2021         SYSTEM         \$1,255.00           01700         TRUNCATED DOMES         Material.         4         Aug.3, 2021         SYSTEM         \$1,255.00           0170         TRUNCATED DOMES         Material.         5         Aug.3, 2021         SYSTEM         \$1,256.00           0         5         Aug.16, 2021         SYSTEM         \$1,256.00         This adjustment offsets the original system-penerated Material Payment Estimate Exception 7 on the current Payment Estimate.           0         Starp 1, 2021         SYSTEM         \$1,256.00         This adjustment offsets the original system-penerated Material Payment Estimate Exception 2 on the current Payment Estimate.           1         Aug.16, 2021         SYSTEM         \$2,555.00						9		SYSTEM	(\$500.00)	
OTO         CONCRETE CURB RAMP         Material Metrial - Total         4         Aug.3. 2021         SYSTEM         51,752.00         The adjustment officits the original system-generated Material Payment Estimate Exception 3 on the outent Payment Estimate.           0100         -Total         5000         -Total         5000         -Total         5000           0110         -Total         5000         -Total         5000         -Total         5000           0110         Total         5000         5100         5000         -Total         5000           0110         TRUNCATED         Material - Total         51000         51000         This adjustment offlets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           0110         TRUNCATED         Material - Total         610,2000         SYSTEM         \$1,20000         This adjustment offlets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           0110         FUNCATED         Aug 16,         SYSTEM         \$1,205000         This adjustment offlets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           0110         Format         SySTEM         \$1,205000         This adjustment offlets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. <td></td> <td></td> <td></td> <td></td> <td>Overrun - T</td> <td>otal</td> <td></td> <td></td> <td>(\$500.00)</td> <td></td>					Overrun - T	otal			(\$500.00)	
0100         CONCRETE UNB FAMP         Matrial         4         Aug.3 2021         SYSTEM         \$1,752.00         The adjustment Odds due is used inside 1 Advanced 1 Advanced 1 Payment Estimate Exception 3 on the current Payment Estimate.           0100         - Total         50.00         50.00         50.00         50.00           0100         - Total         50.00         50.00         50.00         50.00           0100         TRUNCATED         4         Aug.3 2021         SYSTEM         \$1,286.00         This adjustment Offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.           0170         TRUNCATED         Material         Fault System         \$1,286.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.           0170         TRUNCATED         Aug.3 (SYSTEM         \$1,286.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           0180         Aug.16 (Sig.255.00)         SYSTEM         \$1,286.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           0180         Aug.16 (Sig.255.00)         SYSTEM         \$1,255.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment				Overrun - T	otal				(\$500.00)	
CURB RAMP         Image: Part of the current Payment Estimate.         Estimate Exception 3 on the current Payment Estimate.           0         - Total         300 0         - State         - State           0         - Total         300 0         - State         - State           0         - Total         - State         - State         - State           0         - Total         - State         - State         - State           0         - Total         - State         - State         - State           0         - Total         - State         - State         - State           0         - Total         - State         - State         - State           0         - Total         - State         - State         - State         - State           0         - Total         - State         - State         - State         - State           0         - Total         - State         - State         - State         - State         - State           0         - State         - State <td< td=""><td></td><td>0130 -</td><td>Total</td><td></td><td></td><td></td><td></td><td></td><td>(\$500.00)</td><td></td></td<>		0130 -	Total						(\$500.00)	
Image: Note of the image: No		0160		Material		4		SYSTEM	\$1,752.00	Estimate Item Adjustment (0009) due to user hakej1 overridding Payment
Image: state						4		SYSTEM	(\$1,752.00)	
O160 - Total         Source         Source           0170         TRUNCATED DOMES         Material         4         2021         SYSTEM         \$1.295.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.           4         2021         SYSTEM         \$1.295.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate.           5         Aug 16, 2021         SYSTEM         \$1.295.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           6         Sep 16, 2021         SYSTEM         \$1.295.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           6         Sep 16, 2021         SYSTEM         \$2.555.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           7         Sep 16, 2021         SYSTEM         \$4.735.50         This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.           0170 - Total         5 0.00           0180         PAVED N         Material - Total         \$3.00         This adjustment offsets the original system-generated Material Payment Estimate E					- Total				\$0.00	
0170         TRUNCATED DOMES         Material DOMES         Material Network         4         Aug 3, 2021         SYSTEM         \$1.295.00         This adjustment (0010) due to user hake[1 overridding Payment Estimate Exception 7 on the current Payment Estimate.           4         Aug 3, 2021         SYSTEM         \$1.295.00         Fine adjustment (0010) due to user hake[1 overridding Payment Estimate Exception 7 on the current Payment Estimate.           5         Aug 16, 2021         SYSTEM         \$1.295.00         Fine adjustment (0561) due to user hake[1 overridding Payment Estimate Exception 2 on the current Payment Estimate.           6         Sep 2, 2021         SYSTEM         \$1.295.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           6         Sep 2, 2021         SYSTEM         \$2.255.00         This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.           6         Sep 16, 2021         SYSTEM         \$4.735.50         This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.           Material Sep 2011           Y Material Sep 2011           Y Sep 16, 2021         SYSTEM         \$4.735.50           Y Sep 2011           Y Material Sep 2011										



Type Adjustment Number Date By Type																									
3278     0.980 PERCENNE     PACE PERCENNE     Pace PERCENN	Project	Line	Description						Amount	Remarks															
APPROACH, 8, No.         Full L         2021 <td></td> <td></td> <td></td> <td></td> <td>Туре</td> <td></td> <td></td> <td></td> <td></td> <td></td>					Туре																				
Image: state         Set (Set (Set (Set (Set (Set (Set (Set (	583378	0180	APPROACH, 8			4		SYSTEM	\$18.62	Reference Item Price Adjustment Index Adjustment Type applied is FUEL															
v   v   v   v   v   v   v   v   v						5		SYSTEM	\$25.61	Reference Item Price Adjustment Index Adjustment Type applied is FUEL															
Image: state in the s						6		SYSTEM	\$16.44	Reference Item Price Adjustment Index Adjustment Type applied is FUEL															
Index         Side of the second						8		SYSTEM	\$32.08	Reference Item Price Adjustment Index Adjustment Type applied is FUEL															
VICUPUEL         Total         STORE PLEE         Status           100         Total         SUBCEVALK, N. N. P.						11		SYSTEM	\$66.77	Reference Item Price Adjustment Index Adjustment Type applied is FUEL															
Othe         Total         U         Status					- Total				\$168.48																
0190 SIDEWALK, NN NN NN NN NN NN NN NN NN NN NN NN NN				Price FUEL	- Total				\$168.48																
SIDEWALK,4,N,N         Sidewalk,4         N         Entransis tem, Adjustment (006) du's user hadej) overridding Payment Estimate Esception 6 on the current Payment Estimate.           1         3         Ju 16, 2021         SYSTEM         (\$4,860.00)         Estimate Esception 6 on the current Payment Estimate.           1         2021         SYSTEM         \$11,982.60         Estimate Esception 11 on the current Payment Estimate.           1         2021         SYSTEM         \$11,982.60         Estimate Esception 11 on the current Payment Estimate.           1         0         2021         SYSTEM         \$11,982.60         Estimate Esception 11 on the current Payment Estimate.           1         1         1         50.00         Estimate Esception 11 on the current Payment Estimate.           1         1         1         1         50.00         Estimate Esception 40 on the current Payment Estimate.           1         1         2021         SYSTEM         \$885.60         This adjustment officies the original system-generated Material Payment Estimate Esception 4 on the current Payment Estimate.           1         2021         SYSTEM         \$885.60         This adjustment officies the original system-generated Material Payment Estimate Esception 4 on the current Payment Estimate.           1         0         0.01         SYSTEM         \$8856.00         This adjus		0180 -	Total						\$168.48																
Visite         Visite         Visite         Visite         Visite         Visite           4         Aug.3         SYSTEM         S11,982.60         Statuse		0190	SIDEWALK, 4	Material		3		SYSTEM	\$4,860.00	Estimate Item Adjustment (0008) due to user hakej1 overridding Payment															
Image: Provide the second se						3		SYSTEM	(\$4,860.00)																
Concent         Concent         Solution         Solution           0190 - Total         30.00         30.00           0200 - Total         Solution         30.00           0200 - Total         Solution         30.00           0200 - Total         Solution         Solution           7         Sep 16, SYSTEM         \$855.60         This adjustment offsets the original system-operated Material Payment Estimate Exception 4 on the current Payment Estimate           8         Oct 1, SYSTEM         \$855.60         This adjustment offsets the original system-operated Material Payment Estimate           9         Oct 1, SYSTEM         \$855.60         This adjustment offsets the original system-operated Material Payment Estimate           9         Oct 1, SYSTEM         \$855.60         This adjustment offsets the original system-operated Material Payment Estimate           9         Oct 1, SYSTEM         \$855.60         This adjustment offsets the original system-operated Material Payment Estimate           10         Nov 2, SYSTEM         \$855.60         This adjustment offsets the original system-operated Material Payment Estimate           10         Nov 2, SYSTEM         \$855.60         This adjustment offsets the original system-operated Material Payment Estimate           10         Nov 2, SYSTEM         \$855.60         This adjustment offsets the original system-operated Mate						4		SYSTEM	\$11,982.60	Estimate Item Adjustment (0014) due to user hakej1 overridding Payment															
Visite         Visite<						4		SYSTEM	(\$11,982.60)																
Otop - Total         Sub           0200         CONCRETE SIDEWALK, 7 IN.         Material F         2021         SYSTEM         \$855.60         Estimate tem Adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.           7         Sep 16, 2021         SYSTEM         (8855.60)         File adjustment offsets the original system-generated Material Payment.           8         Oct 1, 2021         SYSTEM         (8855.60)         File adjustment offsets the original system-generated Material Payment.           9         Oct 1, 2021         SYSTEM         (8855.60)         File adjustment offsets the original system-generated Material Payment.           9         Oct 18, 2021         SYSTEM         (8855.60)         File adjustment offsets the original system-generated Material Payment.           9         Oct 18, 2021         SYSTEM         (8855.60)         File adjustment offsets the original system-generated Material Payment.           10         Nov 2, 2021         SYSTEM         (8855.60)         File adjustment offsets the original system-generated Material Payment.           11         Nov 2, 2021         SYSTEM         (8855.60)         File adjustment offsets the original system-generated Material Payment.           12         Dec 16, 2021         SYSTEM         (8855.60)         File adjustment offsets the original system-generated Material Pay					- Total				\$0.00																
020         CONCRETE SIDEWALK, 7 IN.         Material F         2021         SYSTEM         \$855.60         This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.           7         Sep 16, 2021         SYSTEM         (8855.60)         This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.           8         Oct 1, 2021         SYSTEM         (8855.60)         This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.           8         Oct 1, 2021         SYSTEM         (8855.60)         This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.           9         Oct 1, 2021         SYSTEM         (8855.60)         This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.           9         Oct 1, 2021         SYSTEM         (8855.60)         This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.           9         Oct 1, 2021         SYSTEM         (8855.60)         This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.           10         Nov 2, 2021         SYSTEM         (8855.60)         This adjustment offsets the original sy				Material - To	otal				\$0.00																
SIDEWALK, 7 N.         Sidewal		0190 -	Total						\$0.00																
Verticity       Value       Value       Value       Value         Value       Value       Value       Value       Value       Value         Value       Value       Value       Value       Value       Value       Value         Value       Value       Value       Value       Value       Value       Value       Value         Value       Val		0200	SIDEWALK, 7	Material		7		SYSTEM	\$855.60	Estimate Item Adjustment (0010) due to user hakej1 overridding Payment															
Value         Value <td< td=""><td></td><td></td><td></td><td rowspan="2"></td><td rowspan="2"></td><td rowspan="2"></td><td rowspan="2"></td><td rowspan="2"></td><td rowspan="2"></td><td rowspan="2"></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>7</td><td></td><td>SYSTEM</td><td>(\$855.60)</td><td></td></td<>																					7		SYSTEM	(\$855.60)	
0         0												8		SYSTEM	\$855.60	Estimate Item Adjustment (0010) due to user hakej1 overridding Payment									
View						8		SYSTEM	(\$855.60)																
<ul> <li> <ul> <li></li></ul></li></ul>						9		SYSTEM	\$855.60	Estimate Item Adjustment (0007) due to user hakej1 overridding Payment															
<ul> <li>Image: A set of the set of the</li></ul>						9		SYSTEM	(\$855.60)																
View															10	,	SYSTEM	\$855.60	Estimate Item Adjustment (0008) due to user hakej1 overridding Payment						
Amount       Amount       2021       Amount       Estimate Item Adjustment (0008) dué to user hakej1 overridding Payment Estimate.         Amount       13       Dec 16, 2021       \$\STEM       \$\Status         - Total       - Total       \$\Status       \$\Status       \$\Status         Material - Total       \$\Status       \$\Status       \$\Status       \$\Status         0200 - Total       \$\Status       \$\Status       \$\Status       \$\Status       \$\Status         0210       MISC. CONCRETE       Material       \$\Status														10		SYSTEM	(\$855.60)								
Vice Add     Vice Add       - Total     2021     \$0.00       Material - Total     \$0.00       0200 - Total     \$0.00       0210     MISC. CONCRETE     Material       0210     MISC. CONCRETE     5     Aug 16, 2021     \$YSTEM     \$16,558.50     This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.       - Total     - Total     \$\$0.00						13		SYSTEM	\$855.60	Estimate Item Adjustment (0008) due to user hakej1 overridding Payment															
Material - Total       \$0.00         0200 - Total       \$0.00         0210       MISC. CONCRETE       Material         0210       MISC. CONCRETE       Material         5       Aug 16, 2021       \$YSTEM       \$16,558.50         5       Aug 16, 2021       \$YSTEM       \$16,558.50         - Total       5       Aug 16, 2021       \$YSTEM       \$(\$16,558.50)         - Total       - Total       \$YSTEM       \$\$0.00						13		SYSTEM	(\$855.60)																
O200 - Total       \$0.00         O210       MISC. CONCRETE       Material       5       Aug 16, 2021       SYSTEM       \$16,558.50       This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.         - Total       - Total       \$0.00					- Total				\$0.00																
0210       MISC. CONCRETE       Material       5       Aug 16, 2021       SYSTEM       \$16,558.50       This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment         5       Aug 16, 2021       SYSTEM       \$16,558.50       This adjustment offsets the original system-generated Material Payment         - Total				Material - To	otal				\$0.00																
CONCRETE CONCRETE 2021 2021 Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 5 Aug 16, 2021 (\$16,558.50) - Total \$0.00		0200 -	Total						\$0.00																
- Total \$0.00		0210		Material		5		SYSTEM	\$16,558.50	Estimate Item Adjustment (0012) due to user hakej1 overridding Payment															
						5		SYSTEM	(\$16,558.50)																
Material - Total \$0.00					- Total				\$0.00																
				Material - To	otal				\$0.00																



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3378	0210	MISC. CONCRETE	Other Item Adjustment	FUEL	6	Sep 2, 2021	hakej1	\$15.81	
					12	Dec 2, 2021	hakej1	\$2.21	Fuel Adjustment
					12	Dec 2, 2021	hakej1	\$38.01	Fuel Adjustment for Estimate 0011
				FUEL - Tota	I			\$56.03	
			Other Item	Adjustment -	Total			\$56.03	
	0210 -	Total						\$56.03	
	0220	MISC. CONCRETE	Material		6	Sep 2, 2021	SYSTEM	\$8,041.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$8,041.00)	
					7	Sep 16, 2021	SYSTEM	\$9,163.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$9,163.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Other Item Adjustment	FUEL	6	Sep 2, 2021	hakej1	\$15.33	
					7	Sep 16, 2021	hakej1	\$1.43	
					8	Oct 1, 2021	hakej1	\$1.47	
					12	Dec 2, 2021	hakej1	\$2.15	Fuel Adjustment
				FUEL - Total				\$20.38	
			Other Item	Adjustment -	Total			\$20.38	
	0220 -	Total						\$20.38	
	0230	CONCRETE CURB (6 IN. HEIGHT AND	Material		7	Sep 16, 2021	SYSTEM	\$18,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
		UNDER)			7	Sep 16, 2021	SYSTEM	(\$18,517.50)	
					8	Oct 1,	SYSTEM	¢10 E17 E0	
						2021		\$18,517.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	2021 Oct 1, 2021	SYSTEM	(\$18,517.50)	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
					8	Oct 1,			Estimate Item Adjustment (0011) due to user hakej1 overridding Payment
						Oct 1, 2021 Oct 18,	SYSTEM	(\$18,517.50)	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment
					9	Oct 1, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM	(\$18,517.50) \$18,517.50	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment
					9 9	Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM	(\$18,517.50) \$18,517.50 (\$18,517.50)	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment
					9 9 10	Oct 1, 2021 Oct 18, 2021 Oct 18, 2021 Nov 2, 2021 Nov 2,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$18,517.50) \$18,517.50 (\$18,517.50) \$18,517.50	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment
					9 9 10 10	Oct 1, 2021           Oct 18, 2021           Oct 18, 2021           Nov 2, 2021           Nov 2, 2021           Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$18,517.50) \$18,517.50 (\$18,517.50) \$18,517.50 (\$18,517.50)	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment
				- Total	9 9 10 10 13	Oct 1,           2021           Oct 18,           2021           Nov 2,           2021           Nov 2,           2021           Dec 16,           Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$18,517.50) \$18,517.50) (\$18,517.50) \$18,517.50) (\$18,517.50) \$76,312.50	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment
			Material - To		9 9 10 10 13	Oct 1,           2021           Oct 18,           2021           Nov 2,           2021           Nov 2,           2021           Dec 16,           Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$18,517.50) \$18,517.50) (\$18,517.50) \$18,517.50) (\$18,517.50) \$76,312.50 (\$76,312.50)	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment
	0230 -	Total	Material - To		9 9 10 10 13	Oct 1,           2021           Oct 18,           2021           Nov 2,           2021           Nov 2,           2021           Dec 16,           Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$18,517.50) \$18,517.50) (\$18,517.50) \$18,517.50) (\$18,517.50) \$76,312.50 (\$76,312.50) (\$76,312.50)	Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate.



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3378	0240	GUTTER TYPE B	Material			2021			Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$9,597.00)	
					4	Aug 3, 2021	SYSTEM	\$16,375.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$16,375.80)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0240 -	Total				_		\$0.00	
	0250	CONCRETE CURB LOW PROFILE TYPE E	Material		5	Aug 16, 2021	SYSTEM	\$7,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$7,840.00)	
					6	Sep 2, 2021	SYSTEM	\$7,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$7,840.00)	
					7	Sep 16, 2021	SYSTEM	\$7,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$7,840.00)	
					8	Oct 1, 2021	SYSTEM	\$9,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$9,100.00)	
					9	Oct 18, 2021	SYSTEM	\$9,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$9,100.00)	
					10	Nov 2, 2021	SYSTEM	\$17,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$17,360.00)	
					11	Nov 16, 2021	SYSTEM	\$17,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user burtoc4 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$17,360.00)	
					12	Dec 2, 2021	SYSTEM	\$17,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user hakej1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$17,360.00)	
					13	Dec 16, 2021	SYSTEM	\$17,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Dec 16, 2021	SYSTEM	(\$17,360.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0250 -	Total						\$0.00	
	0260	CURVED VANE GRTE AND FRAME(2 FT. X 2 FT)	Material		4	Aug 3, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hakej1 overridding Payment Estimate Exception 19 on the current Payment Estimate.



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3378	0260	CURVED VANE GRTE	Material	туре	4	Aug 3, 2021	SYSTEM	(\$2,500.00)	
		AND FRAME(2 FT. X 2 FT)			5	Aug 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$2,500.00)	
					6	Sep 2, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$2,500.00)	
					7	Sep 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$2,500.00)	
					8	Oct 1, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$2,500.00)	
					9	Oct 18, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$2,500.00)	
					10	Nov 2, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$2,500.00)	
					11	Nov 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user burtoc4 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$2,500.00)	
					12	Dec 2, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user hakej1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$2,500.00)	
					13	Dec 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					13	Dec 16, 2021	SYSTEM	(\$2,500.00)	
				- Total				\$0.00	
	0260-	· Total	Material - T					\$0.00 \$0.00	
	0200 -	CURVED	Material		3	Jul 16,	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment
	5210	VANE GRATE AND FRAME(4 FT. X 2 FT	Material			2021			Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$9,000.00)	
					4	Aug 3, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hakej1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$9,000.00)	
					5	Aug 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$9,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
5S3378	0270	CURVED VANE GRATE AND FRAME(4	Material		6	Sep 2, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.												
		FT. X 2 FT			6	Sep 2, 2021	SYSTEM	(\$9,000.00)													
					7	Sep 16, 2021	SYSTEM	\$9,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.												
					7	Sep 16, 2021	SYSTEM	(\$9,000.00)													
				- Total				\$0.00													
			Material - T	otal				\$0.00													
	0270 -	Total					_	\$0.00													
	0280	MANHOLE FRAME AND COVER, TYPE 3	Material		3	Jul 16, 2021	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.												
		0			3	Jul 16, 2021	SYSTEM	(\$2,500.00)													
					4	Aug 3, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hakej1 overridding Payment Estimate Exception 21 on the current Payment Estimate.												
					4	Aug 3, 2021	SYSTEM	(\$3,000.00)													
								5	Aug 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.									
					5	Aug 16, 2021	SYSTEM	(\$3,000.00)													
					6	Sep 2, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
					6	6	Sep 2, 2021	SYSTEM	(\$3,000.00)												
					7	Sep 16, 2021	SYSTEM	\$3,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
									7	Sep 16, 2021	SYSTEM	(\$3,000.00)									
					8	Oct 1, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.												
					8	Oct 1, 2021	SYSTEM	(\$3,500.00)													
																9	Oct 18, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
										9	Oct 18, 2021	SYSTEM	(\$3,500.00)								
					10	10	Nov 2, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
					10	Nov 2, 2021	SYSTEM	(\$3,500.00)													
			2021     Estimate Item Adjustment (0023) due to user burtoc4 over Estimate.       11     Nov 16, 2021     \$YSTEM (\$3,500.00)       12     Dec 2, SYSTEM \$3,500.00     This adjustment offsets the original system-generated Maximum control of the system sys	11	11Nov 16, 2021SYSTEM\$3,500.00This adjustment offsets Estimate Item Adjustment Estimate Exception 4 or11Nov 16, 2021SYSTEM(\$3,500.00)12Dec 2, 2021SYSTEM\$3,500.0012Dec 2, 2021SYSTEM\$3,500.00					11     Nov 16, 2021     SYSTEM     \$3,500.00     This adjustment offsets the original system Estimate Item Adjustment (0023) due to u Estimate Exception 4 on the current Payment       11     Nov 16, SYSTEM     (\$3,500.00)							11		SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user burtoc4 overridding Payment Estimate Exception 4 on the current Payment Estimate.
							12	12	1		1:	12	1:	12	12	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user hakej1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
				12																	
					13	Dec 16, 2021	SYSTEM	\$3,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment												



Dec 29, 2021

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
5S3378	0280	MANHOLE FRAME AND	Material						Estimate Exception 9 on the current Payment Estimate.
		COVER, TYPE			13	Dec 16, 2021	SYSTEM	(\$3,500.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0280 -	Total						\$0.00	
	0340	WARNING LIGHT, TYPE B	Overrun	Overrun		Jun 30, 2021	SYSTEM	(\$180.00)	
					5	Aug 16, 2021	SYSTEM	\$180.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',45.00000 - 45.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - T	otal				\$0.00	
	0340 -	Total						\$0.00	
	0430	MISC. PAVEMENT	Other Item Adjustment	REFL	13	Dec 16, 2021	hakej1	(\$562.75)	20% withholding until retro reflectivity results have been tested and meet MoDOT specification
		MARKINGS		REFL - Tota	I			(\$562.75)	
			Other Item	Adjustment -	Total			(\$562.75)	
	0430 -	Total						(\$562.75)	
	0440	MISC. PAVEMENT MARKINGS	Other Item Adjustment	REFL	13	Dec 16, 2021	hakej1	(\$669.25)	20% withholding until retro reflectivity results have been tested and meet MoDOT specification
		MARKINGS		REFL - Tota	l .			(\$669.25)	
			Other Item	Adjustment -	Total			(\$669.25)	
	0440 -	Total						(\$669.25)	
	0470	15 IN. PIPE CULVERT GROUP B	Overrun	Overrun	8	Oct 1, 2021	SYSTEM	\$1,155.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$1,155.00)	
					9	Oct 18, 2021	SYSTEM	(\$1,155.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
				Overrun - T	otal			(\$1,155.00)	
			Overrun - T	otal				(\$1,155.00)	
	0470 -							(\$1,155.00)	
	0510	CONCRETE DROP INLET 2	Material		4	Aug 3, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hakej1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
		FT X 2 FT			4	Aug 3, 2021	SYSTEM	(\$2,100.00)	
					5	Aug 16, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$2,100.00)	
					6	Sep 2, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$2,100.00)	
					7	Sep 16, 2021	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$2,100.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0510 -	Total						\$0.00	
	0520	PRECAST CONCRETE	Material		2	Jun 30, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user hakej1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3378	0520	DROP INLET 4	Material						Estimate Exception 1 on the current Payment Estimate.
		FT X 2 FT			2	Jun 30, 2021	SYSTEM	(\$2,000.00)	
					3	Jul 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					3	Jul 16, 2021	SYSTEM	(\$12,000.00)	
					4	Aug 3, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					4	Aug 3, 2021	SYSTEM	(\$12,000.00)	
					5	Aug 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Aug 16, 2021	SYSTEM	(\$12,000.00)	
					6	Sep 2, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$12,000.00)	
					7	Sep 16, 2021	SYSTEM	\$12,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$12,000.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0520	- Total						\$0.00	
	0530	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	Material		3	Jul 16, 2021	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
	0530	CONCRETE	Material		3		SYSTEM		Estimate Item Adjustment (0013) due to user hakej1 overridding Payment
	0530	CONCRETE DROP INLET 5	Material			2021 Jul 16,		\$24,000.00	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment
	0530	CONCRETE DROP INLET 5	Material		3	2021 Jul 16, 2021 Aug 3,	SYSTEM	\$24,000.00 (\$24,000.00)	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
	0530	CONCRETE DROP INLET 5	Material		3	2021 Jul 16, 2021 Aug 3, 2021 Aug 3,	SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
	0530	CONCRETE DROP INLET 5	Material		3 4 4	2021 Jul 16, 2021 Aug 3, 2021 Aug 3, 2021 Aug 16,	SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00)	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
	0530	CONCRETE DROP INLET 5	Material		3 4 4 5	2021 Jul 16, 2021 Aug 3, 2021 Aug 3, 2021 Aug 16, Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment
	0530	CONCRETE DROP INLET 5	Material		3 4 4 5 5	2021 Jul 16, 2021 Aug 3, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00)	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.
	0530	CONCRETE DROP INLET 5	Material		3 4 4 5 5 6	2021 Jul 16, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate.
	0530	CONCRETE DROP INLET 5	Material		3 4 4 5 5 6 6	2021 Jul 16, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	0530	CONCRETE DROP INLET 5	Material	- Total	3 4 4 5 5 6 6 7	2021 Jul 16, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00)	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	0530	CONCRETE DROP INLET 5	Material Material - T		3 4 4 5 5 6 6 7	2021 Jul 16, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) (\$24,000.00) \$24,000.00 (\$24,000.00) (\$24,000.00)	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		CONCRETE DROP INLET 5			3 4 4 5 5 6 6 7	2021 Jul 16, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) (\$24,000.00) (\$24,000.00)	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
		CONCRETE DROP INLET 5 FT X 3 FT			3 4 4 5 5 6 6 7	2021 Jul 16, 2021 Aug 3, 2021 Aug 16, 2021 Aug 16, 2021 Sep 2, 2021 Sep 2, 2021 Sep 16, Sep 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) \$24,000.00 (\$24,000.00) (\$24,000.00) \$24,000.00 (\$24,000.00) (\$24,000.00) (\$24,000.00) \$20,000	Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 17 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 24 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
583378	0540	MISC.	Material			2021						
		MANHOLES AND DROP INLETS			5	Aug 16, 2021	SYSTEM	\$4,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
					5	Aug 16, 2021	SYSTEM	(\$4,900.00)				
					6	Sep 2, 2021	SYSTEM	\$4,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.			
					6	Sep 2, 2021	SYSTEM	(\$4,900.00)				
					7	Sep 16, 2021	SYSTEM	\$4,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user hakej1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
					7	Sep 16, 2021	SYSTEM	(\$4,900.00)				
				- Total				\$0.00				
			Material - T	otal				\$0.00				
	0540 -	- Total						\$0.00				
	0550	TURF TYPE TALL FESCUE SODDING	Material		10	Nov 2, 2021	SYSTEM	\$7,086.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.			
					10	Nov 2, 2021	SYSTEM	(\$7,086.60)				
					11	Nov 16, 2021	SYSTEM	\$13,026.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user burtoc4 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
						11	Nov 16, 2021	SYSTEM	(\$13,026.60)			
					12	Dec 2, 2021	SYSTEM	\$17,402.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user hakej1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
								12	Dec 2, 2021	SYSTEM	(\$17,402.40)	
						13	Dec 16, 2021	SYSTEM	\$20,386.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.		
					13	Dec 16, 2021	SYSTEM	(\$20,386.80)				
				- Total				\$0.00				
			Material - T	otal				\$0.00				
	0550 -	- Total						\$0.00				
	0560	CURB INLET CHECK	Material		2	Jun 30, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user hakej1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					2	Jun 30, 2021	SYSTEM	(\$600.00)				
					3	Jul 16, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
				3	3	3	3	3	Jul 16, 2021	SYSTEM	(\$600.00)	
					4	Aug 3, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user hakej1 overridding Payment Estimate Exception 26 on the current Payment Estimate.			
				4 5	Aug 3, 2021	SYSTEM	(\$600.00)					
					5	Aug 16, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hakej1 overridding Payment			
									Estimate Exception 13 on the current Payment Estimate.			
					5	Aug 16, 2021	SYSTEM	(\$600.00)	Estimate Exception 13 on the current Payment Estimate.			



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J5S3378	0560	CURB INLET CHECK	Material			2021			Estimate Item Adjustment (0029) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 2, 2021	SYSTEM	(\$1,800.00)	
					7	Sep 16, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user hakej1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$2,000.00)	
					8	Oct 1, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$2,000.00)	
					9	Oct 18, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$2,000.00)	
					10	Nov 2, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$2,000.00)	
					11	Nov 16, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user burtoc4 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					11	Nov 16, 2021	SYSTEM	(\$2,000.00)	
					12	Dec 2, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user hakej1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$2,000.00)	
					13	Dec 16, 2021	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					13	Dec 16, 2021	SYSTEM	(\$2,000.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0560 -	Total						\$0.00	
	0580	SILT FENCE	Material		7	Sep 16, 2021	SYSTEM	\$60.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user hakej1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Sep 16, 2021	SYSTEM	(\$60.00)	
					8	Oct 1, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Oct 1, 2021	SYSTEM	(\$788.00)	
					9	Oct 18, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user hakej1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Oct 18, 2021	SYSTEM	(\$788.00)	
					10	Nov 2, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Nov 2, 2021	SYSTEM	(\$788.00)	
					11	Nov 16, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user burtoc4 overridding Payment Estimate Exception 7 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3378	0580	SILT FENCE	Material		11	Nov 16, 2021	SYSTEM	(\$788.00)	
					12	Dec 2, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user hakej1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					12	Dec 2, 2021	SYSTEM	(\$788.00)	
					13	Dec 16, 2021	SYSTEM	\$788.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user hakej1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					13	Dec 16, 2021	SYSTEM	(\$788.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0580 -	Total						\$0.00	
	0590	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Other Item Adjustment	OTHR	4	Aug 3, 2021	hakej1	(\$40,000.00)	This is to withhold money until they install the tracer wire.
				OTHR - Total				(\$40,000.00)	
			Other Item Adjustment - Total					(\$40,000.00)	
	0590 - Total							(\$40,000.00)	
	0640	CONDUIT, 2 IN. RIGID, IN TRENCH	Overrun	Overrun	6	Sep 2, 2021	SYSTEM	(\$870.00)	
					10	Nov 2, 2021	SYSTEM	\$870.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - Total					\$0.00	
	0640 -	Total						\$0.00	
J5S3378 - Total								(\$41,057.55)	
Overall - Total								(\$41,057.55)	