

Pay Estimate Created Date: February 28, 2022

Progress Estimate No 10	umber		210416-D07 Emery Sapp & So			y 28, 2022 N	Driginal Contract Amount let Change Order Amoun Current Contract Amount	t (\$67,312.52)			
Approval Date								By User			
March 1, 2022		(Generated and Ap	proved (and	d should be considered	Draft) at the	Project Office Level by	ackert			
March 3, 2022		Revie	ewed and Approv	ed (and sho	uld be considered Draf	t) at the Res	ident Engineer Level by	oeschd?			
March 3, 2022	Reviewed and Approved at the Central Office Controllers Office Level by										
Original Completion	Date	Current Com	pletion Date	Actual	al Completion Date % of Current Contract Amount Complete						
December 1, 202	1	Decembe	r 1, 2021				100.00%				
	Contra	ct Informational Da	tes		Milestone	s					
Date Description	Origina	al Completion Date	Current Compl	etion Date	Date No Milestones Exist for Contract						
Acceptance Date											
Awarded Date	May 5,	2021	May 5, 2021								
Letting Date April 16, 2021 April 16, 2021											
Notice to Proceed Date June 7, 2021 June 7, 2021											
Work Began Date											

Contract Total Pay For Estimate No. 10

		This Estimate	Previous	To Date
210416-D07				
	Total Posted Items Pay	\$0.00	\$2,372,246.34	\$2,372,246.34
	Gross Item Adjustments	\$890.40	\$122.36	\$1,012.76
	Incentive	\$0.00	\$200,000.00	\$200,000.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			<mark>\$2,572,368.70</mark>	\$2,573,259.10
Contract Total Pay	able This Estimate:	\$890.40		

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

Line item	Aujusi	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5I3366	0060	MISC.	Other Item Adjustment	Fuel Price	Fuel Adjustment for the Optional Pavement Item 0060 which is 3297.80 SY this work was completed in September 2021			\$356.16
	0060	MISC.	Other Item Adjustment	Fuel Price	Fuel Adjustment for the Optional Pavement Item 0060 which is 3297.80 SY this work was completed in August 2021			\$534.24
Total								\$890.40



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J5I3366	l 70-3(267)	Bridge rehabilitation	I-70	BOONE	over Perche Creek						
Totals by Job Numbers											
J5I3366	366 Posted Item Pay Gross Item Adjustments Gross Item Pay				This Estimate \$0.00 \$890.40 \$890.40	Previous \$2,372,246.34 \$122.36 \$2,372,368.70	To Date \$2,372,246.34 \$1,012.76 \$2,373,259.10				
	Liquid	tive centive lated Damages Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$200,000.00 \$0.00 \$0.00 \$0.00 \$0.00	\$200,000.00 \$0.00 \$0.00 \$0.00 \$0.00				



Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract	Project	and Valu Category	Line	Item	Report Generated date and can differ from the posted am Description	Bid	Net	Total	IS Gene Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
210416-D07	J5I3366	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$120,100.00	\$120,100.00
		0001	0020	2072000	LINEAR GRADING CLASS 2	77.60	0.00	77.60	STA	77.60	\$900.00	\$69,840.00
		0001	0030	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	78.00	0.00	78.00	100F	78.00	\$140.00	\$10,920.00
		0001	0040	2153000	SHAPING SLOPES, CLASS III	8.00	0.00	8.00	100F	8.00	\$1,399.69	\$11,197.52
		0001	0050	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	6,595.60	-4,216.80	2,378.80	SQYD	2,378.80	\$16.50	\$39,250.20
		0001	0060	4019905	MISC.Optional Shoulder 9 1/2" Asphalt or 8" PCCP	6,595.60	0.00	6,595.60	SQYD	6,595.60	\$92.00	\$606,795.20
		0001	0070	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	4.40	0.00	4.40	CUYD	4.40	\$44.00	\$193.60
		0001	0080	6096042	PLACING TYPE 2 ROCK DITCH LINER	4.40	0.00	4.40	CUYD	4.40	\$17.00	\$74.80
		0001	0090	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	1.00	0.00	1.00	EA	1.00	\$4,290.29	\$4,290.29
		0001	0100	6122020	REPLACEMENT SAND BARREL	2.00	0.00	2.00	EA	2.00	\$474.28	\$948.56
		0001	0110	6122030		3.00	0.00	3.00	EA	3.00	\$787.19	\$2,361.57
		0001	0120	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0001	0130	6161005		1,172.00	0.00	1,172.00	SQFT	1,172.00	\$8.72	\$10,219.84
		0001	0140	6161008	ADVANCED WARNING RAIL SYSTEM	3.00	0.00	3.00	EA	3.00	\$38.16	\$114.48
		0001	0150	6161010	RELOCATED SIGNS	734.00	0.00	734.00	SQFT	734.00	\$7.63	\$5,600.42
		0001	0160	6161025		44.00	0.00	44.00	EA	44.00	\$23.99	\$1,055.56
		0001	0170	6161030		44.00	0.00	44.00	EA	44.00	\$114.48	\$5,037.12
		0001	0180	6161033	DIRECTIONAL INDICATOR BARRICADE	15.00	0.00	15.00	EA	15.00	\$81.77	\$1,226.55
		0001	0190	6161040		2.00	0.00	2.00	EA	2.00	\$926.75	\$1,853.50
		0001	0200	6161055	SEQUENTIAL FLASHING WARNING LIGHT	15.00	0.00	15.00	EA	15.00	\$103.58	\$1,553.70
		0001	0210	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	5.00	0.00	5.00	EA	5.00	\$3,488.93	\$17,444.65
		0001	0220	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	4.00	\$926.75	\$3,707.00
		0001	0230	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	-4.00	0.00	EA	0.00	\$2,398.64	\$0.00
		0001	0240	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	1.00	\$59,965.92	\$59,965.92
		0001	0250	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	1,824.40	0.00	1,824.40	LF	1,824.40	\$36.69	\$66,937.24
		0001	0260	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	1,824.40	0.00	1,824.40	LF	1,824.40	\$13.74	\$25,067.26
		0001	0270	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$242,065.00	\$242,065.00
		0001	0280	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,564.00	0.00	7,564.00	LF	7,564.00	\$0.76	\$5,748.64
		0001	0290	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	4,446.00	0.00	4,446.00	LF	4,446.00	\$0.76	\$3,378.96
		0001	0300	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	20,666.00	0.00	20,666.00	LF	20,666.00	\$0.76	\$15,706.16
		0001	0310	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	20,666.00	0.00	20,666.00	LF	20,666.00	\$0.76	\$15,706.16
		0001	0320	6207001	PAVEMENT MARKING REMOVAL	53,426.00	0.00	53,426.00	LF	53,426.00	\$0.76	\$40,603.76
		0001	0330	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	19.60	0.00	19.60	SQYD	19.60	\$2.00	\$39.20
		0001	0340	6269909	MISC.OPTIONAL SHOULDER RUMBLE STRIPS	77.60	0.00	77.60	STA	77.60	\$250.00	\$19,400.00
		0001	0350	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.00
		0001	0360	8051000A	SEEDING - COOL SEASON MIXTURES	0.90	-0.90	0.00	ACRE	0.00	\$3,270.87	\$0.00
		0001	0370	8061004	SEDIMENT TRAP ROCK	4.40	-4.40	0.00	CUYD	0.00	\$98.13	\$0.00
		0001	0380	8061005	ROCK DITCH CHECK	3,936.00	-3,936.00	0.00	LF	0.00	\$10.90	\$0.00
		0001	0390	8061016	SEDIMENT REMOVAL	587.00	-587.00	0.00	CUYD	0.00	\$20.00	\$0.00
		0001	0400	8061019	SILT FENCE	9,044.00	-9,044.00	0.00	LF	0.00	\$2.45	\$0.00
		0001	0410	8061050	TYPE C BERM	137.00	-137.00	0.00	LF	0.00	\$40.00	\$0.00
		0010	0420	6061060	MGS GUARDRAIL	975.00	0.00	975.00	LF	975.00	\$26.17	\$25,515.75
		0010	0430	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	2.00	\$3,375.34	\$6,750.68
		0010	0440	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	2.00	\$2,901.38	\$5,802.76

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

be: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0416-D07	J5I3366	0070	0450	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	114.00	0.00	114.00	LF	114.00	\$460.00	\$52,440.00
		0070	0460	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	76.00	0.00	76.00	LF	76.00	\$10.00	\$760.00
		0070	0470	2169902	MISC.REMOVE AND REPLACE EXISTING DIAPHRAGM CONNECTION ANGLE	7.00	0.00	7.00	EA	7.00	\$1,200.00	\$8,400.00
		0070	0480	2169903	MISC.REMOVE AND REPLACE BARRIER	87.00	0.00	87.00	LF	87.00	\$325.00	\$28,275.00
		0070	0490	7034214	CLASS B-2 CONCRETE	48.80	0.00	48.80	CUYD	48.80	\$2,020.00	\$98,576.0
		0070	0500	7040101	SUBSTRUCTURE REPAIR (FORMED)	470.00	825.00	1,295.00	SQFT	1,295.00	\$125.00	\$161,875.0
		0070	0510	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	335.00	-332.00	3.00	SQFT	3.00	\$160.00	\$480.00
		0070	0520	7040164	FIBER REINFORCED POLYMER WRAP	196.00	0.00	196.00	SF	196.00	\$57.00	\$11,172.00
		0070	0530	7061070	MECHANICAL BAR SPLICE	149.00	0.00	149.00	EA	149.00	\$45.00	\$6,705.00
		0070	0540	7101000	REINFORCING STEEL (EPOXY COATED)	9,080.00	0.00	9,080.00	LB	9,080.00	\$3.20	\$29,056.00
		0070	0550	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$19,625.21	\$19,625.27
		0070	0560	7123130	REHABILITATE BEARING	1.00	0.00	1.00	EA	1.00	\$5,200.00	\$5,200.0
		0070 0570 7129902 MISC.REPLACE MISSING E			MISC.REPLACE MISSING BOLTS IN DIAPHRAGM CONNECTION ANGLE	8.00	21.00	29.00	EA	29.00	\$120.00	\$3,480.0
	0070 0580 7172001 STRIP SEAL EXPANS			7172001	STRIP SEAL EXPANSION JOINT SYSTEM	114.00	0.00	114.00	LF	114.00	\$535.00	\$60,990.0
		0070	0590	7172054	OPEN CELL FOAM JOINT SEAL	76.00	0.00	76.00	LF	76.00	\$33.00	\$2,508.0
		0071	0600	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	158.00	0.00	158.00	LF	158.00	\$450.00	\$71,100.0
		0071	0610	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	40.00	0.00	40.00	LF	40.00	\$12.00	\$480.0
		0071	0620	2169902	MISC.REMOVE EXISTING END DIAPHRAGM	1.00	0.00	1.00	EA	1.00	\$250.00	\$250.0
		0071	0630	2169903	MISC.REMOVE AND REPLACE BARRIER	29.00	0.00	29.00	LF	29.00	\$1,110.00	\$32,190.0
		0071	0640	7034214	CLASS B-2 CONCRETE	21.90	0.00	21.90	CUYD	21.90	\$4,800.00	\$105,120.0
		0071	0650	7040101	SUBSTRUCTURE REPAIR (FORMED)	125.00	502.00	627.00	SQFT	627.00	\$135.00	\$84,645.0
		0071	0660	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	165.00	-134.00	31.00	SQFT	31.00	\$170.00	\$5,270.0
		0071	0670	7061070	MECHANICAL BAR SPLICE	60.00	0.00	60.00	EA	60.00	\$45.00	\$2,700.0
		0071	0680	7101000	REINFORCING STEEL (EPOXY COATED)	3,820.00	0.00	3,820.00	LB	3,820.00	\$3.30	\$12,606.0
		0071	0690	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$22,896.08	\$22,896.0
		0071	0700	7121000	FABRICATED STRUCTURAL CARBON STEEL (MISC)	170.00	0.00	170.00	LB	170.00	\$12.50	\$2,125.0
		0071	0710	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	158.00	0.00	158.00	LF	158.00	\$535.00	\$84,530.0
		0071	0720	7172054	OPEN CELL FOAM JOINT SEAL	40.00	0.00	40.00	LF	40.00	\$33.00	\$1,320.0
	Project .	J5I3366 - To	otal Value	e Posted to I	Date as of Report Generated Date							\$2,372,246.3
0416-D07 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Re	port Generated Date							\$2,372,246.3



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable). No Data Available



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks																				
Project	LINE	Description	Туре	Adjustment Type	Number	Date	By	Amount	I VEITIGI KS																				
J5I3366	0030	SUBGRADE COMPACTION (6- INCH DEPTH)	Material		2	Sep 1, 2021	SYSTEM	\$5,432.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
					2	Sep 1, 2021	SYSTEM	(\$5,432.00)																					
					3	Sep 16, 2021	SYSTEM	\$7,560.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user metzd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
					3	Sep 15, 2021	SYSTEM	(\$7,560.00)																					
					4	Sep 30, 2021	SYSTEM	\$10,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
					4	Sep 30, 2021	SYSTEM	(\$10,780.00)																					
					5	Oct 15, 2021	SYSTEM	\$10,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user woods6 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
					5	Oct 14, 2021	SYSTEM	(\$10,780.00)																					
					6	Nov 1, 2021	SYSTEM	\$10,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user metzd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
					6	Nov 1, 2021	SYSTEM	(\$10,780.00)																					
					7	Nov 16, 2021	SYSTEM	\$10,780.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user metzd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
					7	Nov 16, 2021	SYSTEM	(\$10,780.00)																					
					8	Dec 2, 2021	SYSTEM	\$10,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user metzd1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																				
					8	Dec 2, 2021	SYSTEM	(\$10,920.00)																					
						9	Feb 15, 2022	SYSTEM	\$10,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ackert1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																			
					9	Feb 15, 2022	SYSTEM	(\$10,920.00)																					
				- Total				\$0.00																					
			Material - To	otal				\$0.00																					
	0030 -	Total						\$0.00																					
	0050	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		2	Sep 1, 2021	SYSTEM	\$54,412.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 2 on the current Payment Estimate.																				
					2	Sep 1, 2021	SYSTEM	(\$54,412.05)																					
											3	Sep 16, 2021	SYSTEM	\$54,412.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user metzd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.														
													3	Sep 15, 2021	SYSTEM	(\$54,412.05)													
																											4	Sep 30, 2021	SYSTEM
					4	Sep 30, 2021	SYSTEM	(\$54,412.05)																					
					Ę			5	Oct 15, 2021	SYSTEM	\$54,412.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user woods6 overridding Payment Estimate Exception 11 on the current Payment Estimate.																	
					5	Oct 14, 2021	SYSTEM	(\$54,412.05)																					
					6	Nov 1, 2021	SYSTEM	\$54,412.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user metzd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.																				



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks	
			Туре	Adjustment Type	Number	Date	Ву			
J5I3366	0050	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		6	Nov 1, 2021	SYSTEM	(\$54,412.05)		
		THICK)			7	Nov 16, 2021	SYSTEM	\$54,412.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user metzd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					7	Nov 16, 2021	SYSTEM	(\$54,412.05)		
					8	Dec 2, 2021	SYSTEM	\$54,412.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user metzd1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					8	Dec 2, 2021	SYSTEM	(\$54,412.05)		
				- Total				\$0.00		
			Material - T	otal				\$0.00		
			Price FUEL		2	Sep 1, 2021	SYSTEM	\$204.79	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
					9	Feb 15, 2022	SYSTEM	(\$82.43)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL	
				- Total				\$122.36		
			Price FUEL	- Total				\$122.36		
	0050 -	Total						\$122.36		
	0060	MISC.	Material		2	Sep 1, 2021	SYSTEM	\$303,388.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
				2	Sep 1, 2021	SYSTEM	(\$303,388.40)			
					3	Sep 16, 2021	SYSTEM	\$365,534.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user metzd1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					3	Sep 15, 2021	SYSTEM	(\$365,534.40)		
						4	Sep 30, 2021	SYSTEM	\$546,112.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woods6 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$546,112.00)		
					5	Oct 15, 2021	SYSTEM	\$546,112.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user woods6 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					5	Oct 14, 2021	SYSTEM	(\$546,112.00)		
					6	Nov 1, 2021	SYSTEM	\$546,112.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user metzd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					6	Nov 1, 2021	SYSTEM	(\$546,112.00)		
					7	Nov 16, 2021	SYSTEM	\$399,793.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user metzd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					7	Nov 16, 2021	SYSTEM	(\$399,793.18)		
					8	Dec 2, 2021	SYSTEM	\$234,191.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user metzd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					8	Dec 2, 2021	SYSTEM	(\$234,191.52)		
					9	Feb 15, 2022	SYSTEM	\$192,791.06	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ackert1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					9	Feb 15, 2022	SYSTEM	(\$192,791.06)		
				- Total				\$0.00		
			Material - T	otal				\$0.00		
			Other Item	FUEL	10	Mar 1,	ackert1	\$534.24	Fuel Adjustment for the Optional Pavement Item 0060 which is 3297.80 SY	



J513366 0060 MISC. Adjustment FUEL 2022 0 this work was completed in August 2021 Image: Home Provide the strength of the strengen of the strength of the strengen of the strengt of	
2022 this work was completed in September 2021 FUEL - Total \$890.40	
	0060 which is 3297.80 SY
Other Item Adjustment - Total \$890.40	
0060 - Total \$890.40	
0070FURN. TYPE 2 ROCK DITCH LINERMaterial7Nov 16, 2021SYSTEM\$193.60This adjustment offsets the original system-general Estimate Item Adjustment (0018) due to user met Estimate Exception 17 on the current Payment estimate	zd1 overridding Payment
7 Nov 16, SYSTEM (\$193.60) 2021	
8 Dec 2, 2021 SYSTEM \$193.60 This adjustment offsets the original system-gener Estimate Item Adjustment (0022) due to user met Estimate Exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate Exception 17 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Es	zd1 overridding Payment
8 Dec 2, 2021 SYSTEM (\$193.60)	
- Total \$0.00	
Material - Total \$0.00	
0070 - Total \$0.00	
0130CONSTRUCTION SIGNSMaterial1Aug 17, 2021SYSTEM 2021\$2,453.28This adjustment offsets the original system-generic Estimate Item Adjustment (0002) due to user met Estimate Exception 1 on the current Payment Estimate	zd1 overridding Payment
1 Aug 17, SYSTEM (\$2,453.28) 2021	
- Total \$0.00	
Material - Total \$0.00	
0130 - Total \$0.00	
0160CHANNELIZER (TRIM LINE)Material1Aug 17, 2021SYSTEM\$1,055.56This adjustment offsets the original system-genere Estimate tem Adjustment (0003) due to user met 	zd1 overridding Payment
1 Aug 17, SYSTEM (\$1,055.56)	
- Total \$0.00	
Material - Total \$0.00	
0160 - Total \$0.00	
0180 DIRECTIONAL INDICATOR BARRICADE Material 1 Aug 17, 2021 SYSTEM \$1,063.01 This adjustment offsets the original system-generative Estimate Item Adjustment (0004) due to user met Estimate Exception 3 on the current Payment Estimate	zd1 overridding Payment
1 Aug 17, SYSTEM (\$1,063.01) 2021	
- Total \$0.00	
Material - Total \$0.00	
0180 - Total \$0.00	
0190 FLASHING Material 1 Aug 17, 2021 SYSTEM \$926.75 This adjustment offsets the original system-gener Estimate Item Adjustment (0005) due to user met Estimate Exception 4 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate E	zd1 overridding Payment
1 Aug 17, SYSTEM (\$926.75) 2021	
- Total \$0.00	
Material - Total \$0.00	
0190 - Total \$0.00	
0200 SEQUENTIAL FLASHING WARNING LIGHT Material 1 Aug 17, 2021 SYSTEM \$1,346.54 This adjustment offsets the original system-gener Estimate Item Adjustment (0006) due to user met Estimate Exception 5 on the current Payment Est	zd1 overridding Payment
1 Aug 17, 2021 SYSTEM (\$1,346.54)	
- Total \$0.00	
Material - Total \$0.00	
0200 - Total \$0.00	



Mar 4, 2022

Image: state in the control in the	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks							
COMUNECATOR Part of the standard st																	
Image: state in the s	J5I3366	0210	COMMUNICATION INTERFACE,	Material		1		SYSTEM	\$6,977.86	Estimate Item Adjustment (0007) due to user metzd1 overridding Payment							
Value Value Value Value Value 020 Value 4 Sep 30, SYSTEM S22.40 The adjustment officits the original system-percented Material Payment Estimate Lengton 8 in the carsen Payment Estimate Lengton 8 in the carsen Payment Estimate Lengton 8 in the carsen Payment Estimate Payment Estimate Payment Research 100 in 200 in			CONT			1		SYSTEM	(\$6,977.86)								
C210 C310 C310 <thc310< th=""> C310 C310 <th< td=""><td></td><td></td><td></td><td></td><td>- Total</td><td></td><td></td><td></td><td>\$0.00</td><td></td></th<></thc310<>					- Total				\$0.00								
6280 NUTERIONE NUTERIN				Material - T	otal				\$0.00								
Number Number Notice Notice Number Number 0201 0201 0201 0201 02000		0210 -	Total						\$0.00								
Construct System System <thsystem< th=""> <thsystem< th=""> System</thsystem<></thsystem<>		0280	BUILD WATERBORNE	Material		4		SYSTEM	\$2,824.01	Estimate Item Adjustment (0017) due to user woods6 overridding Payment							
data relation Material Total 60.00 0260 Total 50.00 0260 N FLELOW NGTEBORRE PANT Material Total 50.01 This adjustment officies the original system-generated Material Payment Ethnicis Even full (010) due to user woods overididing Payment Ethnicis Even full (010) due to user woods overididing Payment Ethnicis Even full (010) due to user woods overididing Payment Ethnicis Even full (010) due to user woods overididing Payment Ethnicis Even full (010) due to user woods overididing Payment Ethnicis Even full (010) due to user woods overididing Payment Ethnic Even full (010) due to user woods ov			PAINT			4		SYSTEM	(\$2,824.01)								
0280 Total File 0290 Material Material 4 269 Sep 30, 2VSTEM 5VSTEM 5VS81.83 The adjustment official bytem-generated Material Payment Estimate. 0290 Val					- Total				\$0.00								
B280 6 N. VELADV NUTERBORNE PAINT Material (1) + EULD PAINT Material (2) 4 99:02 (2) SYSTEM \$1,83.13 (2) Ethic adjustment official system represented Material Payment Estimate Exception 20 on the ourrent Payment Estimate. 0 - Total - Total </td <td></td> <td></td> <td></td> <td>Material - T</td> <td>otal</td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td>				Material - T	otal				\$0.00								
Hich Bulling Hick Bulling Pail 2021 System Estimate Exception 20 on the current Payment Estimate. 0 - Total - Soss - Soss - Soss - Soss 0 - Total - Soss - Soss - Soss - Soss 0 - Total - Soss - Soss - Soss - Soss - Soss 0 - Total - Soss - Sosss - Soss - Soss <td></td> <td>0280 -</td> <td>Total</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td>		0280 -	Total						\$0.00								
Autorial - Total Sep 30 SYSTEM (S1.881.56) 0000 -Total -Sep 30 SYSTEM (S1.881.56) 0200 - Total -Sep 30 SYSTEM S0.00 0200 - Total -Sep 30 SYSTEM S7.837.04 Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 0200 - Votal -Sep 30 SYSTEM (S7.837.04) Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 0200 - Total -Cotal Sep 30 SYSTEM (S7.837.04) Estimate Exception 2 on the current Payment Estimate. 0310 - Total -Total -Sep 30 SYSTEM (S7.837.04) Estimate Exception 2 on the current Payment Estimate. 0310 - Total -Total -Sep 30. SYSTEM (S7.837.04) Estimate Exception 2 on the current Payment Estimate. 0310 - Total -Total -Sep 30. SYSTEM (S7.837.04) Estimate Exception 2 on the current Payment Estimate. 0310 - Total -Total -Sep 30. SYSTEM (S7.837.04) Estimate Exception 2 on the current Payment Estimate.		0290	HIGH BUILD WATERBORNE	Material		4		SYSTEM	\$1,681.36	Estimate Item Adjustment (0018) due to user woods6 overridding Payment							
Image: control in the indication of the inding and indication of the indication of the indication			PAINT			4		SYSTEM	(\$1,681.36)								
O230 - Total View Hurter Material Material System S7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 0330 V AI N. WHITE WATERBORNE PAVEMENT Material 2 Sep 1, 2021 SYSTEM S7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 8 on the current Payment Estimate. 04 Sep 30, 2021 SYSTEM S7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 0310 View Payment Estimate Sep 30, 2021 SYSTEM (\$7,837.04) This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 0310 View Payment					- Total				\$0.00								
0300 4.IN.WHITE WATERBORNE PATEMENT Material MARKING 2 Sep 1, 2021 SYSTEM \$7.837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 0300 AMARKING 4 Sep 30, 2021 SYSTEM (\$7.837.04) This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 0300 - Total Sep 30, 2021 SYSTEM (\$7.837.04) This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate. 0310 - Total - Total Sep 30, 2021 SYSTEM \$7.837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate. 0310 4 MARKING PAYENENY MARKING Material Z Sep 30, 2021 SYSTEM \$7.837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 0310 4 MARKING PAYENENY MARKING Material Sep 30, 2021 SYSTEM \$7.837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 0310				Material - T	otal				\$0.00								
WATERBORNE PAVEMENT WATERBORNE PAVEMENT East and betware them Adjustment (0005) due to user woods0 overiding Payment Estimate Exception 8 on the current Payment Estimate. 2 Sep 1, 2021 SYSTEM \$(7,837.04) 2 Sep 30, 2021 \$YSTEM \$(7,837.04) 4 Sep 30, 2021 \$YSTEM \$(7,837.04) 0 International system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 0 International System \$(7,837.04) 0 International System System \$(7,837.04) 0 International System-generated Material Payment 2		0290 -	Total						\$0.00								
 		0300	WATERBORNE PAVEMENT	BORNE /EMENT		2		SYSTEM	\$7,837.04	Estimate Item Adjustment (0005) due to user woods6 overridding Payment							
$ \begin{array}{ c c c } \hline \\ \hline $													2		SYSTEM	(\$7,837.04)	
O300 - Total Control Street Street 0300 - Total - Total - S0.00 0300 - Total - S0.00 0300 - Total - S0.00 0310 4 IN. YELLOW, WATERBORNE PAARKING Material - Zolz - S0.01 0310 VATERBORNE PAARKING 2 Sep 1, 2021 SYSEM \$7.837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 2 Sep 1, 2021 SYSEM \$7.837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 2 Sep 30, 2021 SYSTEM \$7.837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 0 - Total Sep 30, 2021 SYSTEM \$7.837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 0 - Total Sep 30, 2021 SYSTEM \$7.837.04 This adjustment (0020) due to user woods6 overridding Payment Estimate Exception 23 on the current Payment Estimate. 0310 - Total Sep 30, 2021 SYSTEM \$39.20						4		SYSTEM	\$7,837.04	Estimate Item Adjustment (0019) due to user woods6 overridding Payment							
Material - Total \$0.00 0300 - Total \$0.00 0310 WATERSONE WATERSONE PAVEMENT MARKING Material - Total \$2 \$20,1 \$27,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 2 \$20,1 \$27,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 4 \$20,21 \$20,21 \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. - Total \$20,201 \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. - Total \$20,201 \$7,837.04 \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 0310 - Total \$7,000 \$7,837.04 \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 0310 - Total \$0,000 \$7,837.04 \$3,000 \$1,000 \$2,000 \$2,000 \$2,000 \$1,000 \$2,000 \$2,000								SYSTEM	(\$7,837.04)								
0300 - Total 93.00 0310 4 IN, YELLOW WATERBORNE MARKING Material 2 Sep 1, 2021 SYSTEM \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Item Adjustment (0000) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Item Adjustment (0020) due to user woods6 overridding Payment Estimate Exception 23 on the current Payment Estimate. 0310 - Total 50.00 0310 - ERMANENT ESTIMATE Material 0320 PERMANENT ESTIMATE 7 Nov 16, 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 0330 PERMANENT ESTIMATE 7 Nov 16, 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estim					- Total				\$0.00								
0310 4 IN. YELLOW WATERBORNE MARKING Material 2 Sep 1, 2021 SYSTEM \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 2 Sep 1, 2021 SYSTEM \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 10 on the current Payment Estimate. 4 Sep 30, 2021 SYSTEM \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate. 4 Sep 30, 2021 SYSTEM \$7,837.04 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 0 - total - total - total - total - total 0 - total - total - total - total - total 0310 - Total - total - total - total - total - total 0330 PERMANENC CONTROL GEOTEXTILE Material 7 Nov 16, 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 6 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate.				Material - T	otal				\$0.00								
WATERBORNE WARKING WARKING image: ware ware ware ware ware ware ware ware		0300 -	Total						\$0.00								
0330 PERMANENT EROSION GEOTEXTILE Material		0310	WATERBORNE PAVEMENT	Material		2		SYSTEM	\$7,837.04	Estimate Item Adjustment (0006) due to user woods6 overridding Payment							
$ \begin{array}{ c c c c c } \hline \\ \hline $			MARKING			2		SYSTEM	(\$7,837.04)								
O310 - Total PERMANENT EROSION CONTROL GEOTEXTILE Material 7 Nov 16, 2021 SYSTEM 2021 \$39.20 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0019) due to user metzd1 overridding Payment Estimate tem Adjustment (0019) due to user metzd1 overridding Payment Estimate tem Adjustment (0019) due to user metzd1 overridding Payment Estimate tem Adjustment (0019) due to user metzd1 overridding Payment Estimate tem Adjustment (0019) due to user metzd1 overridding Payment Estimate tem Adjustment (0019) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment Estimate tem Adjustment (0023) due to user metzd1 overridding Payment						4		SYSTEM	\$7,837.04	Estimate Item Adjustment (0020) due to user woods6 overridding Payment							
Material - Total \$0.00 O310 - Total \$0.00 O330 PERMANENT EROSION GEOTEXTILE Material EROSION GEOTEXTILE 7 Nov 16, 2021 SYSTEM 2021 \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user metzd1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 7 Nov 16, 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user metzd1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Dec 2, 2021 SYSTEM \$39.20 8 Dec 2, 2021 SYSTEM \$39.20						4		SYSTEM	(\$7,837.04)								
0310 - Total \$0.00 0330 PERMANENT EROSION CONTROL GEOTEXTILE Material 7 Nov 16, 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 7 Nov 16, 2021 SYSTEM (\$39.20) 8 Dec 2, 2021 SYSTEM \$39.20					- Total				\$0.00								
0330 PERMANENT EROSION CONTROL GEOTEXTILE Material 7 Nov 16, 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user metzd1 overridding Payment 7 Nov 16, 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Exception 18 on the current Payment Estimate. 8 Dec 2, 2021 SYSTEM \$39.20 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user metzd1 overridding Payment Estimate Item Adjustment (0023) due to user metzd1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Dec 2, 2021 SYSTEM \$39.20				Material - T	otal				\$0.00								
EROSION CONTROL GEOTEXTILE 2021 Estimate Item Adjustment (0019) due to user metzd1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 7 Nov 16, 2021 SYSTEM (\$39.20) 8 Dec 2, 2021 SYSTEM \$39.20 8 Dec 2, 2021 SYSTEM \$39.20 8 Dec 2, 2021 SYSTEM \$39.20		0310 -	Total						\$0.00								
7 Nov 16, 2021 SYSTEM (\$39.20) 8 Dec 2, 2021 SYSTEM \$39.20 10 Dec 2, 2021 SYSTEM \$39.20		0330	EROSION CONTROL	Material		7		SYSTEM	\$39.20	Estimate Item Adjustment (0019) due to user metzd1 overridding Payment							
2021 Estimate Item Adjustment (0023) due to user metzd1 overridding Payment Estimate Exception 18 on the current Payment Estimate. 8 Dec 2, 2021 (\$39.20)			GEUTEXTILE			7		SYSTEM	(\$39.20)								
2021						8		SYSTEM	\$39.20	Estimate Item Adjustment (0023) due to user metzd1 overridding Payment							
- Total \$0.00						8		SYSTEM	(\$39.20)								
					- Total				\$0.00								



Mar 4, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3366	0330	PERMANENT EROSION CONTROL GEOTEXTILE	Material - To	otal				\$0.00	
	0330 -							\$0.00	
	0420	MGS GUARDRAIL	Material		3	Sep 16, 2021	SYSTEM	\$10,468.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user metzd1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Sep 15, 2021	SYSTEM	(\$10,468.00)	
					4	Sep 30, 2021	SYSTEM	\$25,515.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woods6 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$25,515.75)	
					5	Oct 15, 2021	SYSTEM	\$25,515.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woods6 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$25,515.75)	
					6	Nov 1, 2021	SYSTEM	\$25,515.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user metzd1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$25,515.75)	
					7	Nov 16, 2021	SYSTEM	\$25,515.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user metzd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$25,515.75)	
					8	Dec 2, 2021	SYSTEM	\$25,515.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user metzd1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$25,515.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0420 -							\$0.00	
	0430	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Material	al	3	Sep 16, 2021	SYSTEM	\$3,375.34	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user metzd1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	Sep 15, 2021	SYSTEM	(\$3,375.34)	
					4	Sep 30, 2021	SYSTEM	\$6,750.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$6,750.68)	
					5	Oct 15, 2021	SYSTEM	\$6,750.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woods6 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$6,750.68)	
					6	Nov 1, 2021	SYSTEM	\$6,750.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user metzd1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$6,750.68)	
					7	Nov 16, 2021	SYSTEM	\$6,750.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user metzd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$6,750.68)	
					8	Dec 2, 2021	SYSTEM	\$6,750.68	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user metzd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.



Mar 4, 2022

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
66	0430	MGS BRIDGE APP. TRANS SEC	Material	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	8	Dec 2, 2021	SYSTEM	(\$6,750.68)	
		(REG/NO CURB)		- Total				\$0.00	
			Material - To	otal				\$0.00	
	0430 -	Total						\$0.00	
	0440	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		3	Sep 16, 2021	SYSTEM	\$2,901.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user metzd1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	Sep 15, 2021	SYSTEM	(\$2,901.38)	
					4	Sep 30, 2021	SYSTEM	\$5,802.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Paymen Estimate Exception 17 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$5,802.76)	
					5	Oct 15, 2021	SYSTEM	\$5,802.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woods6 overridding Paymen Estimate Exception 18 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$5,802.76)	
					6	Nov 1, 2021	SYSTEM	\$5,802.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user metzd1 overridding Paymen Estimate Exception 18 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$5,802.76)	
					7	Nov 16, 2021	SYSTEM	\$5,802.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user metzd1 overridding Paymer Estimate Exception 16 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$5,802.76)	
					8	Dec 2, 2021	SYSTEM	\$5,802.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user metzd1 overridding Paymen Estimate Exception 16 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$5,802.76)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0440 -	Total						\$0.00	
	0470	MISC. REMOVALS	Material		5	Oct 15, 2021	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Paymer Estimate Exception 2 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$8,400.00)	
					6	Nov 1, 2021	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user metzd1 overridding Paymer Estimate Exception 2 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$8,400.00)	
					7	Nov 16, 2021	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user metzd1 overridding Paymer Estimate Exception 2 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$8,400.00)	
					8	Dec 2, 2021	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user metzd1 overridding Paymer Estimate Exception 2 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$8,400.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0470 -	Total						\$0.00	
	0480	MISC. REMOVALS	Material		4	Sep 30, 2021	SYSTEM	\$14,137.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woods6 overridding Paymen Estimate Exception 2 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3366	0480	MISC. REMOVALS	Material		4	Sep 30, 2021	SYSTEM	(\$14,137.50)	
					5	Oct 15, 2021	SYSTEM	\$28,275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$28,275.00)	
					6	Nov 1, 2021	SYSTEM	\$28,275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user metzd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$28,275.00)	
					7	Nov 16, 2021	SYSTEM	\$28,275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user metzd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$28,275.00)	
					8	Dec 2, 2021	SYSTEM	\$28,275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user metzd1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$28,275.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0480 -	Total						\$0.00	
	0490	CLASS B-2 CONCRETE	Material		4	Sep 30, 2021	SYSTEM	\$64,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woods6 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$64,640.00)	
					5	Oct 15, 2021	SYSTEM	\$98,576.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$98,576.00)	
					6	Nov 1, 2021	SYSTEM	\$98,576.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user metzd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$98,576.00)	
					7	Nov 16, 2021	SYSTEM	\$98,576.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user metzd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$98,576.00)	
					8	Dec 2, 2021	SYSTEM	\$98,576.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user metzd1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$98,576.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0490 -							\$0.00	
	0500	SUBSTRUCTURE REPAIR (FORMED)	Material		1	Aug 17, 2021	SYSTEM	\$13,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user metzd1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					1	Aug 17, 2021	SYSTEM	(\$13,750.00)	
					2	Sep 1, 2021	SYSTEM	\$13,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					2	Sep 1, 2021	SYSTEM	(\$13,750.00)	
					3	Sep 16, 2021	SYSTEM	\$13,750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user metzd1 overridding Payment



Mar 4, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3366	0500	SUBSTRUCTURE	Material						Estimate Exception 22 on the current Payment Estimate.
		REPAIR (FORMED)			3	Sep 15, 2021	SYSTEM	(\$13,750.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0500 -	Total						\$0.00	
	0510	SUBSTRUCTURE REPAIR (UNFORMED)	Material		6	Nov 1, 2021	SYSTEM	\$53,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user metzd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
						Nov 1, 2021	SYSTEM	(\$53,600.00)	
					7	Nov 16, 2021	SYSTEM	\$53,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user metzd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$53,600.00)	
					8	Dec 2, 2021	SYSTEM	\$53,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user metzd1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$53,600.00)	
				- Total				\$0.00	
			Material - T					\$0.00	
	0510 -	Total						\$0.00	
	0520		Material		8	Dec 2, 2021	SYSTEM	\$11,172.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user metzd1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$11,172.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0520 -							\$0.00	
	0540	REINFORCING STEEL (EPOXY COATED)	Material		4	Sep 30, 2021	SYSTEM	\$19,177.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woods6 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$19,177.60)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0540 -	Total						\$0.00	
	0550	PROTECTIVE COATING - CONCRETE BENTS AND	Material		8	Dec 2, 2021	SYSTEM	\$19,625.21	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user metzd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
		DENTO AND			8	Dec 2, 2021	SYSTEM	(\$19,625.21)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0550 -	Total						\$0.00	
	0560	REHABILITATE BEARING	Material		5	Oct 15, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$5,200.00)	
					6	Nov 1, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user metzd1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$5,200.00)	
					7	Nov 16, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user metzd1 overridding Payment Estimate Exception 27 on the current Payment Estimate.



Mar 4, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
513366	0560	REHABILITATE BEARING	Material		7	Nov 16, 2021	SYSTEM	(\$5,200.00)	
					8	Dec 2, 2021	SYSTEM	\$5,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user metzd1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$5,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0560 -	Total						\$0.00	
	0580	STRIP SEAL EXPANSION JOINT SYSTEM			4	Sep 30, 2021	SYSTEM	\$40,253.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woods6 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$40,253.40)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0580 -	Total						\$0.00	
	0590	OPEN CELL FOAM JOINT SEAL	Material		4	Sep 30, 2021	SYSTEM	\$1,655.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$1,655.28)	
					5	Oct 15, 2021	SYSTEM	\$1,655.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$1,655.28)	
					6	Nov 1, 2021	SYSTEM	\$1,655.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user metzd1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$1,655.28)	
					7	Nov 16, 2021	SYSTEM	\$2,508.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user metzd1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$2,508.00)	
					8	Dec 2, 2021	SYSTEM	\$2,508.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user metzd1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$2,508.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0590 -	Total						\$0.00	
	0630	MISC. REMOVALS	Material		3	Sep 16, 2021	SYSTEM	\$16,095.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user metzd1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Sep 15, 2021	SYSTEM	(\$16,095.00)	
					4	Sep 30, 2021	SYSTEM	\$16,095.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woods6 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$16,095.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0630 -	Total						\$0.00	
	0640	CLASS B-2 CONCRETE	Material		2	Sep 1, 2021	SYSTEM	\$69,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woods6 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					2	Sep 1,	SYSTEM	(\$69,600.00)	•



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
Fillect	Line	Description	Туре	Adjustment Type		Date	By	Amount	Nendiks
J5I3366	0640	CLASS B-2 CONCRETE	Material			2021			
		CONTRACT			3	Sep 16, 2021	SYSTEM	\$105,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user metzd1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					3	Sep 15, 2021	SYSTEM	(\$105,120.00)	
					4	Sep 30, 2021	SYSTEM	\$105,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woods6 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$105,120.00)	
					5	Oct 15, 2021	SYSTEM	\$69,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woods6 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$69,600.00)	
					6	Nov 1, 2021	SYSTEM	\$69,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user metzd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$69,600.00)	
					7	Nov 16, 2021	SYSTEM	\$69,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user metzd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$69,600.00)	
					8	Dec 2, 2021	SYSTEM	\$69,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user metzd1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$69,600.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0640 -	Total						\$0.00	
	0650	SUBSTRUCTURE REPAIR (FORMED)	Material	terial	5	Oct 15, 2021	SYSTEM	\$8,437.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woods6 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$8,437.50)	
					8	Dec 2, 2021	SYSTEM	\$16,875.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user metzd1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$16,875.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0650 -	Total						\$0.00	
	0660	SUBSTRUCTURE REPAIR (UNFORMED)	Material		6	Nov 1, 2021	SYSTEM	\$28,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user metzd1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$28,050.00)	
					7	Nov 16, 2021	SYSTEM	\$28,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user metzd1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$28,050.00)	
					8	Dec 2, 2021	SYSTEM	\$28,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user metzd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$28,050.00)	
				- Total				\$0.00	
			Material - Te					\$0.00 \$0.00	



Mar 4, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3366	0660 -	Total						\$0.00	
	0680	REINFORCING STEEL (EPOXY COATED)	Material		2	Sep 1, 2021	SYSTEM	\$8,316.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woods6 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					2	Sep 1, 2021	SYSTEM	(\$8,316.00)	
					3	Sep 16, 2021	SYSTEM	\$12,606.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user metzd1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					3	Sep 15, 2021	SYSTEM	(\$12,606.00)	
					4	Sep 30, 2021	SYSTEM	\$12,606.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$12,606.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0680 -	Total						\$0.00	
	0690	PROTECTIVE COATING - CONCRETE BENTS AND	Material		8	Dec 2, 2021	SYSTEM	\$22,896.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user metzd1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
		DEIVIO AND			8	Dec 2, 2021	SYSTEM	(\$22,896.08)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0690 -	Total						\$0.00	
	0700	FAB. STRUCT. CARBON STEEL (MISC)	Material		5	Oct 15, 2021	SYSTEM	\$2,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$2,125.00)	
					6	Nov 1, 2021	SYSTEM	\$2,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user metzd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$2,125.00)	
					7	Nov 16, 2021	SYSTEM	\$2,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user metzd1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$2,125.00)	
					8	Dec 2, 2021	SYSTEM	\$2,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user metzd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$2,125.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0700 -	Total						\$0.00	
	0710	STRIP SEAL EXPANSION JOINT SYSTEM	Material		2	Sep 1, 2021	SYSTEM	\$55,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woods6 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					2	Sep 1, 2021	SYSTEM	(\$55,640.00)	
					3	Sep 16, 2021	SYSTEM	\$84,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user metzd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					3	Sep 15, 2021	SYSTEM	(\$84,530.00)	
					4	Sep 30, 2021	SYSTEM	\$84,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woods6 overridding Payment Estimate Exception 47 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3366	0710	STRIP SEAL EXPANSION	Material		4	Sep 30, 2021	SYSTEM	(\$84,530.00)	
		JOINT SYSTEM			5	Oct 15, 2021	SYSTEM	\$84,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user woods6 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$84,530.00)	
					6	Nov 1, 2021	SYSTEM	\$84,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user metzd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$84,530.00)	
					7	Nov 16, 2021	SYSTEM	\$84,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user metzd1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$84,530.00)	
					8	Dec 2, 2021	SYSTEM	\$84,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user metzd1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$84,530.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0710 -	Total						\$0.00	
	0720	OPEN CELL FOAM JOINT SEAL	Material		2	Sep 1, 2021	SYSTEM	\$858.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user woods6 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					2	Sep 1, 2021	SYSTEM	(\$858.00)	
					3	Sep 16, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user metzd1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					3	Sep 15, 2021	SYSTEM	(\$1,320.00)	
					4	Sep 30, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woods6 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					4	Sep 30, 2021	SYSTEM	(\$1,320.00)	
					5	Oct 15, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user woods6 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					5	Oct 14, 2021	SYSTEM	(\$1,320.00)	
					6	Nov 1, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user metzd1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					6	Nov 1, 2021	SYSTEM	(\$1,320.00)	
					7	Nov 16, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user metzd1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					7	Nov 16, 2021	SYSTEM	(\$1,320.00)	
					8	Dec 2, 2021	SYSTEM	\$1,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user metzd1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$1,320.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0720 -	Total						\$0.00	
J5I3366 -	Total							\$1,012.76	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Overall -	Total						\$1,012.76		