

Pay Estimate Created Date: November 3, 2021

Progress E	stimate lumber	Contract ID	210416-F02		Pay Period Start	October 16, 202	1 Original Contract Amou	nt \$12,888,486.49
8		Prime Contractor	Gershenson Constr Inc.	uction Co.,	Pay Period End	November 1, 2021	Net Change Order Amount Current Contract Amou	\$56,981.50 nt \$12,945,467.99
Approval Date								By User
November 3, 2021			Generated and	Approved (and should be cons	sidered Draft) at t	he Project Office Level by	Aubucj
November 3, 2021			Reviewed and App	roved (and s	should be considere	ed Draft) at the R	esident Engineer Level by	janssm
November 4, 2021				Reviewed	and Approved at the	e Central Office (Controllers Office Level by	ramses1
Original Completi	on Date	Current	Completion Date	Actu	al Completion Dat	e % (of Current Contract Amou	nt Complete
September 1, 2	2023	Septe	ember 1, 2023				8.73%	
	Contr	act Informational	Dates		Mileste	ones		
Date Description	Origi	nal Completion D	ate Current Compl	etion Date	No Milestones Ex	ist for Contract		
Acceptance Date								
Awarded Date	May 5	5, 2021	May 5, 2021					
Letting Date	April	16, 2021	April 16, 2021					
Notice to Proceed Dat	e July 6	6, 2021	July 6, 2021					
Work Began Date								

Contract Total Pay For Estimate No. 8				
	This Estimate	Previous	To Date	
210416-F02				
Total Posted Items Pay	<mark>\$82,325.58</mark>	\$1,047,877.16	\$1,130,202.74	
Gross Item Adjustments	\$0.00	\$0.00	\$0.00	
Incentive	\$0.00	\$0.00	\$0.00	
Disincentive	\$0.00	\$0.00	\$0.00	
Liquidated Damage	\$0.00	\$0.00	\$0.00	
Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
		<mark>\$1,047,877.16</mark>	\$1,130,202.74	
Contract Total Payable This Estimate:	\$82,325.58			

Contract Total Payable This Estimate:

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S3048	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$7.000	1,098.9	\$7,692.30
	0180	6081012	TRUNCATED DOMES	SQFT	\$22.230	20	\$444.60
	0200	6085008	PAVED APPROACH, 8 IN.	SQYD	\$61.480	194.6	\$11,964.01
	0210	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$38.800	603.8	\$23,427.44
	0220	6086007	CONCRETE SIDEWALK, 7 IN.	SQYD	\$55.620	32	\$1,779.84
	0230	6089902	MISC.CONCRETE CURB RAMP	EA	\$1,400.000	1	\$1,400.00
	0270	6089905	MISC.CONCRETE SIDEWALK, 4 IN., CORAL COLOR	SQYD	\$45.270	184.9	\$8,370.42
	0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$31.970	62	\$1,982.14
	0310	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	LF	\$20.780	27	\$561.00
	1360	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	LF	\$25.000	431	\$10,775.00
	1430	9028810	PULL BOX, PREFORMED CLASS 1	EA	\$1,000.000	1	\$1,000.0
	1460	9029100	BASE, CONCRETE	CUYD	\$1,350.000	3.08	\$4,158.0
	1500	9029902	MISC.ADJUST TO GRADE PULL BOX	EA	\$500.000	2	\$1,000.0
	5004	6089905	MISC.Misc. Concrete Sidewalk, 7 IN. Coral Color	SQYD	\$63.000	83.6	\$5,266.8
	5005	6091052	CURB AND GUTTER TYPE B	LF	\$31.970	55.5	\$1,774.34
	5006	6099903	MISC.Integral Curb (6 IN Height and Under), Type A, Coral Color	LF	\$21.780	33.5	\$729.6
Project J6S3	048 - Total						\$82,325.5
Overall - Tota	al						\$82,325.5



Pay Estimate Created Date: November 3, 2021

	Progre 8	ess Estimate Number	Prime Gershenson Construction Co., Inc. Start October 10, 2021 New 2021 New An					Net Change Or Amount	der \$	56,981.50										
`ontract /	diustr	ents This Est	imate				(Current Contra	ct Amount \$	12,945,467.99										
		tments Exist or																		
		nents This Es																		
Project Number	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type	Comm	ents	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount										
J6S3048	0050		GREGATE FOR E (8 IN. THICK)	Material				-51.8	\$12.00	(\$621.60										
	0050		GREGATE FOR E (8 IN. THICK)	Material		overridding Payment Es	Payment Estimate Iter 01) due to user aubu	m cj m	\$12.00	\$621.60										
	0060		GREGATE FOR SE (4 IN. THICK)	Material				-6,384.6	\$7.00	(\$44,692.20										
	0060		GREGATE FOR SE (4 IN. THICK)	Material		overridding Payment Es	Payment Estimate Iter 02) due to user aubu	m cj m	\$7.00	\$44,692.20										
	0200	PAVED APPROACH, 8 IN. Material					-1,957.9	\$61.48	(\$120,371.69											
	0200	PAVED AF	PROACH, 8 IN.	Material		overridding Payment Es	Payment Estimate Iter 05) due to user aubu	m cj m	\$61.48	\$120,371.69										
	0210	CONCRET	E SIDEWALK, 4 IN.	Material				-661.6	\$38.80	(\$25,670.08										
	0210	CONCRET	E SIDEWALK, 4 IN.	Material		overridding Payment Es	Payment Estimate Iter 06) due to user aubu	m cj m	\$38.80	\$25,670.08										
	0220	CONCRET	E SIDEWALK, 7 IN.	Material				-41.1	\$55.62	(\$2,285.98										
	0220	CONCRET	E SIDEWALK, 7 IN.	Material		overridding Payment Es	Payment Estimate Iter 07) due to user aubu	m cj m	\$55.62	\$2,285.98										
	0230		MISC.		MISC.		MISC.		MISC.		MISC.		MISC.					-1	\$1,400.00	(\$1,400.00
	0230		MISC.	Material		overridding Payment	Payment Estimate Iter 08) due to user aubu	m cj 1	\$1,400.00	\$1,400.00										
	0240		MISC.					-22	\$1,897.70	(\$41,749.40										
	0240		MISC.	Material		overridding Payment	Payment Estimate Iter 09) due to user aubu	m cj 4	\$1,897.70	\$41,749.40										
	0270		MISC. Material					-2,443.61	\$45.27	(\$110,622.22										
	0270		MISC.	Material		overridding Payment	Payment Estimate Iter 10) due to user aubu	m cj 5	\$45.27	\$110,622.22										
	0290	CONCRE	TE CURB (6 IN.	Material				-306.83	\$31.97	(\$9,809.36										



Pay Estimate Created Date: November 3, 2021

	Progr 8	ess Estimate Number	Contract ID Prime Contractor	210416-F0 Gershenso Inc.	2 n Constructio	Start		riginal Contra et Change Oro mount urrent Contra	der \$	56,981.50
Project Number	Line No.	Item De	escription	Adjustment Type	Other Item Adjustment Type	Comme	nts	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
6S3048		HEIGHT AND	UNDER) TYPE S							
	0290		TE CURB (6 IN. UNDER) TYPE S	Material		generated Material Pa Adjustment (001 overridding Payment Es	his adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user aubucj verridding Payment Estimate Exception 19 on the current Payment Estimate.			\$9,809.36
	0310		AL CURB (6 IN. UNDER) TYPE A	Material				-32	\$20.78	(\$664.96
	0310		AL CURB (6 IN. UNDER) TYPE A	Material		overridding Payment Es	yment Estimate Item 2) due to user aubuc		\$20.78	\$664.96
	0390		MISC.	Material				-31.17	\$101.87	(\$3,175.29
	0390		MISC.	Material		overridding Payment Es	yment Estimate Item 4) due to user aubuc		\$101.87	\$3,175.29
	0840	TURF TYPE	TALL FESCUE SODDING	Material				-805	\$9.50	(\$7,647.50
	0840	TURF TYPE	TALL FESCUE SODDING	Material		overridding Payment Es	yment Estimate Item 3) due to user aubuc		\$9.50	\$7,647.50
	1460	BAS	SE, CONCRETE	Material				-3.08	\$1,350.00	(\$4,158.00
	1460	BAS	SE, CONCRETE	Material		overridding Payment Es	yment Estimate Item 3) due to user aubuc		\$1,350.00	\$4,158.00
	5004		MISC.	Material				-395.6	\$63.00	(\$24,922.80
	5004		MISC.	Material		overridding Payment Es	yment Estimate Item 4) due to user aubuc		\$63.00	\$24,922.80
	5006		MISC.	Material				-441.15	\$21.78	(\$9,608.25
	5006		MISC.	Material		overridding Payment Es	yment Estimate Item 5) due to user aubuc		\$21.78	\$9,608.25
Total										\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J6S3048	FAF- S500(34)	ADA, signals & entrance improvements	180	ST LOUIS	from Pennridge Drive to I-170
Fotals by J	Job Numbe	rs			
J6S3048					This Estimate Previous To Date

S3048		This Estimate	Previous	To Date
Posted Item Pay		\$82,325.58	\$1,047,877.16	\$1,130,202.74
Gross Item Adjustments		\$0.00	\$0.00	\$0.00
Gross	s Item Pay	\$82,325.58	\$1,047,877.16	\$1,130,202.74
Incentive		\$0.00	\$0.00	\$0.00
Disincentive		\$0.00	\$0.00	\$0.00
Liquidated Damages		\$0.00	\$0.00	\$0.00
Other Contract Adjustments		\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 3040183, Project Item Line Number 0050, Material Set 304018396, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007RCBT1T5 - Agg Base T1/T5 Reclaimed Concrete, Acceptance Action Generic 1007RCBT1T5 is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6085008, Project Item Line Number 0200, Material Set 608500896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086004, Project Item Line Number 0210, Material Set 608600496, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6086007, Project Item Line Number 0220, Material Set 608600796, Material 0501CCB.A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0230, Material Set 608990296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089902, Project Item Line Number 0240, Material Set 608990296, Material 0501CCB.A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 0270, Material Set 6089905, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6089905, Project Item Line Number 5004, Material Set 608990596, Material 0501CCB.A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6091010, Project Item Line Number 0290, Material Set 609101096, Material 0501CCB.A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6092011, Project Item Line Number 0310, Material Set 609201196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Action Generic 100510CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6099903, Project Item Line Number 5006, Material Set 6099903, Material 1036RSDFEC28M13 - Rein Steel EC No. 4/M13 Gr 40/M280 @, Acceptance Action Generic ReSteelBars is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 6119905, Project Item Line Number 0390, Material Set 6119905, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 8031000A, Project Item Line Number 0840, Material Set 8031000A96, Material 0803SO - Sod, Acceptance Action Generic 0803SO is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S3048, Item 9029100, Project Item Line Number 1460, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Construction is aware of the exception and is working with the Contractor/MoDOT Materials to correct. Aubucj 11/3/21	Aubucj	Overridden



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.20	\$895,794.32	\$179,158.86
		0001	0020	2063000	CLASS 3 EXCAVATION	222.00	0.00	222.00	CUYD	0.00	\$20.00	\$0.00
		0001	0030	2071000	LINEAR GRADING CLASS 1	25.00	0.00	25.00	STA	2.98	\$10,515.06	\$31,334.88
		0001	0040	2072000	LINEAR GRADING CLASS 2	320.50	0.00	320.50	STA	58.07	\$383.92	\$22,294.23
		0001	0050	3040183	TYPE 1 AGGREGATE FOR BASE (8 IN. THICK)	2,721.00	0.00	2,721.00	SQYD	51.80	\$12.00	\$621.60
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	33,892.00	0.00	33,892.00	SQYD	6,384.60	\$7.00	\$44,692.20
		0001	0070	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	704.70	0.00	704.70	TONS	8.00	\$160.00	\$1,280.00
		0001	0080	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	38,263.90	0.00	38,263.90	TONS	0.00	\$85.50	\$0.00
		0001	0090	4079912	MISC.HARD PENETRATION ASPHALT EMULSION (SS1-VH)	28,179.00	0.00	28,179.00	GAL	0.00	\$2.55	\$0.00
		0001	0100	5021310	CONCRETE PAVEMENT (10 IN. NON-REINFORCED 15 FT. JOINTS)	697.10	0.00	697.10	SQYD	0.00	\$82.21	\$0.00
		0001	0110	6039902	WATER	40.00	0.00	40.00	EA	0.00	\$350.00	\$0.00
		0001	0120	6039902	WATER	40.00	0.00	40.00	EA	0.00	\$250.00	\$0.00
		0001	0130	6042010	ADJUSTING MANHOLE	65.00	0.00	65.00	EA	0.00	\$557.35	\$0.00
		0001	0140	6042020	ADJUSTING BASIN OR INLET	28.00	0.00	28.00	EA	0.00	\$463.02	\$0.00
		0001	0150	6044011	PIPE COLLAR, TYPE A	2.00	0.00	2.00	EA	0.00	\$1,033.78	\$0.00
		0001	0160	6049902	MISC.CONVERT INLET TO MANHOLE	5.00	0.00	5.00	EA	0.00	\$1,550.84	\$0.00
		0001	0170	6071060	PEDESTRIAN FENCE (STRUCTURES)	36.00	0.00	36.00	LF	0.00	\$157.87	\$0.00
		0001	0180	6081012	TRUNCATED DOMES	4,984.00	-2,240.00	2,744.00	SQFT	30.00	\$22.23	\$666.90
		0001	0190	6083006	6 IN. CONCRETE MEDIAN STRIP	989.00	0.00	989.00	SQYD	0.00	\$58.92	\$0.00
		0001	0200	6085008	PAVED APPROACH, 8 IN.	11,544.40	0.00	11,544.40	SQYD	1,957.90	\$61.48	\$120,371.69
		0001	0210	6086004	CONCRETE SIDEWALK, 4 IN.	9,752.20	0.00	9,752.20	SQYD	661.60	\$38.80	\$25,670.08
		0220	6086007	CONCRETE SIDEWALK, 7 IN.	1,849.90	0.00	1,849.90	SQYD	41.10	\$55.62	\$2,285.98	
		0230	6089902	MISC.CONCRETE CURB RAMP	97.00	0.00	97.00	EA	1.00	\$1,400.00	\$1,400.00	
		0001	0240	6089902	MISC.CONCRETE CURB RAMP, CORAL COLOR	128.00	0.00	128.00	EA	22.00	\$1,897.70	\$41,749.40
		0001	0250	6089905	MISC.CONCRETE SIDEWALK REPAIR, 4 IN.	80.00	0.00	80.00	SQYD	0.00	\$62.33	\$0.00
		0001	0260	6089905	MISC.CONCRETE SIDEWALK REPAIR, 4 IN., CORAL COLOR	80.00	0.00	80.00	SQYD	0.00	\$66.41	\$0.00
		0001	0270	6089905	MISC.CONCRETE SIDEWALK, 4 IN., CORAL COLOR	8,608.30	-750.00	7,858.30	SQYD	3,343.70	\$45.27	\$151,369.30
		0001	0280	6089905	MISC.SIDEWALK GRINDING	15.00	0.00	15.00	SQYD	0.00	\$50.00	\$0.00
		0001	0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	10,374.00	-6,950.00	3,424.00	LF	306.83	\$31.97	\$9,809.36
		0001	0300	6091041	CONCRETE GUTTER TYPE A	9.00	0.00	9.00	LF	0.00	\$100.00	\$0.00
		0001	0310	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	3,437.00	0.00	3,437.00	LF	32.00	\$20.78	\$664.96
		0001	0320	6092021	INTEGRAL CURB (OVER 6 IN. HEIGHT) TYPE A	117.00	0.00	117.00	LF	0.00	\$21.38	\$0.00
		0001	0330	6092031	CONCRETE CURB LOW PROFILE TYPE E	34.00	0.00	34.00	LF	0.00	\$20.00	\$0.00
		0001	0340	6096020	FURNISHING TYPE 2 ROCK DITCH LINER	92.00	0.00	92.00	CUYD	0.00	\$47.96	\$0.00
		0001	0350	6096042	PLACING TYPE 2 ROCK DITCH LINER	92.00	0.00	92.00	CUYD	0.00	\$54.42	\$0.00
		0001	0360	6099903	MISC.LANDSCAPE CURB	343.00	0.00	343.00	LF	0.00	\$98.77	\$0.00
		0001	0370	6099903	MISC.SLOTTED INTEGRAL CURB	364.00	0.00	364.00	LF	0.00	\$19.88	\$0.00
		0001	0380	6116010A	SLOPE PROTECTION	955.00	0.00	955.00	SQYD	0.00	\$91.62	\$0.00
		0001	0390	6119905	MISC.SLOPE PROTECTION, CORAL COLOR	795.00	0.00	795.00	SQYD	31.17	\$101.87	\$3,175.29
		0001	0400	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	179.10	0.00	179.10	SQYD	0.00	\$271.30	\$0.00
		0001	0410	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	179.00	0.00	179.00	SQYD	0.00	\$5.00	\$0.00
		0001	0420	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	179.00	0.00	179.00	SQYD	0.00	\$11.00	\$0.00
		0001	0430	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,378.00	0.00	1,378.00	LF	0.00	\$6.00	\$0.00
		0001	0440	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	320.00	0.00	320.00	EA	0.00	\$5.98	\$0.00
			0450	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	5.00	0.00	5.00	EA	0.00	\$923.77	\$0.00

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q	uantities			ased on R	eport Generated date and can differ from the posted amo	ount at the	time the E	stimate was	Genera	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048	0001	0460	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	3.00	0.00	3.00	EA	0.00	\$1,154.78	\$0.00
		0001	0470	6143010	MANHOLE FRAME AND COVER, TYPE 1-A	6.00	0.00	6.00	EA	0.00	\$320.26	\$0.00
		0001	0480	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.50	\$239,762.00	\$119,881.00
		0001	0490	6169902	MISC.NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN, CONTRACTOR FURNISHED/RETAINED	6.00	0.00	6.00	EA	2.00	\$3,200.00	\$6,400.00
		0001	0500	6179903	MISC.CONCRETE TRAFFIC BARRIER, TYPE C (PERFORATED)	665.00	0.00	665.00	LF	0.00	\$132.86	\$0.00
		0001	0510	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$844,409.28	\$0.00
		0001	0511	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.25	\$764,077.28	\$191,019.32
		0001	0520	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0.00
		0001	0530	6191000	PAVEMENT EDGE TREATMENT	28,023.00	0.00	28,023.00	LF	0.00	\$1.29	\$0.00
		0001	0540	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	4,710.00	0.00	4,710.00	LF	0.00	\$6.00	\$0.00
		0001	0550	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE	46.00	0.00	46.00	LF	0.00	\$11.00	\$0.00
		0001	0560	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	3,702.00	0.00	3,702.00	LF	0.00	\$17.00	\$0.00
		0001	0570	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	154.00	0.00	154.00	LF	0.00	\$18.00	\$0.00
		0001	0580	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	315.00	0.00	315.00	EA	0.00	\$270.00	\$0.00
		0001	0590	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	38.00	0.00	38.00	EA	0.00	\$25.00	\$0.00
		0001	0600	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	24.00	0.00	24.00	EA	0.00	\$40.00	\$0.00
		0001	0610	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	1,356.00	0.00	1,356.00	EA	0.00	\$180.00	\$0.00
		0001	0620	6200042	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	685.00	0.00	685.00	EA	0.00	\$50.00	\$0.00
		0001	0630	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	74,277.00	0.00	74,277.00	LF	0.00	\$0.17	\$0.00
		0001	0640	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	107,464.00	0.00	107,464.00	LF	0.00	\$0.22	\$0.00
		0001	0650	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	208.00	0.00	208.00	LF	0.00	\$1.00	\$0.00
		0001	0660	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,029.00	0.00	2,029.00	LF	0.00	\$2.00	\$0.00
	0001 0670	6207001	PAVEMENT MARKING REMOVAL	23,067.00	0.00	23,067.00	LF	0.00	\$0.75	\$0.00		
		0001	0680	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	31.00	0.00	31.00	EA	0.00	\$50.00	\$0.00
		0001	0690	6209902	MISC.18 IN. WHITE ISLAND TUBULAR MARKIER	172.00	0.00	172.00	EA	0.00	\$52.80	\$0.00
		0001	0700	6209902	MISC.18 IN. YELLOW ISLAND TUBULAR MARKER	155.00	0.00	155.00	EA	0.00	\$52.80	\$0.00
		0001	0710	6209903	MISC.PREFORMED THERMOPLASTIC PAVEEMNT MARKING, 6 IN. YELLOW	1,061.00	0.00	1,061.00	LF	0.00	\$6.00	\$0.00
		0001	0720	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	281,790.00	0.00	281,790.00	SQYD	0.00	\$1.33	\$0.00
		0001	0730	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	276.00	0.00	276.00	SQYD	0.00	\$3.50	\$0.00
		0001	0740	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.13	\$40,000.00	\$5,320.00
		0001	0750	7039903	MISC.SPECIAL GUTTER RETAINING WALL	435.00	0.00	435.00	LF	0.00	\$102.84	\$0.00
		0001	0760	7209904	MISC.SMALL BLOCK RETAINING WALL	606.00	0.00	606.00	SQFT	0.00	\$67.83	\$0.00
		0001	0770	7261012	12 IN. PIPE GROUP A	32.00	0.00	32.00	LF	0.00	\$167.61	\$0.00
		0001	0780	7261018	18 IN. PIPE GROUP A	26.00	0.00	26.00	LF	0.00	\$198.93	\$0.00
		0001	0790	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	5.00	0.00	5.00	FT	0.00	\$623.31	\$0.00
		0001	0800	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	20.00	0.00	20.00	FT	0.00	\$366.12	\$0.00
		0001	0810	7311042	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	10.00	0.00	10.00	FT	0.00	\$467.70	\$0.00
		0001	0820	7319902	MISC.SPECIAL DRAINAGE STRUCTURE	3.00	0.00	3.00	EA	0.00	\$5,183.98	\$0.00
		0001	0830	7319913	MISC.DOUBLE CURB INLET	10.00	0.00	10.00	FT	0.00	\$825.48	\$0.00
		0001	0840	8031000A	TURF TYPE TALL FESCUE SODDING	9,697.00	0.00	9,697.00	SQYD	805.00	\$9.50	\$7,647.50
		0001	0850	8051000A	SEEDING - COOL SEASON MIXTURES	0.30	0.00	0.30	ACRE	0.00	\$9,680.00	\$0.00
		0001	0860	8061005	ROCK DITCH CHECK	40.00	0.00	40.00	LF	0.00	\$12.00	\$0.00
		0001	0870	8061007A	CURB INLET CHECK	335.00	0.00	335.00	EA	0.00	\$95.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

ed date and can differ from the posted amount at the time the Estimate was Generated Report G

Contract	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted amo Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTE To Date (See repor
	110.		110.	Code		Quantity	Order	Quantity		Approved Qty		generated date)
10416-F02	J6S3048	0001	0880	8061016	SEDIMENT REMOVAL	450.00	0.00	450.00	CUYD	0.00	\$1.00	\$0.0
		0001	0890	8061017	TEMPORARY SEEDING AND MULCHING	0.30	0.00	0.30	ACRE	0.00	\$4,840.00	\$0.0
		0001	0900	8061019	SILT FENCE	11,135.00	0.00	11,135.00	LF	0.00	\$2.95	\$0.0
		0001	0910	8064138	TYPE 2D EROSION CONTROL BLANKET	1,528.00	0.00	1,528.00	SQYD	0.00	\$2.95	\$0.0
		0001	0920	8069905	MISC.LANDSCAPING RESTORATION	500.00	0.00	500.00	SQYD	0.00	\$35.00	\$0.0
		0010	0930	6061060	MGS GUARDRAIL	175.00	0.00	175.00	LF	0.00	\$23.90	\$0.0
		0010	0940	6061068	MGS BRIDGE APPROACH TRANSITION SECTION (EXTENDED CURB)	4.00	0.00	4.00	EA	0.00	\$3,053.40	\$0.0
		0010	0950	6061080	MGS END ANCHOR	4.00	0.00	4.00	EA	0.00	\$1,209.00	\$0.0
		0010	0960	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$2,629.50	\$0.
		0020	0970	9011010	RELOCATED POLE	1.00	0.00	1.00	EA	0.00	\$400.00	\$0.
		0020	0980	9011250	LUMINAIRE, 150 WATT HIGH PRESSURE SODIUM	6.00	-6.00	0.00	EA	0.00	\$930.00	\$0.
		0020	0990	9011311	(UNDERPASS) LUMINAIRE, LED-A	7.00	0.00	7.00	EA	0.00	\$300.00	\$0.1
		0020	1000	9014003	CONDUIT, 3 IN. RIGID, PUSHED	91.00	0.00	91.00	LF	0.00	\$28.00	\$0.0
		0020	1010	9015010	TRENCHING TYPE I	26.00	0.00	26.00	LF	0.00	\$8.00	\$0.0
		0020	1020	9016110	PULL BOX. PREFORMED CLASS 1	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0.0
		0020	1030	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	90.00	0.00	90.00	LF	0.00	\$0.85	\$0.1
		0020	1040	9017404	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	140.00	0.00	140.00	LF	0.00	\$5.80	\$0.1
					NEUTRAL, 6 AWG CABLE-CONDUIT. 1 IN., 2 CONDUCTORS AND 1 BARE							
		0020	1050	9017407	NEUTRAL, 8 AWG	30.00	0.00	30.00	LF	0.00	\$5.30	\$0.
		0020	1060	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	1.00	0.00	1.00	EA	0.00	\$876.00	\$0
		0030	1070	9020113	SIGNAL HEAD, TYPE 3T	4.00	0.00	4.00	EA	0.00	\$702.00	\$0
		0030	1080	9020213	SIGNAL HEAD, TYPE 3S	9.00	0.00	9.00	EA	0.00	\$673.00	\$0
		0030	1090	9020215	SIGNAL HEAD, TYPE 5S	1.00	0.00	1.00	EA	0.00	\$931.00	\$0
		0030	1100	9020513	SIGNAL HEAD, TYPE 3B	104.00	0.00	104.00	EA	0.00	\$875.00	\$0
		0030	1110	9020514	SIGNAL HEAD, TYPE 4B	9.00	0.00	9.00	EA	0.00	\$960.00	\$0
		0030	1120	9020515	SIGNAL HEAD, TYPE 5B	2.00	0.00	2.00	EA	0.00	\$1,217.00	\$0
		0030	1130	9020833	SH-FLAT SHEET - SIGNAL SIGN	754.00	0.00	754.00	SQFT	0.00	\$30.00	\$0
		0030	1140	9020834	SIGNAL SIGN, MOUNTING HARDWARE	95.00	0.00	95.00	EA	0.00	\$352.00	\$0
		0030	1150	9022708	POST, SIGNAL 8 FT. OR 2.4 M	160.00	0.00	160.00	EA	0.00	\$526.00	\$0
		0030	1160	9022715	POST, SIGNAL 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	0.00	\$678.00	\$0.
		0030	1170	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	1.00	0.00	1.00	EA	0.00	\$7,194.00	\$0.
		0030	1180	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	1.00	0.00	1.00	EA	0.00	\$8,729.00	\$0.
		0030	1190	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	3.00	0.00	3.00	EA	0.00	\$10,217.00	\$0
		0030	1200	9023145	POST, TYPE CL, 45 FT. ARM OR 13.7 M ARM	1.00	0.00	1.00	EA	0.00	\$10,538.00	\$0.
		0030	1210	9023150	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$11,345.00	\$0.
		0030	1220	9023155	POST, TYPE CL, 55 FT. ARM	1.00	0.00	1.00	EA	0.00	\$12,722.00	\$0
		0030	1230	9023220	POST, TYPE C, 20 FT. ARM OR 6.1 M ARM	2.00	0.00	2.00	EA	0.00	\$5,285.00	\$0
		0030	1240	9023225	POST, TYPE C, 25 FT. ARM OR 7.6 M ARM	3.00	0.00	3.00	EA	0.00	\$6,096.00	\$0.
		0030	1250	9023230	POST, TYPE C, 30 FT. ARM OR 9.1 M ARM	4.00	0.00	4.00	EA	0.00	\$7,084.00	\$0.
		0030	1260	9023235	POST, TYPE C, 35 FT. ARM OR 10.7 M ARM	3.00	0.00	3.00	EA	0.00	\$7,500.00	\$0.
		0030	1270	9023240	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	2.00	0.00	2.00	EA	0.00	\$8,651.00	\$0
		0030	1280	9023245	POST, TYPE C, 45 FT. ARM OR 13.7 M ARM	6.00	0.00	6.00	EA	0.00	\$8,900.00	\$0.
		0030	1290	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	6.00	0.00	6.00	EA	0.00	\$9,235.00	\$0.
		0030	1300	9023255	POST, TYPE C, 55 FT. ARM	4.00	0.00	4.00	EA	0.00	\$10,627.00	\$0.
		0030	1310	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	7.00	0.00	7.00	EA	0.00	\$15,200.00	\$0.
		0030	1320	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	541.00	0.00	541.00	LF	0.00	\$8.30	\$0.
		0030	1330	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	3,675.00	0.00	3,675.00	LF	0.00	\$11.00	\$0.



Revision 4/1/2020

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Page 10 of 20

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Qi Contract Nm.CONTRACT	Project No.	and Valu Category		Item Code	Report Generated date and can differ from the posted amo Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
							Order	Quantity		Approved Qty		generated date)
210416-F02	J6S3048	0030	1340	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	18.00	0.00	18.00	LF	0.00	\$12.60	\$0.00
		0030	1350	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	205.00	0.00	205.00	LF	0.00	\$27.00	\$0.00
		0030	1360	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	6,873.00	0.00	6,873.00	LF	431.00	\$25.00	\$10,775.00
		0030	1370	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	253.00	0.00	253.00	LF	0.00	\$25.00	\$0.00
		0030	1380	9028206	CABLE, 6 AWG 1 CONDUCTOR, POWER	910.00	0.00	910.00	LF	0.00	\$1.40	\$0.00
		0030	1390	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	1,220.00	0.00	1,220.00	LF	0.00	\$1.25	\$0.00
		0030	1400	9028308	CABLE, 16 AWG 2 CONDUCTOR	36,360.00	0.00	36,360.00	LF	0.00	\$0.85	\$0.00
		0030	1410	9028310	CABLE, 16 AWG 5 CONDUCTOR	35,860.00	0.00	35,860.00	LF	0.00	\$1.00	\$0.00
		0030	1420	9028311	CABLE, 16 AWG 7 CONDUCTOR	28,720.00	0.00	28,720.00	LF	0.00	\$1.15	\$0.00
		0030	1430	9028810	PULL BOX, PREFORMED CLASS 1	28.00	0.00	28.00	EA	1.00	\$1,000.00	\$1,000.00
		0030	1440	9028811	PULL BOX, PREFORMED CLASS 2	17.00	0.00	17.00	EA	0.00	\$1,250.00	\$0.00
		0030	1450	9028812	PULL BOX, PREFORMED CLASS 3	16.00	0.00	16.00	EA	0.00	\$1,600.00	\$0.00
		0030	1460	9029100	BASE, CONCRETE	211.70	0.00	211.70	CUYD	3.08	\$1,350.00	\$4,158.00
		0030	1470	9029400	TEMPORARY TRAFFIC SIGNALS	1.00	0.00	1.00	LS	0.00	\$12,000.00	\$0.00
		0030	1480	9029901	MISC.POT HOLING UTILITY FACILITIES	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0030	1490	9029901	MISC.TRAFFIC SIGNAL MAINTENANCE, PROGRAMMING, AND ADJUSTMENT	1.00	0.00	1.00	LS	0.00	\$23,000.00	\$0.00
		0030	1500	9029902	MISC.ADJUST TO GRADE PULL BOX	93.00	0.00	93.00	EA	3.00	\$500.00	\$1,500.00
		0030	1510	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTON & SIGNING W/ VERBAL WALK MESSAGE	200.00	0.00	200.00	EA	0.00	\$630.00	\$0.00
		0030	1512	9029902	MISC.CABINET MODIFICATION – FEE FEE INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1514	9029902	MISC.CABINET MODIFICATION – HOME DEPOT INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1515	9029902	MISC.CABINET MODIFICATION – ADIE INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1516	9029902	MISC.CABINET MODIFICATION – CYPRESS INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1518	9029902	MISC.CABINET MODIFICATION – ST. TIMOTHY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$760.00	\$0.00
		0030	1520	9029902	MISC.COUNTDOWN PEDESTRIAN SIGNAL HEAD, TYPE 1S	189.00	0.00	189.00	EA	0.00	\$390.00	\$0.00
		0030	1522	9029902	MISC.CABINET MODIFICATION – ASHBY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$890.00	\$0.00
		0030	1524	9029902	MISC.CABINET MODIFICATION – INTERNATIONAL PLAZA	1.00	0.00	1.00	EA	0.00	\$780.00	\$0.00
		0030	1525	9029902	INTERSECTION MISC.CABINET MODIFICATION – ST. GREGORY	1.00	0.00	1.00	EA	0.00	\$780.00	\$0.00
			1526	9029902	INTERSECTION MISC.CABINET MODIFICATION - WISMER INTERSECTION	1.00	0.00	1.00	EA	0.00	\$736.00	\$0.00
		0030										
		0030	1527	9029902	MISC.CABINET MODIFICATION - LYNNTOWN INTERSECTION	1.00	0.00	1.00	EA	0.00	\$780.00	\$0.00
		0030	1528	9029902	MISC.CABINET MODIFICATION - EDMUNDSON INTERSECTION	1.00	0.00	1.00	EA	0.00	\$670.00	\$0.00
		0030	1530			6.00	0.00	6.00	EA	0.00	\$1,225.00	\$0.00
		0030	1540	9029902	MISC.OPTIONAL DETECTION - DEPAUL INTERSECTION MISC.OPTIONAL DETECTION - EB I-70 RAMPS INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1550			1.00		1.00	EA	0.00	\$12,890.00	\$0.00
		0030	1560 1570	9029902		1.00	0.00	1.00	EA	0.00	,	
		0030				1.00		1.00	EA		\$18,800.00	\$0.00
		0030	1580	9029902	MISC.OPTIONAL DETECTION - HOME DEPOT INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1590	9029902	MISC.OPTIONAL DETECTION - MARK TWAIN INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1600	9029902	MISC.OPTIONAL DETECTION - ST. TIMOTHY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1610	9029902	MISC.OPTIONAL DETECTION - WB I-70 RAMPS INTERSECTION	1.00	0.00	1.00	EA	0.00	\$12,800.00	\$0.00
		0030	1620	9029902	MISC.OPTIONAL DETECTION CYPRESS INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1630	9029902	MISC.OPTIONAL DETETION - HARMONY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$18,800.00	\$0.00
		0030	1640	9029902	MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$3,900.00	\$0.00
		0030	1650	9029902	MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY & 120 VOLT LIGHTING CONTROLLER	1.00	0.00	1.00	EA	0.00	\$5,800.00	\$0.00
		0030	1660	9029902	MISC.PAD MOUNTED 120 VOLT SIGNAL POWER SUPPLY & 120 VOLT LIGHTING CONTROLLER WITH UNINTERRUPTIBLE POWER SUPPLY	1.00	0.00	1.00	EA	0.00	\$13,600.00	\$0.00
		0030	1670	9029902	MISC.PAD MOUNTED 120V/240V SIGNAL POWER SUPPLY & LIGHTING CONTROLLER WITH UNINTERRUPTIBLE POWER	5.00	0.00	5.00	EA	0.00	\$15,300.00	\$0.00

Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048				SUPPLY							
		0030	1680	9029902	MISC.SL DISTRICT VIDEO DETECTION SYSTEM	6.00	0.00	6.00	EA	0.00	\$18,200.00	\$0.00
		0030	1690	9029902	MISC.VIDEO DETECTION MODIFICAITON - ASHBY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$19,000.00	\$0.00
		0030	1700	9029902	MISC.VIDEO DETECTION MODIFICATION - ADIE INTERSECTION	1.00	0.00	1.00	EA	0.00	\$5,900.00	\$0.00
		0030	1710	9029902	MISC.VIDEO DETECTION MODIFICATION - BROWN INTERSECTION	1.00	0.00	1.00	EA	0.00	\$300.00	\$0.00
		0030	1720	9029902	MISC.VIDEO DETECTION MODIFICATION - EDUNDSON	1.00	0.00	1.00	EA	0.00	\$300.00	\$0.00
		0030	1730	9029902	MISC.VIDEO DETECTION MODIFICATION - INTERNATIONAL PLAZA INTERSECTION	1.00	0.00	1.00	EA	0.00	\$10,000.00	\$0.00
		0030	1740	9029902	MISC.VIDEO DETECTION MODIFICATION - LYNN TOWN INTERSECTION	1.00	0.00	1.00	EA	0.00	\$10,000.00	\$0.00
		0030	1750	9029902	MISC.VIDEO DETECTION MODIFICATION - MCKIBBON	1.00	0.00	1.00	EA	0.00	\$10,000.00	\$0.00
		0030	1760	9029902	INTERSECTION MISC.VIDEO DETECTION MODIFICATION - ST. GREGORY	1.00	0.00	1.00	EA	0.00	\$6,000.00	\$0.00
		0030	1770	9029902	INTERSECTION MISC.VIDEO DETECTION MODIFICATION - ST. JOHN	1.00	0.00	1.00	EA	0.00	\$350.00	\$0.00
				9029902	CROSSING INTERSECTION							
		0030	1780		MISC.VIDEO DETECTION MODIFICATION - WISMER INTERSECTION	1.00	0.00	1.00	EA	0.00	\$350.00	\$0.00
		0030	1790	9029902	MISC.VIDEO DETECTION MODIFICATION - WOODSON INTERSECTION	1.00	0.00	1.00	EA	0.00	\$350.00	\$0.00
		0030	1800	9029903	MISC.2 CONDUCTOR 12 AWG LUMINAIRE CONTROL CABLE	2,280.00	0.00	2,280.00	LF	0.00	\$0.90	\$0.00
		0040	1810	9031010	CONCRETE FOOTINGS, EMBEDDED	7.20	0.00	7.20	CUYD	0.00	\$1,074.00	\$0.00
		0040	1820	9031220	PIPE POSTS	4,930.00	0.00	4,930.00	LB	0.00	\$4.36	\$0.00
		0040	1830	9031270A	2 IN. PSST POST - 12 GA.	1,983.00	0.00	1,983.00	LF	0.00	\$14.85	\$0.00
		0040	1840	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	564.00	0.00	564.00	LF	0.00	\$25.77	\$0.00
		0040	1850	9031280	2.5 IN. PSST POST - 12 GA.	509.00	0.00	509.00	LF	0.00	\$16.65	\$0.00
		0040	1860	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	132.00	0.00	132.00	LF	0.00	\$50.37	\$0.00
		0040	1870	9035004A	SH-FLAT SHEET	1,732.00	0.00	1,732.00	SQFT	0.00	\$15.96	\$0.00
		0040	1880	9035069A	SHF-FLAT SHEET FLUORESCENT	304.00	0.00	304.00	SQFT	0.00	\$19.56	\$0.00
		0040	1890	9039902	MISC.REMOVE AND RELOCATE EXISTING GROUND MOUNT SIGN	27.00	0.00	27.00	EA	0.00	\$132.27	\$0.00
		0050	1900	9108816	PULL BOX, PREFORMED CLASS 5	4.00	0.00	4.00	EA	0.00	\$1,500.00	\$0.00
		0050	1910	9109901	MISC.ITS ASSET MANAGEMENT TOOL	1.00	0.00	1.00	LS	0.00	\$7,373.00	\$0.00
		0050	1920	9109902	MISC.CCTV CAMERA ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$3,600.00	\$0.00
		0050	1930	9109902	MISC.FIBER OPTIC PIGTAIL, SM, FURNISH AND INSTALL	46.00	0.00	46.00	EA	0.00	\$57.00	\$0.00
		0050	1940	9109902	MISC.FIRER OPTIC JUMPER, SM, FURNISH AND INSTALL	36.00	0.00	36.00	EA	0.00	\$51.00	\$0.00
		0050	1950	9109902	MISC.INSTALL CCTV CAMERA ASSEMBLY	2.00	0.00	2.00	EA	0.00	\$1,800.00	\$0.00
		0050	1960	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - ASHBY INTERSECTION	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	1970	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT - DEPAUL INTERSECTION	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	1980	9109902	MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	1990	9109902	LINDBERGH INTERSECTION MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	2000	9109902	MCKELVEY INTERSECTION MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	2010	9109902	NATURAL BRIDGE INTERSECTION MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	2020	9109902	NB I-270 INTERSECTION MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0050	2020	9109902	PENNRIDGE INTERSECTION MISC.RELOCATE EXISTING COMMUNICATION EQUIPMENT -	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
					SB I-270 INTERSECTION							
			MISC.SM FIBER OPTIC FUSION SPLICE	160.00	0.00	160.00	EA	0.00	\$49.00	\$0.00		
		0050	2050	9109902	MISC.WALL-MOUNTED INTERCONNECT CENTER, FURNISH AND INSTALL	7.00	0.00	7.00	EA	0.00	\$910.00	\$0.00
		0050	2060	9109903	MISC.CCTV CAMERA CABLE	190.00	0.00	190.00	LF	0.00	\$1.25	\$0.00
		0050	2070	9109903	MISC.CONDUIT, 2 - 2 IN., RIGID, IN TRENCH	140.00	0.00	140.00	LF	0.00	\$28.00	\$0.00
		0050	2080	9109903	MISC.FIBER OPTIC CABLE, 24 STRAND SINGLE MODE	5,390.00	0.00	5,390.00	LF	0.00	\$3.25	\$0.00

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210416-F02	J6S3048	0050	2090	9109903	MISC.MODOT ITS ASSETS RELOCATION	1,000.00	0.00	1,000.00	LF	0.00	\$11.00	\$0.00
		0001	5001	6189901	MISC.Contract Bond Payment	0.00	1.00	1.00	LS	1.00	\$80,332.00	\$80,332.00
		0001	5002	6081012	TRUNCATED DOMES	0.00	2,240.00	2,240.00	SQFT	358.10	\$24.23	\$8,676.76
		0020	5003	9019902	MISC.Luminaire, LED Wall Pack (Underpass)	0.00	6.00	6.00	EA	0.00	\$930.00	\$0.00
		0001	5004	6089905	MISC.Misc. Concrete Sidewalk, 7 IN. Coral Color	0.00	750.00	750.00	SQYD	395.60	\$63.00	\$24,922.80
		0001	5005	6091052	CURB AND GUTTER TYPE B	0.00	6,950.00	6,950.00	LF	701.20	\$31.97	\$22,417.36
		0001	5006	6099903	MISC.Integral Curb (6 IN Height and Under), Type A, Coral Color	0.00	1,800.00	1,800.00	LF	441.15	\$21.78	\$9,608.25
	Project J	6S3048 - To	otal Value	Posted to D	Date as of Report Generated Date							\$1,130,202.73
210416-F02 Ove	rall - Total	Value Post	ed to Dat	e as of Repo	ort Generated Date							\$1,130,202.73



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project:	J6S3048	В										
Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0060	3040504	TYPE 5 AGGREGATE FOR BASE	11/1/21	11/1/21	1,098.90	SQYD		340 LT		315 LT		10/18 - 10/26
0180	6081012	TRUNCATED DOMES	11/1/21	11/1/21	20.00	SQFT		340 LT		315 LT		10/18 - 10/26
0200	6085008	PAVED APPROACH, 8 IN.	11/1/21	11/1/21	194.60	SQYD		340 LT		315 LT		10/18 - 10/26
0210	6086004	CONCRETE SIDEWALK, 4 IN.	11/1/21	11/1/21	603.80	SQYD		340 LT		315 LT		10/18 - 10/26
0220	6086007	CONCRETE SIDEWALK, 7 IN.	11/1/21	11/1/21	32.00	SQYD		340 LT		315 LT		10/18 - 10/26
0230	6089902	MISC. CONCRETE	11/1/21	11/1/21	1.00	EA		340 LT		315 LT		10/18 - 10/26
0270	6089905	MISC. CONCRETE	11/1/21	11/1/21	184.90	SQYD		340 LT		315 LT		10/18 - 10/26
0290	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	11/1/21	11/1/21	62.00	LF		340 LT		315 LT		10/18 - 10/26
0310	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	11/1/21	11/1/21	27.00	LF		340 LT		315 LT		10/18 - 10/26
1360	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	10/20/21	11/2/21	238.00	LF	Woodson Intersection	0		0		Push Buttons
			10/21/21	11/2/21	193.00	LF	Edmundson Intersection	0		0		Push Buttons
1430	9028810	PULL BOX, PREFORMED CLASS 1	10/22/21	11/3/21	1.00	EA	Edmundson Intersection	0		0		
1460	9029100	BASE, CONCRETE	10/27/21	11/2/21	3.08	CUYD	Edmundson, Woodson Intersections - North Side	0		0		(3) C Bases at Edmundson - Posts 1,2,3 (.44 Each) (4) C Bases at Woodson - Posts 1,2,3,4 (.44 Each)
1500	9029902	MISC.	11/1/21	11/1/21	2.00	EA		340 LT		315 LT		10/18 - 10/26
5004	6089905	MISC. CONCRETE	11/1/21	11/1/21	83.60	SQYD		340 LT		315 LT		10/18 - 10/26
5005	6091052	CURB AND GUTTER TYPE B	11/1/21	11/1/21	55.50	LF		340 LT		315 LT		10/18 - 10/26
5006	6099903	MISC. PAVED DRAINAGE	11/1/21	11/1/21	33.50	LF		340 LT		315 LT		10/18 - 10/26

The information below this line are details for Construction Signs (if applicable). No Data Available



_														
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J6S3048	0050	TYPE 1 AGGREGATE FOR BASE (8	Material		7	Oct 18, 2021	SYSTEM	\$621.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.					
		IN. THICK)			7	Oct 18, 2021	SYSTEM	(\$621.60)						
					8	Nov 3, 2021	SYSTEM	\$621.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					8	Nov 3, 2021	SYSTEM	(\$621.60)						
				- Total				\$0.00						
			Material - T	otal				\$0.00						
	0050 -	Total						\$0.00						
	0060	TYPE 5	Material		3	Aug 17,	SYSTEM	\$3,244.50	This adjustment offsets the original system-generated Material Payment					
	0000	AGGREGATE FOR BASE	Wateria			2021			Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					3	Aug 16, 2021	SYSTEM	(\$3,244.50)						
					4	Sep 3, 2021	SYSTEM	\$10,092.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					4	Sep 2, 2021	SYSTEM	(\$10,092.60)						
					5	Sep 16, 2021	SYSTEM	\$17,085.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.					
								5	Sep 16, 2021	SYSTEM	(\$17,085.60)			
							6	Oct 4, 2021	SYSTEM	\$32,813.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schmij8 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
						6	Oct 4, 2021	SYSTEM	(\$32,813.20)					
					7	Oct 18, 2021	SYSTEM	\$36,999.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					7	Oct 18, 2021	SYSTEM	(\$36,999.90)						
					8	Nov 3, 2021	SYSTEM	\$44,692.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					8	Nov 3, 2021	SYSTEM	(\$44,692.20)						
				- Total				\$0.00						
			Material - T	otal				\$0.00						
	0060 -	Total						\$0.00						
	0180	TRUNCATED DOMES	Material		2	Aug 3, 2021	SYSTEM	\$866.97	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 1 on the current Payment Estimate.					
							2			2	Aug 3, 2021	SYSTEM	(\$866.97)	
													3	Aug 17, 2021
					3 Aug 16 2021	Aug 16, 2021	SYSTEM	(\$2,489.76)						
					4	Sep 3, 2021	SYSTEM	\$4,468.23	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					4	Sep 2, 2021	SYSTEM	(\$4,468.23)						
					5	Sep 16, 2021	SYSTEM	\$6,557.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.					



Project		Description	A allowed and a set	Others	F -4	Our stad	Our stad	A	Dementer			
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S3048	0180	TRUNCATED DOMES	Material		5	Sep 16, 2021	SYSTEM	(\$6,557.85)				
					6	Oct 4, 2021	SYSTEM	\$7,080.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schmij8 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					6	Oct 4, 2021	SYSTEM	(\$7,080.26)				
					7	Oct 18, 2021	SYSTEM	\$222.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					7	Oct 18, 2021	SYSTEM	(\$222.30)				
				- Total				\$0.00				
			Material - T	otal				\$0.00				
	0180 -	- Total						\$0.00				
	0200	PAVED APPROACH, 8 IN.	Material		2	Aug 3, 2021	SYSTEM	\$5,027.83	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					2	Aug 3, 2021	SYSTEM	(\$5,027.83)				
					3	Aug 17, 2021	SYSTEM	\$18,276.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					3	Aug 16, 2021	SYSTEM	(\$18,276.77)				
					4	Sep 3, 2021	SYSTEM	\$50,941.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate.			
							4	Sep 2, 2021	SYSTEM	(\$50,941.10)		
					5	Sep 16, 2021	SYSTEM	\$78,428.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					5	Sep 16, 2021	SYSTEM	(\$78,428.81)				
					6	Oct 4, 2021	SYSTEM	\$93,215.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					6		SYSTEM SYSTEM	\$93,215.98 (\$93,215.98)	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment			
						2021 Oct 4,			Estimate Item Adjustment (0005) due to user schmij8 overridding Payment			
					6	2021 Oct 4, 2021 Oct 18,	SYSTEM SYSTEM	(\$93,215.98)	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment			
					6 7	2021 Oct 4, 2021 Oct 18, 2021 Oct 18,	SYSTEM SYSTEM	(\$93,215.98) \$108,407.68	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					6 7 7	2021 Oct 4, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3,	SYSTEM SYSTEM SYSTEM	(\$93,215.98) \$108,407.68 (\$108,407.68)	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment			
				- Total	6 7 7 8	2021 Oct 4, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3, 2021 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$93,215.98) \$108,407.68 (\$108,407.68) \$120,371.69	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment			
			Material - T		6 7 7 8	2021 Oct 4, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3, 2021 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$93,215.98) \$108,407.68 (\$108,407.68) \$120,371.69 (\$120,371.69)	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment			
	0200 -	Total	Material - Tr		6 7 7 8	2021 Oct 4, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3, 2021 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$93,215.98) \$108,407.68) (\$108,407.68) \$120,371.69 (\$120,371.69) \$0.00	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment			
	0200 - 0210	Total CONCRETE SIDEWALK, 4 IN.	Material - T		6 7 7 8	2021 Oct 4, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3, 2021 Nov 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$93,215.98) \$108,407.68) (\$108,407.68) \$120,371.69 (\$120,371.69) (\$120,371.69) \$0.00	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment			
		CONCRETE SIDEWALK, 4			6 7 7 8 8	2021 Oct 4, 2021 Oct 18, 2021 Oct 18, 2021 Nov 3, 2021 Nov 3, 2021 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$93,215.98) \$108,407.68 (\$108,407.68) \$120,371.69 (\$120,371.69) (\$120,371.69) \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user schmijß overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate.			
		CONCRETE SIDEWALK, 4			6 7 7 8 8 8 8	2021 Oct 4, 2021 Oct 18, 2021 Nov 3, 2021 Nov 3, 2021 Aug 3, 2021 Aug 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$93,215.98) \$108,407.68) (\$108,407.68) \$120,371.69 (\$120,371.69) (\$120,371.69) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0005) due to user schmij8 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 4 on the current Payment Estimate.			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S3048	0210	CONCRETE SIDEWALK, 4 IN.	Material		4	Sep 3, 2021	SYSTEM	\$594.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$594.80)	
					5	Sep 16, 2021	SYSTEM	\$1,972.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$1,972.20)	
					6	Oct 4, 2021	SYSTEM	\$2,002.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schmij8 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$2,002.08)	
					7	Oct 18, 2021	SYSTEM	\$2,242.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$2,242.64)	
					8	Nov 3, 2021	SYSTEM	\$25,670.08	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$25,670.08)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0210 -	Total						\$0.00	
	0220	CONCRETE SIDEWALK, 7 IN.	Material		7	Oct 18, 2021	SYSTEM	\$506.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$506.14)	
					8	Nov 3, 2021	SYSTEM	\$2,285.98	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$2,285.98)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0220 -	Total				_		\$0.00	
	0230	MISC. CONCRETE	Material		8	Nov 3, 2021	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$1,400.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0230 -	Total						\$0.00	
	0240	MISC. CONCRETE	Material		2	Aug 3, 2021	SYSTEM	\$3,795.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$3,795.40)	
					3	Aug 17, 2021	SYSTEM	\$9,488.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$9,488.50)	
					4	Sep 3, 2021	SYSTEM	\$18,977.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Sep 2,	SYSTEM	(\$18,977.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
I6S3048	0240	MISC.	Material			2021			
		CONCRETE			5	Sep 16, 2021	SYSTEM	\$30,363.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$30,363.20)	
					6	Oct 4, 2021	SYSTEM	\$39,851.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schmij8 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$39,851.70)	
					7	Oct 18, 2021	SYSTEM	\$41,749.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$41,749.40)	
					8	Nov 3, 2021	SYSTEM	\$41,749.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$41,749.40)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0240 -	Total						\$0.00	
	0270	MISC. CONCRETE	Material		2	Aug 3, 2021	SYSTEM	\$11,173.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$11,173.99)	
					3	Aug 17, 2021	SYSTEM	\$30,368.47	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$30,368.47)	
					4	Sep 3, 2021	SYSTEM	\$50,604.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$50,604.16)	
					5	Sep 16, 2021	SYSTEM	\$73,977.07	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 10 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$73,977.07)	
					6	Oct 4, 2021	SYSTEM	\$128,652.81	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schmij8 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$128,652.81)	
					7	Oct 18, 2021	SYSTEM	\$102,251.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$102,251.80)	
					8	Nov 3, 2021	SYSTEM	\$110,622.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$110,622.22)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0270 -	Total						\$0.00	
	0290	CONCRETE	Material		2	Aug 3,	SYSTEM	\$8,392.12	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J6S3048	0290	CURB (6 IN. HEIGHT AND	Material			2021			Estimate Item Adjustment (0007) due to user aubucj overridding Payment Estimate Exception 23 on the current Payment Estimate.												
		UNDER)			2	Aug 3, 2021	SYSTEM	(\$8,392.12)													
					3	Aug 17, 2021	SYSTEM	\$12,036.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user aubucj overridding Payment Estimate Exception 18 on the current Payment Estimate.												
					3	Aug 16, 2021	SYSTEM	(\$12,036.70)													
					4	Sep 3, 2021	SYSTEM	\$12,644.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 12 on the current Payment Estimate.												
					4	Sep 2, 2021	SYSTEM	(\$12,644.14)													
						5	Sep 16, 2021	SYSTEM	\$14,961.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user aubucj overridding Payment Estimate Exception 12 on the current Payment Estimate.											
									5	Sep 16, 2021	SYSTEM	(\$14,961.96)									
					6	Oct 4, 2021	SYSTEM	\$15,217.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schmij8 overridding Payment Estimate Exception 12 on the current Payment Estimate.												
					6	Oct 4, 2021	SYSTEM	(\$15,217.72)													
					7	Oct 18, 2021	SYSTEM	\$7,827.22	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 19 on the current Payment Estimate.												
					7	Oct 18, 2021	SYSTEM	(\$7,827.22)													
															8	Nov 3, 2021	SYSTEM	\$9,809.36	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user aubucj overridding Payment Estimate Exception 19 on the current Payment Estimate.		
																				8	Nov 3, 2021
				- Total				\$0.00													
			Material - T	otal				\$0.00													
	0290 -							\$0.00													
	0310	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		4	Sep 3, 2021	SYSTEM	\$2,618.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.												
		01122.1)			4	Sep 2, 2021	SYSTEM	(\$2,618.28)													
																	5	Sep 16, 2021	SYSTEM	\$4,550.82	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user aubucj overridding Payment Estimate Exception 13 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$4,550.82)													
																6	Oct 4, 2021	SYSTEM	\$4,737.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schmij8 overridding Payment Estimate Exception 13 on the current Payment Estimate.	
						6	Oct 4, 2021	SYSTEM	(\$4,737.84)												
												7	Oct 18, 2021	SYSTEM	\$103.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment Estimate Exception 20 on the current Payment Estimate.					
			:		7		7	Oct 18, 2021	SYSTEM	(\$103.90)											
					8	8		8		8	8	٤	٤	8	Nov 3, 2021	SYSTEM	\$664.96	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user aubucj overridding Payment			
									Estimate Exception 20 on the current Payment Estimate.												
					8	Nov 3, 2021	SYSTEM	(\$664.96)	Estimate Exception 20 on the current Payment Estimate.												
				- Total	8	Nov 3,	SYSTEM	(\$664.96) \$0.00	Estimate Exception 20 on the current Payment Estimate.												



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
8	0310 -	Total						\$0.00	
	0390	MISC. EMBANKMENT PROTECTION	Material		2	Aug 3, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user aubucj overridding Paymen Estimate Exception 27 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$3,175.29)	
					3	Aug 17, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Paymen Estimate Exception 21 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$3,175.29)	
					4	Sep 3, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Paymen Estimate Exception 16 on the current Payment Estimate.
					4	Sep 2, 2021	SYSTEM	(\$3,175.29)	
					5	Sep 16, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate.
					5	Sep 16, 2021	SYSTEM	(\$3,175.29)	
					6	Oct 4, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schmij8 overridding Payme Estimate Exception 17 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$3,175.29)	
					7	Oct 18, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Paymen Estimate Exception 28 on the current Payment Estimate.
					7	Oct 18, 2021	SYSTEM	(\$3,175.29)	
					8	Nov 3, 2021	SYSTEM	\$3,175.29	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Payment Estimate Exception 27 on the current Payment Estimate.
					8	Nov 3, 2021	SYSTEM	(\$3,175.29)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0390 -	Total						\$0.00	
	0480	MISC.	Material		3	Aug 17, 2021	SYSTEM	\$11,988.10	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Payment Estimate Exception 25 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$11,988.10)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0480 -	Total						\$0.00	
	0490	MISC. TRAFFIC CONTROL	Material		3	Aug 17, 2021	SYSTEM	\$6,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user aubucj overridding Paymer Estimate Exception 26 on the current Payment Estimate.
		DEVICES			3	Aug 16, 2021	SYSTEM	(\$6,400.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0490 -	Total						\$0.00	
	0840	TURF TYPE TALL FESCUE SODDING	Material		6	Oct 4, 2021	SYSTEM	\$7,647.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schmij8 overridding Payme Estimate Exception 20 on the current Payment Estimate.
					6	Oct 4, 2021	SYSTEM	(\$7,647.50)	
					7	Oct 18, 2021	SYSTEM	\$7,647.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user aubucj overridding Paymer



Nov 5, 2021

JASSANA No. P TURE FYOE SOUTIONN SOUTIONN Marcial Field 7 0 0 0.571H 0.571H Charles of the original system-generated Matchell Payment Estimable into digital setting and source integrity original system-generated Matchell Payment Estimable into digital setting and source integrity original system-generated Matchell Payment Estimable into digital setting and source integrity original settin	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	J6S3048	0840	TALL FESCUE	Material		7		SYSTEM	(\$7,647.50)	
Image: space			SODDING			8		SYSTEM	\$7,647.50	Estimate Item Adjustment (0003) due to user aubucj overridding Payment
Image: state in the						8		SYSTEM	(\$7,647.50)	
640-1ctal 0.00 1 0.00 1460 CONCRETE Material 6 2021 SYSTEM 64.150.00 Testimate lism Adjustment officits the original system-generated Material Payment 1460 CONCRETE Material 6 2021 SYSTEM 64.150.00 Status Exception 31 on the current Payment Estimate Status Exception 30 on the curre					- Total				\$0.00	
1400 CONCRETE Material CONCRETE Material B Nov 2, V221 SYSTEM 94.198.00 The adjustment of total system-personal diversitial payment Estimate Exception 31 on the current Payment Estimate. 0 - Total - Total <td></td> <td></td> <td></td> <td>Material - To</td> <td>otal</td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td>				Material - To	otal				\$0.00	
CONCRETE CONCRETE Additional status Estimate leam Adjustment (0013) due to user aduct) overriding Payment Estimate. 1460 - Total - Total 9 'S'S'E' 900 1460 - Total - Total 9 'S'S'E' 900 1460 - Total - Total 9 'S'S'E' 900 1460 - Total - Total 9 'S'S'E' 100 1 - Total 10 'S'S'E' 100 'S'S'E' 1 - Total 10 'S'S'E' 100 'S'S'E' 1 - Total 10 'S'S'E' 100 'S'S'E' 1 - Total 10 'S'S'E' 10 'S'S'		0840 -	Total						\$0.00	
Vertical vert		1460		Material		8		SYSTEM	\$4,158.00	Estimate Item Adjustment (0013) due to user aubucj overridding Payment
Material - Total Social Social Social 5002 TRUNATED DOMES Material - Total 						8		SYSTEM	(\$4,158.00)	
1440 - Total 0 0 18 9002 FRUNCATED Material 0 0 18 SYSTEM 58.076.76 This adjustment offsets the original system-generated Material Payment Estimate 5002 -Total -Tot					- Total				\$0.00	
5002 TRUNCATED DOMES Material Material 7 Oct 18, 2021 SYSTEM S8.676.76 This adjustment (0fields the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 5002 - Total - Total - Total - S000 5002 - Total - Total - S000 5002 - Total - S000 - S000 - S001 - S000 - S000 - S000 - S001 - S000 - S000 - S000 - S002 - Total - S000 - S000 - S001 - S000 - S000 - S000 - S00				Material - To	otal				\$0.00	
Final Problem DOMES DOMES Payment Estimate Estimate Exception 5 on the current Payment Estimate - Total - Total - S000 - S000 - S000 S002 - Total - Total SYSTEM S000 - S000 S002 - Total - S000 - S000 - S000 - S000 S002 - Total - S000 - S000 - S000 - S000 - S000 S002 - Total - S000 - S000 - S000 - S000 - S000 S002 - Total - S000 - S000 - S000 - S000 - S000 S004 - Total - S000 - S000 - S000 - S000 - S000 S004 - Total - Total - S001 - S000 - S000 - S000 S004 - Total - Total - S000 - S000 - S000 - S000 S004 - Total - Total - S000 - S000 - S000 - S000 S004 - Total - Total - S001 - S000 - S000 - S000 S004 - Total - Total		1460 -	Total						\$0.00	
Image: Construct of the construct		5002		Material		7		SYSTEM	\$8,676.76	Estimate Item Adjustment (0014) due to user aubucj overridding Payment
Material - Total 50.00 5002 - Total 50.00 5004 MISC. CONCRETE Material 7 0.01 \$19,656.00 This adjustment (0013) due to user aubuig overridding Payment Estimate Item Adjustment (0013) due to user aubuig overridding Payment Estimate Item Adjustment (0013) due to user aubuig overridding Payment Estimate Item Adjustment (0014) due to user aubuig overridding Payment Estimate Item Adjustment (0014) due to user aubuig overridding Payment Estimate Item Adjustment (0014) due to user aubuig overridding Payment Estimate Item Adjustment (0014) due to user aubuig overridding Payment Estimate Item Adjustment (0014) due to user aubuig overridding Payment Estimate Item Adjustment (0014) due to user aubuig overridding Payment Estimate Item Adjustment (0014) due to user aubuig overridding Payment Estimate Item Adjustment (01615) due to user aubuig overridding Payment Estimate Item Adjustment (01615) due to user aubuig overridding Payment Estimate Item Adjustment (015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to user aubuig overridding Payment Estimate Item Adjustment (0015) due to use						7		SYSTEM	(\$8,676.76)	
5002 - Total 5004 MISC. CONCRETE Material Barriel All T Oct 18, 2021 SYSTEM \$19,656.00 This adjustment offsets the original system-generated Material Payment Estimate liters Adjustment (013) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (014) due to user aubucj overridding Payment Estimate liters Adjustment (016) due to user aubucj overridding Payment Estimate liters Adjustment (016) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment Estimate liters Adjustment (015) due to user aubucj overridding Payment					- Total				\$0.00	
504 MISC CONCRETE Material 7 Oct 18, 2021 SYSTEM \$19,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. 7 Oct 18, 2021 SYSTEM \$19,656.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. 8 Nov 3, 2021 SYSTEM \$24,922.80 This adjustment (0014) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate. 5004 Material - Total 5000 Stote - Total 5000 Stote - Total				Material - To	otal				\$0.00	
CONCRETE CONCRETE Image: Concrete term adjustment (0013) due to user aubucj overridding Payment Estimate Exception 15 on the current Payment Estimate. 7 Oct 18, 2021 SVSTEM (\$19,656.00) 8 Nov 3, 2021 SVSTEM \$24,922.80 This adjustment (0013) due to user aubucj overridding Payment Estimate Exception 15 on the current Payment Estimate. 8 Nov 3, 2021 SVSTEM \$24,922.80 This adjustment (0014) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate. 8 Nov 3, 2021 SVSTEM \$24,922.80 This adjustment (0014) due to user aubucj overridding Payment Estimate Exception 16 on the current Payment Estimate. 8 Nov 3, 2021 SVSTEM \$24,922.80 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 8 Nov 3, 2021 SVSTEM \$8,87.62 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 500 Material - Total 7 Oct 18, SYSTEM \$8,87.62 This adjustment offsets the original system-generated Material Payment Estimate Exception 23 on the current Payment Estimate. 600 - Total S0021 SVSTEM \$8,608.25 <td></td> <td>5002 -</td> <td>Total</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>\$0.00</td> <td></td>		5002 -	Total						\$0.00	
 		5004		Material		7		SYSTEM	\$19,656.00	Estimate Item Adjustment (0013) due to user aubucj overridding Payment
Image: biologic						7		SYSTEM	(\$19,656.00)	
Image: bit in the stand in the sta						8		SYSTEM	\$24,922.80	Estimate Item Adjustment (0014) due to user aubucj overridding Payment
S004 - Total \$0.00 5006 - Total \$0.00						8		SYSTEM	(\$24,922.80)	
5004 - Total \$0.00 5006 MISC. PAVED Material 7 Oct 18, 2021 \$YSTEM \$8,878.62 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user aubucj overridding Payment Estimate. 7 Oct 18, 2021 \$YSTEM \$\$8,878.62 This adjustment offsets the original system-generated Material Payment Estimate. 8 Nov 3, 2021 \$YSTEM \$\$9,608.25 This adjustment offsets the original system-generated Material Payment Estimate. 0 -Total \$\substrait \$\substrait \$\$\substrait \$\$\substrait 6006 - Total \$\substrait \$\substrait \$\$\substrait \$\$\substrait \$\$\substrait J653048 - Total \$\$\substrait \$\$\substrait \$\$\substrait \$\$\substrait \$\$\substrait					- Total				\$0.00	
5006 MISC. PAVED DRAINAGE Material Image: Fourier of the second condition				Material - To	otal				\$0.00	
DRAINAGE DRAINAGE 2021		5004 -	Total						\$0.00	
Image: Provide the second se		5006		Material		7		SYSTEM	\$8,878.62	Estimate Item Adjustment (0015) due to user aubucj overridding Payment
Image: Solution of the second secon						7		SYSTEM	(\$8,878.62)	
J021 \$0.00 -Total \$0.00 Material - Total \$0.00 5006 - Total \$0.00 J6S3048 - Total \$0.00						8		SYSTEM	\$9,608.25	Estimate Item Adjustment (0015) due to user aubucj overridding Payment
Material - Total \$0.00 5006 - Total \$0.00 J6S3048 - Total \$0.00						8		SYSTEM	(\$9,608.25)	
5006 - Total \$0.00 J6S3048 - Total \$0.00					- Total				\$0.00	
J6S3048 - Total \$0.00				Material - T	otal				\$0.00	
		5006 -	Total						\$0.00	
Overall - Total \$0.00	J6S3048	- Total							\$0.00	
	Overall -	Total							\$0.00	