

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 16, 2022

Progress Estimate N	lumber	Contract ID Prime Contracto	210521-D04 r Concrete Strate	gies, LLC	Pay Period Start Pay Period End		22 Original Contract Amount 22 Net Change Order Amount 22 Current Contract Amount	\$1,611,862.60 \$342,622.18 \$1,954,484.78		
Approval Date								By User		
May 16, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level									
May 16, 2022		R	Reviewed and Appro	oved (and	should be considered	ed Draft) at	the Resident Engineer Level by	grahac1		
May 17, 2022				Reviewed	and Approved at the	e Central O	ffice Controllers Office Level by	ramses1		
Original Completion Date Current Completion Date Actual Completion Date % of Current Contract A										
December 1, 20	21	January	31, 2022	1, 2022 93.14						
	Contract	Informational Dat	es		Milesto	nes				
Date Description	Original	Completion Date	<b>Current Complet</b>	ion Date	No Milestones Exi	ist for Contr	act			
Acceptance Date										
Awarded Date June 2, 2021 June 2, 2021										
Letting Date	May 21, 2021 May 21, 2021									
Notice to Proceed Date	July 6, 20	)21	July 6, 2021							
Open to Traffic Date										

Contract Total Pay For Estimate No. 17			
	This Estimate	Previous	To Date
210521-D04			
Total Posted Items Pay	\$44,797.50	\$1,775,567.43	\$1,820,364.93
Gross Item Adjustments	\$1,778.75	(\$32,786.35)	(\$31,007.60)
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$1,742,781.08	\$1,789,357.33
Contract Total Payable This Estimate:	\$46,576.25		
	•		

September 7, 2021

#### Items Paid This Estimate Period

Work Began Date

September 7, 2021

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3239	0160	6233000	EPOXY POLYMER WEARING SURFACE	\$44,797.50			
Project J5S3239	- Total						\$44,797.50
Overall - Total							\$44,797.50

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3239	0150	LATEX MODIFIED CONCRETE WEARING SURFACE	Other Item Adjustment	Substandard Item	Estimate 17 Removal of Adjustment made on Estimate 6 Corrections have been made to inverted cross slopes in the bridge deck			\$24,177.50
	0160	EPOXY POLYMER WEARING SURFACE	Other Item Adjustment	Material Discrepancy Payment Adjustment	Estimate 17 50% payment for labor. Adjustment will be removed once certs are received \$44,797.50 x 0.50 = \$22,398.75			\$22,398.75
	0160	EPOXY POLYMER WEARING SURFACE	Material			-990	\$45.25	(\$44,797.50)
	0210	MISC.	Material			-15	\$584.00	(\$8,760.00)
	0210	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	15	\$584.00	\$8,760.00

Revision 4/1/2020 Page 1 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: May 16, 2022

Progre		timate Number 17	Contract ID Prime Cont		21-D04 rete Strategies,	Pay Period Start May 2, 2022 Origi LLC Pay Period End May 15, 2022 Net C Curre		Amount \$	1,611,862.60 342,622.18 1,954,484.78
Project Number	Line No.	Item Descr	iption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
Total									\$1,778.75

Revision 4/1/2020 Page 2 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number Proj. Number Route County Location of Work												
J5S3239	FAS S402(3)	Bridge rehabilitation	BR 54	MILLER	on the Bagnell Dam bridge in Lake Ozark							

#### 

Revision 4/1/2020 Page 3 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3239, Item 6233000, Project Item Line Number 0160, Material Set 623300096, Material 1039ERPC - Epoxy Resin Mat for Polymer Conc Overlay, Acceptance Action Generic 1039ERPC is insufficient.	Waiting on Contractor to send certs	graesj1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5S3239, Item 6233000, Project Item Line Number 0160, Material Set 623300096, Material 1039AGPC - Aggregate for Epoxy Polymer Conc Overlay, Acceptance Action Generic 1039AGPC is insufficient.	Waiting on Contractor to send certs	graesj1	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J5S3239, Item 7129902, Project Item Line Number 0210, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Report needed by MoDOT Bridge	graesj1	Overridden
Estimate Exception Type: Item Overrun: Contract 210521-D04, Contract Project J5S3239, Project Item Line Number 0200, Contract Line Item Number 0200, Item 7049903, Minor Item.	Waiting on Contractor to send back Change Order	graesj1	Acknowledged

Revision 4/1/2020 Page 4 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10521-D04	J5S3239	0001	0010	6161005	CONSTRUCTION SIGNS	504.00	4.00	508.00	SQFT	508.00	\$8.90	\$4,521.2
		0001	0020	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$39.00	\$156.0
		0001	0030	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$28.00	\$56.0
		0001	0040	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	12.00	\$173.00	\$2,076.0
		0001	0050	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	1.00	3.00	EA	3.00	\$3,600.00	\$10,800.0
		0001	0060	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$225,000.00	\$225,000.0
		0070	0070	2161001	TOTAL SURFACE HYDRO DEMOLITION	4,936.00	0.00	4,936.00	SQYD	4,936.00	\$39.50	\$194,972.0
		0070	0080	2161502	REMOVAL OF CONCRETE WEARING SURFACE	44,424.00	0.00	44,424.00	SQFT	44,424.00	\$2.75	\$122,166.0
		0070	0090	2161503	REMOVAL OF EXISTING DECK REPAIR	500.00	4,563.00	5,063.00	SQFT	5,063.00	\$18.75	\$94,931.2
		0070	0100	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	103.00	0.00	103.00	LF	82.00	\$111.00	\$9,102.0
		0070	0110	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	1,360.00	0.00	1,360.00	LF	1,360.00	\$3.25	\$4,420.0
		0070	0120	2169901	MISC.REMOVAL OF EXISTING BARRIER CURB JOINT MATERIAL CONTAINING ASBESTOS	1.00	0.00	1.00	LS	1.00	\$16,900.00	\$16,900.0
0070 0130 2169902			0130	2169902	MISC.REMOVAL OF EXISTING BARRIER CURB PROTRUSION	24.00	0.00	24.00	EA	24.00	\$730.00	\$17,520.
		0070	0140	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	35.00	205.00	240.00	CY	225.00	\$700.00	\$157,500.
		0070	0150	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	4,936.00	0.00	4,936.00	SQYD	4,936.00	\$95.00	\$468,920.
		0070	0160	6233000	EPOXY POLYMER WEARING SURFACE	2,568.00	0.00	2,568.00	SQYD	990.00	\$45.25	\$44,797.
		0070	0170	7040104	HALF-SOLE REPAIR	1,564.00	0.00	1,564.00	SQFT	1,375.00	\$56.75	\$78,031.
		0070	0180	7040106	FULL DEPTH REPAIR	400.00	0.00	400.00	SQFT	146.50	\$153.00	\$22,414.
		0070	0190	7049903	MISC.CONCRETE BARRIER CURB REPAIR	25.00	0.00	25.00	LF	23.30	\$688.00	\$16,030.
		0070	0200	7049903	MISC.CURB REPAIR	505.00	0.00	505.00	LF	525.00	\$61.00	\$32,025.0
		0070	0210	7129902	MISC.SLIDE PLATE REPLACEMENT	15.00	0.00	15.00	EA	15.00	\$584.00	\$8,760.0
		0070	0220	7129903	MISC.SINGLE TUBE HANDRAIL	1,702.00	0.00	1,702.00	LF	1,702.00	\$72.50	\$123,395.0
		0070	0230	7172054	OPEN CELL FOAM JOINT SEAL	1,464.00	0.00	1,464.00	LF	1,453.00	\$38.50	\$55,940.8
		0070	5001	5059901	MISC.LATEX MODIFIED CONCRETE WEARING SURFACE - PUMP PLACEMENT	0.00	1.00	1.00	LS	1.00	\$57,303.95	\$57,303.9
		0070	5002	2169901	MISC.REMOVAL OF EXISTING DECK REPAIRS	0.00	1.00	1.00	LS	1.00	\$47,465.63	\$47,465.
		0070	5003	2169901	MISC.HYDRO DEMOLITION - TEST SECTION	0.00	1.00	1.00	LS	1.00	\$5,160.75	\$5,160.7
	Project J	5S3239 - To	otal Value	Posted to	Date as of Report Generated Date							\$1,820,364.9
0521-D04 Ove	erall - Total	Value Post	ted to Dat	te as of Re	port Generated Date							\$1,820,36

Revision 4/1/2020 Page 5 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### $\underline{\textbf{The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.}$

Project: J5S3239

Line Number	Item Code	Description		DWR Approval Date		Units		Offset/ Distance		Comments
0160	6233000	EPOXY POLYMER WEARING SURFACE	5/11/22	5/12/22	990.00	SQYD	Roadway through Headworks			

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 6 of 12



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239	0010	CONSTRUCTION SIGNS	Material	Type	1	Sep 16, 2021	SYSTEM	\$4,523.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user graesj1 overridding Payment
					1	Sep 16, 2021	SYSTEM	(\$4,523.25)	Estimate Exception 1 on the current Payment Estimate.
				- Total		2021		\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun	1	Sep 16, 2021	SYSTEM	\$37.65	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 508.230; Overrun Quantity Balance 4.23.
					1	Sep 16, 2021	SYSTEM	(\$37.65)	
					2	Oct 4, 2021	SYSTEM	(\$37.65)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Dec 3, 2021	SYSTEM	\$37.65	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.90000 - 8.90000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0010 -	Total						\$0.00	
	0020	ADVANCED WARNING RAIL SYSTEM	Material		1	Sep 16, 2021	SYSTEM	\$156.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$156.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0020 -	Total						\$0.00	
	0030	FLAG ASSEMBLY	Material		1	Sep 16, 2021	SYSTEM	\$56.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user graesj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$56.00)	
				- Total				\$0.00	
		_	Material - Tota	1				\$0.00	
	0030 -							\$0.00	
	0040	TYPE III MOVEABLE BARRICADE	Material		1	Sep 16, 2021	SYSTEM	\$2,076.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$2,076.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0040 -							\$0.00	
	0050	CMS WITH COMMUNICATION INTERFACE, CONT F	Material		1	Sep 16, 2021	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		331			1	Sep 16, 2021	SYSTEM	(\$10,800.00)	
				- Total				\$0.00	
			Material - Tota				2)12==	\$0.00	
			Overrun	Overrun	1	Sep 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.
					1	Sep 16, 2021	SYSTEM	(\$3,600.00)	
					2	Oct 4, 2021	SYSTEM	(\$3,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
						6	Dec 3, 2021	SYSTEM	\$3,600.00
				Overrun - To	otal			\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J5S3239	0050	CMS WITH COMMUNICATION INTERFACE, CONT F	Overrun - Tota	ıl				\$0.00					
	0050 -	Total						\$0.00					
	0090	REMOVAL OF EXISTING DECK	Overrun	Overrun	3	Oct 18, 2021	SYSTEM	(\$12,375.00)					
		REPAIR			4	Nov 2, 2021	SYSTEM	(\$5,043.75)					
					6	Dec 3, 2021	SYSTEM	\$17,418.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',18.75000 - 18.75000, 'is applied (if non-zero).				
				Overrun - T	otal			\$0.00					
			Overrun - Tota	ıl				\$0.00					
	0090 -	Total						\$0.00					
	0120	MISC. REMOVALS	Other Item Adjustment	OTHR	1	Sep 16, 2021	graesj1	(\$4,225.00)	Estimate 1 Removal of 25% payment until waste shipment record is received0.25 x \$16,900 = -\$4,225				
					3	Oct 18, 2021	graesj1	\$4,225.00	Estimate 3 removal of line item adjustment made on Estimate 1 Waste Shipment Record has been received.				
				OTHR - Tota				\$0.00					
			Other Item Ad	ustment - To	tal			\$0.00					
	0120 - 0140	SUPPLEMENTARY WEARING	Material		5	Nov 16, 2021	SYSTEM	\$0.00 (\$49,700.00)					
		SURFACE MATERIAL			6	Dec 3, 2021	SYSTEM	(\$135,800.00)					
				- Total		2021		(\$185,500.00)					
			Material - Tota					(\$185,500.00)	Estimate 1 Removal of 25% payment until waste shipment record is received0.25 x \$16,900 = -\$4,225  Estimate 3 removal of line item adjustment made on Estimate 1 Waste Shipment Record has been received.  \$0.00				
			MaterialCredit		6	Dec 3, 2021	SYSTEM	\$49,700.00	0)				
					7	Dec 16, 2021	SYSTEM	\$135,800.00					
				- Total				\$185,500.00					
			MaterialCredit	- Total				\$185,500.00					
			Overrun	Overrun		Nov 16, 2021	SYSTEM	\$25,200.00	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 71.000;				
					5	Nov 16, 2021	SYSTEM	(\$25,200.00)					
				Overrun - T	otal			\$0.00					
			Overrun - Tota					\$0.00					
	0140 -							\$0.00					
	0150	LATEX MODIFIED CONCRETE WEARING	Material		5	Nov 16, 2021	SYSTEM	(\$138,130.00)					
		SURFACE			6	Dec 3, 2021	SYSTEM	\$368,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					6	Dec 3, 2021	SYSTEM	(\$368,315.00)					
				- Total				(\$138,130.00)					
			Material - Tota					(\$138,130.00)					
			MaterialCredit		6	Dec 3, 2021	SYSTEM	\$138,130.00					
			84-4i10	- Total				\$138,130.00					
			MaterialCredit		7	D- 15		\$138,130.00	Editoria 7 Percent of editoria				
			Other Item Adjustment	OTHR Total		Dec 16, 2021	graesj1	\$184,157.50	Estimate 7 Removal of adjustment made on estimate 6 for not reporting required material samples				
				OTHR - Total		Dog 2	gressid	\$184,157.50	50% Dodust due Contractor not reporting yearsign and significant				
				PPP3	U	Dec 3, 2021	graesj1	(\$184,157.50)	50% Deduct due Contractor not reporting required material samples				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J5S3239	0150	LATEX MODIFIED	Other Item	PPPS - Tota	ı			(\$184,157.50)								
		CONCRETE WEARING SURFACE	Adjustment	SUBI	6	Dec 3, 2021	graesj1	(\$24,177.50)	10% Deduct for Inverted Cross Slope Pours 1, 2 & 3, Bent 1 to Bent 29 2545 SY x \$95 x -0.10 = - \$24,177.5 See NCR 001 for more details Deduction will be paid back after corrections have been made							
					17	May 16, 2022	graesj1	\$24,177.50	Estimate 17 Removal of Adjustment made on Estimate 6 Corrections have been made to inverted cross slopes in the bridge deck							
				SUBI - Total				\$0.00								
			Other Item Ad	justment - To	tal			\$0.00								
	0150 -	Total						\$0.00								
	0160	EPOXY POLYMER WEARING	Material		17	May 16, 2022	SYSTEM	(\$44,797.50)								
		SURFACE		- Total				(\$44,797.50)								
			Material - Tota	ıl				(\$44,797.50)								
			Other Item Adjustment	MDPA	17	May 16, 2022	graesj1	\$22,398.75	Estimate 17 50% payment for labor. Adjustment will be removed once certs are received \$44,797.50 x 0.50 = \$22,398.75							
				MDPA - Tota	al			\$22,398.75								
			Other Item Ad	justment - To	tal			\$22,398.75								
	0160 -	Total						(\$22,398.75)								
	0170	HALF-SOLE REPAIR	Material		10	Feb 1, 2022	SYSTEM	\$60,495.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
												10	Feb 1, 2022	SYSTEM	(\$60,495.50)	
						11	Feb 16, 2022	SYSTEM	\$60,495.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.						
											11	Feb 16, 2022	SYSTEM	(\$60,495.50)		
					12	Mar 2, 2022	SYSTEM	\$73,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					12	Mar 2, 2022	SYSTEM	(\$73,548.00)								
					13	Mar 16, 2022	SYSTEM	\$73,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					13	Mar 16, 2022	SYSTEM	(\$73,548.00)								
				- Total				\$0.00								
			Material - Tota	il				\$0.00								
			Other Item Adjustment	SUBI	15	Apr 15, 2022	graesj1	(\$7,388.85)	Estimate 15 10% Deduction for not curing concrete 1302 SF x \$56.75 x -10% = -\$7,388.85							
				SUBI - Total				(\$7,388.85)								
			Other Item Ad	justment - To	tal			(\$7,388.85)								
	0170 -	Total						(\$7,388.85)								
	0180	FULL DEPTH REPAIR	Material		8	Jan 4, 2022	SYSTEM	\$12,775.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					8	Jan 4, 2022	SYSTEM	(\$12,775.50)								
					9	Jan 18, 2022	SYSTEM	\$12,775.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					9	Jan 18, 2022	SYSTEM	(\$12,775.50)								
					11	Feb 16, 2022	SYSTEM	\$22,414.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
						11	Feb 16, 2022	SYSTEM	(\$22,414.50)							
					12	Mar 2,	SYSTEM	\$22,414.50	This adjustment offsets the original system-generated Material Payment							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239	0180	FULL DEPTH REPAIR	Material			2022			Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Mar 2, 2022	SYSTEM	(\$22,414.50)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0180 - Total							\$0.00	
	0190	MISC.	Material		13	Mar 16, 2022	SYSTEM	\$16,030.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Mar 16, 2022	SYSTEM	(\$16,030.40)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0190 - Total							\$0.00	
	0200	MISC.	Material		10	Feb 1, 2022	SYSTEM	\$32,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Feb 1, 2022	SYSTEM	(\$32,025.00)	
					11	Feb 16, 2022	SYSTEM	\$32,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Feb 16, 2022	SYSTEM	(\$32,025.00)	
					12	Mar 2, 2022	SYSTEM	\$32,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user graesj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Mar 2, 2022	SYSTEM	(\$32,025.00)	
					13	Mar 16, 2022	SYSTEM	\$32,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Mar 16, 2022	SYSTEM	(\$32,025.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Other Item Adjustment	OTHR	10	Feb 1, 2022	graesj1	(\$1,220.00)	Estimate 10 adjustment to offset system override of overrun 525 LF (measured) - 505 LF (plan) x \$61 = -\$1220 Will be removed once change order is approved
					14	Apr 4, 2022	veasms1	\$1,220.00	Estimate 14 removal of adjustment made on estimate 10 overrun acknowledged on estimate 14
				OTHR - Tota	al			\$0.00	
			Other Item Ad	djustment - Total				\$0.00	
			Overrun	Overrun		Feb 1, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
					10	Feb 1, 2022	SYSTEM	(\$1,220.00)	
					11	Feb 16, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					11	Feb 16, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
					12	Mar 2, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					12	Mar 2, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
					13	Mar 16, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates
					13	Mar 16,	SYSTEM	\$1,220.00	of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment
						2022			Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7



	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239 0200	MISC.	Overrun	Overrun					on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
				14	Apr 4, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
			Overrun - To	otal			(\$1,220.00)	
		Overrun - Total					(\$1,220.00)	
0200 -	0200 - Total							
0210	MISC.	Material		15	Apr 15, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				15	Apr 15, 2022	SYSTEM	(\$8,760.00)	
				16	May 2, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				16	May 2, 2022	SYSTEM	(\$8,760.00)	Estimate Exception 1 on the durint 1 dynam Estimate.
				17	May 16, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment
				17	May 16,	SYSTEM	(\$8,760.00)	Estimate Exception 3 on the current Payment Estimate.
			- Total		2022		\$0.00	
		Material - Tota					\$0.00	
0210 -	Total	Materiar - 10tal					\$0.00	
0220	MISC. STRUCTURAL STEEL CONSTRUCTION	Material		10	Feb 1, 2022	SYSTEM	\$106,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
				10	Feb 1, 2022	SYSTEM	(\$106,575.00)	
				11	Feb 16, 2022	SYSTEM	\$123,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user graesj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
				11	Feb 16, 2022	SYSTEM	(\$123,395.00)	
			- Total				\$0.00	
		Material - Tota					\$0.00	
	0220 - Total							
0230	OPEN CELL FOAM JOINT SEAL	Material		11	Feb 16, 2022	SYSTEM	(\$3,234.00)	
				12	Mar 2, 2022	SYSTEM	(\$3,234.00)	
				13	Mar 16, 2022	SYSTEM	(\$15,746.50)	
			- Total				(\$22,214.50)	
		Material - Tota					(\$22,214.50)	
		MaterialCredit		12	Mar 2, 2022	SYSTEM	\$3,234.00	
				13	Mar 16, 2022	SYSTEM	\$3,234.00	
			Total	14	Apr 4, 2022	SYSTEM	\$15,746.50	
		MaterialCredit	- Total				\$22,214.50	
		Other Item Adjustment	MDPA	13	Mar 16, 2022	graesj1	\$22,214.50 \$6,256.25	Estimate 13, PAL number was not requested for material resulting in discrepancy. 50% Payment for labor of installment.
				14	Apr 4, 2022	veasms1	(\$6,256.25)	Estimate 14 removal of adjustment made on estimate 13 PAL number received
			MDPA - Total				\$0.00	
		Other Item Adjustment - Total					\$0.00	
	Total					\$0.00		



May 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239 - Total									
Overall -	Total					(\$31,007.60)			