

Pay Estimate Created Date: June 30, 2022

Progress Estimate N 19	lumber	Contract ID Prime Contracto	Contract ID 210521-D04 Prime Contractor Concrete Strategies, LLC			June 2, 2022 June 30, 2022	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,611,862.60 \$284,805.93 \$1,896,668.53
Approval Date								By User
June 30, 2022			Generated and	Approved	(and should be con	sidered Draft) a	t the Project Office Level by	graesj1
June 30, 2022		F	Reviewed and Appro	oved (and	should be considered	ed Draft) at the	Resident Engineer Level by	grahac1
July 5, 2022				Reviewed	and Approved at th	e Central Office	e Controllers Office Level by	ramses1
Original Completion	n Date	Current Cor	npletion Date	Actu	al Completion Dat	e %	of Current Contract Amoun	t Complete
December 1, 202	21	January	31, 2022				99.82%	
	Contract	Informational Dat	tes		Milesto	ones		
Date Description	Original	Completion Date	Current Complet	ion Date	No Milestones Ex	ist for Contract		
Acceptance Date								
Awarded Date	June 2, 2	2021	June 2, 2021					
Letting Date	May 21, 2	2021	May 21, 2021					
Notice to Proceed Date	tice to Proceed Date July 6, 2021 July 6, 2021							
Open to Traffic Date								
Work Began Date	Septemb	er 7, 2021	September 7, 202	1				

Contract Total Pay For Estimate No. 19 This Estimate Previous To Date 210521-D04 \$1,893,192.03 (\$19,228.85) \$0.00 \$0.00 **\$72,827.10** (**\$1,860.00)** \$0.00 \$1,820,364.93 (\$17,368.85) Total Posted Items Pay Gross Item Adjustments \$0.00 Incentive \$0.00 \$0.00 Disincentive Liquidated Damage \$0.00 \$0.00 \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$1,802,996.08 \$1,873,963.18 Contract Total Payable This Estimate: \$70,967.10

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5S3239	0160	6233000	EPOXY POLYMER WEARING SURFACE	SQYD	\$45.250	1,614	\$73,033.50
	0190	7049903	MISC.CONCRETE BARRIER CURB REPAIR	LF	\$688.000	-0.3	(\$206.40)
Project J5S3239	- Total						\$72,827.10
Overall - Total							\$72,827.10

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	rajaoti	nents mis Estinate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5S3239	0200	MISC.	Overrun		Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.00000 - 61.00000, 'is applied (if non-zero).	20	\$61.00	\$1,220.00
	0210	MISC.	MaterialCredit			15	\$584.00	\$8,760.00
	0210	MISC.	Material			-15	\$584.00	(\$8,760.00)
	0230	OPEN CELL FOAM JOINT SEAL	Other Item Adjustment	Other	Estimate 19 adjustment for damaged emseal requiring replacement adjustment will be removed once emseal is replaced 80 ft. * \$38.50 / LF = \$3,080			(\$3,080.00)
Total								(\$1,860.00)



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

						Contract Project Informatio	n									
Project Number	Federal Proj. Number	Description	Route	County		Location of Work										
J5S3239	FAS S402(3)	Bridge rehabilitation	BR 54	MILLER	on the Bagnell Dam bridge in Lake Ozark											
Totals by J	Job Numb	ers														
J5S3239		ed Item Pay ss Item Adjustn		<mark>s Item Pay</mark>	This Estimate \$72,827.10 (\$1,860.00) \$70,967.10	Previous \$1,820,364.93 (\$17,368.85) \$1,802,996.08	To Date \$1,893,192.03 (\$19,228.85) \$1,873,963.18									
	Liqu	ntive ncentive idated Damage er Contract Adju		3	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00									

Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5S3239, Item 7129902, Project Item Line Number 0210, Material Set 7129902, Material 1080BRM - Bridge Material, Acceptance Action Generic 1080BRM is insufficient.	Certification is required from contractor	graesj1	Acknowledged



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10521-D04	J5S3239	0001	0010	6161005	CONSTRUCTION SIGNS	504.00	4.00	508.00	SQFT	508.00	\$8.90	\$4,521.20
		0001	0020	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$39.00	\$156.00
		0001	0030	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$28.00	\$56.00
		0001	0040	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	12.00	\$173.00	\$2,076.00
		0001	0050	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	1.00	3.00	EA	3.00	\$3,600.00	\$10,800.00
		0001	0060	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$225,000.00	\$225,000.00
		0070	0070	2161001	TOTAL SURFACE HYDRO DEMOLITION	4,936.00	0.00	4,936.00	SQYD	4,936.00	\$39.50	\$194,972.00
		0070	0080	2161502	REMOVAL OF CONCRETE WEARING SURFACE	44,424.00	0.00	44,424.00	SQFT	44,424.00	\$2.75	\$122,166.00
		0070	0090	2161503	REMOVAL OF EXISTING DECK REPAIR	500.00	4,563.00	5,063.00	SQFT	5,063.00	\$18.75	\$94,931.25
		0070	0100	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	103.00	-21.00	82.00	LF	82.00	\$111.00	\$9,102.00
		0070	0110	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	1,360.00	0.00	1,360.00	LF	1,360.00	\$3.25	\$4,420.00
		0070	0120	2169901	MISC.REMOVAL OF EXISTING BARRIER CURB JOINT MATERIAL CONTAINING ASBESTOS	1.00	0.00	1.00	LS	1.00	\$16,900.00	\$16,900.00
		0070	0130	2169902	MISC.REMOVAL OF EXISTING BARRIER CURB PROTRUSION	24.00	0.00	24.00	EA	24.00	\$730.00	\$17,520.00
		0070	0140	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	35.00	190.00	225.00	CY	225.00	\$700.00	\$157,500.00
		0070 0150 5052000 LAT	LATEX MODIFIED CONCRETE WEARING SURFACE	4,936.00	0.00	4,936.00	SQYD	4,936.00	\$95.00	\$468,920.00		
		0070	0160	6233000	EPOXY POLYMER WEARING SURFACE	2,568.00	36.00	2,604.00	SQYD	2,604.00	\$45.25	\$117,831.0
		0070	0170	7040104	HALF-SOLE REPAIR	1,564.00	-189.00	1,375.00	SQFT	1,375.00	\$56.75	\$78,031.25
		0070	0180	7040106	FULL DEPTH REPAIR	400.00	-253.00	147.00	SQFT	146.50	\$153.00	\$22,414.50
		0070	0190	7049903	MISC.CONCRETE BARRIER CURB REPAIR	25.00	-2.00	23.00	LF	23.00	\$688.00	\$15,824.00
		0070	0200	7049903	MISC.CURB REPAIR	505.00	20.00	525.00	LF	525.00	\$61.00	\$32,025.00
		0070	0210	7129902	MISC.SLIDE PLATE REPLACEMENT	15.00	0.00	15.00	EA	15.00	\$584.00	\$8,760.00
		0070	0220	7129903	MISC.SINGLE TUBE HANDRAIL	1,702.00	0.00	1,702.00	LF	1,702.00	\$72.50	\$123,395.00
		0070	0230	7172054	OPEN CELL FOAM JOINT SEAL	1,464.00	-11.00	1,453.00	LF	1,453.00	\$38.50	\$55,940.50
		0070	5001	5059901	MISC.LATEX MODIFIED CONCRETE WEARING SURFACE - PUMP PLACEMENT	0.00	1.00	1.00	LS	1.00	\$57,303.95	\$57,303.9
		0070	5002	2169901	MISC.REMOVAL OF EXISTING DECK REPAIRS	0.00	1.00	1.00	LS	1.00	\$47,465.63	\$47,465.63
		0070	5003	2169901	MISC.HYDRO DEMOLITION - TEST SECTION	0.00	1.00	1.00	LS	1.00	\$5,160.75	\$5,160.7
		0070	5004	7040113	CLEANING AND EPOXY COATING	0.00	40.00	40.00	SQFT	0.00	\$85.00	\$0.00
	Project J	5S3239 - To	otal Value	Posted to	Date as of Report Generated Date							\$1,893,192.03
10521-D04 Ove	erall - Total	Value Post	ted to Da	te as of Re	port Generated Date							\$1,893,192.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project:	J5S3239)										
Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0160	6233000	EPOXY POLYMER WEARING SURFACE	6/14/22	6/16/22	95.50	SQYD	1st lift of sidewalk, curb, and barrier wall					900 ft. x 3.75 ft. / 9 = 375 SY * 50% for 1st lift * 50% for labor until pull test) = 93.75 SY 14 x 4.5 SF / 9 = 7 SY * 50% for 1st lift * 50% for labor until pull test) = 1.75 SY
			6/16/22	6/21/22	286.50	SQYD	Sidewalk and Barrier Wall from East Abutment to Bent 1					382 SY (Sidewalk and Barrier wall) - 95.5 SY (Paid for 1st lift) = 286.5 SY Second Lift (100% payment)
			6/22/22	6/27/22	719.00	SQYD	Sidewalk Bent 1 to West Abutment					1700ft. x 3.75ft / 9 = 708.3 SY 22 x 4.5 SF / 9 = 11 SY
			6/27/22	6/28/22	513.00	SQYD	Second Lift of Curb and Barrier Wall					Payment to Plan
0190	7049903	MISC.	6/30/22	6/30/22	-0.30	LF	Final Rounding					

The information below this line are details for Construction Signs (if applicable). No Data Available



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239	0010	CONSTRUCTION SIGNS	Material		1	Sep 16, 2021	SYSTEM	\$4,523.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$4,523.25)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Overrun	Overrun	1	Sep 16, 2021	SYSTEM	\$37.65	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 508.230; Overrun Quantity Balance 4.23.
					1	Sep 16, 2021	SYSTEM	(\$37.65)	
					2	Oct 4, 2021	SYSTEM	(\$37.65)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Dec 3, 2021	SYSTEM	\$37.65	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.90000 - 8.90000, 'is applied (if non-zero).
	Overrun - Tot			Overrun - T	otal			\$0.00	
			Overrun - Tota					\$0.00	
	0010 -	Total						\$0.00	
	0020	ADVANCED WARNING RAIL SYSTEM	Material		1	Sep 16, 2021	SYSTEM	\$156.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$156.00)	
				- Total				\$0.00	
			Material - Total	I				\$0.00	
	0020 -	Total						\$0.00	
	0030	FLAG ASSEMBLY	Material		1	Sep 16, 2021	SYSTEM	\$56.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user graesj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$56.00)	
				- Total				\$0.00	
			Material - Total	I				\$0.00	
	0030 -							\$0.00	
	0040	TYPE III MOVEABLE BARRICADE	Material		1	Sep 16, 2021	SYSTEM	\$2,076.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$2,076.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0040 -							\$0.00	
	0050	CMS WITH COMMUNICATION INTERFACE, CONT F	Material		1	Sep 16, 2021	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$10,800.00)	
				- Total				\$0.00	
			Material - Total		4	Par 40	OVOTEN	\$0.00	This adjustment effects the science in the second
			Overrun	Overrun	1	Sep 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.
					1	Sep 16, 2021	SYSTEM	(\$3,600.00)	
					2	Oct 4, 2021	SYSTEM	(\$3,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Dec 3, 2021	SYSTEM	\$3,600.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3600.00000 - 3600.00000, 'is applied (if non-zero).
	C			Overrun - T	otal			\$0.00	



Jul 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J5S3239	0050	CMS WITH COMMUNICATION INTERFACE, CONT F	Overrun - Tota					\$0.00			
	0050 -	Total						\$0.00			
	0090	REMOVAL OF EXISTING DECK	Overrun	Overrun	3	Oct 18, 2021	SYSTEM	(\$12,375.00)			
		REPAIR			4	Nov 2, 2021	SYSTEM	(\$5,043.75)			
					6	Dec 3, 2021	SYSTEM	\$17,418.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',18.75000 - 18.75000, 'is applied (if non-zero).		
				Overrun - T	otal			\$0.00			
			Overrun - Tota					\$0.00			
	0090 -	Total						\$0.00			
	0120	MISC. REMOVALS	Other Item	OTHR	1	Sep 16,	graesj1	(\$4,225.00)	Estimate 1 Removal of 25% payment until waste shipment record is received.		
	0120	MISC. REMOVALS	Adjustment	OTTIK	3	2021 Oct 18,	graesj1	\$4,225.00	-0.25 x \$16,900 = -\$4,225 Estimate 3 removal of line item adjustment made on Estimate 1		
				OTHR - Tota		2021	graesji	φ 4 ,223.00 \$0.00	Waste Shipment Record has been received.		
			Other Item Ad					\$0.00			
	0120 -	Total	Other item Auj	usuneni - To	lai			\$0.00			
		SUPPLEMENTARY WEARING	Material		5	Nov 16,	SYSTEM	(\$49,700.00)			
		SURFACE			6	2021 Dec 3,	SYSTEM	(\$135,800.00)			
				- Total		2021		(\$185,500.00)			
			Material - Tota	I				(\$185,500.00)			
			MaterialCredit	MaterialCredit	MaterialCredit		6	Dec 3, 2021	SYSTEM	\$49,700.00	
					7	Dec 16, 2021	SYSTEM	\$135,800.00			
				- Total				\$185,500.00			
			MaterialCredit	- Total				\$185,500.00			
			Overrun	Overrun		Nov 16, 2021	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 71.000; Overrun Quantity Balance 36.00.		
					5	Nov 16, 2021	SYSTEM	(\$25,200.00)			
				Overrun - T	otal			\$0.00			
			Overrun - Tota	l				\$0.00			
	0140 -							\$0.00			
	0150	LATEX MODIFIED CONCRETE WEARING	Material		5	Nov 16, 2021	SYSTEM	(\$138,130.00)			
		SURFACE			6	Dec 3, 2021	SYSTEM	\$368,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.		
					6	Dec 3, 2021	SYSTEM	(\$368,315.00)			
				- Total				(\$138,130.00)			
			Material - Tota					(\$138,130.00)			
			MaterialCredit		6	Dec 3, 2021	SYSTEM	\$138,130.00			
				- Total				\$138,130.00			
			MaterialCredit	- Total				\$138,130.00			
			Other Item Adjustment	OTHR	7	Dec 16, 2021	graesj1	\$184,157.50	Estimate 7 Removal of adjustment made on estimate 6 for not reporting required material samples		
				OTHR - Tota	al			\$184,157.50			
				PPPS	6	Dec 3, 2021	graesj1	(\$184,157.50)	50% Deduct due Contractor not reporting required material samples		



Li	ine	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
01	150	LATEX MODIFIED	Other Item	PPPS - Tota	ıl			(\$184,157.50)										
		CONCRETE WEARING SURFACE	Adjustment	SUBI	6	Dec 3, 2021	graesj1	(\$24,177.50)	10% Deduct for Inverted Cross Slope Pours 1, 2 & 3, Bent 1 to Bent 29 2545 SY x \$95 x -0.10 = - \$24,177.5 See NCR 001 for more details Deduction will be paid back after corrections have been made									
					17	May 16, 2022	graesj1	\$24,177.50	Estimate 17 Removal of Adjustment made on Estimate 6 Corrections have been made to inverted cross slopes in the bridge deck									
				SUBI - Tota				\$0.00										
			Other Item Ad	justment - To	tal			\$0.00										
01	150 -	Total						\$0.00										
01	160	EPOXY POLYMER WEARING SURFACE	Material		17	May 16, 2022	SYSTEM	(\$44,797.50)										
		SURFACE		- Total				(\$44,797.50)										
			Material - Tota	ıl				(\$44,797.50)										
			MaterialCredit		18	Jun 2, 2022	SYSTEM	\$44,797.50										
				- Total				\$44,797.50										
			MaterialCredit	- Total				\$44,797.50										
			Other Item Adjustment	MDPA	17	May 16, 2022	graesj1	\$22,398.75	Estimate 17 50% payment for labor. Adjustment will be removed once certs are received \$44,797.50 x 0.50 = \$22,398.75									
				MDPA - Tot	al			\$22,398.75										
				OTHR	18	Jun 1, 2022	graesj1	(\$22,398.75)	Estimate 18 Removal of adjustment made on Estimate 17 50% payment for labor									
				OTHR - Tota	al			(\$22,398.75)										
			Other Item Ad	justment - To	tal			\$0.00										
01	160 - '	Total						\$0.00										
01	170	0 HALF-SOLE REPAIR	Material		10	Feb 1, 2022	SYSTEM	\$60,495.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.									
														10	Feb 1, 2022	SYSTEM	(\$60,495.50)	
					11	Feb 16, 2022	SYSTEM	(\$60,495.50)										
					12	Mar 2, 2022	SYSTEM	\$73,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.									
					12	Mar 2, 2022	SYSTEM	(\$73,548.00)										
														13	Mar 16, 2022	SYSTEM	\$73,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
					13	Mar 16, 2022	SYSTEM	(\$73,548.00)										
				- Total		2022		\$0.00										
			Material - Tota					\$0.00										
			Other Item	SUBI	15	Apr 15	gracait		Estimate 15 10% Deduction for not curing concrete									
			Adjustment	SUBI - Tota		Apr 15, 2022	graesj1	(\$7,388.85)	Estimate 15 10% Deduction for not curing concrete 1302 SF x \$56.75 x -10% = -\$7,388.85									
			Other Item Ad															
	170 - 1	Total	Other Item Ad	justment - 10				(\$7,388.85)										
	170 - 180	FULL DEPTH REPAIR	Material		8	Jan 4, 2022	SYSTEM	(\$7,388.85) \$12,775.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesij1 overridding Paymen									
					8	Jan 4, 2022	SYSTEM	(\$12,775.50)	Estimate Exception 1 on the current Payment Estimate.									
					9	Jan 18, 2022	SYSTEM	\$12,775.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.									



Jul 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239	0180	FULL DEPTH REPAIR	Material		9	Jan 18, 2022	SYSTEM	(\$12,775.50)	
					11	Feb 16, 2022	SYSTEM	\$22,414.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Feb 16, 2022	SYSTEM	(\$22,414.50)	
					12	Mar 2, 2022	SYSTEM	\$22,414.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Mar 2, 2022	SYSTEM	(\$22,414.50)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0180 -	Total						\$0.00	
	0190	MISC.	Material		13	Mar 16, 2022	SYSTEM	\$16,030.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Mar 16, 2022	SYSTEM	(\$16,030.40)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0190 -	Total						\$0.00	
	0200	MISC.	Material		10	Feb 1, 2022	SYSTEM	\$32,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Feb 1, 2022	SYSTEM	(\$32,025.00)	
					11	Feb 16, 2022	SYSTEM	\$32,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					11	Feb 16, 2022	SYSTEM	(\$32,025.00)	
					12	Mar 2, 2022	SYSTEM	\$32,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user graesj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					12	Mar 2, 2022	SYSTEM	(\$32,025.00)	
					13	Mar 16, 2022	SYSTEM	\$32,025.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					13	Mar 16, 2022	SYSTEM	(\$32,025.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
			Other Item Adjustment	OTHR	10	Feb 1, 2022	graesj1	(\$1,220.00)	Estimate 10 adjustment to offset system override of overrun 525 LF (measured) - 505 LF (plan) x \$61 = -\$1220 Will be removed once change order is approved
					14	Apr 4, 2022	veasms1	\$1,220.00	Estimate 14 removal of adjustment made on estimate 10 overrun acknowledged on estimate 14
				OTHR - Tota	al			\$0.00	
			Other Item Ad	justment - To	otal			\$0.00	
			Overrun	Overrun	10	Feb 1, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
					10	Feb 1, 2022	SYSTEM	(\$1,220.00)	
					11	Feb 16, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					11	Feb 16, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
					12	Mar 2, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1583239	0200	MISC.	Overrun	Overrun	12	Mar 2, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
					13	Mar 16, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					13	Mar 16, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
					14	Apr 4, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					19	Jun 30, 2022	SYSTEM	\$1,220.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.00000 - 61.00000, 'is previded (frame previous)
				Overrun - T	otal			\$0.00	applied (if non-zero).
			Overrun - Tota					\$0.00	
	0200 -	Total						\$0.00	
	0210	MISC.	Material		15	Apr 15, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Apr 15, 2022	SYSTEM	(\$8,760.00)	
					16	May 2, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	May 2, 2022	SYSTEM	(\$8,760.00)	
					17	May 16, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	May 16, 2022	SYSTEM	(\$8,760.00)	
							18 Jun 2, SYSTEM (\$8,760.00) 2022		
					19	Jun 30, 2022	SYSTEM	(\$8,760.00)	
				- Total				(\$17,520.00)	
			Material - Tota	I				(\$17,520.00)	
			MaterialCredit		19	Jun 30, 2022	SYSTEM	\$8,760.00	
				- Total				\$8,760.00	
	0010	T -4-1	MaterialCredit	- Total				\$8,760.00	
	0210 - 0220	Total MISC.	Material		10	Feb 1,	SYSTEM	(\$8,760.00) \$106,575.00	This adjustment offsets the original system-generated Material Payment
	0220	STRUCTURAL STEEL CONSTRUCTION	Material			2022			Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Feb 1, 2022	SYSTEM	(\$106,575.00)	
					11	Feb 16, 2022	SYSTEM	\$123,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user graesj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Feb 16, 2022	SYSTEM	(\$123,395.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0220 - 0230	Total OPEN CELL FOAM	Material		11	Feb 16,	SYSTEM	\$0.00 (\$3,234.00)	
		JOINT SEAL			12	2022 Mar 2,	SYSTEM	(\$3,234.00)	
					13	2022 Mar 16, 2022	SYSTEM	(\$15,746.50)	
				- Total		2022		(\$22,214.50)	
				Forta				(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	



Jul 6, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239	0230	OPEN CELL FOAM JOINT SEAL	Material - Total					(\$22,214.50)	
			MaterialCredit		12	Mar 2, 2022	SYSTEM	\$3,234.00	
					13	Mar 16, 2022	SYSTEM	\$3,234.00	
					14	Apr 4, 2022	SYSTEM	\$15,746.50	
				- Total				\$22,214.50	
			MaterialCredit - Total					\$22,214.50	
			Other Item Adjustment	MDPA	13	Mar 16, 2022	graesj1	\$6,256.25	Estimate 13, PAL number was not requested for material resulting in discrepancy. 50% Payment for labor of installment.
					14	Apr 4, 2022	veasms1	(\$6,256.25)	Estimate 14 removal of adjustment made on estimate 13 PAL number received
				MDPA - Total				\$0.00	
				OTHR	19	Jun 30, 2022	graesj1	(\$3,080.00)	Estimate 19 adjustment for damaged emseal requiring replacement adjustment will be removed once emseal is replaced 80 ft. * \$38.50 / LF = \$3,080
				OTHR - Total				(\$3,080.00)	
			Other Item Adjustment - Total					(\$3,080.00)	
0230 - Total							(\$3,080.00)		
J5S3239 - Total							(\$19,228.85)		
Overall -	Overall - Total							(\$19,228.85)	