

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 2, 2022

Progress Estimate Number	Contract ID	210521-D04	Pay Period Start	July 16, 2022	Original Contract Amount	\$1,611,862.60
21	Prime Contractor	Concrete Strategies, LLC	Pay Period End	August 1, 2022	<b>Net Change Order Amount</b>	\$284,805.93
21					Current Contract Amount	\$1,896,668.53

Approval Date		By User
August 2, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	graesj1
August 3, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	grahac1
August 4, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	<b>Current Completion Date</b>	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2021	January 31, 2022		100.00%

	Contract Informational Dates											
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract									
Acceptance Date												
Awarded Date	June 2, 2021	June 2, 2021										
Letting Date	May 21, 2021	May 21, 2021										
Notice to Proceed Date	July 6, 2021	July 6, 2021										
Open to Traffic Date												
Work Began Date	September 7, 2021	September 7, 2021										

Contract Total Pay	For Estimate No. 21				
		This Estimate	Previous	To Date	
210521-D04					
	Total Posted Items Pay	\$0.00	\$1,896,592.03	\$1,896,592.03	
	Gross Item Adjustments	\$0.00	(\$10,468.85)	(\$10,468.85)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			<b>\$1,886,123.18</b>	\$1,886,123.18	
<b>Contract Total Pay</b>	able This Estimate:	\$0.00			

#### Items Paid This Estimate Period

No Data Available

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

#### Line Item Adjustments This Estimate

No Data Available

Revision 4/1/2020 Page 1 of 11




#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information												
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work								
J5S3239	FAS S402(3)	Bridge rehabilitation	BR 54	MILLER	on the Bagnell Dam bridge in Lake Ozark								

#### 

Revision 4/1/2020 Page 2 of 11





# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### Exceptions (Discrepancies) This Estimate Period No Exceptions Exist on Contract

Revision 4/1/2020 Page 3 of 11



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Report Generated date and can differ from the posted an Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
0521-D04	J5S3239	0001	0010	6161005	CONSTRUCTION SIGNS	504.00	4.00	508.00	SQFT	508.00	\$8.90	\$4,521.20
		0001	0020	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$39.00	\$156.0
		0001	0030	6161009	FLAG ASSEMBLY	2.00	0.00	2.00	EA	2.00	\$28.00	\$56.0
		0001	0040	6161030	TYPE III MOVEABLE BARRICADE	12.00	0.00	12.00	EA	12.00	\$173.00	\$2,076.0
		0001	0050	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	1.00	3.00	EA	3.00	\$3,600.00	\$10,800.0
		0001	0060	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$225,000.00	\$225,000.0
		0070	0070	2161001	TOTAL SURFACE HYDRO DEMOLITION	4,936.00	0.00	4,936.00	SQYD	4,936.00	\$39.50	\$194,972.0
		0070	0080	2161502	REMOVAL OF CONCRETE WEARING SURFACE	44,424.00	0.00	44,424.00	SQFT	44,424.00	\$2.75	\$122,166.0
		0070	0090	2161503	REMOVAL OF EXISTING DECK REPAIR	500.00	4,563.00	5,063.00	SQFT	5,063.00	\$18.75	\$94,931.2
		0070	0100	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	103.00	-21.00	82.00	LF	82.00	\$111.00	\$9,102.0
		0070	0110	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	1,360.00	0.00	1,360.00	LF	1,360.00	\$3.25	\$4,420.0
		0070	0120	2169901	MISC.REMOVAL OF EXISTING BARRIER CURB JOINT MATERIAL CONTAINING ASBESTOS	1.00	0.00	1.00	LS	1.00	\$16,900.00	\$16,900.
		0070	0130	2169902	MISC.REMOVAL OF EXISTING BARRIER CURB PROTRUSION	24.00	0.00	24.00	EA	24.00	\$730.00	\$17,520.0
		0070	0140	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	35.00	190.00	225.00	CY	225.00	\$700.00	\$157,500.
		0070	0150	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	4,936.00	0.00	4,936.00	SQYD	4,936.00	\$95.00	\$468,920.
		0070	0160	6233000	EPOXY POLYMER WEARING SURFACE	2,568.00	36.00	2,604.00	SQYD	2,604.00	\$45.25	\$117,831.
		0070	0170	7040104	HALF-SOLE REPAIR	1,564.00	-189.00	1,375.00	SQFT	1,375.00	\$56.75	\$78,031.
		0070	0180	7040106	FULL DEPTH REPAIR	400.00	-253.00	147.00	SQFT	146.50	\$153.00	\$22,414.
		0070	0190	7049903	MISC.CONCRETE BARRIER CURB REPAIR	25.00	-2.00	23.00	LF	23.00	\$688.00	\$15,824.
		0070	0200	7049903	MISC.CURB REPAIR	505.00	20.00	525.00	LF	525.00	\$61.00	\$32,025.0
		0070	0210	7129902	MISC.SLIDE PLATE REPLACEMENT	15.00	0.00	15.00	EA	15.00	\$584.00	\$8,760.
		0070	0220	7129903	MISC.SINGLE TUBE HANDRAIL	1,702.00	0.00	1,702.00	LF	1,702.00	\$72.50	\$123,395.
		0070	0230	7172054	OPEN CELL FOAM JOINT SEAL	1,464.00	-11.00	1,453.00	LF	1,453.00	\$38.50	\$55,940.
		0070	5001	5059901	MISC.LATEX MODIFIED CONCRETE WEARING SURFACE - PUMP PLACEMENT	0.00	1.00	1.00	LS	1.00	\$57,303.95	\$57,303.
		0070	5002	2169901	MISC.REMOVAL OF EXISTING DECK REPAIRS	0.00	1.00	1.00	LS	1.00	\$47,465.63	\$47,465.
		0070	5003	2169901	MISC.HYDRO DEMOLITION - TEST SECTION	0.00	1.00	1.00	LS	1.00	\$5,160.75	\$5,160.
		0070	5004	7040113	CLEANING AND EPOXY COATING	0.00	40.00	40.00	SQFT	40.00	\$85.00	\$3,400.
	Project J	5S3239 - To	otal Value	Posted to	Date as of Report Generated Date							\$1,896,592.
521-D04 Ove	rall - Total	Value Post	ted to Dat	te as of Re	port Generated Date							\$1,896,592.0

Revision 4/1/2020 Page 4 of 11



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 5 of 11



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239	0010	CONSTRUCTION SIGNS	Material	Type	1	Sep 16, 2021	SYSTEM	\$4,523.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user graesj1 overridding Payment
					1	Sep 16, 2021	SYSTEM	(\$4,523.25)	Estimate Exception 1 on the current Payment Estimate.
				- Total		2021		\$0.00	
			Material - Tota					\$0.00	
			Overrun	Overrun	1	Sep 16, 2021	SYSTEM	\$37.65	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 508.230; Overrun Quantity Balance 4.23.
					1	Sep 16, 2021	SYSTEM	(\$37.65)	
					2	Oct 4, 2021	SYSTEM	(\$37.65)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Dec 3, 2021	SYSTEM	\$37.65	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.90000 - 8.90000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0010 -	Total						\$0.00	
	0020	ADVANCED WARNING RAIL SYSTEM	Material		1	Sep 16, 2021	SYSTEM	\$156.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$156.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0020 -	Total						\$0.00	
	0030	FLAG ASSEMBLY	Material		1	Sep 16, 2021	SYSTEM	\$56.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user graesj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$56.00)	
				- Total				\$0.00	
		_	Material - Tota	1				\$0.00	
	0030 -							\$0.00	
	0040	TYPE III MOVEABLE BARRICADE	Material		1	Sep 16, 2021	SYSTEM	\$2,076.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Sep 16, 2021	SYSTEM	(\$2,076.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0040 -							\$0.00	
	0050	CMS WITH COMMUNICATION INTERFACE, CONT F	Material		1	Sep 16, 2021	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		331			1	Sep 16, 2021	SYSTEM	(\$10,800.00)	
				- Total				\$0.00	
			Material - Tota				2)12==	\$0.00	
			Overrun	Overrun	1	Sep 16, 2021	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 3.000; Overrun Quantity Balance 1.00.
					1	Sep 16, 2021	SYSTEM	(\$3,600.00)	
					2	Oct 4, 2021	SYSTEM	(\$3,600.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	Dec 3, 2021	SYSTEM	\$3,600.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3600.00000 - 3600.00000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239	0050	CMS WITH COMMUNICATION INTERFACE, CONT F	Overrun - Tota	ıl				\$0.00	
	0050 -	Total						\$0.00	
	0090	REMOVAL OF	Overrun	Overrun	3	Oct 18,	SYSTEM	(\$12,375.00)	
		EXISTING DECK REPAIR			4	2021 Nov 2,	SYSTEM	(\$5,043.75)	
						2021			
					6	Dec 3, 2021	SYSTEM	\$17,418.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',18.75000 - 18.75000, 'is applied (if non-zero).
				Overrun - To	otal			\$0.00	
			Overrun - Tota	il				\$0.00	
	0090 -	Total						\$0.00	
	0120	MISC. REMOVALS	Other Item Adjustment	OTHR	1	Sep 16, 2021	graesj1	(\$4,225.00)	Estimate 1 Removal of 25% payment until waste shipment record is received0.25 x \$16,900 = -\$4,225
					3	Oct 18, 2021	graesj1	\$4,225.00	Estimate 3 removal of line item adjustment made on Estimate 1 Waste Shipment Record has been received.
				OTHR - Tota	al			\$0.00	
			Other Item Adj	justment - To	tal			\$0.00	
	0120 -	Total						\$0.00	
	0140	SUPPLEMENTARY WEARING SURFACE	Material		5	Nov 16, 2021	SYSTEM	(\$49,700.00)	
		MATERIAL			6	Dec 3, 2021	SYSTEM	(\$135,800.00)	
				- Total				(\$185,500.00)	
			Material - Tota	l				(\$185,500.00)	
			MaterialCredit		6	Dec 3, 2021	SYSTEM	\$49,700.00	
					7	Dec 16, 2021	SYSTEM	\$135,800.00	
				- Total				\$185,500.00	
			Material Credit Overrun	- Total				\$185,500.00	
				Overrun	5	Nov 16, 2021	SYSTEM	\$25,200.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 71.000; Overrun Quantity Balance 36.00.
					5	Nov 16, 2021	SYSTEM	(\$25,200.00)	
				Overrun - To	otal			\$0.00	
			Overrun - Tota	ıl				\$0.00	
	0140 -	Total						\$0.00	
	0150	LATEX MODIFIED CONCRETE WEARING	Material		5	Nov 16, 2021	SYSTEM	(\$138,130.00)	
		SURFACE			6	Dec 3, 2021	SYSTEM	\$368,315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Dec 3, 2021	SYSTEM	(\$368,315.00)	
				- Total				(\$138,130.00)	
			Material - Tota	l				(\$138,130.00)	
			MaterialCredit		6	Dec 3, 2021	SYSTEM	\$138,130.00	
				- Total				\$138,130.00	
			MaterialCredit	- Total				\$138,130.00	
			Other Item Adjustment	OTHR		Dec 16, 2021	graesj1	\$184,157.50	Estimate 7 Removal of adjustment made on estimate 6 for not reporting required material samples
				OTHR - Tota	al			\$184,157.50	
				PPPS	6	Dec 3, 2021	graesj1	(\$184,157.50)	50% Deduct due Contractor not reporting required material samples



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
39	0150	LATEX MODIFIED	Other Item	PPPS - Tota	ıl			(\$184,157.50)			
		CONCRETE WEARING SURFACE	Adjustment	SUBI	6	Dec 3, 2021	graesj1	(\$24,177.50)	10% Deduct for Inverted Cross Slope Pours 1, 2 & 3, Bent 1 to Bent 29 2545 SY x \$95 x - 0.10 = - \$24,177.5 See NCR 001 for more details Deduction will be paid back after corrections have been made		
					17	May 16, 2022	graesj1	\$24,177.50	Estimate 17 Removal of Adjustment made on Estimate 6 Corrections have been made to inverted cross slopes in the bridge deck		
				SUBI - Total				\$0.00			
			Other Item Ad	justment - To	tal			\$0.00			
	0150 -	Total						\$0.00			
	0160	EPOXY POLYMER WEARING SURFACE	Material		17	May 16, 2022	SYSTEM	(\$44,797.50)			
		SURFACE		- Total				(\$44,797.50)			
			Material - Tota					(\$44,797.50)			
			MaterialCredit		18	Jun 2, 2022	SYSTEM	\$44,797.50			
				- Total				\$44,797.50			
			MaterialCredit	- Total				\$44,797.50			
			Other Item Adjustment	MDPA	17	May 16, 2022	graesj1	\$22,398.75	Estimate 17 50% payment for labor. Adjustment will be removed once certs are received \$44,797.50 x 0.50 = \$22,398.75		
				MDPA - Tota	al			\$22,398.75			
				OTHR	18	Jun 1, 2022	graesj1	(\$22,398.75)	Estimate 18 Removal of adjustment made on Estimate 17 50% payment for labor		
				OTHR - Tota	al			(\$22,398.75)			
			Other Item Ad	justment - To	tal			\$0.00			
	0160 -	Total						\$0.00			
	0170	70 HALF-SOLE REPAIR			10	Feb 1, 2022	SYSTEM	\$60,495.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
							10	Feb 1, 2022	SYSTEM	(\$60,495.50)	
									11	Feb 16, 2022	SYSTEM
					11	Feb 16, 2022	SYSTEM	(\$60,495.50)			
					12	Mar 2, 2022	SYSTEM	\$73,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					12	Mar 2, 2022	SYSTEM	(\$73,548.00)			
					13	Mar 16, 2022	SYSTEM	\$73,548.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					13	Mar 16, 2022	SYSTEM	(\$73,548.00)			
				- Total				\$0.00			
			Material - Tota	ıl				\$0.00			
			Other Item Adjustment	SUBI	15	Apr 15, 2022	graesj1	(\$7,388.85)	Estimate 15 10% Deduction for not curing concrete 1302 SF x \$56.75 x -10% = -\$7,388.85		
				SUBI - Total				(\$7,388.85)			
			Other Item Ad	justment - To	tal			(\$7,388.85)			
	0170 -	Total						(\$7,388.85)			
	0180	FULL DEPTH REPAIR	Material		8	Jan 4, 2022	SYSTEM	\$12,775.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					8	Jan 4, 2022	SYSTEM	(\$12,775.50)			
					9	Jan 18, 2022	SYSTEM	\$12,775.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		



SEPTION   PRILL DEFINE   Alternal   2002   11   Feb 10, SVSTEM   122.41.510   This adjustment officials the regard system generated Material Physical Extension   12   Mar 2, SVSTEM   122.41.510   This adjustment officials the regard system generated Material Physical Extension   12   Mar 2, SVSTEM   122.41.510   This adjustment officials the regard system generated Material Physical Extension   12   Mar 2, SVSTEM   122.41.510   This adjustment officials the regard system generated Material Physical Extension   12   Mar 2, SVSTEM   122.41.510   This adjustment officials the regard system generated Material Physical Extension   12   Mar 10, SVSTEM   150.00	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
11	J5S3239	0180		Material	, , , , , , , , , , , , , , , , , , ,	9		SYSTEM	(\$12,775.50)			
2022   12   May 2, SYSTEM   322,414.50   This adjustment offeres the original system-generated Material Payment Editinals Exception 2 on the current Payment Editinals Exception 3 on the current Payment Editinals Exception 4 on the current Payment Editinals Exception 4 on the current Payment Editinals Exception 4 on the current Payment Editinals Exception 6 on the current Payme						11	Feb 16,	SYSTEM	\$22,414.50	Estimate Item Adjustment (0017) due to user graesj1 overridding Payment		
2022   SYSTEM   (\$22,114.50)   SYSTEM   (\$20,114.50)   SYSTEM   SYSTEM						11		SYSTEM	(\$22,414.50)			
1000   MISC						12		SYSTEM	\$22,414.50	Estimate Item Adjustment (0004) due to user graesj1 overridding Payment		
1000   MISC.   Material   13						12		SYSTEM	(\$22,414.50)			
130					- Total				\$0.00			
NISC   Material   13   Mar 16,   SYSTEM   \$10.030.4   Estimate from Applicant python-generated Material Pyment Estimate Exception 2 on the current Pyment Estimate.				Material - Tota	ı				\$0.00			
Setting   Estimate   Exception 2 on the current Polyment   Estimate   Exception 3 on the current Polyment   Estimate   Exception 3 on the current Polyment   Estimate   Exception 4 on the current Polyment   Estimate   Estimate   Exception 5 on the current Polyment   Estimate   Estimate   Exception 4 on the current Polyment   Estimate   Exception 5 on the current Polyment   Estimate   Exception 5 on the current Polyment   Estimate   Exception 6 on the current Polyment   Estimate   Exception 6 on the current Polyment   Estimate   Exception 6 on the current Polyment   Estimate   Exception 7 on the current Polyment   Est		0180 -	Total						\$0.00			
Total		0190	MISC.	Material		13		SYSTEM	\$16,030.40	Estimate Item Adjustment (0005) due to user graesj1 overridding Payment		
						13		SYSTEM	(\$16,030.40)			
					- Total				\$0.00			
Misc.   Material				Material - Tota	ı				\$0.00			
2022   Estimate Item Adjustment (0003) due to user grasely overridding Payment Estimate   2022   2		0190 -	Total						\$0.00			
11		0200	MISC.	Material		10		SYSTEM	\$32,025.00	Estimate Item Adjustment (0003) due to user graesj1 overridding Payment		
2022   Estimate Item Adjustment (0015) due to user graces) overridding Payment Estimate Exception 4 on the current Payment Estimate.						10		SYSTEM	(\$32,025.00)			
2022   12   Mar 2, 2022   20								11		SYSTEM	\$32,025.00	Estimate Item Adjustment (0015) due to user graesj1 overridding Payment
Estimate Item Adjustment (0002) due to user graespt overridding Payment Estimate Exception 3 on the current Payment Estimate.  12 Mar 2, 2022  13 Mar 16, 2022  13 Mar 16, 2022  13 Mar 16, 2022  14 SySTEM  15 SySTEM  16 SySTEM  17 SySTEM  18 SySTEM  18 SySTEM  18 SySTEM  19 S						11		SYSTEM	(\$32,025.00)			
13								12		SYSTEM	\$32,025.00	Estimate Item Adjustment (0002) due to user graesj1 overridding Payment
Estimate Item Adjustment (0003) due to user graesj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.    13						12		SYSTEM	(\$32,025.00)			
Total   So.00						13		SYSTEM	\$32,025.00	Estimate Item Adjustment (0003) due to user graesj1 overridding Payment		
Solution   Common						13		SYSTEM	(\$32,025.00)			
Other Item Adjustment  OTHR   10					- Total				\$0.00			
Adjustment  2022  S25 LF (measured) - 505 LF (plan) x \$61 = -\$1220 Will be removed once change order is approved  14				Material - Tota					\$0.00			
Other Item Adjustment - Total  Overrun					OTHR	10		graesj1	(\$1,220.00)	525 LF (measured) - 505 LF (plan) x \$61 = -\$1220		
Other Item Adjustment - Total  Overrun						14		veasms1	\$1,220.00			
Overrun  Overrun  Overrun  Overrun  Overrun  Overrun  Overrun  I  SYSTEM  \$1,220.00  This adjustment offsets the original system-generated Overrun Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.  II  Feb 1, 2022  SYSTEM  (\$1,220.00)  Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.  Mar 2, SYSTEM  \$1,220.00  Averaged Price Adjustment from this item on all previous payment estimates					OTHR - Tota	al			\$0.00			
Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.  10 Feb 1, 2022  11 Feb 16, 2022  12 SYSTEM (\$1,220.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  13 Feb 16, 2022  14 Feb 16, 2022  15 SYSTEM (\$1,220.00) This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.  15 Mar 2, SYSTEM (\$1,220.00) Averaged Price Adjustment from this item on all previous payment estimates				Other Item Ad	justment - To	tal			\$0.00			
2022  11 Feb 16, 2022  13 Feb 16, 2022  14 Feb 16, 2022  15 Feb 16, 2022  16 Feb 16, 2022  17 Feb 16, 2022  18 Feb 16, 2022  19 Feb 16, 2022  10 Feb 16, 2022  11 Feb 16, 2022  12 Mar 2, SYSTEM (\$1,220.00) Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).  18 Feb 16, 2022  19 Feb 16, 2022  10 Fis adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.  19 Feb 16, 2022  10 Feb 16, 2022  11 Feb 16, 2022  12 Feb 16, 2022  13 Feb 16, 2022  14 Feb 16, 2022  15 Feb 16, 2022  16 Feb 16, 2022  17 Feb 16, 2022  18 Feb 16, 2022  19 Feb 16, 2022  10 Feb 16, 2022  10 Feb 16, 2022  11 Feb 16, 2022  12 Feb 16, 2022  13 Feb 16, 2022  14 Feb 16, 2022  15 Feb 16, 2022  16 Feb 16, 2022  17 Feb 16, 2022  18 Feb 16, 2022  19 Feb 16, 2022  10 Feb 16, 2022  10 Feb 16, 2022  10 Feb 16, 2022  10 Feb 16, 2022  11 Feb 16, 2022  12 Feb 16, 2022  13 Feb 16, 2022  14 Feb 16, 2022  15 Feb 16, 2022  16 Feb 16, 2022  17 Feb 16, 2022  18 Feb 16, 2022  18 Feb 16, 2022  19 Feb 16, 2022  19 Feb 16, 2022  10 Feb 16, 2022  11 Feb 16, 2022  11 Feb 16, 2022  12 Feb 16, 2022  11 Feb 16, 2022  12 Feb 16, 2022  13 Feb 16, 2022  14 Feb 16, 2022  15 Feb 16, 2022  16 Feb 16, 2022  17 Feb 16, 2022  18 Feb 16, 2022  19 Feb 16, 2022  10 Feb 16, 2			Overrun	Overrun	10		SYSTEM	\$1,220.00	Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000;			
2022 of '0.00000' is applied (if non-zero).  11 Feb 16, 2022 This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0014) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.  12 Mar 2, SYSTEM (\$1,220.00) Averaged Price Adjustment from this item on all previous payment estimates						10		SYSTEM	(\$1,220.00)			
2022 Estimate Item Adjustment (0014) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.  12 Mar 2, SYSTEM (\$1,220.00) Averaged Price Adjustment from this item on all previous payment estimates						11		SYSTEM	(\$1,220.00)			
12 Mar 2, SYSTEM (\$1,220.00) Averaged Price Adjustment from this item on all previous payment estimates						11		SYSTEM	\$1,220.00	Estimate Item Adjustment (0014) overridding Payment Estimate Exception 9 on the current Payment Estimate. Material Insufficiency Quantity 525.000;		
						12		SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates		



ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
3239	0200	MISC.	Overrun	Overrun	12	Mar 2, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.		
					13	Mar 16, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
							13	Mar 16, 2022	SYSTEM	\$1,220.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 7 on the current Payment Estimate. Material Insufficiency Quantity 525.000; Overrun Quantity Balance 20.00.
					14	Apr 4, 2022	SYSTEM	(\$1,220.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					19	Jun 30, 2022	SYSTEM	\$1,220.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',61.00000 - 61.00000, 'is applied (if non-zero).		
				Overrun - To	otal			\$0.00			
			Overrun - Tota	ıl				\$0.00			
	0200 -	Total						\$0.00			
	0210	MISC.	Material		15	Apr 15, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					15	Apr 15, 2022	SYSTEM	(\$8,760.00)			
					16	May 2, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user graesj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
					16	May 2, 2022	SYSTEM	(\$8,760.00)			
					17	May 16, 2022	SYSTEM	\$8,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					17	May 16, 2022	SYSTEM	(\$8,760.00)			
					18	Jun 2, 2022	SYSTEM	(\$8,760.00)			
					19	Jun 30, 2022	SYSTEM	(\$8,760.00)			
				- Total				(\$17,520.00)			
			Material - Tota	l				(\$17,520.00)			
			MaterialCredit		19	Jun 30, 2022	SYSTEM	\$8,760.00			
					20	Jul 18, 2022	SYSTEM	\$8,760.00			
				- Total				\$17,520.00			
	0040	T.4.1	MaterialCredit	- Total				\$17,520.00			
	0210 - 0220	MISC. STRUCTURAL STEEL	Material		10	Feb 1, 2022	SYSTEM	\$0.00 \$106,575.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user graesj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
		CONSTRUCTION			10	Feb 1, 2022	SYSTEM	(\$106,575.00)	Estimate Exception 6 on the current rayment Estimate.		
					11	Feb 16, 2022	SYSTEM	\$123,395.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user graesj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					11	Feb 16, 2022	SYSTEM	(\$123,395.00)			
				- Total				\$0.00			
			Material - Tota	ı				\$0.00			
	0220 -	Total						\$0.00			
	0230	OPEN CELL FOAM JOINT SEAL	Material		11	Feb 16, 2022	SYSTEM	(\$3,234.00)			
					12	Mar 2, 2022	SYSTEM	(\$3,234.00)			
					13	Mar 16, 2022	SYSTEM	(\$15,746.50)			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5S3239	0230	OPEN CELL FOAM JOINT SEAL	Material	- Total				(\$22,214.50)	
			Material - Total					(\$22,214.50)	
			MaterialCredit		12	Mar 2, 2022	SYSTEM	\$3,234.00	
					13	Mar 16, 2022	SYSTEM	\$3,234.00	
					14	Apr 4, 2022	SYSTEM	\$15,746.50	
				- Total				\$22,214.50	
			MaterialCredit - Total					\$22,214.50	
			Other Item Adjustment	MDPA	13	Mar 16, 2022	graesj1	\$6,256.25	Estimate 13, PAL number was not requested for material resulting in discrepancy. 50% Payment for labor of installment.
					14	Apr 4, 2022	veasms1	(\$6,256.25)	Estimate 14 removal of adjustment made on estimate 13 PAL number received
				MDPA - Total				\$0.00	
				OTHR	19	Jun 30, 2022	graesj1	(\$3,080.00)	Estimate 19 adjustment for damaged emseal requiring replacement adjustment will be removed once emseal is replaced 80 ft. * \$38.50 / LF = \$3,080
				OTHR - Total				(\$3,080.00)	
			Other Item Adjustment - Total					(\$3,080.00)	
0230 - Total							(\$3,080.00)		
J5S3239 - Total							(\$10,468.85)		
Overall - Total							(\$10,468.85)		