

Pay Estimate Created Date: August 16, 2022

Progress Estimate Number 25		Contract ID Prime Contractor	210521-F01 KCI Construction Compan			Original Contract Amount Net Change Order Amount Current Contract Amount	\$30,573,000.00 \$546,150.68 \$31,119,150.68	
Approval Date							By User	
August 16, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by							
August 17, 2022			Reviewed and Approved (a	and should be consid	ered Draft) at the	Resident Engineer Level by	morgac1	
August 18, 2022		Reviewed and Approved at the Central Office Controllers Office Level by						
Onininal Completion Date		C	mulation Data	-t C -t D	-4- 0/	-f C Cambra at A	4 Campulata	

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
July 1, 2023	July 1, 2023		30.25%

Contract Informational Dates									
Date Description	Original Completion Date	Current Completion Date							
Acceptance Date									
Awarded Date	June 2, 2021	June 2, 2021							
Letting Date	May 21, 2021	May 21, 2021							
Notice to Proceed Date	July 26, 2021	July 26, 2021							
Open to Traffic Date									
Work Began Date	August 3, 2021	August 3, 2021							

Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
JSP R-F 1.1 Black Creek Bridge Reconstruction	August 28, 2022	August 28, 2022	10	
JSP R-F 1.2 Pedestrian Underpass at Mary Avenue Work	August 30, 2022	August 30, 2022	12	
JSP R-F 1.3 Deer Creek Bridge Rehabilitation	June 11, 2022	June 11, 2022	Milestone Complete	

Milestones

Contract Total Pay For Estimate No. 25									
		This Estimate	Previous	To Date					
210521-F01									
	Total Posted Items Pay	\$576,302.29	\$8,835,724.81	\$9,412,027.10					
	Gross Item Adjustments	(\$50,387.09)	\$426,267.23	\$375,880.14					
	Incentive	\$0.00	\$0.00	\$0.00					
	Disincentive	\$0.00	\$0.00	\$0.00					
	Liquidated Damage	\$0.00	\$0.00	\$0.00					
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00					
	•		\$9,261,992.04	\$9,787,907.24					
Contract Total Pa	yable This Estimate:	\$525,915.20							

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S1718	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$6.300	174.18	\$1,097.33
	0130	5021107	CONCRETE PAVEMENT (7 IN. NON-REINF)	SQYD	\$88.000	10.6	\$932.80
	0180	6081012	TRUNCATED DOMES	SQFT	\$15.000	152.2	\$2,283.00
	0210	6085007	PAVED APPROACH, 7 IN.	SQYD	\$76.000	52.55	\$3,993.80
	0220	6086004	CONCRETE SIDEWALK, 4 IN.	SQYD	\$50.000	95.98	\$4,799.00
	0250	6089902	MISC.CONCRETE CURB RAMP (7 IN. THICK)	EA	\$1,765.000	2	\$3,530.00
	0260	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	LF	\$30.000	272.8	\$8,184.00
	0270	6091052	CURB AND GUTTER TYPE B	LF	\$30.000	22.7	\$681.00
	0740	8061007A	CURB INLET CHECK	EA	\$15.250	1	\$15.25
	0750	8061016	SEDIMENT REMOVAL	CUYD	\$16.000	1.5	\$24.00
	0840	9014004	CONDUIT, 4 IN. RIGID, PUSHED	LF	\$27.500	181	\$4,977.50
	1440	2063000	CLASS 3 EXCAVATION	CUYD	\$31.000	576.13	\$17,860.03
	1490	7250318A	18 IN. PIPE GROUP B	LF	\$81.000	426.5	\$34,546.50
	1750	7319903	MISC.MSD PCC 48" MANHOLE	LF	\$775.000	5	\$3,875.00
	1810	7319903	MISC.MSD PCC DOUBLE STREET INLET	LF	\$963.000	12	\$11,556.00
	1830	7319903	MISC.MSD PCC SINGLE STREET INLET - 60" BASE	LF	\$998.000	15	\$14,970.00
	1910	9029902	MISC.19' Pole, w/38' Mast Arm, Steel	EA	\$6,232.000	2	\$12,464.00

Revision 4/1/2020 Page 1 of 70



Pay Estimate Created Date: August 16, 2022

Progress Estimate Number	Contract ID Prime Contractor			Original Contract Amount Net Change Order Amount	
25		, , , , , , , , , , , , , , , , , , , ,	 ,	Current Contract Amount	. ,

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6S1718	1920	9029902	MISC.19' Pole, w/44' Mast Arm, Steel	EA	\$6,604.000	1	\$6,604.00
	1930	9029902	MISC.Base, Type B-9, Concrete	EA	\$2,300.000	3	\$6,900.00
	1950	9029902	MISC.Base, Type D-8PH, Concrete	EA	\$2,979.000	1	\$2,979.00
	1990	9029902	MISC.Pull Box, Double, Concrete	EA	\$3,400.000	1	\$3,400.00
	2000	9029902	MISC.Pull Box, Single, Concrete	EA	\$2,300.000	2	\$4,600.00
	2020	9029902	MISC.Signal Head, Type 34S	EA	\$1,715.000	3	\$5,145.00
	2030	9029902	MISC.Signal Head, Type 3B, Terminal Compartment, and Astro Bracket Mounting	EA	\$878.000	6	\$5,268.00
	2040	9029902	MISC.Signal Head, Type 4B, Terminal Compartment, and Astro Bracket Mounting	EA	\$1,021.000	3	\$3,063.00
	2050	9029902	MISC.Signal Head, Type 4S	EA	\$1.000	3	\$3.00
	2110	9029903	MISC.Cable, Signal, #14 Gauge, 7 Conductor	LF	\$1.550	2,710	\$4,200.50
	2120	9029903	MISC.Conduit, 4"	LF	\$26.000	490	\$12,740.00
2340		7034221	SLAB ON CONCRETE NU-GIRDER	SQYD	\$360.000	600	\$216,000.00
roject J6S	<mark>1718 - Tota</mark>	ı					\$396,691.71
J6S1718B	2510	2035500	EMBANKMENT IN PLACE	CUYD	\$4.500	387.2	\$1,742.40
	2590	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$6.300	375.52	\$2,365.78
	2680	5021107	CONCRETE PAVEMENT (7 IN. NON-REINF)	SQYD	\$88.000	64.84	\$5,705.92
	2820	6089902	MISC.7 IN. CONCRETE CURB RAMP (10 FT WIDE)	EA	\$2,500.000	2	\$5,000.00
	2880	6089905	MISC.4 IN. CONCRETE SIDEWALK (10 FT WIDE)	SQYD	\$34.000	310.68	\$10,563.12
	2950	6099903	MISC.MODIFIED CURB	LF	\$28.000	20.4	\$571.20
	3170	7201200	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	CUYD	\$38.000	880.82	\$33,471.16
	3570	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	LF	\$13.500	12	\$162.00
	3580	9014004	CONDUIT, 4 IN. RIGID, PUSHED	LF	\$26.500	618	\$16,377.00
	3590	9015010	TRENCHING TYPE I	LF	\$4.500	4,776	\$21,492.00
	3600	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$980.000	3	\$2,940.00
Project J6S	1718B - Tot	al					\$100,390.58
I6S1718C	4800	9016110	PULL BOX, PREFORMED CLASS 1	EA	\$980.000	2	\$1,960.00
	4830	9019902	MISC.ORNAMENTAL LIGHT POLE AND LUMINAIRE - KIRKWOOD STREETSCAPING	EA	\$3,863.000	20	\$77,260.00
Project J6S	1718C - Tot	al					\$79,220.00
Overall - To	tal						\$576,302.29

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
	0150	CONCRETE APPROACH PAVEMENT	Material			-116.7	\$115.00	(\$13,420.50)
	0150	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0072) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	116.7	\$115.00	\$13,420.50
	0280	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	Material			-96.5	\$18.50	(\$1,785.25)
	0280	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	96.5	\$18.50	\$1,785.25

Revision 4/1/2020 Page 2 of 70



Pay Estimate Created Date: August 16, 2022

Progress Estimate Number 25 Contract ID 210521-F01 Pay Period Start August 2, 2022 Original Contract Amount \$30,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$30,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$31,119,150.68

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S1718		А			Adjustment (0073) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.			
	0350	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-115.5	\$3.00	(\$346.50
	0350	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0074) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	115.5	\$3.00	\$346.50
	0740	CURB INLET CHECK	Material			-13	\$15.25	(\$198.25
	0740	CURB INLET CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0075) due to user schirj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.	13	\$15.25	\$198.25
	1670	MISC.	Material			-5	\$1,962.00	(\$9,810.00
	1670	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	5	\$1,962.00	\$9,810.00
	1690	MISC.	Material			-7	\$2,253.00	(\$15,771.00
	1690	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0077) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.	7	\$2,253.00	\$15,771.00
	1860	WATER	Material			-8	\$4,859.00	(\$38,872.00
	1860	WATER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0078) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	8	\$4,859.00	\$38,872.00
	1910	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$9,984.32
	1910	MISC.	Material			-2	\$6,232.00	(\$12,464.00
	1910	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0079) due to user schirj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	2	\$6,232.00	\$12,464.00
	1920	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$5,428.10
	1920	MISC.	Material			-1	\$6,604.00	(\$6,604.00
	1920	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0080) due to user schirj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.	1	\$6,604.00	\$6,604.00
	1930	MISC.	Material			-3	\$2,300.00	(\$6,900.00
	1930	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0081) due to user schirj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	3	\$2,300.00	\$6,900.00
	1950	MISC.	Material			-1	\$2,979.00	(\$2,979.00
	1950	MISC.	Material		This adjustment offsets the original system-	1	\$2,979.00	\$2,979.00

Revision 4/1/2020 Page 3 of 70



Pay Estimate Created Date: August 16, 2022

Progress Estimate Number 25 Contract ID 210521-F01 Pay Period Start August 2, 2022 Original Contract Amount \$30,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Pe

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S1718					generated Material Payment Estimate Item Adjustment (0082) due to user schirj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.			
	1990	MISC.	Material			-1	\$3,400.00	(\$3,400.00)
	1990	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0083) due to user schirj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	1	\$3,400.00	\$3,400.00
	2000	MISC.	Material			-2	\$2,300.00	(\$4,600.00)
	2000	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0084) due to user schirj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.	2	\$2,300.00	\$4,600.00
	2020	MISC.	Material			-3	\$1,715.00	(\$5,145.00)
	2020	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0085) due to user schirj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.	3	\$1,715.00	\$5,145.00
	2030	MISC.	Material			-6	\$878.00	(\$5,268.00)
	2030	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0086) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.	6	\$878.00	\$5,268.00
	2040	MISC.	Material			-3	\$1,021.00	(\$3,063.00)
	2040	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0087) due to user schirj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.	3	\$1,021.00	\$3,063.00
	2050	MISC.	Material			-3	\$1.00	(\$3.00)
	2050	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0088) due to user schirj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.	3	\$1.00	\$3.00
	2110	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$3,678.99)
	2110	MISC.	Material			-2,710	\$1.55	(\$4,200.50)
	2110	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0089) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.	2,710	\$1.55	\$4,200.50
	2120	MISC.	Material			-490	\$26.00	(\$12,740.00)
	2120	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0090) due to user schirj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.	490	\$26.00	\$12,740.00
	2210	TYPE D BARRIER	Material			-271	\$140.00	(\$37,940.00)
	2210	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0091) due to user schirj1 overridding Payment Estimate Exception 20	271	\$140.00	\$37,940.00

Revision 4/1/2020 Page 4 of 70



Pay Estimate Created Date: August 16, 2022

Progress Estimate Number 25 Contract ID 210521-F01 Pay Period Start August 2, 2022 Original Contract Amount \$30,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Pe

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S1718					on the current Payment Estimate.			
	2220	SIDEWALK (BRIDGES)	Material			-2,259	\$17.00	(\$38,403.00
	2220	SIDEWALK (BRIDGES)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0092) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.	2,259	\$17.00	\$38,403.00
	2290	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material			-598	\$87.00	(\$52,026.00)
	2290	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0093) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	598	\$87.00	\$52,026.00
	2320	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-91	\$724.00	(\$65,884.00)
	2320	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0094) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	91	\$724.00	\$65,884.00
	2340	SLAB ON CONCRETE NU- GIRDER	Material			-1,140	\$360.00	(\$410,400.00)
	2340	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	1,140	\$360.00	\$410,400.00
	2380	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	Material			-6	\$600.00	(\$3,600.00)
	2380	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0096) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	6	\$600.00	\$3,600.00
	2390	SLAB DRAIN	Material			-12	\$240.00	(\$2,880.00)
	2390	SLAB DRAIN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0097) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	12	\$240.00	\$2,880.00
J6S1718B	2510	EMBANKMENT IN PLACE	Material			-387.2	\$4.50	(\$1,742.40)
	2510	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0071) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	387.2	\$4.50	\$1,742.40
	2680	CONCRETE PAVEMENT (7 IN. NON-REINF)	Material			-585.03	\$88.00	(\$51,482.64)
	2680	CONCRETE PAVEMENT (7 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0052) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	585.03	\$88.00	\$51,482.64
	2880	MISC.	Material			-1,412.313	\$34.00	(\$48,018.64)
	2880	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0053) due to user schirj1 overridding Payment Estimate Exception 12	1,412.313	\$34.00	\$48,018.64

Revision 4/1/2020 Page 5 of 70



Pay Estimate Created Date: August 16, 2022

Progress Estimate Number 25 Contract ID 210521-F01 Pay Period Start August 2, 2022 Original Contract Amount \$30,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Pe

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S1718B					on the current Payment Estimate.			
	2940	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	Material			-261.5	\$19.00	(\$4,968.50)
	2940	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0054) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	261.5	\$19.00	\$4,968.50
	3060	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-26	\$550.00	(\$14,300.00)
	3060	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0055) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	26	\$550.00	\$14,300.00
	3130	REINFORCING STEEL (EPOXY COATED)	Material			-945	\$3.00	(\$2,835.00)
	3130	REINFORCING STEEL (EPOXY COATED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0056) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.	945	\$3.00	\$2,835.00
	3160	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-459.9	\$45.00	(\$20,695.50)
	3160	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0057) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.	459.9	\$45.00	\$20,695.50
	3170	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	Material			-880.82	\$38.00	(\$33,471.16)
	3170	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0058) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.	880.82	\$38.00	\$33,471.16
	3610	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material			-566	\$3.15	(\$1,782.90)
	3610	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	566	\$3.15	\$1,782.90
	3840	SEWER	Material			-257	\$827.00	(\$212,539.00)
	3840	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0060) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	257	\$827.00	\$212,539.00
	3850	SEWER	Material			-119.6	\$1,057.00	(\$126,417.20)
	3850	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0061) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	119.6	\$1,057.00	\$126,417.20
	3860	SEWER	Material			-41	\$188.00	(\$7,708.00)

Revision 4/1/2020 Page 6 of 70



Pay Estimate Created Date: August 16, 2022

Progress Estimate Number 25 Contract ID 210521-F01 Pay Period Start August 2, 2022 Original Contract Amount \$30,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Period End August 15, 2022 Original Contract Amount \$40,573,000.00 Pay Pe

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6S1718B	3860	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0062) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	41	\$188.00	\$7,708.00
	3870	SEWER	Material			-385.06	\$432.00	(\$166,345.92)
	3870	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0063) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	385.06	\$432.00	\$166,345.92
	4100	SEWER	Material			-161.6	\$112.00	(\$18,099.20)
	4100	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0064) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	161.6	\$112.00	\$18,099.20
	4110	SEWER	Material			-26	\$130.00	(\$3,380.00)
	4110	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0065) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.	26	\$130.00	\$3,380.00
	4130	SEWER	Material			-24.5	\$171.00	(\$4,189.50)
	4130	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	24.5	\$171.00	\$4,189.50
	4140	SEWER	Material			-109	\$274.00	(\$29,866.00)
	4140	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0067) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.	109	\$274.00	\$29,866.00
	4150	SEWER	Material			-115	\$286.00	(\$32,890.00)
	4150	SEWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0068) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	115	\$286.00	\$32,890.00
	4180	MISC.	Material			-2	\$4,120.00	(\$8,240.00)
	4180	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0069) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	2	\$4,120.00	\$8,240.00
	4220	MISC.	Material			-1	\$46,106.00	(\$46,106.00)
	4220	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0070) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.	1	\$46,106.00	\$46,106.00
J6S1718C	4810	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material			-3,744	\$3.15	(\$11,793.60)
	4810	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0098) due to user schirj1 overridding Payment Estimate Exception 48	3,744	\$3.15	\$11,793.60

Revision 4/1/2020 Page 7 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2022

Progres	s Estin 25	nate Number	Contract ID Prime Contra	210521-F ctor KCI Cons		. , ,		Amount \$5	30,573,000.00 546,150.68 31,119,150.68
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity Adjust Unit F		Adjustment amount
J6S1718C						on the current Payment Estimate.			
	4830		MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$31,295.68)
	4830		MISC.	Material			-23	\$3,863.00	(\$88,849.00)
	4830		MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0099) due to user schirj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.	23	\$3,863.00	\$88,849.00
Total									(\$50,387.09)

Page 8 of 70 Revision 4/1/2020



					Co	ontract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work				
J6S1718	FAF-100-1(70)	Pavement, ADA, Signal and Drainage improvements	100	ST LOUIS	from Big Bend Road	oad to Lindbergh Boulevard					
J6S1718B	FAF-100-1(80)	Pedestrian Trail, Underpass & Sanitary Sewer	100	ST LOUIS	from Bremerton to E						
J6S1718C	FAF-100-1(81)	Pedestrian and Streetscape enhancements	100	ST LOUIS	from Kenmore Drive	e to Lindbergh					
Totals by Jo	b Numbers										
J6S1718	Posted Item Gross Item A	Adjustments	Item Pa	/	This Estimate \$396,691.71 (\$19,091.41) \$377,600.30	Previous \$5,755,743.31 \$254,614.48 \$6,010,357.79	To Date \$6,152,435.02 \$235,523.07 \$6,387,958.09				
	Incentive Disincentive Liquidated D Other Contra				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J6S1718B	Posted Item Pay Gross Item Adjustments Gross Item Pay				This Estimate \$100,390.58 \$0.00 \$100,390.58	Previous \$2,969,454.30 \$34,456.53 \$3,003,910.83	To Date \$3,069,844.88 \$34,456.53 \$3,104,301.41				
	Incentive Disincentive Liquidated D Other Contra				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				
J6S1718C	Posted Item Gross Item A	Adjustments	Item Pa	/	This Estimate \$79,220.00 (\$31,295.68) \$47,924.32	Previous \$110,527.20 \$137,196.22 \$247,723.42	To Date \$189,747.20 \$105,900.54 \$295,647.74				
	Incentive Disincentive Liquidated D Other Contra				\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00				

Revision 4/1/2020 Page 9 of 70



Exceptions (Discrepancies) This Estimate Period

Equation (Control Price and Services) Asserting (Control Price and Services) and the Services (Control Price and S	Exceptions (Discrepancies) This Estimate Period			
Number 2010, Material Sci 2000.0000008. Abereal 9000000000 - Compared Sci let field highest from the international Accordance Action Career Sci 1911 - Sci 1912 - Sci	Exceptions / Discrepencies	Explanation		Status
Namera 2000, Materials Set 0001010700-NDCODA Concrete Proposition of the Control Contr	Number 2510, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade	Working with materials to complete required testing.	schirj1	Overridden
Number OFD, Material Set 50410000, Material Orts DMDGPRE List understand Corrupted PE (**TOloren)**, Acceptant Action Control 17 (MDDGPRE**). It is implicated to the Complete required testing. **SOURCE Control Type: Insufficient Materials Project. 455116, Item 5041000, Project Item Lise Doubland Sign, Acceptance Action General Control (MDDGPRE**). It is implicated to Set 50120006. Materials 6551100006. Materials 655110006. M	Number 2680, Material Set 502110796, Material 0501CCPAQCQA - Concrete, Pavment contractor mix	Working with materials to complete required testing.	schirj1	Overridden
Numero (15), Material Set (514 000000), Material (977-AMTRIE-2019 - The Bar & Col-4 No. 0.0119 Gr.) Eliminate Exception Type: Insufficient Materials: Project y 557118, Item 505100, Project Item Line Colomo (150-1000), Project Item Line Eliminate Exception Type: Insufficient Materials: Project y 557118, Item 505100, Project Item Line Colomo (150-1000), Project Item Line Colomo (150-1000), Project Item Line Eliminate Exception Type: Insufficient Materials: Project y 557118, Item 505100, Project Item Line Colomo (150-1000), Project Item Line Eliminate Exception Type: Insufficient Materials: Project y 557118, Item 5051000, Project Item Line Klames (150-1000), Project Item Line Colomo (150-1000), Project Item Line Klames (150-1000), Project Item Line Colomo (150-1000), Project Item Line Northing with materials to complete required testing Northing with materials of complete required t	Number 0150, Material Set 504100096, Material 1013DMCRPE04 - Underdrain Corrugated PE	Working with materials to complete required testing.	schirj1	Overridden
Number 105, Material Set 561 000056, Material 1073./TATREZ3019 - The Bar E of clif 47 No. 6.0119 Gr 400000000000000000000000000000000000	Number 0150, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr	Working with materials to complete required testing.	schirj1	Overridden
Number 0158, Material Set 594100066, Material SPICEPARCOA - Contracte, Perminent contractor mix or COCAA. Acceptance Action Generic 0500 CPAPACCA is installicant. Estimate Exception Type: Installiciant Materials: Project J851718, Bren 0503902, Project Item Line Number 1058, Materials and Ecotogologo. Materials Project J851718, Bren 0503902, Project Item Line Number 1058, Materials Set 050390208, Materials O708MFC - Force Main Pipe, Acceptance Action Generic 0509078, bit shufflows: Estimate Exception Type: Installicant Materials: Project J851718, Bren 0503902, Project Item Line Number 3050, Materials Set 05030238, Materials 0726MFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insulficion. Estimate Exception Type: Installicant Materials: Project J851718, Bren 0503902, Project Item Line Number 3050, Materials Set 05030238, Materials 0726MFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insulficion. Estimate Exception Type: Insulficient Materials: Project J8517188, Bren 0503902, Project Item Line Number 3050, Materials Set 05030238, Materials 0726MFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insulficient. Estimate Exception Type: Insulficient Materials: Project J8517188, Bren 0503902, Project Item Line Number 3050, Materials Set 05030238, Materials O726MFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insulficient. Estimate Exception Type: Insulficient Materials: Project J8517188, Bren 0503902, Project Item Line Number 3050, Material Set 050300508, Materials O726MFC - Force Main Pipe, Acceptance Action Generic 0726MFC is insulficient. Estimate Exception Type: Insulficient Materials: Project J8517188, Bren 0503902, Project Item Line Number 2050, Material Set 050300508, Materials 100501, COCHARD-PCP-OF Resception PARCES ACTION Project Item Line Number 2050, Material Set 050300508, Materials 100501, COCHARD-PCP-OF Resception PARCES ACTION PARCES ACTION Project Item Line Number 2050, Material Set 050300508, Materials 100501, COCHARD-PCP-OF Resception PARCES ACTION PAR	Number 0150, Material Set 504100096, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr	Working with materials to complete required testing.	schirj1	Overridden
Namber 1850, Material Set 600390230, Material 00187W Material for Waterline, Acceptance Action Generic 0025W. It is irradiciont. Estimate Exception Type: Insufficient Materials: Project_US\$1718B, Item 6039023, Project Item Line Namber 2400, Material 59016002300, Material 0728MPPC - Force Main Pipe, Acceptance Action Generic 0728MPPC is insufficient. Estimate Exception Type: Insufficient Materials: Project_US\$1718B, Item 6039023, Project Item Line Namber 2400, Material Set 60092230, Material 0728MPPC - Force Main Pipe, Acceptance Action Generic 0728MPPC in situatificant. Estimate Exception Type: Insufficient Materials: Project_US\$1718B, Item 6039023, Project Item Line Namber 2500, Material 0726MPPC - Force Main Pipe, Acceptance Action Generic 0728MPPC in situatificant. Estimate Exception Type: Insufficient Materials: Project_US\$1718B, Item 6039023, Project Item Line Namber 2500, Material Set 60093030, Material 0726MPPC - Force Main Pipe, Acceptance Action Generic 0728MPPC is insufficient. Estimate Exception Type: Insufficient Materials: Project_US\$1718B, Item 6039003, Project Item Line Namber 2500, Material Set 60093050, Material 0750MPPC - Force Main Pipe, Acceptance Action Generic 0728MPPC is insufficient. Estimate Exception Type: Insufficient Materials: Project_US\$1718B, Item 6009005, Project Item Line Namber 2500, Material Set 60093050, Material 07510 CPCMID - PCCP or Main Pipe, Acceptance Action Generic 07510 CPCMID is insufficient. Estimate Exception Type: Insufficient Materials: Project_US\$1718B, Item 6009005, Project Item Line Namber 2500, Material Set 60093050, Material 07510 CPCMID - PCCP or Main Pipe, Acceptance Action Generic 07510 CPCMID is insufficient. Estimate Exception Type: Insufficient Materials: Project_US\$1718B, Item 6009001, Project Item Line Namber 2500, Material Set 6009005000, Material 07510 CPCMID Acception Acceptance Action Generic 07510 CPCMID Set Item Line Namber 2500, Material Set 6000000000000000000000000000000000000	Number 0150, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Payment contractor mix	Working with materials to complete required testing.	schirj1	Overridden
Number 3960. Material Set 809302306, Material 0726MPCP - Force Main Pipe, Acceptance Action Gernetic D726MPC is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718 B, tem 6039923, Project Item Line Number 3860, Material Set 803002306, Material 0726MPCP - Force Main Pipe, Acceptance Action Gernetic D726MPC is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718 B, tem 6039923, Project Item Line Number 3860, Material Set 803002306, Material 0726MPCP - Force Main Pipe, Acceptance Action Gernetic D726MPC is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718 B, tem 6039923, Project Item Line Number 370, Material Set 803002306, Material 0726MPCP - Force Main Pipe, Acceptance Action Gerotic D726MPC is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718 B, tem 6039903, Project Item Line Number 370, Material Set 803002306, Material 0726MPCP - Force Main Pipe, Acceptance Action Georetic D726MPC is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718 B, tem 6039903, Project Item Line Number 2800, Material Set 8030108, Material D726MPCP - Force Main Pipe, Acceptance Action Georetic D726MPC is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718 B, tem 6039903, Project Item Line Number 2800, Material Set 8030108, Material Set 9030108, Material Set 9030108, Project Item Line Number 2800, Material Set 9030108, Material Set 9030108, Insufficient. Estimate Exception Type: Insufficient Materials: Project J851718, Item 8030011, Project Item Line Number 2800, Material Set 90301036, Material Set 00301036, M	Number 1860, Material Set 603990296, Material 0603WL - Material for Waterline, Acceptance Action	Working with materials to complete required testing.	schirj1	Overridden
Number 380, Material Set 03992396, Material 0726MPFC - Force Main Pipe, Acceptance Action Genetic 0726MPFC is insufficient. Estimate Exception Type: Insufficient Materials: Project JBS1718, Item 8039023, Project Item Line Number 380, Material Set 03992396, Material 0726MPFC - Force Main Pipe, Acceptance Action Genetic 0726MPFC is insufficient. Estimate Exception Type: Insufficient Materials: Project JBS1718, Item 8039023, Project Item Line Number 380, Material Set 03992396, Material 0726MPFC - Force Main Pipe, Acceptance Action Genetic 0726MPFC is insufficient. Estimate Exception Type: Insufficient Materials: Project JBS1718, Item 8039023, Project Item Line Number 280, Material Set 0890956, Material 0726MPFC - Force Main Pipe, Acceptance Action Genetic 0726MPFC is insufficient. Estimate Exception Type: Insufficient Materials: Project JBS1718, Item 803903, Project Item Line Number 280, Material Set 0809056, Material 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment Contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concrete, Perment Contractor mix or OCOA, Acceptance Action Genetic 0801 CCPADCDA - Concr	Number 3840, Material Set 603992396, Material 0726MPFC - Force Main Pipe, Acceptance Action	Working with materials to complete required testing.	schirj1	Overridden
Reimen 2786/06/15 is insufficient Materials Project J651718, Item 639923, Project Item Line Number 3870, Material Set 603992366, Material 0726MPFC - Force Main Pipe, Acceptance Action Genetic 0726MPFC is insufficient. Betimate Exception Type: Insufficient Materials: Project J651718, Item 6389905, Project Item Line Number 2880, Material Set 603992366, Material 100510, CPCMLD is Insufficient. Betimate Exception Type: Insufficient Materials: Project J6517188, Item 6389905, Project Item Line Number 2880, Material Set 603990586, Material 100510, CPCMLD - PCCP or Masonry 1" Max LS/IDO, Acceptance Action Generic 100510 - (CPCMLD is Insufficient. Betimate Exception Type: Insufficient Materials: Project J6517188, Item 698905, Project Item Line Number 2880, Material Set 60390586, Material Set 6039058	Number 3850, Material Set 603992396, Material 0726MPFC - Force Main Pipe, Acceptance Action	Working with materials to complete required testing.	schirj1	Overridden
Number 3870, Material Set 603992396, Material OSE 603992396, Material Set 603992396, Material Set 603990396, Project Item Line Number 2880, Material Set 603990396, Material 10510 1.0. PCMLD = PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510. PCMLD = insufficient Estimate Exception Type: Insufficient Materials: Project J851718, Item 6039905, Project Item Line Number 2880, Material Set 603990396, Ma	Number 3860, Material Set 603992396, Material 0726MPFC - Force Main Pipe, Acceptance Action	Working with materials to complete required testing.	schirj1	Overridden
Number 2880, Material Set 608990596, Material 5007-007-007-007-007-007-007-007-007-007	Number 3870, Material Set 603992396, Material 0726MPFC - Force Main Pipe, Acceptance Action	Working with materials to complete required testing.	schirj1	Overridden
Number 2880, Material Set 6089905969, Material Concrete, Pavment contractor mix or OCQA. Acceptance Action Generic 0501CCPAQCQA is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718, Item 6092011, Project Item Line Number 0280, Material Set 609201196, Material 0501CCPAQCQA is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718, Item 6092012, Project Item Line Number 2020, Material Set 609201296, Material 60510CCPAQCQA is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718, Item 6092012, Project Item Line Number 2020, Material Set 609201296, Material 60510CCPAQCQA is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718, Item 6131012, Project Item Line Number 2030, Material Set 60101296, Material 6010200XXCS is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718, Item 7021212, Project Item Line Number 2020, Material Set 702121296, Material O7125172 - Galvanizing of Components for Str Steel, Acceptance Action Generic 07125172. Insufficient Materials: Project J851718, Item 7032003, Project Item Line Number 3080, Material Set 703200396, Material 60510CCB. A Concrete, Class B w/Air, Acceptance Action Generic 07125172. Insufficient Materials: Project J851718, Item 7032003, Project Item Line Number 3080, Material Set 703200396, Material 60510CCB. A Concrete, Class B w/Air, Acceptance Action Generic 07125172. Insufficient Materials: Project J851718, Item 7032003, Project Item Line Number 2200, Material Set 703200396, Material 60510CCB. A Concrete, Class B w/Air, Acceptance Action Generic 05010CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A, Material 10501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 05010CCB1, A is insufficient. Estimate Exception Type: Insufficient Materials: Project J851718, Item 7034219A, Project Item Line Number 2104, Material Se	Number 2880, Material Set 608990596, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,	Working with materials to complete required testing.	schirj1	Overridden
Number 2280, Material Set 609201196, Material 0501CCPAQCACA - Concrete, Pavment contractor mix or OCQA, Acceptance Action Generic 0501CCBA, a Set 1971	Number 2880, Material Set 608990596, Material 0501CCPAQCQA - Concrete, Pavment contractor mix	Working with materials to complete required testing.	schirj1	Overridden
Number 2940, Material Set 609201296, Material 0501CCPAQCQA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 6131012, Project Item Line Number 2300, Material Set 613101296, Material 5200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7021212, Project Item Line Number 2290, Material Set 702121296, Material 9210XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 3060, Material Set 703200396, Material 9501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 3060, Material Set 703200396, Material 5051CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 2320, Material Set 703200396, Material 0501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 10501CSB. Is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 0501CCB. A - Concrete, Class B-1 w/Air, Acceptance Action Generic 10505CSB. Is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 7034219A96, Material 0501CCB1. A - Concrete, Class B-2 w/Air, Acceptance Action Generic 10501CCB1. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line N	Number 0280, Material Set 609201196, Material 0501CCPAQCQA - Concrete, Payment contractor mix	Working with materials to complete required testing.	schirj1	Overridden
Number 0350, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7031212, Project Item Line Number 2290, Material Set 703121296, Material 0712STZC - Galvanizing of Components for Str Steel, Acceptance Action Generic 0712STZC is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7032003, Project Item Line Number 3000, Material Set 703200396, Material O501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 2320, Material Set 703200396, Material O501CCB. A - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 1053CSSIL - Concrete, Class B - W/Air, Acceptance Action Generic 0501CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034217, Project Item Line Number 2210, Material Set 7034219A9, Material O501CCB1A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 70342196, Material Set 70342196, Material O501CCB2A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material T053CSSIL - Concrete Sealer (CS) - Silane @. Acceptance Action Generic 0501CCB2A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item L	Number 2940, Material Set 609201296, Material 0501CCPAQCQA - Concrete, Pavment contractor mix	Working with materials to complete required testing.	schirj1	Overridden
Number 2290, Material Set 702121296, Material O712STZC - Galvanizing of Components for Str Steel, Acceptance Action Generic 0712STZC is insufficient. Stimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 3060, Material Set 703200396, Material	Number 0350, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade	Working with materials to complete required testing.	schirj1	Overridden
Number 3060, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7032003, Project Item Line Number 2320, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Working with materials to complete required testing. Working with materials to complete required testing. Working with materials to complete required testing. Schirj1 Overridden Working with materials to complete required testing. Working with materials to complete required testing. Schirj1 Overridden Working with materials to complete required testing. Working with materials to complete required testing. Schirj1 Overridden Working with materials to complete required testing.	Number 2290, Material Set 702121296, Material 0712STZC - Galvanizing of Components for Str Steel,	Working with materials to complete required testing.	schirj1	Overridden
Number 2320, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCB. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 0501CCB1. A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2210, Material Set 7034219A96, Material 0501CCB1. A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 0501CCB2. A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2. A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Working with materials to complete required testing. Schirj1 Overridden Working with materials to complete required testing.	Number 3060, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance	Working with materials to complete required testing.	schirj1	Overridden
Number 2210, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @. Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034219A, Project Item Line Number 2340, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Working with materials to complete required testing. Schirj1 Overridden Working with materials to complete required testing. Schirj1 Overridden Working with materials to complete required testing.	Number 2320, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance	Working with materials to complete required testing.	schirj1	Overridden
Number 2210, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Working with materials to complete required testing. Working with materials to complete required testing. Schirj1 Overridden Working with materials to complete required testing.	Number 2210, Material Set 7034219A96, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Working with materials to complete required testing.	schirj1	Overridden
Number 2340, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane Acceptance Action Generic 1053CSSIL is insufficient. Working with materials to complete required testing. working with materials to complete required testing. Schirj1 Overridden Working with materials to complete required testing.	Number 2210, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance	Working with materials to complete required testing.	schirj1	Overridden
Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient. Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034221, Project Item Line Working with materials to complete required testing. schirj1 Overridden	Number 2340, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance	Working with materials to complete required testing.	schirj1	Overridden
	Number 2340, Material Set 703422196, Material 1053CSSIL - Concrete Sealer (CS) - Silane @,	Working with materials to complete required testing.	schirj1	Overridden
		Working with materials to complete required testing.	schirj1	Overridden

Revision 4/1/2020 Page 10 of 70



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7034430, Project Item Line Number 2220, Material Set 703443096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSSRECAB - Epoxy Ctd Sprl Stl Rein for Anch Bolts @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7101000, Project Item Line Number 3130, Material Set 710100096, Material 1036RSDFEC42M29 - Rein Steel EC No. 9/M29 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7123301, Project Item Line Number 2380, Material Set 712330196, Material 0712STDIIG - Diaphram for Concrete I-Girder, Acceptance Action Generic 0712STDIIG is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7123610, Project Item Line Number 2390, Material Set 712361096, Material 0712STDRSB - Slab Drain, Acceptance Action Generic 0712STDRSB is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3160, Material Set 720100096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3160, Material Set 720100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3160, Material Set 720100096, Material 0720MSEW - MSE Wall System -Bridge Approved Design, Acceptance Action Generic 0720MSEW is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201000, Project Item Line Number 3160, Material Set 720100096, Material 1011GXT4 - Geotextile Fabric for Separation (T4), Acceptance Action Generic 1011GXT4 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7201200, Project Item Line Number 3170, Material Set 720120096, Material 1010SGBF - Select Gran Backfill for Structural Sys, Acceptance Action Generic 1010SGBF is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4100, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4110, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4130, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4140, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7269923, Project Item Line Number 4150, Material Set 726992396, Material 4028SPPV08 - 8" PVC Sewer Pipe, Acceptance Action Generic 4028SPPV08 is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7319902, Project Item Line Number 4180, Material Set 7319902, Material 3099XX - See Remarks for Description of Material, Acceptance Action Generic 3099XX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 7319902, Project Item Line Number 4220, Material Set 7319902, Material 1033MSDMPP - MSD Miscellaneous Precast Products, Acceptance Action Generic 1033MSDMPP is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7319902, Project Item Line Number 1670, Material Set 7319902, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7319902, Project Item Line Number 1670, Material Set 7319902, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance Action Generic 0614DFMNFC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 7319902, Project Item Line Number 1690, Material Set 7319902, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance Action Generic 0614DFMNFC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 8061007A, Project Item Line Number 0740, Material Set 8061007A96, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718B, Item 9017407, Project Item Line Number 3610, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718C, Item 9017407, Project Item Line	Working with materials to complete required testing.	schirj1	Overridden

Revision 4/1/2020 Page 11 of 70



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Feriod			
Exceptions / Discrepencies	Explanation	Entered By	Status
Number 4810, Material Set 901740796, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J6S1718C, Item 9019902, Project Item Line Number 4830, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 1910, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 1920, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 1930, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 1950, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 1990, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 2000, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 2020, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 2030, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 2040, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029902, Project Item Line Number 2050, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029903, Project Item Line Number 2110, Material Set 902990396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6S1718, Item 9029903, Project Item Line Number 2120, Material Set 902990396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with materials to complete required testing.	schirj1	Overridden
Estimate Exception Type: Item Overrun: Contract 210521-F01, Contract Project J6S1718B, Project Item Line Number 2770, Contract Line Item Number 2770, Item 6081012, Minor Item.	Working on Change Order.	schirj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210521-F01, Contract Project J6S1718, Project Item Line Number 1550, Contract Line Item Number 1550, Item 7259903, Minor Item.	Working on change order.	schirj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210521-F01, Contract Project J6S1718, Project Item Line Number 1590, Contract Line Item Number 1590, Item 7261015, Minor Item.	Working on change order.	schirj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 210521-F01, Contract Project J6S1718, Project Item Line Number 2230, Contract Line Item Number 2230, Item 7040104, Minor Item.	Working on change order.	schirj1	Acknowledged

Revision 4/1/2020 Page 12 of 70



Total Paid / All Items / All Estimates (Including this Estimate)

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTED To Date (See report generated date)
10521-F01	J6S1718	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	Qty 0.28	\$2,469,600.00	\$691,488.0
		0001	0020	2031000	CLASS A EXCAVATION	596.00	0.00	596.00	CUYD	0.00	\$13.40	\$0.0
		0001	0030	2035500	EMBANKMENT IN PLACE	106.00	0.00	106.00	CUYD	0.00	\$8.00	\$0.0
		0001	0040	2036000	COMPACTING EMBANKMENT	477.00	0.00	477.00	CUYD	0.00	\$10.45	\$0.0
		0001	0050	2037075	COMPACTING IN CUT	2.00	0.00	2.00	STA	0.00	\$2,123.00	\$0.0
		0001	0060	2071000	LINEAR GRADING CLASS 1	403.50	-403.50	0.00	STA	0.00	\$900.00	\$0.0
		0001	0070	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	60,618.00	0.00	60,618.00	SQYD	11,897.33	\$6.30	\$74,953.1
		0001	0080	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	1,248.30	0.00	1,248.30	TONS	0.00	\$124.50	\$0.0
		0001	0090	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	3,242.40	0.00	3,242.40	TONS	0.00	\$139.00	\$0.0
		0001	0100	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	12,462.40	0.00	12,462.40	TONS	0.00	\$87.00	\$0.0
		0001	0110	4030208	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP190C MIX)	14,886.20	0.00	14,886.20	TONS	0.00	\$80.00	\$0.0
		0001	0120	4071005	TACK COAT	31,850.00	0.00	31,850.00	GAL	30.00	\$2.50	\$75.0
		0001	0130	5021107	CONCRETE PAVEMENT (7 IN. NON-REINF)	7,894.00	0.00	7,894.00	SQYD	478.27	\$88.00	\$42,087.7
		0001	0140	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	2,377.40	0.00	2,377.40	SQYD	529.60	\$82.00	\$43,427.2
		0001	0150	5041000	CONCRETE APPROACH PAVEMENT	481.70	0.00	481.70	SQYD	116.70	\$115.00	\$13,420.5
		0001	0160	6071102	MODIFIED CONCRETE GUTTER TYPE B	424.00	0.00	424.00	LF	0.00	\$35.00	\$0.0
		0001	0170	6079903	MISC.48 " Decorative Pedestrian Fence (Structures)	733.00	0.00	733.00	LF	0.00	\$105.00	\$0.0
		0001	0180	6081012	TRUNCATED DOMES	2,477.00	0.00	2,477.00	SQFT	323.10	\$15.00	\$4,846.5
		0001	0190	6083008	8 IN. CONCRETE MEDIAN STRIP	1,535.20	0.00	1,535.20	SQYD	0.00	\$90.00	\$0.0
		0001	0200	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	424.00	0.00	424.00	LF	0.00	\$130.00	\$0.0
		0001	0210	6085007	PAVED APPROACH, 7 IN.	14,086.90	0.00	14,086.90	SQYD	4,384.25	\$76.00	\$333,203.0
		0001	0220	6086004	CONCRETE SIDEWALK, 4 IN.	14,425.90	0.00	14,425.90	SQYD	2,780.94	\$50.00	\$139,047.0
		0001	0230	6086008	CONCRETE SIDEWALK, 8 IN.	182.70	0.00	182.70	SQYD	0.00	\$84.00	\$0.0
		0001	0240	6089901	MISC.STAIRS AND HANDRAILS AT CURB RAMP 72	1.00	0.00	1.00	LS	0.00	\$5,700.00	\$0.0
		0001	0250	6089902	MISC.CONCRETE CURB RAMP (7 IN. THICK)	153.00	0.00	153.00	EA	21.00	\$1,765.00	\$37,065.0
		0001	0260	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	14,712.00	0.00	14,712.00	LF	3,290.42	\$30.00	\$98,712.6
		0001	0270	6091052	CURB AND GUTTER TYPE B	17,779.00	0.00	17,779.00	LF	5,214.29	\$30.00	\$156,428.7
			0280	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	1,311.00	0.00	1,311.00	LF	96.50	\$18.50	\$1,785.2
		0001	0290	6092012	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	3,878.00	0.00	3,878.00	LF	180.42	\$19.00	\$3,427.9
		0001	0300	6099903	MISC.MODIFIED CURB	873.00	0.00	873.00	LF	264.40	\$28.00	\$7,403.2
		0001	0310	6099903	MISC.MODIFIED CURB TYPE A	774.00	0.00	774.00	LF	79.30	\$25.50	\$2,022.1
		0001			FURNISHING TYPE 2 ROCK BLANKET		0.00		CUYD	608.60		
		0001	0320	6113020 6113040	PLACING TYPE 2 ROCK BLANKET	716.00 716.00	0.00	716.00 716.00	CUYD	608.60	\$30.00 \$18.00	\$18,258.0 \$10,954.8
			0340	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL		0.00		SQYD			
		0001			DEPTH PAVEMENT REPAIR	304.00		304.00		115.50	\$200.00	\$23,100.0
		0001	0350	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	304.00	0.00	304.00	SQYD	115.50	\$3.00	\$346.5
		0001	0360	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	304.00	0.00	304.00	SQYD	115.50	\$4.00	\$462.0
		0001	0370	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,266.00	0.00	1,266.00	LF	147.00	\$4.50	\$661.5
		0001	0380	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	760.00	0.00	760.00	EA	34.00	\$15.00	\$510.0
		0001	0390	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH	380.00	0.00	380.00	EA	2.00	\$13.00	\$26.0
		0001	0400	6161005	BASKETS) FOR FULL DEPTH PAVEMENT REPAIR CONSTRUCTION SIGNS	2,102.00	0.00	2,102.00	SQFT	2.102.00	\$9.50	\$19,969.0
		0001	0410	6161008	ADVANCED WARNING RAIL SYSTEM	87.00	0.00	87.00	EA	4.00	\$35.00	\$140.0
		0001	0420	6161009	FLAG ASSEMBLY	39.00	0.00	39.00	EA	5.00	\$25.00	\$125.0
		0001	0430	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.40	\$750,000.00	\$300,000.0
		0001	0440	6169901	MISC.TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING	1.00	0.00	1.00	LS	0.00	\$18,000.00	\$0.0
			0440	6169901	MISC. TRAFFIC SIGNAL MAINTENANCE AND PROGRAMMING MISC. NTCIP COMPLIANT CHANGEABLE MESSAGE SIGN	6.00	0.00	6.00	EA	6.00	\$3,500.00	\$21,000.0
		0001			(CONTRACTOR FURNISHED AND RETAINED)							
		0001	0460	6173101	CONCRETE TRAFFIC BARRIER, TYPE D (MODIFIED)	33.00	0.00	33.00	LF	0.00	\$250.00	\$0.0



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

					ne the Es		port Generated date and can differ from the posted amou	ased on Re				
Total Value POS To Date (See re generated dat	Unit Price	Total Posted Approved Qty	Unit	Total Current Quantity	Net Change Order	Bid Quantity	Description	Item Code	Line No.	Category	Project No.	Contract Nm.CONTRACT
\$30,58	\$22.45	1,362.50	LF	1,450.00	0.00	1,450.00	TEMPORARY TRAFFIC BARRIER, CONTRACTOR FURNISHED / RETAINED	6173600D	0470	0001	J6S1718	10521-F01
\$4,50	\$8.50	537.50	LF	1,260.00	0.00	1,260.00	RELOCATING TEMPORARY TRAFFIC BARRIER	6175010A	0480	0001		
;	\$643.00	0.00	EA	9.00	0.00	9.00	MISC.CONCRETE BARRIER HEIGHT TRANSITION	6179902	0490	0001		
	\$3,099,938.53	0.00	LS	0.00	-1.00	1.00	MOBILIZATION	6181000	0500	0001		
\$1,482,96	\$2,965,936.53	0.50	LS	1.00	1.00	0.00	MOBILIZATION	6181000	0501	0001		
\$	\$20.00	0.00	LF	2,680.00	0.00	2,680.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	6200015	0510	0001		
	\$300.00	0.00	EA	83.00	0.00	83.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	6200021	0520	0001		
\$	\$350.00	0.00	EA	11.00	0.00	11.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	6200027	0530	0001		
	\$1,600.00	0.00	EA	8.00	1.00	7.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	6200036	0540	0001		
	\$50.00	0.00	EA	24.00	0.00	24.00	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN WHITE, YIELD LINE TRIANGLES	6200042	0550	0001		
\$1,02	\$0.16	6,381.00	LF	64,692.00	0.00	64,692.00	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6205901A	0560	0001		
\$1,62	\$0.22	7,386.00	LF	82,056.00	0.00	82,056.00	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	6205902A	0570	0001		
\$	\$1.00	0.00	LF	2,401.00	0.00	2,401.00	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6206000C	0580	0001		
\$	\$5.00	0.00	LF	258.00	0.00	258.00	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	6206125A	0590	0001		
\$	\$20.00	0.00	LF	72.00	0.00	72.00	4 IN. WHITE ACRYLIC COPOLYMER FAST DRY PAVEMENT MARKING PAINT	6206150A	0600	0001		
\$	\$10.00	0.00	LF	168.00	0.00	168.00	4 IN. YELLOW ACRYLIC COPOLYMER FAST DRY PAVEMENT MARKING PAINT	6206151A	0610	0001		
\$5,93	\$0.70	8,484.00	LF	17,981.00	0.00	17,981.00	PAVEMENT MARKING REMOVAL	6207001	0620	0001		
	\$40.00	0.00	EA	37.00	0.00	37.00	MISC.PARKING BLOCK	6209902	0630	0001		
	\$13.25	0.00	SQYD	2,366.00	0.00	2,366.00	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	6221001	0640	0001		
	\$3.45	0.00	SQYD	120,693.00	0.00	120,693.00	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	6221003	0650	0001		
\$4,13	\$4.00	1,033.10	SQYD	1,182.00	0.00	1,182.00	SEPARATION GEOTEXTILE	6240104A	0660	0001		
\$55,00	\$275,000.00	0.20	LS	1.00	0.00	1.00	CONTRACTOR FURNISHED SURVEYING AND STAKING	6274000	0670	0001		
	\$45.00	0.00	SQFT	2,272.00	0.00	2,272.00	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	7201000	0680	0001		
	\$60.00	0.00	SQFT	135.00	0.00	135.00	MISC.RE-CONSTRUCT WALL IN PLACE	7209904	0690	0001		
	\$36.00	0.00	SQFT	2,277.00	0.00	2,277.00	MISC.SMALL BLOCK WALL	7209904	0700	0001		
	\$8.45	0.00	SQYD	17,974.00	0.00	17,974.00	TURF TYPE TALL FESCUE SODDING	8031000A	0710	0001		
	\$5,000.00	0.00	ACRE	1.00	0.00	1.00	MISC.FERTILIZER, SEEDING, AND MULCHING	8059919	0720	0001		
	\$1.90	0.00	LF	6.00	0.00	6.00	ALTERNATE DITCH CHECK	8061006	0730	0001		
\$19	\$15.25	13.00	EA	204.00	0.00	204.00	CURB INLET CHECK	8061007A	0740	0001		
\$1,10	\$16.00	69.35	CUYD	370.00	0.00	370.00	SEDIMENT REMOVAL	8061016	0750	0001		
	\$1,800.00	0.00	ACRE	2.00	0.00	2.00	TEMPORARY SEEDING	8061017	0760	0001		
	\$0.35	0.00	LF	17,312.00	0.00	17,312.00	SILT FENCE	8061019	0770	0001		
\$6,0	\$25.00	242.00	LF	456.00	0.00	456.00	TYPE C BERM	8061050	0780	0001		
	\$1,900.00	0.00	EA	2.00	0.00	2.00	RELOCATED POLE	9011010	0790	0020		
	\$2,186.00	0.00	EA	12.00	0.00	12.00	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	9011030	0800	0020		
	\$847.00	0.00	EA	12.00	0.00	12.00	BRACKET ARM, 15 FT. OR 4.6 M	9011115	0810	0020		
	\$425.00	0.00	EA	25.00	0.00	25.00	LUMINAIRE, LED-A	9011311	0820	0020		
	\$10.50	0.00	LF	92.00	0.00	92.00	CONDUIT, 2 IN. RIGID, IN TRENCH	9013002	0830	0020		
\$4,9	\$27.50	181.00	LF	309.00	0.00	309.00	CONDUIT, 4 IN. RIGID, PUSHED	9014004	0840	0020		
	\$6.00	0.00	LF	89.00	0.00	89.00	TRENCHING TYPE I	9015010	0850	0020		
	\$1.00	0.00	LF	2,500.00	0.00	2,500.00	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	9017110	0860	0020		
	\$5.20	0.00	LF	570.00	0.00	570.00	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	9017407	0870	0020		
,		0.00				12.00	NEUTRAL, 8 AWG POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	9018230	0880	0020		
	\$980.00		EA	12.00	0.00							

Revision 4/1/2020 Page 14 of 70



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718	0020	0900	9019902	MISC.REMOVE AND RELOCATE PRIVATELY-OWNED LIGHT POLE	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.00
		0030	0910	9020115	SIGNAL HEAD, TYPE 5T	1.00	0.00	1.00	EA	0.00	\$971.00	\$0.00
		0030	0920	9020211	SIGNAL HEAD, TYPE 1S	52.00	0.00	52.00	EA	0.00	\$443.00	\$0.00
		0030	0930	9020213	SIGNAL HEAD, TYPE 3S	6.00	0.00	6.00	EA	0.00	\$679.00	\$0.00
		0030	0940	9020214	SIGNAL HEAD, TYPE 4S	6.00	0.00	6.00	EA	0.00	\$815.00	\$0.00
		0030	0950	9020215	SIGNAL HEAD, TYPE 5S	3.00	0.00	3.00	EA	0.00	\$940.00	\$0.00
		0030	0960	9020513	SIGNAL HEAD, TYPE 3B	30.00	0.00	30.00	EA	0.00	\$877.00	\$0.00
		0030	0970	9020514	SIGNAL HEAD, TYPE 4B	11.00	0.00	11.00	EA	0.00	\$1,021.00	\$0.00
		0030	0980	9020515	SIGNAL HEAD, TYPE 5B	2.00	0.00	2.00	EA	0.00	\$1,346.00	\$0.00
		0030	0985	9020833	SH-FLAT SHEET - SIGNAL SIGN	242.00	0.00	242.00	SQFT	0.00	\$34.33	\$0.00
		0030	0990	9020834	SIGNAL SIGN, MOUNTING HARDWARE	40.00	0.00	40.00	EA	0.00	\$297.00	\$0.00
		0030	1000	9022708	POST, SIGNAL 8 FT. OR 2.4 M	31.00	0.00	31.00	EA	0.00	\$538.00	\$0.00
		0030	1010	9022715	POST, SIGNAL 15 FT. OR 4.6 M	4.00	0.00	4.00	EA	0.00	\$690.00	\$0.00
		0030	1030	9023125	POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	2.00	0.00	2.00	EA	0.00	\$6,917.00	\$0.00
		0030	1040	9023130	POST, TYPE CL, 30 FT. ARM OR 9.1 M ARM	2.00	0.00	2.00	EA	0.00	\$8,117.00	\$0.00
		0030	1050	9023135	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	1.00	0.00	1.00	EA	0.00	\$8,018.00	\$0.00
		0030	1060	9023140	POST, TYPE CL, 40 FT. ARM OR 12.2 M ARM	4.00	0.00	4.00	EA	0.00	\$10,954.00	\$0.00
		0030	1070	9023150	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$12,000.00	\$0.00
		0030	1075	9023240	POST, TYPE C, 40 FT. ARM OR 12.2 M ARM	1.00	0.00	1.00	EA	0.00	\$9,361.00	\$0.00
		0030	1077	9023320	POST, TYPE B, LONGEST ARM 20 FT. OR 6.1 M	1.00	0.00	1.00	EA	0.00	\$7,728.00	\$0.00
		0030	1080	9023435	POST, TYPE BL, LONGEST ARM 35 FT. OR 10.7 M	1.00	0.00	1.00	EA	0.00	\$13,405.00	\$0.00
		0030	1090	9023455	POST, TYPE BL, LONGEST ARM 55 FT.	1.00	0.00	1.00	EA	0.00	\$20,332.00	\$0.00
		0030	1100	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	5.00	0.00	5.00	EA	0.00	\$16,878.00	\$0.00
		0030	1110	9024975	VIDEO DETECTION SYSTEM	7.00	0.00	7.00	EA	0.00	\$16,428.00	\$0.00
		0030	1120	9025020	CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE	30.00	0.00	30.00	LF	0.00	\$16.00	\$0.00
		0030	1130	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	1,840.00	0.00	1,840.00	LF	0.00	\$12.50	\$0.00
		0030	1140	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	700.00	0.00	700.00	LF	0.00	\$13.50	\$0.00
		0030	1150	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	330.00	0.00	330.00	LF	0.00	\$15.60	\$0.00
		0030	1160	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	480.00	0.00	480.00	LF	0.00	\$24.00	\$0.00
		0030	1170	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	100.00	0.00	100.00	LF	0.00	\$25.00	\$0.00
		0030	1180	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	1,130.00	0.00	1,130.00	LF	0.00	\$27.00	\$0.00
		0030	1190	9027502	CONDUIT, 2 IN., EXTERNAL ON STRUCTURE	30.00	0.00	30.00	LF	0.00	\$94.00	\$0.00
		0030	1200	9028204	CABLE, 4 AWG 1 CONDUCTOR, POWER	300.00	0.00	300.00	LF	0.00	\$2.25	\$0.00
		0030	1210	9028302	CABLE, 12 AWG 2 CONDUCTOR	2,380.00	0.00	2,380.00	LF	0.00	\$1.25	\$0.00
		0030	1220	9028308	CABLE, 16 AWG 2 CONDUCTOR	8,290.00	0.00	8,290.00	LF	0.00	\$1.15	\$0.00
		0030	1230	9028310	CABLE, 16 AWG 5 CONDUCTOR	8,360.00	0.00	8,360.00	LF	0.00	\$1.25	\$0.00
		0030	1240	9028311	CABLE, 16 AWG 7 CONDUCTOR	12,210.00	0.00	12,210.00	LF	0.00	\$1.35	\$0.00
		0030	1250	9028611	POWER SUPPLY ASSEMBLY, TYPE 1 WITH 120V LIGHTING CONTROL CABINET	1.00	0.00	1.00	EA	0.00	\$3,569.00	\$0.00
		0030	1260	9028621	POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING CONTROL CABINET	2.00	0.00	2.00	EA	0.00	\$4,800.00	\$0.00
		0030	1270	9028810	PULL BOX, PREFORMED CLASS 1	6.00	0.00	6.00	EA	0.00	\$990.00	\$0.00
		0030	1280	9028811	PULL BOX, PREFORMED CLASS 2	11.00	0.00	11.00	EA	0.00	\$1,350.00	\$0.00
		0030	1290	9028812	PULL BOX, PREFORMED CLASS 3	5.00	0.00	5.00	EA	0.00	\$1,650.00	\$0.00
		0030	1300	9028821	PULL BOX, CONCRETE, DOUBLE, TYPE A	3.00	0.00	3.00	EA	0.00	\$3,400.00	\$0.00
		0030	1310	9029100	BASE, CONCRETE	69.40	0.00	69.40	CUYD	0.00	\$1,350.00	\$0.00
		0030	1320	9029902	MISC.AUDIBLE PEDESTRIAN PUSH BUTTONS AND SIGNING	54.00	0.00	54.00	EA	0.00	\$726.00	\$0.00
		0030	1330	9029902	MISC.NETWORK CONNECTED SIGNAL MONITOR	7.00	0.00	7.00	EA	0.00	\$1,196.00	\$0.00

Revision 4/1/2020 Page 15 of 70



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718	0030	1340	9029902	MISC.RECTANGULAR RAPID FLASHING BEACON	7.00	0.00	7.00	EA	0.00	\$10,171.00	\$0.00
		0040	1350	9031010	CONCRETE FOOTINGS, EMBEDDED	8.80	0.00	8.80	CUYD	0.00	\$1,000.00	\$0.00
		0040	1360	9031220	PIPE POSTS	5,590.00	0.00	5,590.00	LB	0.00	\$7.00	\$0.00
		0040	1370	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	24.00	0.00	24.00	EA	0.00	\$300.00	\$0.00
		0040	1380	9031250A	TUBE) U-CHANNEL POST, 3 LB	84.00	0.00	84.00	LF	0.00	\$20.00	\$0.00
		0040	1390	9031260	WOOD POST, 4 IN. BY 4 IN.	46.00	0.00	46.00	LF	0.00	\$25.00	\$0.00
		0040	1400	9031261	WOOD POST, 4 IN. BY 6 IN.	28.00	0.00	28.00	LF	0.00	\$25.00	\$0.00
		0040	1410		2 IN. PSST POST - 12 GA.	2,507.00	0.00	2,507.00	LF	0.00	\$15.00	\$0.00
		0040	1420	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	582.00	0.00	582.00	LF	0.00	\$28.00	\$0.00
		0040	1430	9035004A	SH-FLAT SHEET	1,763.00	0.00	1,763.00	SQFT	0.00	\$25.00	\$0.00
		0055	1440	2063000	CLASS 3 EXCAVATION	14,695.00	0.00	14,695.00	CUYD	5,066.61	\$31.00	\$157,064.91
		0055	1450	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	1.00	\$2,080.00	\$2,080.00
			1460	6149902	MISC.ADA COMPLIANT GRATE	1.00	0.00	1.00	EA	0.00	\$1,116.00	\$0.00
		0055	1470	7250312A	12 IN. PIPE GROUP B	25.00		25.00	LF			\$0.00
		0055			15 IN. PIPE GROUP B		0.00			0.00	\$96.00	\$66.641.70
		0055	1480	7250315A		2,420.00	0.00	2,420.00	LF	912.90	\$73.00	
		0055	1490	7250318A	18 IN. PIPE GROUP B	5,456.00	0.00	5,456.00	LF	1,188.50	\$81.00	\$96,268.50
		0055	1500	7250321A	21 IN. PIPE GROUP B	310.00	0.00	310.00	LF	0.00	\$98.00	\$0.00
		0055	1510	7250324A	24 IN. PIPE GROUP B	1,102.00	0.00	1,102.00	LF	241.00	\$98.00	\$23,618.00
		0055	1520	7250330A	30 IN. PIPE GROUP B	154.00	0.00	154.00	LF	153.00	\$121.00	\$18,513.00
		0055	1530	7250336A	36 IN. PIPE GROUP B	493.00	0.00	493.00	LF	471.00	\$143.00	\$67,353.00
		0055	1540	7259902	MISC.8" CLEANOUT	1.00	0.00	1.00	EA	1.00	\$1,244.00	\$1,244.00
		0055	1550	7259903	MISC.8" PVC PIPE	5.00	0.00	5.00	LF	18.00	\$114.00	\$2,052.00
		0055	1560	7259903	MISC.CLASS III RCP PIPE - 15"	141.00	0.00	141.00	LF	85.00	\$103.00	\$8,755.00
		0055	1570	7259903	MISC.CLASS III RCP PIPE - 18"	169.00	0.00	169.00	LF	45.00	\$118.00	\$5,310.00
		0055	1580	7259903	MISC.CLASS III RCP PIPE - 21"	12.00	0.00	12.00	LF	0.00	\$168.00	\$0.00
		0055	1590	7261015	15 IN. PIPE GROUP A	271.00	0.00	271.00	LF	292.00	\$99.00	\$28,908.00
		0055	1600	7261018	18 IN. PIPE GROUP A	1,272.00	0.00	1,272.00	LF	0.00	\$91.00	\$0.00
		0055	1610	7261021	21 IN. PIPE GROUP A	124.00	0.00	124.00	LF	0.00	\$103.00	\$0.00
		0055	1620	7261024	24 IN. PIPE GROUP A	383.00	0.00	383.00	LF	317.00	\$112.00	\$35,504.00
		0055	1630	7261030	30 IN. PIPE GROUP A	166.00	0.00	166.00	LF	94.00	\$121.00	\$11,374.00
		0055	1640	7261036	36 IN. PIPE GROUP A	183.00	0.00	183.00	LF	93.00	\$137.00	\$12,741.00
		0055	1650	7269902	MISC.MSD STANDARD CONNECTION TO LARGE SEWERS	3.00	0.00	3.00	EA	0.00	\$5,307.00	\$0.00
		0055	1660	7319902	MISC.REPLACE EXISTING INLET TOP WITH MAHNOLE FRAME AND LOCKING COVER	2.00	0.00	2.00	EA	0.00	\$1,888.00	\$0.00
		0055	1670	7319902	MISC.REPLACE EXISTING INLET TOP WITH MANHOLE FRAME AND COVER	9.00	0.00	9.00	EA	5.00	\$1,962.00	\$9,810.00
		0055	1680	7319902	MISC.REPLACE EXISTING MANHOLE COVER WITH LOCKING COVER	3.00	0.00	3.00	EA	0.00	\$939.00	\$0.00
		0055	1690	7319902	MISC.TBR&R PER MSD INSPECTOR	20.00	0.00	20.00	EA	7.00	\$2,253.00	\$15,771.00
		0055	1700	7319903	MISC.MSC PCC DOUBLE TRAPPED STEET INLET	8.00	0.00	8.00	LF	8.00	\$1,628.00	\$13,024.00
		0055	1710	7319903	MISC.MSD PCC 2 GRATE INLET WITH SIDE INTAKE - 48" BASE	155.00	0.00	155.00	LF	20.00	\$1,001.00	\$20,020.00
		0055	1720	7319903	MISC.MSD PCC 2 GRATE INLET WITH SIDE INTAKE - 60" BASE	46.00	0.00	46.00	LF	38.00	\$1,014.00	\$38,532.00
		0055	1730	7319903	MISC.MSD PCC 2 GRATE STEET INLET - 48" BASE	27.00	0.00	27.00	LF	16.00	\$816.00	\$13,056.00
		0055	1740	7319903	MISC.MSD PCC 42" SHORT TOP MANHOLE	6.00	0.00	6.00	LF	6.00	\$708.00	\$4,248.00
		0055	1750	7319903	MISC.MSD PCC 48" MANHOLE	249.00	0.00	249.00	LF	64.00	\$775.00	\$49,600.00
		0055	1760	7319903	MISC.MSD PCC 48" MANHOLE WITH LOCKING COVER	45.00	0.00	45.00	LF	8.00	\$792.00	\$6,336.00
		0055	1770	7319903	MISC.MSD PCC 60" MANHOLE	50.00	0.00	50.00	LF	21.00	\$917.00	\$19,257.00
		0055	1780	7319903	MISC.MSD PCC 60" MANHOLE WITH LOCKING COVER	19.00	0.00	19.00	LF	6.00	\$957.00	\$5,742.00
		0055	1790	7319903	MISC.MSD PCC 72" MANHOLE WITH LOCKING COVER	6.00	0.00	6.00	LF	6.00	\$1,116.00	\$6,696.00

Revision 4/1/2020 Page 16 of 70



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Total Value POST	Unit Price	Total	Generate Unit	Total	Net	Bid	port Generated date and can differ from the posted amou Description	Item	Line	Category	Project	Contract
To Date (See rep generated date)		Posted Approved Qty		Current Quantity	Change Order	Quantity		Code	No.		No.	Nm.CONTRACT
\$5,185	\$1,037.00	5.00	LF	5.00	0.00	5.00	MISC.MSD PCC AREA INLET - 4 SIDES	7319903	1800	0055	J6S1718	0521-F01
\$79,929	\$963.00	83.00	LF	313.00	0.00	313.00	MISC.MSD PCC DOUBLE STREET INLET	7319903	1810	0055		
\$63,140	\$770.00	82.00	LF	167.00	0.00	167.00	MISC.MSD PCC SINGLE STREET INLET - 48" BASE	7319903	1820	0055		
\$28,942	\$998.00	29.00	LF	53.00	0.00	53.00	MISC.MSD PCC SINGLE STREET INLET - 60" BASE	7319903	1830	0055		
\$0	\$1,335.00	0.00	LF	5.00	0.00	5.00	MISC.MSD PCC TRAPPED 2 GRATE INLET WITH SIDE INTAKE - 48" BASE	7319903	1840	0055		
\$1,700	\$100.00	17.00	EA	81.00	0.00	81.00	WATER	6039902	1850	0060		
\$38,872	\$4,859.00	8.00	EA	44.00	0.00	44.00	WATER	6039902	1860	0060		
\$1,10	\$100.00	11.00	EA	127.00	0.00	127.00	GAS	6039932	1870	0060		
\$6,25	\$250.00	25.00	EA	165.00	0.00	165.00	ADJUSTING MANHOLE	6042010	1880	0060		
\$5,73	\$956.00	6.00	EA	34.00	0.00	34.00	ADJUSTING BASIN OR INLET	6042020	1890	0060		
\$	\$1,519.00	0.00	LS	1.00	0.00	1.00	MISC.Relocate Video Detection System	9029901	1900	0065		
\$12,46	\$6,232.00	2.00	EA	2.00	0.00	2.00	MISC.19' Pole, w/38' Mast Arm, Steel	9029902	1910	0065		
\$6,60	\$6,604.00	1.00	EA	2.00	0.00	2.00	MISC.19' Pole, w/44' Mast Arm, Steel	9029902	1920	0065		
\$6,90	\$2,300.00	3.00	EA	4.00	0.00	4.00	MISC.Base, Type B-9, Concrete	9029902	1930	0065		
\$	\$1,348.00	0.00	EA	1.00	0.00	1.00	MISC.Base, Type C-3, Concrete	9029902	1940	0065		
\$2,97	\$2,979.00	1.00	EA	1.00	0.00	1.00	MISC.Base, Type D-8PH, Concrete	9029902	1950	0065		
\$0	\$980.00	0.00	EA	1.00	0.00	1.00	MISC Conduit Repair (locate broken conduit, excavate, remove existing cable, repair/replace conduit, reinstall cable, backfill and restore) (Does not include sidewalk or pavement removal and replacement)	9029902	1960	0065		
\$	\$900.00	0.00	EA	8.00	0.00	8.00	MISC.Detector, Pedestrian Push Button, APS, Freezeproof	9029902	1970	0065		
\$	\$560.00	0.00	EA	1.00	0.00	1.00	MISC.Post, Signal, w/Sq. Pedestal Base and Post Cap, 10' Total Height, Aluminum	9029902	1980	0065		
\$3,40	\$3,400.00	1.00	EA	1.00	0.00	1.00	MISC.Pull Box, Double, Concrete	9029902	1990	0065		
\$4,60	\$2,300.00	2.00	EA	4.00	0.00	4.00	MISC.Pull Box, Single, Concrete	9029902	2000	0065		
5	\$386.00	0.00	EA	8.00	0.00	8.00	MISC.Signal Head, Type 1S, Pedestrian	9029902	2010	0065		
\$5,14	\$1,715.00	3.00	EA	4.00	0.00	4.00	MISC.Signal Head, Type 34S	9029902	2020	0065		
\$5,26	\$878.00	6.00	EA	8.00	0.00	8.00	MISC.Signal Head, Type 3B, Terminal Compartment, and Astro Bracket Mounting	9029902	2030	0065		
\$3,06	\$1,021.00	3.00	EA	4.00	0.00	4.00	MISC.Signal Head, Type 4B, Terminal Compartment, and Astro Bracket Mounting	9029902	2040	0065		
5	\$1.00	3.00	EA	4.00	0.00	4.00	MISC.Signal Head, Type 4S	9029902	2050	0065		
5	\$1.00	0.00	LF	200.00	0.00	200.00	MISC.Cable, Communication, #18 Gauge, 4 Conductor (APS)	9029903	2060	0065		
	\$1.80	0.00	LF	100.00	0.00	100.00	MISC.Cable, Power, #6 Gauge, 1 Conductor	9029903	2070	0065		
\$	\$1.20	0.00	LF	180.00	0.00	180.00	MISC.Cable, Power, Video Detection Camera	9029903	2080	0065		
	\$1.10	0.00	LF	4,000.00	0.00	4,000.00	MISC.Cable, Push Button and/or Detector Loop Lead-In, #18 Gauge, 2 Conductor (Shielded)	9029903	2090	0065		
	\$1.30	0.00	LF	730.00	0.00	730.00	MISC.Cable, Signal, #14 Gauge, 5 Conductor	9029903	2100	0065		
\$4,20	\$1.55	2,710.00	LF	3,610.00	0.00	3,610.00	MISC.Cable, Signal, #14 Gauge, 7 Conductor	9029903	2110	0065		
\$12,74	\$26.00	490.00	LF	490.00	0.00	490.00	MISC.Conduit, 4"	9029903	2120	0065		
5	\$1.80	0.00	LF	260.00	0.00	260.00	MISC.Wire, Stranded Ground, #6 Gauge	9029903	2130	0065		
\$17,8	\$66.00	271.00	LF	271.00	0.00	271.00	CURB REMOVAL	2164000	2140	0070		
\$6,9	\$52.00	134.00	LF	134.00	0.00	134.00	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	2165000	2150	0070		
\$30,42	\$45.00	676.00	SQFT	676.00	0.00	676.00	MISC.PARTIAL REMOVAL & REPLACEMENT OF APPROACH SLAB	2169904	2160	0070		
\$18,3	\$15.00	1,220.00	SQFT	1,220.00	0.00	1,220.00	MISC.REMOVAL OF EXISTING CANTILEVER SIDEWALK	2169904	2170	0070		
	\$130.00	0.00	LF	269.00	0.00	269.00	MISC.(30 IN.) DECORATIVE PEDESTRIAN FENCE	6079903	2180	0070		
	\$120.00	0.00	LF	37.00	0.00	37.00	MISC.(74.5 IN.) DECORATIVE PEDESTRIAN FENCE	6079903	2190	0070		
	\$58.00	0.00	SQYD	1,298.00	0.00	1,298.00	MISC.EPOXY URETHANE POLYMER WEARING SURFACE	6239905	2205	0070		
\$37,9	\$140.00	271.00	LF	271.00	0.00	271.00	TYPE D BARRIER	7034219A	2210	0070		
\$38,4	\$17.00	2,259.00	SQFT	2,259.00	0.00	2,259.00	SIDEWALK (BRIDGES)	7034430	2220	0070		
\$10,40	\$65.00	160.00	SQFT	50.00	0.00	50.00	HALF-SOLE REPAIR	7040104	2230	0070		
\$10,31	\$77.00	134.00	LF	134.00	0.00	134.00	OPEN CELL FOAM JOINT SEAL	7172054	2240	0070		

Revision 4/1/2020 Page 17 of 70



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values ar	e based on Report (Reperated date and	can differ from the posted a	amount at the time the F	stimate was Generated

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
10521-F01	J6S1718	0071	2250	2061000	CLASS 1 EXCAVATION	114.00	0.00	114.00	CUYD	114.00	\$55.00	\$6,270.00
		0071	2260	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$150,000.00	\$150,000.0
		0071	2270	5031010A	BRIDGE APPROACH SLAB (MAJOR)	418.00	0.00	418.00	SQYD	0.00	\$252.00	\$0.0
		0071	2280	6079903	MISC.DECORATIVE PEDESTRIAN FENCE	265.00	0.00	265.00	LF	0.00	\$301.00	\$0.0
		0071	2290	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	826.00	0.00	826.00	LF	598.00	\$87.00	\$52,026.0
		0071	2300	7025001	DYNAMIC PILE TESTING	2.00	0.00	2.00	EA	2.00	\$2,000.00	\$4,000.0
		0071	2310	7027000	PILE POINT REINFORCEMENT	28.00	0.00	28.00	EA	28.00	\$150.00	\$4,200.0
		0071	2320	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	91.00	0.00	91.00	CUYD	91.00	\$724.00	\$65,884.0
		0071	2330	7034219A	TYPE D BARRIER	398.00	0.00	398.00	LF	0.00	\$140.00	\$0.0
		0071	2340	7034221	SLAB ON CONCRETE NU-GIRDER	1,201.00	0.00	1,201.00	SQYD	1,140.00	\$360.00	\$410,400.0
		0071	2350	7034430	SIDEWALK (BRIDGES)	1,007.00	0.00	1,007.00	SQFT	0.00	\$13.00	\$0.0
		0071	2360	7056022	NU 43, PRESTRESSED CONCRETE NU-GIRDER	1,210.00	0.00	1,210.00	LF	1,210.00	\$267.50	\$323,675.0
		0071	2370	7079903	MISC.CONDUIT SYSTEM ON STRUCTURE	283.00	0.00	283.00	LF	0.00	\$25.00	\$0.0
		0071	2380	7123301	STEEL INTERMEDIATE DIAPHRAGM FOR P/S CONCRETE GIRDERS	6.00	0.00	6.00	EA	6.00	\$600.00	\$3,600.0
		0071	2390	7123610	SLAB DRAIN	12.00	0.00	12.00	EA	12.00	\$240.00	\$2,880.0
		0071	2400	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$4,600.00	\$0.0
		0071	2410	7161003	LAMINATED NEOPRENE BEARING PAD (TAPERED)	22.00	0.00	22.00	EA	0.00	\$360.00	\$0.0
		0001	5001	6189901	MISC.Payment for Contract Bond	0.00	1.00	1.00	LS	1.00	\$134,002.00	\$134,002.0
		0001	5002	2079909	MISC.Modified Linear Grading, Class 2	0.00	403.50	403.50	STA	90.00	\$1,600.00	\$144,000.0
		0055	5003	2063100	CLASS 3 EXCAVATION IN ROCK	0.00	20.00	20.00	CUYD	0.00	\$85.00	\$0.0
	Project J65	61718 - Tota	al Value F	Posted to Da	te as of Report Generated Date							\$6,152,435.0
	J6S1718B	0001	2420	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.20	\$150,000.00	\$30,000.0
		0001	2430	2024027	REMOVAL OF THERMAL SYSTEM INSULATION ACM (FRIABLE)	4.00	0.00	4.00	SQFT	4.00	\$187.50	\$750.0
		0001	2430 2440	2024027	REMOVAL OF THERMAL SYSTEM INSULATION ACM (FRIABLE) REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE)	4.00 15.00	0.00	4.00 0.00	SQFT	4.00 0.00	\$187.50 \$50.00	
												\$0.0
		0001	2440	2024038	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE)	15.00	-15.00	0.00	SQFT	0.00	\$50.00	\$0.0 \$13,357.0
		0001	2440 2450	2024038	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS	15.00 1,924.00	-15.00 1,182.30	0.00 3,106.30	SQFT	0.00 3,106.30	\$50.00 \$4.30	\$0.0 \$13,357.0 \$7,524.0
		0001 0001 0001	2440 2450 2460	2024038 2024043 2024046	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE)	15.00 1,924.00 627.00	-15.00 1,182.30 0.00	0.00 3,106.30 627.00	SQFT SQFT LF	0.00 3,106.30 627.00	\$50.00 \$4.30 \$12.00	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0
		0001 0001 0001 0001	2440 2450 2460 2470	2024038 2024043 2024046 2024070	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE	15.00 1,924.00 627.00 310.00	-15.00 1,182.30 0.00 40.00	0.00 3,106.30 627.00 350.00	SQFT SQFT LF SQFT	0.00 3,106.30 627.00 350.00	\$50.00 \$4.30 \$12.00 \$19.50	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3
		0001 0001 0001 0001 0001	2440 2450 2460 2470 2480	2024038 2024043 2024046 2024070 2024098	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE)	15.00 1,924.00 627.00 310.00 1,914.00	-15.00 1,182.30 0.00 40.00	0.00 3,106.30 627.00 350.00 1,914.00	SQFT SQFT LF SQFT SQFT	0.00 3,106.30 627.00 350.00 1,914.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0
		0001 0001 0001 0001 0001	2440 2450 2460 2470 2480 2490	2024038 2024043 2024046 2024070 2024098 2029950	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS	15.00 1,924.00 627.00 310.00 1,914.00	-15.00 1,182.30 0.00 40.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00	SQFT SQFT LF SQFT SQFT LS	0.00 3,106.30 627.00 350.00 1,914.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0
		0001 0001 0001 0001 0001 0001	2440 2450 2460 2470 2480 2490 2500	2024038 2024043 2024046 2024070 2024098 2029950 2031000	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION	15.00 1,924.00 627.00 310.00 1,914.00 1.00	-15.00 1,182.30 0.00 40.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00	SQFT SQFT LF SQFT SQFT LS CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0
		0001 0001 0001 0001 0001 0001 0001	2440 2450 2460 2470 2480 2490 2500 2510	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00	SQFT SQFT LF SQFT SQFT CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00	SQFT SQFT LF SQFT SQFT LS CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD STA	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2500 2510 2520 2530 2540	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC. AMENDED SOILS	15.00 1,924.00 627.00 310.00 1,914.00 12,116.00 1,900.00 1,361.00 109.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 12,116.00 1,900.00 1,361.00 19.53	SQFT SQFT LF SQFT LS CUYD CUYD CUYD STA CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$4.50 \$8.50 \$500.00	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0 \$82,656.0
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2500 2510 2520 2530 2540 2550	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC. AMENDED SOILS MISC. SOFT SOIL REMEDIATION	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 1361.00 1090.00 2,020.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1,43 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 19.53 109.00 2,020.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00 1,312.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$4.50 \$8.50 \$500.00 \$115.00	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0 \$82,656.0 \$78,516.9
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2500 2510 2520 2530 2540 2550 2560	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 18.10 109.00 2,020.00 3,403.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 19.53 109.00 2,020.00 3,403.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00 1,312.00 2,379.30	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0 \$2,00 \$78,516.9 \$8,062.5
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2039907 2063000 2063300	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC AMENDED SOILS MISC SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 3 EXCAVATION	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,361.00 18.10 109.00 2,020.00 3,403.00 751.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 19.53 109.00 2,020.00 3,403.00 751.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00 1,312.00 2,379.30 375.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$33.00	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0 \$2,0 \$78,516.9 \$8,062.5 \$124,480.0
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2039907 2063000 2063300 2065500	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 4 EXCAVATION CLASS 4 EXCAVATION TEMPORARY SHORING	15.00 1,924.00 627.00 310.00 1,914.00 1.00 1.2,116.00 1,900.00 1.361.00 2,020.00 3,403.00 751.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00 1,312.00 2,379.30 375.00 0.50	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$4.50 \$500.00 \$115.00 \$63.00 \$33.00 \$21.50	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0 \$78,516.9 \$8,062.5 \$124,480.0 \$28,252.2
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2590	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2039907 2063000 2063300 2065500 3040504	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 4 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,361.00 18.10 109.00 2,020.00 3,403.00 751.00 1.00 8,428.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 1.00 8,428.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00 1,312.00 2,379.30 375.00 0.50 4,484.49	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$21.50 \$248,960.00	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0 \$78,516.9 \$8,062.5 \$124,480.0 \$28,252.2
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2590	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000 2063300 2065500 3040504	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION TLASS 3 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 18.10 109.00 2,020.00 3,403.00 751.00 1.00 8,428.00 4,095.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 1.00 8,428.00 4,095.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00 1,312.00 2,379.30 375.00 0.50 4,484.49 0.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$33.00 \$21.50 \$248,960.00 \$6.30 \$8.00	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0 \$20.0 \$78,516.9 \$8,062.5 \$124,480.0 \$28,252.2 \$0.0
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2590 2600	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000 2063300 2065500 3040504 3040905	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NON-FRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC. AMENDED SOILS MISC. SOFT SOIL REMEDIATION CLASS 3 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) MISC. ASTM NO. 2 AGGREGATE 12 IN. THICK	15.00 1,924.00 627.00 310.00 1,914.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 8,428.00 4,095.00 216.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 6,428.00 4,095.00 216.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD CUYD STA SQFT CUYD STA CUYD STA CUYD STA CUYD SQYD SQYD SQYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 0.00 0.00 1,312.00 2,379.30 375.00 0.50 4,484.49 0.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$21.50 \$248,960.00 \$6.30 \$8.00 \$17.75	\$0.0 \$13,357.0 \$7,524.0 \$6,825.0 \$14,259.3 \$175,000.0 \$40,584.0 \$1,742.4 \$0.0 \$0.0 \$20.0 \$78,516.9 \$8,062.5 \$124,480.0 \$28,252.2 \$0.0
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2600 2610 2620	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000 2063300 2065500 3040504 3049905	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NON-FRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 4 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) MISC.ASTM NO. 2 AGGREGATE 12 IN. THICK MISC.ASTM NO. 57 AGGREGATE 4 IN. THICK	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,361.00 18.10 109.00 2,020.00 3,403.00 751.00 4,095.00 216.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 3,106.30 627.00 350.00 1,914.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 4,095.00 216.00	SQFT SQFT LF SQFT LS CUYD CUYD STA CUYD CUYD CUYD STA SQYD SQYD SQYD SQYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00 1,312.00 2,379.30 375.00 0.50 4,484.49 0.00 0.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$21.50 \$248,960.00 \$6.30 \$8.00 \$17.75	\$0.00 \$13,357.00 \$7,524.01 \$6,825.01 \$14,259.31 \$175,000.01 \$40,584.01 \$1,742.41 \$0.00 \$0.00 \$78,516.90 \$8,062.51 \$124,480.01 \$28,252.21 \$0.00 \$0.00 \$0.00
		0001 0001 0001 0001 0001 0001 0001 000	2440 2450 2460 2470 2480 2490 2500 2510 2520 2530 2540 2550 2560 2570 2580 2600 2610 2620 2630	2024038 2024043 2024046 2024070 2024098 2029950 2031000 2035500 2036000 2037075 2039907 2063000 2063000 2065500 3040504 3040504 3040506 3049905	REMOVAL OF TRANSITE (CATEGORY II NON-FRIABLE) REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE) REMOVAL OF CAULKING/GLAZING COMPOUNDS (WINDOWS/DOORS) (CATEGORY II NONFRIABLE) REMOVAL OF FLOOR SHEETING ACM ON WOOD (FRIABLE) REMOVAL OF FLOOR TILE AND MASTIC ACM ON CONCRETE (CATEGORY I NON-FRIABLE) DEMOLITION AND REMOVAL OF BUILDINGS CLASS A EXCAVATION EMBANKMENT IN PLACE COMPACTING EMBANKMENT COMPACTING IN CUT MISC.AMENDED SOILS MISC.SOFT SOIL REMEDIATION CLASS 3 EXCAVATION CLASS 4 EXCAVATION TEMPORARY SHORING TYPE 5 AGGREGATE FOR BASE (4 IN. THICK) MISC.ASTM NO. 2 AGGREGATE 12 IN. THICK MISC.ASTM NO. 57 AGGREGATE 2 IN. THICK MISC.ASTM NO. 57 AGGREGATE 2 IN. THICK	15.00 1,924.00 627.00 310.00 1,914.00 1.00 12,116.00 1,900.00 13,361.00 2,020.00 3,403.00 751.00 1.00 8,428.00 4,095.00 216.00 216.00	-15.00 1,182.30 0.00 40.00 0.00 0.00 0.00 1.43 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 3,106.30 627.00 350.00 1,914.00 1.00 12,116.00 1,900.00 1,361.00 2,020.00 3,403.00 751.00 1.00 4,095.00 216.00 216.00	SQFT SQFT LF SQFT LS CUYD CUYD CUYD CUYD CUYD CUYD CUYD CUYD	0.00 3,106.30 627.00 350.00 1,914.00 1.00 2,136.00 387.20 0.00 0.00 1,312.00 2,379.30 375.00 0.50 4,484.49 0.00 0.00 0.00	\$50.00 \$4.30 \$12.00 \$19.50 \$7.45 \$175,000.00 \$19.00 \$4.50 \$8.50 \$500.00 \$115.00 \$63.00 \$21.50 \$248,960.00 \$6.30 \$8.00 \$17.75 \$7.00	\$750.00 \$0.00 \$13,357.09 \$7,524.00 \$6,825.00 \$14,259.30 \$175,000.00 \$40,584.00 \$1,742.40 \$0.00 \$82,656.00 \$78,516.90 \$28,252.29 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00

Revision 4/1/2020 Page 18 of 70



Total Paid / All Items / All Estimates (Including this Estimate)

lote: Posted Q	uantities a	nd Value	s are ba	sed on Re	port Generated date and can differ from the posted amou	int at the tir	me the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718B	0001	2670	4019905	MISC.OPTIONAL PAVEMENT	2,887.20	0.00	2,887.20	SQYD	0.00	\$59.00	\$0.00
		0001	2680	5021107	CONCRETE PAVEMENT (7 IN. NON-REINF)	1,645.00	0.00	1,645.00	SQYD	585.03	\$88.00	\$51,482.64
		0001	2690	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	1,054.60	0.00	1,054.60	SQYD	854.07	\$82.00	\$70,033.74
		0001	2700	5029903	MISC.12 IN. CONCRETE HEADER	987.00	0.00	987.00	LF	0.00	\$41.00	\$0.00
		0001	2710	5029907	MISC.CLASS B CONCRETE (CONCRETE ENCASEMENT)	5.00	0.00	5.00	CUYD	0.00	\$1,000.00	\$0.00
		0001	2720	6071102	MODIFIED CONCRETE GUTTER TYPE B	207.00	0.00	207.00	LF	0.00	\$35.00	\$0.00
		0001	2730	6079902	MISC.TEMPORARY DRIVE GATE	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0001	2740	6079903	MISC.18" DECORATIVE PEDESTRIAN FENCE (STRUCTURES)	278.00	0.00	278.00	LF	0.00	\$105.00	\$0.00
		0001	2750	6079903	MISC.48" DECORATIVE PEDESTRIAN FENCE (STRUCTURES)	684.00	0.00	684.00	LF	0.00	\$105.00	\$0.00
		0001	2760	6079903	MISC.72-INCH TEMPORARY CHAIN LINK FENCE	228.00	0.00	228.00	LF	228.00	\$18.00	\$4,104.00
		0001	2770	6081012	TRUNCATED DOMES	158.00	0.00	158.00	SQFT	240.20	\$18.00	\$4,323.60
		0001	2780	6083008	8 IN. CONCRETE MEDIAN STRIP	18.90	0.00	18.90	SQYD	0.00	\$95.00	\$0.00
		0001	2790	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	81.00	0.00	81.00	LF	0.00	\$130.00	\$0.00
		0001	2800	6085007	PAVED APPROACH, 7 IN.	473.80	0.00	473.80	SQYD	0.00	\$78.00	\$0.00
		0001	2810	6089901	MISC.THICKENED SIDEWALK SLAB OVER BOX CULVERT	1.00	0.00	1.00	LS	0.00	\$700.00	\$0.00
		0001	2820	6089902	MISC.7 IN. CONCRETE CURB RAMP (10 FT WIDE)	19.00	0.00	19.00	EA	13.00	\$2,500.00	\$32,500.00
		0001	2830	6089902	MISC.BANNER POLE	24.00	0.00	24.00	EA	0.00	\$7,450.00	\$0.00
		0001	2840	6089902	MISC.BENCH	2.00	0.00	2.00	EA	0.00	\$3,400.00	\$0.00
		0001	2850	6089902	MISC.STREET SIGN POLES. POWDERCOATED	18.00	0.00	18.00	EA	0.00	\$500.00	\$0.00
		0001	2860	6089902	MISC. WARNING AND REGULATORY SIGN POLES,	74.00	0.00	74.00	EA	0.00	\$500.00	\$0.00
		0001	2870	6089902	POWDERCOATED MISC.WASTE/RECYCLING RECEPTACLE	1.00	0.00	1.00	EA	0.00	\$3,500.00	\$0.00
		0001	2880	6089905	MISC.4 IN. CONCRETE SIDEWALK (10 FT WIDE)	4,870.60	0.00	4,870.60	SQYD	3,078.98	\$34.00	\$104,685.32
		0001	2890	6089905	MISC.4-3/4 INCH CONCRETE MEDIAN STRIP	16.20	0.00	16.20	SQYD	0.00	\$84.00	\$0.00
		0001	2900	6089905	MISC.ROGERS PARKWAY CONCRETE PAVERS	634.00	0.00	634.00	SQYD	0.00	\$148.50	\$0.00
		0001	2910	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	216.00	0.00	216.00	LF	37.80	\$30.00	\$1,134.00
			2920	6091052	CURB AND GUTTER TYPE B	542.00	0.00	542.00	LF	0.00	\$33.00	\$0.00
		0001	2930	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	570.00	0.00	570.00	LF	329.50	\$18.50	\$6,095.75
		0001							LF			
		0001	2940	6092012	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE B	1,017.00	0.00	1,017.00		261.50	\$19.00	\$4,968.50
		0001	2950 2960	6099903	MISC.MODIFIED CURB MISC.PERMEABLE INTERLOCKING CONCRETE PAVERS (3-1/8	500.00 216.00	0.00	500.00 216.00	LF	256.40	\$28.00 \$148.50	\$7,179.20 \$0.00
					IN. THICK)							
		0001	2970	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$150,000.00	\$0.00
		0001	2980	6173200	CONCRETE TRAFFIC BARRIER, TYPE E	183.00	0.00	183.00	LF	0.00	\$140.00	\$0.00
		0001	2990	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$500,000.00	\$250,000.00
		0001	3000	6206150A	4 IN. WHITE ACRYLIC COPOLYMER FAST DRY PAVEMENT MARKING PAINT	773.00	0.00	773.00	LF	0.00	\$5.00	\$0.00
		0001	3010	6206151A	4 IN. YELLOW ACRYLIC COPOLYMER FAST DRY PAVEMENT MARKING PAINT	27.00	0.00	27.00	LF	0.00	\$20.00	\$0.00
		0001	3020	6209902	MISC.ACCESSIBLE PARKING SYMBOL	1.00	0.00	1.00	EA	0.00	\$1,000.00	\$0.00
		0001	3030	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,611.00	0.00	1,611.00	SQYD	0.00	\$13.25	\$0.00
		0001	3040	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.15	\$75,000.00	\$11,250.00
		0001	3050	7032002	CLASS B CONCRETE (MISC)	65.40	27.40	92.80	CUYD	0.00	\$425.00	\$0.00
		0001	3060	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	51.10	0.00	51.10	CUYD	26.00	\$550.00	\$14,300.00
		0001	3070	7039902	MISC.PEDESTRIAN UNDERPASS CAST STONE MASONRY COLUMN	4.00	0.00	4.00	EA	0.00	\$3,642.00	\$0.00
		0001	3080	7039903	MISC.PEDESTRIAN UNDERPASS CAST STONE MASONRY COPING	36.00	0.00	36.00	LF	0.00	\$242.85	\$0.00
		0001	3090	7039904	MISC.PEDESTRIAN UNDERPASS CAST STONE MASONRY FACADE	196.00	0.00	196.00	SQFT	0.00	\$177.37	\$0.00
		0001	3100	7039904	MISC.PEDESTRIAN UNDERPASS INTERIOR PAINT	1,065.00	0.00	1,065.00	SQFT	0.00	\$8.70	\$0.00
		0001	3110	7039904	MISC.PEDESTRIAN UNDERPASS WALL PANEL	1,022.00	0.00	1,022.00	SQFT	0.00	\$75.45	\$0.00

Revision 4/1/2020 Page 19 of 70



Total Paid / All Items / All Estimates (Including this Estimate)

	uantities a	nd Value	s are ba	sed on Re	port Generated date and can differ from the posted amou	int at the tir	ne the Es	timate was	Generate	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718B	0001	3120	7039904	MISC.PEDESTRIAN UNDERPASS WAVE PANEL	330.00	0.00	330.00	SQFT	0.00	\$75.45	\$0.00
		0001	3130	7101000	REINFORCING STEEL (EPOXY COATED)	1,890.00	0.00	1,890.00	LB	945.00	\$3.00	\$2,835.00
		0001	3140	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$9,134.50	\$0.00
		0001	3150	7159902	MISC.VERTICAL DRAIN FOR THREE-SIDED STRUCTURE	1.00	0.00	1.00	EA	0.50	\$25,000.00	\$12,500.00
		0001	3160	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	1,036.00	0.00	1,036.00	SQFT	459.90	\$45.00	\$20,695.50
		0001	3170	7201200	SELECT GRANULAR BACKFILL FOR STRUCTURAL SYSTEMS	1,762.00	0.00	1,762.00	CUYD	880.82	\$38.00	\$33,471.16
		0001	3180	7209904	MISC.PRECAST CONCRETE MODULAR BLOCK WALL	4,532.00	0.00	4,532.00	SQFT	0.00	\$55.00	\$0.00
		0001	3190	7209904	MISC.SMALL BLOCK WALL	429.00	0.00	429.00	SQFT	0.00	\$36.00	\$0.00
		0001	3200	7339901	MISC.PRECAST CONCRETE STRUCTURE	1.00	0.00	1.00	LS	0.50	\$250,000.00	\$125,000.00
		0001	3210	7339901	MISC.WATERPROOFING MEMBRANE FOR THREE-SIDED STRUCTURE	1.00	0.00	1.00	LS	0.50	\$15,000.00	\$7,500.00
		0001	3220	8031000A	TURF TYPE TALL FESCUE SODDING	406.00	0.00	406.00	SQYD	0.00	\$8.45	\$0.00
		0001	3230	8039905A	MISC.SODDING	3,960.00	405.00	4,365.00	SQYD	0.00	\$8.45	\$0.00
		0001	3240	8041000	TOPSOIL	225.00	0.00	225.00	CUYD	0.00	\$45.00	\$0.00
		0001	3250	8049907A	MISC.PLANTING SOIL MIX	517.00	0.00	517.00	CUYD	0.00	\$50.00	\$0.00
		0001	3260	8051000A	SEEDING - COOL SEASON GRASSES	10.00	0.00	10.00	ACRE	0.00	\$5,000.00	\$0.00
		0001	3270	8069901	MISC.DEWATERING	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.00
		0001	3280	8080119	BLACK GUM	18.00	0.00	18.00	EA	0.00	\$575.00	\$0.00
		0001	3290	8089901	MISC.IRRIGATION SYSTEM	1.00	0.00	1.00	LS	0.00	\$13,860.00	\$0.00
		0001	3300	8089902	MISC.ANDORRA CREEPING JUNIPER	401.00	0.00	401.00	EA	0.00	\$57.00	\$0.00
		0001	3310	8089902	MISC.BALTIMORE ORIOLE DAYLILY	1,775.00	0.00	1,775.00	EA	0.00	\$31.00	\$0.00
		0001	3320	8089902	MISC.BLACK-EYED SUSAN	588.00	0.00	588.00	EA	0.00	\$21.00	\$0.00
		0001	3330	8089902	MISC.BLUE GRAMA 'BLOND AMBITION'	1,154.00	0.00	1,154.00	EA	0.00	\$42.00	\$0.00
		0001	3340	8089902	MISC.EASTERN REDBUD	13.00	0.00	13.00	EA	0.00	\$575.00	\$0.00
		0001	3350	8089902	MISC.FEATHER REED GRASS	63.00	0.00	63.00	EA	0.00	\$53.00	\$0.00
		0001	3360	8089902	MISC.GINKGO BILOBA	22.00	0.00	22.00	EA	0.00	\$650.00	\$0.00
		0001	3370	8089902	MISC.GREY OWL JUNIPER	116.00	0.00	116.00	EA	0.00	\$53.00	\$0.00
		0001	3380	8089902	MISC.GRO-LOW SUMAC	382.00	0.00	382.00	EA	0.00	\$53.00	\$0.00
		0001	3390	8089902	MISC.HEATH ASTER	521.00	0.00	521.00	EA	0.00	\$37.00	\$0.00
		0001	3400	8089902	MISC.JAPANESE ZELKOVA	19.00	0.00	19.00	EA	0.00	\$575.00	\$0.00
		0001	3410	8089902	MISC.KOUSA DOGWOOD	8.00	0.00	8.00	EA	0.00	\$575.00	\$0.00
		0001	3420	8089902	MISC.LITTLE BLUESTEM	890.00	0.00	890.00	EA	0.00	\$22.00	\$0.00
		0001	3430	8089902	MISC.NEW JERSEY TEA	103.00	0.00	103.00	EA	0.00	\$33.00	\$0.00
		0001	3440	8089902	MISC.PRAIRIE DROPSEED	382.00	0.00	382.00	EA	0.00	\$22.00	\$0.00
		0001	3450	8089902	MISC.RIVER BIRCH	6.00	0.00	6.00	EA	0.00	\$575.00	\$0.00
		0001	3460	8089902	MISC.SILVER LINDEN	3.00	0.00	3.00	EA	0.00	\$600.00	\$0.00
		0001	3470	8089902	MISC.THREADLEAF COREOPSIS	626.00	0.00	626.00	EA	0.00	\$23.00	\$0.00
		0001	3480	8089902	MISC.WOODLAND PHLOX	1,588.00	0.00	1,588.00	EA	0.00	\$24.00	\$0.00
		0001	3490	8089902	MISC.YELLOW TWIG DOGWOOD	123.00	0.00	123.00	EA	0.00	\$55.00	\$0.00
		0001	3500	8089903	MISC.LANDSCAPE EDGING	147.00	0.00	147.00	LF	0.00	\$40.00	\$0.00
		0001	3510	9039904	MISC.BLACK VINYL SIGN WRAP	519.00	0.00	519.00	SQFT	0.00	\$6.00	\$0.00
		0010	3520	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	50.00	0.00	50.00	LF	0.00	\$33.00	\$0.00
		0010	3530	6062204A	BRIDGE ANCHOR SECTION, 6.5 FT. POSTS (SAFETY BARRIER CURB) (NEW CONSTRUCTION ONLY)	1.00	0.00	1.00	EA	0.00	\$3,000.00	\$0.00
		0010	3540	6062300A	TRANSITION SECTION, 6.5 FT. POSTS	1.00	0.00	1.00	EA	0.00	\$400.00	\$0.00
		0010	3550	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	0.00	\$2,800.00	\$0.00
		0020	3560	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	6.00	0.00	6.00	EA	0.00	\$5,800.00	\$0.00

Revision 4/1/2020 Page 20 of 70



Total Paid / All Items / All Estimates (Including this Estimate)

Contract lm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
0521-F01	J6S1718B	0020	3580	9014004	CONDUIT, 4 IN. RIGID, PUSHED	1,283.00	0.00	1,283.00	LF	618.00	\$26.50	\$16,377.0
		0020	3590	9015010	TRENCHING TYPE I	9,570.00	0.00	9,570.00	LF	5,342.00	\$4.50	\$24,039.0
		0020	3600	9016110	PULL BOX, PREFORMED CLASS 1	32.00	0.00	32.00	EA	3.00	\$980.00	\$2,940.0
		0020	3610	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	13,160.00	0.00	13,160.00	LF	566.00	\$3.15	\$1,782.9
		0020	3620	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	6.00	0.00	6.00	EA	0.00	\$6,400.00	\$0.
		0020	3630	9019902	MISC.F1-LED TWIN FIXTURE AND POLE ASSEMBLY AT UNDERPASS	4.00	0.00	4.00	EA	0.00	\$3,084.00	\$0.
		0020	3640	9019902	MISC.F-2 LED UNDERPASS UP/DOWN FIXTURE, 4 FOOT LENGTH	4.00	0.00	4.00	EA	0.00	\$1,227.00	\$0.
		0020	3650	9019902	MISC.F2-LED UNDERPASS UP/DOWN FIXTURE, 8 FOOT LENGTH	18.00	0.00	18.00	EA	0.00	\$1,596.00	\$0.
		0020	3660	9019902	MISC.ORNAMENTAL LIGHT POLE AND LUMINAIRE - BRENTWOOD STREETSCAPE	92.00	0.00	92.00	EA	0.00	\$4,300.00	\$0.
		0030	3670	9029902	MISC.BLACK POWDER COATED MAST ARM AND SIGNAL POST	4.00	0.00	4.00	EA	0.00	\$1,200.00	\$0.
		0030	3680	9029902	MISC.BLACK POWDER COATED PEDESTRIAN POST	2.00	0.00	2.00	EA	0.00	\$256.00	\$0
		0030	3690	9029902	MISC.DETECTOR, PEDESTRIAN PUSH BUTTON, APS	8.00	0.00	8.00	EA	0.00	\$908.00	\$0
					FREEZEPROOF							
		0030	3700	9029902	MISC.ILLUMINATED STREET SIGN	4.00	0.00	4.00	EA	0.00	\$2,144.00	\$0.
		0030	3710	9029902	MISC.POST, SIGNAL W/SQ PEDESTAL BASE AND POST CAP, 10' TOTAL HEIGHT, ALUMINUM	5.00	0.00	5.00	EA	0.00	\$549.00	\$0.
		0030	3720	9029902	MISC.PREFORMED PULL BOX - 17 IN. W X 30 IN. L X 26 IN. MIN. H - REINFROCED POLYMER CONCRETE	7.00	0.00	7.00	EA	0.00	\$995.00	\$0
		0030	3730	9029903	MISC.CABLE, DETECTOR LOOP, #14 GAUGE, 1 CONDUCTOR W/TUBE JACKET (IN SAWED SLOT)	3,590.00	0.00	3,590.00	LF	0.00	\$4.60	\$0
		0030	3735	9029903	MISC.CABLE, PUSH BUTTON AND/OR DETECTOR LOOP LEAD- IN, 18 GAUGE, 2 CONDUCTOR (SHIELDED)	5,860.00	0.00	5,860.00	LF	0.00	\$1.10	\$0
		0030	3740	9029903	MISC.CABLE, DETECTOR LOOP, #14 GAUGE, 1 CONDUCTOR, WITUBE JACKET (IN CONDUIT AND PULL BOXES)	210.00	0.00	210.00	LF	0.00	\$0.50	\$0
		0030	3750	9029907	MISC.BASE, TYPE C-3, CONCRETE	1.40	0.00	1.40	CUYD	0.00	\$2,600.00	\$0
		0030	3760	9039904	MISC.BLACK VINYL SIGN WRAP, SIGNAL SIGNS	110.00	0.00	110.00	SQFT	0.00	\$3.25	\$0
		0050	3770	6039921	SEWER	1.00	0.00	1.00	LS	0.50	\$72,500.00	\$36,250
		0050	3780	6039921	SEWER	1.00	0.00	1.00	LS	0.25	\$7,500.00	\$1,875
		0050	3790	6039922	SEWER	6.00	0.00	6.00	EA	6.00	\$5,869.00	\$35,214
		0050	3800	6039922	SEWER	2.00	0.00	2.00	EA	2.00	\$7,328.00	\$14,656
		0050	3810	6039922	SEWER	5.00	0.00	5.00	EA	0.00	\$340.00	\$0
		0050	3820	6039922	SEWER	5.00	0.00	5.00	EA	0.00	\$283.00	\$0
		0050	3830	6039923	SEWER	335.00	0.00	335.00	LF	0.00	\$50.00	\$0
		0050	3840	6039923	SEWER	257.00	0.00	257.00	LF	257.00	\$827.00	\$212,539
		0050	3850	6039923	SEWER	120.00	0.00	120.00	LF	119.60	\$1,057.00	\$126,417
		0050	3860	6039923	SEWER	41.00	0.00	41.00	LF	41.00	\$188.00	\$7,708
		0050	3870	6039923	SEWER	424.00	0.00	424.00	LF	385.06	\$432.00	\$166,345
		0050	3880	6039924	SEWER	544.00	0.00	544.00	CUYD	543.63	\$381.00	\$207,123
		0050	3890	6039924	SEWER	210.00	0.00	210.00	CUYD	210.00	\$118.00	\$24,780
		0050	3900	6039924	SEWER	2,330.00	0.00	2,330.00	CUYD	2,329.70	\$50.00	\$116,485
		0050	3910	6039924	SEWER	2,394.00	0.00	2,394.00	CUYD	1,796.67	\$112.00	\$201,227
		0050	3920	6039925	SEWER	444.00	0.00	444.00	SQYD	0.00	\$5.00	\$1
		0050	3930	6039925	SEWER	53.00	0.00	53.00	SQYD	0.00	\$200.00	\$0
		0050	3940	6039925	SEWER	323.00	0.00	323.00	SQYD	0.00	\$150.00	\$0
		0055	3950	6049902	MISC.OBSERVATION WELL	2.00	0.00	2.00	EA	0.00	\$1,000.00	\$0
		0055	3960	6059903	MISC.4" RIGID SCHEDULE 40 PVC	57.00	0.00	57.00	LF	0.00	\$40.00	\$0
		0055	3970	6059903	MISC.PERFORATED UNDERDRAIN 4" RIGID SCHEDULE 40 PVC	54.00	0.00	54.00	LF	0.00	\$60.00	\$(
		0055	3980	6249905	MISC.MSD TYPE 4 FILTER FABRIC	281.00	0.00	281.00	SQYD	0.00	\$6.00	\$(
		0055	3990	7250312A		219.00	0.00	219.00	LF	146.90	\$122.00	\$17,92
					18 IN. PIPE GROUP B	72.00			LF			\$17,321
		0055	4000	12503 TOA	TO INC. I II E GROOF B	12.00	0.00	72.00	LF	0.00	\$115.00	\$

Revision 4/1/2020 Page 21 of 70



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ntract NTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amou Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
F01	J6S1718B	0055	4010	7250324A	24 IN. PIPE GROUP B	79.00	0.00	79.00	LF	0.00	\$134.00	\$0.00
		0055	4020	7250348A	48 IN. PIPE GROUP B	486.00	0.00	486.00	LF	486.00	\$208.00	\$101,088.00
		0055	4030	7259903	MISC.10 IN. C-900 PIPE	114.00	0.00	114.00	LF	0.00	\$176.00	\$0.00
		0055	4040	7259903	MISC.12 IN. PIPE GROUP B - PVC	32.00	0.00	32.00	LF	0.00	\$125.00	\$0.00
		0055	4050	7259903	MISC.6 IN. PIPE GROUP B - PVC	20.00	0.00	20.00	LF	20.00	\$92.00	\$1,840.00
		0055	4060	7259903	MISC.8 IN. C-900 PIPE	8.00	0.00	8.00	LF	0.00	\$134.00	\$0.00
		0055	4070	7261012	12 IN. PIPE GROUP A	136.00	0.00	136.00	LF	0.00	\$60.00	\$0.00
		0055	4080	7261018	18 IN. PIPE GROUP A	38.00	0.00	38.00	LF	0.00	\$99.00	\$0.00
		0055	4090	7261048	48 IN. PIPE GROUP A	120.00	0.00	120.00	LF	41.60	\$315.00	\$13,104.00
		0055	4100	7269923	SEWER	341.00	0.00	341.00	LF	161.60	\$112.00	\$18,099.20
		0055	4110	7269923	SEWER	26.00	0.00	26.00	LF	26.00	\$130.00	\$3,380.00
		0055	4120	7269923	SEWER	192.00	0.00	192.00	LF	0.00	\$117.00	\$0.00
		0055	4130	7269923	SEWER	40.00	0.00	40.00	LF	24.50	\$171.00	\$4,189.50
		0055	4140	7269923	SEWER	109.00	0.00	109.00	LF	109.00	\$274.00	\$29,866.00
		0055	4150	7269923	SEWER	115.00	0.00	115.00	LF	115.00	\$286.00	\$32,890.00
		0055	4160	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	60.00	0.00	60.00	FT	24.20	\$689.00	\$16,673.80
		0055	4170	7310060	PRECAST CONCRETE MANHOLE - 60 IN.	8.00	0.00	8.00	FT	0.00	\$829.00	\$0.00
		0055	4180	7319902	MISC.12 IN. DRAIN BASIN WITH PEDESTRIAN GRATE	4.00	0.00	4.00	EA	2.00	\$4,120.00	\$8,240.00
		0055	4190	7319902	MISC.42 IN. AREA INLET	3.00	0.00	3.00	EA	2.00	\$3,590.00	\$7,180.00
		0055	4200	7319902	MISC.42 IN. CURB INLET	3.00	0.00	3.00	EA	2.00	\$3,447.00	\$6,894.00
		0055	4210	7319902	MISC.42 IN. GRATE INLET WITH SIDE INTAKE	1.00	0.00	1.00	EA	0.00	\$5,025.00	\$0.00
		0055	4220	7319902	MISC.48" HYDRODYNAMIC SEPARATOR	1.00	0.00	1.00	EA	1.00	\$46,106.00	\$46,106.00
		0055	4230	7319902	MISC.48" MANHOLE WITH EXTERNAL FOULWATER DROP	1.00	0.00	1.00	EA	1.00	\$9,874.00	\$9,874.00
			4240	7319902	MISC.72 IN. MANHOLE WITH 42 IN. REDUCER	7.00	0.00	7.00	EA	7.00	\$11,498.00	\$80,486.00
		0055	4250	7319902	MISC.96 IN. MANHOLE WITH 42 IN. REDUCER	3.00	0.00	3.00	EA	2.00	\$12,749.00	\$25,498.00
		0055	4260									
		0055		7319902	MISC CANITARY 40 IN MANUALE	5.00	0.00	5.00	EA	0.00	\$5,035.00	\$0.00
		0055	4270	7319903	MISC.SANITARY 48 IN. MANHOLE	9.00	0.00	9.00	LF	0.00	\$521.00	\$0.00
		0060	4280	6039902	WATER	1.00	0.00	1.00	EA	0.00	\$100.00	\$0.00
		0060	4290	6039923	SEWER	114.00	0.00	114.00	LF	0.00	\$179.00	\$0.00
		0060	4300	6039923	SEWER	8.00	0.00	8.00	LF	0.00	\$134.00	\$0.00
		0060	4310	6039924	SEWER	5.00	0.00	5.00	CUYD	0.00	\$372.00	\$0.00
		0060	4320	6039932	GAS	2.00	0.00	2.00	EA	0.00	\$100.00	\$0.00
		0060	4330	6042010	ADJUSTING MANHOLE	5.00	0.00	5.00	EA	0.00	\$250.00	\$0.00
		0001	5101	2029901	MISC.Removal of Transite (Category II Non-Friable)	0.00	1.00	1.00	LS	1.00	\$4,168.50	\$4,168.50
		0001	5102	2024018	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	0.00	50.00	50.00	LF	0.00	\$52.50	\$0.00
		0050	5103	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$6,109.63	\$6,109.63
		0001	5104	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$4,463.92	\$4,463.92
		0001	5105	2029901	MISC.Additional Removal OF Improvements For Rogers Parkway	0.00	1.00	1.00	LS	0.00	\$7,638.44	\$0.00
		0020	5106	9019901	MISC.Receptacles on Ornamental Lighting (City of Brentwood)	0.00	1.00	1.00	LS	0.00	\$75,337.50	\$0.00
					ate as of Report Generated Date							\$3,069,844.88
	J6S1718C	0001	4340	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.20	\$50,000.00	\$10,000.00
		0001	4350	2071000	LINEAR GRADING CLASS 1	4.60	-4.60	0.00	STA	0.00	\$900.00	\$0.00
		0001	4360	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,249.00	0.00	1,249.00	SQYD	0.00	\$6.30	\$0.00
		0001	4370	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	37.90	0.00	37.90	TONS	12.80	\$124.50	\$1,593.60
		0001	4380	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	92.70	0.00	92.70	TONS	29.50	\$139.00	\$4,100.50
		0001	4390	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	64.30	0.00	64.30	TONS	0.00	\$87.00	\$0.00
		0001	4400	4030208	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP190C MIX)	37.50	0.00	37.50	TONS	0.00	\$80.00	\$0.00

Revision 4/1/2020 Page 22 of 70



Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
0521-F01	J6S1718C	0001	4410	4071005	TACK COAT	175.00	0.00	175.00	GAL	10.00	\$2.50	\$25.0
		0001	4420	5021107	CONCRETE PAVEMENT (7 IN. NON-REINF)	360.00	0.00	360.00	SQYD	0.00	\$88.00	\$0.0
		0001	4430	6071102	MODIFIED CONCRETE GUTTER TYPE B	79.00	0.00	79.00	LF	0.00	\$35.00	\$0.0
		0001	4440	6079903	MISC.48" DECORATIVE PEDESTRIAN FENCE (STRUCTURES)	336.00	0.00	336.00	LF	0.00	\$105.00	\$0.
		0001	4450	6079903	MISC.72-INCH TEMPORARY CHAIN LINK FENCE	1,159.00	0.00	1,159.00	LF	1,159.00	\$18.00	\$20,862.
		0001	4460	6079903	MISC.GREEN POWDER COATED CHAIN LINK FENCE (48 IN.)	1,159.00	0.00	1,159.00	LF	0.00	\$30.00	\$0.
		0001	4470	6084023	SIDEWALK HAND-RAILING WITHOUT BALUSTERS	403.00	0.00	403.00	LF	0.00	\$130.00	\$0.
		0001	4480	6085007	PAVED APPROACH, 7 IN.	179.30	0.00	179.30	SQYD	0.00	\$76.00	\$0.
		0001	4490	6086004	CONCRETE SIDEWALK, 4 IN.	257.00	0.00	257.00	SQYD	0.00	\$50.00	\$0.
		0001	4500	6089905	MISC.DECORATIVE CONCRETE PAVING	213.30	0.00	213.30	SQYD	0.00	\$150.00	\$0.
		0001	4510	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	120.00	0.00	120.00	LF	0.00	\$30.00	\$0.
		0001	4520	6091052	CURB AND GUTTER TYPE B	157.00	0.00	157.00	LF	0.00	\$33.00	\$0
		0001	4530	6099903	MISC.MODIFIED CONCRETE CURB TYPE A	11.00	0.00	11.00	LF	0.00	\$26.00	\$0.
		0001	4540	6099903	MISC.MODIFIED CURB	191.00	0.00	191.00	LF	0.00	\$28.00	\$0
		0001	4550	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.00	\$50,000.00	\$0
		0001	4560	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.50	\$50,000.00	\$25,000
		0001	4570	6209902	MISC.BIKE LANE ARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING	7.00	0.00	7.00	EA	0.00	\$250.00	\$0
		0001	4580	6209902	MISC.BIKE LANE BIKE PREFORMED THERMOPLASTIC PAVEMENT MARKING	7.00	0.00	7.00	EA	0.00	\$250.00	\$0
		0001	4590	6209902	MISC.SHARED USE SHARROW PREFORMED THERMOPLASTIC PAVEMENT MARKING	2.00	0.00	2.00	EA	0.00	\$250.00	\$0
		0001	4600	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	304.00	0.00	304.00	SQYD	0.00	\$3.45	\$0
		0001	4610	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.10	\$25,000.00	\$2,50
		0001	4620	7011103	DRILLED SHAFTS (2 FT. 6 IN. DIA.)	11.00	0.00	11.00	LF	0.00	\$200.00	\$
		0001	4630	7034214	CLASS B-2 CONCRETE	0.70	0.00	0.70	CUYD	0.00	\$1,700.00	\$1
		0001	4640	7061000	REINFORCING STEEL	450.00	0.00	450.00	LB	0.00	\$5.00	\$1
		0001	4650	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	1,397.00	0.00	1,397.00	SQFT	0.00	\$45.00	\$
		0001	4670	7209904	MISC.SMALL BLOCK WALL	1,606.00	0.00	1,606.00	SQFT	0.00	\$36.00	\$1
		0001	4680	8080504	RED OSIER DOGWOOD	24.00	0.00	24.00	EA	0.00	\$33.00	\$
		0001	4690	8089901	MISC.VERTICAL GATEWAY MONUMENT	1.00	0.00	1.00	LS	0.00	\$21,645.00	\$1
		0001	4700	8089902	MISC.CRIMSON PYGMY BARBERRY	63.00	0.00	63.00	EA	0.00	\$66.00	\$1
		0001	4710	8089902	MISC.DWARF WINGED BURNING BUSH	10.00	0.00	10.00	EA	0.00	\$77.00	\$1
		0001	4720	8089902	MISC.ELIJAH BLUE FESCUE	21.00	0.00	21.00	EA	0.00	\$53.00	\$1
		0001	4730	8089902	MISC.SHAMROCK INKBERRY	20.00	0.00	20.00	EA	0.00	\$77.00	\$1
		0001	4740	8089902	MISC.SPARTAN JUNIPER	21.00	0.00	21.00	EA	0.00	\$72.00	\$0
		0001	4750	8089902	MISC.WINTERGREEN BOXWOOD	30.00	0.00	30.00	EA	0.00	\$77.00	\$0
		0020	4760	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	3.00	0.00	3.00	EA	0.00	\$4,537.00	\$1
		0020	4770	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	20.00	0.00	20.00	LF	6.00	\$16.00	\$90
		0020	4780	9014004	CONDUIT, 4 IN. RIGID, PUSHED	865.00	0.00	865.00	LF	200.00	\$26.50	\$5,300
		0020	4790	9015010	TRENCHING TYPE I	8,527.00	0.00	8,527.00	LF	3,055.00	\$4.50	\$13,74
		0020	4800	9016110	PULL BOX, PREFORMED CLASS 1	15.00	0.00	15.00	EA	6.00	\$980.00	\$5,88
		0020	4810	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	11,160.00	0.00	11,160.00	LF	3,744.00	\$3.15	\$11,79
		0020	4820	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	3.00	0.00	3.00	EA	0.00	\$3,000.00	\$
		0020	4830	9019902	MISC.ORNAMENTAL LIGHT POLE AND LUMINAIRE - KIRKWOOD STREETSCAPING	94.00	0.00	94.00	EA	23.00	\$3,863.00	\$88,84
		0020	4840	9019902	MISC.REMOVE AND RELOCATE PRIVATELY-OWNED LIGHT POLE	9.00	0.00	9.00	EA	0.00	\$1,500.00	\$
		0060	4850	6039932	GAS	1.00	0.00	1.00	EA	0.00	\$100.00	\$1
		0020	5201	9019901	MISC.Receptacles on Ornamental Lighting (City of Kirkwood)	0.00	1.00	1.00	LS	0.00	\$133,970.55	\$1

Revision 4/1/2020 Page 23 of 70



Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and	nd Values are based on Report Gene	erated date and can differ from the posted amount at the time the Estimate was Generated.

Note: 1 obtou &	aannaa a		J GIO DG	ood on ito	port contrated date and earl affer from the posted affect	int at the th		timate was	Contorat	ou.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-F01	J6S1718C	0001	5202	2079909	MISC.Modified Linear Grading, Class 2	0.00	4.60	4.60	STA	0.00	\$1,600.00	\$0.00
	Project J65	61718C - To	tal Value	Posted to D	ate as of Report Generated Date							\$189,747.20
210521-F01 Ove	rall - Total V	alue Poste	d to Date	as of Repor	t Generated Date							\$9,412,027.08

Revision 4/1/2020 Page 24 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6S1718

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0070	3040504	TYPE 5 AGGREGATE FOR BASE	8/3/22	8/12/22	3.10	SQYD	Kamp K9-Pavement in front of inlet	4+93.50	LT	5+08.39	LT	
				8/12/22	7.60	SQYD	Curb and Gutter at Sunnen	25+31.50			LT	
				8/12/22	12.30	SQYD	Sidewalk at Sunnan	25+31.50	LT	25+51.20	LT	
				8/12/22	17.10	SQYD	Kamp K9 Sidewalk behind inlet.	4+93.50	LT	5+15.10	LT	
				8/12/22	98.90	SQYD	Ace Hardware Approach Entrance - West Half	71+93.50				
			8/9/22	8/12/22	7.50		Bartold Grated Inlet Pavement.	22+64.55		22+74.38		
				8/12/22		SQYD	Northeast Hanely/Manchester Sidewalk.	29+95.24		30+21.87		
0130	5021107	CONCRETE PAVEMENT (7 IN. NON-REINF)		8/12/22		SQYD	Kamp K9	4+93.50		5+08.39		
0.400		TOURISHTED DOLLES	8/9/22	8/12/22	7.50	SQYD	Bartold Grated Inlet Pavement.	22+65.55		22+74.38	LT	
0180	6081012	TRUNCATED DOMES	8/2/22	8/12/22	12.00	SQFT	Redo at Metro Link because of bicycle tracks and foot prints.	24+00	LT			
			8/5/22	8/12/22	54.00	SQFT	Brentwood Intersection Island	77+71.41	LT	77+94.98	LT	
			8/9/22	8/12/22	12.00	SQFT	Northeast Hanley/Manchester Curb Ramp 5	29+95.24	RT	30+21.87	RT	
				8/12/22	20.00	SQFT	Society of the Blind curb ramp 36	74+35.50	LT	76+53.87	LT	
				8/12/22	22.20	SQFT	Society of the Blind curb ramp 37	110+45.89	LT	110+79.44	LT	
				8/12/22	32.00	SQFT	Northeast Hanley/Manchester Quadrant Median Island.	30+33.69	LT	30+47.62	LT	
0210	6085007	PAVED APPROACH, 7 IN.	8/5/22	8/12/22	52.55	SQYD	Ace Hardware Approach Entrance - West Half	71+93.50				
0220	6086004	CONCRETE SIDEWALK, 4 IN.	8/2/22	8/12/22	38.88	SQYD	Redo at Metro Link because of bicycle tracks and foot prints.	22+50	LT	24+15	LT	
			8/3/22	8/12/22	12 30	SQYD	'	25+31.50	LT	25+51.20	LT	
			GOILL	8/12/22		SQYD	Kamp K9	4+93.50		5+15.10		
			8/9/22	8/12/22	27.70	SQYD	Northeast Hanley/Manchester Sidewalk.	29+95.24		30+21.87		
0250	6089902	MISC. CONCRETE		8/12/22	1.00		Redo at Metro Link because of bicycle tracks and foot	24+00				
							prints.					
			8/9/22	8/12/22	1.00		Northeast Hanley/Manchester Curb Ramp 5	29+95.24		30+21.87		
0260	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	8/3/22	8/12/22	23.70	LF	1 1	4+93.50		5+15.10	LT	
			8/5/22	8/12/22	13.90	LF	McKinleys curb - East Side	169+48.03				
				8/12/22	27.00		Ace Hardware Approach Entrance - West Half	71+93.50				
				8/12/22	116.70	LF	Society of the Blind S Curb.	74+45.62 1+70.64		76+42.48		
			8/10/22		7.75		Martin Drive S Curb.			1+77.40		
				8/16/22	8.00	LF		74+45.62		76+42.48		
				8/16/22	10.75		Bartold Grated Inlet.	22+65.55		22+74.38		
0.070	0004050	OURD AND OUTTER THE D	010100	8/16/22	65.00		Society of the blind.	110+33.39		110+78.61		
0270	6091052			8/12/22	22.70		Curb & Gutter by Sunnen Approach.	25+31.50		25+51.20	LI	
0740 0750	8061007A 8061016		8/9/22 8/2/22	8/12/22 8/12/22	1.00	CUYD	Area Inlet 1-11 Inlets around Dorothy & Manchester	65+95.91 1+45		281+06	DT/IT	
0840	9014004	CONDUIT, 4 IN. RIGID, PUSHED	8/11/22	8/16/22	55.00		E1 to E2	54+71.90			RT RT	
0040	3014004	CONDOTT, 4 IN. NIGIB, I COLLED	0/11/22	8/16/22	58.00		F1-F2	43+70.46		43+71.56		
				8/16/22	68.00		G1 to G2	23+97.37		29+02.10		
1440	2063000	CLASS 3 EXCAVATION	8/2/22	8/12/22	20.00		Pipe ID: DI-301B	132+83.04		20.02.10		
			0,0,0	8/12/22	115.00	CUYD	Structure Run: DI-301B to DI-301A		RT		RT	
							Pipe ID: SS-301B					
			8/3/22	8/12/22	80.00	CUYD	Structure Run: MH-301C to DI-301B Pipe ID: SS-301C-1		RT		RT	
			8/5/22	8/12/22	9.00	CUYD	Pipe ID: MH-301C	131+38.87	IT			
			GOILL	8/12/22	14.16		Structure Run: DI-301C to MH-301C	101100.01	LT		LT	
							Pipe ID: SS-301C-2					
				8/12/22	58.00	CUYD	Structure Run: MH-301C to DI-301B Pipe ID: SS-301C-1		RT		RT	
			8/8/22	8/12/22	9.84	CUYD	Structure Run: DI-301C to MH-301C		LT		LT	
			0.0.				Pipe ID: SS-301C-2					
				8/12/22	18.00	CUYD	Pipe ID: DI-301C	131+05.82	LT		LT	
				8/12/22	77.49	CUYD	Structure Run: DI-301D to DI-301C Pipe ID: SS-301D		LT		LT	
			8/9/22	8/12/22	68 04	CUYD	Structure Run: DI-301D to DI-301C		LT		LT	
			5,5122		55.04	2010	Pipe ID: SS-301D					
			8/10/22	8/16/22	53.30	CUYD	East of Raritan	144+81.18	LT			
1490	7250318A	18 IN. PIPE CULVERT GROUP B	8/2/22	8/12/22	116.00	LF	Structure Run: DI-301B to DI-301A Pipe ID: SS-301B		RT		RT	
			8/3/22	8/12/22	80.00	LF	Structure Run: MH-301C to DI-301B		RT		RT	
			370722		50.00		Pipe ID: SS-301C-1					
			8/5/22	8/12/22	16.50	LF	Structure Run: DI-301C to MH-301C Pipe ID: SS-301C-2		LT		LT	
				8/12/22	50.00	10	Structure Run: MH-301C to DI-301B		LT		LT	
				JI 12/22	30.00	Lr	Pipe ID: SS-301C-1		-1		-1	
			8/8/22	8/12/22	11.50	LF	Structure Run: DI-301C to MH-301C		LT		LT	
				8/12/22	80.50	10	Pipe ID: SS-301C-2 Structure Run: DI-301D to DI-301C		LT		LT	
				0112122	00.00	LF	Pipe ID: SS-301D		-1		-1	
				0/12/22	72.00	LF	Structure Run: DI-301D to DI-301C		LT		LT	
			8/9/22	0/12/22			Pipe ID: SS-301D	121.00.07	LT			
4750	7040000	MISC MANIFOLES AND DOOD IN 570			F 00			131+38.87	L.I			
1750		MISC. MANHOLES AND DROP INLETS	8/5/22	8/12/22	5.00		South Bremerton	400 -00 0	DT			
1750 1810		MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS	8/5/22 8/2/22	8/12/22 8/12/22	6.00	LF	Pipe ID: DI-301B	132+83.04				
1810	7319903	MISC. MANHOLES AND DROP INLETS	8/5/22 8/2/22 8/8/22	8/12/22 8/12/22 8/12/22	6.00	LF LF	Pipe ID: DI-301B Pipe ID: DI-301C	131+05.82	LT			
	7319903		8/5/22 8/2/22 8/8/22	8/12/22 8/12/22 8/12/22 8/16/22	6.00 6.00 7.00	LF LF	Pipe ID: DI-301B Pipe ID: DI-301C East of Raritan	131+05.82 144+81.18	LT LT			
1810 1830	7319903 7319903	MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS	8/5/22 8/2/22 8/8/22 8/10/22	8/12/22 8/12/22 8/12/22 8/16/22 8/16/22	6.00 6.00 7.00 8.00	LF LF LF	Pipe ID: DI-301B Pipe ID: DI-301C East of Raritan East of Raritan	131+05.82	LT LT LT		LT/DT	
1810 1830 1910	7319903 7319903 9029902	MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS MISC.	8/5/22 8/2/22 8/8/22 8/10/22 8/11/22	8/12/22 8/12/22 8/12/22 8/16/22 8/16/22 8/16/22	6.00 6.00 7.00 8.00 2.00	LF LF LF LF	Pipe ID: DI-301B Pipe ID: DI-301C East of Raritan East of Raritan Post # 2/5	131+05.82 144+81.18	LT LT LT LT/RT		LT/RT	
1810 1830 1910 1920	7319903 7319903 9029902 9029902	MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS MISC. MISC.	8/5/22 8/2/22 8/8/22 8/10/22 8/11/22 8/11/22	8/12/22 8/12/22 8/12/22 8/16/22 8/16/22 8/16/22 8/16/22	6.00 6.00 7.00 8.00 2.00 1.00	LF LF LF EA	Pipe ID: DI-301B Pipe ID: DI-301C East of Raritan East of Raritan Post # 2/5 Post # 2 NW Corner	131+05.82 144+81.18	LT LT LT LT/RT		RT	
1810 1830 1910 1920 1930	7319903 7319903 9029902 9029902 9029902	MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS MISC. MISC. MISC.	8/5/22 8/2/22 8/8/22 8/10/22 8/11/22 8/11/22	8/12/22 8/12/22 8/12/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22	6.00 6.00 7.00 8.00 2.00 1.00 3.00	LF LF LF EA EA	Pipe ID: DI-301B Pipe ID: DI-301C East of Raritan East of Raritan Post # 2/5 Post # 2 NW Corner Route 100 at Hanley	131+05.82 144+81.18	LT LT LT LT/RT RT LT/RT		RT LT/RT	
1810 1830 1910 1920 1930 1950	7319903 7319903 9029902 9029902 9029902 9029902	MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS MISC. MISC. MISC. MISC.	8/5/22 8/2/22 8/8/22 8/10/22 8/11/22 8/11/22 8/11/22 8/11/22	8/12/22 8/12/22 8/12/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22	6.00 6.00 7.00 8.00 2.00 1.00 3.00	LF LF LF EA EA	Pipe ID: DI-301B Pipe ID: DI-301C East of Raritan East of Raritan Post # 2/5 Post # 2 NW Corner Route 100 at Hanley Route 100 at Hanley	131+05.82 144+81.18	LT LT LT LT/RT RT LT/RT RT		RT LT/RT RT	
1810 1830 1910 1920 1930 1950 1990	7319903 7319903 9029902 9029902 9029902 9029902	MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS MISC. MISC. MISC. MISC. MISC. MISC.	8/5/22 8/2/22 8/8/22 8/10/22 8/11/22 8/11/22 8/11/22 8/11/22 8/11/22	8/12/22 8/12/22 8/12/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22	6.00 7.00 8.00 2.00 1.00 3.00 1.00	LF LF LF EA EA EA	Pipe ID: DI-301B Pipe ID: DI-301C East of Raritan East of Raritan Post # 2/5 Post # 2 NW Corner Route 100 at Hanley Route 100 at Hanley NW Corner Route 100 at Hanley	131+05.82 144+81.18	LT LT LT LT/RT RT LT/RT RT RT RT		RT LT/RT RT RT	
1810 1830 1910 1920 1930 1950	7319903 7319903 9029902 9029902 9029902 9029902	MISC. MANHOLES AND DROP INLETS MISC. MANHOLES AND DROP INLETS MISC. MISC. MISC. MISC. MISC. MISC. MISC.	8/5/22 8/2/22 8/8/22 8/10/22 8/11/22 8/11/22 8/11/22 8/11/22	8/12/22 8/12/22 8/12/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22 8/16/22	6.00 6.00 7.00 8.00 2.00 1.00 3.00	LF LF LF EA EA EA EA	Pipe ID: DI-301B Pipe ID: DI-301C East of Raritan East of Raritan Post # 2/5 Post # 2 NW Corner Route 100 at Hanley Route 100 at Hanley	131+05.82 144+81.18	LT LT LT LT/RT RT LT/RT RT		RT LT/RT RT	

Revision 4/1/2020 Page 25 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
2040	9029902	MISC.	8/11/22	8/16/22	3.00	EA	Post # 2/5		LT/RT		LT/RT	
2050	9029902	MISC.	8/11/22	8/16/22	3.00	EA	Post # 2/5		LT/RT		LT/RT	
2110	9029903	MISC.	8/11/22	8/16/22	2,710.00	LF	Post # 2/3/4/5		LT/RT		LT/RT	
2120	9029903	MISC.	8/11/22	8/16/22	490.00	LF	NW / SW Corner of Route 100 at Hanley		LT/RT		LT/RT	
2340	7034221	SLAB ON CONCRETE NU-GIRDER	8/10/22	8/15/22	180.00	SQYD	Rebar Tied in Place (15%)					
			8/11/22	8/15/22	420.00	SQYD	Concrete Placement (35%)					

	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
2510	2035500	EMBANKMENT IN PLACE	8/10/22	8/15/22	168.00	CUYD	Stage 1 Tunnel	64+00		66+00		
			8/11/22	8/15/22	219.20	CUYD	Stage 1 Tunnel	64+00		66+00		
590	3040504	TYPE 5 AGGREGATE FOR BASE	8/3/22	8/12/22	232.20	SQYD	Society for the blind sidewalk & bus pad	74+35.50	LT	76+53.87	LT	
			8/6/22	8/12/22	25.28	SQYD	ROUTE 100	69+68.8	LT	71+79.4		ARBU'S SIDEWALK
				8/12/22			BRENTWOOD	110+48.84		110+78.93		BRENTWOOD INTERSECTION MEDIAN ISLAND PAVEMENT
			8/9/22	8/12/22			Ace Hardware Sidewalk.	72+22.41		74+04.50		
	5004407	CONCRETE PAVEMENT (7 IN. NON-REINF)	0.10.100	8/12/22	33.64		Society of Blind Sidewalk.	110+45.89		110+79.44	LT	DESIGNATION DESIGNATION OF THE PROPERTY OF THE
2680	5021107	CONCRETE PAVEMENT (7 IN. NON-REINF)	8/6/22	8/12/22	64.84	SQYD	BRENTWOOD INTERSECTION	110+48.84	KI	110+78.93		BRENTWOOD INTERSECTION MEDIAN ISLAND PAVEMENT
820	6089902	MISC. CONCRETE	8/9/22	8/12/22	1.00	EA	Society of the Blind curb ramp 36	74+35.50	LT	76+53.87	LT	
				8/12/22	1.00	EA	Society of the Blind curb ramp 37	110+45.89	LT	110+79.44	LT	
2880	6089905	MISC. CONCRETE	8/3/22	8/12/22	232.20		Society for the blind sidewalk & bus pad.	74+35.50		76+53.87	LT	
			8/6/22	8/12/22	25.28	SQYD	ROUTE 100	69+68.8		71+79.4		ARBY'S SIDEWALK
			8/9/22	8/12/22	19.56	SQYD	Ace Hardware Sidewalk	72+22.41		74+04.50		
				8/12/22			Society of the Blind Sidewalk.	110+45.89		110+79.44		
		MISC. PAVED DRAINAGE		8/12/22	20.40		Society of the blind parking lot.	73+85.20	LT	74+04.50	LT	
11/0	7201200	SELECT GRANULAR BACKFILL FOR STRUCTURAL		8/15/22			Stage 1 Tunnel	66+00	I T/DT			From 7/E
			0/15/22	8/16/22 8/16/22	150.35 399.72		Stage 1 Tunnel Stage 1 Tunnel		LT/RT LT/RT			From 7/5 From 7/6
570	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	8/11/22	8/16/22	6.00		Cont A to PBA1	36+49.39		36+55.21	LT	
5.0	50.0004	The state of the s	U/ 11/22	8/16/22	6.00		Cont B to PBB1	51+12.09		51+06.86		
3580	9014004	CONDUIT, 4 IN. RIGID, PUSHED	8/11/22	8/16/22	5.00		PBD1 to PBD4	75+58.02		75+49.25		
				8/16/22	50.00		PBE1 to PBE2	125+43.12		125+43.12		
				8/16/22	51.00	LF	PBB1 to PBB2	51+06.86		51+11.07		
				8/16/22	51.00	LF	PBB5 to PBB6	54+87.76	RT	55+38.40	RT	
				8/16/22	53.00	LF	PBC1 to PBC2	65+04.70	LT/RT	65+17.76	LT/RT	
				8/16/22	68.00	LF	PBA1 to PBA2	36+55.27	LT/RT	36+63.84	LT/RT	
				8/16/22	81.00	LF	PBD5 to D402	81+59.50	LT	82+40.58	LT	
				8/16/22	115.00	LF	A403 to A404	39+24.80	LT	40+40.70		
				8/16/22	144.00	LF	PBD3 to PBD4	76+71.22	LT	78+14.72	LT	
3590	9015010	TRENCHING TYPE I	8/11/22	8/16/22	6.00		CONT A to A101					
				8/16/22	7.00		CONT A to A201					
				8/16/22 8/16/22	7.00 9.00		CONT D to D201 CONT B to B301					
				8/16/22	10.00		CONT B to B201					
				8/16/22	38.00		CONT E to E201					
				8/16/22	54.00		B102 to B103					
				8/16/22	65.00		B401 to B402					
				8/16/22	65.00		C103 to C104					
				8/16/22	68.00	LF	C104 to C105					
				8/16/22	68.00	LF	D401 to D402					
				8/16/22	70.00	LF	CONT B to B101					
				8/16/22	77.00	LF	A401 to A402					
				8/16/22	78.00	LF	B301 to B302					
				8/16/22	80.00	LF	D201 to D202					
				8/16/22	80.00		D202 to D203					
				8/16/22	81.00		D402 to D403					
				8/16/22	85.00		B201 to B202					
				8/16/22	87.00		B103 to B104					
				8/16/22 8/16/22	87.00 92.00		B205 to B206 A301 to A302					
				8/16/22	92.00		CONT A to A301					
				8/16/22	95.00		B302 to B303					
				8/16/22	97.00		A405 to A406					
				8/16/22	97.00		B105 to B106					
				8/16/22	97.00		B403 to B404					
				8/16/22	97.00	LF	D203 to D204					
				8/16/22	99.00	LF	CPNT A to A401					
				8/16/22	101.00	LF	B101 to B102					
				8/16/22	101.00	LF	B303 to B304					
				8/16/22	108.00		A402 to A403					
				8/16/22	111.00		B202 to B203					
				8/16/22	113.00		E201 to E202					
				8/16/22	122.00		A101 to A102					
							B104 to B105					
				8/16/22	128.00							
				8/16/22 8/16/22 8/16/22	128.00 128.00 135.00	LF	D204 to D205 A201 to A202					

Revision 4/1/2020 Page 26 of 70



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
3590	9015010	TRENCHING TYPE I	8/11/22	8/16/22	157.00	LF	B304 to B305					
				8/16/22	161.00	LF	B204 to B205					
				8/16/22	176.00	LF	B203 to B204					
				8/16/22	195.00	LF	A406 to A407					
				8/16/22	290.00	LF	D205 to D206					
				8/16/22	322.00	LF	B402 to B403					
				8/16/22	403.00	LF	CONT D to D401					
3600	9016110	PULL BOX, PREFORMED CLASS 1	8/11/22	8/16/22	1.00	EA	PBA1	36+55.27	LT			
				8/16/22	1.00	EA	PBB1	51+06.86	LT			
				8/16/22	1.00	EA	PBD5	81+59.50	LT			

Project: J6S1718C

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
4800	9016110	PULL BOX, PREFORMED CLASS 1	8/11/22	8/16/22	1.00	EA	PBD3	76+71.22	LT			
				8/16/22	1.00	EA	PBD4	78+14.75	LT			
4830	9019902	MISC. HIGHWAY LIGHTING	8/11/22	8/16/22	1.00	EA	G403	261+24.43	RT			
				8/16/22	1.00	EA	G404	262+24.45	RT			
				8/16/22	1.00	EA	G405	263+24.39	RT			
				8/16/22	1.00	EA	G406	264+24.43	RT			
				8/16/22	1.00	EA	G407	265+32.38	RT			
				8/16/22	1.00	EA	G408	266+57.67	RT			
				8/16/22	1.00	EA	H201	268+76.62	LT			
				8/16/22	1.00	EA	H202	267+40.82	RT			
				8/16/22	1.00	EA	H401	269+75.50	RT			
				8/16/22	1.00	EA	H402	270+86.73	RT			
				8/16/22	1.00	EA	H403	271+80.83	RT			
				8/16/22	1.00	EA	H404	272+80.74	RT			
				8/16/22	1.00	EA	H405	273+80.07	RT			
				8/16/22	1.00	EA	H406	274+78.28	RT			
				8/16/22	1.00	EA	H407	275+79.78	RT			
				8/16/22	1.00	EA	H408	276+79.83	RT			
				8/16/22	1.00	EA	H409	277+69.15	RT			
				8/16/22	1.00	EA	H410	278+69.15	RT			
				8/16/22	1.00	EA	H411	279+69.15	RT			
				8/16/22	1.00	EA	H412	280+69.15	RT			

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 27 of 70



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
6S1718	0070	TYPE 5 AGGREGATE FOR BASE	Material		6	Nov 2, 2021	SYSTEM	\$1,440.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																	
					6	Nov 2, 2021	SYSTEM	(\$1,440.18)																		
					7	Nov 15, 2021	SYSTEM	\$3,793.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																	
					7	Nov 15, 2021	SYSTEM	(\$3,793.86)																		
					8	Dec 2, 2021	SYSTEM	\$5,880.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																	
					8	Dec 2, 2021	SYSTEM	(\$5,880.42)																		
					9	Dec 16, 2021	SYSTEM	\$11,088.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																	
					9	Dec 16, 2021	SYSTEM	(\$11,088.00)																		
					10	Jan 3, 2022	SYSTEM	\$14,165.55	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
					10	Jan 3, 2022	SYSTEM	(\$14,165.55)																		
					11	Jan 18, 2022	SYSTEM	\$17,583.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
						11	Jan 18, 2022	SYSTEM	(\$17,583.30)																	
					12	Feb 1, 2022	SYSTEM	\$20,444.26	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	
							12	Feb 1, 2022	SYSTEM	(\$20,444.26)																
							13	Feb 16, 2022	SYSTEM	\$22,144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.															
							13	Feb 16, 2022	SYSTEM	(\$22,144.00)																
						14	Mar 1, 2022	SYSTEM	\$24,859.61	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																
												14	Mar 1, 2022	SYSTEM	(\$24,859.61)											
																							15 Mar 16, SYSTEM \$30,004.57 This adjustment offsets the original system-g 2022 Estimate Item Adjustment (0008) due to user	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
																	15	Mar 16, 2022	SYSTEM	(\$30,004.57)						
																			16	Apr 4, 2022	SYSTEM	\$33,636.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					16	Apr 4, 2022	SYSTEM	(\$33,636.64)																		
									17	Apr 18, 2022	SYSTEM	\$36,271.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.													
					1	1		17	Apr 18, 2022	SYSTEM	(\$36,271.18)															
														1		1						18	May 2, 2022	SYSTEM	\$42,418.03	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
								18	May 2, 2022	SYSTEM	(\$42,418.03)															
					19	May 16, 2022	SYSTEM	\$52,594.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																		
J6S1718	0070	TYPE 5	Material			2022																					
		AGGREGATE FOR BASE			20	Jun 2, 2022	SYSTEM	\$57,328.99	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																		
					20	Jun 2, 2022	SYSTEM	(\$57,328.99)																			
					21	Jun 16, 2022	SYSTEM	\$60,755.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																		
					21	Jun 16, 2022	SYSTEM	(\$60,755.18)																			
					22	Jul 1, 2022	SYSTEM	\$64,044.79	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.																		
				22	Jul 1, 2022	SYSTEM	(\$64,044.79)																				
					23	Jul 18, 2022	SYSTEM	\$71,273.03	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																		
					23	Jul 18, 2022	SYSTEM	(\$71,273.03)																			
							24	Aug 2, 2022	SYSTEM	\$73,855.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user steppr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.																
					24	Aug 2, 2022	SYSTEM	(\$73,855.84)																			
				- Total				\$0.00																			
			Material - Tot					\$0.00																			
	0070 - Total						\$0.00																				
	0130	CONCRETE PAVEMENT (7 IN. NON-REINF)	Material		9	Dec 16, 2021	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																		
						9	Dec 16, 2021	SYSTEM	(\$1,478.40)																		
						10	Jan 3, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																	
						10	Jan 3, 2022	SYSTEM	(\$1,478.40)																		
							11	Jan 18, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																
																					11	Jan 18, 2022	SYSTEM	(\$1,478.40)			
																									12	Feb 1, 2022	SYSTEM
																			12	Feb 1, 2022	SYSTEM	(\$1,478.40)					
								13	Feb 16, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.															
			1	12	14				13	Feb 16, 2022	SYSTEM	(\$1,478.40)															
																	1			1	1-		14	Mar 1, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		1				14	Mar 1, 2022	SYSTEM	(\$1,478.40)																		
					15	Mar 16, 2022	SYSTEM	\$1,478.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.																		
					15	Mar 16, 2022	SYSTEM	(\$1,478.40)																			
					16	Apr 4, 2022	SYSTEM	\$2,094.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J6S1718	0130	CONCRETE PAVEMENT (7 IN.	Material		16	Apr 4, 2022	SYSTEM	(\$2,094.40)																		
		NON-REINF)			17	Apr 18, 2022	SYSTEM	\$2,094.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
					17	Apr 18, 2022	SYSTEM	(\$2,094.40)																		
					18	May 2, 2022	SYSTEM	\$2,094.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
					18	May 2, 2022	SYSTEM	(\$2,094.40)																		
					19	May 16, 2022	SYSTEM	\$3,267.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.																	
					19	May 16, 2022	SYSTEM	(\$3,267.44)																		
					20	Jun 2, 2022	SYSTEM	\$4,733.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 6 on the current Payment Estimate.																	
					20	Jun 2, 2022	SYSTEM	(\$4,733.52)																		
				- Total				\$0.00																		
			Material - Tot	ial				\$0.00																		
	0130 -	Total						\$0.00																		
	0140	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		6	Nov 2, 2021	SYSTEM	\$9,905.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
					6	Nov 2, 2021	SYSTEM	(\$9,905.60)																		
					7	Nov 15, 2021	SYSTEM	\$17,015.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
					7	Nov 15, 2021	SYSTEM	(\$17,015.00)																		
					8	Dec 2, 2021	SYSTEM	\$17,015.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.																	
							8	Dec 2, 2021	SYSTEM	(\$17,015.00)																
					9	Dec 16, 2021	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.																	
					9	Dec 16, 2021	SYSTEM	(\$37,277.20)																		
					10	Jan 3, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																	
					10	Jan 3, 2022	SYSTEM	(\$37,277.20)																		
					11	Jan 18, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																	
					11	Jan 18, 2022	SYSTEM	(\$37,277.20)																		
																							12	Feb 1, 2022	SYSTEM	\$37,277.20
					12	Feb 1, 2022	SYSTEM	(\$37,277.20)																		
					13	Feb 16, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																	
					13	Feb 16, 2022	SYSTEM	(\$37,277.20)																		
					14	Mar 1, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S1718	0140	CONCRETE PAVEMENT (9 IN.	Material		14	Mar 1, 2022	SYSTEM	(\$37,277.20)												
	NON-REINF)			15	Mar 16, 2022	SYSTEM	\$43,895.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.												
					15	Mar 16, 2022	SYSTEM	(\$43,895.42)												
					16	Apr 4, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.											
					16	Apr 4, 2022	SYSTEM	(\$37,277.20)												
					17	Apr 18, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.											
					17	Apr 18, 2022	SYSTEM	(\$37,277.20)												
					18	May 2, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.											
					18	May 2, 2022	SYSTEM	(\$37,277.20)												
					19	May 16, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.											
					19	May 16, 2022	SYSTEM	(\$37,277.20)												
					20	Jun 2, 2022	SYSTEM	\$37,277.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					20	Jun 2, 2022	SYSTEM	(\$37,277.20)												
				- Total				\$0.00												
			Material - To	tal				\$0.00												
	0140 -							\$0.00												
	0150	CONCRETE APPROACH PAVEMENT	Material		19	May 16, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.											
						19	May 16, 2022	SYSTEM	(\$13,420.50)											
					20	Jun 2, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
					20	Jun 2, 2022	SYSTEM	(\$13,420.50)												
													21	Jun 16, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user schirj1 overridding Payment Estimate Exception 5 on the current Payment Estimate.			
																			21	Jun 16, 2022
																22	Jul 1, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user steppr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$13,420.50)												
					23	Jul 18, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					23	Jul 18, 2022	SYSTEM	(\$13,420.50)												
			2	24	Aug 2, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.												
					24	Aug 2, 2022	SYSTEM	(\$13,420.50)												
					25	Aug 16, 2022	SYSTEM	\$13,420.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6S1718	0150	CONCRETE APPROACH	Material		25	Aug 16, 2022	SYSTEM	(\$13,420.50)															
		PAVEMENT		- Total				\$0.00															
			Material - Tot	tal				\$0.00															
	0150 -	Total						\$0.00															
	0210	PAVED APPROACH, 7 IN.	Material		6	Nov 2, 2021	SYSTEM	\$1,808.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					6	Nov 2, 2021	SYSTEM	(\$1,808.80)															
					7	Nov 15, 2021	SYSTEM	\$9,484.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.														
					7	Nov 15, 2021	SYSTEM	(\$9,484.80)															
						8	Dec 2, 2021	SYSTEM	\$25,064.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.													
						8	Dec 2, 2021	SYSTEM	(\$25,064.80)														
					9	Dec 16, 2021	SYSTEM	\$47,530.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					9	Dec 16, 2021	SYSTEM	(\$47,530.40)															
					10	Jan 3, 2022	SYSTEM	\$59,120.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
					10	Jan 3, 2022	SYSTEM	(\$59,120.40)															
					11	Jan 18, 2022	SYSTEM	\$79,579.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
						11	Jan 18, 2022	SYSTEM	(\$79,579.60)														
						12	Feb 1, 2022	SYSTEM	\$92,916.84	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.													
					12	Feb 1, 2022	SYSTEM	(\$92,916.84)															
					13	Feb 16, 2022	SYSTEM	\$99,261.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
				13	Feb 16, 2022	SYSTEM	(\$99,261.32)																
															14	Mar 1, 2022	SYSTEM	\$113,541.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
											14	Mar 1, 2022	SYSTEM	(\$113,541.72)									
						15	Mar 16, 2022	SYSTEM	\$129,024.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.													
									1		15	Mar 16, 2022	SYSTEM	(\$129,024.44)									
																				16	Apr 4, 2022	SYSTEM	\$162,121.68
										16	Apr 4, 2022	SYSTEM	(\$162,121.68)										
							17	Apr 18, 2022	SYSTEM	\$181,030.48	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.												
					17	Apr 18, 2022	SYSTEM	(\$181,030.48)															
					18	May 2, 2022	SYSTEM	\$204,634.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J6S1718	0210	PAVED APPROACH, 7 IN.	Material		18	May 2, 2022	SYSTEM	(\$204,634.56)																
					19	May 16, 2022	SYSTEM	\$236,441.32	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.															
					19	May 16, 2022	SYSTEM	(\$236,441.32)																
				- Total				\$0.00																
			Material - To	tal				\$0.00																
	0210 -	Total						\$0.00																
	0220	CONCRETE SIDEWALK, 4 IN.	Material		6	Nov 2, 2021	SYSTEM	\$6,015.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
					6	Nov 2, 2021	SYSTEM	(\$6,015.00)																
						7	Nov 15, 2021	SYSTEM	\$12,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
						7	Nov 15, 2021	SYSTEM	(\$12,950.00)															
						8	Dec 2, 2021	SYSTEM	\$14,305.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
					8	Dec 2, 2021	SYSTEM	(\$14,305.00)																
					9	Dec 16, 2021	SYSTEM	\$22,445.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.															
						9	Dec 16, 2021	SYSTEM	(\$22,445.00)															
					10	Jan 3, 2022	SYSTEM	\$29,005.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.															
					10	Jan 3, 2022	SYSTEM	(\$29,005.00)																
					11	Jan 18, 2022	SYSTEM	\$29,936.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.															
					11	Jan 18, 2022	SYSTEM	(\$29,936.00)																
					12	Feb 1, 2022	SYSTEM	\$40,869.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.															
					12	Feb 1, 2022	SYSTEM	(\$40,869.00)																
					13	Feb 16, 2022	SYSTEM	\$42,549.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.															
					13	Feb 16, 2022	SYSTEM	(\$42,549.00)																
					14	Mar 1, 2022	SYSTEM	\$49,964.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.															
					14	Mar 1, 2022	SYSTEM	(\$49,964.50)																
																				15	Mar 16, 2022	SYSTEM	\$66,135.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
											15	Mar 16, 2022	SYSTEM	(\$66,135.50)										
					16	Apr 4, 2022	SYSTEM	\$66,186.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.															
					16	Apr 4,	SYSTEM	(\$66,186.00)	Exception 27 on the outlott I symmet Estimate.															
					17	2022 Apr 18, 2022	SYSTEM	\$69,894.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J6S1718	0220	CONCRETE SIDEWALK, 4 IN.	Material		17	Apr 18, 2022	SYSTEM	(\$69,894.50)																		
					18	May 2, 2022	SYSTEM	\$79,450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																	
					18	May 2, 2022	SYSTEM	(\$79,450.00)																		
					19	May 16, 2022	SYSTEM	\$91,951.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																	
					19	May 16, 2022	SYSTEM	(\$91,951.50)																		
				- Total				\$0.00																		
			Material - To	tal				\$0.00																		
	0220 -	- Total						\$0.00																		
	0250	MISC. CONCRETE	Material		7	Nov 15, 2021	SYSTEM	\$5,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																	
					7	Nov 15, 2021	SYSTEM	(\$5,295.00)																		
					8	Dec 2, 2021	SYSTEM	\$5,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.																	
					8	Dec 2, 2021	SYSTEM	(\$5,295.00)																		
					9	Dec 16, 2021	SYSTEM	\$7,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj¹ overridding Payment Estimate Exception 24 on the current Payment Estimate.																	
					9	Dec 16, 2021	SYSTEM	(\$7,060.00)																		
					10	Jan 3, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																	
					10	Jan 3, 2022	SYSTEM	(\$10,590.00)																		
					11	Jan 18, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																	
						Jan 18, 2022	SYSTEM	(\$10,590.00)																		
					12	Feb 1, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																	
					12	Feb 1, 2022	SYSTEM	(\$10,590.00)																		
					13	Feb 16, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj¹ overridding Payment Estimate Exception 23 on the current Payment Estimate.																	
					13	Feb 16, 2022	SYSTEM	(\$10,590.00)																		
					14	Mar 1, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																	
					14	Mar 1, 2022	SYSTEM	(\$10,590.00)																		
													-									15	Mar 16, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schiŋ¹ overridding Payment Estimate Exception 25 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$10,590.00)																		
					16	Apr 4, 2022	SYSTEM	\$10,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																	
					16	Apr 4, 2022	SYSTEM	(\$10,590.00)																		
					17	Apr 18, 2022	SYSTEM	\$12,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																	
J6S1718	0250	MISC. CONCRETE	Material		17	Apr 18, 2022	SYSTEM	(\$12,355.00)																		
					18	May 2, 2022	SYSTEM	\$12,355.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																	
					18	May 2, 2022	SYSTEM	(\$12,355.00)																		
					19	May 16, 2022	SYSTEM	\$14,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																	
					19	May 16, 2022	SYSTEM	(\$14,120.00)																		
				- Total				\$0.00																		
			Material - To	tal				\$0.00																		
		Total						\$0.00																		
	0260	(6 IN. HEIGHT AND UNDER)	Material			6	Nov 2, 2021	SYSTEM	\$15,855.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.																
							6	Nov 2, 2021	SYSTEM	(\$15,855.00)																
						7	Nov 15, 2021	SYSTEM	\$17,445.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																
					7	Nov 15, 2021	SYSTEM	(\$17,445.00)																		
					8	Dec 2, 2021	SYSTEM	\$17,445.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.																	
					8	Dec 2, 2021	SYSTEM	(\$17,445.00)																		
					9	Dec 16, 2021	SYSTEM	\$22,101.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																	
			9 Dec 16, SYSTEM (\$22,101.00)																							
					10	Jan 3, 2022	SYSTEM	\$22,194.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																	
											10	Jan 3, 2022	SYSTEM	(\$22,194.00)												
					11	Jan 18, 2022	SYSTEM	\$23,919.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																	
					11	Jan 18, 2022	SYSTEM	(\$23,919.00)																		
																						12	Feb 1, 2022	SYSTEM	\$26,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
							12	Feb 1, 2022	SYSTEM	(\$26,502.00)																
					13	Feb 16, 2022	SYSTEM	\$26,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																	
							13	Feb 16, 2022	SYSTEM	(\$26,502.00)																
															14	Mar 1, 2022	SYSTEM	\$26,502.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.							
					14	Mar 1, 2022	SYSTEM	(\$26,502.00)																		
					15	Mar 16, 2022	SYSTEM	\$32,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.																	
					15	Mar 16, 2022	SYSTEM	(\$32,475.00)																		
					16	Apr 4, 2022	SYSTEM	\$33,708.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.																	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J6S1718	0260	CONCRETE CURB (6 IN. HEIGHT AND	Material	1350	16	Apr 4, 2022	SYSTEM	(\$33,708.00)																				
		UNDER)			17	Apr 18, 2022	SYSTEM	\$39,729.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.																			
					17	Apr 18, 2022	SYSTEM	(\$39,729.00)																				
					18	May 2, 2022	SYSTEM	\$43,711.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.																			
					18	May 2, 2022	SYSTEM	(\$43,711.50)																				
					19	May 16, 2022	SYSTEM	\$57,541.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj¹ overridding Payment Estimate Exception 35 on the current Payment Estimate.																			
					19	May 16, 2022	SYSTEM	(\$57,541.80)																				
				- Total				\$0.00																				
			Material - To	tal				\$0.00																				
	0260 -	Total						\$0.00																				
	0270	CURB AND GUTTER TYPE B	Material		8	Dec 2, 2021	SYSTEM	\$5,724.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																			
					8	Dec 2, 2021	SYSTEM	(\$5,724.00)																				
						9	Dec 16, 2021	SYSTEM	\$12,030.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																		
																			9	Dec 16, 2021	SYSTEM	(\$12,030.00)						
					10	Jan 3, 2022	SYSTEM	\$26,457.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																			
							10	Jan 3, 2022	SYSTEM	(\$26,457.00)																		
						11	Jan 18, 2022	SYSTEM	\$50,775.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																		
					11	Jan 18, 2022	SYSTEM	(\$50,775.00)																				
								12	Feb 1, 2022	SYSTEM	\$55,842.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																
					12	Feb 1, 2022	SYSTEM	(\$55,842.00)																				
																								13	Feb 16, 2022	SYSTEM	\$69,582.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
										13	Feb 16, 2022	SYSTEM	(\$69,582.00)															
					14	Mar 1, 2022	SYSTEM	\$78,102.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.																			
					14	Mar 1, 2022	SYSTEM	(\$78,102.00)																				
														1							15	Mar 16, 2022	SYSTEM	\$93,342.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.			
													1	15	Mar 16, 2022	SYSTEM	(\$93,342.00)											
					16	Apr 4, 2022	SYSTEM	\$103,083.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																			
					16	Apr 4, 2022	SYSTEM	(\$103,083.00)																				
					17	Apr 18, 2022	SYSTEM	\$106,458.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0270	CURB AND GUTTER TYPE B	Material		17	Apr 18, 2022	SYSTEM	(\$106,458.00)	
					18	May 2, 2022	SYSTEM	\$113,588.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$113,588.70)	
					19	May 16, 2022	SYSTEM	\$118,133.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$118,133.70)	
				- Total				\$0.00	
			Material - Tot	ial				\$0.00	
	0270 -						0) (0==1.1	\$0.00	
	0280	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		21	Jun 16, 2022	SYSTEM	\$610.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$610.50)	
					22	Jul 1, 2022	SYSTEM	\$1,785.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$1,785.25)	
					23	Jul 18, 2022	SYSTEM	\$1,785.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$1,785.25)	
					24	Aug 2, 2022	SYSTEM	\$1,785.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user steppr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$1,785.25)	
					25	Aug 16, 2022	SYSTEM	\$1,785.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$1,785.25)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0280 -	Total						\$0.00	
	0290	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		6	Nov 2, 2021	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					6	Nov 2, 2021	SYSTEM	(\$228.00)	
					7	Nov 15, 2021	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$228.00)	
					8	Dec 2, 2021	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$228.00)	
					9	Dec 16, 2021	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					9	Dec 16, 2021	SYSTEM	(\$228.00)	
					10	Jan 3, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					10	Jan 3,	SYSTEM	(\$228.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S1718	0290	INTEGRAL CURB	Material			2022						
		(6 IN. HEIGHT AND UNDER)			11	Jan 18, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
					11	Jan 18, 2022	SYSTEM	(\$228.00)				
					12	Feb 1, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
					12	Feb 1, 2022	SYSTEM	(\$228.00)				
					13	Feb 16, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
					13	Feb 16, 2022	SYSTEM	(\$228.00)				
					14	Mar 1, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
								14	Mar 1, 2022	SYSTEM	(\$228.00)	
					15	Mar 16, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.			
					15	Mar 16, 2022	SYSTEM	(\$228.00)				
					16	Apr 4, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.			
					16	Apr 4, 2022	SYSTEM	(\$228.00)				
					17	Apr 18, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.			
					17	Apr 18, 2022	SYSTEM	(\$228.00)				
						18	May 2, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.		
					18	May 2, 2022	SYSTEM	(\$228.00)				
					19	May 16, 2022	SYSTEM	\$228.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.			
					19	May 16, 2022	SYSTEM	(\$228.00)				
				- Total				\$0.00				
			Material - Tot	tal				\$0.00				
	0290 -	- Total						\$0.00				
	0300		Material		13	Feb 16, 2022	SYSTEM	\$1,649.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
					13	Feb 16, 2022	SYSTEM	(\$1,649.20)				
					14	Mar 1, 2022	SYSTEM	\$1,649.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
					14	Mar 1, 2022	SYSTEM	(\$1,649.20)				
					15	Mar 16, 2022	SYSTEM	\$1,649.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.			
						15	Mar 16, 2022	SYSTEM	(\$1,649.20)			
					16	Apr 4, 2022	SYSTEM	\$1,649.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0300	MISC. PAVED DRAINAGE	Material		16	Apr 4, 2022	SYSTEM	(\$1,649.20)	
					17	Apr 18, 2022	SYSTEM	\$1,649.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$1,649.20)	
					18	May 2, 2022	SYSTEM	\$6,633.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$6,633.20)	
					19	May 16, 2022	SYSTEM	\$6,633.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$6,633.20)	
					20	Jun 2, 2022	SYSTEM	\$6,633.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$6,633.20)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0300 -	- Total						\$0.00	
	0310	MISC. PAVED DRAINAGE	Material		19	May 16, 2022	SYSTEM	\$2,022.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$2,022.15)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0310 -	- Total						\$0.00	
	0340	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		11	Jan 18, 2022	SYSTEM	\$3,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					11	Jan 18, 2022	SYSTEM	(\$3,800.00)	
					12	Feb 1,	SYSTEM	\$13,560.00	This adjustment offsets the original system-generated Material Payment
						2022		* 10,000100	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					12	Feb 1, 2022	SYSTEM	(\$13,560.00)	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment
					12	Feb 1,	SYSTEM		Estimate Item Adjustment (0013) due to user schirj1 overridding Payment
						Feb 1, 2022 Feb 16,		(\$13,560.00)	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment
					13	Feb 1, 2022 Feb 16, 2022 Feb 16,	SYSTEM	(\$13,560.00) \$23,100.00	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment
					13	Feb 1, 2022 Feb 16, 2022 Feb 16, 2022 Mar 1,	SYSTEM SYSTEM	(\$13,560.00) \$23,100.00 (\$23,100.00)	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment
					13 13	Feb 1, 2022 Feb 16, 2022 Feb 16, 2022 Mar 1, 2022	SYSTEM SYSTEM	(\$13,560.00) \$23,100.00 (\$23,100.00) \$23,100.00	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment
					13 13 14	Feb 1, 2022 Feb 16, 2022 Feb 16, 2022 Mar 1, 2022 Mar 1, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,560.00) \$23,100.00 (\$23,100.00) \$23,100.00 (\$23,100.00)	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment
					13 13 14 14 15	Feb 1, 2022 Feb 16, 2022 Feb 16, 2022 Mar 1, 2022 Mar 1, 2022 Mar 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,560.00) \$23,100.00 (\$23,100.00) \$23,100.00 (\$23,100.00) \$23,100.00	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment
					13 13 14 14 15	Feb 1, 2022 Feb 16, 2022 Feb 16, 2022 Mar 1, 2022 Mar 1, 2022 Mar 16, 2022 Apr 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,560.00) \$23,100.00 (\$23,100.00) \$23,100.00 (\$23,100.00) \$23,100.00	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 39 on the current Payment Estimate.
					13 14 14 15 15 16	Feb 1, 2022 Feb 16, 2022 Mar 1, 2022 Mar 1, 2022 Mar 16, 2022 Mar 16, 2022 Apr 4, 2022 Apr 4,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$13,560.00) \$23,100.00 (\$23,100.00) \$23,100.00 (\$23,100.00) \$23,100.00 (\$23,100.00)	Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 39 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J6S1718	0340	FURN & PLACE	Material			2022																						
		CONC MATL FOR FULL DEPTH			18	May 2, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.																			
					18	May 2, 2022	SYSTEM	(\$23,100.00)																				
					19	May 16, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.																			
					19	May 16, 2022	SYSTEM	(\$23,100.00)																				
					20	Jun 2, 2022	SYSTEM	\$23,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.																			
					20	Jun 2, 2022	SYSTEM	(\$23,100.00)	,																			
				- Total		ZUZZ		\$0.00																				
			Material - To					\$0.00																				
	0340 -	Total						\$0.00																				
	0340 - Total 0350 SUBGRADE COMPACTION (6 IN. DEPTH)	Material		12	Feb 1, 2022	SYSTEM	\$146.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.																				
		(PAVEM									12	Feb 1, 2022	SYSTEM	(\$146.40)														
											13	Feb 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.													
					13	Feb 16, 2022	SYSTEM	(\$346.50)																				
					14	Mar 1, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.																			
					14	Mar 1, 2022	SYSTEM	(\$346.50)																				
					15	Mar 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.																			
					15	Mar 16, 2022	SYSTEM	(\$346.50)																				
					16	Apr 4, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.																			
						16	Apr 4, 2022	SYSTEM	(\$346.50)																			
																								17	Apr 18, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
			1 1 1				17	Apr 18, 2022	SYSTEM	(\$346.50)																		
										18	May 2, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.														
							18	May 2, 2022	SYSTEM	(\$346.50)																		
									19	15	15						-		1		1		19	May 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	
												19	May 16, 2022	SYSTEM	(\$346.50)													
													20	Jun 2, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.											
					20	Jun 2, 2022	SYSTEM	(\$346.50)																				
					21	Jun 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J6S1718	0350	SUBGRADE COMPACTION (6	Material		21	Jun 16, 2022	SYSTEM	(\$346.50)																	
		IN. DEPTH) (PAVEM			22	Jul 1, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																
					22	Jul 1, 2022	SYSTEM	(\$346.50)																	
					23	Jul 18, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.																
					23	Jul 18, 2022	SYSTEM	(\$346.50)																	
					24	Aug 2, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																
					24	Aug 2, 2022	SYSTEM	(\$346.50)																	
					25	Aug 16, 2022	SYSTEM	\$346.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																
					25	Aug 16, 2022	SYSTEM	(\$346.50)																	
				- Total				\$0.00																	
			Material - Tot	tal				\$0.00																	
	0350 -	Total						\$0.00																	
	0360	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. TH	Material		12	Feb 1, 2022	SYSTEM	\$195.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.																
					12	Feb 1, 2022	SYSTEM	(\$195.20)																	
					13	Feb 16, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.																
					13	Feb 16, 2022	SYSTEM	(\$462.00)																	
					14	Mar 1, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.																
						14	Mar 1, 2022	SYSTEM	(\$462.00)																
					15	Mar 16, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.																
					15	Mar 16, 2022	SYSTEM	(\$462.00)																	
					16	Apr 4, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.																
									16	Apr 4, 2022	SYSTEM	(\$462.00)													
													17	Apr 18, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.								
					17	Apr 18, 2022	SYSTEM	(\$462.00)																	
																	1		1		18	May 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
																18	May 2, 2022	SYSTEM	(\$462.00)						
					19	May 16, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																
		15		19	May 16, 2022	SYSTEM	(\$462.00)																		
					20	Jun 2, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J6S1718	0360	TYPE 1 OR 5 AGGREGATE FOR	Material		20	Jun 2, 2022	SYSTEM	(\$462.00)												
		BASE (4 IN. TH			21	Jun 16, 2022	SYSTEM	\$462.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
					21	Jun 16, 2022	SYSTEM	(\$462.00)												
				- Total				\$0.00												
			Material - Tot	al				\$0.00												
	0360 -							\$0.00												
	0380	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		12	Feb 1, 2022	SYSTEM	\$120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.											
		11401			12	Feb 1, 2022	SYSTEM	(\$120.00)												
					13	Feb 16, 2022	SYSTEM	\$120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.											
					13	Feb 16, 2022	SYSTEM	(\$120.00)												
					14	Mar 1, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.											
					14	Mar 1, 2022	SYSTEM	(\$510.00)												
					15	Mar 16, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.											
																15	Mar 16, 2022	SYSTEM	(\$510.00)	
													16	Apr 4, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.			
														16	Apr 4, 2022	SYSTEM	(\$510.00)			
					17	Apr 18, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.											
					17	Apr 18, 2022	SYSTEM	(\$510.00)												
					18	May 2, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 62 on the current Payment Estimate.											
					18	May 2, 2022	SYSTEM	(\$510.00)												
					19	May 16, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.											
					19	May 16, 2022	SYSTEM	(\$510.00)												
					20	Jun 2, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.											
					20	Jun 2, 2022	SYSTEM	(\$510.00)												
					21	Jun 16, 2022	SYSTEM	\$510.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.											
					21	Jun 16, 2022	SYSTEM	(\$510.00)	·											
				- Total				\$0.00												
			Material - Tot					\$0.00												
	0380 -	Total						\$0.00												
	0390	DOWEL BAR (FURNISH AND INSTALL WITH	Material		12	Feb 1, 2022	SYSTEM	\$13.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.											
		BASK			12	Feb 1,	SYSTEM	(\$13.00)												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0390	DOWEL BAR	Material	, ,,		2022			
		(FURNISH AND INSTALL WITH BASK			13	Feb 16, 2022	SYSTEM	\$13.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$13.00)	
					14	Mar 1, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					14	Mar 1, 2022	SYSTEM	(\$26.00)	Estimate Exception 43 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$26.00)	
					16	Apr 4, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$26.00)	
					17	Apr 18, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$26.00)	
					18	May 2, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schirj1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$26.00)	
					19	May 16, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$26.00)	
					20	Jun 2, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$26.00)	
					21	Jun 16, 2022	SYSTEM	\$26.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$26.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
		- Total						\$0.00	
	0430	MISC.	Material		6	Nov 2, 2021	SYSTEM	\$37,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					6	Nov 2, 2021	SYSTEM	(\$37,500.00)	
					7	Nov 15, 2021	SYSTEM	\$37,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Nov 15, 2021	SYSTEM	(\$37,500.00)	
					8	Dec 2, 2021	SYSTEM	\$37,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					8	Dec 2, 2021	SYSTEM	(\$37,500.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	0430	- Total						\$0.00	



CECOTEXTILE	Line	e Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
2022 21 Jan 16, SYSTEM \$2.484.40 Estimate Internal payers generated Material Payer Estimate Internal payers (2006) que to see set/sity coveridating Payers (2006) Pa	8 066		Material		20		SYSTEM	\$2,484.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.															
2022 21					20		SYSTEM	(\$2,484.40)																
1-701a 1-70					21		SYSTEM	\$2,484.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.															
					21		SYSTEM	(\$2,484.40)																
Color				- Total				\$0.00																
17			Material - To	tal				\$0.00																
CHECK	066	0 - Total						\$0.00																
18	074		Material		17		SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 74 on the current Payment Estimate.															
2022 Estimate Item Adjustment (0020) due to user schirjf overridding Pay Estimate Exception 75 on the current Payment Estimate.					17		SYSTEM	(\$183.00)																
19					18		SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schirj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.															
2022 Estimate Item Adjustment (003) due to user schift overridding Pay Estimate Exception 59 on the current Payment Estimate.					18		SYSTEM	(\$183.00)																
2022 20					19		SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.															
20						19		SYSTEM	(\$183.00)															
2022 21					20		SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.															
2022 Estimate Item Adjustment (0060) due to user schipf1 overridding Pay Estimate Exception 39 on the current Payment Estimate.														20		SYSTEM	(\$183.00)							
2022 22							21		SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.													
2022 Estimate Item Adjustment (0020) due to user steppr1 overridding Palestimate Exception 36 on the current Payment Estimate.										21		SYSTEM	(\$183.00)											
2022 23 Jul 18, 2022 24 Aug 2, 2022 25 Aug 16, 2022 26 Aug 16, 2022 27 SYSTEM \$183.00 28 SYSTEM \$183.00 29 SYSTEM \$183.00 20 SYSTEM \$183.0					22		SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user steppr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.															
Estimate Item Adjustment (0070) due to user schirj1 overridding Pay Estimate Exception 35 on the current Payment Estimate. 23					22		SYSTEM	(\$183.00)																
2022 24 Aug 2, 2022 24 Aug 2, 2022 25 Aug 16, 2022 25 Aug 16, 2022 26 Aug 16, 2022 27 Aug 16, 2022 28 SYSTEM 29 SYSTEM 20 SYST					23		SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.															
2022 Estimate Item Adjustment (0027) due to user steppr1 overridding Pa Estimate Exception 44 on the current Payment Estimate.					23		SYSTEM	(\$183.00)																
2022 25																				24		SYSTEM	\$183.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user steppr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
25 Aug 16, 2022 \$198.25 This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0075) due to user schirj1 overridding Pay Estimate Exception 46 on the current Payment Estimate. 25 Aug 16, 2022 \$0.00 - Total \$0.00 Material - Total \$0.00 0740 - Total \$0.00 TYPE C BERM Material 20 Jun 2, 2022 \$100.00 This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0024) due to user schirj1 overridding Pay Estimate Exception 42 on the current Payment Estimate.								24		SYSTEM	(\$183.00)													
Type C Berm Material 20 Jun 2, 2022 2022					25	Aug 16,	SYSTEM	\$198.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user schirj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.															
Total \$0.00 Material - Total \$0.00					25		SYSTEM	(\$198.25)																
TYPE C BERM Material 20 Jun 2, 2022 SYSTEM \$6,050.00 This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0024) due to user schirj1 overridding Payn Estimate Exception 42 on the current Payment Estimate.				- Total				\$0.00																
TYPE C BERM Material 20 Jun 2, 2022 SYSTEM \$6,050.00 This adjustment offsets the original system-generated Material Payn Estimate Item Adjustment (0024) due to user schirj1 overridding Pay Estimate Exception 42 on the current Payment Estimate.			Material - To	tal				\$0.00																
2022 Estimate Item Adjustment (0024) due to user schirj1 overridding Pay Estimate Exception 42 on the current Payment Estimate.	074	0 - Total						\$0.00																
20 Jun 2, SYSTEM (\$6,050.00)	078	TYPE C BERM	Material		20		SYSTEM	\$6,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.															
2022					20		SYSTEM	(\$6,050.00)																
- Total \$0.00				- Total				\$0.00																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	0780	TYPE C BERM	Material - Tot	tal				\$0.00	
	0780 -	Total						\$0.00	
	0800	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$17,847.84	Payment Estimate Item Adjustment generated Stockpile Transaction
			011111	- Total				\$17,847.84	
			Construction	Stockpile S	TMI - Total			\$17,847.84	
	0800 -	Total						\$17,847.84	
	0810	BRACKET ARM, 15 FT. OR 4.6 M	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$7,576.68	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$7,576.68	
			Construction	Stockpile S	TMI - Total			\$7,576.68	
	0810 -							\$7,576.68	
	0990	SIGNAL SIGN, MOUNTING HARDWARE	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$5,625.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$5,625.00	
		_	Construction	Stockpile S	TMI - Total			\$5,625.00	
	0990 -							\$5,625.00	
	1000	FT. OR 2.4 M	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$11,718.31	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$11,718.31	
			Construction	Stockpile S	IMI - Iotai			\$11,718.31	
		Total	-					\$11,718.31	
	1010	POST, SIGNAL 15 FT. OR 4.6 M	Construction Stockpile STMI	- Total	23	Jul 18, 2022	SYSTEM	\$2,047.64	Payment Estimate Item Adjustment generated Stockpile Transaction
			Camatuustian		TAGE TOTAL			\$2,047.64	
	1010	Total	Construction	Stockpile S	TIVII - TOtal			\$2,047.64 \$2,047.64	
	1030	10 - Total 30 POST, TYPE CL, 25 FT. ARM OR 7.6 M ARM	Construction Stockpile		23	Jul 18, 2022	SYSTEM	\$10,473.04	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$10,473.04	
			Construction	Stockpile S	TMI - Total			\$10,473.04	
	1030 -	Total						\$10,473.04	
	1040	POST, TYPE CL, 30 FT. ARM OR 9.1	Construction Stockpile		23	Jul 18, 2022	SYSTEM	\$12,695.78	Payment Estimate Item Adjustment generated Stockpile Transaction
		M ARM	STMI	- Total				\$12,695.78	
			Construction	Stockpile S	TMI - Total			\$12,695.78	
	1040 -	Total						\$12,695.78	
	1050	POST, TYPE CL, 35 FT. ARM OR 10.7 M ARM	Stockpile		23	Jul 18, 2022	SYSTEM	\$6,554.92	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$6,554.92	
			Construction	Stockpile S	TMI - Total			\$6,554.92	
	1050 - 1060	POST, TYPE CL,	Construction		23	Jul 18,	SYSTEM	\$6,554.92 \$34,285.61	Payment Estimate Item Adjustment generated Stockpile Transaction
		40 FT. ARM OR 12.2 M ARM	Stockpile STMI	Total		2022		\$24.205.04	
			Construction	- Total	TMI Total			\$34,285.61 \$34,285.61	
	1000	Total	Construction	Этоскрие 5	HWII - TOTAI			\$34,285.61	
			Construction		22	Jul 40	CVCTEN	\$34,285.61	Doument Estimate Item Adjustment seconds Objects III Transaction
	1070	POST, TYPE CL, 50 FT. ARM OR 15.2 M ARM	Construction Stockpile STMI	- Total	23	Jul 18, 2022	SYSTEM	\$9,703.63 \$9,703.63	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		TMI_Total			\$9,703.63	
	1070	Total	Construction	- Stockpile S	rwii - Total			\$9,703.63	
	1070 -	POST, TYPE C, 40			23	Jul 18, 2022	SYSTEM	\$7,599.34	Payment Estimate Item Adjustment generated Stockpile Transaction
		FT. ARM OR 12.2 S						\$7,599.34	
			Construction		TMI - Total			\$7,599.34	
								,1,000.04	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S1718	1075 -	· Total						\$7,599.34		
	1077	POST, TYPE B, LONGEST ARM 20 FT. OR 6.1	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$5,339.52	Payment Estimate Item Adjustment generated Stockpile Transaction	
		11.010.1		- Total				\$5,339.52		
			Construction	Stockpile S	MI - Total			\$5,339.52		
	1077 -	Total						\$5,339.52		
	1080	POST, TYPE BL, LONGEST ARM 35 FT. OR 10.	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$10,737.75	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$10,737.75		
			Construction	Stockpile S	「MI - Total			\$10,737.75		
	1080 -	· Total						\$10,737.75		
	1090	POST, TYPE BL, LONGEST ARM 55 FT.	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$15,812.56	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$15,812.56		
			Construction	Stockpile S	「MI - Total			\$15,812.56		
	1090 -	Total						\$15,812.56		
	1320	MISC.	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$23,505.66	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$23,505.66 \$23,505.66		
			Construction	nstruction Stockpile STMI - Total						
	1320 -	Total						\$23,505.66		
	1340	MISC.	Construction Stockpile		19	May 16, 2022	SYSTEM	(\$7.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
			- Total					(\$7.00)		
					Stockpile - 1	otal			(\$7.00)	
			Construction Stockpile STMI		18	May 2, 2022	SYSTEM	\$7.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
					19	May 16, 2022	SYSTEM	\$51,460.89	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$51,467.89		
			Construction	Stockpile S	MI - Total			\$51,467.89		
		· Total						\$51,460.89		
	1550	MISC. METAL PIPE	Overrun	Overrun	22	Jul 1, 2022	SYSTEM	(\$1,482.00)		
				Overrun - T	otal			(\$1,482.00)		
			Overrun - To	tal				(\$1,482.00)		
	1550 -	·Total						(\$1,482.00)		
	1590	15 IN. PIPE GROUP A	Overrun	Overrun		Jul 18, 2022	SYSTEM	(\$2,079.00)		
				Overrun - T	otal			(\$2,079.00)		
			Overrun - To	tal				(\$2,079.00)		
	1590 -	Total						(\$2,079.00)		
	1670	MISC. MANHOLES AND DROP INLETS	Material		14	Mar 1, 2022	SYSTEM	\$5,886.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schirj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	
					14	Mar 1, 2022	SYSTEM	(\$5,886.00)		
					15	Mar 16, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schirj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	
					15	Mar 16, 2022	SYSTEM	(\$7,848.00)	Examine Exception of on the outlotter ayment Estimate.	
					16	Apr 4, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment	
					16	Apr 4, 2022	SYSTEM	(\$7,848.00)	Estimate Exception 64 on the current Payment Estimate.	
					17	Apr 18, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 70 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J6S1718	1670	MISC. MANHOLES AND DROP	Material		17	Apr 18, 2022	SYSTEM	(\$7,848.00)																
		INLETS			18	May 2, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schirj1 overridding Payment Estimate Exception 71 on the current Payment Estimate.															
					18	May 2, 2022	SYSTEM	(\$7,848.00)																
					19	May 16, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.															
					19	May 16, 2022	SYSTEM	(\$7,848.00)																
					20	Jun 2, 2022	SYSTEM	\$7,848.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.															
					20	Jun 2, 2022	SYSTEM	(\$7,848.00)																
					21	Jun 16, 2022	SYSTEM	\$9,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.															
									21	Jun 16, 2022	SYSTEM	(\$9,810.00)												
					22	Jul 1, 2022	SYSTEM	\$9,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user steppr1 overridding Payment Estimate Exception 33 on the current Payment Estimate.															
					22	Jul 1, 2022	SYSTEM	(\$9,810.00)																
					23	Jul 18, 2022	SYSTEM	\$9,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.															
					23	Jul 18, 2022	SYSTEM	(\$9,810.00)																
					24	Aug 2, 2022	SYSTEM	\$9,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user steppr1 overridding Payment Estimate Exception 41 on the current Payment Estimate.															
					24	Aug 2, 2022	SYSTEM	(\$9,810.00)																
					25	Aug 16, 2022	SYSTEM	\$9,810.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.															
					25	Aug 16, 2022	SYSTEM	(\$9,810.00)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																
	1690	MISC. MANHOLES AND DROP INLETS	Material		22	Jul 1, 2022	SYSTEM	\$0.00 \$15,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user steppr1 overridding Payment Estimate Exception 35 on the current Payment Estimate.															
		INLLIS																		22	Jul 1, 2022	SYSTEM	(\$15,771.00)	Exemple Exemple of the outline aymone Estimate.
																			23	Jul 18, 2022	SYSTEM	\$15,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	
							23	Jul 18, 2022	SYSTEM	(\$15,771.00)	, , , , , , , , , , , , , , , , , , , ,													
																2	2	2	24	24	Aug 2, 2022	SYSTEM	\$15,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user steppr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
															24	24	Aug 2, 2022	SYSTEM	(\$15,771.00)					
					25	Aug 16, 2022	SYSTEM	\$15,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user schirj1 overridding Payment Estimate Exception 45 on the current Payment Estimate.															
					25	Aug 16, 2022	SYSTEM	(\$15,771.00)																
				- Total				\$0.00																
			Material - Tot	tal				\$0.00																



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J6S1718	1690 -	- Total						\$0.00															
	1850	WATER - UTILITY ITEM	Material		7	Nov 15, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					7	Nov 15, 2021	SYSTEM	(\$100.00)															
					8	Dec 2, 2021	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.														
					8	Dec 2, 2021	SYSTEM	(\$100.00)															
					9	Dec 16, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					9	Dec 16, 2021	SYSTEM	(\$400.00)															
					10	Jan 3, 2022	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
					10	Jan 3, 2022	SYSTEM	(\$500.00)	Estimate Estapator 10 of the carrotter ayricht Estimate.														
				- Total		2022		\$0.00															
			Material - To					\$0.00															
	1850 -	- Total						\$0.00															
	1860	- Total WATER - UTILITY ITEM	Material		16	Apr 4, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
											16	Apr 4, 2022	SYSTEM	(\$4,859.00)									
						17	Apr 18, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.													
					17	Apr 18, 2022	SYSTEM	(\$4,859.00)															
					18	May 2, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.														
					18	May 2, 2022	SYSTEM	(\$4,859.00)															
					19	May 16, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.														
					19	May 16, 2022	SYSTEM	(\$4,859.00)															
																	20	Jun 2, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
					20	Jun 2, 2022	SYSTEM	(\$4,859.00)															
									21	Jun 16, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
					21	Jun 16, 2022	SYSTEM	(\$4,859.00)															
				2	2	22 22 23							;				;		22	Jul 1, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
							22	Jul 1, 2022	SYSTEM	(\$4,859.00)													
															5		23	Jul 18, 2022	SYSTEM	\$4,859.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.		
					23	Jul 18, 2022	SYSTEM	(\$4,859.00)															
					24	Aug 2, 2022	SYSTEM	\$38,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user steppr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S1718	1860	WATER - UTILITY ITEM	Material		24	Aug 2, 2022	SYSTEM	(\$38,872.00)		
					25	Aug 16, 2022	SYSTEM	\$38,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0078) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					25	Aug 16, 2022	SYSTEM	(\$38,872.00)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	1860 -	Total						\$0.00		
	1910	MISC.	Construction Stockpile		25	Aug 16, 2022	SYSTEM	(\$9,984.32)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$9,984.32)		
			Construction	Stockpile - 1	Total			(\$9,984.32)		
			Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$9,984.32	Payment Estimate Item Adjustment generated Stockpile Transaction	
			OTIVII	- Total				\$9,984.32		
			Construction	Stockpile S1	TMI - Total			\$9,984.32		
			Material		25	Aug 16, 2022	SYSTEM	\$12,464.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user schirj1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	
					25	Aug 16, 2022	SYSTEM	(\$12,464.00)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	1910 -	Total						\$0.00		
	1920	MISC.	Construction Stockpile		25	Aug 16, 2022	SYSTEM	(\$5,428.10)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				(\$5,428.10)		
			Construction	Stockpile - 1	Γotal			(\$5,428.10)		
			Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$10,856.20	Payment Estimate Item Adjustment generated Stockpile Transaction	
			O T IVII	- Total				\$10,856.20		
			Construction	ı Stockpile STMI - Total				\$10,856.20		
			Material	Material		25	Aug 16, 2022	SYSTEM	\$6,604.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0080) due to user schirj1 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$6,604.00)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	1920 -	Total						\$5,428.10		
	1930	MISC.	Material		25	Aug 16, 2022	SYSTEM	\$6,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0081) due to user schirj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	
					25	Aug 16, 2022	SYSTEM	(\$6,900.00)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	1930 -							\$0.00		
	1950	MISC.	Material		25	Aug 16, 2022	SYSTEM	\$2,979.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0082) due to user schirj1 overridding Payment Estimate Exception 53 on the current Payment Estimate.	
					25	Aug 16, 2022	SYSTEM	(\$2,979.00)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	1950 -	Total						\$0.00		
	1990	MISC.	Material		25	Aug 16, 2022	SYSTEM	\$3,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0083) due to user schirj1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718	1990	MISC.	Material	Туре	25	Aug 16,	SYSTEM	(\$3,400.00)	
						2022		00.00	
			Material - Tot	- Total				\$0.00 \$0.00	
	1990 -	Total	Wateriai - 10	lai				\$0.00	
	2000	MISC.	Material		25	Aug 16, 2022	SYSTEM	\$4,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0084) due to user schirj1 overridding Payment Estimate Exception 55 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$4,600.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2000 -	Total						\$0.00	
	2020	MISC.	Material		25	Aug 16, 2022	SYSTEM	\$5,145.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0085) due to user schirj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$5,145.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2020 -							\$0.00	
	2030) MISC.	Material		25	Aug 16, 2022	SYSTEM	\$5,268.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0086) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$5,268.00)	
				- Total				\$0.00	
	0000		Material - Tot	tal				\$0.00	
	2030 - 2040	MISC.	Material		25	Aug 16, 2022	SYSTEM	\$0.00 \$3,063.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0087) due to user schirj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$3,063.00)	Zamato Zaoptonoso an ale canonin ayrion Zamato.
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	2040 -	Total						\$0.00	
	2050	MISC.	Material		25	Aug 16, 2022	SYSTEM	\$3.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0088) due to user schirj1 overridding Payment Estimate Exception 59 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$3.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	2050 - 2110	Total MISC.	Construction Stockpile		25	Aug 16, 2022	SYSTEM	\$0.00 (\$3,678.99)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stookbile	- Total		2022		(\$3,678.99)	
			Construction		Γota <u>l</u>			(\$3,678.99)	
			Construction Stockpile		18	May 2, 2022	SYSTEM	\$3,610.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI		19	May 16, 2022	SYSTEM	\$1,290.79	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$4,900.79	
			Construction	Stockpile S	ΓΜΙ - Total			\$4,900.79	
			Material		25	Aug 16, 2022	SYSTEM	\$4,200.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0089) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$4,200.50)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J6S1718	2110	MISC.	Material - To	tal				\$0.00				
	2110 -	Total						\$1,221.80				
	2120	MISC.	Material		25	Aug 16, 2022	SYSTEM	\$12,740.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0090) due to user schirj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.			
					25	Aug 16, 2022	SYSTEM	(\$12,740.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	2120 -	Total						\$0.00				
	2210	TYPE D BARRIER	Material		20	Jun 2, 2022	SYSTEM	\$18,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.			
					20	Jun 2, 2022	SYSTEM	(\$18,900.00)				
					21	Jun 16, 2022	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.			
					21	Jun 16, 2022	SYSTEM	(\$37,940.00)				
					22	Jul 1, 2022	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user steppr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
						22	Jul 1, 2022	SYSTEM	(\$37,940.00)			
					23	Jul 18, 2022	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.			
					23	Jul 18, 2022	SYSTEM	(\$37,940.00)				
					24	Aug 2, 2022	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user steppr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
					24	Aug 2, 2022	SYSTEM	(\$37,940.00)				
					25	Aug 16, 2022	SYSTEM	\$37,940.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0091) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			
					25	Aug 16, 2022	SYSTEM	(\$37,940.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
	2210 -	Total						\$0.00				
	2220	SIDEWALK (BRIDGES)	Material		19	May 16, 2022	SYSTEM	\$19,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schirj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.			
							19	May 16, 2022	SYSTEM	(\$19,125.00)		
						20	Jun 2, 2022	SYSTEM	\$19,125.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.		
								20	Jun 2, 2022	SYSTEM	(\$19,125.00)	
								21	Jun 16, 2022	SYSTEM	\$38,403.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$38,403.00)				
					22	Jul 1, 2022	SYSTEM	\$38,403.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user steppr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.			
					22	Jul 1, 2022	SYSTEM	(\$38,403.00)				
					23	Jul 18, 2022	SYSTEM	\$38,403.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user schirj1 overridding Payment Estimate Exception 20 on the current Payment Estimate.			



Material 1-Total	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
2002	J6S1718	2220		Material		23		SYSTEM	(\$38,403.00)							
2002 25 Aug 140, SYSTEM 338,403.00 This adjustment offers the original system-generated Material Payment Ediminal Ethnological State user activity resembled. Material Payment Ediminal Ethnological State user activity resembled. Similar Ediminals Ethnological State user activity resembled. Similar Ediminals Ethnological State user activity resembled. Similar Ediminals Ethnological State user activity resembled. Similar Ethnological State on the outroit Payment Ediminals Ethnological State on the outroit Payment Edimals Ethnological State on the outroit Payment Ediminals Ethn						24		SYSTEM	\$38,403.00	Estimate Item Adjustment (0032) due to user steppr1 overridding Payment						
2002 25						24	Aug 2, 2022	SYSTEM	(\$38,403.00)							
2220 Total 2220 Material - Total 2220 May 16, SYSTEM 2022 2220 Total 2220						25		SYSTEM	\$38,403.00	Estimate Item Adjustment (0092) due to user schirj1 overridding Payment						
Material - Total 19						25		SYSTEM	(\$38,403.00)							
19					- Total				\$0.00							
Page				Material - Tot	tal				\$0.00							
REPAIR		2220 -	Total						\$0.00							
Total Second Se		2230		Material		19		SYSTEM	\$487.50	Estimate Item Adjustment (0038) due to user schirj1 overridding Payment						
Material - Total						19		SYSTEM	(\$487.50)							
Overrun Overrun 21 Jun 16, 2922 (57,150.00)					- Total				\$0.00							
2002				Material - Tot	tal				\$0.00							
2230 - Total 2240 OPEN CELL FOAM Material 20 Jun 2, 275TEM \$6,930.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 33 on the current Payment Estimate Exception 26 on the current Payment Estimate Exception 27 on the current Payment Estimate Exception 27 on the current Payment Estimate Exception 28 on the current Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI				Overrun	Overrun	21		SYSTEM	(\$7,150.00)							
2230 - Total					Overrun - T	otal			(\$7,150.00)							
240 OPEN CELL FOAM Material 20 Jun 2 2022 SYSTEM \$6,930.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (020) due to user schipt overridding Payment Estimate Exception 33 on the current Payment Estimate Payment Estimate Exception 33 on the current Payment Estimate Payment Estimate Exception 33 on the current Payment Estimate Payment Estimate Exception 28 on the current Payment Estimate Exception 28				Overrun - To	tal				(\$7,150.00)							
JOINT SEAL 2022 SYSTEM (\$6,930.00) 2022 SYSTEM (\$6,930.00) 21 Jun 16, 2022 SYSTEM (\$10,318.00) 2240 - Total 2290 GALVANIZED STRUCTURAL STEEL PILES [12] NO Construction Stockpile - Total 2290 Construction Stockpile - Total 2290 Construction Stockpile - Total 2290 STRUCTURAL STEEL PILES [12] NO Construction Stockpile - Total 2290 Construction Stockpile - Total 2290 STMI Total 2290 STMI SYSTEM (\$10,393.50) 2022 SYSTEM SYSTE		2230 -	Total						(\$7,150.00)							
2022 21 Jun 16, 2022 21 Jun 16, 2022 22 Jun 16, 2022 23 Jun 16, 2022 24 Jun 16, 2022 25 Jun 16,			OPEN CELL FOAM	Material		20		SYSTEM	\$6,930.00	Estimate Item Adjustment (0029) due to user schirj1 overridding Payment						
2022 Estimate Item Adjustment (0065) due to user schijf overridding Payment Estimate Exception 28 on the current Payment Estimate.						20		SYSTEM	(\$6,930.00)							
Construction Stockpile Transaction Stockpile Tra						21		SYSTEM	\$10,318.00	Estimate Item Adjustment (0065) due to user schirj1 overridding Payment						
Material - Total S0.00						21		SYSTEM	(\$10,318.00)							
2240 - Total 2290 GALVANIZED STRUCTURAL STEEL PILES (12 IN Construction Stockpile - Total Construction Stockpile 12 Feb 1, 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022 2022 2011 2022					- Total				\$0.00							
230 GALVANIZED STRUCTURAL STEEL PILES (12 IN STEEL				Material - Tot	al				\$0.00							
STRUCTURAL STEEL PILES 12 1 1 1 1 1 1 1 1		2240 -	Total						\$0.00							
Construction Stockpile - Total Construction Stockpile 12 Feb 1, 2022 SYSTEM \$17,993.50 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$17,993.50 Construction Stockpile STMI - Total \$17,993.50 Material 21 Jun 16, 2022 SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 21 Jun 16, SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate Item Adjustment (0026) due to user schirj1 overridding Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 22 Jul 1, 2022 SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 23 Jul 18, SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 23 Jul 18, SYSTEM \$52,026.00 Stockpoole Stockpo		2290	STRUCTURAL			21		SYSTEM	(\$17,993.50)	Payment Estimate Item Adjustment generated Stockpile Transaction						
Construction Stockpile STMI 12 Feb 1, 2022 \$YSTEM \$17,993.50 Payment Estimate Item Adjustment generated Stockpile Transaction Construction Stockpile STMI - Total \$17,993.50 Material 21 Jun 16, 2022 \$YSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Item Adjustment (0076) due to user schirj1 overridding Payment Item Adju					- Total				(\$17,993.50)							
Stockpile STMI - Total \$17,993.50				Construction	Stockpile - 1	Γotal			(\$17,993.50)							
Construction Stockpile STMI - Total \$17,993.50				Stockpile		12		SYSTEM	\$17,993.50	Payment Estimate Item Adjustment generated Stockpile Transaction						
Material 21 Jun 16, 2022 SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. 21 Jun 16, 2022 22 Jul 1, 2022 SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 22 Jul 1, 2022 SYSTEM \$52,026.00 23 Jul 18, SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 16 on the current Payment Estimate. 23 Jul 18, SYSTEM \$52,026.00 This adjustment (0026) due to user steppr1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 24 Jul 18, SYSTEM \$52,026.00 SYSTEM \$52,026.00 This adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.																
Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 21 on the current Payment Estimate. 21				Construction	Stockpile ST	ΓMI - Total			\$17,993.50							
22 Jul 1, 2022 SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 22 Jul 1, 2022 SYSTEM (\$52,026.00) 23 Jul 18, 2022 SYSTEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 23 Jul 18, SYSTEM (\$52,026.00)				Material		21		SYSTEM	\$52,026.00	Estimate Item Adjustment (0066) due to user schirj1 overridding Payment						
2022 Estimate Item Adjustment (0026) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate. 22 Jul 1, 2022 23 Jul 18, 29STEM \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 23 Jul 18, SYSTEM (\$52,026.00)						21		SYSTEM	(\$52,026.00)							
23 Jul 18, 2022 System \$52,026.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 23 Jul 18, System (\$52,026.00)						22		SYSTEM	\$52,026.00	Estimate Item Adjustment (0026) due to user steppr1 overridding Payment						
2022 Estimate Item Adjustment (0076) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate. 23 Jul 18, SYSTEM (\$52,026.00)						22		SYSTEM	(\$52,026.00)							
						23		SYSTEM	\$52,026.00	Estimate Item Adjustment (0076) due to user schirj1 overridding Payment						
(23	Jul 18, 2022	SYSTEM	(\$52,026.00)	



STELL PILES N	roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
24 2022 275TEM 352,026.00 1761 adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Esti	6S1718	2290	STRUCTURAL STEEL PILES (12	Material		24		SYSTEM	\$52,026.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user steppr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
2022 25			IIV			24		SYSTEM	(\$52,026.00)															
2007 Total						25		SYSTEM	\$52,026.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0093) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.														
						25		SYSTEM	(\$52,026.00)															
2310 PILE POINT Stockpile 21 Jun 16, SYSTEM (31,050,00) Payment Estimate Item Adjustment generated Stockpile Transaction 12 Feb 1, SYSTEM (31,050,00) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total STOCKPILE SYSTEM STOCKPILE					- Total				\$0.00															
PILE POINT Construction Shodquis -Total (\$1,050.00) Payment Estimate Item Adjustment generated Stockpile Transaction (\$1,050.00)				Material - Tot	tal				\$0.00															
Total		2290 -	Total						\$0.00															
Construction Stockpile - Total SYSTEM S1,050.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STM		2310				21		SYSTEM	(\$1,050.00)	Payment Estimate Item Adjustment generated Stockpile Transaction														
Construction 12					- Total				(\$1,050.00)															
Stockpile STM - Total S1,050,00				Construction	Stockpile - 1	Γotal			(\$1,050.00)															
Construction Stockple STMI - Total				Stockpile		12		SYSTEM	\$1,050.00	Payment Estimate Item Adjustment generated Stockpile Transaction														
Material 21				O I IVII	- Total				\$1,050.00															
2022 Estimate Item Adjustment (0067) due to user schift overridding Paym Estimate Exception 23 on the current Payment Estimate.				Construction	Stockpile S	TMI - Total			\$1,050.00															
2022 South				Material	Material	21		SYSTEM	\$4,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.														
Solid Soli						21		SYSTEM	(\$4,200.00)															
2310 - Total 2320 CLASS B CONCRETE (SUBSTRUCTURE)					- Total				\$0.00															
2320 CLASS B CONCRETE (SUBSTRUCTURE) Material CONCRETE (SUBSTRUCTURE) 2022 2			tal				\$0.00																	
CONCRETE (SUBSTRUCTURE) 2022 Estimate Item Adjustment (0027) due to user steppr1 overridding Payr Estimate Exception 18 on the current Payment Estimate.		2310 -	Total						\$0.00															
2022		2320	CONCRETE	Material		22		SYSTEM	\$65,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user steppr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.														
2022 Estimate Item Adjustment (0077) due to user schirj1 overridding Paym Estimate Exception 17 on the current Payment Estimate.						22		SYSTEM	(\$65,884.00)															
2022 24 Aug 2, 2022 24 Aug 2, 2022 25 Aug 16, 2022 26 Aug 16, 2022 27 SYSTEM \$65,884.00 28 SYSTEM \$65,884.00 29 SYSTEM \$65,884.00 2022 2022 21 Aug 16, 2022 22 Aug 16, 2022 23 Aug 16, 2022 24 Aug 2, 2022 25 Aug 16, 2022 26 Aug 16, 2022 27 Aug 16, 2022 28 SYSTEM \$65,884.00 29 SYSTEM \$65,884.00 2022 29 Aug 16, 2022 2020 2020 2020 2020 2020 2020 202									23		SYSTEM	\$65,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
Estimate Item Adjustment (0034) due to user steppr1 overridding Payle Estimate Exception 18 on the current Payment Estimate. 24						23		SYSTEM	(\$65,884.00)															
2022 25						24		SYSTEM	\$65,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user steppr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.														
Estimate Item Adjustment (0094) due to user schirj1 overridding Paym Estimate Exception 19 on the current Payment Estimate. 25 Aug 16, 2022 \$0.00 Naterial - Total \$0.00 \$0.00 SLAB ON CONCRETE NU-GIRDER						24		SYSTEM	(\$65,884.00)															
2320 - Total S0.00 2320 - Total S0.00 2320 - Total S0.00 2340 SLAB ON CONCRETE NU-GIRDER 24 Aug 2, 2022 SYSTEM \$194,400.00 24 Aug 2, 2022 SYSTEM \$194,400.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0035) due to user steppr1 overridding Payre Estimate Exception 21 on the current Payment Estimate. 24 Aug 2, 2022 25 Aug 16, SYSTEM \$410,400.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0																				25		SYSTEM	\$65,884.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0094) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
Total S0.00 2320 - Total SLAB ON CONCRETE NU-GIRDER Aug 2, 2022 Aug 2, 2022 SYSTEM \$194,400.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0035) due to user steppr1 overridding Payme Estimate Exception 21 on the current Payment Estimate. 24 Aug 2, 2022 SYSTEM \$194,400.00 This adjustment offsets the original system-generated Material Payment Estimate. 25 Aug 16, SYSTEM \$410,400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adj						25		SYSTEM	(\$65,884.00)															
Substitute Sub					- Total				\$0.00															
2320 - Total SLAB ON CONCRETE NU-GIRDER 24 Aug 2, 2022 SYSTEM \$194,400.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0035) due to user steppr1 overridding Payre Estimate Exception 21 on the current Payment Estimate. 24 Aug 2, 2022 SYSTEM \$194,400.00) This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Estimate Item Adjustment (0095) due to user schirj1 overridding Payment Item Adjust				Mater <u>ial - To</u> t																				
2340 SLAB ON CONCRETE NU-GIRDER 24 Aug 2, 2022 SYSTEM \$194,400.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0035) due to user steppr1 overridding Payme Estimate Exception 21 on the current Payment Estimate. 24 Aug 2, 2022 SYSTEM (\$194,400.00) 25 Aug 16, 2022 SYSTEM \$410,400.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Payme Item Adjustment (0095) due to use		2320 -	Total																					
24 Aug 2, 2022 25 Aug 16, 2022 25 Aug 16, 2022 26 Estimate Item Adjustment (0095) due to user schirj1 overridding Payme			SLAB ON CONCRETE NU-	Material		24		SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user steppr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
25 Aug 16, SYSTEM \$410,400.00 This adjustment offsets the original system-generated Material Payme Estimate Item Adjustment (0095) due to user schirj1 overridding Paym						24	Aug 2,	SYSTEM	(\$194,400.00)	. , , , , , , , , , , , , , , , , , , ,														
Estimate exception 22 on the current Payment Estimate.						25	Aug 16,	SYSTEM	\$410,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0095) due to user schirjf overridding Payment Estimate Execution 22 on the current Payment Estimate.														
25 Aug 16, SYSTEM (\$410,400.00)						25		SYSTEM	(\$410,400.00)	Estimate Exception 22 on the current Payment Estimate.														
- Total \$0.00					- Total		2022		\$0.00															
Material - Total \$0.00				Material Tes																				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J6S1718	2340 -	· Total						\$0.00		
	2380	STEEL INTERMEDIATE DIAPHRAGM FOR	Material		24	Aug 2, 2022	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user steppr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	
		P/S CON			24	Aug 2, 2022	SYSTEM	(\$3,600.00)		
					25	Aug 16, 2022	SYSTEM	\$3,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0096) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					25	Aug 16, 2022	SYSTEM	(\$3,600.00)	Estimate Estaplica Estapli	
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	2380 -	· Total						\$0.00		
	2390	SLAB DRAIN	Material		24	Aug 2, 2022	SYSTEM	\$2,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user steppr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.	
					24	Aug 2, 2022	SYSTEM	(\$2,880.00)		
					25	Aug 16, 2022	SYSTEM	\$2,880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0097) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
					25	Aug 16, 2022	SYSTEM	(\$2,880.00)		
				- Total				\$0.00		
			Material - Tot	al				\$0.00		
	2390 - Total	Total						\$0.00		
	2410	LAMINATED NEOPRENE BEARING PAD	Construction Stockpile		12	Feb 1, 2022	SYSTEM	\$6,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
		BEARING PAD (TAPERED)	STMI	- Total				\$6,600.00		
			Construction	Stockpile S	ΓΜΙ - Total			\$6,600.00		
	2410 -	· Total						\$6,600.00		
J6S1718 - 1	Total							\$235,523.07		
J6S1718B	2450	0 REMOVAL OF MISCELLANEOUS	ANEOUS	Overrun Overrur	Overrun	1	Aug 16, 2021	SYSTEM	(\$215.00)	
		ACM NON- FRIABLE			2	Sep 1, 2021	SYSTEM	(\$4,868.89)		
					4	Oct 1, 2021	SYSTEM	\$5,083.89	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4.30000 - 4.30000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - To	al				\$0.00		
	2450 -	Total						\$0.00		
	2470	REMOVAL OF FLOOR SHEETING ACM ON WOOD	Overrun	Overrun		Aug 16, 2021	SYSTEM	(\$780.00)		
					4	Oct 1, 2021	SYSTEM	\$780.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',19.50000 - 19.50000, 'is applied (if non-zero).	
				Overrun - T	otal			\$0.00		
			Overrun - To	tal				\$0.00		
	2470 -	· Total						\$0.00		
	2510	EMBANKMENT IN PLACE	Material		25	Aug 16, 2022	SYSTEM	\$1,742.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	
					25	Aug 16, 2022	SYSTEM	(\$1,742.40)		
			- Total					\$0.00		
			Material - Tot	al				\$0.00		
	2510 -	· Total						\$0.00		
	2590	TYPE 5 AGGREGATE FOR BASE	Material		10	Jan 3, 2022	SYSTEM	\$1,328.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	2590	TYPE 5 AGGREGATE FOR	Material		10	Jan 3, 2022	SYSTEM	(\$1,328.04)	
		BASE			11	Jan 18, 2022	SYSTEM	\$3,194.73	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Jan 18, 2022	SYSTEM	(\$3,194.73)	
					12	Feb 1, 2022	SYSTEM	\$7,126.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Feb 1, 2022	SYSTEM	(\$7,126.56)	
					13	Feb 16, 2022	SYSTEM	\$7,126.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$7,126.56)	
					14	Mar 1, 2022	SYSTEM	\$7,126.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Mar 1, 2022	SYSTEM	(\$7,126.56)	
					15	Mar 16, 2022	SYSTEM	\$7,126.56	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$7,126.56)	
					16	Apr 4, 2022	SYSTEM	\$11,266.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$11,266.42)	
					17	Apr 18, 2022	SYSTEM	\$12,498.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$12,498.44)	
					18	May 2, 2022	SYSTEM	\$14,427.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$14,427.38)	
					19	May 16, 2022	SYSTEM	\$15,278.51	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$15,278.51)	
					20	Jun 2, 2022	SYSTEM	\$18,088.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$18,088.75)	
					21	Jun 16, 2022	SYSTEM	\$21,935.91	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schirj1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$21,935.91)	
			Material - To	- Total				\$0.00 \$0.00	
	2590 -	Total	material - 10					\$0.00	
	2680	CONCRETE PAVEMENT (7 IN. NON-REINF)	Material		17	Apr 18, 2022	SYSTEM	\$2,689.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$2,689.28)	
					18	May 2, 2022	SYSTEM	\$2,689.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J6S1718B	2680	CONCRETE PAVEMENT (7 IN.	Material	Турс	18	May 2, 2022	SYSTEM	(\$2,689.28)														
		NON-REINF)			19	May 16, 2022	SYSTEM	\$6,704.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					19	May 16, 2022	SYSTEM	(\$6,704.72)														
					20	Jun 2, 2022	SYSTEM	\$6,704.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					20	Jun 2, 2022	SYSTEM	(\$6,704.72)	·													
					21	Jun 16, 2022	SYSTEM	\$28,585.04	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schirj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.													
					21	Jun 16, 2022	SYSTEM	(\$28,585.04)														
							22	Jul 1, 2022	SYSTEM	\$45,776.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					22	Jul 1, 2022	SYSTEM	(\$45,776.72)														
							23	Jul 18, 2022	SYSTEM	\$45,776.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
																	23	Jul 18, 2022	SYSTEM	(\$45,776.72)		
								24	Aug 2, 2022	SYSTEM	\$45,776.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
							24	Aug 2, 2022	SYSTEM	(\$45,776.72)												
					25	Aug 16, 2022	SYSTEM	\$51,482.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user schirj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.													
					25	Aug 16, 2022	SYSTEM	(\$51,482.64)														
			Material - Tot	- Total				\$0.00 \$0.00														
	2680 -	Total	Material - 10	lai				\$0.00														
	2690	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		16	Apr 4, 2022	SYSTEM	\$13,236.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.													
					16	Apr 4, 2022	SYSTEM	(\$13,236.44)														
																		17	Apr 18, 2022	SYSTEM	\$13,236.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
																	17	Apr 18, 2022	SYSTEM	(\$13,236.44)		
					18	May 2, 2022	SYSTEM	\$13,236.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.													
																	18	May 2, 2022	SYSTEM	(\$13,236.44)		
													19	May 16, 2022	SYSTEM	\$13,236.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.					
						:		19								1	19	May 16, 2022	SYSTEM	(\$13,236.44)		
									20	Jun 2, 2022	SYSTEM	\$38,815.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.									
							20	Jun 2, 2022	SYSTEM	(\$38,815.52)												
			- Total					\$0.00														
			Material - To	tal				\$0.00														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	2690 -	- Total						\$0.00	
	2770	TRUNCATED DOMES	Overrun	Overrun	16	Apr 4, 2022	SYSTEM	(\$219.60)	
					18	May 2, 2022	SYSTEM	(\$540.00)	
					19	May 16, 2022	SYSTEM	(\$360.00)	
					24	Aug 2, 2022	SYSTEM	(\$360.00)	
				Overrun - T	otal			(\$1,479.60)	
			Overrun - To	tal				(\$1,479.60)	
	2770 -	- Total						(\$1,479.60)	
	2820	MISC. CONCRETE	Material		10	Jan 3, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					10	Jan 3, 2022	SYSTEM	(\$5,000.00)	
					11	Jan 18, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					11	Jan 18, 2022	SYSTEM	(\$5,000.00)	
					12	Feb 1, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					12	Feb 1, 2022	SYSTEM	(\$5,000.00)	
					13	Feb 16, 2022	SYSTEM	\$5,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					13	Feb 16, 2022	SYSTEM	(\$5,000.00)	
					14	Mar 1, 2022	SYSTEM	\$7,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					14	Mar 1, 2022	SYSTEM	(\$7,500.00)	
					15	Mar 16, 2022	SYSTEM	\$7,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$7,500.00)	
					16	Apr 4, 2022	SYSTEM	\$17,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$17,500.00)	
					17	Apr 18, 2022	SYSTEM	\$17,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$17,500.00)	·
					18	May 2, 2022	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$20,000.00)	
					19	May 16, 2022	SYSTEM	\$22,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$22,500.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	2820	- Total						\$0.00	
	2880	MISC. CONCRETE	Material		16	Apr 4,	SYSTEM	\$57,453.54	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6S1718B	2880	MISC. CONCRETE	Material			2022			Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.									
					16	Apr 4, 2022	SYSTEM	(\$57,453.54)										
					17	Apr 18, 2022	SYSTEM	\$63,063.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.									
					17	Apr 18, 2022	SYSTEM	(\$63,063.54)										
					18	May 2, 2022	SYSTEM	\$73,473.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.									
					18	May 2, 2022	SYSTEM	(\$73,473.66)										
					19	May 16, 2022	SYSTEM	\$76,515.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 32 on the current Payment Estimate.									
					19	May 16, 2022	SYSTEM	(\$76,515.64)										
					20	Jun 2, 2022	SYSTEM	\$24,211.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schirj1 overridding Payment Estimate Exception 18 on the current Payment Estimate.									
					20	Jun 2, 2022	SYSTEM	(\$24,211.50)										
					21	Jun 16, 2022	SYSTEM	\$24,211.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.									
					21	Jun 16, 2022	SYSTEM	(\$24,211.50)										
														22	Jul 1, 2022	SYSTEM	\$25,250.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$25,250.20)										
					23	Jul 18, 2022	SYSTEM	\$25,250.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
					23	Jul 18, 2022	SYSTEM	(\$25,250.20)										
					24	Aug 2, 2022	SYSTEM	\$37,455.52	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					24	Aug 2, 2022	SYSTEM	(\$37,455.52)										
										25	Aug 16, 2022	SYSTEM	\$48,018.64	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.				
					25	Aug 16, 2022	SYSTEM	(\$48,018.64)										
				- Total				\$0.00										
	2000	Total	Material - Tot	al				\$0.00										
	2910	- Total CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		17	Apr 18, 2022	SYSTEM	\$0.00 \$1,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.									
		,			17	Apr 18, 2022	SYSTEM	(\$1,134.00)										
					18	May 2, 2022	SYSTEM	\$1,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.									
					18	May 2, 2022	SYSTEM	(\$1,134.00)										
					19	May 16, 2022	SYSTEM	\$1,134.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.									
					19	May 16, 2022	SYSTEM	(\$1,134.00)										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6S1718B	2910	CONCRETE CURB (6 IN. HEIGHT AND	Material	- Total				\$0.00									
		UNDER)	Material - To	tal				\$0.00									
	2910 -	- Total						\$0.00									
	2930	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		16	Apr 4, 2022	SYSTEM	\$1,165.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.								
					16	Apr 4, 2022	SYSTEM	(\$1,165.50)									
					17	Apr 18, 2022	SYSTEM	\$1,165.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.								
					17	Apr 18, 2022	SYSTEM	(\$1,165.50)									
					18	May 2, 2022	SYSTEM	\$1,165.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.								
					18	May 2, 2022	SYSTEM	(\$1,165.50)									
					20	20	Jun 2, 2022	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 19 on the current Payment Estimate.							
					20	Jun 2, 2022	SYSTEM	(\$3,108.00)									
				- Total				\$0.00									
	2930 - Total	Material - To	tal				\$0.00										
							\$0.00										
	2940	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material		21	Jun 16, 2022	SYSTEM	\$3,895.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
							21	Jun 16, 2022	SYSTEM	(\$3,895.00)							
					22	Jul 1, 2022	SYSTEM	\$4,968.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
				22	22	Jul 1, 2022	SYSTEM	(\$4,968.50)									
					23	Jul 18, 2022	SYSTEM	\$4,968.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user schirj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.								
					23	Jul 18, 2022	SYSTEM	(\$4,968.50)									
					24	Aug 2, 2022	SYSTEM	\$4,968.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
					24	Aug 2, 2022	SYSTEM	(\$4,968.50)									
					25	Aug 16, 2022	SYSTEM	\$4,968.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
					25	Aug 16, 2022	SYSTEM	(\$4,968.50)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
		- Total						\$0.00									
	3060	CLASS B CONCRETE (SUBSTRUCTURE)	Material		22	Jul 1, 2022	SYSTEM	\$14,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user steppr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					22	Jul 1, 2022	SYSTEM	(\$14,300.00)									
					23	Jul 18, 2022	SYSTEM	\$14,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.								
					23	Jul 18, 2022	SYSTEM	(\$14,300.00)									
													24	Aug 2, 2022	SYSTEM	\$14,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6S1718B	3060	CLASS B	Material						Estimate Exception 17 on the current Payment Estimate.									
		CONCRETE (SUBSTRUCTURE)			24	Aug 2, 2022	SYSTEM	(\$14,300.00)										
					25	Aug 16, 2022	SYSTEM	\$14,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0055) due to user schirjf overridding Payment									
					25	Aug 16, 2022	SYSTEM	(\$14,300.00)	Estimate Exception 18 on the current Payment Estimate.									
				- Total				\$0.00										
			Material - Tot	al				\$0.00										
	3060 -	·Total						\$0.00										
	3130	REINFORCING STEEL (EPOXY COATED)	Material		22	Jul 1, 2022	SYSTEM	\$2,835.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user steppr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.									
					22	Jul 1, 2022	SYSTEM	(\$2,835.00)										
					23	Jul 18, 2022	SYSTEM	\$2,835.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.									
					23	Jul 18, 2022	SYSTEM	(\$2,835.00)										
					24	Aug 2, 2022	SYSTEM	\$2,835.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.									
				24	Aug 2, 2022	SYSTEM	(\$2,835.00)											
					25	Aug 16, 2022	SYSTEM	\$2,835.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0056) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.									
					25	Aug 16, 2022	SYSTEM	(\$2,835.00)										
				- Total				\$0.00										
			Material - Tot	al				\$0.00										
	3130 -	Total						\$0.00										
	3160	MECHANICALLY STABILIZED EARTH WALL SYS	Material		14	Mar 1, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schirj1 overridding Payment Estimate Exception 46 on the current Payment Estimate.									
					14	Mar 1, 2022	SYSTEM	(\$20,695.50)										
					15	Mar 16, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schirj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.									
					15	Mar 16, 2022	SYSTEM	(\$20,695.50)										
							_							16	Apr 4, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$20,695.50)										
												17	Apr 18, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.		
												1	1	1	17	Apr 18, 2022	SYSTEM	(\$20,695.50)
					18	May 2, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 66 on the current Payment Estimate.									
					18	May 2, 2022	SYSTEM	(\$20,695.50)										
					19	May 16, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 52 on the current Payment Estimate.									
					19	May 16, 2022	SYSTEM	(\$20,695.50)										
						20	Jun 2, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J6S1718B	3160	MECHANICALLY STABILIZED	Material		20	Jun 2, 2022	SYSTEM	(\$20,695.50)									
		EARTH WALL SYS			21	Jun 16, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.								
					21	Jun 16, 2022	SYSTEM	(\$20,695.50)									
					22	Jul 1, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user steppr1 overridding Payment Estimate Exception 25 on the current Payment Estimate.								
					22	Jul 1, 2022	SYSTEM	(\$20,695.50)									
					23	Jul 18, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.								
					23	Jul 18, 2022	SYSTEM	(\$20,695.50)									
					24	Aug 2, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.								
					24	Aug 2, 2022	SYSTEM	(\$20,695.50)									
					25	Aug 16, 2022	SYSTEM	\$20,695.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0057) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.								
					25	Aug 16, 2022	SYSTEM	(\$20,695.50)									
				- Total				\$0.00									
			Material - Tot	tal				\$0.00									
	3160 -	Total						\$0.00									
	3170	SELECT GRANULAR BACKFILL FOR STRUCTURAL	Material		25	Aug 16, 2022	SYSTEM	\$33,471.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.								
		01110010101	TOTAL		25	Aug 16, 2022	SYSTEM	(\$33,471.16)									
				- Total				\$0.00									
		_	Material - Tot	tal				\$0.00									
	3170 - 3610	Total CABLE-CONDUIT,	Construction		22	Iul 40	CVCTEM	\$0.00	Downsont Fetimete How Adjustment repeated Steeling Transaction								
	3010	1 IN., 2 CONDUCTORS	Construction Stockpile STMI		23	Jul 18, 2022	SYSTEM	\$18,692.09	Payment Estimate Item Adjustment generated Stockpile Transaction								
			0 1 11	- Total				\$18,692.09									
			Construction Material	і этоскріїе 5	15	Mar 16, 2022	SYSTEM	\$18,692.09 \$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schirj1 overridding Payment Estimate Exception 57 on the current Payment Estimate.								
					15	Mar 16, 2022	SYSTEM	(\$1,782.90)									
					16	Apr 4, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 68 on the current Payment Estimate.								
												16	16	Apr 4, 2022	SYSTEM	(\$1,782.90)	
					17	Apr 18, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 75 on the current Payment Estimate.								
					17	Apr 18, 2022	SYSTEM	(\$1,782.90)									
					18	May 2, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.								
				18	May 2, 2022	SYSTEM	(\$1,782.90)										
					19	May 16, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 60 on the current Payment Estimate.								
					19	May 16,	SYSTEM	(\$1,782.90)									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	3610	CABLE-CONDUIT,	Material			2022			
		1 IN., 2 CONDUCTORS			20	Jun 2, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$1,782.90)	
					21	Jun 16, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$1,782.90)	
					22	Jul 1, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user steppr1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$1,782.90)	
					23	Jul 18, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0058) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$1,782.90)	
					24	Aug 2, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$1,782.90)	
					25	Aug 16, 2022	SYSTEM	\$1,782.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$1,782.90)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	3610 -	Total						\$18,692.09	
	3680	MISC.	Construction Stockpile		23	Jul 18, 2022	SYSTEM	\$512.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$512.00	
			Construction	Stockpile S	MI - Total			\$512.00	
	3680 -	Total						\$512.00	
	3700	MISC.	Construction Stockpile		23				
						Jul 18, 2022	SYSTEM	\$5,417.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total			SYSTEM	\$5,417.80 \$5,417.80	Payment Estimate Item Adjustment generated Stockpile Transaction
						2022	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
	3700 -	·Total	STMI			2022	SYSTEM	\$5,417.80	Payment Estimate Item Adjustment generated Stockpile Transaction
	3700 - 3710	Total MISC.	Construction Construction Stockpile			2022	SYSTEM	\$5,417.80 \$5,417.80	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction Construction		「MI - Total	2022 Jul 18,		\$5,417.80 \$5,417.80 \$5,417.80	
			Construction Construction Stockpile	Stockpile ST	TMI - Total	Jul 18, 2022		\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55	
		MISC.	Construction Construction Stockpile STMI	Stockpile ST	TMI - Total	Jul 18, 2022		\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55 \$1,941.55	
	3710	MISC.	Construction Construction Stockpile STMI	Stockpile ST	TMI - Total	Jul 18, 2022		\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55 \$1,941.55	Payment Estimate Item Adjustment generated Stockpile Transaction
	3710 3710 -	MISC. Total SEWER - UTILITY	Construction Construction Stockpile STMI Construction Construction	Stockpile ST	MI - Total 23 MI - Total	Jul 18, 2022	SYSTEM	\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55 \$1,941.55 \$1,941.55 \$1,941.55	Payment Estimate Item Adjustment generated Stockpile Transaction
	3710 3710 -	MISC. Total SEWER - UTILITY	Construction Construction Stockpile STMI Construction Construction	Stockpile ST	23 IMI - Total	Jul 18, 2022 Mar 16, 2022 Apr 4,	SYSTEM	\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55 \$1,941.55 \$1,941.55 \$1,941.55 \$1,941.55 \$49,088.16)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	3710 3710 -	MISC. Total SEWER - UTILITY	Construction Construction Stockpile STMI Construction Construction	- Total - Total - Total	23 FMI - Total 15 16	Jul 18, 2022 Mar 16, 2022 Apr 4,	SYSTEM	\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55 \$1,941.55 \$1,941.55 \$1,941.55 \$49,088.16) (\$10,419.66)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	3710 3710 -	MISC. Total SEWER - UTILITY	Construction Construction Stockpile STMI Construction Construction Stockpile Construction Construction	- Total - Total - Total	23 FMI - Total 15 16	Jul 18, 2022 Mar 16, 2022 Apr 4,	SYSTEM	\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55 \$1,941.55 \$1,941.55 \$1,941.55 \$49,088.16) (\$10,419.66) (\$59,507.82)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	3710 3710 -	MISC. Total SEWER - UTILITY	Construction Construction Stockpile STMI Construction Construction Construction Construction Construction	- Total - Total - Total	23 TMI - Total 15 16	Jul 18, 2022 Mar 16, 2022 Apr 4, 2022 Nov 15,	SYSTEM SYSTEM	\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55 \$1,941.55 \$1,941.55 \$1,941.55 (\$49,088.16) (\$10,419.66) (\$59,507.82)	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	3710 3710 -	MISC. Total SEWER - UTILITY	Construction Construction Stockpile STMI Construction Construction Stockpile Construction Construction	- Total - Total Stockpile ST - Total Stockpile - Total	23 TMI - Total 15 16 Total 7	Jul 18, 2022 Mar 16, 2022 Apr 4, 2022 Nov 15, 2021	SYSTEM SYSTEM	\$5,417.80 \$5,417.80 \$5,417.80 \$1,941.55 \$1,941.55 \$1,941.55 \$1,941.55 (\$49,088.16) (\$10,419.66) (\$59,507.82) \$59,507.82	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	3840	SEWER - UTILITY	Material		15	Mar 16, 2022	SYSTEM	(\$175,324.00)	
					16	Apr 4, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schirj1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$212,539.00)	
					17	Apr 18, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$212,539.00)	
					18	May 2, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$212,539.00)	
					19	May 16, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$212,539.00)	
					20	Jun 2, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schirj1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$212,539.00)	
					21	Jun 16, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$212,539.00)	
					22	Jul 1, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user steppr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$212,539.00)	
					23	Jul 18, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$212,539.00)	
					24	Aug 2, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$212,539.00)	
					25	Aug 16, 2022	SYSTEM	\$212,539.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user schirj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$212,539.00)	
				- Total				\$0.00	
	3840 -	Total	Material - Tot	ar				\$0.00 \$0.00	
	3850	SEWER - UTILITY	Material		15	Mar 16,	SYSTEM	\$52,850.00	This adjustment offsets the original system-generated Material Payment
	2000	ITEM			15	Mar 16, 2022	SYSTEM	(\$52,850.00)	Estimate Item Adjustment (0007) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	2022	STOTEIVI	(ψυΣ,υυυ.υυ)	
					16	Apr 4, 2022	SYSTEM	\$52,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$52,850.00)	
					17	Apr 18, 2022	SYSTEM	\$52,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	3850	SEWER - UTILITY	Material		17	Apr 18, 2022	SYSTEM	(\$52,850.00)	
					18	May 2, 2022	SYSTEM	\$79,275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$79,275.00)	
					19	May 16, 2022	SYSTEM	\$79,275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$79,275.00)	
					20	Jun 2, 2022	SYSTEM	\$79,275.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schirj1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$79,275.00)	Example 2.00pton to on the carrotter symbol 20mate.
					21	Jun 16, 2022	SYSTEM	\$115,213.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$115,213.00)	
					22	Jul 1, 2022	SYSTEM	\$115,213.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$115,213.00)	
					23	Jul 18, 2022	SYSTEM	\$115,213.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$115,213.00)	
					24	Aug 2, 2022	SYSTEM	\$126,417.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$126,417.20)	
					25	Aug 16, 2022	SYSTEM	\$126,417.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user schirj1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$126,417.20)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	3860	Total SEWER - UTILITY ITEM	Material		24	Aug 2, 2022	SYSTEM	\$0.00 \$7,708.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user steppr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$7,708.00)	
					25	Aug 16, 2022	SYSTEM	\$7,708.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$7,708.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	3860 -	Total						\$0.00	
	3870	SEWER - UTILITY ITEM	Construction Stockpile		16	Apr 4, 2022	SYSTEM	(\$28,971.11)	Payment Estimate Item Adjustment generated Stockpile Transaction
					18	May 2, 2022	SYSTEM	(\$20,933.96)	Payment Estimate Item Adjustment generated Stockpile Transaction
					21	Jun 16, 2022	SYSTEM	(\$12,523.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					24	Aug 2, 2022	SYSTEM	(\$9,543.64)	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	3870	SEWER - UTILITY ITEM	Construction Stockpile	- Total				(\$71,971.71)	
			Construction	Stockpile - 1	otal			(\$71,971.71)	
			Construction Stockpile		10	Jan 3, 2022	SYSTEM	\$79,250.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$79,250.00	
			Construction	Stockpile S	MI - Total			\$79,250.00	
			Material		16	Apr 4, 2022	SYSTEM	\$66,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schirj1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$66,960.00)	
					17	Apr 18, 2022	SYSTEM	\$66,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$66,960.00)	
					18	May 2, 2022	SYSTEM	\$115,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					18	May 2, 2022	SYSTEM	(\$115,344.00)	
					19	May 16, 2022	SYSTEM	\$115,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schirj1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					19	May 16, 2022	SYSTEM	(\$115,344.00)	
					20	Jun 2, 2022	SYSTEM	\$115,344.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schirj1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					20	Jun 2, 2022	SYSTEM	(\$115,344.00)	
					21	Jun 16, 2022	SYSTEM	\$144,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schirj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$144,288.00)	
					22	Jul 1, 2022	SYSTEM	\$144,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user steppr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$144,288.00)	
					23	Jul 18, 2022	SYSTEM	\$144,288.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0061) due to user schirj1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$144,288.00)	
					24	Aug 2, 2022	SYSTEM	\$166,345.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user steppr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$166,345.92)	
					25	Aug 16, 2022	SYSTEM	\$166,345.92	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user schirj1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$166,345.92)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	3870 -	Total						\$7,278.29	
	4100	SEWER - RIGID PIPE	Material		24	Aug 2, 2022	SYSTEM	\$18,099.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user steppr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$18,099.20)	
					25	Aug 16, 2022	SYSTEM	\$18,099.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user schirj1 overridding Payment



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
1718B	4100	SEWER - RIGID PIPE	Material		0.5	A 40	OVOTERA	(0.40, 000, 00)	Estimate Exception 36 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$18,099.20)	
				- Total				\$0.00	
	4400	Total	Material - To	tal				\$0.00	
		Total	Material		04	lum 40	OVOTEM	\$0.00	This call to the control of the through the control of the control
	4110	SEWER - RIGID PIPE	Material		21	Jun 16, 2022	SYSTEM	\$3,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schirl 1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$3,380.00)	
					22	Jul 1, 2022	SYSTEM	\$3,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user steppr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$3,380.00)	
					23	Jul 18, 2022	SYSTEM	\$3,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user schirj1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$3,380.00)	
					24	Aug 2, 2022	SYSTEM	\$3,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user steppr1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$3,380.00)	
					25	Aug 16, 2022	SYSTEM	\$3,380.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$3,380.00)	Example Exception of the current symmetry
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	4110 -	Total						\$0.00	
	4130	SEWER - RIGID PIPE	Material		21	Jun 16, 2022	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user schirj1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					21	Jun 16, 2022	SYSTEM	(\$4,189.50)	
					22	Jul 1, 2022	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user steppr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					22	Jul 1, 2022	SYSTEM	(\$4,189.50)	
					23	Jul 18, 2022	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user schirj1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$4,189.50)	
					24	Aug 2, 2022	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user steppr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$4,189.50)	
					25	Aug 16, 2022	SYSTEM	\$4,189.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$4,189.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	4130 -	Total						\$0.00	
	4140	SEWER - RIGID PIPE	Material		21	Jun 16, 2022	SYSTEM	\$29,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user schirj1 overridding Payment Estimate Exception 35 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks																														
J6S1718B	4140	SEWER - RIGID PIPE	Material	Туре	21	Jun 16, 2022	SYSTEM	(\$29,866.00)																															
		FIFE			22	Jul 1, 2022	SYSTEM	\$29,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user steppr1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																														
					22	Jul 1, 2022	SYSTEM	(\$29,866.00)																															
					23	Jul 18, 2022	SYSTEM	\$29,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user schirj1 overridding Payment Estimate Exception 30 on the current Payment Estimate.																														
					23	Jul 18, 2022	SYSTEM	(\$29,866.00)	Estimate Exception 30 on the current Payment Estimate.																														
					24	Aug 2, 2022	SYSTEM	\$29,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user steppr1 overridding Payment																														
					24	Aug 2,	SYSTEM	(\$29,866.00)	Estimate Exception 37 on the current Payment Estimate.																														
					25	2022 Aug 16, 2022	SYSTEM	\$29,866.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user schirj1 overridding Payment Estimate Exception 39 on the current Payment Estimate.																														
					25	Aug 16, 2022	SYSTEM	(\$29,866.00)																															
				- Total				\$0.00																															
			Material - Tot	tal				\$0.00																															
	4140 -	· Total						\$0.00																															
	4150	SEWER - RIGID PIPE	Material		18	May 2, 2022	SYSTEM	\$7,750.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schirj1 overridding Payment Estimate Exception 70 on the current Payment Estimate.																														
					18	May 2, 2022	SYSTEM	(\$7,750.60)																															
						19	May 16, 2022	SYSTEM	\$7,750.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schirj1 overridding Payment Estimate Exception 56 on the current Payment Estimate.																													
					19	May 16, 2022	SYSTEM	(\$7,750.60)																															
					20	Jun 2, 2022	SYSTEM	\$7,750.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																														
							20	Jun 2, 2022	SYSTEM	(\$7,750.60)																													
					21	Jun 16, 2022	SYSTEM	\$32,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user schirj1 overridding Payment Estimate Exception 36 on the current Payment Estimate.																														
														21	Jun 16, 2022	SYSTEM	(\$32,890.00)																						
					22	Jul 1, 2022	SYSTEM	\$32,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user steppr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.																														
																											22	Jul 1, 2022	SYSTEM	(\$32,890.00)									
																	23	Jul 18, 2022	SYSTEM	\$32,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user schirj1 overridding Payment Estimate Exception 31 on the current Payment Estimate.																		
																						23	Jul 18, 2022	SYSTEM	(\$32,890.00)														
																								24	Aug 2, 2022	SYSTEM	\$32,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user steppr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.											
					24	Aug 2, 2022	SYSTEM	(\$32,890.00)																															
																	2	2		2	2	25	25		2	25	25						2	2	25	Aug 16, 2022	SYSTEM	\$32,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user schirj1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					:	25	Aug 16, 2022	SYSTEM	(\$32,890.00)																														
				- Total				\$0.00																															
			Material - Tot	tal				\$0.00																															



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718B	4150 -	- Total						\$0.00	
	4180	MISC. MANHOLES AND DROP	Construction Stockpile		24	Aug 2, 2022	SYSTEM	(\$2,094.39)	Payment Estimate Item Adjustment generated Stockpile Transaction
		INLETS		- Total				(\$2,094.39)	
			Construction	Stockpile - 1	otal .			(\$2,094.39)	
			Construction Stockpile		21	Jun 16, 2022	SYSTEM	\$4,188.79	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$4,188.79	
			Construction	Stockpile S	ΓΜΙ - Total			\$4,188.79	
			Material		24	Aug 2, 2022	SYSTEM	\$8,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user steppr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$8,240.00)	
					25	Aug 16, 2022	SYSTEM	\$8,240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$8,240.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	4180 -	- Total						\$2,094.40	
	4220	MISC. MANHOLES AND DROP INLETS	Construction Stockpile		24	Aug 2, 2022	SYSTEM	(\$13,675.84)	Payment Estimate Item Adjustment generated Stockpile Transaction
		III		- Total				(\$13,675.84)	
			Construction	Stockpile - 1	otal			(\$13,675.84)	
			Construction Stockpile STMI		21	Jun 16, 2022	SYSTEM	\$13,675.84	Payment Estimate Item Adjustment generated Stockpile Transaction
			OTIVII	- Total				\$13,675.84	
			Construction	Stockpile S	MI - Total			\$13,675.84	
			Material		24	Aug 2, 2022	SYSTEM	\$46,106.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user steppr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$46,106.00)	
					25	Aug 16, 2022	SYSTEM	\$46,106.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$46,106.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
	4220 -	- Total						\$0.00	
J6S1718B	- Total							\$34,456.53	
J6S1718C	4810	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS	Material		15	Mar 16, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schirj1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					15	Mar 16, 2022	SYSTEM	(\$3,159.45)	
					16	Apr 4, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 69 on the current Payment Estimate.
					16	Apr 4, 2022	SYSTEM	(\$3,159.45)	
					17	Apr 18, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schirj1 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					17	Apr 18, 2022	SYSTEM	(\$3,159.45)	
					18	May 2, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schirj1 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					18	May 2,	SYSTEM	(\$3,159.45)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J6S1718C	4810	CABLE-CONDUIT,	Material			2022					
	1 IN., 2 CONDUCTORS			19	May 16, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schirj1 overridding Payment Estimate Exception 61 on the current Payment Estimate.			
					19	May 16, 2022	SYSTEM	(\$3,159.45)			
					20	Jun 2, 2022	SYSTEM	\$3,159.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schirj1 overridding Payment Estimate Exception 44 on the current Payment Estimate.		
					20	Jun 2, 2022	SYSTEM	(\$3,159.45)			
					21	Jun 16, 2022	SYSTEM	\$11,793.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user schirj1 overridding Payment Estimate Exception 41 on the current Payment Estimate.		
					21	Jun 16, 2022	SYSTEM	(\$11,793.60)			
					22	Jul 1, 2022	SYSTEM	\$11,793.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user steppr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.		
					22	Jul 1, 2022	SYSTEM	(\$11,793.60)			
					23	Jul 18, 2022	SYSTEM	\$11,793.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0078) due to user schirj1 overridding Payment Estimate Exception 37 on the current Payment Estimate.		
					23	Jul 18, 2022	SYSTEM	(\$11,793.60)			
					24	Aug 2, 2022	SYSTEM	\$11,793.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user steppr1 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
							24	Aug 2, 2022	SYSTEM	(\$11,793.60)	
					25	Aug 16, 2022	SYSTEM	\$11,793.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0098) due to user schirj1 overridding Payment Estimate Exception 48 on the current Payment Estimate.		
					25	Aug 16, 2022	SYSTEM	(\$11,793.60)			
				- Total				\$0.00			
			Material - Tot	tal				\$0.00			
	4810 -							\$0.00			
	4830	MISC. HIGHWAY LIGHTING	Construction Stockpile		19	May 16, 2022	SYSTEM	(\$52.00)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					21	Jun 16, 2022	SYSTEM	(\$4,522.88)	Payment Estimate Item Adjustment generated Stockpile Transaction		
					25	Aug 16, 2022	SYSTEM	(\$31,295.68)	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				(\$35,870.56)			
			Construction	Stockpile - 1				(\$35,870.56)			
			Construction Stockpile STMA		23	Jul 18, 2022	SYSTEM	\$63,321.30	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				\$63,321.30			
			Construction	Stockpile S				\$63,321.30			
			Construction Stockpile STMI		18	May 2, 2022	SYSTEM	\$52.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
			3		19	May 16, 2022	SYSTEM	\$78,397.80	Payment Estimate Item Adjustment generated Stockpile Transaction		
				- Total				\$78,449.80			
			Construction	Stockpile S				\$78,449.80			
			Material		21	Jun 16, 2022	SYSTEM	\$11,589.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user schirj1 overridding Payment Estimate Exception 42 on the current Payment Estimate.		
						Jun 16, 2022	SYSTEM	(\$11,589.00)			
					22	Jul 1, 2022	SYSTEM	\$11,589.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user steppr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.		





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6S1718C	4830	MISC. HIGHWAY LIGHTING	Material		22	Jul 1, 2022	SYSTEM	(\$11,589.00)	
					23	Jul 18, 2022	SYSTEM	\$11,589.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user schirj1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					23	Jul 18, 2022	SYSTEM	(\$11,589.00)	
					24	Aug 2, 2022	SYSTEM	\$11,589.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user steppr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					24	Aug 2, 2022	SYSTEM	(\$11,589.00)	
					25	Aug 16, 2022	SYSTEM	\$88,849.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0099) due to user schirj1 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					25	Aug 16, 2022	SYSTEM	(\$88,849.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	4830 -	Total						\$105,900.54	
J6S1718C -	- Total							\$105,900.54	
Overall - To	otal							\$375,880.14	