

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

Progress Estim	nate Number	Contract ID Prime Contractor	210521-H04 Apex Paving Co.	Pay Period Start Pay Period End	August 2, 2021 August 15, 2021	Original Contract Amount Net Change Order Amount Current Contract Amount	\$1,219,630.79 (\$22,682.88) \$1,196,947.91
Approval Date							By User
August 16, 2021		G	enerated and Appr	oved (and should be	e considered Draft)	at the Project Office Level by	turnep3
August 16, 2021		Revie	wed and Approved	(and should be con	sidered Draft) at th	e Resident Engineer Level by	wilkem1
August 17, 2021		ce Controllers Office Level by	ramses1				

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2022	November 1, 2022		102.70%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	June 2, 2021	June 2, 2021	
Letting Date	May 21, 2021	May 21, 2021	
Notice to Proceed Date	July 6, 2021	July 6, 2021	
Open to Traffic Date	July 23, 2021	July 23, 2021	
Work Began Date	July 6, 2021	July 6, 2021	

Contract Total Pa	ay For Estimate No. 3				
		This Estimate	Previous	To Date	
210521-H04					
	Total Posted Items Pay	\$9,255.96	\$1,220,008.55	\$1,229,264.51	
	Gross Item Adjustments	\$0.00	\$7,132.48	\$7,132.48	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$1,227,141.03	\$1,236,396.99	
Contract Total Pa	avable This Estimate:	\$9.255.96			

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
J9S3358	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	EA	\$0.000	2	\$0.00		
Project J9S33	58 - Total						\$0.00		
J9S3359	0190	4134000	BITUMINOUS FOG SEAL	GAL	\$3.920	774	\$3,034.08		
	0200	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	EA	\$0.000	2	\$0.00		
Project J9S33	59 - Total						\$3,034.08		
J9S3361	0330	4134000	BITUMINOUS FOG SEAL	GAL	\$3.780	1,646	\$6,221.88		
	0340	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	EA	\$0.000	2	\$0.00		
Project J9S33	61 - Total						\$6,221.88		
Overall - Total									

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3358	0010	MISC.	Overrun		Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).	-1,256.7	\$36.00	(\$45,241.20)
	0010	MISC.	Overrun		This adjustment offsets the original system-	1,256.7	\$36.00	\$45,241.20

Revision 4/1/2020 Page 1 of 11



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: August 16, 2021

BITUMINOUS FOG SEAL

BITUMINOUS FOG SEAL

Overrun

Overrun

0330

0330

Total

Progr		imate Number 3	Contract II		0521-H04 ex Paving Co.	Pay Period Start A Pay Period End A	Contract Amount   \$1,219,630.79   tage Order Amount   \$22,682.88   \$1,196,947.91				
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments			Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3358						overridding Paymen	0001) due to use	r turnep3 otion 5 on			
J9S3359	0150		MISC.	Overrun		Averaged Price Adj all previous paymen	-223.2	\$36.00	(\$8,035.20)		
	0150		MISC.	Overrun		This adjustment o generated Overru Adjustment (( overridding Paymen the c	nate Item r turnep3	223.2	\$36.00	\$8,035.20	
	0190	BITUMINOUS	S FOG SEAL	Overrun					-554	\$3.92	(\$2,171.68)
	0190	BITUMINOUS	S FOG SEAL	Overrun		This adjustment o generated Overru Adjustment (( overridding Paymen the c	554	\$3.92	\$2,171.68		
J9S3361	0290	MISC.		Overrun		Averaged Price Adjustment from this item of all previous payment estimates of '0.00000' in applied (if non-zero)				\$36.00	(\$14,864.40)
	0290		MISC.	Overrun		This adjustment of	offsets the origina	l system-	412.9	\$36.00	\$14,864.40

generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 3 on

This adjustment offsets the original system-

generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.

the current Payment Estimate.

-1,171

1,171

\$3.78 (\$4,426.38)

\$4,426.38

\$0.00

\$3.78

Revision 4/1/2020 Page 2 of 11



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	Contract Project Information	on			
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work			
J9S3358	FAS S703(44)	Pavement Improvements	N	BUTLER	from Rte.51 in Quilin to R	Rte.51 in Fagus				
J9S3359	FAS S703(43)									
J9S3361	FAS S703(45)	Pavement Improvements	KK	BUTLER	from Rte.T to Rte. W					
Totals by .	Job Numbe	rs								
J9S3358	Poste Gross	d Item Pay Item Adjustme		tem Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$774,477.41 \$4,502.08 \$778,979.49	To Date \$774,477.41 \$4,502.08 \$778,979.49			
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J9S3359		d Item Pay Item Adjustme		Item Pay	This Estimate \$3,034.08 \$0.00 \$3,034.08	Previous \$155,025.01 \$867.17 \$155,892.18	To Date \$158,059.09 \$867.17 \$158,926.26			
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J9S3361		d Item Pay Item Adjustme		Item Pay	This Estimate \$6,221.88 \$0.00 <b>\$6,221.88</b>	Previous \$290,506.13 \$1,763.23 \$292,269.36	To Date \$296,728.01 \$1,763.23 \$298,491.24			
	Liquid	tive centive lated Damages Contract Adjus	tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 3 of 11



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 210521-H04, Contract Project J9S3359, Project Item Line Number 0150, Contract Line Item Number 0150, Item 3049910, Minor Item.	Change Order written and to be submitted for approval.	turnep3	Overridden
Estimate Exception Type: Item Overrun: Contract 210521-H04, Contract Project J9S3359, Project Item Line Number 0190, Contract Line Item Number 0190, Item 4134000, Minor Item.	Change Order written and to be submitted for approval.	turnep3	Overridden
Estimate Exception Type: Item Overrun: Contract 210521-H04, Contract Project J9S3361, Project Item Line Number 0290, Contract Line Item Number 0290, Item 3049910, Minor Item.	Change Order written and to be submitted for approval.	turnep3	Overridden
Estimate Exception Type: Item Overrun: Contract 210521-H04, Contract Project J9S3361, Project Item Line Number 0330, Contract Line Item Number 0330, Item 4134000, Minor Item.	Change Order written and to be submitted for approval.	turnep3	Overridden
Estimate Exception Type: Item Overrun: Contract 210521-H04, Contract Project J9S3358, Project Item Line Number 0010, Contract Line Item Number 0010, Item 3049910, Minor Item.	Change Order written and to be submitted for approval.	turnep3	Overridden

Revision 4/1/2020 Page 4 of 11



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
521-H04	J9S3358	0001	0010	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	1,146.00	0.00	1,146.00	TONS	2,402.70	\$36.00	\$86,497.2
		0001	0020	3105002	GRAVEL (A) OR CRUSHED STONE (B)	23.00	0.00	23.00	TONS	23.00	\$36.00	\$828.
		0001	0030	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	10,685.90	-39.80	10,646.10	TONS	10,646.10	\$60.14	\$640,256.4
		0001	0040	4071005	TACK COAT	12,254.00	-5,381.00	6,873.00	GAL	6,873.00	\$1.50	\$10,309.
		0001	0050	4134000	BITUMINOUS FOG SEAL	1,114.00	-1,114.00	0.00	GAL	0.00	\$3.89	\$0.
		0001	0060	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$0.00	\$0.
		0001	0070	6161005	CONSTRUCTION SIGNS	719.00	-5.00	714.00	SQFT	714.00	\$6.50	\$4,641
		0001	0800	6161009	FLAG ASSEMBLY	10.00	-5.00	5.00	EA	5.00	\$20.00	\$100
		0001	0090	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	0.00	\$13.00	\$0
		0001	0100	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$100.00	\$0
		0001	0110	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$22,805.61	\$22,805
		0001	0120	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	134,070.00	0.00	134,070.00	LF	0.00	\$0.11	\$0
		0001	0130	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	108,052.00	0.00	108,052.00	LF	0.00	\$0.11	\$1
		0001	0140	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	2,184.00	-912.60	1,271.40	SQYD	1,271.40	\$7.11	\$9,03
					ate as of Report Generated Date							\$774,47
	J9S3359	0001	0150	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	229.00	0.00	229.00	TONS	452.20	\$36.00	\$16,27
		0001	0160	3105002	GRAVEL (A) OR CRUSHED STONE (B)	7.00	0.00	7.00	TONS	7.00	\$36.00	\$25
	0001 0170			4020520	ITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE 2,009.00 42.10 2,051.10 TONS 2,051 EVELING)  ACK COAT 2,543.00 -994.00 1,549.00 GAL 1,549.00 TONS 2,543.00 -994.00 1,549.00 GAL 1,549.00 CAL 1,						\$59.22	\$121,46
		0001	0180	4071005						1,549.00	\$1.50	\$2,32
		0001	0190	4134000	BITUMINOUS FOG SEAL	220.00	0.00	220.00	GAL	774.00	\$3.92	\$3,03
		0001	0200	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$0.00	\$
		0001	0210	6161005	CONSTRUCTION SIGNS	752.00	-241.00	511.00	SQFT	511.00	\$6.50	\$3,32
		0001	0220	6161009	FLAG ASSEMBLY	10.00	-5.00	5.00	EA	5.00	\$20.00	\$10
		0001	0230	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	0.00	\$13.00	\$
		0001	0240	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$100.00	\$
		0001	0250	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$7,350.91	\$7,35
		0001	0260	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	21,627.00	0.00	21,627.00	LF	0.00	\$0.11	\$
		0001	0270	6206001C	4 IN, YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	21,627.00	0.00	21,627.00	LF	0.00	\$0.11	\$
		0001	0280	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	717.00	-325.00	392.00	SQYD	392.00	\$10.03	\$3,93
	Project J	S3359 - To	tal Value	Posted to D	ate as of Report Generated Date							\$158,05
	J9S3361	0001	0290	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	470.00	0.00	470.00	TONS	882.90	\$36.00	\$31,78
		0001	0300	3105002	GRAVEL (A) OR CRUSHED STONE (B)	2.00	0.00	2.00	TONS	2.00	\$36.00	\$7
		0001	0310	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	4,104.00	68.30	4,172.30	TONS	4,172.30	\$56.07	\$233,94
		0001	0320	4071005	TACK COAT	2,629.00	469.00	3,098.00	GAL	3,098.00	\$1.50	\$4,64
		0001	0330	4134000	BITUMINOUS FOG SEAL	475.00	0.00	475.00	GAL	1,646.00	\$3.78	\$6,22
		0001	0340	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$0.00	\$
		0001	0350	6161005	CONSTRUCTION SIGNS	735.00	-128.00	607.00	SQFT	607.00	\$6.50	\$3,94
		0001	0360	6161009	FLAG ASSEMBLY	10.00	-5.00	5.00	EA	5.00	\$20.00	\$10
		0001	0370	6161025	CHANNELIZER (TRIM LINE)	50.00	0.00	50.00	EA	0.00	\$13.00	\$
		0001	0380	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	0.00	\$100.00	\$
		0001	0390	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$9,323.18	\$9,32
		0001	0400	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	52,156.00	0.00	52,156.00	LF	0.00	\$0.11	\$
		0001	0410	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	24,943.00	0.00	24,943.00	LF	0.00	\$0.11	\$

Revision 4/1/2020 Page 5 of 11



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note. Fosted Q	uantities	anu valu	es ale b	aseu on it	eport Generated date and can dilier from the posted and	ount at the t	unic the L	Stilliate was	OCHCIA	itcu.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210521-H04	Project JS	9S3361 - To	tal Value	Posted to D	ate as of Report Generated Date							\$296,728.01
210521-H04 Ove	210521-H04 Overall - Total Value Posted to Date as of Report Generated Date										\$1,229,264.52	

Revision 4/1/2020 Page 6 of 11



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3358

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance		Offset/ Distance	Comments
0060	6123000A	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	8/11/21	8/16/21	2.00	EA	Utilized for Mobile Striping Operation.	0.000	RLC	12.840	RLC	

#### Project: J9S3359

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0190	4134000	BITUMINOUS FOG SEAL	8/11/21	8/16/21	774.00	GAL	NB and SB Lanes	0.000	RLC	2.540	RLC	
							800 Gal corrected to 774 Gal					
0200	6123000A	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	8/11/21	8/16/21	2.00	EA	Utilized for Mobile Striping Operation.	0.000	RLC	2.540	RLC	

#### Project: J9S3361

Line Numbe	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0330	4134000	BITUMINOUS FOG SEAL	8/11/21	8/16/21	1,646.00	GAL	EB and WB Lanes	0.000	RLC	5.220	RLC	
							1700 Gal corrected to 1646 Gal					
0340	6123000A	TRUCK OR TRAILER MOUNTED ATTEN (TMA)	8/11/21	8/16/21	2.00	EA	Utilized for Mobile Striping Operation.	0.000	RLC	5.220	RLC	

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 7 of 11



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
S3358	0010	MISC. AGGREGATE FOR BASE	Material		2	Aug 3, 2021	SYSTEM	\$86,497.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$86,497.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	FUEL	2	Aug 3, 2021	turnep3	\$48.29	Fuel Price Adjustment: \$48.29
				FUEL - Tota	ıl			\$48.29	
			Other Item A	Adjustment -	Total			\$48.29	
			Overrun	Overrun	2	Aug 3, 2021	SYSTEM	\$45,241.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) overridding Payment Estimate Exception 18 on the current Payment Estimate. Material Insufficiency Quantity 2402.700; Overrun Quantity Balance 1256.70.
					2	Aug 3, 2021	SYSTEM	(\$45,241.20)	
					3	Aug 16, 2021	SYSTEM	(\$45,241.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Aug 16, 2021	SYSTEM	\$45,241.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
				Overrun - Total				\$0.00	
			Overrun - To	otal				\$0.00	
	0010 -	Total						\$48.29	
	0020	GRAVEL (A) OR CRUSHED STONE (B)	Ŕ		2	Aug 3, 2021	SYSTEM	\$828.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$828.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0020 -	Total						\$0.00	
	0030	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Material		1	Jul 16, 2021	SYSTEM	\$640,256.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jul 16, 2021	SYSTEM	(\$640,256.45)	
					2	Aug 3, 2021	SYSTEM	\$640,256.45	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user turnep3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$640,256.45)	
				- Total				\$0.00	
			Material - To					\$0.00	
			Other Item Adjustment	ACAD Total		Jul 16, 2021	turnep3	\$3,393.44	AC Index Price Adjustment: \$3,393.44
			Others	ACAD - Tot				\$3,393.44	
				Adjustment -		1112	0)(0777	\$3,393.44	86 8 8 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
			Price FUEL		1	Jul 16, 2021	SYSTEM	\$181.32	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					1	Jul 16, 2021	SYSTEM	\$879.03	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$1,060.35	
			Price FUEL	- Total				\$1,060.35	
								\$4,453.79	
	0030 -	Total							



	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3358	0040	TACK COAT	Material		1	Jul 16, 2021	SYSTEM	(\$10,309.50)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0040	- Total						\$0.00	
J9S3358	- Total							\$4,502.08	
J9S3359	0150	MISC. AGGREGATE FOR BASE	Material		2	Aug 3, 2021	SYSTEM	\$16,279.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Aug 3, 2021	SYSTEM	(\$16,279.20)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
			Other Item Adjustment	FUEL	2	Aug 3, 2021	turnep3	\$9.09	Fuel Price Adjustment: \$9.09
				FUEL - Tota	ıl			\$9.09	
			Other Item /	Adjustment -	Total			\$9.09	
			Overrun	Overrun	2	Aug 3, 2021	SYSTEM	\$8,035.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0008) overridding Payment Estimate Exception 19 on the current Payment Estimate. Material Insufficiency Quantity 452.200; Overrun Quantity Balance 223.20.
					2	Aug 3, 2021	SYSTEM	(\$8,035.20)	
					3	Aug 16, 2021	SYSTEM	(\$8,035.20)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					3	Aug 16, 2021	SYSTEM	\$8,035.20	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) due to user turnep3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
				Overrun - T	otal			\$0.00	
			Overrun - T		otal			\$0.00 \$0.00	
	0150 -	- Total	Overrun - T		otal				
	<b>0150</b> · 0160	GRAVEL (A) OR CRUSHED	Overrun - To		2	Aug 3, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		GRAVEL (A) OR					SYSTEM	\$0.00 \$9.09	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment
		GRAVEL (A) OR CRUSHED	Material	otal - Total	2	2021 Aug 3,		\$0.00 \$9.09 \$252.00 (\$252.00)	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment
	0160	GRAVEL (A) OR CRUSHED STONE (B)		otal - Total	2	2021 Aug 3,		\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment
	0160	GRAVEL (A) OR CRUSHED STONE (B)	Material  Material - To	otal - Total	2	2021 Aug 3,		\$0.00 \$9.09 \$252.00 (\$252.00)	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE	Material  Material - To	otal - Total	2	2021 Aug 3,		\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT	Material  Material - To	otal - Total	2	Aug 3, 2021  Aug 3, 2021	SYSTEM	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE PG64-22	Material  Material - To	otal - Total	2	Aug 3, 2021  Aug 3, 2021  Aug 3, 2021	SYSTEM	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00 \$121,466.14	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE PG64-22	Material  Material - To	- Total otal	2	Aug 3, 2021  Aug 3, 2021  Aug 3, 2021	SYSTEM	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00 \$121,466.14	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE PG64-22	Material - To	- Total otal	2 2 2	Aug 3, 2021  Aug 3, 2021  Aug 3, 2021	SYSTEM	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00 \$121,466.14 (\$121,466.14)	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE PG64-22	Material - To  Material - To  Material - To  Other Item	- Total  - Total  - Total	2 2 2	Aug 3, 2021  Aug 3, 2021  Aug 3, 2021  Aug 3, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00 \$121,466.14 (\$121,466.14) \$0.00	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE PG64-22	Material - To  Material - To  Other Item Adjustment	- Total  - Total  - Total  ACAD	2 2 2 2 2 al	Aug 3, 2021  Aug 3, 2021  Aug 3, 2021  Aug 3, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00 \$121,466.14 (\$121,466.14) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE PG64-22	Material - To  Material - To  Other Item Adjustment	- Total  - Total  otal  ACAD	2 2 2 2 2 Total	Aug 3, 2021  Aug 3, 2021  Aug 3, 2021  Aug 3, 2021	SYSTEM SYSTEM SYSTEM	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00 \$121,466.14 (\$121,466.14) \$0.00 \$653.79	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE PG64-22	Material - To  Material - To  Material - To  Other Item Adjustment	- Total  - Total  otal  ACAD  ACAD - Total	2 2 2 2 2 Total	Aug 3, 2021	SYSTEM SYSTEM SYSTEM tumep3	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00 \$121,466.14 (\$121,466.14) \$0.00 \$0.00 \$653.79 \$653.79	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.  Asphalt Index Price Adjustment: \$653.79
	0160	GRAVEL (A) OR CRUSHED STONE (B)  Total  BITUMINOUS PAVEMENT MIXTURE PG64-22	Material - To  Material - To  Material - To  Other Item Adjustment	- Total  - Total  otal  ACAD  ACAD - Total	2 2 2 2 al Total 2 2	Aug 3, 2021  Aug 3, 2021	SYSTEM SYSTEM tumep3	\$0.00 \$9.09 \$252.00 (\$252.00) \$0.00 \$0.00 \$121,466.14 (\$121,466.14) \$0.00 \$653.79 \$653.79 (\$2,497.36)	Estimate Item Adjustment (0010) due to user turnep3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 8 on the current Payment Estimate.  Asphalt Index Price Adjustment: \$653.79  Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 16 on the current Payment Estimate. Material Insufficiency Quantity 2051.100;



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks		
1 Tojout	Line	Description	Туре	Adjustment Type	Number	Date	Ву	Amount	Remains		
J9S3359	0170	BITUMINOUS PAVEMENT	Price FUEL		2	Aug 3, 2021	SYSTEM	\$204.29	Reference Item Price Adjustment Index Adjustment Type applied is FUEL		
		MIXTURE PG64-22		- Total				\$204.29			
		(SUR	Price FUEL	- Total				\$204.29			
	0170 -	- Total						\$858.08			
	0190	BITUMINOUS FOG SEAL	Overrun	Overrun	3	Aug 16, 2021	SYSTEM	\$2,171.68	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) due to user turnep3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					3	Aug 16, 2021	SYSTEM	(\$2,171.68)			
				Overrun - To	otal			\$0.00			
			Overrun - To	otal				\$0.00			
	0190 -	· Total						\$0.00			
J9S3359	- Total							\$867.17			
J9S3361	0290	MISC. AGGREGATE FOR BASE	Material		2	Aug 3, 2021	SYSTEM	\$31,784.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					2	Aug 3, 2021	SYSTEM	(\$31,784.40)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Other Item Adjustment	FUEL	2	Aug 3, 2021	turnep3	\$17.75	Fuel Price Adjustment: \$17.75		
				FUEL - Tota	l .			\$17.75			
			Other Item A	Adjustment -	Total			\$17.75			
			Overrun	Overrun	Overrun	Overrun	2	Aug 3, 2021	SYSTEM	\$14,864.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0011) overridding Payment Estimate Exception 20 on the current Payment Estimate. Material Insufficiency Quantity 882.900; Overrun Quantity Balance 412.90.
					2	Aug 3, 2021	SYSTEM	(\$14,864.40)			
					3	Aug 16, 2021	SYSTEM	(\$14,864.40)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).		
					3	Aug 16, 2021	SYSTEM	\$14,864.40	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0004) due to user turnep3 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
				Overrun - To	otal			\$0.00			
			Overrun - To	otal				\$0.00			
	0290 -	- Total						\$17.75			
	0300	GRAVEL (A) OR CRUSHED STONE (B)	Material		2	Aug 3, 2021	SYSTEM	\$72.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user turnep3 overridding Payment Estimate Exception 6 on the current Payment Estimate.		
					2	Aug 3, 2021	SYSTEM	(\$72.00)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
	0300 -	· Total						\$0.00			
	0310		Material		2	Aug 3, 2021	SYSTEM	\$233,940.86	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user turnep3 overridding Payment Estimate Exception 9 on the current Payment Estimate.		
					2	Aug 3, 2021	SYSTEM	(\$233,940.86)			
				- Total				\$0.00			
			Material - To	otal				\$0.00			
			Other Item Adjustment	ACAD	2	Aug 3, 2021	turnep3	\$1,329.92	Asphalt Index Price Adjustment: \$1,329.92		
				ACAD - Tota	al			\$1,329.92			
			Other Item A	Adjustment -	Total			\$1,329.92			





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9S3361	0310	BITUMINOUS PAVEMENT	Overrun	Overrun	2	Aug 3, 2021	SYSTEM	(\$3,836.38)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
		MIXTURE PG64-22 (SUR			2	Aug 3, 2021	SYSTEM	\$3,836.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0017) overridding Payment Estimate Exception 17 on the current Payment Estimate. Material Insufficiency Quantity 4172.300; Overrun Quantity Balance 68.30.				
				Overrun - To	otal			\$0.00					
			Overrun - T	otal				\$0.00					
			Price FUEL		2	Aug 3, 2021	SYSTEM	\$415.56	Reference Item Price Adjustment Index Adjustment Type applied is FUEL				
				- Total				\$415.56					
			Price FUEL	- Total				\$415.56					
	0310 -	Total						\$1,745.48					
	0320	TACK COAT	Overrun	Overrun	2	Aug 3, 2021	SYSTEM	\$703.50	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0019) due to user turnep3 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					2	Aug 3, 2021	SYSTEM	(\$703.50)					
				Overrun - T	otal			\$0.00					
			Overrun - T	otal				\$0.00					
	0320 -	Total						\$0.00					
	0330	BITUMINOUS FOG SEAL	Overrun	Overrun	Overrun	Overrun	Overrun	Overrun	3	Aug 16, 2021	SYSTEM	\$4,426.38	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0005) due to user turnep3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Aug 16, 2021	SYSTEM	(\$4,426.38)					
				Overrun - To	otal			\$0.00					
			Overrun - T	otal				\$0.00					
0330 - Total								\$0.00					
J9S3361 - Total								\$1,763.23					
Overall - Total								\$7,132.48					