

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 3, 2022

	illiato italiiboi	Contract ID Prime Contractor	210618-C01 J M Scheidle,		eriod Start Decemberiod End January	/ 1, 2022 Net	ginal Contract Amount Change Order Amount rent Contract Amount	\$688,470.00 (\$30,930.00) \$657,540.00				
Approval Date								By User				
January 3, 2022		G	enerated and A	ted and Approved (and should be considered Draft) at the Project Office Level by								
January 3, 2022		Revie	wed and Appro	nd Approved (and should be considered Draft) at the Resident Engineer Level by								
January 4, 2022			F	Reviewed and Approved at the Central Office Controllers Office Level by								
Original Con	pletion Date	Current Compl	etion Date	Actual	Completion Date	% of C	urrent Contract Amount	Complete				
Decembe	December 1, 2021 December 1, 20			1 October 13, 2021 90.33%								
Co	ontract Information	nal Dates		Milestones								
Date Description	Original Completion Da	Current te Completion D		Description	Original Completion Date	Current Completion Da	Days Remaining on Milestone	Diary Charge Days				
Acceptance Date			Milesto	ne - lar Time	September 21, 2021	September 21, 2021	Milestone Complete					
Awarded Date	July 7, 2021	July 7, 2021										
Letting Date	June 18, 2021	June 18, 2021										
Notice to Proceed Date	July 8, 2021	July 8, 2021										
Open to Traffic Date	October 13, 2021	October 13, 20	21									

Contract Total Pay F	For Estimate No. 11			
		This Estimate	Previous	To Date
210618-C01				
	Total Posted Items Pay	\$0.00	\$593,976.00	\$593,976.00
	Gross Item Adjustments	\$0.00	\$482.30	\$482.30
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	(\$36,800.00)	(\$36,800.00)
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
			\$557,658.30	\$557,658.30
Contract Total Payal	ble This Estimate:	\$0.00		

Items Paid This Estimate Period

No Data Available

Work Began Date

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

July 21, 2021

July 21, 2021

ine Item /	Adjusti	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmen amount
J3S3209	0040	COMPACTING IN CUT	Material			-1.7	\$900.00	(\$1,530.00
	0040	COMPACTING IN CUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.	1.7	\$900.00	\$1,530.00
	0070	CURB AND GUTTER TYPE B	Material			-170	\$30.00	(\$5,100.00
	0070	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate.	170	\$30.00	\$5,100.00
	0170	FLOWABLE BACKFILL	Material			-33	\$220.00	(\$7,260.00)
	0170	FLOWABLE BACKFILL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user laymar	33	\$220.00	\$7,260.00

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 3, 2022

Progress Estimate Number 11 Contract Prime Co	210618-C01 Pay Period Sta ractor J M Scheidle, LLC Pay Period End		Original Contract Amount Net Change Order Amount Current Contract Amount	
---	--	--	--	--

Duningt	Lina	Itana Daganintian	Λ ali a t-aa a -a t	Oth an Itama	Commonto	Λ ali a tua a ua t	Line Here	A divertise a seri
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustmen amount
J3S3209					overridding Payment Estimate Exception 5 on the current Payment Estimate.			
	0280	COMPACTING IN CUT	Material			-0.6	\$2,000.00	(\$1,200.00)
	0280	COMPACTING IN CUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.	0.6	\$2,000.00	\$1,200.00
	0320	CURB AND GUTTER TYPE B	Material			-265	\$30.00	(\$7,950.00)
	0320	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Exception 4 on the current Payment Estimate.	265	\$30.00	\$7,950.00
	5001	MISC.	Material			-1	\$500.00	(\$500.00)
	5001	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user laymar overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$500.00	\$500.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	n					
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work					
J3S3209	FAS S303(16)	Slide repair	13	LAFAYETTE	from Rte. 224 to Delaware Street in Lexington							
Totals by J	Job Numbe	ers										
J3S3209		d Item Pay s Item Adjustm		s Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$593,976.00 \$482.30 \$594,458.30	To Date \$593,976.00 \$482.30 \$594,458.30					
	Liquid	tive centive dated Damages Contract Adju		i	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$36,800.00) \$5.00 \$0.00 \$0.00 \$0.00							

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J3S3209, Item 2037075, Project Item Line Number 0040, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	QC need to enter test results	laymar	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3209, Item 2037075, Project Item Line Number 0280, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	QC need to enter test results	laymar	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3209, Item 6091052, Project Item Line Number 0070, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	QC need to enter test results	laymar	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3209, Item 6091052, Project Item Line Number 0320, Material Set 609105296, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	QC need to enter test results	laymar	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3209, Item 6214600A, Project Item Line Number 0170, Material Set 6214600A96, Material 0621FB - Flowable Backfill, Acceptance Action Generic 0621FB is insufficient.	QC need to enter test results	laymar	Overridden
Estimate Exception Type: Insufficient Materials: Project J3S3209, Item 9019901, Project Item Line Number 5001, Material Set 9019901, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	QC need to enter test results	laymar	Overridden

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repo generated date)
618-C01	J3S3209	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	-	\$10,000.00	\$10,000.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,000.0
		0001	0030	2031000	CLASS A EXCAVATION	3,636.00	0.00	3,636.00	CUYD	3,636.00	\$6.50	\$23,634.
		0001	0040	2037075	COMPACTING IN CUT	1.70	0.00	1.70	STA	1.70	\$900.00	\$1,530.
		0001	0050	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	260.00	0.00	260.00	SQYD	260.00	\$50.00	\$13,000
		0001	0060	4019905	MISC.OPTIONAL PAVEMENT	203.10	0.00	203.10	SQYD	203.10	\$150.00	\$30,465
		0001	0070	6091052	CURB AND GUTTER TYPE B	170.00	0.00	170.00	LF	170.00	\$30.00	\$5,100
		0001	0080	6096040A	FURNISHING TYPE 4 ROCK DITCH LINER	136.00	0.00	136.00	CUYD	136.00	\$65.00	\$8,840
		0001	0090	6096044	PLACING TYPE 4 ROCK DITCH LINER	136.00	0.00	136.00	CUYD	136.00	\$25.00	\$3,400
		0001	0100	6096050	BEDDING MATERIAL FOR ROCK DITCH LINER	55.00	0.00	55.00	CUYD	55.00	\$60.00	\$3,300
		0001 0110 6113010 FURNISHING TYPE 1 ROCK BLANKET		4,025.00	0.00	4,025.00	CUYD	2,929.00	\$32.00	\$93,728		
		0001	0120	6113030	PLACING TYPE 1 ROCK BLANKET	4,025.00	0.00	4,025.00	CUYD	2,929.00	\$25.00	\$73,225
		0001	0130	6161005	CONSTRUCTION SIGNS	109.00	-109.00	0.00	SQFT	0.00	\$20.00	\$0
		0001	0140	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	6.00	\$235.00	\$1,410
		0001	0150	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,000
		0001	0160	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	40.00	-40.00	0.00	LF	0.00	\$25.00	\$0
		0001	0170	6214600A	FLOWABLE BACKFILL	163.00	-130.00	33.00	CUYD	33.00	\$220.00	\$7,260
		0001	0180	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	241.00	0.00	241.00	SQYD	241.00	\$2.00	\$48
		0001	0190	6240104A	SEPARATION GEOTEXTILE	2,905.00	0.00	2,905.00	SQYD	2,385.00	\$2.10	\$5,00
		0001	0200	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$17,000.00	\$17,00
		0001	0210	8061005	ROCK DITCH CHECK	92.00	0.00	92.00	LF	92.00	\$20.00	\$1,84
		0001	0220	8061007A	CURB INLET CHECK	6.00	0.00	6.00	EA	6.00	\$100.00	\$60
		0001	0230	8061016	SEDIMENT REMOVAL	11.00	-11.00	0.00	CUYD	0.00	\$150.00	\$
		0001	0240	8061019	SILT FENCE	200.00	0.00	200.00	LF	200.00	\$5.00	\$1,00
		0051 0250 2022010 REMOVAL OF IMPROVEMENTS	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$11,000.00	\$11,00		
		0051	0260	2031000	CLASS A EXCAVATION	6,637.00	0.00	6,637.00	CUYD	6,637.00	\$6.50	\$43,14
		0051	0270	2036000	COMPACTING EMBANKMENT	7,999.00	0.00	7,999.00	CUYD	7,999.00	\$6.00	\$47,99
		0051	0280	2037075	COMPACTING IN CUT	0.60	0.00	0.60	STA	0.60	\$2,000.00	\$1,20
		0051	0290	2063000	CLASS 3 EXCAVATION	1,536.00	0.00	1,536.00	CUYD	1,536.00	\$14.00	\$21,50
		0051	0300	3040143	TYPE 1 AGGREGATE FOR BASE (4 IN. THICK)	447.00	0.00	447.00	SQYD	447.00	\$50.00	\$22,35
		0051	0310	4019905	MISC.OPTIONAL PAVEMENT	360.30	0.00	360.30	SQYD	360.30	\$100.00	\$36,03
		0051	0320	6091052	CURB AND GUTTER TYPE B	260.00	5.00	265.00	LF	265.00	\$30.00	\$7,95
		0051	0330	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$10,000.00	\$10,00
		0051	0340	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT	30.00	-30.00	0.00	LF	0.00	\$5.00	\$
		0051	0350	7269903	MARKING PAINT, TYPE P BEADS MISC.60 IN. CLASS V REINFORCED CONCRETE PIPE	183.00	0.00	183.00	LF	183.00	\$300.00	\$54,90
		0051	0360	7320060A	60 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,00
		0051	0370	8051000A	SECTION SEEDING - COOL SEASON MIXTURES	0.30	0.00	0.30	ACRE	0.30	\$1,000.00	\$30
		0051	0380	8061016	SEDIMENT REMOVAL	4.00	-4.00	0.00	CUYD	0.00	\$100.00	\$1
		0051	0390	8061017	TEMPORARY SEEDING AND MULCHING	0.10	-0.10	0.00	ACRE	0.00	\$1,000.00	\$1
		0051	0400	8061019	SILT FENCE	357.00	500.00	857.00	LF	857.00	\$5.00	\$4,28
		0001	5001	9019901		0.00	1.00	1.00	LS	1.00	\$500.00	\$50
	Project-l				ate as of Report Generated Date							\$593,970
40 004 000					ort Generated Date							\$593,97

Revision 4/1/2020 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Page 6 of 14 Revision 4/1/2020



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
S3209	0030	CLASS A EXCAVATION	Price FUEL		1	Aug 2, 2021	SYSTEM	\$6.64	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					2	Aug 16, 2021	SYSTEM	\$20.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					3	Sep 1, 2021	SYSTEM	\$19.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
				- Total				\$46.18												
			Price FUEL	- Total				\$46.18												
	0030 -	Total						\$46.18												
	0040	COMPACTING IN CUT	Material		3	Sep 1, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					3	Sep 1, 2021	SYSTEM	(\$450.00)												
					4	Sep 15, 2021	SYSTEM	\$450.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					4	Sep 15, 2021	SYSTEM	(\$450.00)												
					5	Sep 30, 2021	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.											
									5	Sep 30, 2021	SYSTEM	(\$1,530.00)								
							6	Oct 15, 2021	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.									
					6	Oct 15, 2021	SYSTEM	(\$1,530.00)												
					7	Nov 2, 2021	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					7	Nov 2, 2021	SYSTEM	(\$1,530.00)												
					8	Nov 16, 2021	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					8	Nov 16, 2021	SYSTEM	(\$1,530.00)												
					9	Dec 1, 2021	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.											
					9	Dec 1, 2021	SYSTEM	(\$1,530.00)												
					10	Dec 16, 2021	SYSTEM	\$1,530.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.											
								10	Dec 16, 2021	SYSTEM	(\$1,530.00)									
																				11
					11	Jan 3, 2022	SYSTEM	(\$1,530.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0040 -	Total						\$0.00												
	0050	TYPE 1 AGGREGATE FOR BASE (4	Material		6	Oct 15, 2021	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate.											
		IN. THICK)	BASE (4				,	6	Oct 15, 2021	SYSTEM	(\$13,000.00)									
					7	Nov 2,	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J3S3209	0050	TYPE 1 AGGREGATE	Material	. , po		2021			Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate.																
		FOR BASE (4 IN. THICK)			7	Nov 2, 2021	SYSTEM	(\$13,000.00)																	
					8	Nov 16, 2021	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					8	Nov 16, 2021	SYSTEM	(\$13,000.00)																	
					9	Dec 1, 2021	SYSTEM	\$13,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate.																
					9	Dec 1, 2021	SYSTEM	(\$13,000.00)																	
				- Total				\$0.00																	
			Material - To					\$0.00																	
			Price FUEL	Star	6	Oct 15, 2021	SYSTEM	\$11.70	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																
				- Total				\$11.70																	
			Price FUEL					\$11.70																	
	0050		FIICE FUEL	- Total																					
		- Total			_			\$11.70																	
	0060	MISC.	Other Item Adjustment	ACAD		Nov 2, 2021	laymar	\$38.12	Index Difference (\$/T) x 1.98 T/CY x Thickness (in.)/36 x Quantity (SY) x Virgin AC%																
				ACAD - Tota	al			\$38.12																	
		O		FUEL	7	Nov 2, 2021	laymar	\$102.27	Fuel Index Adjustment Factor x Units of Work Performed in the Pay Period x Fuel Usage Factor the																
				FUEL - Tota	ı			\$102.27																	
			Other Item A		Total			\$140.39																	
	0060 -	- Total						\$140.39																	
	0070		Material	Material	Material	Material	Material	Material	Material	Material	Material	Material	Material	Material	Material	Material	Material	Material	Material		7	Nov 2, 2021	SYSTEM	\$5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Nov 2, 2021	SYSTEM	(\$5,100.00)																	
					_		CVCTEN	\$5,100.00																	
					8	Nov 16, 2021	SYSTEM	\$ 5,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate.																
					8		SYSTEM	(\$5,100.00)	Estimate Item Adjustment (0003) due to user laymar overridding Payment																
						2021 Nov 16,			Estimate Item Adjustment (0003) due to user laymar overridding Payment																
					8	2021 Nov 16, 2021 Dec 1,	SYSTEM	(\$5,100.00)	Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment																
					8	2021 Nov 16, 2021 Dec 1, 2021	SYSTEM SYSTEM	(\$5,100.00) \$5,100.00	Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment																
					9	2021 Nov 16, 2021 Dec 1, 2021 Dec 1, 2021 Dec 16,	SYSTEM SYSTEM	(\$5,100.00) \$5,100.00 (\$5,100.00)	Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment																
					8 9 9	2021 Nov 16, 2021 Dec 1, 2021 Dec 1, 2021 Dec 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,100.00) \$5,100.00 (\$5,100.00) \$5,100.00	Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment																
					9 9 10	2021 Nov 16, 2021 Dec 1, 2021 Dec 1, 2021 Dec 16, 2021 Jan 3,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,100.00) \$5,100.00 (\$5,100.00) \$5,100.00 (\$5,100.00)	Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment																
				- Total	9 9 10 10 11	2021 Nov 16, 2021 Dec 1, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 3, 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,100.00) \$5,100.00 (\$5,100.00) \$5,100.00 (\$5,100.00)	Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment																
			Material - To		9 9 10 10 11	2021 Nov 16, 2021 Dec 1, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 3, 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,100.00) \$5,100.00 (\$5,100.00) \$5,100.00 (\$5,100.00) \$5,100.00	Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment																
	0070	- Total	Material - To		9 9 10 10 11	2021 Nov 16, 2021 Dec 1, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 3, 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$5,100.00) \$5,100.00 (\$5,100.00) \$5,100.00 (\$5,100.00) \$5,100.00 (\$5,100.00)	Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment																



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks								
			Туре	Type	Number	Date	Бу										
J3S3209	0110	FURNISHING TYPE 1 ROCK BLANKET	Material		5	Sep 30, 2021	SYSTEM	(\$27,744.00)									
		DEANNET			6	Oct 15, 2021	SYSTEM	\$27,744.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate.								
					6	Oct 15, 2021	SYSTEM	(\$27,744.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0110 -	· Total						\$0.00									
	0140	TYPE III MOVEABLE BARRICADE	Material		1	Aug 2, 2021	SYSTEM	\$1,410.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					1	Aug 2, 2021	SYSTEM	(\$1,410.00)									
						2	Aug 16, 2021	SYSTEM	\$1,410.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.							
					2	Aug 16, 2021	SYSTEM	(\$1,410.00)									
				- Total				\$0.00									
			Material - To	otal				\$0.00									
	0140 -	Total						\$0.00									
	0170	FLOWABLE BACKFILL			4	Sep 15, 2021	SYSTEM	\$7,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate.								
													4	Sep 15, 2021	SYSTEM	(\$7,260.00)	
						5	Sep 30, 2021	SYSTEM	\$7,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 4 on the current Payment Estimate.							
					5	Sep 30, 2021	SYSTEM	(\$7,260.00)									
					6	Oct 15, 2021	SYSTEM	\$7,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Exception 6 on the current Payment Estimate.								
					6	Oct 15, 2021	SYSTEM	(\$7,260.00)									
					7	Nov 2, 2021	SYSTEM	\$7,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					7	Nov 2, 2021	SYSTEM	(\$7,260.00)									
								8	Nov 16, 2021	SYSTEM	\$7,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 11 on the current Payment Estimate.					
					8	Nov 16, 2021	SYSTEM	(\$7,260.00)									
					9	Dec 1, 2021	SYSTEM	\$7,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 11 on the current Payment Estimate.								
					9	Dec 1, 2021	SYSTEM	(\$7,260.00)									
					10	Dec 16, 2021	SYSTEM	\$7,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate.								
					10	Dec 16, 2021	SYSTEM	(\$7,260.00)									
						11	Jan 3, 2022	SYSTEM	\$7,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate.							
					11	Jan 3, 2022	SYSTEM	(\$7,260.00)									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
3S3209	0170	FLOWABLE BACKFILL	Material	- Total				\$0.00						
		DACKI ILL	Material - T	otal				\$0.00						
	0170 -	- Total						\$0.00						
	0210	ROCK DITCH CHECK	Material		5	Sep 30, 2021	SYSTEM	\$1,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					5	Sep 30, 2021	SYSTEM	(\$1,840.00)						
					6	Oct 15, 2021	SYSTEM	\$1,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate.					
					6	Oct 15, 2021	SYSTEM	(\$1,840.00)						
							7	Nov 2, 2021	SYSTEM	\$1,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Exception 13 on the current Payment Estimate.			
					7	Nov 2, 2021	SYSTEM	(\$1,840.00)						
					8	Nov 16, 2021	SYSTEM	\$1,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Exception 15 on the current Payment Estimate.					
								8	Nov 16, 2021	SYSTEM	(\$1,840.00)			
					9	Dec 1, 2021	SYSTEM	\$1,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Exception 15 on the current Payment Estimate.					
					9	Dec 1, 2021	SYSTEM	(\$1,840.00)						
				- Total				\$0.00						
			Material - T	otal				\$0.00						
	0210 -	- Total						\$0.00						
	0220	0210 - Total 0220 CURB INLET CHECK			5	Sep 30, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Exception 6 on the current Payment Estimate.					
						5	Sep 30, 2021	SYSTEM	(\$600.00)					
					6	Oct 15, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					6	Oct 15, 2021	SYSTEM	(\$600.00)						
					7	Nov 2, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user laymar overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					7	Nov 2, 2021	SYSTEM	(\$600.00)						
										8	Nov 16, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user laymar overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Nov 16, 2021	SYSTEM	(\$600.00)						
								9			OVOTERA	0000.00	I	
						Dec 1, 2021	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user laymar overridding Payment Estimate Exception 16 on the current Payment Estimate.					
					9		SYSTEM	(\$600.00)	Estimate Item Adjustment (0006) due to user laymar overridding Payment					
				- Total		2021 Dec 1,			Estimate Item Adjustment (0006) due to user laymar overridding Payment					
			Material - T			2021 Dec 1,		(\$600.00)	Estimate Item Adjustment (0006) due to user laymar overridding Payment					
	0220 -	·Total	Material - T			2021 Dec 1,		(\$600.00)	Estimate Item Adjustment (0006) due to user laymar overridding Payment					
	0220 - 0260	-Total CLASS A EXCAVATION	Price			2021 Dec 1,		(\$600.00) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user laymar overridding Payment					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3S3209	0260	CLASS A EXCAVATION	Price FUEL			2021			
				- Total				\$74.20	
			Price FUEL	- Total				\$74.20	
	0260 -	Total						\$74.20	
	0270	COMPACTING EMBANKMENT	Material		3	Sep 1, 2021	SYSTEM	\$9,598.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Sep 1, 2021	SYSTEM	(\$9,598.80)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0270 -	Total						\$0.00	
	0280	COMPACTING IN CUT	Material		3	Sep 1, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Sep 1, 2021	SYSTEM	(\$400.00)	
					4	Sep 15, 2021	SYSTEM	\$400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Sep 15, 2021	SYSTEM	(\$400.00)	
					5	Sep 30, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Sep 30, 2021	SYSTEM	(\$1,200.00)	
					6	Oct 15, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Oct 15, 2021	SYSTEM	(\$1,200.00)	
					7	Nov 2, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Nov 2, 2021	SYSTEM	(\$1,200.00)	
					8	Nov 16, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Nov 16, 2021	SYSTEM	(\$1,200.00)	
					9	Dec 1, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Dec 1, 2021	SYSTEM	(\$1,200.00)	
					10	Dec 16, 2021	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Dec 16, 2021	SYSTEM	(\$1,200.00)	
					11	Jan 3, 2022	SYSTEM	\$1,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user laymar overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Jan 3, 2022	SYSTEM	(\$1,200.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0280 -	· Total						\$0.00	
	0300	TYPE 1 AGGREGATE	Material		6	Oct 15, 2021	SYSTEM	\$22,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user laymar overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J3S3209	0300	FOR BASE (4 IN. THICK)	Material						Estimate Exception 4 on the current Payment Estimate.
					6	Oct 15, 2021	SYSTEM	(\$22,350.00)	
					7	Nov 2, 2021	SYSTEM	\$22,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user laymar overridding Payment Estimate Exception 4 on the current Payment Estimate.
					7	Nov 2, 2021	SYSTEM	(\$22,350.00)	
					8	Nov 16, 2021	SYSTEM	\$22,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user laymar overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Nov 16, 2021	SYSTEM	(\$22,350.00)	
					9	Dec 1, 2021	SYSTEM	\$22,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user laymar overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Dec 1, 2021	SYSTEM	(\$22,350.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Price FUEL		6	Oct 15, 2021	SYSTEM	\$20.12	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$20.12	
			Price FUEL	- Total				\$20.12	
	0300 -	Total						\$20.12	
	0310	MISC.	Other Item Adjustment	ACAD	7	Nov 2, 2021	laymar	\$51.51	Index Difference (\$/T) x 1.98 T/CY x Thickness (in.)/36 x Quantity (SY) x Virgin AC%
				ACAD - Tota	al			\$51.51	
				FUEL	7	Nov 2, 2021	laymar	\$138.20	Fuel Index Adjustment Factor x Units of Work Performed in the Pay Period x Fuel Usage Factor the
				FUEL - Total				\$138.20	
		Other Item Adjustment - Total						\$189.71	
			10 - Total						
	0320							\$189.71	
		CURB AND GUTTER TYPE B	Material		7	Nov 2, 2021	SYSTEM	\$189.71 \$7,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate.
		GUTTER TYPE	Material		7		SYSTEM SYSTEM		Estimate Item Adjustment (0009) due to user laymar overridding Payment
		GUTTER TYPE	Material			2021 Nov 2,		\$7,800.00	Estimate Item Adjustment (0009) due to user laymar overridding Payment
		GUTTER TYPE	Material		7	2021 Nov 2, 2021 Nov 16,	SYSTEM	\$7,800.00 (\$7,800.00)	Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment
		GUTTER TYPE	Material		7	2021 Nov 2, 2021 Nov 16, 2021	SYSTEM SYSTEM	\$7,800.00 (\$7,800.00) \$7,800.00	Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment
		GUTTER TYPE	Material		7 8	Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 1,	SYSTEM SYSTEM	\$7,800.00 (\$7,800.00) \$7,800.00 (\$7,800.00)	Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment
		GUTTER TYPE	Material		7 8 8 9	2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 1, 2021 Dec 1,	SYSTEM SYSTEM SYSTEM SYSTEM	\$7,800.00 (\$7,800.00) \$7,800.00 (\$7,800.00) \$7,950.00	Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment
		GUTTER TYPE	Material		7 8 8 9	2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 1, 2021 Dec 1, 2021 Dec 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$7,800.00 (\$7,800.00) \$7,800.00 (\$7,800.00) \$7,950.00	Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment
		GUTTER TYPE	Material		7 8 8 9 9	2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 1, 2021 Dec 16, 2021 Dec 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,800.00 (\$7,800.00) \$7,800.00 (\$7,800.00) \$7,950.00 (\$7,950.00)	Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment
		GUTTER TYPE	Material		7 8 8 9 9 10	2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 1, 2021 Dec 1, 2021 Dec 16, 2021 Jan 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,800.00 (\$7,800.00) \$7,800.00 (\$7,800.00) \$7,950.00 (\$7,950.00) (\$7,950.00)	Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.
		GUTTER TYPE	Material	- Total	7 8 8 9 9 10 10	2021 Nov 2, 2021 Nov 16, 2021 Nov 16, 2021 Dec 1, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 3, 3	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$7,800.00 (\$7,800.00) \$7,800.00 (\$7,800.00) \$7,950.00 (\$7,950.00) (\$7,950.00) \$7,950.00	Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 7 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user laymar overridding Payment Estimate Exception 8 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user laymar overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.



J3S3209 0320 - Total \$0.00	Remarks
0360 60 IN GROUP Material 2 Aug 16 SYSTEM \$3,500,00 This adjustment offsets	
B FLARED 2021 Estimate Item Adjustme	the original system-generated Material Payment ent (0004) due to user laymar overridding Payment n the current Payment Estimate.
2 Aug 16, SYSTEM (\$3,500.00)	
- Total \$0.00	
Material - Total \$0.00	
0360 - Total \$0.00	
COOL 2021 Estimate Item Adjustme	the original system-generated Material Payment ent (0010) due to user laymar overridding Payment on the current Payment Estimate.
7 Nov 2, SYSTEM (\$300.00)	
2021 Estimate Item Adjustme	the original system-generated Material Payment ent (0010) due to user laymar overridding Payment on the current Payment Estimate.
8 Nov 16, SYSTEM (\$300.00)	
2021 Estimate Item Adjustme	the original system-generated Material Payment ent (0010) due to user laymar overridding Payment on the current Payment Estimate.
9 Dec 1, SYSTEM (\$300.00)	
2021 Estimate Item Adjustme	the original system-generated Material Payment ent (0006) due to user laymar overridding Payment n the current Payment Estimate.
10 Dec 16, SYSTEM (\$300.00)	
2021	
- Total \$0.00	
- Total \$0.00	
Total \$0.00	i the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate.
Total \$0.00	ent (0011) due to user laymar overridding Payment
Total \$0.00	ent (0011) due to user laymar overridding Payment
Total \$0.00	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. If the original system-generated Material Payment ent (0011) due to user laymar overridding Payment
Total \$0.00	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. If the original system-generated Material Payment ent (0011) due to user laymar overridding Payment
Total \$0.00	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment ent (0011) due to user laymar overridding Payment
Nov 2	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment ent (0011) due to user laymar overridding Payment
Nov 2	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. If the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. If the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate.
Total \$0.00	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. If the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. If the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate.
Total \$0.00	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0007) due to user laymar overridding Payment in the current Payment Estimate.
Nov 2	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0007) due to user laymar overridding Payment in the current Payment Estimate.
Nov 2	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0007) due to user laymar overridding Payment in the current Payment Estimate.
Total S0.00 Material - Total S0.00 S0.00	ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0011) due to user laymar overridding Payment on the current Payment Estimate. Is the original system-generated Material Payment ent (0007) due to user laymar overridding Payment in the current Payment Estimate.



Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
Overall -	Total						\$482.30		

Jan 5, 2022