

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2022

Progress Estima	Progress Estimate Number 16		210820-F02 Reinhold Electric, Inc	Pay Period Start Pay Period End		2022	Original Contract Amoun Net Change Order Amoun Current Contract Amount	nt \$1,080.00
Approval Date								By User
December 2, 2022			Generated and App	roved (and should be	considered Dra	aft) at tl	ne Project Office Level by	burlbe
December 2, 2022		Re	eviewed and Approved	(and should be con	sidered Draft) at	t the Re	esident Engineer Level by	vancef1
December 5, 2022	Reviewed and Approved at the Central Office Controllers Office Level by							ramses1
Original Comp	letion Date	Current Completion Date Actual Completion Date % of Current Contract Amou					t Complete	
June 1, 2	2022	July 25	, 2022				95.28%	

	Milestones		
Date Description	Original Completion Date	No Milestones Exist for Contract	
Acceptance Date			
Awarded Date	September 8, 2021	September 8, 2021	
Letting Date	August 20, 2021	August 20, 2021	
Notice to Proceed Date	October 4, 2021	October 4, 2021	
Open to Traffic Date			
Work Began Date	November 4, 2021	November 4, 2021	

Contract Total Pay For Estimate No. 16										
		This Estimate	Previous	To Date						
210820-F02										
	Total Posted Items Pay	\$0.00	\$234,843.60	\$234,843.60						
	Gross Item Adjustments	\$0.00	(\$42,157.60)	(\$42,157.60)						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
			\$192,686.00	\$192,686.00						
Contract Total Payal	ole This Estimate:	\$0.00								
Brown Build This Bulletin										

Items Paid This Estimate Period

No Data Available

Contract Adjustments This Estimate

		tments Exist on Contract nents This Estimate						
Line item.	Aujusti	Hents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6P3596	0060	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	MaterialCredit			47	\$41.00	\$1,927.00
	0060	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-47	\$41.00	(\$1,927.00)
	0070	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	MaterialCredit			60	\$13.00	\$780.00
	0070	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	Material			-60	\$13.00	(\$780.00)
	0190	MISC.	MaterialCredit			1.5	\$450.00	\$675.00
	0190	MISC.	Material			-1.5	\$450.00	(\$675.00)
	0240	SH-FLAT SHEET - SIGNAL SIGN	MaterialCredit			15	\$33.00	\$495.00
	0240	SH-FLAT SHEET - SIGNAL SIGN	Material			-15	\$33.00	(\$495.00)

Revision 4/1/2020 Page 1 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 2, 2022

Progr	ess Esti 1	mate Number 6	Contract ID Prime Cont	210820 ractor Reinhol				Original Contract Net Change Ord Current Contract	er Amount	\$245,391.00 \$1,080.00 \$246,471.00
Project Number	Line No.	Item Descr	ription	Adjustment Type	Other Item Adjustment Type	Cor	mments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6P3596	0260	POST, SIGNAL 15 FT. OR 4.6 M		MaterialCredit				3	\$934.00	\$2,802.00
	0260	POST, SIGNA	L 15 FT. OR 4.6 M	Material				-3	\$934.00	(\$2,802.00
	0400	BASE,	CONCRETE	MaterialCredit				7.87	\$1,780.00	\$14,008.60
	0400	BASE,	CONCRETE	Material				-7.87	\$1,780.00	(\$14,008.60
	0420		MISC.	MaterialCredit				1	\$16,148.00	\$16,148.00
	0420		MISC.	Material				-1	\$16,148.00	(\$16,148.00
	0430		MISC.	MaterialCredit				1	\$1,104.00	\$1,104.00
	0430		MISC.	Material				-1	\$1,104.00	(\$1,104.00
	0460	2 IN. PSST PC	OST - 12 GA.	MaterialCredit				39.5	\$18.00	\$711.00
	0460	2 IN. PSST PC	OST - 12 GA.	Material				-39.5	\$18.00	(\$711.00
	0470	POST ANCHO	R FOR 2 IN. SST - 12 GA.	MaterialCredit				9	\$33.00	\$297.00
	0470	POST ANCHO	R FOR 2 IN. SST - 12 GA.	Material				-9	\$33.00	(\$297.00
	0480	SH-F	LAT SHEET	MaterialCredit				2	\$30.00	\$60.00
	0480	SH-F	LAT SHEET	Material				-2	\$30.00	(\$60.00
	0490	SHF-FLAT SHEET FLUORESCENT		MaterialCredit				75	\$42.00	\$3,150.00
	0490		LAT SHEET ORESCENT	Material				-75	\$42.00	(\$3,150.00
Γotal										\$0.00

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information					
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work						
J6P3596	FAF-21-2(88)	Signal and lighting installation	21	JEFFERSON	at Rte. 110 and Liberty School Rd. intersection						
Totals by J	Job Numbers										
J6P3596					This Estimate	Previous	To Date				
	Posted Ite	m Pay			\$0.00	\$234,843.60	\$234,843.60				
	Gross Iter	n Adjustments	5		\$0.00	(\$42,157.60)	(\$42,157.60)				
		· G	ross Ite	m Pay	\$0.00	\$192,686.00	\$192,686.00				
	Incentive				\$0.00	\$0.00	\$0.00				
	Disincenti	ve			\$0.00	\$0.00	\$0.00				
		d Damages			\$0.00 \$0.00 \$0.00						
		tract Adjustm			\$0.00 \$0.00 \$0.00						

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 6200015, Project Item Line Number 0060, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 6205901A, Project Item Line Number 0070, Material Set 6205901A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 6205901A, Project Item Line Number 0070, Material Set 6205901A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9019902, Project Item Line Number 0190, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	This payment is for labor cost only. This will be resolved when the contractor gets the material and installs the LED's.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9020833, Project Item Line Number 0240, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9022715, Project Item Line Number 0260, Material Set 902271596, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9022715, Project Item Line Number 0260, Material Set 902271596, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9029100, Project Item Line Number 0400, Material Set 902910096, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	Working with contractor to resolve.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9029100, Project Item Line Number 0400, Material Set 902910096, Material 1036RSDFPL42M13 - Reinforcing Steel No. 4/M13 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL reports.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9029100, Project Item Line Number 0400, Material Set 902910096, Material 1036RSDFPL42M19 - Reinforcing Steel No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL reports	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9029902, Project Item Line Number 0420, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9029902, Project Item Line Number 0430, Material Set 9029902, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9031270A, Project Item Line Number 0460, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9031271, Project Item Line Number 0470, Material Set 903127196, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9035004A, Project Item Line Number 0480, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9035069A, Project Item Line Number 0490, Material Set 9035069A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Waiting on Certs from the contractor.	burlbe	Acknowledged

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ole. Fosieu Q	uaniiiies	and valu	es are i	pased on R	eport Generated date and can differ from the posted amo	ount at the	e ume un	e Estimate v	was Ger	ieraied.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210820-F02	J6P3596	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$1,200.00	\$1,200.0
		0001	0020	6083006	6 IN. CONCRETE MEDIAN STRIP	23.00	0.00	23.00	SQYD	0.00	\$210.00	\$0.0
		0001	0030	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.95	\$12,000.00	\$11,400.0
		0001	0040	6169902	MISC.NTCIP Compliant Changeable Message Sign, Contractor Furnished/Retained	3.00	0.00	3.00	EA	3.00	\$1,000.00	\$3,000.0
		0001	0050	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$6,500.00	\$6,500.0
		0001	0060	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	47.00	0.00	47.00	LF	47.00	\$41.00	\$1,927.0
		0001	0070	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	60.00	0.00	60.00	LF	60.00	\$13.00	\$780.0
		0001	0800	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$450.00	\$450.0
		0001	0090	8061005	ROCK DITCH CHECK	5.00	0.00	5.00	LF	1.00	\$90.00	\$90.0
		0001	0100	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	0.00	\$60.00	\$0.0
		0001	0110	8061019	SILT FENCE	420.00	0.00	420.00	LF	0.00	\$1.00	\$0.0
		0020	0120	9014003	CONDUIT, 3 IN. RIGID, PUSHED	180.00	0.00	180.00	LF	180.00	\$42.00	\$7,560.0
		0020	0130	9015010	TRENCHING TYPE I	240.00	0.00	240.00	LF	240.00	\$7.50	\$1,800.0
		0020	0140	9015020	TRENCHING TYPE II	30.00	0.00	30.00	LF	30.00	\$52.00	\$1,560.0
		0020	0150	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	4.00	\$1,079.00	\$4,316.0
		0020	0160	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	270.00	0.00	270.00	LF	270.00	\$0.50	\$135.0
		0020	0170	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	770.00	0.00	770.00	LF	770.00	\$3.50	\$2,695.0
		0020	0180	9018245	NEUTRAL, 8 AWG POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	3.00	0.00	3.00	EA	3.00	\$2.005.00	\$6,015.0
		0020	0190	9019902	MISC.170W TOP MOUNTED LED-B LUMINAIRE	3.00	0.00	3.00	EA	1.50	\$450.00	\$675.
		0020	0200	9019902	MISC.45 FT. TOP MOUNT POLE	3.00	0.00	3.00	EA	3.00	\$3,698.00	\$11,094.
		0030	0210	9020111	SIGNAL HEAD, TYPE 1T	3.00	0.00	3.00	EA	2.00	\$524.00	\$1,048.
		0030	0220	9020513	SIGNAL HEAD, TYPE 3B	6.00	0.00	6.00	EA	6.00	\$704.00	\$4,224.
		0030	0230	9020514	SIGNAL HEAD, TYPE 4B	1.00	0.00	1.00	EA	1.00	\$798.00	\$798.
			0240	9020833	SH-FLAT SHEET - SIGNAL SIGN	15.00	0.00	15.00	SQFT	15.00	\$33.00	\$495.
		0030										
		0030	0250	9020834	SIGNAL SIGN, MOUNTING HARDWARE	2.00	0.00	2.00	EA	2.00	\$22.00	\$44
		0030	0260	9022715	POST, SIGNAL 15 FT. OR 4.6 M	3.00	0.00		EA		\$934.00	\$2,802
		0030	0270	9023215	POST, TYPE C, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	1.00	\$7,159.00	\$7,159
		0030	0280	9023350	POST, TYPE B, LONGEST ARM 50 FT. OR 15.2 M	1.00	0.00	1.00	EA	1.00		\$19,825
		0030	0290	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	1.00		\$11,690
		0030	0300	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	1,852.00	-40.00	1,812.00	LF	1,812.00	\$12.00	\$21,744
		0030	0310	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	193.00	0.00	193.00	LF	193.00	\$14.00	\$2,702
		0030	0320	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	235.00	40.00	275.00	LF	275.00	\$39.00	\$10,725
		0030	0330	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	211.00	0.00	211.00	LF	211.00	\$42.00	\$8,862
		0030	0340	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	80.00	0.00	80.00	LF	80.00	\$1.00	\$80
		0030	0350	9028309	CABLE, 16 AWG 3 CONDUCTOR	2,940.00	0.00	2,940.00	LF	2,940.00	\$1.50	\$4,410
		0030	0360	9028311	CABLE, 16 AWG 7 CONDUCTOR	1,210.00	0.00	1,210.00	LF	1,210.00	\$1.50	\$1,815
		0030	0370	9028810	PULL BOX, PREFORMED CLASS 1	13.00	0.00	13.00	EA	13.00	\$1,079.00	\$14,027
		0030	0380	9028811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	3.00	\$1,217.00	\$3,651
		0030	0390	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$1,714.00	\$1,714
		0030	0400	9029100	BASE, CONCRETE	9.20	0.00	9.20	CUYD	7.87	\$1,780.00	\$14,008
		0030	0410	9029902	MISC.ATC Traffic Signal Controller	1.00	0.00	1.00	EA	1.00	\$3,920.00	\$3,920
		0030	0420	9029902	MISC.COMBINATION PAD-MOUNTED 120/240V PS & LIGHTING CS WITH UPS	1.00	0.00	1.00	EA	1.00	\$16,148.00	\$16,148.
		0030	0430	9029902	MISC.Network Connected Signal Monitor	1.00	0.00	1.00	EA	1.00	\$1,104.00	\$1,104.
		0030	0440	9029902	MISC.Retroreflective Backplates	7.00	0.00	7.00	EA	7.00	\$115.00	\$805.0

Revision 4/1/2020 Page 5 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
210820-F02	J6P3596	0030	0450	9029902	MISC.SL VIDEO DETECTION SYSTEM	4.00	0.00	4.00	EA	4.00	\$3,907.00	\$15,628.00
		0040	0460	9031270A	2 IN. PSST POST - 12 GA.	87.00	0.00	87.00	LF	39.50	\$18.00	\$711.00
		0040	0470	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	21.00	0.00	21.00	LF	9.00	\$33.00	\$297.00
		0040	0480	9035004A	SH-FLAT SHEET	2.00	0.00	2.00	SQFT	2.00	\$30.00	\$60.00
		0040	0490	9035069A	SHF-FLAT SHEET FLUORESCENT	75.00	0.00	75.00	SQFT	75.00	\$42.00	\$3,150.00
Project J6P3596 - Total Value Posted to Date as of Report Generated Date										\$234,843.60		
210820-F02 Overall - Total Value Posted to Date as of Report Generated Date										\$234,843.60		

Revision 4/1/2020 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Page 7 of 14 Revision 4/1/2020



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6P3596	0060	PREF THERMO PVMT MARK,	Material		15	Nov 15, 2022	SYSTEM	(\$1,927.00)					
		24 IN WHIT			16	Dec 2, 2022	SYSTEM	(\$1,927.00)					
				- Total				(\$3,854.00)					
			Material - Tota	ı				(\$3,854.00)					
			MaterialCredit		16	Dec 2, 2022	SYSTEM	\$1,927.00					
				- Total				\$1,927.00					
			MaterialCredit	- Total				\$1,927.00					
	0060 -	· Total						(\$1,927.00)					
	0070	4 IN. YELLOW	Material		15	Nov 15,	SYSTEM	(\$780.00)					
		HIGH BUILD WATERBORNE PAINT			16	2022 Dec 2,	SYSTEM	(\$780.00)					
		TAINT				2022		, ,					
				- Total				(\$1,560.00)					
			Material - Tota	l				(\$1,560.00)					
			MaterialCredit		16	Dec 2, 2022	SYSTEM	\$780.00					
				- Total				\$780.00					
			MaterialCredit	MaterialCredit - Total				\$780.00					
	0070 -	- Total						(\$780.00)					
	0090		ROCK DITCH				Material		4	Jan 3, 2022	SYSTEM	\$90.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.
				4	Jan 3, 2022	SYSTEM	(\$90.00)						
				- Total				\$0.00					
			Material - Tota	ı				\$0.00					
	0090 -	· Total	Material - Tota	ı				\$0.00 \$0.00					
	0090 -	CABLE, 10 AWG 1 CONDUCTOR,			1	Nov 16, 2021	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.				
		CABLE, 10 AWG 1		ı	1		SYSTEM	\$0.00	Estimate Item Adjustment (0001) due to user burlbe overridding Payment				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &				2021 Nov 16,		\$0.00 \$45.00	Estimate Item Adjustment (0001) due to user burlbe overridding Payment				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1	2021 Nov 16, 2021 Dec 2,	SYSTEM	\$0.00 \$45.00 (\$45.00)	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1 2	2021 Nov 16, 2021 Dec 2, 2021 Dec 2,	SYSTEM SYSTEM	\$0.00 \$45.00 (\$45.00) \$45.00	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1 2 2	2021 Nov 16, 2021 Dec 2, 2021 Dec 2, 2021 Dec 16,	SYSTEM SYSTEM	\$0.00 \$45.00 (\$45.00) \$45.00	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1 2 2 3	2021 Nov 16, 2021 Dec 2, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$45.00 (\$45.00) \$45.00 (\$45.00) \$135.00	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1 2 2 3 3 3	2021 Nov 16, 2021 Dec 2, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$45.00 (\$45.00) \$45.00 (\$45.00) \$135.00	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1 2 2 3 3 4	2021 Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 3, 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$45.00 (\$45.00) \$45.00 (\$45.00) \$135.00 (\$135.00)	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1 2 2 3 3 4 4 4	2021 Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 18,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$45.00 (\$45.00) \$45.00 (\$45.00) \$135.00 (\$135.00)	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1 2 2 3 3 4 4 5 5	2021 Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 18, 2022 Jan 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$45.00 (\$45.00) \$45.00 (\$45.00) \$135.00 (\$135.00) \$135.00	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.				
		CABLE, 10 AWG 1 CONDUCTOR, POLE &			1 2 2 3 3 4 4 5 5 5	2021 Nov 16, 2021 Dec 2, 2021 Dec 16, 2021 Dec 16, 2021 Jan 3, 2022 Jan 18, 2022 Jan 18, 2022 Feb 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$45.00 (\$45.00) \$45.00 (\$45.00) \$135.00 (\$135.00) \$135.00 (\$135.00)	Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 1 on the current Payment Estimate.				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3596	0160		Material						Estimate Exception 1 on the current Payment Estimate.
		AWG 1 CONDUCTOR, POLE &			7	Feb 16, 2022	SYSTEM	(\$135.00)	
		BRACKE			8	Mar 1, 2022	SYSTEM	\$135.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brakep1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Mar 1, 2022	SYSTEM	(\$135.00)	
					9	Mar 16, 2022	SYSTEM	\$135.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Mar 16, 2022	SYSTEM	(\$135.00)	
					10	Apr 4, 2022	SYSTEM	\$135.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.
						10	Apr 4, 2022	SYSTEM	(\$135.00)
						11	Apr 18, 2022	SYSTEM	\$135.00
					11	Apr 18, 2022	SYSTEM	(\$135.00)	
					12	Jul 18, 2022	SYSTEM	(\$135.00)	
				- Total				(\$135.00)	
			Material - Tota					(\$135.00)	
			MaterialCredit		13	Aug 2, 2022	SYSTEM	\$135.00	
				- Total				\$135.00	
			MaterialCredit	- Total				\$135.00	
	0160 -	Total						\$0.00	
	0170	CABLE- CONDUIT, 1 IN., 2 CONDUCTORS	Material		1	Nov 16, 2021	SYSTEM	\$721.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.
		CONDUCTORS			1	Nov 16, 2021	SYSTEM	(\$721.00)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
	0170 -							\$0.00	
	0180	POLE FOUNDATION (45 FT. OR 13.5	Material		11	Apr 18, 2022	SYSTEM	(\$6,015.00)	
		M			12	Jul 18, 2022	SYSTEM	(\$6,015.00)	
				- Total				(\$12,030.00)	
			Material - Tota					(\$12,030.00)	
			MaterialCredit		12	Jul 18, 2022	SYSTEM	\$6,015.00	
					13	Aug 2, 2022	SYSTEM	\$6,015.00	
				- Total				\$12,030.00	
			MaterialCredit	- Total				\$12,030.00	
								\$0.00	
	0190	HIGHWAY LIGHTING	Material		15	Nov 15, 2022	SYSTEM	(\$675.00)	
					16	Dec 2, 2022	SYSTEM	(\$675.00)	
				- Total				(\$1,350.00)	
			Material - Tota					(\$1,350.00)	
			MaterialCredit		16	Dec 2,	SYSTEM	\$675.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J6P3596	0190	MISC. HIGHWAY	MaterialCredit			2022												
		LIGHTING		- Total				\$675.00										
			MaterialCredit	- Total				\$675.00										
	0190 -	Total						(\$675.00)										
	0200	MISC. HIGHWAY LIGHTING	Material		12	Jul 18, 2022	SYSTEM	\$11,094.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user burlbe overridding Payment Estimate Exception 3 on the current Payment Estimate.									
					12	Jul 18, 2022	SYSTEM	(\$11,094.00)										
				- Total				\$0.00										
			Material - Tota	ı				\$0.00										
	0200 -	Total						\$0.00										
	0220	SIGNAL HEAD, TYPE 3B	Material		12	Jul 18, 2022	SYSTEM	\$1,408.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 4 on the current Payment Estimate.									
					12	Jul 18, 2022	SYSTEM	(\$1,408.00)										
				- Total				\$0.00										
			Material - Tota	ı				\$0.00										
	0220 -	Total						\$0.00										
	0240	SH-FLAT SHEET -	Material		13	Aug 2, 2022	SYSTEM	(\$247.50)										
		SIGNAL SIGN			14	Nov 2, 2022	SYSTEM	(\$247.50)										
					15	Nov 15, 2022	SYSTEM	(\$495.00)										
					16	Dec 2, 2022	SYSTEM	(\$495.00)										
				- Total				(\$1,485.00)										
			Material - Tota	ıl				(\$1,485.00)										
			MaterialCredit		14	Nov 2, 2022	SYSTEM	\$247.50										
														15	Nov 15, 2022	SYSTEM	\$247.50	
					16	Dec 2, 2022	SYSTEM	\$495.00										
				- Total				\$990.00										
			MaterialCredit	- Total				\$990.00										
	0240 -	Total						(\$495.00)										
	0260	POST, SIGNAL 15 FT. OR 4.6 M	Material		15	Nov 15, 2022	SYSTEM	(\$2,802.00)										
					16	Dec 2, 2022	SYSTEM	(\$2,802.00)										
				- Total				(\$5,604.00)										
			Material - Tota	ı				(\$5,604.00)										
			MaterialCredit		16	Dec 2, 2022	SYSTEM	\$2,802.00										
				- Total				\$2,802.00										
			MaterialCredit	- Total				\$2,802.00										
	0260 -	Total						(\$2,802.00)										
	0270	POST, TYPE C, 15 FT. ARM OR 4.6 M ARM	Material		12	Jul 18, 2022	SYSTEM	\$7,159.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate.									
					12	Jul 18, 2022	SYSTEM	(\$7,159.00)										
					13	Aug 2, 2022	SYSTEM	\$7,159.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					13	Aug 2,	SYSTEM	(\$7,159.00)										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3596	0270	POST, TYPE C, 15 FT. ARM OR 4.6 M ARM	Material			2022			
				- Total				\$0.00	
			Material - Total					\$0.00	
	0270 -	Total						\$0.00	
	0280	POST, TYPE B, LONGEST ARM 50 FT. OR 15.	Material		12	Jul 18, 2022	SYSTEM	\$19,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buribe overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Jul 18, 2022	SYSTEM	(\$19,825.00)	
					13	Aug 2, 2022	SYSTEM	\$19,825.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user burlbe overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Aug 2, 2022	SYSTEM	(\$19,825.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0280 -	Total						\$0.00	
	0300	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Material		1	Nov 16, 2021	SYSTEM	\$2,868.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user burlbe overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Nov 16, 2021	SYSTEM	(\$2,868.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0300 -	Total						\$0.00	
	0310	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		1	Nov 16, 2021	SYSTEM	\$882.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user burlbe overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Nov 16, 2021	SYSTEM	(\$882.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0310 -	Total						\$0.00	
	0320	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	2		1	Nov 16, 2021	SYSTEM	\$6,708.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user burlbe overridding Payment Estimate Exception 5 on the current Payment Estimate.
					1	Nov 16, 2021	SYSTEM	(\$6,708.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
			Overrun	Overrun	2	Dec 2, 2021	SYSTEM	(\$1,560.00)	
					9	Mar 16, 2022	SYSTEM	\$1,560.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',39.00000 - 39.00000, 'is applied (if non-zero).
				Overrun - T	un - Total		\$0.00		
			Overrun - Total					\$0.00	
	0320 -	Total						\$0.00	
	0340	CABLE, 8 AWG	Material		12	Jul 18,	SYSTEM	(\$80.00)	
		1 CONDUCTOR, POWER		- Total		2022		/\$20.00	
			Matorial Teta					(\$80.00)	
			Material - Tota		13	Aug 2	SYSTEM	(\$80.00) \$80.00	
			MaterialCredit		13	Aug 2, 2022	SISIEW		
				- Total				\$80.00	
	00.10		MaterialCredit	- Total				\$80.00	
	0340 -						2) (2)	\$0.00	
	0360	CABLE, 16 AWG 7	Material		12	Jul 18, 2022	SYSTEM	(\$1,815.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3596	0360	CONDUCTOR	Material	- Total				(\$1,815.00)	
			Material - Total					(\$1,815.00)	
			MaterialCredit		13	Aug 2, 2022	SYSTEM	\$1,815.00	
				- Total				\$1,815.00	
			MaterialCredit	- Total				\$1,815.00	
	0360 -	· Total						\$0.00	
	0370	PULL BOX, PREFORMED CLASS 1	Material		1	Nov 16, 2021	SYSTEM	\$1,079.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment Estimate.
					1	Nov 16, 2021	SYSTEM	(\$1,079.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0370 -	Total						\$0.00	
	0390	PULL BOX, PREFORMED CLASS 3	Material		2	Dec 2, 2021	SYSTEM	\$1,714.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buribe overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Dec 2, 2021	SYSTEM	(\$1,714.00)	
					3	Dec 16, 2021	SYSTEM	\$1,714.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Dec 16, 2021	SYSTEM	(\$1,714.00)	
					4	Jan 3, 2022	SYSTEM	\$1,714.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user burlbe overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jan 3, 2022	SYSTEM	(\$1,714.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0390 - Total							\$0.00	
	0400	BASE, CONCRETE			10	Apr 4, 2022	SYSTEM	(\$14,008.60)	
					11	Apr 18, 2022	SYSTEM	(\$14,008.60)	
					12	Jul 18, 2022	SYSTEM	(\$14,008.60)	
					13	Aug 2, 2022	SYSTEM	(\$14,008.60)	
					14	Nov 2, 2022	SYSTEM	(\$14,008.60)	
					15	Nov 15, 2022	SYSTEM	(\$14,008.60)	
					16	Dec 2, 2022	SYSTEM	(\$14,008.60)	
				- Total				(\$98,060.20)	
			Material - Tota	ıl			(\$98,060.20)		
			MaterialCredit		11	Apr 18, 2022	SYSTEM	\$14,008.60	
					12	Jul 18, 2022	SYSTEM	\$14,008.60	
					13	Aug 2, 2022	SYSTEM	\$14,008.60	
					14	Nov 2, 2022	SYSTEM	\$14,008.60	
					15	Nov 15, 2022	SYSTEM	\$14,008.60	
					16	Dec 2, 2022	SYSTEM	\$14,008.60	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3596	0400	BASE,	MaterialCredit	- Total				\$84,051.60	
		CONCRETE	MaterialCredit - Total					\$84,051.60	
	0400 - Total							(\$14,008.60)	
	0420	MISC.	Material		11	Apr 18, 2022	SYSTEM	(\$16,148.00)	
					12	Jul 18, 2022	SYSTEM	\$16,148.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user burlbe overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Jul 18, 2022	SYSTEM	(\$16,148.00)	
					13	Aug 2, 2022	SYSTEM	(\$16,148.00)	
					14	Nov 2, 2022	SYSTEM	(\$16,148.00)	
					15	Nov 15, 2022	SYSTEM	(\$16,148.00)	
					16	Dec 2, 2022	SYSTEM	(\$16,148.00)	
				- Total				(\$80,740.00)	
			Material - Tota	ı				(\$80,740.00)	
			MaterialCredit		12	Jul 18, 2022	SYSTEM	\$16,148.00	
					14	Nov 2, 2022	SYSTEM	\$16,148.00	
					15	Nov 15, 2022	SYSTEM	\$16,148.00	
					16	Dec 2, 2022	SYSTEM	\$16,148.00	
				- Total				\$64,592.00	
			MaterialCredit - Total					\$64,592.00	
	0420 -	- Total						(\$16,148.00)	
	0430	MISC.	Material		15	Nov 15, 2022	SYSTEM	(\$1,104.00)	
					16	Dec 2, 2022	SYSTEM	(\$1,104.00)	
				- Total				(\$2,208.00)	
			Material - Tota					(\$2,208.00)	
			Material - Tota	I	16	Dec 2, 2022	SYSTEM	(\$2,208.00) \$1,104.00	
				l - Total	16		SYSTEM		
				- Total	16		SYSTEM	\$1,104.00	
	0430 -	- Total	MaterialCredit	- Total	16		SYSTEM	\$1,104.00 \$1,104.00	
	0430 - 0440	- Total MISC.	MaterialCredit	- Total	16		SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user burlbe overridding Payment Estimate Exception 15 on the current Payment Estimate.
			MaterialCredit MaterialCredit	- Total		2022 Jul 18,		\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00)	Estimate Item Adjustment (0014) due to user burlbe overridding Payment
			MaterialCredit MaterialCredit	- Total	12	Jul 18, 2022 Jul 18,	SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00) \$230.00	Estimate Item Adjustment (0014) due to user burlbe overridding Payment
			MaterialCredit MaterialCredit	- Total - Total - Total	12	Jul 18, 2022 Jul 18,	SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00) \$230.00	Estimate Item Adjustment (0014) due to user burlbe overridding Payment
		MISC.	MaterialCredit MaterialCredit Material	- Total - Total - Total	12	Jul 18, 2022 Jul 18,	SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00) \$230.00 (\$230.00)	Estimate Item Adjustment (0014) due to user burlbe overridding Payment
	0440	MISC.	MaterialCredit MaterialCredit Material	- Total - Total - Total	12	Jul 18, 2022 Jul 18,	SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00) \$230.00 (\$230.00) \$0.00	Estimate Item Adjustment (0014) due to user burlbe overridding Payment
	0440	MISC. - Total 2 IN. PSST	MaterialCredit MaterialCredit Material Material	- Total - Total - Total	12	Jul 18, 2022 Jul 18, 2022 Jul 2022	SYSTEM SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00) \$230.00 (\$230.00) \$0.00 \$0.00	Estimate Item Adjustment (0014) due to user burlbe overridding Payment
	0440	MISC. - Total 2 IN. PSST	MaterialCredit MaterialCredit Material Material	- Total - Total - Total	12	Jul 18, 2022 Jul 18, 2022 Nov 2, 2022 Nov 15,	SYSTEM SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00) \$230.00 (\$230.00) \$0.00 \$0.00 (\$711.00)	Estimate Item Adjustment (0014) due to user burlbe overridding Payment
	0440	MISC. - Total 2 IN. PSST	MaterialCredit MaterialCredit Material Material	- Total - Total - Total	12 12 14 15	Jul 18, 2022 Jul 18, 2022 Nov 2, 2022 Nov 15, 2022 Dec 2,	SYSTEM SYSTEM SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00) \$230.00 (\$230.00) \$0.00 \$0.00 (\$711.00)	Estimate Item Adjustment (0014) due to user burlbe overridding Payment
	0440	MISC. - Total 2 IN. PSST	MaterialCredit MaterialCredit Material Material	- Total - Total	12 12 14 15	Jul 18, 2022 Jul 18, 2022 Nov 2, 2022 Nov 15, 2022 Dec 2,	SYSTEM SYSTEM SYSTEM	\$1,104.00 \$1,104.00 \$1,104.00 (\$1,104.00) \$230.00 (\$230.00) \$0.00 \$0.00 (\$711.00) (\$711.00)	Estimate Item Adjustment (0014) due to user burlbe overridding Payment

Dec 6, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
		·	Туре	Adjustment Type	Number	Date	Ву		
J6P3596	0460	2 IN. PSST POST - 12 GA.	MaterialCredit			2022			
		F031 - 12 GA.			16	Dec 2, 2022	SYSTEM	\$711.00	
				- Total				\$1,422.00	
			MaterialCredit - Total					\$1,422.00	
	0460 - Total							(\$711.00)	
	0470	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		14	Nov 2, 2022	SYSTEM	(\$297.00)	
					15	Nov 15, 2022	SYSTEM	(\$297.00)	
					16	Dec 2, 2022	SYSTEM	(\$297.00)	
				- Total	- Total			(\$891.00)	
			Material - Tota	ı				(\$891.00)	
			MaterialCredit		15	Nov 15, 2022	SYSTEM	\$297.00	
					16	Dec 2, 2022	SYSTEM	\$297.00	
				- Total				\$594.00	
			MaterialCredit	- Total				\$594.00	
	0470 -	· Total						(\$297.00)	
	0480	SH-FLAT SHEET	Material		15	Nov 15, 2022	SYSTEM	(\$60.00)	
					16	Dec 2, 2022	SYSTEM	(\$60.00)	
				- Total				(\$120.00)	
			Material - Tota	ı				(\$120.00)	
			MaterialCredit		16	Dec 2, 2022	SYSTEM	\$60.00	
				- Total				\$60.00	
			MaterialCredit	terialCredit - Total					
	0480 - Total							(\$60.00)	
	0490	SHF-FLAT SHEET FLUORESCENT	Material		13	Aug 2, 2022	SYSTEM	(\$1,344.00)	
					14	Nov 2, 2022	SYSTEM	(\$2,478.00)	
					15	Nov 15, 2022	SYSTEM	(\$3,150.00)	
					16	Dec 2, 2022	SYSTEM	(\$3,150.00)	
				- Total				(\$10,122.00)	
			Material - Tota					(\$10,122.00)	
			MaterialCredit		14	Nov 2, 2022	SYSTEM	\$1,344.00	
					15	Nov 15, 2022	SYSTEM	\$2,478.00	
					16	Dec 2, 2022	SYSTEM	\$3,150.00	
				- Total				\$6,972.00	
			MaterialCredit	- Total				\$6,972.00	
	0490 -	Total						(\$3,150.00)	
J6P3596	- Total							(\$42,157.60)	
Overall -	Total							(\$42,157.60)	