

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 3, 2022

	210820-F02 Reinhold Electric, Inc.	January 1, 2022	Original Contract Amount Net Change Order Amount Current Contract Amount	t \$0.00
4 15 1				D 11

Approval Date		By User
January 3, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	burlbe
January 3, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	vancef1
January 4, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
June 1, 2022	June 1, 2022		38.35%

	Contract Informational Dates											
Date Description	Original Completion Date	Current Completion Date	No Milestones Exist for Contract									
Acceptance Date												
Awarded Date	September 8, 2021	September 8, 2021										
Letting Date	August 20, 2021	August 20, 2021										
Notice to Proceed Date	October 4, 2021	October 4, 2021										
Open to Traffic Date												
Work Began Date	November 4, 2021	November 4, 2021										

Contract Total P	ay For Estimate No. 4			
		This Estimate	Previous	To Date
210820-F02				
	Total Posted Items Pay	\$90.00	\$94,009.00	\$94,099.00
	Gross Item Adjustments	\$0.00	(\$1,560.00)	(\$1,560.00)
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
	·		\$92,449.00	\$92,539.00
Contract Total P	avable This Estimate:	\$90.00		

Items Paid This Estimate Period

Project Number	ject Number Line Number Item Code		Item Description Unit Unit P			Current Installed Qty	Current Installed Amount				
J6P3596	0090	8061005	ROCK DITCH CHECK	LF	\$90.000	1	\$90.00				
Project J6P3596 -	Project J6P3596 - Total Overall - Total										
Overall - Total											

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

	,	ments Exist on Contract ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Other Item Comments Adjustment Type Adjustment Type				Line Item Adjustment Unit Price	Adjustment amount
J6P3596	0090	ROCK DITCH CHECK	Material			-1	\$90.00	(\$90.00)
	0090	ROCK DITCH CHECK	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.	1	\$90.00	\$90.00
	0160	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material			-270	\$0.50	(\$135.00)
	0160	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.	270	\$0.50	\$135.00
	0390	PULL BOX, PREFORMED	Material			-1	\$1,714.00	(\$1,714.00)

Revision 4/1/2020 Page 1 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 3, 2022

Progre		imate Number 4	Contract ID Prime Contr	210820 actor Reinho		. Pay Period End January 1, 2022 Net C	nal Contract Change Orde ent Contract	245,391.00 0.00 245,391.00	
Project Number	·			Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	,	
J6P3596		CLASS 3							
	0390	PULL BOX, F	PREFORMED CLASS 3			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user burlbe overridding Payment Estimate Exception 3 on the current Payment Estimate.	1	\$1,714.00	\$1,714.00
Total									\$0.00

Revision 4/1/2020 Page 2 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(Contract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J6P3596	FAF-21-2(88)	Signal and lighting installation	21	JEFFERSON	at Rte. 110 and Li	berty School Rd. intersection	n
Γotals by .	Job Numbers						
J6P3596	Posted Ite Gross Iter	n Adjustments	s Gross Ite	m Pay	This Estimate \$90.00 \$0.00 \$90.00	Previous \$94,009.00 (\$1,560.00) \$92,449.00	To Date \$94,099.00 (\$1,560.00) \$92,539.00
		ve d Damages itract Adjustm			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 8061005, Project Item Line Number 0090, Material Set 806100596, Material 0806TEC - Temporary Erosion Control, Acceptance Action Generic 0806TEC is insufficient.	Working with contractor and SL Materials to resolve this exception.	burlbe	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9017110, Project Item Line Number 0160, Material Set 901711096, Material 0901LHXX - Highway Lighting Material, Acceptance Action Generic 0901LHXX is insufficient.	Working with contractor and SL Materials to resolve this exception.	burlbe	Overridden
Estimate Exception Type: Insufficient Materials: Project J6P3596, Item 9028812, Project Item Line Number 0390, Material Set 902881296, Material 1062PBPF - Pull Box Preformed Poly Resin Fiber, Acceptance Action Generic 1062PBPF is insufficient.	Working with contractor and SL Materials to resolve this exception.	burlbe	Overridden
Estimate Exception Type: Item Overrun: Contract 210820-F02, Contract Project J6P3596, Project Item Line Number 0320, Contract Line Item Number 0320, Item 9027200, Minor Item.	CO Forthcoming.	burlbe	Acknowledged

Revision 4/1/2020 Page 4 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor- generated date)
0820-F02	J6P3596	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$1,200.00	\$0.0
		0001	0020	6083006	6 IN. CONCRETE MEDIAN STRIP	23.00	0.00	23.00	SQYD	0.00	\$210.00	\$0.0
		0001	0030	6169901	MISC.TEMPORARY TRAFFIC CONTROL		0.00	1.00	LS	0.50	\$12,000.00	\$6,000.0
		0001	0040	6169902	MISC.NTCIP Compliant Changeable Message Sign, Contractor Furnished/Retained	3.00	0.00	3.00	EA	3.00	\$1,000.00	\$3,000.0
		0001	0050	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$6,500.00	\$4,875.0
		0001	0060	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	47.00	0.00	47.00	LF	0.00	\$41.00	\$0.0
		0001	0070	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	60.00	0.00	60.00	LF	0.00	\$13.00	\$0.
		0001	0800	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$450.00	\$0.
		0001	0090	8061005	ROCK DITCH CHECK	5.00	0.00	5.00	LF	1.00	\$90.00	\$90
		0001	0100	8061016	SEDIMENT REMOVAL	10.00	0.00	10.00	CUYD	0.00	\$60.00	\$0.
		0001	0110	8061019	SILT FENCE	420.00	0.00	420.00	LF	0.00	\$1.00	\$0
		0020	0120	9014003	CONDUIT, 3 IN. RIGID, PUSHED	180.00	0.00	180.00	LF	180.00	\$42.00	\$7,560
		0020	0130	9015010	TRENCHING TYPE I	240.00	0.00	240.00	LF	240.00	\$7.50	\$1,800
		0020	0140	9015020	TRENCHING TYPE II	30.00	0.00	30.00	LF	30.00	\$52.00	\$1,560
		0020	0150	9016110	PULL BOX, PREFORMED CLASS 1	4.00	0.00	4.00	EA	4.00	\$1,079.00	\$4,316
		0020	0160	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	270.00	0.00	270.00	LF	270.00	\$0.50	\$135
		0020	0170	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	770.00	0.00	770.00	LF	770.00	\$3.50	\$2,695
		0020	0180	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	3.00	0.00	3.00	EA	0.00	\$2,005.00	\$0
		0020	0190	9019902	MISC.170W TOP MOUNTED LED-B LUMINAIRE	3.00	0.00	3.00	EA	0.00	\$450.00	\$0
			0200	9019902	MISC.45 FT. TOP MOUNT POLE	3.00	0.00	3.00	EA	0.00	\$3,698.00	\$0
		0030	0210	9020111	SIGNAL HEAD, TYPE 1T	3.00	0.00	3.00	EA	0.00	\$524.00	\$0
			9020513	SIGNAL HEAD, TYPE 3B	6.00	0.00	6.00	EA	0.00	\$704.00	\$0	
		0030	0230	9020514	SIGNAL HEAD, TYPE 4B	1.00	0.00	1.00	EA	0.00	\$798.00	\$0
		0030	0240	9020833	SH-FLAT SHEET - SIGNAL SIGN	15.00	0.00	15.00	SQFT	0.00	\$33.00	\$0
		0030	0250	9020834	SIGNAL SIGN, MOUNTING HARDWARE	2.00	0.00	2.00	EA	0.00	\$22.00	\$0
		0030	0260	9022715	POST, SIGNAL 15 FT. OR 4.6 M	3.00	0.00	3.00	EA	0.00	\$934.00	\$0
		0030	0270	9023215	POST, TYPE C, 15 FT. ARM OR 4.6 M ARM	1.00	0.00	1.00	EA	0.00	\$7,159.00	\$0
		0030	0280	9023350	POST, TYPE B, LONGEST ARM 50 FT. OR 15.2 M	1.00	0.00	1.00	EA	0.00	\$19,825.00	\$0
		0030	0290	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	0.00	\$11,690.00	\$1
		0030	0300	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	1,852.00	0.00	1,852.00	LF	1,812.00	\$12.00	\$21,744
		0030	0310	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	193.00	0.00	193.00	LF	183.00	\$14.00	\$2,562
		0030	0320	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	235.00	0.00	235.00	LF	275.00	\$39.00	\$10,725
		0030	0330	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	211.00	0.00	211.00	LF	211.00	\$42.00	\$8,862
		0030	0340	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	80.00	0.00	80.00	LF	0.00	\$1.00	\$0
		0030	0350	9028309	CABLE, 16 AWG 3 CONDUCTOR	2,940.00	0.00	2,940.00	LF	0.00	\$1.50	\$(
		0030	0360	9028311	CABLE, 16 AWG 7 CONDUCTOR	1,210.00	0.00	1,210.00	LF	0.00	\$1.50	\$(
		0030	0370	9028810	PULL BOX, PREFORMED CLASS 1	13.00	0.00	13.00	EA	13.00	\$1,079.00	\$14,02
		0030	0380	9028811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	2.00	\$1,217.00	\$2,434
		0030	0390	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$1,714.00	\$1,714
		0030	0400	9029100	BASE, CONCRETE	9.20	0.00	9.20	CUYD	0.00	\$1,780.00	\$(
		0030	0410	9029902	MISC.ATC Traffic Signal Controller	1.00	0.00	1.00	EA	0.00	\$3,920.00	\$(
		0030	0420	9029902	MISC.COMBINATION PAD-MOUNTED 120/240V PS & LIGHTING	1.00	0.00	1.00	EA	0.00	\$16,148.00	\$(
					CS WITH UPS							
		0030	0430	9029902	MISC.Network Connected Signal Monitor MISC.Retroreflective Backplates	7.00	0.00	7.00	EA	0.00	\$1,104.00	\$0

Revision 4/1/2020 Page 5 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)		
210820-F02	J6P3596	0030	0450	9029902	MISC.SL VIDEO DETECTION SYSTEM	4.00	0.00	4.00	EA	0.00	\$3,907.00	\$0.00		
				0040	0460	9031270A	2 IN. PSST POST - 12 GA.	87.00	0.00	87.00	LF	0.00	\$18.00	\$0.00
		0040	0470	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	21.00	0.00	21.00	LF	0.00	\$33.00	\$0.00		
				0040	0480	9035004A	SH-FLAT SHEET	2.00	0.00	2.00	SQFT	0.00	\$30.00	\$0.00
		0040	0490	9035069A	SHF-FLAT SHEET FLUORESCENT	75.00	0.00	75.00	SQFT	0.00	\$42.00	\$0.00		
	Project J6P3596 - Total Value Posted to Date as of Report Generated Date													
210820-F02 Ove	10820-F02 Overall - Total Value Posted to Date as of Report Generated Date													

Revision 4/1/2020 Page 6 of 9



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J6P3596

Line Number	Item Code	Description		DWR Approval Date		Units			Offset/ Distance	Offset/ Distance	Comments
0090	8061005	ROCK DITCH CHECK	12/21/21	12/30/21	1.00	LF	Rte 21 LT	907			

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 7 of 9



Line Item Adjustments by Estimate

Contract ID:190621-F01

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6P3596	0090	ROCK DITCH CHECK	Material		4	Jan 3, 2022	SYSTEM	\$90.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Jan 3, 2022	SYSTEM	(\$90.00)	
				- Total				\$0.00	
		Material - Total							
	0090 -	Total						\$0.00	
	0160		Material		1	Nov 16, 2021	SYSTEM	\$45.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Nov 16, 2021	SYSTEM	(\$45.00)	
					2	Dec 2, 2021	SYSTEM	\$45.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Dec 2, 2021	SYSTEM	(\$45.00)	
					3	Dec 16, 2021	SYSTEM	\$135.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user burlbe overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Dec 16, 2021	SYSTEM	(\$135.00)	
					4	Jan 3, 2022	SYSTEM	\$135.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Jan 3, 2022	SYSTEM	(\$135.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0160 -	Total						\$0.00	
	0170	CABLE- CONDUIT, 1 IN., 2 CONDUCTORS	Material		1	Nov 16, 2021	SYSTEM	\$721.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Nov 16,	SYSTEM	(\$721.00)	
						2021			
				- Total		2021		\$0.00	
			Material - To			2021		\$0.00 \$0.00	
	0170 -	· Total	Material - To			2021			
	0170 - 0300	CONDUIT, 2 IN., TRENCH WITH TRACER			1	Nov 16, 2021	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user burlbe overridding Payment Estimate Exception 3 on the current Payment Estimate.
		CONDUIT, 2 IN., TRENCH			1	Nov 16,	SYSTEM	\$0.00 \$0.00 \$2,868.00	Estimate Item Adjustment (0003) due to user burlbe overridding Payment
		CONDUIT, 2 IN., TRENCH WITH TRACER				Nov 16, 2021		\$0.00 \$0.00 \$2,868.00	Estimate Item Adjustment (0003) due to user burlbe overridding Payment
		CONDUIT, 2 IN., TRENCH WITH TRACER		otal - Total		Nov 16, 2021		\$0.00 \$0.00 \$2,868.00 (\$2,868.00)	Estimate Item Adjustment (0003) due to user burlbe overridding Payment
		CONDUIT, 2 IN., TRENCH WITH TRACER WIRE	Material	otal - Total		Nov 16, 2021		\$0.00 \$0.00 \$2,868.00 (\$2,868.00) \$0.00	Estimate Item Adjustment (0003) due to user burlbe overridding Payment
	0300	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE Total CONDUIT, 3 IN., TRENCH WITH TRACER	Material Material - To	otal - Total		Nov 16, 2021		\$0.00 \$0.00 \$2,868.00 (\$2,868.00) \$0.00	Estimate Item Adjustment (0003) due to user burlbe overridding Payment
	0300	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE Total CONDUIT, 3 IN., TRENCH	Material Material - To	otal - Total	1	Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM	\$0.00 \$0.00 \$2,868.00 (\$2,868.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user buribe overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buribe overridding Payment
	0300	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE Total CONDUIT, 3 IN., TRENCH WITH TRACER	Material Material - To	otal - Total	1	Nov 16, 2021 Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM	\$0.00 \$0.00 \$2,868.00 (\$2,868.00) \$0.00 \$0.00 \$882.00	Estimate Item Adjustment (0003) due to user burlbe overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user burlbe overridding Payment
	0300	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE Total CONDUIT, 3 IN., TRENCH WITH TRACER	Material Material - To	- Total - Total	1	Nov 16, 2021 Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM	\$0.00 \$0.00 \$2,868.00 (\$2,868.00) \$0.00 \$0.00 \$882.00	Estimate Item Adjustment (0003) due to user buribe overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buribe overridding Payment
	0300	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE Total CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material - To	- Total - Total	1	Nov 16, 2021 Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM	\$0.00 \$0.00 \$2,868.00 (\$2,868.00) \$0.00 \$0.00 \$882.00 (\$882.00)	Estimate Item Adjustment (0003) due to user buribe overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buribe overridding Payment
	0300 - 0310	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE Total CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material - To	- Total - Total	1	Nov 16, 2021 Nov 16, 2021 Nov 16, 2021 Nov 16, 2021	SYSTEM	\$0.00 \$0.00 \$2,868.00) (\$2,868.00) \$0.00 \$0.00 \$882.00 (\$882.00) \$0.00	Estimate Item Adjustment (0003) due to user buribe overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buribe overridding Payment

Jan 5, 2022



Line Item Adjustments by Estimate

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J6P3596	0320	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	Material	- Total				\$0.00					
			Material - To	otal				\$0.00					
			Overrun	Overrun	2	Dec 2, 2021	SYSTEM	(\$1,560.00)					
				Overrun - T	otal			(\$1,560.00)					
			Overrun - To	otal				(\$1,560.00)					
	0320 -	320 - Total						(\$1,560.00)					
	0370	PULL BOX, PREFORMED CLASS 1	Material		1	Nov 16, 2021	SYSTEM	\$1,079.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user burlbe overridding Payment Estimate Exception 6 on the current Payment Estimate.				
					1	Nov 16, 2021	SYSTEM	(\$1,079.00)					
				- Total				\$0.00					
			Material - To	otal				\$0.00					
	0370 -	Total						\$0.00					
	0390	PULL BOX, PREFORMED CLASS 3	Material		2	Dec 2, 2021	SYSTEM	\$1,714.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					2	Dec 2, 2021	SYSTEM	(\$1,714.00)					
					3	Dec 16, 2021	SYSTEM	\$1,714.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user burlbe overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					3	Dec 16, 2021	SYSTEM	(\$1,714.00)					
									4	Jan 3, 2022	SYSTEM	\$1,714.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user burlbe overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Jan 3, 2022	SYSTEM	(\$1,714.00)					
				- Total				\$0.00					
			Material - Total					\$0.00					
	0390 -	Total						\$0.00					
6P3596	- Total							(\$1,560.00)					
verall -	Total						(\$1,560.00)						