

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 3, 2023

Progress Estimate Number	Contract ID	211015-B01	Pay Period Start	December 2, 2022	Original Contract Amount	\$725,803.61
8	Prime Contractor	Emery Sapp & Sons, Inc.	Pay Period End		Net Change Order Amount Current Contract Amount	

Approval Date		By User
January 3, 2023	Generated and Approved (and should be considered Draft) at the Project Office Level by	worthk
January 3, 2023	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	lincom
January 4, 2023	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
November 1, 2022	November 1, 2022		94.22%

	Contract Informational Dates											
Date Description	Original Completion Date	No Milestones Exist for Contract										
Acceptance Date												
Awarded Date	November 3, 2021	November 3, 2021										
Letting Date	October 15, 2021	October 15, 2021										
Notice to Proceed Date	May 22, 2022	May 22, 2022										
Open to Traffic Date												
Work Began Date												

Contract Total Pay For Estimate No. 8								
		This Estimate	Previous	To Date				
211015-B01								
1	Total Posted Items Pay	\$0.00	\$683,879.32	\$683,879.32				
	Gross Item Adjustments	\$0.00	\$302,672.60	\$302,672.60				
I	ncentive	\$0.00	\$0.00	\$0.00				
	Disincentive	\$0.00	\$0.00	\$0.00				
L	₋iquidated Damage	\$0.00	\$0.00	\$0.00				
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00				
			\$986,551.92	\$986,551.92				
Contract Total Payable	This Estimate:	\$0.00						

Items Paid This Estimate Period

No Data Available Contract Adjustments This Estimate

No Contrac	ct Adjus	stments Exist on Contract						
Line Item .	<u>Adjustı</u>	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2P3281	0050	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-21	\$1.00	(\$21.00)
	0050	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user worthk overridding Payment Estimate Exception 2 on the current Payment Estimate.	21	\$1.00	\$21.00
	0800	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-280	\$6.20	(\$1,736.00)
	0080	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user worthk overridding Payment Estimate Exception 3 on the current Payment Estimate.	280	\$6.20	\$1,736.00
	0090	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	Material			-20	\$12.00	(\$240.00)
	0090	DOWEL BAR (FURNISHING	Material		This adjustment offsets the original system-	20	\$12.00	\$240.00

Revision 4/1/2020 Page 1 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 3, 2023

Progress Estimate Number
8 Contract ID 211015-B01 Pay Period Start December 2, 2022 Original Contract Amount \$725,803.61 Pay Period End January 1, 2023 Net Change Order Amount \$0.00 \$725,803.61

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2P3281		AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR			generated Material Payment Estimate Item Adjustment (0003) due to user worthk overridding Payment Estimate Exception 5 on the current Payment Estimate.			
	0100	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material			-10	\$5.75	(\$57.50)
	0100	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user worthk overridding Payment Estimate Exception 8 on the current Payment Estimate.	10	\$5.75	\$57.50
	0110	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	Material			-63	\$1,270.00	(\$80,010.00)
	0110	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user worthk overridding Payment Estimate Exception 11 on the current Payment Estimate.	63	\$1,270.00	\$80,010.00
	0130	CROSS STITCH TIE BAR	Material			-66	\$113.00	(\$7,458.00)
	0130	CROSS STITCH TIE BAR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user worthk overridding Payment Estimate Exception 14 on the current Payment Estimate.	66	\$113.00	\$7,458.00
	0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material			-4	\$3,511.00	(\$14,044.00)
	0300	TYPE A CRASHWORTHY END TERMINAL (MASH)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate.	4	\$3,511.00	\$14,044.00
Total								\$0.00

Revision 4/1/2020 Page 2 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information								
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work				
J2P3281	FAF 24-3(51)	Pavement repair and diamond grinding	24	MARION	from 0.9 mile east of Rte. 61 to Mississippi River at West Quincy				

Totals by Job Nur	mbers			
J2P3281		This Estimate	Previous	To Date
Po	osted Item Pay	\$0.00	\$683,879.32	\$683,879.32
Gı	ross Item Adjustments	\$0.00	\$302,672.60	\$302,672.60
	Gross Item Pay	\$0.00	\$875,290.47	\$875,290.47
In	centive	\$0.00	\$0.00	\$0.00
Di	sincentive	\$0.00	\$0.00	\$0.00
Li	quidated Damages	\$0.00	\$0.00	\$0.00
01	ther Contract Adjustments	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 3 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered	Status
		Ву	
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6063014, Project Item Line Number 0300, Material Set 606301496, Material 1040GRCWA - Crashworthy End Terminal Type A, Acceptance Action Generic 1040GRCWA is insufficient.	Working with NE Materials to resolve discrepancies on guardrail items.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131012, Project Item Line Number 0050, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Working with QC/QA to resolve discrepancies on subgrade compaction.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131015, Project Item Line Number 0080, Material Set 613101596, Material 1057JMDBEC6.10 - Dowel Bar Epoxy Ctd Gr60 1" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131015, Project Item Line Number 0080, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131017, Project Item Line Number 0090, Material Set 613101796, Material 1057JMDBEC6.11 - Dowel Bar Epoxy Ctd Gr60 1 1/4 @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131017, Project Item Line Number 0090, Material Set 613101796, Material 1057JMDAEC6.11 - Dowel Assemblies Epoxy Ctd Gr60 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131017, Project Item Line Number 0090, Material Set 613101796, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131018, Project Item Line Number 0100, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131018, Project Item Line Number 0100, Material Set 613101896, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6131018, Project Item Line Number 0100, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6132018, Project Item Line Number 0110, Material Set 613201896, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6132018, Project Item Line Number 0110, Material Set 613201896, Material 1036RSWFPLW6W4 - W6.3-W4 Plain Weld Wire Fabric for PCCP@, Acceptance Action Generic ReSteelFabric is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6132018, Project Item Line Number 0110, Material Set 613201896, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6134002, Project Item Line Number 0130, Material Set 613400296, Material 1036RSDFEC42M19 - Rein Steel EC No. 6/M19 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden
Estimate Exception Type: Insufficient Materials: Project J2P3281, Item 6134002, Project Item Line Number 0130, Material Set 613400296, Material 0704CMRP - Rapid Set Concrete Patching Material, Acceptance Action Generic 0704CMRP is insufficient.	Working with contractor in materials used in full depth concrete patching.	worthk	Overridden

Revision 4/1/2020 Page 4 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11015-B01	J2P3281	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$3,511.00	\$3,511.00
		0001	0020	2153000	SHAPING SLOPES, CLASS III	6.00	0.00	6.00	100F	6.00	\$1,536.00	\$9,216.0
		0001	0030	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$750.00	\$0.00
		0001	0040	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	205.50	0.00	205.50	SQYD	205.50	\$286.00	\$58,773.0
		0001	0050	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	21.00	0.00	21.00	SQYD	21.00	\$1.00	\$21.0
		0001	0060	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	21.00	0.00	21.00	SQYD	21.00	\$1.00	\$21.0
		0001	0070	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	702.00	0.00	702.00	LF	702.00	\$5.00	\$3,510.0
		0001	0800	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	280.00	0.00	280.00	EA	280.00	\$6.20	\$1,736.0
		0001	0090	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	20.00	0.00	20.00	EA	20.00	\$12.00	\$240.0
		0001	0100	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	10.00	0.00	10.00	EA	10.00	\$5.75	\$57.5
		0001	0110	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	65.30	0.00	65.30	CUYD	63.00	\$1,270.00	\$80,010.0
		0001	0120	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	523.00	0.00	523.00	SQYD	505.00	\$245.00	\$123,725.0
		0001	0130	6134002	CROSS STITCH TIE BAR	66.00	0.00	66.00	EA	66.00	\$113.00	\$7,458.0
		0001	0140	6161005	CONSTRUCTION SIGNS	1,433.00	0.00	1,433.00	SQFT	1,433.00	\$5.00	\$7,165.0
		0001	0150	6161025	CHANNELIZER (TRIM LINE)	225.00	0.00	225.00	EA	225.00	\$22.00	\$4,950.0
		0001	0160	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$121.00	\$1,210.0
		0001	0170	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$549.00	\$1,098.0
		0001	0180	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,743.00	\$5,486.0
		0001	0190	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	4.00	\$2,195.00	\$8,780.0
		0001	0200	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$47,000.00	\$47,000.0
		0001	0210	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	32.00	0.00	32.00	EA	0.00	\$356.00	\$0.0
		0001	0220	6205901A	4 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	12,179.00	0.00	12,179.00	LF	0.00	\$0.19	\$0.0
		0001	0230	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	47,301.00	0.00	47,301.00	LF	0.00	\$0.24	\$0.
		0001	0240	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	25,546.00	0.00	25,546.00	LF	0.00	\$0.24	\$0.0
		0001	0250	6206125A	24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	173.00	0.00	173.00	LF	0.00	\$11.00	\$0.0
		0001	0260	6209901	MISC.OPTIONAL TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.00	\$1.00	\$0.0
		0001	0270	6223010	DIAMOND GRINDING (CONCRETE PAVEMENT)	104,278.00	0.00	104,278.00	SQYD	104,278.00	\$2.69	\$280,507.
		0010	0280	6061060	MGS GUARDRAIL	250.00	0.00	250.00	LF	250.00	\$40.00	\$10,000.0
		0010	0290	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	4.00	0.00	4.00	EA	4.00	\$3,840.00	\$15,360.0
	0010 0300 6063014 TYPE A CRASHWORTHY END TERMINAL (MASH)						0.00	4.00	EA	4.00	\$3,511.00	\$14,044.0
	Project J	2P3281 - To	otal Value	Posted to D	ate as of Report Generated Date							\$683,879.3
1015-B01 Ove	rall - Total	Value Pos	ted to Da	te as of Repo	ort Generated Date							\$683,879.

Revision 4/1/2020 Page 5 of 11



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 6 of 11

MoDOT

Line Item Adjustments by Estimate

roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
P3281	0040	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		4	Oct 18, 2022	SYSTEM	\$30,030.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					4	Oct 18, 2022	SYSTEM	\$30,030.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					4	Oct 18, 2022	SYSTEM	(\$30,030.00)									
				- Total				\$30,030.00									
			Material - Tota	al				\$30,030.00									
			MaterialCredit		5	Nov 2, 2022	SYSTEM	\$30,030.00									
				- Total				\$30,030.00									
			MaterialCredit	it - Total				\$30,030.00									
	0040 -	Total						\$60,060.00									
	0050	SUBGRADE COMPACTION (6 IN. DEPTH)	Material		4	Oct 18, 2022	SYSTEM	\$11.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user worthk overridding Payment Estimate Exception 2 on the current Payment Estimate.								
		(PAVEM			4	Oct 18, 2022	SYSTEM	\$11.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user worthk overridding Payment Estimate Exception 2 on the current Payment Estimate.								
					4	Oct 18, 2022	SYSTEM	(\$11.00)									
					5	Nov 2, 2022	SYSTEM	\$21.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate.								
						5	Nov 2, 2022	SYSTEM	(\$21.00)								
					6	Nov 16, 2022	SYSTEM	\$21.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate.								
					6	Nov 16, 2022	SYSTEM	(\$21.00)									
					7	Dec 2, 2022	SYSTEM	\$21.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user worthk overridding Payment Estimate Exception 2 on the current Payment Estimate.								
													7	Dec 2, 2022	SYSTEM	(\$21.00)	
														8	Jan 3, 2023	SYSTEM	\$21.00
					8	Jan 3, 2023	SYSTEM	(\$21.00)									
				- Total				\$11.00									
			Material - Tota					\$11.00									
			MaterialCredit		5	Nov 2, 2022	SYSTEM	\$11.00									
				- Total				\$11.00									
			MaterialCredit	- Total				\$11.00									
	0050 -	Total						\$22.00									
	0060	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN.	Material		4	Oct 18, 2022	SYSTEM	\$11.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user worthk overridding Payment Estimate Exception 3 on the current Payment Estimate.								
		TH			4	Oct 18, 2022	SYSTEM	\$11.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user worthk overridding Payment Estimate Exception 3 on the current Payment Estimate.								
					4	Oct 18, 2022	SYSTEM	(\$11.00)									
				- Total				\$11.00									
			Material - Tota	ı				\$11.00									
			MaterialCredit		5	Nov 2, 2022	SYSTEM	\$11.00									
				- Total				\$11.00									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3281	0060	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN.	MaterialCredit	- Total				\$11.00	
	0060	Tetal						\$22.00	
	0080	DOWEL BAR (DRILLING, FURNISHING AND	Material		4	Oct 18, 2022	SYSTEM	\$899.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user worthk overridding Payment Estimate Exception 4 on the current Payment Estimate.
		INST			4	Oct 18, 2022	SYSTEM	\$899.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user worthk overridding Payment Estimate Exception 4 on the current Payment Estimate.
					4	Oct 18, 2022	SYSTEM	(\$899.00)	
					5	Nov 2, 2022	SYSTEM	\$1,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user worthk overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Nov 2, 2022	SYSTEM	(\$1,736.00)	
					6	Nov 16, 2022	SYSTEM	\$1,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user worthk overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Nov 16, 2022	SYSTEM	(\$1,736.00)	
					7	Dec 2, 2022	SYSTEM	\$1,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user worthk overridding Payment Estimate Exception 3 on the current Payment Estimate.
					7	Dec 2, 2022	SYSTEM	(\$1,736.00)	
					8	Jan 3, 2023	SYSTEM	\$1,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user worthk overridding Payment Estimate Exception 3 on the current Payment Estimate.
					8	Jan 3, 2023	SYSTEM	(\$1,736.00)	
				- Total				\$899.00	
			Material - Tota					\$899.00	
			MaterialCredit		5	Nov 2, 2022	SYSTEM	\$899.00	
			M (1 10 11	- Total				\$899.00	
	0080 -	· Total	MaterialCredit	- Iotai				\$899.00 \$1,798.00	
	0090	DOWEL BAR (FURNISH AND INSTALL WITH BASK	ND TH	aterial	4	Oct 18, 2022	SYSTEM	\$132.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user worthk overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Oct 18, 2022	SYSTEM	\$132.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user worthk overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Oct 18, 2022	SYSTEM	(\$132.00)	,
					5	Nov 2, 2022	SYSTEM	\$240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user worthk overridding Payment Estimate Exception 4 on the current Payment Estimate.
					5	Nov 2, 2022	SYSTEM	(\$240.00)	·
					6	Nov 16, 2022	SYSTEM	\$240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user worthk overridding Payment Estimate Exception 4 on the current Payment Estimate.
					6	Nov 16, 2022	SYSTEM	(\$240.00)	
					7	Dec 2, 2022	SYSTEM	\$240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user worthk overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Dec 2, 2022	SYSTEM	(\$240.00)	
					8	Jan 3, 2023	SYSTEM	\$240.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user worthk overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J2P3281	0090	DOWEL BAR (FURNISH AND	Material		8	Jan 3, 2023	SYSTEM	(\$240.00)		
		INSTALL WITH BASK		- Total				\$132.00		
			Material - Tota					\$132.00		
			MaterialCredit		5	Nov 2, 2022	SYSTEM	\$132.00		
				- Total				\$132.00		
			MaterialCredit	- Total				\$132.00		
	0090 -	Total						\$264.00		
	0100	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		4	Oct 18, 2022	SYSTEM	\$28.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user worthk overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					4	Oct 18, 2022	SYSTEM	\$28.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user worthk overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					4	Oct 18, 2022	SYSTEM	(\$28.75)		
					5	Nov 2, 2022	SYSTEM	\$57.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user worthk overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					5	Nov 2, 2022	SYSTEM	(\$57.50)		
					6	Nov 16, 2022	SYSTEM	\$57.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user worthk overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					6	Nov 16, 2022	SYSTEM	(\$57.50)		
					7	Dec 2, 2022	SYSTEM	\$57.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user worthk overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					7	Dec 2, 2022	SYSTEM	(\$57.50)		
					8	Jan 3, 2023	SYSTEM	\$57.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user worthk overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					8	Jan 3, 2023	SYSTEM	(\$57.50)		
				- Total				\$28.75		
			Material - Tota					\$28.75		
			MaterialCredit		5	Nov 2, 2022	SYSTEM	\$28.75		
				- Total				\$28.75		
			MaterialCredit	- Total				\$28.75		
	0100 -	Total						\$57.50		
	0110	FURN & PLACE CONC MATL FOR CL A PARTIAL	TL FOR	Material		2	Sep 16, 2022	SYSTEM	\$24,879.30	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Sep 16, 2022	SYSTEM	(\$24,879.30)		
					3	Oct 2, 2022	SYSTEM	(\$80,149.70)		
					4	Oct 18, 2022	SYSTEM	\$80,149.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user worthk overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					4	Oct 18, 2022	SYSTEM	\$80,149.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user worthk overridding Payment Estimate Exception 14 on the current Payment Estimate.	
					4	Oct 18, 2022	SYSTEM	(\$80,149.70)		
					5	Nov 2, 2022	SYSTEM	\$80,149.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user worthk overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					5	Nov 2, 2022	SYSTEM	(\$80,149.70)		
						2022				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2P3281	0110	FURN & PLACE CONC MATL FOR CL A PARTIAL	Material		6	Nov 16, 2022	SYSTEM	\$80,149.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user worthk overridding Payment Estimate Exception 10 on the current Payment Estimate.
					6	Nov 16, 2022	SYSTEM	(\$80,149.70)	
					7	Dec 2, 2022	SYSTEM	\$80,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user worthk overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Dec 2, 2022	SYSTEM	(\$80,010.00)	
					8	Jan 3, 2023	SYSTEM	\$80,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user worthk overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Jan 3, 2023	SYSTEM	(\$80,010.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			MaterialCredit		4	Oct 18, 2022	SYSTEM	\$80,149.70	
					5	Nov 2, 2022	SYSTEM	\$80,149.70	
				- Total				\$160,299.40	
			MaterialCredit	- Total				\$160,299.40	
			Other Item Adjustment		3	Oct 2, 2022	worthk	\$80,149.70	
				- Total				\$80,149.70	
			Other Item Ad	justment - To	tal			\$80,149.70	
	0110 -	Total						\$240,449.10	
	0130	CROSS STITCH TIE BAR	Material		7	Dec 2, 2022	SYSTEM	\$7,458.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user worthk overridding Payment Estimate Exception 14 on the current Payment Estimate.
					7	Dec 2, 2022	SYSTEM	(\$7,458.00)	
					8	Jan 3, 2023	SYSTEM	\$7,458.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user worthk overridding Payment Estimate Exception 14 on the current Payment Estimate.
					8	Jan 3, 2023	SYSTEM	(\$7,458.00)	
				- Total				\$0.00	
			Material - Tota	Material - Total				\$0.00	
	0130 -	Total						\$0.00	
	0140	CONSTRUCTION SIGNS			2	Sep 16, 2022	SYSTEM	\$7,165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user worthk overridding Payment Estimate Exception 4 on the current Payment Estimate.
					2	Sep 16, 2022	SYSTEM	(\$7,165.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0140 -	Total						\$0.00	
	0150	CHANNELIZER (TRIM LINE)	Material		2	Sep 16, 2022	SYSTEM	\$4,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user worthk overridding Payment Estimate Exception 5 on the current Payment Estimate.
					2	Sep 16, 2022	SYSTEM	(\$4,950.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0150 -	Total						\$0.00	
	0160	TYPE III MOVEABLE BARRICADE			2	Sep 16, 2022	SYSTEM	\$1,210.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user worthk overridding Payment Estimate Exception 6 on the current Payment Estimate.
					2	Sep 16, 2022	SYSTEM	(\$1,210.00)	



1998 1999 Type Machinal Type Machina	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
156	J2P3281	0160	MOVEABLE								
Process			BARRICADE	Material - Tota					\$0.00		
ARRON PANEL		0160 -	Total						\$0.00		
Total		0170		Material		2		SYSTEM	\$1,098.00	Estimate Item Adjustment (0005) due to user worthk overridding Payment	
1710 - Total						2		SYSTEM	(\$1,098.00)		
170 - Total					- Total				\$0.00		
Original Communication Com				Material - Total					\$0.00		
2022 Sap 16, SYSTEM \$5,486.00		0170 -	Total						\$0.00		
1701 1702 1703 1704		0180	COMMUNICATION INTERFACE,	Material		2		SYSTEM	\$5,486.00	Estimate Item Adjustment (0006) due to user worthk overridding Payment	
National			CONT F/			2		SYSTEM	(\$5,486.00)		
190 TEMPORARY SHORT TERM Part Stock Stock					- Total				\$0.00		
190				Material - Tota	l e				\$0.00		
SHORT-TERM 2022 Estimate Item Adjustment (0007) due to user worthis coveriding Payment Estimate Exception 9 on the current Payment Estimate. 2		0180 -	Total						\$0.00		
10190 - Total		0190	SHORT-TERM	Material		2		SYSTEM	\$8,780.00	Estimate Item Adjustment (0007) due to user worthk overridding Payment	
						2		SYSTEM	(\$8,780.00)		
1					- Total				\$0.00		
O280 MGS GUARDRAIL Construction Stockpile Total (85,045,00) Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile Total (85,045,00)				Material - Total					\$0.00		
Stockpile		0190 -	Total						\$0.00		
Construction Stockpile Total		0280	MGS GUARDRAIL			7		SYSTEM	(\$5,045.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
Construction Stockpile STMI - Total Stockpile State Stockpile State Stockpile STMI - Total Stockpile State Stockpile					- Total				(\$5,045.00)		
Stockpile STM Stockpile STM - Total Statistical Statist				Construction S	Stockpile - Total				(\$5,045.00)		
Construction Stockpile STMI - Total \$5,045.00				Stockpile		1		SYSTEM	\$5,045.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
1											
1				Construction S	Stockpile STI	VII - Total					
CRASHWORTHY END TERMINAL -Total (\$7,800.00)		0280 -									
Construction Stockpile - Total Construction Stockpile 1		0300	CRASHWORTHY END TERMINAL			7		SYSTEM	, , ,	Payment Estimate Item Adjustment generated Stockpile Transaction	
Construction Stockpile STMI - Total \$7,800.00 Payment Estimate Item Adjustment generated Stockpile Transaction Stockpile STMI - Total \$7,800.00											
Stockpile STMI -Total \$7,800.00				Construction Stockpile STMI	отоскрие - то		11 10	OVOTEN			
Construction Stockpile STMI - Total \$7,800.00								SYSTEM	\$7,800.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
Material This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment (0008) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate. Suppose					- Total				\$7,800.00		
Estimate Item Adjustment (0008) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate. 7 Dec 2, 2022 8 Jan 3, 2023 SYSTEM \$14,044.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user worthk overridding Payment Estimate Item Adjustment (0007) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate. 8 Jan 3, 2023 SYSTEM \$14,044.00 SYSTEM \$0.00 Material - Total \$0.00 J2P3281 - Total \$300,672.60				Construction S	onstruction Stockpile STMI - Total				\$7,800.00		
2022				Mate	Material		7		SYSTEM	\$14,044.00	Estimate Item Adjustment (0008) due to user worthk overridding Payment
2023 Estimate Item Adjustment (0007) due to user worthk overridding Payment Estimate Exception 1 on the current Payment Estimate. 3						7		SYSTEM	(\$14,044.00)		
2023						8		SYSTEM	\$14,044.00	Estimate Item Adjustment (0007) due to user worthk overridding Payment	
Material - Total \$0.00 0300 - Total \$0.00 J2P3281 - Total \$302,672.60						8		SYSTEM	(\$14,044.00)		
0300 - Total \$0.00 J2P3281 - Total \$302,672.60									\$0.00		
J2P3281 - Total \$302,672.60				Material - Tota							
		0300 -	Total						\$0.00		
Overall - Total \$302,672.60	J2P3281 -	Total							\$302,672.60		
	Overall -	Total						\$302,672.60			