

Pay Estimate Created Date: August 2, 2022

ū	timate Number 10		211015-C03 Pyramid Contrac		riod Start July 16, riod End August		Contract Amount ge Order Amount	\$5,861,477.94 \$18,645.51		
	10			, •		Current C	Contract Amount	\$5,880,123.45		
Approval Date								By User		
August 2, 2022			Generated and	Approved (and sh	ould be considered	Draft) at the Project	ct Office Level by	vohsr		
August 3, 2022		Re	viewed and Appr	oved (and should	be considered Draft	t) at the Resident E	ngineer Level by	kneibr		
August 3, 2022				Reviewed and Ap	proved at the Centr	al Office Controller	s Office Level by	ramses		
Original Cor	riginal Completion Date Current Completion Date Actual Completion Date %						ent Contract Amount Complete			
February 18, 2023 February			8, 2023	, 2023 70.29%						
Cor	ntract Informationa	l Dates	Milestones							
Date Description	Original Completion Date	Current Completion Date	Date	Description	Original Completion Date	Current Completion Date	Days Remaining Milestone	on Diary Charge Days		
Acceptance Date			Milestone - Ca Phase 2	alendar Time -	September 14, 2022	September 14, 2022		42		
Awarded Date	November 3, 2021	November 3, 2021	Milestone - Co Phase 2 Incer	ompletion Date - ntive	October 15, 2022	October 15, 2022		73		
Letting Date	October 15, 2021	October 15, 2021								
Notice to Proceed Date	January 3, 2022	January 3, 2022								
Open to Traffic Date										
Work Began	March 28, 2022	March 28, 2022								

Contract Total Pay For Estimate No. 10										
		This Estimate	Previous	To Date						
211015-C03	Total Posted Items Pay Gross Item Adjustments Incentive Disincentive Liquidated Damage Other Contract Adjustments	\$355,940.08 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$3,777,125.12 \$86,284.16 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$3,863,409.28	\$4,133,065.20 \$86,284.16 \$0.00 \$0.00 \$0.00 \$0.00 \$4,219,349.36						
Contract Total Pa	ayable This Estimate:	\$355,940.08								

Items Paid This Estimate Period

Date

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3009	0030	2031000	CLASS A EXCAVATION	CUYD	\$17.000	1,607	\$27,319.00
	0050	2036000	COMPACTING EMBANKMENT	CUYD	\$2.500	2,405	\$6,012.50
	0060	2037075	COMPACTING IN CUT	STA	\$350.000	8	\$2,800.00
	0090	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	SQYD	\$16.500	38	\$627.00
	0110	3049905	MISC.OPTIONAL BASE	SQYD	\$11.000	7,079	\$77,869.00
	0120	4010150	TYPE A2 SHOULDER	SQYD	\$27.000	1,134.7	\$30,636.90
	0140	4019905	MISC.RAMP OPTIONAL PAVEMENT	SQYD	\$60.000	38	\$2,280.00
	0150	4019905	MISC.US-50 OPTIONAL PAVEMENT	SQYD	\$52.000	3,383.96	\$175,965.92
	0270	6113010	FURNISHING TYPE 1 ROCK BLANKET	CUYD	\$65.000	143	\$9,295.00
	0280	6113030	PLACING TYPE 1 ROCK BLANKET	CUYD	\$20.000	143	\$2,860.00
	0370	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	LF	\$200.000	28	\$5,600.00
	0510	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	SQYD	\$5.000	215	\$1,075.00
	0660	8061019	SILT FENCE	LF	\$1.350	845	\$1,140.75
	5004	7209901	MISC.FLOWABLE FILL FOR GAS LINE REMOVAL	LS	\$12,459.010	1	\$12,459.01

Revision 4/1/2020 Page 1 of 31



Pay Estimate Created Date: August 2, 2022

Progress Estimate		211015-C03	•		• •	\$5,861,477.94
10	Prime Contra	actor Pyramid Contractors, Inc	. Pay Period End	August 1, 2022	Net Change Order Amount	\$18,645.51
10					Current Contract Amount	\$5,880,123.45

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount		
Project J4P300	Project J4P3009 - Total								
Overall - Total							\$355,940.08		

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009	0040	EMBANKMENT IN PLACE	Material			-3,626	\$20.00	(\$72,520.00
	0040	EMBANKMENT IN PLACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	3,626	\$20.00	\$72,520.00
	0050	COMPACTING EMBANKMENT	Material			-5,294	\$2.50	(\$13,235.00)
	0050	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	5,294	\$2.50	\$13,235.00
	0060	COMPACTING IN CUT	Material			-32	\$350.00	(\$11,200.00)
	0060	COMPACTING IN CUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	32	\$350.00	\$11,200.00
	0110	MISC.	Material			-11,716	\$11.00	(\$128,876.00)
	0110	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	11,716	\$11.00	\$128,876.00
	0180	CONCRETE APPROACH PAVEMENT	Material			-379.8	\$108.60	(\$41,246.28)
	0180	CONCRETE APPROACH PAVEMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	379.8	\$108.60	\$41,246.28
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material			-490	\$48.00	(\$23,520.00)
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	490	\$48.00	\$23,520.00
	0370	CONCRETE TRAFFIC BARRIER, TYPE C	Material			-177	\$200.00	(\$35,400.00
	0370	CONCRETE TRAFFIC BARRIER, TYPE C	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	177	\$200.00	\$35,400.00
	0730	MISC.	Material			-2	\$5,000.00	(\$10,000.00)
	0730	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1	2	\$5,000.00	\$10,000.00

Revision 4/1/2020 Page 2 of 31



Pay Estimate Created Date: August 2, 2022

Progress Estimate Number
10

Contract ID 211015-C03 Pay Period Start July 16, 2022 Original Contract Amount S5,861,477.94
Prime Contractor Pyramid Contractors, Inc. Pay Period End August 1, 2022 Net Change Order Amount Current Contract Amount S5,880,123.45

					- Juli	ent Contract	Amount	\$5,880,123.45
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009					overridding Payment Estimate Exception 17 on the current Payment Estimate.			
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	Material			-1	\$8,500.00	(\$8,500.00
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 54 on the current Payment Estimate.	1	\$8,500.00	\$8,500.00
	0960	BRIDGE APPROACH SLAB (MAJOR)	Material			-182	\$249.10	(\$45,336.20
	0960	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	182	\$249.10	\$45,336.20
	0970	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material			-52	\$985.00	(\$51,220.00
	0970	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.	52	\$985.00	\$51,220.00
	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material			-32	\$642.00	(\$20,544.00
	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	32	\$642.00	\$20,544.00
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-93.4	\$860.00	(\$80,324.00
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.	93.4	\$860.00	\$80,324.00
	1050	TYPE D BARRIER	Material			-306	\$170.00	(\$52,020.00
	1050	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.	306	\$170.00	\$52,020.00
	1060	SLAB ON CONCRETE NU- GIRDER	Material			-468.1	\$398.00	(\$186,303.80
	1060	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.	468.1	\$398.00	\$186,303.80
	1200	BRIDGE APPROACH SLAB (MAJOR)	Material			-182	\$249.10	(\$45,336.20
	1200	BRIDGE APPROACH SLAB (MAJOR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	182	\$249.10	\$45,336.20
	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material			-44	\$985.00	(\$43,340.00

Revision 4/1/2020 Page 3 of 31



Pay Estimate Created Date: August 2, 2022

Progress Estimate Number
10

Contract ID 211015-C03 Pay Period Start July 16, 2022 Original Contract Amount S5,861,477.94
Prime Contractor Pyramid Contractors, Inc. Pay Period End August 1, 2022 Net Change Order Amount Current Contract Amount S5,880,123.45

								, ,
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.	44	\$985.00	\$43,340.00
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material			-32	\$642.00	(\$20,544.00
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.	32	\$642.00	\$20,544.00
	1280	CLASS B CONCRETE (SUBSTRUCTURE)	Material			-92.1	\$870.00	(\$80,127.00
	1280	CLASS B CONCRETE (SUBSTRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.	92.1	\$870.00	\$80,127.00
	1290	TYPE D BARRIER	Material			-306	\$170.00	(\$52,020.00)
	1290	TYPE D BARRIER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 41 on the current Payment Estimate.	306	\$170.00	\$52,020.00
	1300	SLAB ON CONCRETE NU- GIRDER	Material			-573.8	\$398.00	(\$228,372.40)
	1300	SLAB ON CONCRETE NU- GIRDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.	573.8	\$398.00	\$228,372.40
	1440	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,786	\$74.00	(\$280,164.00)
	1440	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.	3,786	\$74.00	\$280,164.00
	1470	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material			-3,422	\$75.00	(\$256,650.00)
	1470	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.	3,422	\$75.00	\$256,650.00
J4P3009B	1660	CURB AND GUTTER TYPE B	Material			-563	\$35.05	(\$19,733.15)
	1660	CURB AND GUTTER TYPE B	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	563	\$35.05	\$19,733.15
Total								\$0.00

Revision 4/1/2020 Page 4 of 31



						Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County		Location of Work				
J4P3009	FAF 50-1(54)	Bridge replacement	50	JACKSON	over Chipman Road nea	er Chipman Road near Lee's Summit				
J4P3009B	FAF 50-1(55)	Grading and paving	50	JACKSON	from w/o Murray Road t	to w/ Blue Parkway				
Totals by Jo	ob Number	s								
J4P3009		l Item Pay Item Adjustme		Item Pay	This Estimate \$355,940.08 \$0.00 \$355,940.08	Previous \$3,552,187.47 \$86,284.16 \$3,638,471.63	To Date \$3,908,127.55 \$86,284.16 \$3,994,411.71			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			
J4P3009B		l Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$224,937.65 \$0.00 \$224,937.65	To Date \$224,937.65 \$0.00 \$224,937.65			
					\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 5 of 31



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 2035500, Project Item Line Number 0040, Material Set 203550096, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on contractor QC testing results for soil compaction.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 2036000, Project Item Line Number 0050, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on contractor QC testing results for soil compaction.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 2037075, Project Item Line Number 0060, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Waiting on contractor QC testing results for soil compaction.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 3049905, Project Item Line Number 0110, Material Set 304990596, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	Waiting on contractor base rock compaction results.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 3049905, Project Item Line Number 0110, Material Set 304990596, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Waiting on contractor base rock compaction results.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 0960, Material Set 5031010A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 0960, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 0960, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 1200, Material Set 5031010A96, Material 0501CCPAQCQA - Concrete, Payment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 1200, Material Set 5031010A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5031010A, Project Item Line Number 1200, Material Set 5031010A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5041000, Project Item Line Number 0180, Material Set 504100096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5041000, Project Item Line Number 0180, Material Set 504100096, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5041000, Project Item Line Number 0180, Material Set 504100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5041000, Project Item Line Number 0180, Material Set 504100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 5041000, Project Item Line Number 0180, Material Set 504100096, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Waiting on PAL for reinforcing steel	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6069902, Project Item Line Number 0730, Material Set 6069902, Material 1040GUAAZC - Guard Cable Galv Anchor Assembly, Acceptance Action Generic 1040GUAAZC is insufficient.	Working with Materials to resolve acception.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6071102, Project Item Line Number 0210, Material Set 607110296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6071102, Project Item Line Number 0210, Material Set 607110296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6091052, Project Item Line Number 1660, Material Set 609105296, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6091052, Project Item Line Number 1660, Material Set 609105296, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 6091052, Project Item Line Number 1660, Material Set 609105296, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6173000, Project Item Line Number 0370, Material Set 617300096, Material 0501CCPAQCQA - Concrete, Pavment contractor mix or QCQA, Acceptance Action Generic 0501CCPAQCQA is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6173000, Project Item Line Number 0370, Material Set 617300096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden

Revision 4/1/2020 Page 6 of 31



Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Generic 1005GDCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 6173000, Project Item Line Number 0370, Material Set 617300096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 0970, Material Set 701110696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 0970, Material Set 701110696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 1210, Material Set 701110696, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011106, Project Item Line Number 1210, Material Set 701110696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 0980, Material Set 701120596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 0980, Material Set 701120596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 1220, Material Set 701120596, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7011205, Project Item Line Number 1220, Material Set 701120596, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1040, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1040, Material Set 703200396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1280, Material Set 703200396, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7032003, Project Item Line Number 1280, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1050, Material Set 7034219A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1050, Material Set 7034219A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1050, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1290, Material Set 7034219A96, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1290, Material Set 7034219A96, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034219A, Project Item Line Number 1290, Material Set 7034219A96, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1060, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1300, Material Set 703422196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number	Waiting on QC T27, T85, and TM71 for Masonry Grade D	vohsr1	Overridden

Revision 4/1/2020 Page 7 of 31



Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
1300, Material Set 703422196, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Aggregate		
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7034221, Project Item Line Number 1300, Material Set 703422196, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Waiting on 28 day break testing results for QC and QA.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1440, Material Set 720100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 1005GDCMLD - Masonry Grade D LS/DO, Acceptance Action Generic 1005GDCMLD is insufficient.	Waiting on QC T27, T85, and TM71 for Masonry Grade D Aggregate	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 7201000, Project Item Line Number 1470, Material Set 720100096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Waiting on T-27 Sand Gradation for QC.	vohsr1	Overridden
Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9103714, Project Item Line Number 0840, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient.	Waiting on PAL for Reinforcing Steel.	vohsr1	Overridden

Revision 4/1/2020 Page 8 of 31



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009	0001	0010	2013000	CLEARING AND GRUBBING	5.00	0.00	5.00	ACRE	1.50	\$5,500.00	\$8,250.00
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.95	\$250,000.00	\$237,500.00
		0001	0030	2031000	CLASS A EXCAVATION	6,088.00	0.00	6,088.00	CUYD	6,088.00	\$17.00	\$103,496.00
		0001	0040	2035500	EMBANKMENT IN PLACE	3,626.00	0.00	3,626.00	CUYD	3,626.00	\$20.00	\$72,520.00
		0001	0050	2036000	COMPACTING EMBANKMENT	5,294.00	0.00	5,294.00	CUYD	5,294.00	\$2.50	\$13,235.00
		0001	0060	2037075	COMPACTING IN CUT	32.00	0.00	32.00	STA	32.00	\$350.00	\$11,200.00
		0001	0070	2063000	CLASS 3 EXCAVATION	117.00	0.00	117.00	CUYD	87.00	\$12.00	\$1,044.00
		0001	0080	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	0.00	\$2,000.00	\$0.00
		0001	0090	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,718.00	38.00	1,756.00	SQYD	1,756.00	\$16.50	\$28,974.00
		0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	466.00	0.00	466.00	SQYD	466.00	\$15.00	\$6,990.00
		0001	0110	3049905	MISC.OPTIONAL BASE	11,716.00	0.00	11,716.00	SQYD	11,716.00	\$11.00	\$128,876.00
		0001	0120	4010150	TYPE A2 SHOULDER	2,721.10	0.00	2,721.10	SQYD	1,904.80	\$27.00	\$51,429.60
		0001	0130	4019905	MISC.CHIPMAN ROAD OPTIONAL PAVEMENT	466.00	0.00	466.00	SQYD	466.00	\$100.00	\$46,600.00
		0001	0140	4019905	MISC.RAMP OPTIONAL PAVEMENT	1,718.00	38.00	1,756.00	SQYD	1,756.00	\$60.00	\$105,360.00
		0001	0150	4019905	MISC.US-50 OPTIONAL PAVEMENT	8,995.00	0.00	8,995.00	SQYD	6,425.78	\$52.00	\$334,140.56
		0001	0160	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	421.70	0.00	421.70	TONS	421.70	\$115.00	\$48,495.50
		0001	0170	4071005	TACK COAT	213.00	0.00	213.00	GAL	0.00	\$2.50	\$0.00
		0001	0180	5041000	CONCRETE APPROACH PAVEMENT	379.80	0.00	379.80	SQYD	379.80	\$108.60	\$41,246.28
		0001	0190	6044011	PIPE COLLAR, TYPE A	3.00	0.00	3.00	EA	3.00	\$1,100.00	\$3,300.00
		0001	0200	6064500	AGGREGATE BEDDING FOR 3 - STRAND GUARD CABLE	93.00	0.00	93.00	CUYD	0.00	\$40.00	\$0.00
		0001	0210	6071102	MODIFIED CONCRETE GUTTER TYPE B	490.00	0.00	490.00	LF	490.00	\$48.00	\$23,520.00
		0001	0220	6079903	MISC.ORNAMENTAL PEDESTRIAN FENCE (48") (RETAINING	331.00	0.00	331.00	LF	0.00	\$135.00	\$0.00
			0000	0004000	WALLS)	2.00	0.00	2.00	COVD	0.00	#200 OF	60.00
		0001	0230	6081000	CONCRETE MEDIAN	2.80	0.00	2.80	SQYD	0.00	\$399.25	\$0.00
		0001	0240	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$65.00	\$0.00
		0001	0250	6096041	PLACING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$60.00	\$0.00
		0001	0260	6097000	ROCK LINING	15.00	0.00	15.00	CUYD	3.00	\$85.00	\$255.00
		0001	0270	6113010	FURNISHING TYPE 1 ROCK BLANKET	143.00	0.00	143.00	CUYD	143.00	\$65.00	\$9,295.00
		0001	0280	6113030	PLACING TYPE 1 ROCK BLANKET	143.00	0.00	143.00	CUYD	143.00	\$20.00	\$2,860.00
		0001	0290	6161005	CONSTRUCTION SIGNS	1,610.00	0.00	1,610.00	SQFT	1,610.00	\$6.50	\$10,465.00
		0001	0300	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	8.00	\$100.00	\$800.00
		0001	0310	6161025	CHANNELIZER (TRIM LINE)	222.00	0.00	222.00	EA	222.00	\$31.00	\$6,882.00
		0001	0320	6161030	TYPE III MOVEABLE BARRICADE	50.00	0.00	50.00	EA	50.00	\$185.00	\$9,250.00
		0001	0330	6161033	DIRECTIONAL INDICATOR BARRICADE	37.00	0.00	37.00	EA	14.00	\$135.00	\$1,890.00
		0001	0340	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.00
		0001	0350	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$9,500.00	\$19,000.00
		0001	0360	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.00
		0001	0370	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	177.00	0.00	177.00	LF	177.00	\$200.00	\$35,400.00
		0001	0380	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$195,000.00	\$0.00
		0001	0381	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$141,674.00	\$141,674.00
		0001	0390	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.00
		0001	0400	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	168.00	0.00	168.00	LF	0.00	\$20.00	\$0.00
		0001	0410	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	0.00	16.00	EA	0.00	\$250.00	\$0.00
		0001	0420	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	13,609.00	-13,609.00	0.00	LF	0.00	\$1.55	\$0.00
		0001	0430	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	13,273.00	-13,273.00	0.00	LF	0.00	\$1.55	\$0.00
					TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT	8.00	0.00	8.00	EA	0.00	\$115.00	\$0.00

Revision 4/1/2020 Page 9 of 31



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11015-C03	J4P3009	0001	0450	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	15,875.00	0.00	15,875.00	LF	0.00	\$0.55	\$0.0
		0001	0460	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	11,706.00	0.00	11,706.00	LF	0.00	\$0.55	\$0.0
		0001	0470	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,840.00	0.00	1,840.00	LF	0.00	\$0.90	\$0.0
		0001	0480	6207001	PAVEMENT MARKING REMOVAL	2,376.00	0.00	2,376.00	LF	2,376.00	\$0.55	\$1,306.8
		0001	0490	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	16.00	0.00	16.00	EA	0.00	\$55.00	\$0.0
		0001	0500	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,646.00	0.00	2,646.00	SQYD	681.00	\$6.25	\$4,256.2
		0001	0510	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	319.00	0.00	319.00	SQYD	215.00	\$5.00	\$1,075.0
		0001	0520	6240104A	SEPARATION GEOTEXTILE	838.00	0.00	838.00	SQYD	0.00	\$4.50	\$0.0
		0001	0530	6269909	MISC.OPTIONAL PAVEMENT RUMBLE STRIP	56.60	0.00	56.60	STA	0.00	\$158.85	\$0.0
		0001	0540	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.
		0001	0550	7261018	18 IN. PIPE GROUP A	18.00	0.00	18.00	LF	0.00	\$110.00	\$0.
		0001	0560 0570	7261024 7261030	24 IN. PIPE GROUP A 30 IN. PIPE GROUP A	73.00	0.00	73.00	LF LF	73.00	\$105.00	\$7,665.0
		0001	0580	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	28.00	0.00	1.00	EA	0.00	\$160.00 \$1,500.00	\$0.
		0001			SECTION							
		0001	0590	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,700.00	\$3,400.0
		0001	0600	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	0.00	\$1,850.00	\$0.
		0001	0610	8051000A	SEEDING - COOL SEASON GRASSES	5.30	0.00	5.30	ACRE	0.00	\$1,600.00	\$0.
		0001	0620	8061004	SEDIMENT TRAP ROCK	29.80	0.00	29.80	CUYD	0.00	\$100.00	\$0.
		0001	0630	8061005	ROCK DITCH CHECK	140.00	0.00	140.00	LF	89.00	\$45.00	\$4,005
		0001	0640	8061006	ALTERNATE DITCH CHECK	976.00	0.00	976.00	LF	0.00	\$4.35	\$0.
		0001	0650	8061016	SEDIMENT REMOVAL	189.00	0.00	189.00	CUYD	0.00	\$20.00	\$0.
		0001	0660	8061019	SILT FENCE	3,187.00	0.00	3,187.00	LF	1,475.00	\$1.35	\$1,991.
		0001	0670	8064128	TYPE 1 TURF REINFORCEMENT MAT	729.00	0.00	729.00	SQYD	0.00	\$1.95	\$0.
		0001	0680	8064138	TYPE 2D EROSION CONTROL BLANKET	3,973.00	0.00	3,973.00	SQYD	0.00	\$4.25	\$0
		0010	0690	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,463.00	0.00	1,463.00	LF	0.00	\$31.50	\$0
		0010	0700	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	5.00	0.00	5.00	EA	0.00	\$3,000.00	\$0
		0010	0710	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	0.00	\$950.00	\$0
		0010	0720	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	0.00	\$2,700.00	\$0
		0010	0730	6069902	MISC.HTGC ANCHOR ASSEMBLY	2.00	2.00	4.00	EA	2.00	\$5,000.00	\$10,000
		0010	0740	6069903	MISC.HIGH TENSION GUARD CABLE	1,256.00	0.00	1,256.00	LF	0.00	\$24.00	\$0
		0040	0750	7040101	SUBSTRUCTURE REPAIR (FORMED)	150.00	0.00	150.00	SQFT	0.00	\$75.00	\$0.
		0040	0760	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	0.00	\$1,762.00	\$0.
		0040	0770	9031010	CONCRETE FOOTINGS, EMBEDDED	1.00	0.00	1.00	CUYD	0.00	\$1,300.00	\$0.
		0040	0780	9031210	STRUCTURAL STEEL POSTS	650.00	0.00	650.00	LB	0.00	\$4.25	\$0.
		0040	0790	9031270A	2 IN. PSST POST - 12 GA.	75.00	0.00	75.00	LF	0.00	\$20.50	\$0
		0040	0800	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	18.00	0.00	18.00	LF	0.00	\$40.00	\$0
		0040	0810	9035004A	SH-FLAT SHEET	27.00	0.00	27.00	SQFT	0.00	\$23.50	\$0
		0040	0820	9035011A	ST-STRUCTURAL	80.00	0.00	80.00	SQFT	0.00	\$21.50	\$0.
		0040	0830	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$37.50	\$0.
		0050	0840	9103714	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	1.00	0.00	1.00	EA	1.00	\$8,500.00	\$8,500.
		0050	0850	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	227.00	0.00	227.00	LF	227.00	\$13.50	\$3,064
		0050	0860	9108206	CABLE, 6 AWG, 1 CONDUCTOR, POWER	3,390.00	0.00	3,390.00	LF	0.00	\$2.50	\$0
		0050	0870	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	1,130.00	0.00	1,130.00	LF	0.00	\$2.50	\$0.
		0050	0880	9108811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	0.00	\$1,575.00	\$0.
		0050	0890	9109901	MISC.Fiber Optic Splicing, Testing, & Documentation	1.00	0.00	1.00	LS	1.00	\$5,500.00	\$5,500.

Revision 4/1/2020 Page 10 of 31



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009	0050	0900	9109902	MISC.CCTV Pole Relocation	1.00	0.00	1.00	EA	1.00	\$6,000.00	\$6,000.00
		0050	0910	9109902	MISC.Scout Fiber Optic Pull Box	3.00	0.00	3.00	EA	0.00	\$3,500.00	\$0.00
		0050	0920	9109903	MISC."CONDUIT, TWO 2 IN., PUSHED"	181.00	0.00	181.00	LF	181.00	\$30.00	\$5,430.00
		0050	0930	9109903	MISC."CONDUIT, TWO 2 IN., RIGID, IN SAME TRENCH"	692.00	0.00	692.00	LF	672.00	\$20.00	\$13,440.00
		0070	0940	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	17.00	0.00	17.00	SQFT	17.00	\$275.00	\$4,675.00
		0070	0950	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$68,000.00	\$68,000.00
		0070	0960	5031010A	BRIDGE APPROACH SLAB (MAJOR)	182.00	0.00	182.00	SQYD	182.00	\$249.10	\$45,336.20
		0070	0970	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	52.00	0.00	52.00	LF	52.00	\$985.00	\$51,220.00
		0070	0980	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	32.00	0.00	32.00	LF	32.00	\$642.00	\$20,544.00
		0070	0990	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$200.00	\$800.00
		0070	1000	7011400	FOUNDATION INSPECTION HOLES	72.00	0.00	72.00	LF	72.00	\$105.00	\$7,560.00
		0070	1010	7011600	SONIC LOGGING TESTING	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800.00
		0070	1020	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	525.00	0.00	525.00	LF	450.00	\$109.00	\$49,050.00
		0070	1030	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$125.00	\$1,750.00
		0070	1040	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	93.40	0.00	93.40	CUYD	93.40	\$860.00	\$80,324.00
		0070	1050	7034219A	TYPE D BARRIER	306.00	0.00	306.00	LF	306.00	\$170.00	\$52,020.00
		0070	1060	7034221	SLAB ON CONCRETE NU-GIRDER	604.00	0.00	604.00	SQYD	468.10	\$398.00	\$186,303.80
		0070	1070	7034620	FORM LINERS	197.00	0.00	197.00	SQYD	0.00	\$90.00	\$0.00
		0070	1080	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	491.00	0.00	491.00	LF	491.00	\$360.00	\$176,760.00
		0070	1090	7061060	REINFORCING STEEL (BRIDGES)	7,860.00	0.00	7,860.00	LB	7,860.00	\$1.70	\$13,362.00
		0070	1100	7101000	REINFORCING STEEL (EPOXY COATED)	11,140.00	0.00	11,140.00	LB	11,140.00	\$2.25	\$25,065.00
		0070	1110	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,860.00	\$0.00
		0070	1120	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,860.00	\$0.00
		0070	1130	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.00
		0070	1140	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0070	1150	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600.00
		0070	1160	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$385.00	\$3,080.00
		0070	1170	7201300	PIPE PILE SPACERS	18.00	0.00	18.00	EA	18.00	\$1,525.00	\$27,450.00
		0070	1180	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	17.00	0.00	17.00	SQFT	17.00	\$275.00	\$4,675.00
			1190	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$68,000.00	\$68,000.00
		0071	1200	5031010A	BRIDGE APPROACH SLAB (MAJOR)	182.00	0.00	182.00	SQYD	182.00	\$249.10	\$45,336.20
		0071	1210	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	44.00	0.00	44.00	LF	44.00	\$985.00	\$43,330.20
		0071	1220	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	32.00	0.00	32.00	LF	32.00	\$642.00	\$20,544.00
			1230	7011203	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$200.00	\$800.00
		0071	1240	7011400	FOUNDATION INSPECTION HOLES	72.00	0.00	72.00	LF	72.00	\$105.00	
		0071		7011600	SONIC LOGGING TESTING			4.00				\$7,560.00 \$4,800.00
		0071	1250			4.00	0.00		EA LF	4.00	\$1,200.00	
		0071	1260	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	497.00	0.00	497.00		412.00	\$109.00	\$44,908.00
		0071	1270	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$125.00	\$1,750.00
		0071	1280	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	92.10	0.00	92.10	CUYD	92.10	\$870.00	\$80,127.00
		0071	1290		TYPE D BARRIER	306.00	0.00	306.00	LF	306.00	\$170.00	\$52,020.00
		0071	1300	7034221	SLAB ON CONCRETE NU-GIRDER	604.00 194.00	0.00	604.00	SQYD	573.80	\$398.00	\$228,372.40
		0071	1310	7034620	FORM LINERS NIL 35 DESTRESSED CONCRETE NIL GIPDED		0.00	194.00	SQYD	0.00	\$90.00	\$0.00
	0071 1320 7056021 NU 35, PRESTRESSED CONCRETE NU-GIRDER		491.00	0.00	491.00	LF	491.00	\$360.00	\$176,760.00			
		0071	1330	7061060	REINFORCING STEEL (BRIDGES)	7,230.00	0.00	7,230.00	LB	7,230.00	\$1.75	\$12,652.50
		0071	1340	7101000	REINFORCING STEEL (EPOXY COATED)	11,070.00	0.00	11,070.00	LB	11,070.00	\$2.10	\$23,247.00
		0071	1350	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,860.00	\$0.00
		0071	1360	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	0.00	\$1,860.00	\$0.00

Revision 4/1/2020 Page 11 of 31



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

ote: Posted G	uantities a	ind Value	s are ba	ased on Re	port Generated date and can differ from the posted amou	unt at the	ime the Es	timate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11015-C03	J4P3009	0071	1370	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	0.00	\$4,000.00	\$0.00
		0071	1380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0071	1390	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600.00
		0071	1400	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$385.00	\$3,080.00
		0071	1410	7201300	PIPE PILE SPACERS	18.00	0.00	18.00	EA	18.00	\$1,525.00	\$27,450.00
		0072	1420	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,367.50	\$3,367.50
		0072	1430	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,367.50	\$3,367.50
		0072	1440	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,786.00	0.00	3,786.00	SQFT	3,786.00	\$74.00	\$280,164.0
		0073	1450	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,115.00	\$3,115.0
		0073	1460	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,115.00	\$3,115.0
		0073	1470	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,422.00	0.00	3,422.00	SQFT	3,422.00	\$75.00	\$256,650.0
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$53,326.00	\$53,326.0
		0001	5002	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	0.00	26,882.00	26,882.00	LF	16,704.00	\$1.05	\$17,539.2
		0001	5003	1046002	VALUE ENGINEERING	0.00	6,720.50	6,720.50	EA	6,720.50	\$1.00	\$6,720.5
		0072	5004	7209901	MISC.FLOWABLE FILL FOR GAS LINE REMOVAL	0.00	1.00	1.00	LS	1.00	\$12,459.01	\$12,459.0
	Project J4	P3009 - Tot	al Value	Posted to Da	te as of Report Generated Date							\$3,908,127.5
	J4P3009B	0001	1480	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.06	\$85,000.00	\$5,100.0
		0001	1490	2031000	CLASS A EXCAVATION	637.00	0.00	637.00	CUYD	0.00	\$22.00	\$0.0
		0001	1500	2036000	COMPACTING EMBANKMENT	260.00	0.00	260.00	CUYD	0.00	\$18.00	\$0.0
		0001	1510	2063000	CLASS 3 EXCAVATION	109.00	0.00	109.00	CUYD	51.00	\$20.00	\$1,020.0
		0001	1520	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	268.00	0.00	268.00	SQYD	0.00	\$17.00	\$0.0
		0001	1530	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	822.00	0.00	822.00	SQYD	0.00	\$16.00	\$0.0
		0001	1540	4019905	MISC.OPTIONAL PAVEMENT - CHIPMAN	434.00	0.00	434.00	SQYD	14.00	\$192.00	\$2,688.0
		0001	1550	4019905	MISC.OPTIONAL PAVEMENT - MURRAY	388.00	0.00	388.00	SQYD	0.00	\$110.00	\$0.0
		0001	1560	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	1,688.10	0.00	1,688.10	TONS	0.00	\$95.00	\$0.0
		0001	1570	4071005	TACK COAT	1,459.00	0.00	1,459.00	GAL	0.00	\$2.50	\$0.0
		0001	1580	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	92.00	0.00	92.00	GAL	0.00	\$3.00	\$0.0
		0001	1590	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	0.00	\$1,400.00	\$0.0
		0001	1600	6081000	CONCRETE MEDIAN	430.80	0.00	430.80	SQYD	0.00	\$65.55	\$0.0
		0001	1610	6081010	CONCRETE CURB RAMP	229.30	0.00	229.30	SQYD	0.00	\$127.27	\$0.0
		0001	1620	6081012	TRUNCATED DOMES	396.00	0.00	396.00	SQFT	0.00	\$17.65	\$0.0
		0001	1630	6083006	6 IN. CONCRETE MEDIAN STRIP	67.70	0.00	67.70	SQYD	0.00	\$161.45	\$0.0
		0001	1640	6086004	CONCRETE SIDEWALK, 4 IN.	1,484.60	0.00	1,484.60	SQYD	0.00	\$38.55	\$0.0
		0001	1650	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	896.00	0.00	896.00	LF	0.00	\$34.65	\$0.0
		0001	1660	6091052	CURB AND GUTTER TYPE B	802.00	0.00	802.00	LF	563.00	\$35.05	\$19,733.1
		0001	1670	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	3.00	0.00	3.00	CUYD	0.00	\$75.00	\$0.0
		0001	1680	6096041	PLACING TYPE 1 ROCK DITCH LINER	3.00	0.00	3.00	CUYD	0.00	\$75.00	\$0.0
		0001	1690	6097000	ROCK LINING	7.00	0.00	7.00	CUYD	2.00	\$95.00	\$190.0
		0001	1700	6099903	MISC.CURB AND GUTTER TYPE CG-1	522.00	0.00	522.00	LF	0.00	\$30.90	\$0.0
		0001	1710	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	1.00	0.00	1.00	EA	0.00	\$1,050.00	\$0.0
					600MM)							
		0001	1720	6143014	MANHOLE FRAME AND COVER, TYPE 4	1.00	0.00	1.00	EA	0.00	\$750.00	\$0.0
		0001	1730	6161005	CONSTRUCTION SIGNS	339.00	0.00	339.00	SQFT	249.00	\$6.50	\$1,618.5
		0001	1740	6161025	CHANNELIZER (TRIM LINE)	189.00	0.00	189.00	EA	160.00	\$31.00	\$4,960.0
		0001	1750	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$185.00	\$1,850.0
		0001	1760	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	1.00	\$2,500.00	\$2,500.0
		0001	1770	6169902	MISC.TYPE II PEDESTRIAN BARRICADE	5.00	0.00	5.00	EA	0.00	\$150.00	\$0.0
		0001	1780	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$110,000.00	\$110,000.0

Revision 4/1/2020 Page 12 of 31



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11015-C03	J4P3009B	0001	1790	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.0
		0001	1800	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	141.00	0.00	141.00	LF	0.00	\$4.50	\$0.0
		0001	1810	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	462.00	0.00	462.00	LF	0.00	\$20.00	\$0.0
		0001	1820	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	96.00	0.00	96.00	LF	0.00	\$14.00	\$0.0
		0001	1830	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	23.00	0.00	23.00	EA	0.00	\$275.00	\$0.0
		0001	1840	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD	1.00	0.00	1.00	EA	0.00	\$450.00	\$0.0
		0001	1850	6200036	(ONLY) PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN	78.00	0.00	78.00	EA	0.00	\$185.00	\$0.0
		0001	1860	6205301B	WHITE MIDBLOCK TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,606.00	0.00	5,606.00	LF	0.00	\$2.00	\$0.0
		0001	1870	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,561.00	0.00	2,561.00	LF	0.00	\$2.00	\$0.
		0001	1880	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	8.00	0.00	8.00	EA	8.00	\$115.00	\$920.
		0001	1890	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING	3,951.00	0.00	3,951.00	LF	0.00	\$0.55	\$0.0
		0001	1900	6205903A	PAINT, TYPE L BEADS 6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT	2,361.00	0.00	2,361.00	LF	0.00	\$0.55	\$0.0
		0001	1910	6205906A	MARKING PAINT, TYPE L BEADS 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT	333.00	0.00	333.00	LF	0.00	\$0.90	\$0.0
			1920	6207001	MARKING PAINT, TYPE L BEADS PAVEMENT MARKING REMOVAL	630.00	0.00	630.00	LF	252.00	\$1.00	\$252.
		0001	1930	6207001	PAVEMENT MARKING REMOVAL (SYMBOLS)	10.00	0.00	10.00	EA	3.00	\$1.00	\$252.1
		0001	1940	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	15,347.00	0.00	15,347.00	SQYD	0.00	\$3.00	\$0.0
		0001	1950	6240103A	SURFACING (3 IN. THICK OR LESS) PERMANENT EROSION CONTROL GEOTEXTILE	8.00	0.00	8.00	SQYD	0.00	\$5.00	\$0.0
		0001	1960	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$24,000.00	\$24,000.
		0001	1970	7261015	15 IN. PIPE GROUP A	97.00	0.00	97.00	LF	57.00	\$80.00	\$4,560
		0001	1980	7261030	30 IN. PIPE GROUP A	15.00	0.00	15.00	LF	0.00	\$160.00	\$0.
		0001	1990	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	7.00	0.00	7.00	FT	0.00	\$625.00	\$0.
		0001	2000	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	6.00	0.00	6.00	FT	0.00	\$775.00	\$0
		0001	2010	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,950.00	\$1,950
		0001	2020	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	0.00	\$2,500.00	\$0.
		0001	2030	8031000A	TURF TYPE TALL FESCUE SODDING	1,064.00	0.00	1,064.00	SQYD	0.00	\$5.65	\$0.
		0001	2040	8051000A	SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00	\$1,600.00	\$0.
		0001	2050	8061004	SEDIMENT TRAP ROCK	18.00	0.00	18.00	CUYD	0.00	\$90.00	\$0.
		0001	2060	8061005	ROCK DITCH CHECK	188.00	0.00	188.00	LF	0.00	\$55.00	\$0.
		0001	2070	8061007A	CURB INLET CHECK	5.00	0.00	5.00	EA	0.00	\$63.00	\$0
		0001	2080	8061016	SEDIMENT REMOVAL	53.00	0.00	53.00	CUYD	0.00	\$25.00	\$0.
		0001	2090	8061019	SILT FENCE	793.00	0.00	793.00	LF	0.00	\$1.35	\$0.
		0001	2100	8064128	TYPE 1 TURF REINFORCEMENT MAT	593.00	0.00	593.00	SQYD	0.00	\$1.95	\$0.
		0020	2110	9011010	RELOCATED POLE	6.00	0.00	6.00	EA	0.00	\$800.00	\$0.
		0020	2120	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.
		0020	2130	9011115	BRACKET ARM, 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,200.00	\$0
		0020	2140	9011312	LUMINAIRE, LED-B	7.00	0.00	7.00	EA	0.00	\$200.00	\$0
		0020	2150	9014004	CONDUIT, 4 IN. RIGID, PUSHED	136.00	0.00	136.00	LF	136.00	\$35.00	\$4,760
		0020	2160	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	322.00	0.00	322.00	LF	0.00	\$60.00	\$0
		0020	2170	9015010	TRENCHING TYPE I	795.00	0.00	795.00	LF	53.00	\$6.00	\$318
		0020	2180	9016110	PULL BOX, PREFORMED CLASS 1	5.00	0.00	5.00	EA	2.00	\$355.00	\$710
		0020	2190	9017004	CABLE, 4 AWG 1 CONDUCTOR	1,110.00	0.00	1,110.00	LF	0.00	\$3.00	\$0
		0020	2200	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,700.00	0.00	1,700.00	LF	456.00	\$2.50	\$1,140
		0020	2210	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	120.00	0.00	120.00	LF	0.00	\$2.00	\$0.
			2220	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE	920.00	0.00	920.00	LF	0.00	\$12.50	\$0.

Page 13 of 31 Revision 4/1/2020



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009B	0020	2230	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	0.00	\$1,400.00	\$0.00
		0020	2240	9019902	MISC.LEE'S SUMMIT 40 FT. POLE FOUNDATION B40D SCREW-IN	3.00	0.00	3.00	EA	0.00	\$1,500.00	\$0.00
		0020	2250	9019902	MISC.LUMINAIRE, LED-A WALL PACK (INCLUDING HOUSING)	4.00	0.00	4.00	EA	0.00	\$1,200.00	\$0.00
		0020	2260	9019902	MISC.PULL BOX LID REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.00
		0020	2270	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	410.00	0.00	410.00	LF	91.00	\$25.00	\$2,275.00
		0030	2280	9020211	SIGNAL HEAD, TYPE 1S	18.00	0.00	18.00	EA	0.00	\$175.00	\$0.00
		0030	2290	9020215	SIGNAL HEAD, TYPE 5S	1.00	0.00	1.00	EA	0.00	\$1,500.00	\$0.00
		0030	2300	9020513	SIGNAL HEAD, TYPE 3B	9.00	0.00	9.00	EA	0.00	\$975.00	\$0.00
		0030	2310	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	0.00	\$1,275.00	\$0.00
		0030	2320	9020833	SH-FLAT SHEET - SIGNAL SIGN	42.00	0.00	42.00	SQFT	0.00	\$80.00	\$0.00
		0030	2330	9020834	SIGNAL SIGN, MOUNTING HARDWARE	21.00	0.00	21.00	EA	0.00	\$60.00	\$0.00
		0030	2340	9022708	POST, SIGNAL 8 FT. OR 2.4 M	11.00	0.00	11.00	EA	0.00	\$1,325.00	\$0.00
		0030	2350	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,750.00	\$0.00
		0030	2360	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	0.00	\$15,000.00	\$0.00
		0030	2370	9024920	DETECTOR, PUSHBUTTON	18.00	0.00	18.00	EA	0.00	\$1,250.00	\$0.00
		0030	2380	9024975	VIDEO DETECTION SYSTEM	3.00	0.00	3.00	EA	1.00	\$24,000.00	\$24,000.00
		0030	2390	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	267.00	0.00	267.00	LF	0.00	\$17.50	\$0.00
		0030	2400	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	37.00	0.00	37.00	LF	0.00	\$13.00	\$0.00
		0030	2410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	789.00	0.00	789.00	LF	314.00	\$32.00	\$10,048.00
		0030	2420	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,450.00	0.00	3,450.00	LF	0.00	\$1.50	\$0.00
		0030	2430	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,460.00	0.00	3,460.00	LF	0.00	\$2.00	\$0.00
		0030	2440	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,110.00	0.00	2,110.00	LF	0.00	\$2.50	\$0.00
		0030	2450	9028811	PULL BOX, PREFORMED CLASS 2	13.00	0.00	13.00	EA	0.00	\$1,750.00	\$0.00
		0030	2460	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	0.00	\$1,825.00	\$0.00
		0030	2470	9029100	BASE, CONCRETE	11.80	0.00	11.80	CUYD	0.00	\$2,500.00	\$0.00
		0030	2480	9029902	MISC.POST, SIGNAL 4 FT.	3.00	0.00	3.00	EA	0.00	\$985.00	\$0.00
		0030	2490	9029902	MISC.PULL BOX CLASS 3 LID REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$250.00	\$0.00
		0030	2500	9109902	MISC.CCTV CAMERA ASSEMBLY, INSTALLED	2.00	0.00	2.00	EA	0.00	\$8,000.00	\$0.00
		0040	2510	9031010	CONCRETE FOOTINGS, EMBEDDED	1.70	0.00	1.70	CUYD	0.00	\$1,300.00	\$0.00
		0040	2520	9031210	STRUCTURAL STEEL POSTS	1,520.00	0.00	1,520.00	LB	0.00	\$4.25	\$0.00
		0040	2530	9031270A	2 IN. PSST POST - 12 GA.	236.00	0.00	236.00	LF	0.00	\$20.50	\$0.00
		0040	2540	9035004A	SH-FLAT SHEET	67.00	0.00	67.00	SQFT	0.00	\$23.50	\$0.00
		0040	2550	9035011A	ST-STRUCTURAL	318.00	0.00	318.00	SQFT	0.00	\$21.50	\$0.00
		0040	2560	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$37.50	\$0.00
					Date as of Report Generated Date							\$224,937.65
211015-C03 Ove	erall - Total V	/alue Poste	d to Date	as of Repor	t Generated Date							\$4,133,065.20

Revision 4/1/2020 Page 14 of 31



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3009

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0030	2031000	CLASS A EXCAVATION	7/25/22	8/1/22	15.00	CUYD	ramp 1	1+23.88		12+71.77		
				8/1/22	19.00	CUYD		0+00		8+89.94		
				8/1/22	96.00	CUYD	ramp 2	0+00		11+00		
				8/1/22	1,477.00	CUYD		560+00		576+50		
0050	2036000	COMPACTING EMBANKMENT	7/25/22	8/1/22	13.00	CUYD	ramp1	1+23.88		12+71.77		
				8/1/22	17.00	CUYD	ramp 2	0+00		11+00		
				8/1/22	17.00	CUYD	ramp 3	0+00		8+89.94		
				8/1/22	109.00	CUYD	ramp 4	1+20.96		11+94.66		
				8/1/22	965.00	CUYD		560+00		576+50		
				8/1/22	1,284.00	CUYD		560+00		576+50		
0060	2037075	COMPACTING IN CUT	7/25/22	8/1/22	8.00	STA		560+00		576+50		
0090	3040504	TYPE 5 AGGREGATE FOR BASE	7/28/22	8/2/22	38.00	SQYD	Ramp 4 Optional Pavement Overrun	1+20.13		1+80.00		
0110	3049905	MISC. AGGREGATE FOR BASE	7/25/22	8/1/22	3,497.00	SQYD		560+00		568+37.66		
				8/1/22	3,582.00	SQYD		560+00		568+53.77		
0120	4010150	TYPE A2 SHOULDER	8/1/22	8/2/22	556.22	SQYD	EB US-50	560+44.50	N/A	568+37.66	N/A	4" Bit Base
				8/2/22	578.48	SQYD	WB US-50	560+26.31	N/A	568+53.27	N/A	4" Bit Base
0140	4019905	MISC.	7/28/22	8/2/22	38.00	SQYD	Ramp 4 Additional Optional Pavement	1+20.13		1+80.00		
0150	4019905	MISC.	7/30/22	8/2/22	1,675.24	SQYD	EB US-50	560+00.00	N/A	568+37.66	N/A	7.75" SP190C Base Course
				8/2/22	1,708.72	SQYD	WB US-50	560+00.00	N/A	568+53.77	N/A	7.75" SP190C Base Course
0270	6113010	FURNISHING TYPE 1 ROCK BLANKET	7/20/22	8/1/22	71.00	CUYD		568+51.64	rt	569+12.79	It	
				8/1/22	72.00	CUYD		569+85.38	rt	570+47.62	It	
0280	6113030	PLACING TYPE 1 ROCK BLANKET	7/20/22	8/1/22	71.00	CUYD		568+51.64	rt	569+12.79	It	
				8/1/22	72.00	CUYD		569+85.38	rt	570+47.62	It	
0370	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	7/20/22	8/1/22	14.00	LF		12+07		12+21		
				8/1/22	14.00	LF		13+70		13+84		
0510	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	7/20/22	8/1/22	107.00	SQYD		568+51.64		569+12.79		
				8/1/22	108.00	SQYD		569+85.38		570+47.62		
0660	8061019	SILT FENCE	7/28/22	8/1/22	305.00	LF		567+59		570+64		
				8/1/22	540.00	LF		569+00		574+40		
5004	7209901	MISC.	7/28/22	8/2/22	1.00	LS	North MSE Wall Extra Work	568+94.03		568+94.03		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 15 of 31



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0040	EMBANKMENT IN PLACE	Material		3	Apr 18, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$12,020.00)	
					4	May 2, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$12,020.00)	
					5	May 16, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$12,020.00)	
					6	Jun 1, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$12,020.00)	, ,
					7	Jun 16, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$12,020.00)	,
					8	Jul 1, 2022	SYSTEM	\$63,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$63,400.00)	,
					9	Jul 18, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$72,520.00)	
					10	Aug 2, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$72,520.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0040 -	Total						\$0.00	
	0050	COMPACTING EMBANKMENT	Material		3	Apr 18, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$272.50)	
					4	May 2, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$272.50)	
					5	May 16, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$272.50)	
					6	Jun 1, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$272.50)	
					7	Jun 16, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$272.50)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
3009	0050	COMPACTING EMBANKMENT	Material		8	Jul 1, 2022	SYSTEM	\$4,010.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					8	Jul 1, 2022	SYSTEM	(\$4,010.00)			
					9	Jul 18, 2022	SYSTEM	\$7,222.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					9	Jul 18, 2022	SYSTEM	(\$7,222.50)			
					10	Aug 2, 2022	SYSTEM	\$13,235.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		
					10	Aug 2, 2022	SYSTEM	(\$13,235.00)			
				- Total				\$0.00			
			Material - Tota	l e				\$0.00			
	0050 -	Total						\$0.00			
	0060	COMPACTING IN CUT	Material		8	Jul 1, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					8	Jul 1, 2022	SYSTEM	(\$5,600.00)			
					9	Jul 18, 2022	SYSTEM	\$8,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
					9	Jul 18, 2022	SYSTEM	(\$8,400.00)			
							10	Aug 2, 2022	SYSTEM	\$11,200.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$11,200.00)			
				- Total				\$0.00			
			Material - Tota	l				\$0.00			
	0060 -	Total						\$0.00			
	0090	060 - Total	Material		2	Apr 4,	SYSTEM	\$10,271.25	This adjustes of effects the existent content of Material December		
		AGGREGATE FOR BASE				2022		\$10,271.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.		
	A				2	2022 Apr 4, 2022	SYSTEM	(\$10,271.25)	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment		
					2	Apr 4,	SYSTEM		Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment		
						Apr 4, 2022 Apr 18,		(\$10,271.25)	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment		
				- Total	3	Apr 4, 2022 Apr 18, 2022 Apr 18,	SYSTEM	(\$10,271.25) \$23,941.50	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment		
			Material - Tota		3	Apr 4, 2022 Apr 18, 2022 Apr 18,	SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50)	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment		
	0090 -	BASE	Material - Tota		3	Apr 4, 2022 Apr 18, 2022 Apr 18,	SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment		
	0090 - 0100	Total TYPE 5 AGGREGATE FOR BASE (6 IN.			3	Apr 4, 2022 Apr 18, 2022 Apr 18,	SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment		
		Total TYPE 5 AGGREGATE FOR			3	Apr 4, 2022 Apr 18, 2022 Apr 18, 2022 May 16,	SYSTEM SYSTEM SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment		
		Total TYPE 5 AGGREGATE FOR BASE (6 IN.	Material	- Total	3	Apr 4, 2022 Apr 18, 2022 Apr 18, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00 \$0.00 \$6,990.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment		
	0100	Total TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)		- Total	3	Apr 4, 2022 Apr 18, 2022 Apr 18, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00 \$0.00 \$6,990.00 (\$6,990.00) \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment		
		Total TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material	- Total	3 3 5 5	Apr 4, 2022 Apr 18, 2022 Apr 18, 2022 May 16, 2022	SYSTEM SYSTEM SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00 \$0.00 \$6,990.00 (\$6,990.00)	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment		
	0100	Total TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) Total MISC. AGGREGATE FOR	Material	- Total	3 3 5 5	Apr 4, 2022 Apr 18, 2022 Apr 18, 2022 May 16, 2022 Jun 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00 \$0.00 \$6,990.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		
	0100	Total TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) Total MISC.	Material Material - Tota	- Total	3 3 5 5	Apr 4, 2022 Apr 18, 2022 Apr 18, 2022 May 16, 2022 Jun 16,	SYSTEM SYSTEM SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00 \$0.00 \$6,990.00 (\$6,990.00) \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate.		
	0100	Total TYPE 5 AGGREGATE FOR BASE (6 IN. THICK) Total MISC. AGGREGATE FOR	Material Material - Tota	- Total	3 3 5 5	Apr 4, 2022 Apr 18, 2022 Apr 18, 2022 Apr 18, 2022 Jun 16, 2022 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$10,271.25) \$23,941.50 (\$23,941.50) \$0.00 \$0.00 \$6,990.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment		



ACCRECATE FOR 9											
AGDRE CATE FOR	ject	Line	Description		Adjustment				Amount	Remarks	
9	3009	0110	AGGREGATE FOR	Material			2022			Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
2022 10 Aug. SYSTEM (\$126,878.00)			BASE			9		SYSTEM	(\$51,007.00)		
Address						10		SYSTEM	\$128,876.00	Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	
Material - Total						10		SYSTEM	(\$128,876.00)		
Material - Total					- Total				(\$51,007.00)		
Material Credit				Material - Tota					(\$51,007.00)		
Material Credit - Total						8		SYSTEM			
110											
1797 Apr Application Acad Application Acad Application Acad Application Acad A				MaterialCredit	- Total				\$51,007.00		
SHOULDER Adjustment		0110 -	Total						\$0.00		
		0120			ACAD	8		vohsr1	\$1,787.70	This Adjustment is being made for the Bit Base lift for the Type A2 Shoulder for the pavement South of the bridge.	
MiSC Material					ACAD - Tota	al			\$1,787.70		
Misc. Material				Other Item Adj	ustment - To	tal			\$1,787.70		
2022 Estimate Item Aglustment (0030) due to user voher1 overridding Payment Estimate Exception 3 on the current Payment Estimate.		0120 -	Total						\$1,787.70		
2022 5		0130	MISC.	Material		4		SYSTEM	\$24,000.00	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment	
2022 SYSTEM \$46,600.00						4		SYSTEM	(\$24,000.00)		
2022						5		SYSTEM	\$46,600.00	Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment	
2022 Estimate Item Adjustment (0020) due to user vorbart overridding Payment Estimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate Payment Estimate Item Adjustment (0020) due to user vorbart overridding Payment Estimate Item Adjustment (0020) due to user vorbart overridding Payment Estimate Item Adjustment (0020) due to user vorbart overridding Payment Estimate Exception 4 on the current Payment Estimate. 7							5		SYSTEM	(\$46,600.00)	
2022 7						6		SYSTEM	\$46,600.00	Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment	
2022 Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						6		SYSTEM	(\$46,600.00)		
2022						7		SYSTEM	\$46,600.00	Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment	
2022 Estimate Item Adjustment (0027) due to user voher1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 8 Jul 1, 2022 9 Jul 18, 2022 1 SYSTEM \$46,600.00 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. 9 Jul 18, 2022 2 SYSTEM \$46,600.00 - Total S0.00 Material - Total S0.00 0130 - Total NISC. Material 2 Apr 4, 2022 3 Apr 4, 2022 3 Apr 18, SYSTEM \$37,350.00 3 Apr 18, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 Apr 18, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 1 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 Apr 18, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.						7		SYSTEM	(\$46,600.00)		
2022 9						8		SYSTEM	\$46,600.00	Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment	
Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate. 9 Jul 18, 2022 \$0.00 Material - Total \$0.00 0130 - Total \$0.00 0140 MISC. Material \$2 Apr 4, 2022 SYSTEM \$37,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 2 Apr 4, SYSTEM \$37,350.00 2 Apr 18, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 Apr 18, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						8		SYSTEM	(\$46,600.00)		
Total So.00 Material - Total \$0.00 0130 - Total MISC. Material 2 Apr 4, 2022 3 Apr 4, 2022 3 Apr 18, 2022 3 Apr 18, 2022 3 Apr 18, 2022 3 Apr 18, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 2 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. 3 Apr 18, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate.						9		SYSTEM	\$46,600.00	Estimate Item Adjustment (0007) due to user raybol1 overridding Payment	
Material - Total \$0.00						9		SYSTEM	(\$46,600.00)		
System Stimate Item Adjustment (0003) due to user vohsr1 overridding Payment Stimate Exception 2 on the current Payment System Stimate Stim					- Total				\$0.00		
MISC. Material 2 Apr 4, 2022 SYSTEM \$37,350.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate. 3 Apr 18, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 3 Apr 18, SYSTEM \$103,080.00)				Material - Tota					\$0.00		
MISC. Material 2 Apr 4, 2022 3 Apr 4, 2022 3 Apr 18, 2022 4 SYSTEM (\$103,080.00)		0130	Total						\$0.00		
2 Apr 4, 2022 SYSTEM (\$37,350.00) 3 Apr 18, 2022 SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 3 Apr 18, SYSTEM (\$103,080.00)				Material		2		SYSTEM		Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment	
3 Apr 18, 2022 SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate. 3 Apr 18, SYSTEM (\$103,080.00)						2		SYSTEM	(\$37,350.00)		
3 Apr 18, SYSTEM (\$103,080.00)						3	Apr 18,	SYSTEM	\$103,080.00	Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment	
ZÜZZ						3	Apr 18, 2022	SYSTEM	(\$103,080.00)	,	
4 May 2, SYSTEM \$103,080.00 This adjustment offsets the original system-generated Material Payment						4		CVCTEL	¢102.000.00	This adjustment affects the original system represed Metarial Demonstration	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
009	0140	MISC.	Material			2022			Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$103,080.00)	
					5	May 16, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$103,080.00)	
					6	Jun 1, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$103,080.00)	
					7	Jun 16, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$103,080.00)	
					8	Jul 1, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$103,080.00)	
					9	Jul 18, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$103,080.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0140 -	Total						\$0.00	
	0150	0 - Total MISC.	Other Item Adjustment	ACAD	8	Jul 1, 2022	vohsr1	\$11,167.45	This adjustment is being made for the SP 190 C asphalt placed on the sou side of the bridge.
					8	Jul 1, 2022	vohsr1	\$4,209.06	This adjustment is being made for the SP 190 C asphalt placed on the sou side of the bridge.
				ACAD - Tota				\$15,376.51	
	0450		Other Item Ad	justment - 10	tal			\$15,376.51	
	0150 -		011 11	4040				\$15,376.51	A 1 1 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	0160	ASPHALTIC CONCRETE MIXTURE PG	Other Item Adjustment	ACAD		May 2, 2022	vohsr1	\$1,167.05	Asphalt Cement Price Adjustment for Line 0180, April 2022
		70-22 (SP125C MIX)	Other Item Ad	ACAD - Tota				\$1,167.05	
	0160 -	,	Other Item Ad	justinent - 10	itai			\$1,167.05	
	0180	CONCRETE APPROACH PAVEMENT	Material		9	Jul 18, 2022	SYSTEM	\$1,167.05 \$41,246.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$41,246.28)	
					10	Aug 2, 2022	SYSTEM	\$41,246.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$41,246.28)	
	0180 - Total 0190 PIF			- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
J		Total						\$0.00	
		PIPE COLLAR, TYPE A	Material		4	May 2, 2022	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$3,300.00)	
						5	May 16, 2022	SYSTEM	\$3,300.00



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3009	0190	PIPE COLLAR, TYPE A	Material		5	May 16, 2022	SYSTEM	(\$3,300.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0190 -	Total						\$0.00	
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material		6	Jun 1, 2022	SYSTEM	\$14,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$14,064.00)	
					7	Jun 16, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$23,520.00)	
					8	Jul 1, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$23,520.00)	
					9	Jul 18, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$23,520.00)	
					10	Aug 2, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$23,520.00)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
	0210 -	Total						\$0.00	
	0350	CMS W/O COMMUNICATION INTERFACE,	Material		1	Mar 18, 2022	SYSTEM	\$19,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		CONT F/			1	Mar 18, 2022	SYSTEM	(\$19,000.00)	
				- Total				\$0.00	
			Material - Tota	l .				\$0.00	
	0350 -	Total						\$0.00	
	0370	CONCRETE TRAFFIC BARRIER, TYPE C	Material		8	Jul 1, 2022	SYSTEM	\$29,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$29,800.00)	
					9	Jul 18, 2022	SYSTEM	\$29,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$29,800.00)	
					10	Aug 2, 2022	SYSTEM	\$35,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$35,400.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0370 -	Total						\$0.00	
	0660	SILT FENCE	Material		4	May 2, 2022	SYSTEM	\$850.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$850.50)	



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
09	0660	SILT FENCE	Material - Tota	l				\$0.00					
	0660 -	Total						\$0.00					
	0690	MGS GUARDRAIL, 8 FT. POSTS, 6 FT. - 3 IN	Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$33,968.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
		- 5 114	STIVII	- Total				\$33,968.00					
			Construction	Stockpile STI	MI - Total			\$33,968.00					
	0690 -	Total						\$33,968.00					
	0700	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$1,851.85	Payment Estimate Item Adjustment generated Stockpile Transaction				
		(1.25/110 001.2)	011111	- Total				\$1,851.85					
			Construction	Stockpile STI	MI - Total			\$1,851.85					
	0700 -	Total						\$1,851.85					
	0710	MGS END ANCHOR	Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$830.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
			STIVII	- Total				\$830.00					
			Construction	Stockpile STI	MI - Total			\$830.00					
	0710 -	Total						\$830.00					
	0720	CRASHWORTHY	Construction Stockpile		4	May 2, 2022	SYSTEM	\$7,520.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
		END TERMINAL (MASH)	STMI	- Total				\$7,520.00					
			Construction Stockpile STMI - Total					\$7,520.00					
	0720 -	Total						\$7,520.00					
ſ	0730	0 MISC. GUARDRAIL ITEM	Construction Stockpile		8	Jul 1, 2022	SYSTEM	(\$3,300.00)	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total				(\$3,300.00)					
			Construction	Stockpile - To	otal			(\$3,300.00)					
					Construction		2	Apr 4,	SYSTEM	\$3,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction		
			Stockpile STMI			2022			. , ,				
							STIVII	- Total				\$3,300.00	
							Construction	Stockpile STI	VII - Total			\$3,300.00	
			Material		8	Jul 1, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					8	Jul 1, 2022	SYSTEM	(\$10,000.00)					
					9	Jul 18, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.				
					9	Jul 18, 2022	SYSTEM	(\$10,000.00)					
					10	Aug 2, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					10	Aug 2, 2022	SYSTEM	(\$10,000.00)	Example 2.50pton 1. Strate cancel a symbol 25minute				
				- Total				\$0.00					
			Material - Tota					\$0.00					
	0730 -	Total						\$0.00					
		MISC. GUARDRAIL	Construction Stockpile		2	Apr 4, 2022	SYSTEM	\$21,968.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
			STMI	- Total				\$21,968.00					
			Construction		VII - Total			\$21,968.00					
	0740 -	Total						\$21,968.00					
	0840	CCTV POLE FOUNDATION, 45	Material		4	May 2, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment				
		FT OR 13.7M MOU			4	May 2, 2022	SYSTEM	(\$8,500.00)	Estimate Exception 13 on the current Payment Estimate.				
					5	May 16, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.				



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0840	CCTV POLE FOUNDATION, 45	Material		5	May 16, 2022	SYSTEM	(\$8,500.00)	
		FT OR 13.7M MOU			6	Jun 1, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$8,500.00)	
					7	Jun 16, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$8,500.00)	
					8	Jul 1, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$8,500.00)	
					9	Jul 18, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$8,500.00)	
					10	Aug 2, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$8,500.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0840 -	· Total						\$0.00	
	0850	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		2	Apr 4, 2022	SYSTEM	\$3,064.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$3,064.50)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0850 -							\$0.00	
	0890	MISC. ITS	Material		4	May 2, 2022	SYSTEM	\$5,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$5,500.00)	
				- Total			\$0.00		
			Material - Tota					\$0.00	
	0890 - 0900	Total MISC. ITS	Material		4	May 2, 2022	SYSTEM	\$0.00 \$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment
					4	May 2,	SYSTEM	(\$6,000.00)	Estimate Exception 16 on the current Payment Estimate.
				- Total		2022		\$0.00	
			Material - Tota					\$0.00	
	0900 -	· Total						\$0.00	
	0930	MISC. ITS	Material		2	Apr 4, 2022	SYSTEM	\$13,440.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$13,440.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0930 -	Total						\$0.00	
	0960	BRIDGE APPROACH SLAB	Material		9	Jul 18, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J4P3009	0960	(MAJOR ROAD)	Material						Estimate Exception 10 on the current Payment Estimate.								
					9	Jul 18,	SYSTEM	(\$45,336.20)									
					10	2022 Aug 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment								
					10	Aug 2, 2022	SYSTEM	(\$45,336.20)	Estimate Exception 6 on the current Payment Estimate.								
				- Total		2022		\$0.00									
			Material - Tota					\$0.00									
	0960 -	Total						\$0.00									
	0970	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
					5	May 16, 2022	SYSTEM	(\$51,220.00)	Esumate Exception 11 on the current Payment Estimate.								
					6	Jun 1, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.								
							6	Jun 1, 2022	SYSTEM	(\$51,220.00)							
											7	Jun 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.		
											7	Jun 16, 2022	SYSTEM	(\$51,220.00)			
											8	Jul 1, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
										8	Jul 1, 2022	SYSTEM	(\$51,220.00)				
									9	Jul 18, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.				
																	9
					10	Aug 2, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.								
					10	Aug 2, 2022	SYSTEM	(\$51,220.00)									
				- Total				\$0.00									
			Material - Tota	ıl				\$0.00									
	0970 -	Total						\$0.00									
	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.								
					5	May 16, 2022	SYSTEM	(\$20,544.00)									
					6						6	Jun 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.		
						7	Jun 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
						7	Jun 16, 2022	SYSTEM	(\$20,544.00)								
					3	8	8			8	Jul 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.			
					8	Jul 1, 2022	SYSTEM	(\$20,544.00)									
				9	Jul 18, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.									



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks					
J4P3009	0980	ROCK SOCKETS	Material	Туре	9	Jul 18,	SYSTEM	(\$20,544.00)						
		(3 FT 6 IN. DIA.)			10	2022 Aug 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.					
					10	Aug 2, 2022	SYSTEM	(\$20,544.00)	Estimate Exception 30 on the current rayment Estimate.					
				- Total		2022		\$0.00						
			Material - Tota					\$0.00						
	0980 -	Total						\$0.00						
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material		5	May 16, 2022	SYSTEM	\$13,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.					
					5	May 16, 2022	SYSTEM	(\$13,760.00)						
					6	Jun 1, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.					
					6	Jun 1, 2022	SYSTEM	(\$80,324.00)						
					7	Jun 16, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.					
					7	Jun 16, 2022	SYSTEM	(\$80,324.00)						
					8	Jul 1, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.					
					8	Jul 1, 2022	SYSTEM	(\$80,324.00)						
										9	Jul 18, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
							9	Jul 18, 2022	SYSTEM	(\$80,324.00)				
					10	Aug 2, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.					
					10	Aug 2, 2022	SYSTEM	(\$80,324.00)						
				- Total				\$0.00						
			Material - Tota	I				\$0.00						
	1040 -	Total						\$0.00						
	1050	TYPE D BARRIER	Construction Stockpile		9	Jul 18, 2022	SYSTEM	(\$6,593.71)	Payment Estimate Item Adjustment generated Stockpile Transaction					
				- Total				(\$6,593.71)						
			Construction S	Stockpile - To	otal			(\$6,593.71)						
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$6,593.71	Payment Estimate Item Adjustment generated Stockpile Transaction					
			STMI	- Total				\$6,593.71						
			Construction S	Stockpile STI	MI - Total			\$6,593.71						
			Material		9	Jul 18, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.					
					9	Jul 18, 2022	SYSTEM	(\$52,020.00)						
					10	10	Aug 2, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.				
					10	Aug 2, 2022	SYSTEM	(\$52,020.00)						
				- Total				\$0.00						
			Material - Total					\$0.00						
	1050 -	Total						\$0.00						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4P3009	1060	SLAB ON CONCRETE NU- GIRDER	Material		7	Jun 16, 2022	SYSTEM	\$144,235.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.			
					7	Jun 16, 2022	SYSTEM	(\$144,235.20)				
					8	Jul 1, 2022	SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 33 on the current Payment Estimate.			
					8	Jul 1, 2022	SYSTEM	(\$186,303.80)				
					9	Jul 18, 2022	SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 56 on the current Payment Estimate.			
					9	Jul 18, 2022	SYSTEM	(\$186,303.80)				
					10	Aug 2, 2022	SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.			
					10	Aug 2, 2022	SYSTEM	(\$186,303.80)	,			
				- Total		2022		\$0.00				
			Material - Tota					\$0.00				
	1060 -	Total						\$0.00				
	1080	NU 35, PRESTRESSED	Construction Stockpile		7	Jun 16, 2022	SYSTEM	(\$36,307.98)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		CONC NU-GIRDER		- Total				(\$36,307.98)				
			Construction S	Stockpile - To	otal			(\$36,307.98)				
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$36,307.98	Payment Estimate Item Adjustment generated Stockpile Transaction			
			STMI	- Total				\$36,307.98				
			Construction S	Stockpile STI	MI - Total			\$36,307.98				
	1080 -	Total						\$0.00				
	1090	REINFORCING STEEL (BRIDGES)	Construction Stockpile		6	Jun 1, 2022	SYSTEM	(\$6,607.60)	Payment Estimate Item Adjustment generated Stockpile Transaction			
							- Total				(\$6,607.60)	
			Construction S	Stockpile - To			01/0==1/	(\$6,607.60)				
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$6,607.60	Payment Estimate Item Adjustment generated Stockpile Transaction			
			0	- Total				\$6,607.60				
	1090 -	Total	Construction S	тоскрие 5 гг	vii - Totai			\$6,607.60				
	1100	REINFORCING STEEL (EPOXY	Construction Stockpile		5	May 16, 2022	SYSTEM	\$0.00 (\$5,333.75)	Payment Estimate Item Adjustment generated Stockpile Transaction			
		COATED)	Stoonpile		6	Jun 1, 2022	SYSTEM	(\$11,868.91)	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				(\$17,202.66)				
			Construction S		otal			(\$17,202.66)				
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$17,202.66	Payment Estimate Item Adjustment generated Stockpile Transaction			
			STMI	- Total				\$17,202.66				
			Construction S	Stockpile STI	MI - Total			\$17,202.66				
	1100 -	Total						\$0.00				
	1140	VERTICAL DRAIN AT END BENTS	Material		8	Jul 1, 2022	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.			
					8	Jul 1, 2022	SYSTEM	(\$6,000.00)				
				- Total				\$0.00				
			Material - Tota					\$0.00				
	1140 -	Total						\$0.00				
	1200	BRIDGE	Material		9	Jul 18,	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment			



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
J4P3009	1200	APPROACH SLAB (MAJOR ROAD)	Material			2022			Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
					9	Jul 18, 2022	SYSTEM	(\$45,336.20)									
					10	Aug 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					10	Aug 2, 2022	SYSTEM	(\$45,336.20)									
				- Total				\$0.00									
	1200 -	Total	Material - Tota	al				\$0.00									
		DRILLED SHAFTS	Material		5	May 16	SYSTEM	\$0.00	This adjustment affects the original system generated Material Dayment								
	1210	(4 FT. 0 IN. DIA.)	Material		5	May 16, 2022	STSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
					5	May 16, 2022	SYSTEM	(\$43,340.00)									
					6	Jun 1, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
					6	Jun 1, 2022	SYSTEM	(\$43,340.00)									
					7	Jun 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.								
						7	Jun 16, 2022	SYSTEM	(\$43,340.00)								
					8	Jul 1, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.								
						8	Jul 1, 2022	SYSTEM	(\$43,340.00)								
						9	Jul 18, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.							
						9	Jul 18, 2022	SYSTEM	(\$43,340.00)								
					10	Aug 2, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.								
					10	Aug 2, 2022	SYSTEM	(\$43,340.00)									
				- Total				\$0.00									
			Material - Tota	al				\$0.00									
	1210 -	Total						\$0.00									
	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.								
			5 6 6 7	6			Ę	5		5	May 16, 2022	SYSTEM	(\$20,544.00)				
											6	Jun 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.		
																	6
				7	Jun 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.									
					7	Jun 16, 2022	SYSTEM	(\$20,544.00)									
					8	Jul 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.								
				8	8	Jul 1,	SYSTEM	(\$20,544.00)									
						2022											



ASP-0009 GOAD CACCACTES Maneral	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
9	J4P3009	1220		Material						Estimate Exception 42 on the current Payment Estimate.								
10			(3 FT 6 IN. DIA.)			9		SYSTEM	(\$20,544.00)									
10						10	Aug 2,	SYSTEM	\$20,544.00	Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment								
1200 Total 10.00						10		SYSTEM	(\$20,544.00)	Estimate Exception 32 on the current Payment Estimate.								
1220 - Total					- Total				\$0.00									
1,280 CLASS Material CONCRETE Substitute Subs				Material - Tota					\$0.00									
SUBSTRUCTURE		1220 -	Total						\$0.00									
2022 SYSTEM \$80,127.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 26 on the current Payment Estimate (2009) due to user volves 1 overridding Payment Estimate (2009) due to user volves 1 overridding Payment Estimate (2009) due to user volves 1 overridding Payment Estimate (2009) due to user volves 1 overridding Payment (2009) due to user volves 1 ove		1280	CONCRETE	Material		5		SYSTEM	\$13,920.00	Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment								
2022 SYSTEM S80,127.00 This adjustment (0059) due to user votant overridding Payment						5		SYSTEM	(\$13,920.00)									
2022 7 2021 7 2022 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022 7 2022						6		SYSTEM	\$80,127.00	Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment								
2022 SYSTEM (\$80,127.00) This adjustment (0003) due to user volard overridding Payment Estimate Exception 27 on the current Payment Estimate.						6		SYSTEM	(\$80,127.00)									
2002 8													7		SYSTEM	\$80,127.00	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment	
2022 Estimate Item Adjustment (040) due to user volsar) overridding Payment Estimate Estimate														7		SYSTEM	(\$80,127.00)	
2022 9													8		SYSTEM	\$80,127.00	Estimate Item Adjustment (0040) due to user vohsr1 overridding Payment	
2022 Estimate Item Adjustment (0022) due to user voloral overridding Payment Estimate Exception 46 on the current Payment Estimate Item Adjustment (0019) due to user voloral overridding Payment Estimate Item Adjustment (0019) due to user voloral overridding Payment Estimate Item Adjustment (0019) due to user voloral overridding Payment Estimate Item Adjustment (0019) due to user voloral overridding Payment Estimate Item Adjustment (0019) due to user voloral overridding Payment Estimate Exception 36 on the current Payment Estimate. 10										8		SYSTEM	(\$80,127.00)					
2022 10 Aug 2, 2VSTEM \$80,127.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user voltant overridding Payment Estimate Exception 36 on the current Payment Estimate.						9		SYSTEM	\$80,127.00	Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment								
2022 Estimate Item Adjustment (0019) due to user voher1 overridding Payment Estimate Exception 36 on the current Payment Estimate.								9		SYSTEM	(\$80,127.00)							
Total \$0.00							10		SYSTEM	\$80,127.00	Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment							
Type D BARRIER Construction Stockpile - Total Section Stockpile - Total Section Stockpile - Total Section Section Stockpile - Total Section Sect						10		SYSTEM	(\$80,127.00)									
1280 - Total Summer Summ					- Total				\$0.00									
TYPE D BARRIER Construction Stockpile Total Construction Stockpile - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S6,593.71 Construction Stockpile STMI - Total S6,593.71 Construction Stockpile STMI - Total S6,593.71 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate. 9 Jul 18, 2022 10 Aug 2, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 52 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM (\$52,020.00) This adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 41 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM (\$52,020.00)				Material - Tota	al				\$0.00									
Stockpile 2022 (\$6,593.71) Construction Stockpile - Total (\$6,593.71) Construction Stockpile - Total (\$6,593.71) Construction Stockpile STMI - Total \$6,593.71 Construction Stockpile STMI - Total \$6,593.71 Material 9 Jul 18, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate. 9 Jul 18, 2022 SYSTEM (\$52,020.00) 10 Aug 2, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 41 on the current Payment Estimate.		1280 -	Total															
Construction Stockpile - Total Construction Stockpile STMI - Total Construction Stockpile STMI - Total S6,593.71 Construction Stockpile STMI - Total Material 9 Jul 18, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate. 9 Jul 18, SYSTEM (\$52,020.00) 10 Aug 2, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 52 on the current Payment Estimate. 10 Aug 2, SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 41 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM (\$52,020.00)		1290	TYPE D BARRIER			9		SYSTEM	(\$6,593.71)	Payment Estimate Item Adjustment generated Stockpile Transaction								
Construction Stockpile STMI					- Total				(\$6,593.71)									
Stockpile STMI - Total S6,593.71 Construction Stockpile STMI - Total Material 9 Jul 18, 2022 10 Aug 2, 2022 SYSTEM 10 Aug 2, 2022 SYSTEM S52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 52 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM S52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 52 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM S52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user voher1 overridding Payment Estimate Exception 41 on the current Payment Estimate.				Construction S	Stockpile - To	otal			(\$6,593.71)									
Construction Stockpile STMI - Total Material 9 Jul 18, 2022 9 Jul 18, 2022 10 Aug 2, 2022 10 Aug 2, 2022 - Total \$6,593.71 \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate. 9 Jul 18, SYSTEM (\$52,020.00) 10 Aug 2, SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 41 on the current Payment Estimate. 10 Aug 2, SYSTEM (\$52,020.00)				Stockpile		4		SYSTEM	\$6,593.71	Payment Estimate Item Adjustment generated Stockpile Transaction								
Material 9 Jul 18, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user voher1 overridding Payment Estimate Exception 52 on the current Payment Estimate. 9 Jul 18, 2022 SYSTEM (\$52,020.00) 10 Aug 2, 2022 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user voher1 overridding Payment Estimate Item Adjustment (0020) due to user voher1 overridding Payment Estimate Exception 41 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM (\$52,020.00) - Total \$0.00									\$6,593.71									
2022 Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate. 9 Jul 18, 2022 10 Aug 2, 2022 2022 2022 3 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 41 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM \$52,020.00) - Total \$0.00				Construction S	Stockpile STI				\$6,593.71									
2022 10 Aug 2, 2022 10 Aug 2, 2022 10 Aug 2, 2022 10 Aug 2, 2022 10 SYSTEM \$52,020.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user voher1 overridding Payment Estimate Exception 41 on the current Payment Estimate.				Material		9		SYSTEM	\$52,020.00	Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment								
Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 41 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM (\$52,020.00) - Total \$0.00						9		SYSTEM	(\$52,020.00)									
- Total \$0.00						10		SYSTEM	\$52,020.00	Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment								
						10		SYSTEM	(\$52,020.00)									
Material - Total \$0.00					- Total				\$0.00									
				Material - Tota	I				\$0.00									



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
J4P3009	1290 -	Total						\$0.00										
	1300	SLAB ON CONCRETE NU-	Construction Stockpile		7	Jun 16, 2022	SYSTEM	(\$16,335.42)	Payment Estimate Item Adjustment generated Stockpile Transaction									
		GIRDER			8	Jul 1, 2022	SYSTEM	(\$18,150.47)	Payment Estimate Item Adjustment generated Stockpile Transaction									
				- Total				(\$34,485.89)										
			Construction S	Stockpile - To	tal			(\$34,485.89)										
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$36,300.94	Payment Estimate Item Adjustment generated Stockpile Transaction									
			STMI	- Total				\$36,300.94										
			Construction S	Stockpile STI	/II - Total			\$36,300.94										
			Material		7	Jun 16, 2022	SYSTEM	\$108,176.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.									
					7	Jun 16, 2022	SYSTEM	(\$108,176.40)										
					8	Jul 1, 2022	SYSTEM	\$228,372.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.									
						8	Jul 1, 2022	SYSTEM	(\$228,372.40)									
															9	Jul 18, 2022	SYSTEM	\$228,372.40
												9	Jul 18, 2022	SYSTEM	(\$228,372.40)			
							10	Aug 2, 2022	SYSTEM	\$228,372.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.							
					10	Aug 2, 2022	SYSTEM	(\$228,372.40)										
				- Total														
			Material - Tota	Material - Total														
	1300 -							\$1,815.05										
	1330	REINFORCING STEEL (BRIDGES)	Construction Stockpile		6	Jun 1, 2022	SYSTEM	(\$5,063.80)	Payment Estimate Item Adjustment generated Stockpile Transaction									
				- Total				(\$5,063.80)										
				uction Stockpile - To						(\$5,063.80)								
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$5,063.80	Payment Estimate Item Adjustment generated Stockpile Transaction									
			- Total					\$5,063.80										
	1330 -	T-4-1	Construction	Stockpile STI	/II - Total			\$5,063.80										
	1330 -	VERTICAL DRAIN AT END BENTS	Material		8	Jul 1, 2022	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.									
					8	Jul 1, 2022	SYSTEM	(\$6,000.00)										
				- Total				\$0.00										
			Material - Tota	ı				\$0.00										
	1380 -	Total						\$0.00										
	1440	MECHANICALLY STABILIZED	Construction Stockpile		5	May 16, 2022	SYSTEM	(\$777.26)	Payment Estimate Item Adjustment generated Stockpile Transaction									
		EARTH WALL SYS			6	Jun 1, 2022	SYSTEM	(\$86.36)	Payment Estimate Item Adjustment generated Stockpile Transaction									
				- Total				(\$863.62)										
			Construction S	Stockpile - To	otal			(\$863.62)										
			Construction Stockpile No		4	May 2, 2022	SYSTEM	\$863.62	Payment Estimate Item Adjustment generated Stockpile Transaction									
		Tran	Transaction Type	- Total				\$863.62										
			Construction S	Stockpile No	Transacti	on Type -	Total	\$863.62										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1440	MECHANICALLY STABILIZED EARTH WALL SYS	Material		5	May 16, 2022	SYSTEM	\$252,147.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$252,147.60)	
					6	Jun 1, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$280,164.00)	
					7	Jun 16, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$280,164.00)	
					8	Jul 1, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$280,164.00)	
					9	Jul 18, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$280,164.00)	
					10	Aug 2, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$280,164.00)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	1440 -	- Total						\$0.00	
	4470	MECHANICALLY	Construction		5	May 16,	SYSTEM	(\$863.61)	Payment Estimate Item Adjustment generated Stockpile Transaction
	1470	STABILIZED	Stockpile			2022		(,,,,,	, , , , ,
	1470			- Total				(\$863.61)	
	1470	STABILIZED	Stockpile Construction		otal			, ,	
	1470	STABILIZED	Construction Construction Stockpile	Stockpile - To			SYSTEM	(\$863.61) (\$863.61) \$863.61	Payment Estimate Item Adjustment generated Stockpile Transaction
	1470	STABILIZED	Construction Stockpile	Stockpile - To	otal 4	2022 May 2,		(\$863.61) (\$863.61) \$863.61	
	1470	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	otal 4 MI - Total	2022 May 2, 2022	SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61	Payment Estimate Item Adjustment generated Stockpile Transaction
	1470	STABILIZED	Construction Stockpile	Stockpile - To	otal 4	2022 May 2,		(\$863.61) (\$863.61) \$863.61	
	1470	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	otal 4 MI - Total	May 2, 2022	SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment
	1470	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	otal 4 MI - Total 5	May 2, 2022 May 16, 2022	SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61 \$863.61 \$256,650.00	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment
	1470	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	otal 4 MI - Total 5	2022 May 2, 2022 May 16, 2022 May 16, 2022 Jun 1,	SYSTEM SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61 \$256,650.00 (\$256,650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment
	14/0	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	5 6	May 2, 2022 May 16, 2022 May 16, 2022 Jun 1, 2022	SYSTEM SYSTEM SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61 \$256,650.00 (\$256,650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment
	14/0	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	5 5 6 6	May 2, 2022 May 16, 2022 May 16, 2022 Jun 1, 2022 Jun 1, 2022 Jun 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61 \$863.61 \$256,650.00 (\$256,650.00) \$256,650.00	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment
	14/0	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	Stal	May 2, 2022 May 16, 2022 May 16, 2022 Jun 1, 2022 Jun 1, 2022 Jun 16, 2022 Jun 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61 \$256,650.00 (\$256,650.00) \$256,650.00 (\$256,650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment
	14/0	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	Stal 4	May 16, 2022 May 16, 2022 Jun 1, 2022 Jun 16, 2022 Jun 16, 2022 Jun 16, 2022 Jun 16, 2022 Jun 17, 2022 Jun 17, 2022 Jun 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61 \$256,650.00 (\$256,650.00) \$256,650.00 (\$256,650.00) \$256,650.00	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 43 on the current Payment Estimate.
	14/0	STABILIZED	Construction : Construction Stockpile STMI Construction :	Stockpile - To	5 6 7 8	May 16, 2022 May 16, 2022 Jun 1, 2022 Jun 16, 2022 Jun 16, 2022 Jun 16, 2022 Jul 11, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$863.61) (\$863.61) \$863.61 \$863.61 \$863.61 \$256,650.00 (\$256,650.00) \$256,650.00 (\$256,650.00) \$256,650.00 (\$256,650.00)	Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user vohsr1 overridding Payment Estimate Item Adjustment (0044) due to user vohsr1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1470	MECHANICALLY	Material	Туре	10	Aug 2,	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment
		STABILIZED EARTH WALL SYS				2022			Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$256,650.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1470 -	Total						\$0.00	
J4P3009 - 1	Total							\$86,284.16	
J4P3009B	1540	MISC.	Material		4	May 2, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$2,688.00)	
					5	May 16, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$2,688.00)	
					6	Jun 1, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$2,688.00)	
					7	Jun 16, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$2,688.00)	
					8	Jul 1, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$2,688.00)	
					9	Jul 18, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$2,688.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1540 -	Total						\$0.00	
	1660	CURB AND GUTTER TYPE B	Material		9	Jul 18, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$19,733.15)	
					10	Aug 2, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$19,733.15)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1660 -	Total						\$0.00	
	1880	TEMPORARY NON-REMOVABLE TAPE LT/RT	Material		4	May 2, 2022	SYSTEM	\$920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
		ARROW			4	May 2, 2022	SYSTEM	(\$920.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1880 -	Total						\$0.00	
	2200	CABLE, 8 AWG 1 CONDUCTOR	Material		6	Jun 1, 2022	SYSTEM	\$1,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment

Aug 4, 2022



Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009B	2200	CABLE, 8 AWG 1	Material						Estimate Exception 39 on the current Payment Estimate.
		CONDUCTOR			6	Jun 1, 2022	SYSTEM	(\$1,140.00)	
				- Total				\$0.00	
			Material - Tota	d				\$0.00	
	2200 -	Total						\$0.00	
J4P3009B	- Total						\$0.00		
Overall - T	Overall - Total								