

Pay Estimate Created Date: October 17, 2022

Progress Estimate Number 15	 211015-C03 Pyramid Contractors, Inc.	October 15, 2022	Original Contract Amount Net Change Order Amount Current Contract Amount	t \$32,918.11
Approval Data				Dy Hoor

Approval Date		By User
October 17, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	raybol1
October 18, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	penner1
October 18, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
February 18, 2023	February 18, 2023		93.08%

Contract Informational Dates Milestones

Date Description	Original Completion Date	Current Completion Date
Acceptance Date		
Awarded Date	November 3, 2021	November 3, 2021
Letting Date	October 15, 2021	October 15, 2021
Notice to Proceed Date	January 3, 2022	January 3, 2022
Open to Traffic Date		
Work Began Date	March 28, 2022	March 28, 2022

		0.01100		
Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days
Milestone - Calendar Time - Day Count	January 20, 2023	January 20, 2023	94	
Milestone - Calendar Time - Phase 2	September 14, 2022	September 14, 2022	Milestone Complete	
Milestone - Completion Date - Phase 2 Incentive	October 15, 2022	October 15, 2022	Milestone Complete	

Contract Total Pay For Estimate No. 15			
	This Estimate	Previous	To Date
211015-C03			
Total Posted Items Pay	\$12,274.40	\$5,474,406.18	\$5,486,680.58
Gross Item Adjustments	\$25,542.85	\$65,622.76	\$91,165.61
Incentive	\$0.00	\$294,000.00	\$294,000.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damage	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
		\$5,834,028.94	\$5,871,846.19
Contract Total Payable This Estimate:	\$37,817.25		

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J4P3009	0330	6161033	DIRECTIONAL INDICATOR BARRICADE	EA	\$135.000	-23	(\$3,105.00)
	0570	7261030	30 IN. PIPE GROUP A	LF	\$160.000	9	\$1,440.00
Project J4P3009	- Total						(\$1,665.00)
J4P3009B	1480	2022010	REMOVAL OF IMPROVEMENTS	LS	\$85,000.000	0.05	\$4,250.00
	1510	2063000	CLASS 3 EXCAVATION	CUYD	\$20.000	10	\$200.00
	1620	6081012	TRUNCATED DOMES	SQFT	\$17.650	396	\$6,989.40
	1760	6161040	FLASHING ARROW PANEL	EA	\$2,500.000	1	\$2,500.00
Project J4P3009	B - Total						\$13,939.40
Overall - Total							\$12,274.40

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item A	<u>djustm</u>	ents This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009	0330	DIRECTIONAL INDICATOR BARRICADE			A line adjustment was made on Estimate 0014 to deduct for accidental pay of 23 DIBS @ \$135/EA. This is to zero out this adjustment.			\$3,105.00

Revision 4/1/2020 Page 1 of 47



Pay Estimate Created Date: October 17, 2022

Progress Estimate Number 15

Contract ID211015-C03Pay Period Start Pay Period EndOctober 1, 2022 October 15, 2023Original Contract Amount Net Change Order Amount Current Contract Amount\$5,861,477.94Pay Period EndOctober 15, 2022 October 15, 2023Net Change Order Amount Current Contract Amount\$32,918.11

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
I4P3009					The actual line item quantity was corrected on this estimate.			
	0760	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material			-1	\$1,762.00	(\$1,762.00
	0760	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	1	\$1,762.00	\$1,762.00
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	Material			-1	\$8,500.00	(\$8,500.00
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	1	\$8,500.00	\$8,500.00
	0860	CABLE, 6 AWG, 1 CONDUCTOR, POWER	Material			-3,390	\$2.50	(\$8,475.00
	0860	CABLE, 6 AWG, 1 CONDUCTOR, POWER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 20 on the current Payment Estimate.	3,390	\$2.50	\$8,475.00
	0870	FIBER OPTIC CABLE, 12- STRAND, SINGLE MODE	Material			-1,130	\$2.50	(\$2,825.00
	0870	FIBER OPTIC CABLE, 12- STRAND, SINGLE MODE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate.	1,130	\$2.50	\$2,825.00
	0910	MISC.	Material			-3	\$3,500.00	(\$10,500.00
	0910	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate.	3	\$3,500.00	\$10,500.00
	5005	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Material			-6	\$65.63	(\$393.78
	5005	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	6	\$65.63	\$393.78
	5006	2.5 IN. PSST POST - 12 GA.	Material			-92	\$33.60	(\$3,091.20
	5006	2.5 IN. PSST POST - 12 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	92	\$33.60	\$3,091.20
	5007	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material			-24	\$78.49	(\$1,883.76
	5007	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	24	\$78.49	\$1,883.76
	5008	BREAKAWAY ASSEMBLY	Material			-8	\$540.75	(\$4,326.00

Page 2 of 47 Revision 4/1/2020



Pay Estimate Created Date: October 17, 2022

Progress Estimate Number 15

Contract ID211015-C03Pay Period Start Pay Period EndOctober 1, 2022 October 15, 2023Original Contract Amount Net Change Order Amount Current Contract Amount\$5,861,477.94Pay Period EndOctober 15, 2022 October 15, 2023Net Change Order Amount Current Contract Amount\$32,918.11

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009		(PERFORATED SQUARE STEEL TUBE)						
	5008	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	8	\$540.75	\$4,326.00
4P3009B	1500	COMPACTING EMBANKMENT	Material			-260	\$18.00	(\$4,680.00
	1500	COMPACTING EMBANKMENT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	260	\$18.00	\$4,680.00
	1550	MISC.	Material			-388	\$110.00	(\$42,680.00
	1550	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	388	\$110.00	\$42,680.00
	1560	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	AC Price Adjustment for Line 1560 for September 2022.			\$14,291.60
	1560	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Other Item Adjustment	Asphalt Cement Price Adjustment	AC Price Adjustment for Line 1560 for September 2022.			\$8,146.25
	1620	TRUNCATED DOMES	Material			-396	\$17.65	(\$6,989.40
	1620	TRUNCATED DOMES	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	396	\$17.65	\$6,989.40
	1710	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	Material			-1	\$1,050.00	(\$1,050.00)
	1710	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	1	\$1,050.00	\$1,050.00
	1720	MANHOLE FRAME AND COVER, TYPE 4	Material			-1	\$750.00	(\$750.00)
	1720	MANHOLE FRAME AND COVER, TYPE 4	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1	\$750.00	\$750.00
	1990	PRECAST CONCRETE MANHOLE - 48 IN.	Material			-7	\$625.00	(\$4,375.00)
	1990	PRECAST CONCRETE MANHOLE - 48 IN.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	7	\$625.00	\$4,375.00
	2000	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material			-6	\$775.00	(\$4,650.00)
	2000	PRECAST CONCRETE	Material		This adjustment offsets the original system-	6	\$775.00	\$4,650.00

Page 3 of 47 Revision 4/1/2020



Pay Estimate Created Date: October 17, 2022

Progress Estimate Number
15

Contract ID 211015-C03 Pay Period Start October 1, 2022 Original Contract Amount \$5,861,477.94 Prime Contractors, Inc. Pay Period End October 15, 2022 Original Contract Amount \$32,918.11 \$32,918.11 \$5,894,396.05

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4P3009B		DROP INLET 2 FT X 2 FT			generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
	2020	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material			-1	\$2,500.00	(\$2,500.00)
	2020	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	1	\$2,500.00	\$2,500.00
	2250	MISC.	Material			-4	\$1,200.00	(\$4,800.00)
	2250	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	4	\$1,200.00	\$4,800.00
	2320	SH-FLAT SHEET - SIGNAL SIGN	Material			-42	\$80.00	(\$3,360.00)
	2320	SH-FLAT SHEET - SIGNAL SIGN	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	42	\$80.00	\$3,360.00
	2360	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material			-1	\$15,000.00	(\$15,000.00)
	2360	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate.	1	\$15,000.00	\$15,000.00
	5015	MISC.	Material			-2	\$2,079.00	(\$4,158.00)
	5015	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	2	\$2,079.00	\$4,158.00
Total								\$25,542.85

Revision 4/1/2020 Page 4 of 47



					(Contract Project Information				
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work					
J4P3009	FAF 50-1(54)	Bridge replacement	50	JACKSON	over Chipman Road nea	ar Lee's Summit				
J4P3009B	FAF 50-1(55)	Grading and paving	50	JACKSON	from w/o Murray Road to	o w/ Blue Parkway				
Totals by Jo	ob Number	s								
J4P3009	Posted Item Pay Gross Item Adjustments Gross Item Pay			Item Pay	This Estimate (\$1,665.00) \$3,105.00 \$1,440.00	Previous \$4,479,757.69 \$57,297.31 \$4,537,055.00	To Date \$4,478,092.69 \$60,402.31 \$4,538,495.00			
	Incentive Disincentive Liquidated Damages Other Contract Adjustments				\$0.00 \$0.00 \$0.00 \$0.00	\$228,732.00 \$0.00 \$0.00 \$0.00	\$228,732.00 \$0.00 \$0.00 \$0.00			
J4P3009B		Posted Item Pay Gross Item Adjustments Gross Item Pay		This Estimate \$13,939.40 \$22,437.85 \$36,377.25	Previous \$994,648.49 \$8,325.45 \$1,002,973.94	To Date \$1,008,587.89 \$30,763.30 \$1,039,351.19				
					\$0.00 \$0.00 \$0.00 \$0.00	\$65,268.00 \$0.00 \$0.00 \$0.00	\$65,268.00 \$0.00 \$0.00 \$0.00			

Revision 4/1/2020 Page 5 of 47



Exceptions (Discrepancies) This Estimate Period

Esteroide Disciption Types Handford Materials Proport Jampsoffice, Horn 200000, Proved then University of Control of State of	Exceptions (Discrepancies) This Estimate Period			
Number 1900. Material Sez 2018/000000, Raterial 2018/0000, Serial 2018/00000, Serial 2018/0000, Serial 2018/0000, Serial 2018/0000, Serial	Exceptions / Discrepencies	Explanation		Status
Number 1500, Material Sex 6/1995056, Material Schrift CPACCA-Concrete, Pervient contractor rans or COLA, Acceptance Action Genetic Strict CPACCA is Institutional Contractor Transport of Extended Contractor Transport (Contractor) and Contractor Transport (Contractor) and Contractor Transport (Contractor) and Contractor Transport (Contractor) and Contractor) and Contractor Transport (Contractor) and Contractor Transport (Contractor) and Contractor) and Contractor Transport (Contractor) and Contractor (Contractor) and Contractor Transport (Contractor) and Contractor (Contractor) and Contractor) and Contractor (Contractor) and Contractor (Contractor) and Contractor (Contractor) and Contractor (Contractor) and Contractor) and Contractor (Contractor) and Contractor) and C	Number 1500, Material Set 203600096, Material 0200XXCS - Compacted Soil for Subgrade	Need to enter in soil compaction results for both QC and QA.	raybol1	Overridden
Number 1620, Material 15et 68801736, in Material 1097TRO - Truncated Droves for ADA, Acceptance Action Genetic 1007TRO is insufficient. Action Genetic 1007TRO is insufficient. Project JAPP2008, lare 814122. Project filem Line Action Genetic 1007TRO is insufficient. See 1411220. Material 15et 120710. Action Genetic 1007TRO is insufficient. Action Genetic 1007TRO is insufficient. See 1411220. Action Genetic 1007TRO is insufficient. Acceptance Action Genetic 1007TRO is	Number 1550, Material Set 401990596, Material 0501CCPAQCQA - Concrete, Payment contractor mix or		raybol1	Overridden
Number 1700, Material Set 61st 1130000, Material Schopfort VY- Curved Varie Grate and Frame, Estimate Exception Type: Insufficient Materials Project JAPS00008, Item 0143014, Project Item Line Number 2000, Materials and 154301148, Project JAPS00008, Item 1140014, Project Item Line Number 2000, Material Schopfort Materials Project JAPS00008, Item 1140004, Project Item Line Number 2000, Material Schopfort Materials Project JAPS00008, Item 1140004, Project Item Line Number 2000, Material Schopfort Materials Project JAPS00008, Item 1140004, Project Item Line Number 2000, Material Schopfort Materials Project JAPS00008, Item 1140004, Project Item Line Number 2000, Material Schopfort Materials Project JAPS00008, Item 1140004, Item 201004, Project Item Line Number 2000, Material Schopfort Materials Project JAPS00008, Item 1140004, Item 201004, It	Number 1620, Material Set 608101296, Material 1067TRDO - Truncated Domes for ADA, Acceptance	Need to enter in materials report for the Truncated Domes.	raybol1	Overridden
Number 1720, Material Set of 1490-1496, Material Set of 1490-1490-1490-1490-1490-1490-1490-1490-	Number 1710, Material Set 614112096, Material 0614DFGTCV - Curved Vane Grate and Frame,		raybol1	Overridden
0750, Material Set 71/002006, Material 1059/PDCEDBP - Institutioners. Eliminate Exception Type: Institutioners Materials: Project JAP30068, Item 7310048, Project Item Line Number 1990, Materials Set 73100488 (Material Set 73100488) (Material Set 73100488) (Material Set 73100488) (Material Set 73100488) (Material Set 73100290, Material Set 73100290) (Material Set	Number 1720, Material Set 614301496, Material 0614DFMNFC - Manhole Frame and Cover, Acceptance		raybol1	Overridden
Number 1990, Material Set 731004586, Material 1033MHCPK - Precast Conc Manhole, Acceptance Action Genetic 1033MHCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 731032, Project Item Line Number 2000, Material 32031MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 7320830A, Project Item Line Number 2003, Material 32031MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 9019002, Project Item Line Number 2003, Material 32031MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 9019002, Project Item Line Number 2003, Material 32031MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 9019002, Project Item Line Number 2003, Material 32031MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 9019002, Project Item Line Number 2003, Material 32031MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 9019002, Project Item Line Number 3015, Material Set 9019003, Material 40021MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 9002303, Project Item Line Number 2003, Material 32031MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 9002305, Project Item Line Number 2004, Material Set 900330330, Material 32031MCPK is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P30098, ltem 9003235, Project Item Line Number 2004, Material Set 90032309, Material 900371879. Traffic Signals Acceptance Action Genetic 000371879. Material Set 90032309, Material 900371879. Traffic Signals Material Set 90032309, Material 900371879. Traffic Signals Material Set 90037180, Material Set 90037180, Material 900371879. Traffic Signals Material Set 90037180, Material Set 90037180, Material 900371879. Traffic Signals Material Set 90037180, Material 900	0760, Material Set 711020096, Material 1059PCECBP - Protective Coat Bents and Piers - Epoxy,		raybol1	Overridden
Number 2000, Material Set 731102298, Material 1033DIRCPK is instifficient. Estimate Exception Type: Insufficient Materials: Project JAP20098, Item 7320830A, Project Item Line Number 2020, Material 1032ESRCP is insufficient. Estimate Exception Type Insufficient Materials: Project JAP20098, Item 8019092, Project Item Line Number 2020, Material Set 9019902, Material 1030ESRCP is insufficient. Estimate Exception Type Insufficient Materials: Project JAP20098, Item 8019902, Project Item Line Number 2020, Material Set 9019902, Material 1030ESRCP is insufficient. Estimate Exception Type Insufficient Materials: Project JAP20098, Item 9019902, Project Item Line Number 2015, Material Set 9019902, Material 901EASR JAP20098, Item 9019902, Project Item Line Number 2015, Material Set 9019902, Material 901EASR JAP20098, Item 9019902, Project Item Line Number 2015, Material Set 9019902, Material 901EASR JAP20098, Item 9020833, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9020833, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9023200, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9031221, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9031221, Project Item Line Number 2015, Material 901EASR JAP20098, Item 9031221, Project Item Line Number 2015, Material 901EASR JAP20098, Material 901EASR JAP20098, Item 9031220, Project Item Line Number 2015, Material 901EASR JAP20098, Material 901EASR JAP20098	Number 1990, Material Set 731004896, Material 1033MHRCPK - Precast Conc Manhole, Acceptance		raybol1	Overridden
Number 2200, Material Set 7320630A96, Material 1032ESRCP - Conc End Section for Round Pipe. Estimate Exception Type: Insufficient Materials: Project JAP30098, Item 9019002, Project Item Line Number 2506, Material Set 9019002, Material 9001LHXX - Highway Lighting Material, Acceptance Action Genetic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project JAP30098, Item 9019002, Project Item Line Number 25016, Material Set 9019092, Material 9001LHXX - Highway Lighting Material, Acceptance Action Genetic 0901LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project JAP30098, Item 901902, Project Item Line Number 25016, Material Set 90208396, Material 10901LHXX - Highway Lighting Material, Acceptance Action Genetic 001LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project JAP30098, Item 9020332, Project Item Line Number 2500, Material Set 90208396, Material 10426M - Significant Materials: Project JAP30098, Item 9023250, Project Item Line Number 2500, Material Set 90208396, Material 10426M - Significant Materials: Project JAP30098, Item 9023250, Project Item Line Number 2500, Material Set 90232506, Material 10427M - Significant Materials: Project JAP30098, Item 9023250, Project Item Line Number 2500, Material Set 90232506, Material 10427M - Significant Materials: Project JAP30098, Item 9033250, Project Item Line Number 2500, Material Set 90232508, Material 10427M - Significant Materials: Project JAP30098, Item 9031241, Project Item Line Number 2500, Material Set 902325086, Material 10427M - Significant Materials: Project JAP30098, Item 9031241, Project Item Line Number 2500, Material Set 903124168, Material 9003HSB - Traffic Signal Postificant Materials: Project JAP3009, Item 9031241, Project Item Line Number 5005, Material Set 90312416, Material 9003HSB - Tubular Steel Sign Support, Acceptance Action Genetic 0003HSB is insufficient. Estimate Exception Type: Insufficient Materials: Project JAP3009, Item 9031281, Project Item Line Number 5005	Number 2000, Material Set 731102296, Material 1033DIRCPK - Precast Conc Drop Inlet, Acceptance		raybol1	Overridden
Number 225G, Material Set 9019902, Material (901 LHXX - Highway Lighting Material, Acceptance Action Ceneric Committee (11 Materials Set 9019902, Material Set 901902, Project Item Line Number 5015, Material Set 901902, Material Genetic O901 LHXX - Highway Lighting Material, Acceptance Action Replacements. Need to enter a materials report for the Pull Box Replacements. Need to enter a materials report for the Signal Sign SH-Flat Taylord (14 Materials Set 902035396, Material 10425M-Sign Material, Acceptance Action Genetic O901 LHXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9023250, Project Item Line Number 230G, Material Set 902325050, Material Set 902325050, Project J4P3009B, Item 9023250, Project Item Line Number 230G, Material Set 902325050, Project J4P3009B, Item 9023250, Project Item Line Number 230G, Material Set 902325050, Project J4P3009B, Item 9023250, Project Item Line Number 230G, Material Set 902325050, Project J4P3009B, Item 9023250, Project Item Line Number 10 Materials Project J4P3009B, Item 903250, Project Item Line Number 10 Materials Project J4P3009B, Item 9031250, Project Item Line Number 10 Materials Project J4P3009B, Item 9031273, Project Item Line Number 10 Materials Project J4P3009B, Item 9031273, Project Item Line Number 10 Materials Project J4P3009B, Item 9031273, Project Item Line Number 10 Materials Project J4P3009B, Item 9031273, Project Item Line Number 10 Materials Project J4P3009B, Item 9031273, Project Item Line Number 10 Materials Project J4P3009B, Item 9031273, Project Item Line Number 10 Materials Project J4P3009B, Item 9031281, Project Item Line Number 10 Materials Project J4P3009B, Item 9031281, Project Item Line Number 10 Materials Project J4P3009B, Item 9031281, Project Item Line Number 10 Materials Project J4P3009B, Item 9031281, Project Item Line Number 10 Materials Project J4P3009B, Item 9031281, Project Item Line Number 10 Materials Project J4P3009B, Item 9031281, Project Item Line Number 10 Materials Project J4P3009B, It	Number 2020, Material Set 7320630A96, Material 1032ESRCF - Conc End Section for Round Pipe,		raybol1	Overridden
Number 5015, Material Set 9019902, Material Set 9019902, Material Set 9019902, Material Set 9019902, Material Set 9019802, Material Set 9019803, Project Item Line Number 2300, Material Set 9019802, Material Set 901980, Material Set 9019802, Material Set 901980, Mater	Number 2250, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action		raybol1	Overridden
Number 2320, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 0402SM is mustificient. Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 903250, Project Item Line Number 2360, Material Set 902325066, Material 0902TSPT/CAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSPT/CAB is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 9023250, Project Item Line Number 2360, Material Set 902325096, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 0902TSPS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031241, Project Item Line Number 2003, Material 954093124196, Mat	Number 5015, Material Set 9019902, Material 0901LHXX - Highway Lighting Material, Acceptance Action		raybol1	Overridden
Number 2360, Material Set 902325096, Material 9092TSBTZCAB - Bolts Galv Anchor for Traffic Signals, Acceptance Action Generic 0902TSBTZCAB is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009B, Item 903250, Project Item Line Number 2360, Material Set 902325096, Material 1092TSPS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031241, Project Item Line Number 5008, Material Set 903124196, Material 90315BA is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031273, Project Item Line Number 5008, Material Set 903127396, Material 90315BA is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031273, Project Item Line Number 5005, Material Set 903127396, Material Set 903127397 (Project Item Line Number 5006, Material Set 903128096, Material 9033HSTS - Tubular Steel Sign Support, Acceptance Action Generic 903014STS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 5007, Material Set 903128096, Material 9033HSTS - Tubular Steel Sign Support, Acceptance Action Generic 9030HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 903744, Project Item Line Number 60074, Material Set 90312864, Material 30838SDFP142M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @. Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 60902TSXX is insufficient. Estimate Exception Type:	Number 2320, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic		raybol1	Overridden
Number 2360, Material Set 902325096, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031241, Project Item Line Number 5008, Material Set 903124196, Material 903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031273, Project Item Line Number 5005, Material Set 903127396, Material 903HSBA - Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031273, Project Item Line Number 5005, Material Set 903127396, Material 903HSTS - Tubular Steel Sign Support, Acceptance Action 6eneric 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031280, Project Item Line Number 5006, Material Set 903128096, Material 9093HSTS - Tubular Steel Sign Support, Acceptance Action 6eneric 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 5007, Material Set 903128196, Material 903HSTS - Tubular Steel Sign Support, Acceptance Action 6eneric 903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9103714, Project Item Line Number 6040, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 69, Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108206, Project Item Line Number 6080, Material Set 910820696, Material 9092TSXX - Traffic Signals Material, Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 6080, Material Set 91083096, Material 9092TSXX - Traffic Signals Material, Acceptance Action Gene	Number 2360, Material Set 902325096, Material 0902TSBTZCAB - Bolts Galv Anchor for Traffic Signals,	Working with Materials to resolve exception.	raybol1	Overridden
South Material Set 903124196, Material 9903HSBA'- Breakaway Assembly for Highway Signing, Acceptance Action Generic 0903HSBA is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031273, Project Item Line Number 5005, Material Set 903127396, Material 9903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTs is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 5006, Material Set 903128096, Material 903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 5007, Material Set 903128196, Material 9003HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 6007, Material Set 903128196, Material 9003HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9103714, Project Item Line Number 0840, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 60, Acceptance Action Generic ReSteelBasr is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108206, Project Item Line Number 0860, Material Set 910820596, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic Restricted Basr is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic Pater a materials report for the Traffic Signals Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic Pater a materials report for the Scout Fiber Pull Boxes. Project J4P3009, Item 9109902, Project Item Line	Number 2360, Material Set 902325096, Material 1092TSPS - Traffic Signal Post(s) - All Types,	Working with Materials to resolve exception.	raybol1	Overridden
Sotiant Exception Type: Insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 5007, Material Set 903128198, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 5007, Material Set 903128198, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 5007, Material Set 903128198, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9103714, Project Item Line Number 0840, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 (@). Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108206, Project Item Line Number 0860, Material Set 910820696, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9109902, Project Item Line Number 0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9109902, Project Item Line Number 0910, Material Set 9108092, Material 0910TXX - Misc Intelligent Traffic Sys Components, Acceptance	5008, Material Set 903124196, Material 0903HSBA - Breakaway Assembly for Highway Signing,	Need to enter materials report for the Breakaway Assemblies.	raybol1	Overridden
Solon, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient Materials: Project J4P3009, Item 9031281, Project Item Line Number 5007, Material Set 903128196, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action 6003HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9103714, Project Item Line Number 0840, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108206, Project Item Line Number 0860, Material Set 910820696, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9109902, Project Item Line Number 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9109902, Project Item Line Number 0910, Material Set 9109092, Material 0910TXX - Misc Intelligent Traffic Sys Components, Acceptance	5005, Material Set 903127396, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action		raybol1	Overridden
S007, Material Set 903128196, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9103714, Project Item Line Number 0840, Material 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @. Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108206, Project Item Line Number 0860, Material Set 910820696, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 0870, Material Set 9108035396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9109902, Project Item Line Number 0910, Material Set 9109902, Material 0910TXX - Misc Intelligent Traffic Sys Components, Acceptance Need to enter a materials report for the Scout Fiber Pull Boxes. raybol1 Overridden	5006, Material Set 903128096, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action	Need to enter a materials report for the 2.5 IN. PSST Posts.	raybol1	Overridden
0840, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420 @, Acceptance Action Generic ReSteelBars is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108206, Project Item Line Number 0800, Material Set 910820696, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number Material. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number Material. Need to enter a materials report for the Traffic Signals Material 0902TSXX is insufficient. Poetro of the Traffic Signals Material O902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9109902, Project Item Line Number 0910, Material Set 9109902, Material 0910TXX - Misc Intelligent Traffic Sys Components, Acceptance	5007, Material Set 903128196, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action		raybol1	Overridden
0860, Material Set 910820696, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9108353, Project Item Line Number 0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9109902, Project Item Line Number 0910, Material Set 9109092, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Need to enter a materials report for the Scout Fiber Pull Boxes. raybol1 Overridden	0840, Material Set 910371496, Material 1036RSDFPL42M25 - Reinforcing Steel No. 8/M25 Gr 60/M420	Working with Materials to resolve exception.	raybol1	Overridden
0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient. Estimate Exception Type: Insufficient Materials: Project J4P3009, Item 9109902, Project Item Line Number 0910, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance Material. Need to enter a materials report for the Scout Fiber Pull Boxes. raybol1 Overridden	0860, Material Set 910820696, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic		raybol1	Overridden
0910, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance	0870, Material Set 910835396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic		raybol1	Overridden
	0910, Material Set 9109902, Material 0910ITXX - Misc Intelligent Traffic Sys Components, Acceptance	Need to enter a materials report for the Scout Fiber Pull Boxes.	raybol1	Overridden

Revision 4/1/2020 Page 6 of 47



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	port Generated date and can differ from the posted amo Description	Bid Quantity	Net Change	Total Current	Unit	Total Posted	Unit Price	Total Value POSTED To Date (See report
							Order	Quantity		Approved Qty		generated date)
211015-C03	J4P3009	0001	0010	2013000	CLEARING AND GRUBBING	5.00	0.00	5.00	ACRE	2.50	\$5,500.00	\$13,750.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$250,000.00	\$250,000.0
		0001	0030	2031000	CLASS A EXCAVATION	6,088.00	0.00	6,088.00	CUYD	6,088.00	\$17.00	\$103,496.0
		0001	0040	2035500	EMBANKMENT IN PLACE	3,626.00	0.00	3,626.00	CUYD	3,626.00	\$20.00	\$72,520.0
		0001	0050	2036000	COMPACTING EMBANKMENT	5,294.00	0.00	5,294.00	CUYD	5,294.00	\$2.50	\$13,235.0
		0001	0060	2037075	COMPACTING IN CUT	32.00	0.00	32.00	STA	32.00	\$350.00	\$11,200.0
		0001	0070	2063000	CLASS 3 EXCAVATION	117.00	0.00	117.00	CUYD	117.00	\$12.00	\$1,404.0
		0001	0080	2063500	CULVERT CLEANOUT	3.00	0.00	3.00	EA	3.00	\$2,000.00	\$6,000.0
		0001	0090	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,718.00	38.00	1,756.00	SQYD	1,756.00	\$16.50	\$28,974.0
		0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	466.00	0.00	466.00	SQYD	466.00	\$15.00	\$6,990.0
		0001	0110	3049905	MISC.OPTIONAL BASE	11,716.00	0.00	11,716.00	SQYD	11,716.00	\$11.00	\$128,876.0
		0001	0120	4010150	TYPE A2 SHOULDER	2,721.10	0.00	2,721.10	SQYD	2,721.10	\$27.00	\$73,469.7
		0001	0130	4019905	MISC.CHIPMAN ROAD OPTIONAL PAVEMENT	466.00	0.00	466.00	SQYD	466.00	\$100.00	\$46,600.0
		0001	0140	4019905	MISC.RAMP OPTIONAL PAVEMENT	1,718.00	38.00	1,756.00	SQYD	1,756.00	\$60.00	\$105,360.0
		0001	0150	4019905	MISC.US-50 OPTIONAL PAVEMENT	8,995.00	0.00	8,995.00	SQYD	8,995.00	\$52.00	\$467,740.0
		0001	0160	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	421.70	0.00	421.70	TONS	421.70	\$115.00	\$48,495.5
		0001	0170	4071005	TACK COAT	213.00	0.00	213.00	GAL	213.00	\$2.50	\$532.5
		0001	0180	5041000	CONCRETE APPROACH PAVEMENT	379.80	0.00	379.80	SQYD	379.80	\$108.60	\$41,246.2
		0001	0190	6044011	PIPE COLLAR, TYPE A	3.00	0.00	3.00	EA	3.00	\$1,100.00	\$3,300.0
		0001	0200	6064500	AGGREGATE BEDDING FOR 3 - STRAND GUARD CABLE	93.00	0.00	93.00	CUYD	93.00	\$40.00	\$3,720.0
		0001	0210	6071102	MODIFIED CONCRETE GUTTER TYPE B	490.00	0.00	490.00	LF	490.00	\$48.00	\$23,520.0
		0001	0220	6079903	MISC.ORNAMENTAL PEDESTRIAN FENCE (48") (RETAINING	331.00	0.00	331.00	LF	331.00	\$135.00	\$44,685.0
		0001	0230	6081000	WALLS) CONCRETE MEDIAN	2.80	0.00	2.80	SQYD	2.80	\$399.25	\$1,117.9
		0001	0240	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$65.00	\$0.0
		0001	0250	6096041	PLACING TYPE 1 ROCK DITCH LINER	34.00	0.00	34.00	CUYD	0.00	\$60.00	\$0.0
			0260	6097000	ROCK LINING	15.00	0.00	15.00	CUYD	15.00	\$85.00	\$1,275.0
		0001	0270	6113010			0.00		CUYD			
		0001	0270	6113030	FURNISHING TYPE 1 ROCK BLANKET PLACING TYPE 1 ROCK BLANKET	143.00	0.00	143.00	CUYD	143.00	\$65.00 \$20.00	\$9,295.0 \$2,860.0
		0001	0290	6161005	CONSTRUCTION SIGNS	1,610.00	0.00	1,610.00	SQFT	1,610.00	\$6.50	\$10,465.0
		0001	0300	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	8.00	\$100.00	\$800.0
		0001	0300		CHANNELIZER (TRIM LINE)			222.00				
		0001		6161025	TYPE III MOVEABLE BARRICADE	222.00	0.00		EA	222.00	\$31.00	\$6,882.0
		0001	0320	6161030		50.00	0.00	50.00	EA	50.00	\$185.00	\$9,250.0
		0001	0330	6161033	DIRECTIONAL INDICATOR BARRICADE	37.00	0.00	37.00	EA	14.00	\$135.00	\$1,890.0
		0001	0340	6161040	FLASHING ARROW PANEL CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.0
		0001	0350	6161098A	INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$9,500.00	\$19,000.0
		0001	0360	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,000.00	\$0.0
		0001	0370	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	177.00	0.00	177.00	LF	177.00	\$200.00	\$35,400.0
		0001	0380	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$195,000.00	\$0.0
		0001	0381	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$141,674.00	\$141,674.0
		0001	0390	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.0
		0001	0400	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	168.00	0.00	168.00	LF	0.00	\$20.00	\$0.0
		0001	0410	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	16.00	0.00	16.00	EA	0.00	\$250.00	\$0.0
		0001	0420	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	13,609.00	-13,609.00	0.00	LF	0.00	\$1.55	\$0.0
		0001	0430	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	13,273.00	-13,273.00	0.00	LF	0.00	\$1.55	\$0.0
		0001	0440	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	8.00	0.00	8.00	EA	0.00	\$115.00	\$0.0

Revision 4/1/2020 Page 7 of 47



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11015-C03	J4P3009	0001	0450	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	15,875.00	0.00	15,875.00	LF	0.00	\$0.55	\$0.0
		0001	0460	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	11,706.00	0.00	11,706.00	LF	0.00	\$0.55	\$0.0
		0001	0470	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	1,840.00	0.00	1,840.00	LF	0.00	\$0.90	\$0.0
		0001	0480	6207001	PAVEMENT MARKING REMOVAL	2,376.00	0.00	2,376.00	LF	2,376.00	\$0.55	\$1,306.8
		0001	0490	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	16.00	0.00	16.00	EA	16.00	\$55.00	\$880.0
		0001	0500	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,646.00	0.00	2,646.00	SQYD	2,646.00	\$6.25	\$16,537.5
		0001	0510	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	319.00	0.00	319.00	SQYD	319.00	\$5.00	\$1,595.0
		0001	0520	6240104A	SEPARATION GEOTEXTILE	838.00	0.00	838.00	SQYD	838.00	\$4.50	\$3,771.0
		0001	0530	6269909	MISC.OPTIONAL PAVEMENT RUMBLE STRIP	56.60	0.00	56.60	STA	56.60	\$158.85	\$8,990.
		0001	0540	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$5,000.00	\$5,000.
		0001	0550 0560	7261018 7261024	18 IN. PIPE GROUP A 24 IN. PIPE GROUP A	18.00	0.00	18.00 73.00	LF	73.00	\$110.00 \$105.00	\$1,980.
		0001	0570	7261024	30 IN. PIPE GROUP A	73.00	0.00	28.00	LF	28.00	\$160.00	\$7,665. \$4,480.
		0001	0580	7320618A	18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END	1.00	0.00	1.00	EA	1.00	\$1,500.00	\$1,500.0
					SECTION							
		0001	0590	7320624A	24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,700.00	\$3,400.0
		0001	0600	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	2.00	0.00	2.00	EA	2.00	\$1,850.00	\$3,700.
		0001	0610	8051000A	SEEDING - COOL SEASON GRASSES	5.30	0.00	5.30	ACRE	0.90	\$1,600.00	\$1,440.
		0001	0620	8061004	SEDIMENT TRAP ROCK	29.80	0.00	29.80	CUYD	0.00	\$100.00	\$0.
		0001	0630	8061005	ROCK DITCH CHECK	140.00	0.00	140.00	LF	89.00	\$45.00	\$4,005
		0001	0640	8061006	ALTERNATE DITCH CHECK	976.00	0.00	976.00	LF	0.00	\$4.35	\$0
		0001	0650	8061016	SEDIMENT REMOVAL	189.00	0.00	189.00	CUYD	10.00	\$20.00	\$200.
		0001	0660	8061019	SILT FENCE	3,187.00	0.00	3,187.00	LF	1,475.00	\$1.35	\$1,991.
		0001	0670	8064128	TYPE 1 TURF REINFORCEMENT MAT	729.00	0.00	729.00	SQYD	0.00	\$1.95	\$0.
		0001	0680	8064138	TYPE 2D EROSION CONTROL BLANKET	3,973.00	0.00	3,973.00	SQYD	3,973.00	\$4.25	\$16,885
		0010	0690	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,463.00	0.00	1,463.00	LF	1,438.00	\$31.50	\$45,297
		0010	0700	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	5.00	0.00	5.00	EA	5.00	\$3,000.00	\$15,000
		0010	0710	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$950.00	\$950
		0010	0720	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	4.00	0.00	4.00	EA	4.00	\$2,700.00	\$10,800
		0010	0730	6069902	MISC.HTGC ANCHOR ASSEMBLY	2.00	2.00	4.00	EA	4.00	\$5,000.00	\$20,000
		0010	0740	6069903	MISC.HIGH TENSION GUARD CABLE	1,256.00	0.00	1,256.00	LF	1,256.00	\$24.00	\$30,144
		0040	0750	7040101	SUBSTRUCTURE REPAIR (FORMED)	150.00	0.00	150.00	SQFT	150.00	\$75.00	\$11,250
		0040	0760	7110200	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (EPOXY)	1.00	0.00	1.00	LS	1.00	\$1,762.00	\$1,762
		0040	0770	9031010	CONCRETE FOOTINGS, EMBEDDED	1.00	0.50	1.50	CUYD	1.00	\$1,300.00	\$1,300
		0040	0780	9031210	STRUCTURAL STEEL POSTS	650.00	-85.00	565.00	LB	565.00	\$4.25	\$2,401
		0040	0790	9031270A	2 IN. PSST POST - 12 GA.	75.00	-46.00	29.00	LF	0.00	\$20.50	\$0.
		0040	0800	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	18.00	-18.00	0.00	LF	0.00	\$40.00	\$0.
		0040	0810	9035004A	SH-FLAT SHEET	27.00	0.00	27.00	SQFT	0.00	\$23.50	\$0
		0040	0820		ST-STRUCTURAL	80.00	0.00	80.00	SQFT	0.00	\$21.50	\$0.
		0040	0830		SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$37.50	\$0.
		0050	0840	9103714	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOUNTING HEIGHT, INSTALLED	1.00	0.00	1.00	EA	1.00	\$8,500.00	\$8,500.
		0050	0850	9105200	CONDUIT, 2 IN., RIGID, IN TRENCH	227.00	0.00	227.00	LF	227.00	\$13.50	\$3,064
		0050	0860	9108206	CABLE, 6 AWG, 1 CONDUCTOR, POWER	3,390.00	0.00	3,390.00	LF	3,390.00	\$2.50	\$8,475
		0050	0870	9108353	FIBER OPTIC CABLE, 12-STRAND, SINGLE MODE	1,130.00	0.00	1,130.00	LF	1,130.00	\$2.50	\$2,825.
		0050	0880	9108811	PULL BOX, PREFORMED CLASS 2	3.00	0.00	3.00	EA	3.00	\$1,575.00	\$4,725.
		0050	0890	9109901	MISC.Fiber Optic Splicing, Testing, & Documentation	1.00	0.00	1.00	LS	1.00	\$5,500.00	\$5,500.0

Revision 4/1/2020 Page 8 of 47



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	Line	Item	port Generated date and can differ from the posted at Description	Bid	Net	Total	Jenerate Unit	Total	Unit Price	Total Value POSTE
lm.CONTRACT	No.		No.	Code		Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
1015-C03	J4P3009	0050	0900	9109902	MISC.CCTV Pole Relocation	1.00	0.00	1.00	EA	1.00	\$6,000.00	\$6,000.
		0050	0910	9109902	MISC.Scout Fiber Optic Pull Box	3.00	0.00	3.00	EA	3.00	\$3,500.00	\$10,500.
		0050	0920	9109903	MISC."CONDUIT, TWO 2 IN., PUSHED"	181.00	0.00	181.00	LF	181.00	\$30.00	\$5,430.
		0050	0930	9109903	MISC."CONDUIT, TWO 2 IN., RIGID, IN SAME TRENCH"	692.00	0.00	692.00	LF	692.00	\$20.00	\$13,840.
		0070	0940	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	17.00	0.00	17.00	SQFT	17.00	\$275.00	\$4,675.
		0070	0950	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$68,000.00	\$68,000
		0070	0960	5031010A	BRIDGE APPROACH SLAB (MAJOR)	182.00	0.00	182.00	SQYD	182.00	\$249.10	\$45,336
		0070	0970	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	52.00	0.00	52.00	LF	52.00	\$985.00	\$51,220
		0070	0980	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	32.00	0.00	32.00	LF	32.00	\$642.00	\$20,544
		0070	0990	7011300	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$200.00	\$800
		0070	1000	7011400	FOUNDATION INSPECTION HOLES	72.00	0.00	72.00	LF	72.00	\$105.00	\$7,560
		0070	1010	7011600	SONIC LOGGING TESTING	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800
		0070	1020	7021212	GALVANIZED STRUCTURAL STEEL PILES (12 IN)	525.00	0.00	525.00	LF	450.00	\$109.00	\$49,050
		0070	1030	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$125.00	\$1,750
		0070	1040	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	93.40	0.00	93.40	CUYD	93.40	\$860.00	\$80,324
		0070	1050	7034219A	TYPE D BARRIER	306.00	0.00	306.00	LF	306.00	\$170.00	\$52,020
		0070	1060	7034221	SLAB ON CONCRETE NU-GIRDER	604.00	0.00	604.00	SQYD	604.00	\$398.00	\$240,39
		0070	1070	7034620	FORM LINERS	197.00	0.00	197.00	SQYD	197.00	\$90.00	\$17,73
		0070	1080	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	491.00	0.00	491.00	LF	491.00	\$360.00	\$176,76
		0070	1090	7061060	REINFORCING STEEL (BRIDGES)	7,860.00	0.00	7,860.00	LB	7,860.00	\$1.70	\$13,36
		0070	1100	7101000	REINFORCING STEEL (EPOXY COATED)	11,140.00	0.00	11,140.00	LB	11,140.00	\$2.25	\$25,06
		0070	1110	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,860.00	\$1,86
		0070	1120	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$1,860.00	\$1,86
		0070	1130	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,00
		0070	1140	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,00
		0070	1150	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,60
		0070	1160	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$385.00	\$3,08
		0070	1170	7201300	PIPE PILE SPACERS	18.00	0.00	18.00	EA	18.00	\$1,525.00	\$27,45
		0071	1180	2024043	REMOVAL OF MISCELLANEOUS ACM (NON-FRIABLE)	17.00	0.00	17.00	SQFT	17.00	\$275.00	\$4,67
		0071	1190	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$68,000.00	\$68,00
		0071	1200		BRIDGE APPROACH SLAB (MAJOR)	182.00	0.00	182.00	SQYD	182.00	\$249.10	\$45,33
		0071	1210	7011106	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	44.00	0.00	44.00	LF	44.00	\$985.00	\$43,34
		0071	1220	7011205	ROCK SOCKETS (3 FT 6 IN. DIA.)	32.00	0.00	32.00	LF	32.00	\$642.00	\$20,54
			1230	7011203	VIDEO CAMERA INSPECTION	4.00	0.00	4.00	EA	4.00	\$200.00	\$80
		0071	1240	7011400	FOUNDATION INSPECTION HOLES	72.00	0.00	72.00	LF	72.00	\$105.00	\$7,56
		0071	1250	7011600	SONIC LOGGING TESTING	4.00	0.00		EA	4.00	\$1,200.00	\$4,80
		0071		7021212				4.00	LF			
		0071	1260		GALVANIZED STRUCTURAL STEEL PILES (12 IN)	497.00	0.00	497.00		412.00	\$109.00	\$44,90
		0071	1270	7027000	PILE POINT REINFORCEMENT	14.00	0.00	14.00	EA	14.00	\$125.00	\$1,75
		0071	1280	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	92.10	0.00	92.10	CUYD	92.10	\$870.00	\$80,12
		0071	1290	7034219A	TYPE D BARRIER	306.00	0.00	306.00	LF	306.00	\$170.00	\$52,02
		0071	1300	7034221	SLAB ON CONCRETE NU-GIRDER	604.00	0.00	604.00	SQYD	604.00	\$398.00	\$240,39
		0071	1310	7034620	FORM LINERS	194.00	0.00	194.00	SQYD	194.00	\$90.00	\$17,46
		0071	1320	7056021	NU 35, PRESTRESSED CONCRETE NU-GIRDER	491.00	0.00	491.00	LF	491.00	\$360.00	\$176,76
		0071	1330	7061060	REINFORCING STEEL (BRIDGES)	7,230.00	0.00	7,230.00	LB	7,230.00	\$1.75	\$12,65
		0071	1340	7101000	REINFORCING STEEL (EPOXY COATED)	11,070.00	0.00	11,070.00	LB	11,070.00	\$2.10	\$23,24
		0071	1350	7110300	0300 CONCRETE AND MASONRY PROTECTION SYSTEM		0.00	1.00	LS	1.00	\$1,860.00	\$1,86
		0071 1360 7110400 SACRIFICIAL GRAFFITI PROTECTION SYSTEM					0.00	1.00	LS	1.00	\$1,860.00	\$1,86

Revision 4/1/2020 Page 9 of 47



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009	0071	1370	7121060	FABRICATED SIGN SUPPORT BRACKETS	1.00	0.00	1.00	LS	1.00	\$4,000.00	\$4,000.00
		0071	1380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$3,000.00	\$6,000.00
		0071	1390	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$200.00	\$1,600.00
		0071	1400	7161002	LAMINATED NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$385.00	\$3,080.00
		0071	1410	7201300	PIPE PILE SPACERS	18.00	0.00	18.00	EA	18.00	\$1,525.00	\$27,450.00
		0072	1420	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,367.50	\$3,367.50
		0072	1430	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,367.50	\$3,367.50
		0072	1440	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,786.00	0.00	3,786.00	SQFT	3,786.00	\$74.00	\$280,164.00
		0073	1450	7110300	CONCRETE AND MASONRY PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,115.00	\$3,115.00
		0073	1460	7110400	SACRIFICIAL GRAFFITI PROTECTION SYSTEM	1.00	0.00	1.00	LS	1.00	\$3,115.00	\$3,115.00
		0073	1470	7201000	MECHANICALLY STABILIZED EARTH WALL SYSTEMS	3,422.00	0.00	3,422.00	SQFT	3,422.00	\$75.00	\$256,650.00
		0001	5001	6189901	MISC.CONTRACT BOND PAYMENT	0.00	1.00	1.00	LS	1.00	\$53,326.00	\$53,326.00
		0001	5002	6208076	4 IN TEMPORARY PAVEMENT MARKING PAINT	0.00	26,882.00	26,882.00	LF	16,704.00	\$1.05	\$17,539.20
		0001	5003	1046002	VALUE ENGINEERING	0.00	6,720.50	6,720.50	EA	6,720.50	\$1.00	\$6,720.50
		0072	5004	7209901	MISC.FLOWABLE FILL FOR GAS LINE REMOVAL	0.00	1.00	1.00	LS	1.00	\$12,459.01	\$12,459.01
		0040	5005	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	0.00	6.00	6.00	LF	6.00	\$65.63	\$393.78
		0040	5006	9031280	2.5 IN. PSST POST - 12 GA.	0.00	92.00	92.00	LF	92.00	\$33.60	\$3,091.20
		0040	5007	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	0.00	24.00	24.00	LF	24.00	\$78.49	\$1,883.76
		0040	5008	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL	0.00	8.00	8.00	EA	8.00	\$540.75	\$4,326.00
	Project IA	23009 - Tot	al Value I	Posted to Da	TUBE) te as of Report Generated Date							\$4,478,092.69
	J4P3009B	0001	1480	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$85,000.00	\$85,000.00
		0001	1490	2031000	CLASS A EXCAVATION	637.00	0.00	637.00	CUYD	637.00	\$22.00	\$14,014.00
		0001	1500	2036000	COMPACTING EMBANKMENT	260.00	0.00	260.00	CUYD	260.00	\$18.00	\$4,680.00
		0001	1510	2063000	CLASS 3 EXCAVATION	109.00	0.00	109.00	CUYD	109.00	\$20.00	\$2,180.00
		0001	1520	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	268.00	0.00	268.00	SQYD	268.00	\$17.00	\$4,556.00
		0001	1530	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	822.00	0.00	822.00	SQYD	822.00	\$16.00	\$13,152.00
		0001	1540	4019905	MISC.OPTIONAL PAVEMENT - CHIPMAN	434.00	0.00	434.00	SQYD	434.00	\$192.00	\$83,328.00
		0001	1550	4019905	MISC.OPTIONAL PAVEMENT - MURRAY	388.00	0.00	388.00	SQYD	388.00	\$110.00	\$42,680.00
		0001	1560	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	1,688.10	0.00	1,688.10	TONS	1,688.10	\$95.00	\$160,369.50
		0001	1570	4071005	TACK COAT	1,459.00	0.00	1,459.00	GAL	1,425.00	\$2.50	\$3,562.50
		0001	1580	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	92.00	0.00	92.00	GAL	0.00	\$3.00	\$0.00
		0001	1590	6044011	PIPE COLLAR, TYPE A	1.00	0.00	1.00	EA	1.00	\$1,400.00	\$1,400.00
		0001	1600	6081000	CONCRETE MEDIAN	430.80	0.00	430.80	SQYD	430.80	\$65.55	\$28,238.94
		0001	1610	6081010	CONCRETE CURB RAMP	229.30	0.00	229.30	SQYD	229.30	\$127.27	\$29,183.01
		0001	1620	6081012	TRUNCATED DOMES	396.00	0.00	396.00	SQFT	396.00	\$17.65	\$6,989.40
		0001	1630	6083006	6 IN. CONCRETE MEDIAN STRIP	67.70	0.00	67.70	SQYD	67.70	\$161.45	\$10,930.16
		0001	1640	6086004	CONCRETE SIDEWALK, 4 IN.	1,484.60	0.00	1,484.60	SQYD	1,484.60	\$38.55	\$57,231.33
		0001	1650	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	896.00	0.00	896.00	LF	896.00	\$34.65	\$31,046.40
		0001	1660	6091052	CURB AND GUTTER TYPE B	802.00	0.00	802.00	LF	802.00	\$35.05	\$28,110.10
		0001	1670	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	3.00	0.00	3.00	CUYD	0.00	\$75.00	\$0.00
		0001	1680	6096041	PLACING TYPE 1 ROCK DITCH LINER	3.00	0.00	3.00	CUYD	0.00	\$75.00	\$0.00
		0001	1690	6097000	ROCK LINING	7.00	0.00	7.00	CUYD	7.00	\$95.00	\$665.00
		0001	1700	6099903	MISC.CURB AND GUTTER TYPE CG-1	522.00	0.00	522.00	LF	522.00	\$30.90	\$16,129.80
			1710	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X	1.00	0.00	1.00	EA	1.00	\$1,050.00	\$10,129.80
		0001			600MM)							
		0001	1720	6143014	MANHOLE FRAME AND COVER, TYPE 4	1.00	0.00	1.00	EA	1.00	\$750.00	\$750.00
		0001	1730	6161005	CONSTRUCTION SIGNS	339.00	0.00	339.00	SQFT	339.00	\$6.50	\$2,203.50

Revision 4/1/2020 Page 10 of 47



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract	Project	Category	s are ba	Item	port Generated date and can differ from the posted amo	Bid	lime the Es Net	Total	Unit	ed. Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.	,	No.	Code	·	Quantity	Change Order	Current Quantity		Posted Approved Qty		To Date (See report generated date)
211015-C03	J4P3009B	0001	1740	6161025	CHANNELIZER (TRIM LINE)	189.00	0.00	189.00	EA	189.00	\$31.00	\$5,859.0
		0001	1750	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$185.00	\$1,850.0
		0001	1760	6161040	FLASHING ARROW PANEL	2.00	0.00	2.00	EA	2.00	\$2,500.00	\$5,000.0
		0001	1770	6169902	MISC.TYPE II PEDESTRIAN BARRICADE	5.00	0.00	5.00	EA	0.00	\$150.00	\$0.0
		0001	1780	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$110,000.00	\$110,000.0
		0001	1790	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	1.00	0.00	1.00	EA	0.00	\$600.00	\$0.0
		0001	1800	6200009	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 6 IN. WHITE	141.00	0.00	141.00	LF	0.00	\$4.50	\$0.0
		0001	1810	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	462.00	0.00	462.00	LF	0.00	\$20.00	\$0.0
		0001	1820	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	96.00	0.00	96.00	LF	0.00	\$14.00	\$0.0
		0001	1830	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	23.00	0.00	23.00	EA	0.00	\$275.00	\$0.0
		0001	1840	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	1.00	0.00	1.00	EA	0.00	\$450.00	\$0.0
		0001	1850	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	78.00	0.00	78.00	EA	0.00	\$185.00	\$0.0
		0001	1860	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	5,606.00	0.00	5,606.00	LF	0.00	\$2.00	\$0.0
		0001	1870	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,561.00	0.00	2,561.00	LF	0.00	\$2.00	\$0.0
		0001	1880	6205440A	TEMPORARY NON-REMOVABLE MARKING TAPE LEFT/RIGHT ARROW	8.00	0.00	8.00	EA	8.00	\$115.00	\$920.0
		0001	1890	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	3,951.00	0.00	3,951.00	LF	0.00	\$0.55	\$0.0
		0001	1900	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	2,361.00	0.00	2,361.00	LF	0.00	\$0.55	\$0.0
		0001	1910	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	333.00	0.00	333.00	LF	0.00	\$0.90	\$0.0
		0001	1920	6207001	PAVEMENT MARKING REMOVAL	630.00	0.00	630.00	LF	252.00	\$1.00	\$252.0
		0001	1930	6207002	PAVEMENT MARKING REMOVAL (SYMBOLS)	10.00	0.00	10.00	EA	3.00	\$115.00	\$345.0
		0001	1940	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	15,347.00	0.00	15,347.00	SQYD	15,347.00	\$3.00	\$46,041.0
		0001	1950	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	8.00	0.00	8.00	SQYD	0.00	\$5.00	\$0.0
		0001	1960	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$24,000.00	\$24,000.0
		0001	1970	7261015	15 IN. PIPE GROUP A	97.00	0.00	97.00	LF	97.00	\$80.00	\$7,760.0
		0001	1980	7261030	30 IN. PIPE GROUP A	15.00	0.00	15.00	LF	15.00	\$160.00	\$2,400.0
		0001	1990	7310048	PRECAST CONCRETE MANHOLE - 48 IN.	7.00	0.00	7.00	FT	7.00	\$625.00	\$4,375.0
		0001	2000	7311022	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	6.00	0.00	6.00	FT	6.00	\$775.00	\$4,650.0
		0001	2010	7320615A	15 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$1,950.00	\$1,950.0
		0001	2020	7320630A	30 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION	1.00	0.00	1.00	EA	1.00	\$2,500.00	\$2,500.0
		0001	2030	8031000A	TURF TYPE TALL FESCUE SODDING	1,064.00	0.00	1,064.00	SQYD	0.00	\$5.65	\$0.0
		0001	2040	8051000A	SEEDING - COOL SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00	\$1,600.00	\$0.0
		0001	2050	8061004	SEDIMENT TRAP ROCK	18.00	0.00	18.00	CUYD	0.00	\$90.00	\$0.0
		0001	2060	8061005	ROCK DITCH CHECK	188.00	0.00	188.00	LF	0.00	\$55.00	\$0.0
		0001	2070	8061007A	CURB INLET CHECK	5.00	0.00	5.00	EA	5.00	\$63.00	\$315.0
		0001	2080	8061016	SEDIMENT REMOVAL	53.00	0.00	53.00	CUYD	53.00	\$25.00	\$1,325.0
		0001	2090	8061019	SILT FENCE	793.00	0.00	793.00	LF	0.00	\$1.35	\$0.0
		0001	2100	8064128	TYPE 1 TURF REINFORCEMENT MAT	593.00	0.00	593.00	SQYD	0.00	\$1.95	\$0.0
		0020	2110	9011010	RELOCATED POLE	6.00	0.00	6.00	EA	4.00	\$800.00	\$3,200.0
		0020	2120	9011060	LIGHTING POLE, 45 FT. OR 13.5 M, TYPE AT DESIGN 1	1.00	0.00	1.00	EA	0.00	\$4,000.00	\$0.0
		0020	2130	9011115	BRACKET ARM, 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,200.00	\$0.0
		0020	2140	9011312	LUMINAIRE, LED-B	7.00	0.00	7.00	EA	0.00	\$200.00	\$0.0
		0020	2150	9014004	CONDUIT, 4 IN. RIGID, PUSHED	136.00	0.00	136.00	LF	136.00	\$35.00	\$4,760.0
		0020	2160	9014502	CONDUIT, 2 IN. RIGID, EXTERNAL ON STRUCTURE	322.00	0.00	322.00	LF	322.00	\$60.00	\$19,320.0
		0020	2170	9015010	TRENCHING TYPE I	795.00	0.00	795.00	LF	53.00	\$6.00	\$318.0

Revision 4/1/2020 Page 11 of 47



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	J4P3009B	0020	2180	9016110	PULL BOX, PREFORMED CLASS 1	5.00	0.00	5.00	EA	4.00	\$355.00	\$1,420.00
		0020	2190	9017004	CABLE, 4 AWG 1 CONDUCTOR	1,110.00	0.00	1,110.00	LF	0.00	\$3.00	\$0.00
		0020	2200	9017008	CABLE, 8 AWG 1 CONDUCTOR	1,700.00	0.00	1,700.00	LF	765.00	\$2.50	\$1,912.50
		0020	2210	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	120.00	0.00	120.00	LF	0.00	\$2.00	\$0.00
		0020	2220	9017407	CABLE-CONDUIT, 1 IN., 2 CONDUCTORS AND 1 BARE NEUTRAL, 8 AWG	920.00	0.00	920.00	LF	0.00	\$12.50	\$0.00
		0020	2230	9018245	POLE FOUNDATION (45 FT. OR 13.5 M MOUNTING HEIGHT)	4.00	0.00	4.00	EA	0.00	\$1,400.00	\$0.00
		0020	2240	9019902	MISC.LEE'S SUMMIT 40 FT. POLE FOUNDATION B40D SCREW-	3.00	0.00	3.00	EA	0.00	\$1,500.00	\$0.00
		0020	2250	9019902	IN MISC.LUMINAIRE, LED-A WALL PACK (INCLUDING HOUSING)	4.00	0.00	4.00	EA	4.00	\$1,200.00	\$4,800.00
		0020	2260	9019902	MISC.PULL BOX LID REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$900.00	\$0.00
		0020	2270	9027200	CONDUIT, 2 IN., PUSHED WITH TRACER WIRE	410.00	0.00	410.00	LF	410.00	\$25.00	\$10,250.00
		0030	2280	9020211	SIGNAL HEAD, TYPE 1S	18.00	0.00	18.00	EA	0.00	\$175.00	\$0.00
		0030	2290	9020215	SIGNAL HEAD, TYPE 5S	1.00	0.00	1.00	EA	0.00	\$1,500.00	\$0.00
		0030	2300	9020513	SIGNAL HEAD, TYPE 3B	9.00	0.00	9.00	EA	0.00	\$975.00	\$0.00
		0030	2310	9020514	SIGNAL HEAD, TYPE 4B	3.00	0.00	3.00	EA	0.00	\$1,275.00	\$0.00
		0030	2320	9020833	SH-FLAT SHEET - SIGNAL SIGN	42.00	0.00	42.00	SQFT	42.00	\$80.00	\$3,360.00
		0030	2330	9020834	SIGNAL SIGN, MOUNTING HARDWARE	21.00	0.00	21.00	EA	21.00	\$60.00	\$1,260.00
		0030	2340	9022708	POST, SIGNAL 8 FT. OR 2.4 M	11.00	0.00	11.00	EA	0.00	\$1,325.00	\$0.00
		0030	2350	9022715	POST, SIGNAL 15 FT. OR 4.6 M	1.00	0.00	1.00	EA	0.00	\$1,750.00	\$0.00
		0030	2360	9023250	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	1.00	0.00	1.00	EA	1.00	\$15,000.00	\$15,000.00
		0030	2370	9024920	DETECTOR, PUSHBUTTON	18.00	0.00	18.00	EA	0.00	\$1,250.00	\$0.00
		0030	2380	9024975	VIDEO DETECTION SYSTEM	3.00	0.00	3.00	EA	1.00	\$24,000.00	\$24,000.00
		0030	2390	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	267.00	0.00	267.00	LF	162.00	\$17.50	\$2,835.00
		0030	2400	9025400	CONDUIT, 4 IN., TRENCH WITH TRACER WIRE	37.00	0.00	37.00	LF	0.00	\$13.00	\$0.00
		0030	2410	9027300	CONDUIT, 3 IN., PUSHED WITH TRACER WIRE	789.00	0.00	789.00	LF	789.00	\$32.00	\$25,248.00
		0030	2420	9028308	CABLE, 16 AWG 2 CONDUCTOR	3,450.00	0.00	3,450.00	LF	1,970.00	\$1.50	\$2,955.00
		0030	2430	9028310	CABLE, 16 AWG 5 CONDUCTOR	3,460.00	0.00	3,460.00	LF	1,990.00	\$2.00	\$3,980.00
		0030	2440	9028311	CABLE, 16 AWG 7 CONDUCTOR	2,110.00	0.00	2,110.00	LF	1,335.00	\$2.50	\$3,337.50
		0030	2450	9028811	PULL BOX, PREFORMED CLASS 2	13.00	-2.00	11.00	EA	8.00	\$1,750.00	\$14,000.00
		0030	2460	9028812	PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	0.00	\$1,825.00	\$0.00
		0030	2470	9029100	BASE, CONCRETE	11.80	0.00	11.80	CUYD	5.20	\$2,500.00	\$13,000.00
		0030	2480	9029902	MISC.POST, SIGNAL 4 FT.	3.00	0.00	3.00	EA	0.00	\$985.00	\$0.00
		0030	2490	9029902	MISC.PULL BOX CLASS 3 LID REPLACEMENT	1.00	0.00	1.00	EA	0.00	\$250.00	\$0.00
		0030	2500	9109902	MISC.CCTV CAMERA ASSEMBLY, INSTALLED	2.00	0.00	2.00	EA	0.00	\$8,000.00	\$0.00
		0040	2510	9031010	CONCRETE FOOTINGS, EMBEDDED	1.70	0.20	1.90	CUYD	0.00	\$1,300.00	\$0.00
		0040	2520	9031210	STRUCTURAL STEEL POSTS	1,520.00	0.00	1,520.00	LB	0.00	\$4.25	\$0.00
		0040	2530	9031270A	2 IN. PSST POST - 12 GA.	236.00	-53.00	183.00	LF	0.00	\$20.50	\$0.00
		0040	2540	9035004A	SH-FLAT SHEET	67.00	0.00	67.00	SQFT	0.00	\$23.50	\$0.00
		0040	2550	9035011A	ST-STRUCTURAL	318.00	0.00	318.00	SQFT	0.00	\$21.50	\$0.00
		0040	2560	9035069A	SHF-FLAT SHEET FLUORESCENT	18.00	0.00	18.00	SQFT	0.00	\$37.50	\$0.00
		0040	5009	9031271	POST ANCHOR FOR 2 IN. PSST - 12 GA.	0.00	21.00	21.00	LF	0.00	\$42.00	\$0.00
		0040	5010	9031273	POST ANCHOR FOR 2 IN. PSST - 7 GA.	0.00	21.00	21.00	LF	0.00	\$65.63	\$0.00
		0040	5011	9031280	2.5 IN. PSST POST - 12 GA.	0.00	27.00	27.00	LF	0.00	\$33.60	\$0.00
		0040	5012	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	0.00	6.00	6.00	LF	0.00	\$78.49	\$0.00
		0030	5013	9029901	MISC.PULL BOX HEIGHT ADJUSTMENT	0.00	1.00	1.00	LS	1.00	\$1,001.74	\$1,001.74
		0040	5014	9039902	MISC.SIGN RELOCATION	0.00	6.00	6.00	EA	6.00	\$246.75	\$1,480.50
		0020	5015	9019902	MISC.PULL BOX REMOVAL AND REPLACEMENT	0.00	2.00	2.00	EA	2.00	\$2,079.00	\$4,158.00

Revision 4/1/2020 Page 12 of 47



Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generat ated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C03	Project J4F	P3009B - To	tal Value	Posted to D	Pate as of Report Generated Date							\$1,008,587.89
211015-C03 Ove	rall - Total V	/alue Poste	d to Date	as of Repor	t Generated Date							\$5,486,680.58

Revision 4/1/2020 Page 13 of 47



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4P3009

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0330	6161033	DIRECTIONAL INDICATOR BARRICADE	10/14/22	10/14/22	-23.00	EA	Correcting overpayment of DIBS on 9/23/22 DWR.	560+00		576+52.76		
0570	7261030	30 IN. PIPE GROUP A	10/8/22	10/14/22	9.00	LF		568+07.53	rt	568+08.37	rt	

Project: J4P3009B

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1480	2022010	REMOVAL OF IMPROVEMENTS	10/8/22	10/14/22	0.05	LS		0+00		0+00		
1510	2063000	CLASS 3 EXCAVATION	10/8/22	10/14/22	10.00	CUYD		1+13.31		1+21.75		Paid to bring total up from 51 to 61 on this install.
1620	6081012	TRUNCATED DOMES	10/8/22	10/14/22	10.00	SQFT	Chipman	10+84.4	rt	10+89.71	rt	
				10/14/22	10.00	SQFT	Chipman	10+95.71	rt	11+01.23	rt	
				10/14/22	10.00	SQFT	Chipman	11+10.35	rt	11+12.92	rt	
				10/14/22	10.00	SQFT	Chipman	11+48.4	rt	11+50.4	rt	
				10/14/22	10.00	SQFT	Chipman	14+97.08	rt	14+99.08	rt	
				10/14/22	10.00	SQFT	Chipman	15+32.03	rt	15+34.58	rt	
				10/14/22	10.00	SQFT	Chipman	15+53.77	rt	15+58.33	rt	
				10/14/22	10.00	SQFT	Chipman	15+79.21	rt	15+84	rt	
				10/14/22	10.00	SQFT	Chipman	7+24	It	7+29	It	
				10/14/22	10.00	SQFT	Chipman	7+24	rt	7+29		
				10/14/22	20.00	SQFT	Chipman	10+18.61	It	10+25.65	It	
				10/14/22	20.00	SQFT	Chipman	10+48.01	It	10+55.2	It	
				10/14/22	20.00	SQFT	Chipman	10+65.52	Lt	10+68+. 5	Ly	
				10/14/22	20.00	SQFT	Chipman	11+04.32	It	11+06.32	It	
				10/14/22	20.00	SQFT	Chipman	14+60.16	It	14+62.16	It	
				10/14/22	20.00	SQFT	Chipman	14+98.54	It	15+01.3	It	
				10/14/22	20.00	SQFT	Chipman	15+17.92	It	15+27.87	It	
				10/14/22	20.00	SQFT	Chipman	15+27.29	It	15+37.11	It	
				10/14/22	20.00	SQFT	Chipman	17+34.03	It	17+42.47	It	
				10/14/22	20.00	SQFT	Chipman	17+48.68	It	17+57.22	It	
				10/14/22	36.00	SQFT	Chipman	8+39.24	rt	8+58.04	rt	
				10/14/22	40.00	SQFT	Chipman	7+36.98	rt	7+57.95	rt	
1760	6161040	FLASHING ARROW PANEL	10/14/22	10/14/22	1.00	EA	Chipman Road	4+00		19+47.61		

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 14 of 47



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3009	0040	EMBANKMENT IN PLACE	Material		3	Apr 18, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$12,020.00)	
					4	May 2, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$12,020.00)	
					5	May 16, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$12,020.00)	
					6	Jun 1, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$12,020.00)	
					7	Jun 16, 2022	SYSTEM	\$12,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$12,020.00)	
					8	Jul 1, 2022	SYSTEM	\$63,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$63,400.00)	
					9	Jul 18, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Paymen Estimate Exception 1 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$72,520.00)	
					10	Aug 2, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$72,520.00)	
					11	Aug 16, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0060) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$72,520.00)	
					12	Sep 2, 2022	SYSTEM	\$72,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$72,520.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0040 -	Total						\$0.00	
	0050	COMPACTING EMBANKMENT	Material		3	Apr 18, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$272.50)	
					4	May 2, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$272.50)	
					5	May 16, 2022	SYSTEM	\$272.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	May 16,	SYSTEM	(\$272.50)	



Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Estimate Exception 2 on the current Payment Estimate Payment Estimate Exception 2 on the current Payment Estimate Payment Estimate Exception 2 on the current Payment Estimate Payment Payme	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
2022	4P3009	0050	COMPACTING EMBANKMENT	Material		6		SYSTEM	\$272.50	Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment	
Settmale Item Adjustment (0018) due to user voltant overridding Payment Estimate Exception 2 on the current Payment Estimate Estimate Item Adjustment (0023) due to user voltant overridding Payment Estimate Estimate Item Adjustment (0023) due to user voltant overridding Payment Estimate Exception 2 on the current Payment Estimate. Payment Estimate Exception 2 on the current Payment Estimate Estimate Estimate Estimate Exception 2 on the current Payment Estimate Estim						6		SYSTEM	(\$272.50)		
8						7		SYSTEM	\$272.50	Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment	
Balance Beatmante Beatma						7		SYSTEM	(\$272.50)		
						8		SYSTEM	\$4,010.00	Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment	
9						8		SYSTEM	(\$4,010.00)		
10						9		SYSTEM	\$7,222.50	Estimate Item Adjustment (0004) due to user raybol1 overridding Paymen	
10						9		SYSTEM	(\$7,222.50)		
2022 11						10	Aug 2,	SYSTEM	\$13,235.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment	
System Estimate Item Adjustment (0081) due to user vohsr1 overridding Payment Estimate Estimate Exception 2 on the current Payment Estimate Estimate Exception 2 on the current Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment Estimate Payment						10		SYSTEM	(\$13,235.00)		
12 Sep 2, SYSTEM \$13,235.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate.						11		SYSTEM	\$13,235.00	Estimate Item Adjustment (0061) due to user vohsr1 overridding Payment	
Sep 2, 2022 SYSTEM (\$13,235.00)						11		SYSTEM	(\$13,235.00)		
12						12		SYSTEM	\$13,235.00	Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment	
Material - Total							12		SYSTEM	(\$13,235.00)	
Material 8					- Total				\$0.00		
Material Material Section Sec		0050	Total	Material - Total							
8 Jul 1, 2022 SYSTEM (\$5,600.00) 9 Jul 18, 2022 SYSTEM \$8,400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 9 Jul 18, 2022 SYSTEM (\$8,400.00) 10 Aug 2, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user voher1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM (\$11,200.00) 11 Aug 16, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 11 Aug 16, 2022 SYSTEM (\$11,200.00) 12 Sep 2, SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 12 Sep 2, SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate. 12 Sep 2, SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 3 on the current Payment Estimate Estimate Exception 3 on the current Payment Estimate.		0050 -	COMPACTING IN CUT	Material		8		SYSTEM		Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment	
9 Jul 18, 2022 SYSTEM \$8,400.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 9 Jul 18, 2022 SYSTEM (\$8,400.00) 10 Aug 2, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 10 Aug 2, SYSTEM (\$11,200.00) 11 Aug 16, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user vohsr1 overridding Payment Estimate Item Adjustment (0062) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Aug 16, 2022 SYSTEM (\$11,200.00) 12 Sep 2, SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 12 Sep 2, SYSTEM (\$11,200.00)						8		SYSTEM	(\$5,600.00)	Example Exception 6 of the carrotter agreement.	
9 Jul 18, 2022 SYSTEM (\$8,400.00) 10 Aug 2, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM (\$11,200.00) 11 Aug 16, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Aug 16, 2022 SYSTEM (\$11,200.00) 12 Sep 2, SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 12 Sep 2, 2022 SYSTEM (\$11,200.00) 1-Total \$0.00						9	Jul 18,	SYSTEM	\$8,400.00	Estimate Item Adjustment (0005) due to user raybol1 overridding Paymen	
10 Aug 2, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 10 Aug 2, 2022 SYSTEM (\$11,200.00) 11 Aug 16, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Aug 16, 2022 SYSTEM (\$11,200.00) 12 Sep 2, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 12 Sep 2, 2022 SYSTEM (\$11,200.00) 13 Sep 2, 2022 SYSTEM (\$11,200.00)						9		SYSTEM	(\$8,400.00)		
11 Aug 16, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0062) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11 Aug 16, 2022 SYSTEM (\$11,200.00) 12 Sep 2, 2022 SYSTEM \$11,200.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 12 Sep 2, 2022 SYSTEM (\$11,200.00)						10	Aug 2,	SYSTEM	\$11,200.00	Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment	
Estimate Item Adjustment (0062) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 11						10		SYSTEM	(\$11,200.00)		
2022 12 Sep 2, 2022 13 Sep 2, 2022 14 Sep 2, 2022 15 Sep 2, 2022 16 Sep 2, 2022 17 Sep 2, 2022 18 Sep 2, 2022 19 Sep 2, 2022 10 Sep 2, 2022 10 Sep 2, 2022 11 Sep 2, 2022 12 Sep 2, 2022 13 Sep 2, 2022 14 Sep 2, 2022 15 Sep 2, 2022 16 Sep 2, 2022 17 Sep 2, 2022 18 Sep 2						11		SYSTEM	\$11,200.00	Estimate Item Adjustment (0062) due to user vohsr1 overridding Payment	
Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate. 12 Sep 2, 2022 \$YSTEM (\$11,200.00) - Total \$0.00						11	Aug 16, 2022	SYSTEM	(\$11,200.00)		
- Total \$0.00						12		SYSTEM	\$11,200.00	Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment	
					12		SYSTEM	(\$11,200.00)			
Material - Total \$0.00											
					- Total				\$0.00		
\$0.00				Material - Total							
\$0.00 Solution Material 2 Apr 4, SYSTEM \$10,271.25 This adjustment offsets the original system-generated Material Parameters of the property o							2022 Sep 2,			Estimate Item Adjustment (0003) due to user vohsr1 overridding I	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0090	AGGREGATE FOR BASE	Material			2022			Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$10,271.25)	
					3	Apr 18, 2022	SYSTEM	\$23,941.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Apr 18, 2022	SYSTEM	(\$23,941.50)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0090 -	Total						\$0.00	
	0100	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		5	May 16, 2022	SYSTEM	\$6,990.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		micky			5	May 16, 2022	SYSTEM	(\$6,990.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0100 -							\$0.00	
	0110	MISC. AGGREGATE FOR	Material		7	Jun 16, 2022	SYSTEM	(\$51,007.00)	
		BASE			8	Jul 1, 2022	SYSTEM	\$51,007.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$51,007.00)	
					9	Jul 18, 2022	SYSTEM	\$51,007.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$51,007.00)	
					10	Aug 2, 2022	SYSTEM	\$128,876.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$128,876.00)	
					11	Aug 16, 2022	SYSTEM	\$128,876.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0063) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$128,876.00)	
				- Total				(\$51,007.00)	
			Material - Tota					(\$51,007.00)	
			MaterialCredit		8	Jul 1, 2022	SYSTEM	\$51,007.00	
				- Total				\$51,007.00	
			MaterialCredit	- Total				\$51,007.00	
	0110 -							\$0.00	
	0120	TYPE A2 SHOULDER	Other Item Adjustment	ACAD		Jul 1, 2022	vohsr1	\$1,787.70	This Adjustment is being made for the Bit Base lift for the Type A2 Shoulder for the pavement South of the bridge.
					11	Aug 17, 2022	vohsr1	\$2,827.28	AC Adjustment for BB JUL-22 Period 2.
					11	Aug 17, 2022	vohsr1	\$1,627.42	Corrected AC adjustment for BB E JUN-22 Period 2
					11	Aug 16, 2022	vohsr1	(\$1,787.70)	This adjustment is being made to correct the adjustment made on Estimate 8.
				ACAD - Tota	al			\$4,454.70	
			Other Item Adj	ustment - To	tal			\$4,454.70	
	0120 -							\$4,454.70	
	0130	MISC.	Material		4	May 2, 2022	SYSTEM	\$24,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	May 2,	SYSTEM	(\$24,000.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3009	0130	MISC.	Material			2022				
					5	May 16, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					5	May 16, 2022	SYSTEM	(\$46,600.00)		
					6	Jun 1, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					6	Jun 1, 2022	SYSTEM	(\$46,600.00)		
					7	Jun 16, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					7	Jun 16, 2022	SYSTEM	(\$46,600.00)		
					8	Jul 1, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					8	Jul 1, 2022	SYSTEM	(\$46,600.00)		
					9	Jul 18, 2022	SYSTEM	\$46,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					9	Jul 18, 2022	SYSTEM	(\$46,600.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	0130 -	Total						\$0.00		
	0140	MISC.	Material	Material		2	Apr 4, 2022	SYSTEM	\$37,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vohsr1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$37,350.00)		
					3	Apr 18, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					3	Apr 18, 2022	SYSTEM	(\$103,080.00)		
					4	May 2, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					4	May 2, 2022	SYSTEM	(\$103,080.00)		
					5	May 16, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					5	May 16, 2022	SYSTEM	(\$103,080.00)		
					6	Jun 1, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					6	Jun 1, 2022	SYSTEM	(\$103,080.00)		
					7	Jun 16, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					7	Jun 16, 2022	SYSTEM	(\$103,080.00)		
					8	Jul 1, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					8	Jul 1, 2022	SYSTEM	(\$103,080.00)		
					9	Jul 18, 2022	SYSTEM	\$103,080.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					9	Jul 18,	SYSTEM	(\$103,080.00)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0140	MISC.	Material			2022			
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0140 -	- Total						\$0.00	
	0150	MISC.	Other Item Adjustment	ACAD	8	Jul 1, 2022	vohsr1	\$11,167.45	This adjustment is being made for the SP 190 C asphalt placed on the south side of the bridge.
					8	Jul 1, 2022	vohsr1	\$4,209.06	This adjustment is being made for the SP 190 C as phalt placed on the south side of the bridge.
					11	Aug 17, 2022	vohsr1	\$8,621.83	AC Adjustment for AUG-22 First Period SP-190B.
					11	Aug 17, 2022	vohsr1	\$21,106.92	AC Adjustment for JUL-22 Second Period SP-190C.
					11	Aug 16, 2022	vohsr1	\$8,960.71	AC Adjustment for SP-125C AUG-22 First Period
					11	Aug 17, 2022	vohsr1	(\$4,209.06)	AC Ajustment for SP190B was incorrectly Labeled as SP190C on Estimate 8. This adjustment is correcting that comment.
					11	Aug 17, 2022	vohsr1	(\$11,167.45)	AC Ajustment for SP190C was incorrectly calculated on Estimate 8. This adjustment is correcting that adjustment.
					11	Aug 17, 2022	vohsr1	\$4,209.06	Corrected AC Adjustment for JUN-22 Second Period SP-190B From Estimate 8.
					11	Aug 17, 2022	vohsr1	\$11,601.34	Corrected AC Adjustment for JUN-22 Second Period SP-190C.
				ACAD - Tot	al			\$54,499.86	
			Other Item Adj	ustment - To	tal			\$54,499.86	
	0150 -	- Total						\$54,499.86	
	0160	ASPHALTIC CONCRETE MIXTURE PG	E Adjustment	ACAD	4	May 2, 2022	vohsr1	\$1,167.05	Asphalt Cement Price Adjustment for Line 0180, April 2022
		MIXTURE PG 70-22 (SP125C		ACAD - Tot	al			\$1,167.05	
		MIX)	Other Item Adjustment - Total					\$1,167.05	
	0160 -	- Total						\$1,167.05	
	0180	CONCRETE APPROACH PAVEMENT	Material		9	Jul 18, 2022	SYSTEM	\$41,246.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$41,246.28)	
					10	Aug 2, 2022	SYSTEM	\$41,246.28	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment
					10				Estimate Exception 12 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$41,246.28)	
					11		SYSTEM	(\$41,246.28) \$41,246.28	
						2022 Aug 16,		, ,	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment
					11	2022 Aug 16, 2022 Aug 16,	SYSTEM	\$41,246.28	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment
					11	Aug 16, 2022 Aug 16, 2022 Sep 2,	SYSTEM SYSTEM	\$41,246.28 (\$41,246.28)	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
					11 11 12	Aug 16, 2022 Aug 16, 2022 Sep 2, 2022 Sep 2,	SYSTEM SYSTEM	\$41,246.28 (\$41,246.28) \$41,246.28	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment
					11 11 12	Aug 16, 2022 Aug 16, 2022 Sep 2, 2022 Sep 2, 2022 Sep 16,	SYSTEM SYSTEM SYSTEM	\$41,246.28 (\$41,246.28) \$41,246.28	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment
					11 11 12 12 13	2022 Aug 16, 2022 Aug 16, 2022 Sep 2, 2022 Sep 2, 2022 Sep 16, 2022 Sep 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$41,246.28 (\$41,246.28) \$41,246.28 (\$41,246.28) \$41,246.28	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment
					11 11 12 12 13 13 13	2022 Aug 16, 2022 Aug 16, 2022 Sep 2, 2022 Sep 2, 2022 Sep 16, 2022 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$41,246.28 (\$41,246.28) \$41,246.28 (\$41,246.28) \$41,246.28	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment
				- Total	11 11 12 12 13 13 14	2022 Aug 16, 2022 Aug 16, 2022 Sep 2, 2022 Sep 2, 2022 Sep 16, 2022 Oct 3, 2022 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$41,246.28 (\$41,246.28) \$41,246.28 (\$41,246.28) \$41,246.28 (\$41,246.28) \$41,246.28	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment
			Material - Tota		11 11 12 12 13 13 14	2022 Aug 16, 2022 Aug 16, 2022 Sep 2, 2022 Sep 2, 2022 Sep 16, 2022 Oct 3, 2022 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$41,246.28 (\$41,246.28) \$41,246.28 (\$41,246.28) \$41,246.28 (\$41,246.28) \$41,246.28	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment
	0180 -	- Total	Material - Tota		11 11 12 12 13 13 14	2022 Aug 16, 2022 Aug 16, 2022 Sep 2, 2022 Sep 2, 2022 Sep 16, 2022 Oct 3, 2022 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$41,246.28 (\$41,246.28) \$41,246.28 (\$41,246.28) \$41,246.28 (\$41,246.28) \$41,246.28 \$41,246.28	Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0064) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
4P3009	0190	TYPE A	Material			2022			Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					4	May 2, 2022	SYSTEM	(\$3,300.00)					
					5	May 16, 2022	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.				
					5	May 16, 2022	SYSTEM	(\$3,300.00)					
				- Total				\$0.00					
	0100		Material - Tota	ıl				\$0.00					
	0190 -		Material		44	A 40	OVOTEM	\$0.00	This allows at West the mining of particles and Material Decree				
	0200	AGGR. BEDDING FOR 3 - STRAND GUARD CABLE	Material		11	Aug 16, 2022	SYSTEM	\$3,720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0059) due to user vohsr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.				
					11	Aug 16, 2022	SYSTEM	(\$3,720.00)					
				- Total				\$0.00					
			Material - Tota	I				\$0.00					
	0200 -							\$0.00					
	0210	MODIFIED CONCRETE GUTTER TYPE B	Material	Material	Material	Material	Material		6	Jun 1, 2022	SYSTEM	\$14,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$14,064.00)					
					7	Jun 16, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.				
					7	Jun 16, 2022	SYSTEM	(\$23,520.00)					
					8	Jul 1, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.				
					8	Jul 1, 2022	SYSTEM	(\$23,520.00)					
					9	Jul 18, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.				
					9	Jul 18, 2022	SYSTEM	(\$23,520.00)					
					10	Aug 2, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					10	Aug 2, 2022	SYSTEM	(\$23,520.00)					
					11	Aug 16, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0065) due to user vohsr1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
					11	Aug 16, 2022	SYSTEM	(\$23,520.00)					
							1:	12	12	Sep 2, 2022	SYSTEM	\$23,520.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$23,520.00)					
				- Total				\$0.00					
			Material - Tota	ı				\$0.00					
	0210 -							\$0.00					
	0220	MISC. FENCING	Material		11	Aug 16, 2022	SYSTEM	\$44,685.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0066) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.				
					11	Aug 16, 2022	SYSTEM	(\$44,685.00)					
					12	Sep 2, 2022	SYSTEM	\$44,685.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vohsr1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0220	MISC. FENCING	Material	Туре	12	Sep 2,	SYSTEM	(\$44,685.00)	
					13	2022 Sep 16,	SYSTEM	\$44,685.00	This adjustment offsets the original system-generated Material Payment
					13	2022	SISILW	\$ 44 ,005.00	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$44,685.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0220 -	Total						\$0.00	
	0230	CONCRETE MEDIAN	Material		13	Sep 16, 2022	SYSTEM	\$1,117.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$1,117.90)	
					14	Oct 3, 2022	SYSTEM	\$1,117.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$1,117.90)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0230 -	Total						\$0.00	
	0330	DIRECTIONAL INDICATOR BARRICADE	TOR Adjustment	OTHR	14	Oct 3, 2022	raybol1	(\$3,105.00)	Deducting for accidental pay of 23 DIBS @ \$135.00/EA.
					15	Oct 17, 2022	raybol1	\$3,105.00	A line adjustment was made on Estimate 0014 to deduct for accidental pay of 23 DIBS @ \$135/EA. This is to zero out this adjustment. The actual line item quantity was corrected on this estimate.
				OTHR - Tota	al			\$0.00	
			Other Item Ad	justment - To	tal			\$0.00	
	0330 -	Total						\$0.00	
	0350	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		1	Mar 18, 2022	SYSTEM	\$19,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user vohsr1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Mar 18, 2022	SYSTEM	(\$19,000.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00 \$0.00	
	0350 -	Total	Material - Tota						
	0350 - 0370	Total CONCRETE TRAFFIC BARRIER, TYPE C			8	Jul 1, 2022	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		CONCRETE TRAFFIC			8		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment
		CONCRETE TRAFFIC				2022 Jul 1,		\$0.00 \$0.00 \$29,800.00	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment
		CONCRETE TRAFFIC			8	Jul 1, 2022 Jul 18,	SYSTEM	\$0.00 \$0.00 \$29,800.00 (\$29,800.00)	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment
		CONCRETE TRAFFIC			8	Jul 1, 2022 Jul 18, 2022 Jul 18,	SYSTEM SYSTEM	\$0.00 \$0.00 \$29,800.00 (\$29,800.00) \$29,800.00	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment
		CONCRETE TRAFFIC			8 9	Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2,	SYSTEM SYSTEM	\$0.00 \$0.00 \$29,800.00 (\$29,800.00) \$29,800.00 (\$29,800.00)	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment
		CONCRETE TRAFFIC			8 9 9	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$29,800.00 (\$29,800.00) \$29,800.00 (\$29,800.00) \$35,400.00	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment
		CONCRETE TRAFFIC			8 9 9 10 10	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$29,800.00 (\$29,800.00) \$29,800.00 (\$29,800.00) \$35,400.00	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user vohsr1 overridding Payment Estimate Item Adjustment (0067) due to user vohsr1 overridding Payment
		CONCRETE TRAFFIC			8 9 9 10 10	Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$29,800.00 (\$29,800.00) \$29,800.00 (\$29,800.00) \$35,400.00 (\$35,400.00)	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user vohsr1 overridding Payment Estimate Item Adjustment (0067) due to user vohsr1 overridding Payment
		CONCRETE TRAFFIC			8 9 9 10 10 11 11 11	Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 16, 2022 Aug 16, 2022 Sep 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$29,800.00 (\$29,800.00) \$29,800.00 (\$29,800.00) \$35,400.00 (\$35,400.00)	Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0067) due to user vohsr1 overridding Payment Estimate Exception 33 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment Estimate Item Adjustment (0007) due to user vohsr1 overridding Payment



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
	20	2000.i.p.iio.i.	Туре	Adjustment Type	Number	Date	Ву	7 1110 1111	
J4P3009	0370	CONCRETE TRAFFIC	Material			2022			Estimate Item Adjustment (0004) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
		BARRIER, TYPE C			13	Sep 16, 2022	SYSTEM	(\$35,400.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0370 -	Total						\$0.00	
	0520	SEPARATION GEOTEXTILE	Material		11	Aug 16, 2022	SYSTEM	\$3,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0068) due to user vohsr1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$3,771.00)	
					12	Sep 2, 2022	SYSTEM	\$3,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment
					12	Sep 2,	SYSTEM	(\$3,771.00)	Estimate Exception 39 on the current Payment Estimate.
						2022			
					13	Sep 16, 2022	SYSTEM	\$3,771.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$3,771.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0520 -	Total						\$0.00	
	0660	660 SILT FENCE	Material		4	May 2, 2022	SYSTEM	\$850.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					4	May 2, 2022	SYSTEM	(\$850.50)	
				- Total				\$0.00	
			Material - Tota	İ				\$0.00	
	0660 -	Total						\$0.00	
	0690	690 MGS GUARDRAIL, 8 FT. POSTS, 6 FT. - 3 IN	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$33,387.55)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$33,387.55)	
			Construction	Stockpile - To	otal			(\$33,387.55)	
			Construction Stockpile STMI	4 May 2, SYSTEM 2022			\$33,968.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total				\$33,968.00	
			Construction S	Stockpile STI				\$33,968.00	
			Material		11	Aug 16, 2022	SYSTEM	\$45,297.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0069) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$45,297.00)	
					12	Sep 2, 2022	SYSTEM	\$45,297.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$45,297.00)	
				- Total				\$0.00	
			Material - Tota	l .				\$0.00	
	0690 -	Total						\$580.45	
	0700	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$1,851.85)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(- Total				(\$1,851.85)	
			Construction S	Stockpile - To	otal			(\$1,851.85)	
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$1,851.85	Payment Estimate Item Adjustment generated Stockpile Transaction
		S		- Total				\$1,851.85	
			Construction	Stockpile STMI - Total				\$1,851.85	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3009	0700	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Material		11	Aug 16, 2022	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0070) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$15,000.00)	
					12	Sep 2, 2022	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$15,000.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0700 -	Total						\$0.00	
	0710	MGS END ANCHOR	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$830.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$830.00)	
			Construction	Stockpile - To	otal			(\$830.00)	
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$830.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$830.00	
			Construction	Stockpile STI	MI - Total			\$830.00	
			Material		11	Aug 16, 2022	SYSTEM	\$950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0071) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$950.00)	
					12	Sep 2, 2022	SYSTEM	\$950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$950.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0710 -	Total						\$0.00	
	0720	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		11	Aug 16, 2022	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)	0 1 11	- Total				(\$7,520.00)	
			Construction	Stockpile - To			OVOTELL	(\$7,520.00)	
			Construction Stockpile STMI	Tatal	4	May 2, 2022	SYSTEM	\$7,520.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction :	- Total	MI - Total			\$7,520.00 \$7,520.00	
			Material	этоскрие от	11	Aug 16, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0072) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$10,800.00)	
					12	Sep 2, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$10,800.00)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
	0720 -	Total						\$0.00	
	0730	MISC. GUARDRAIL ITEM	Construction Stockpile		8	Jul 1, 2022	SYSTEM	(\$3,300.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$3,300.00)	
			Construction	Stockpile - To				(\$3,300.00)	
			Construction Stockpile STMI		2	Apr 4, 2022	SYSTEM	\$3,300.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$3,300.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0730	MISC. GUARDRAIL	Construction	Stockpile STI	MI - Total			\$3,300.00	
		ITEM	Material		8	Jul 1, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$10,000.00)	
					9	Jul 18, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$10,000.00)	
					10	Aug 2, 2022	SYSTEM	\$10,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$10,000.00)	
					11	Aug 16, 2022	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0073) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$20,000.00)	. ,
					12	Sep 2, 2022	SYSTEM	\$20,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
						12	Sep 2, 2022	SYSTEM	(\$20,000.00)
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0730 -	- Total						\$0.00	
	0740	ITEM	Construction Stockpile		11	Aug 16, 2022	SYSTEM	(\$21,968.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$21,968.00)	
			Construction	Stockpile - To	otal			(\$21,968.00)	
			Construction Stockpile STMI		2	Apr 4, 2022	SYSTEM	\$21,968.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$21,968.00	
			Construction	Stockpile STI	MI - Total			\$21,968.00	
			Material		11	Aug 16, 2022	SYSTEM	\$30,144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0074) due to user vohsr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$30,144.00)	
					12	Sep 2, 2022	SYSTEM	\$30,144.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$30,144.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0740	- Total						\$0.00	
	0750	SUBSTRUCTURE REPAIR (FORMED)	Material		12	Sep 2, 2022	SYSTEM	\$11,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$11,250.00)	
					13	Sep 16, 2022	SYSTEM	\$11,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$11,250.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00 \$0.00	
	0750	- Total	Material - Tota						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4P3009	0760	COATING - CONCRETE	Material			2022			Estimate Item Adjustment (0005) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate.			
		BENTS AND			14	Oct 3, 2022	SYSTEM	(\$1,762.00)				
					15	Oct 17, 2022	SYSTEM	\$1,762.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user raybol1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					15	Oct 17, 2022	SYSTEM	(\$1,762.00)				
				- Total				\$0.00				
			Material - Tota					\$0.00				
	0760 -	- Total						\$0.00				
	0770	CONCRETE	Material		12	Sep 2,	SYSTEM	\$728.00	This adjustment offsets the original system-generated Material Payment			
	0110	FOOTINGS, EMBEDDED	Waterial		12	2022		ψ120.00	Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 72 on the current Payment Estimate.			
					12	Sep 2, 2022	SYSTEM	(\$728.00)				
					13	Sep 16, 2022	SYSTEM	\$728.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 53 on the current Payment Estimate.			
					13	Sep 16, 2022	SYSTEM	(\$728.00)				
				- Total				\$0.00				
			Material - Tota	ıl				\$0.00				
	0770 -	- Total						\$0.00				
	0790	2 IN. PSST POST - 12 GA. Construction Stockpile			11	Aug 16, 2022	SYSTEM	\$311.75	Payment Estimate Item Adjustment generated Stockpile Transaction			
			STMI	- Total				\$311.75				
			Construction	Stockpile STI	VII - Total			\$311.75				
	0790 -	- Total						\$311.75				
	0810	SH-FLAT SHEET	Construction Stockpile STMI		11	Aug 16, 2022	SYSTEM	\$240.30	Payment Estimate Item Adjustment generated Stockpile Transaction			
			- Total Construction Stockpile STMI - Total					\$240.30				
			Construction	Stockpile STI	MI - Total			\$240.30				
	0810 -	- Total						\$240.30				
	0820	ST-STRUCTURAL	Construction Stockpile STMI		11	Aug 16, 2022	SYSTEM	\$1,072.00	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$1,072.00				
			Construction	Stockpile STI	VII - Total			\$1,072.00				
	0820 -	- Total						\$1,072.00				
	0830	SHF-FLAT SHEET FLUORESCENT			11	Aug 16, 2022	SYSTEM	\$196.20	Payment Estimate Item Adjustment generated Stockpile Transaction			
				- Total				\$196.20				
			Construction	Stockpile STI	MI - Total			\$196.20				
	0830 -	- Total						\$196.20				
	0840	CCTV POLE FOUNDATION, 45 FT OR 13.7M MOU	Material		4	May 2, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 13 on the current Payment Estimate.			
		FT OR 13.7M MOU							May 2	SYSTEM	(\$8,500.00)	
					4	May 2, 2022	STSTEW	(40,000.00)				
					5		SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.			
						2022 May 16,		, , ,	Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment			
					5	2022 May 16, 2022 May 16,	SYSTEM	\$8,500.00	Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment			
					5	2022 May 16, 2022 May 16, 2022 Jun 1,	SYSTEM	\$8,500.00 (\$8,500.00)	Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment			



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3009	0840	CCTV POLE FOUNDATION, 45	Material		7	Jun 16, 2022	SYSTEM	(\$8,500.00)	
		FT OR 13.7M MOU			8	Jul 1, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$8,500.00)	
					9	Jul 18, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 71 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$8,500.00)	
					10	Aug 2, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vohsr1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$8,500.00)	
					11	Aug 16, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0075) due to user vohsr1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$8,500.00)	
					12	Sep 2, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 74 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$8,500.00)	
					13	Sep 16, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user raybol1 overridding Paymen Estimate Exception 55 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$8,500.00)	
					14	Oct 3, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Paymen Estimate Exception 25 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$8,500.00)	
					15	Oct 17, 2022	SYSTEM	\$8,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Paymen Estimate Exception 19 on the current Payment Estimate.
					15	Oct 17, 2022	SYSTEM	(\$8,500.00)	
				- Total				\$0.00	
	0840 -	Total	Material - Tota					\$0.00 \$0.00	
	0850	CONDUIT, 2 IN., RIGID, IN TRENCH	Material		2	Apr 4, 2022	SYSTEM	\$3,064.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					2	Apr 4, 2022	SYSTEM	(\$3,064.50)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	0850 -	Total						\$0.00	
					13	Sep 16,	SYSTEM	\$8,475.00	This adjustment offsets the original system-generated Material Payment
	0860	CABLE, 6 AWG, 1 CONDUCTOR, POWER	Material		10	2022			Estimate Item Adjustment (0009) due to user raybol1 overridding Paymen Estimate Exception 56 on the current Payment Estimate.
	0860	CONDUCTOR,	Material		13		SYSTEM	(\$8,475.00)	
	0860	CONDUCTOR,	Material			2022 Sep 16,	SYSTEM	(\$8,475.00) \$8,475.00	Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
	0860	CONDUCTOR,	Material		13	2022 Sep 16, 2022 Oct 3,			Estimate Exception 56 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment
	0860	CONDUCTOR,	Material		13	2022 Sep 16, 2022 Oct 3, 2022	SYSTEM	\$8,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Paymen



CABLE, 12- STRAND, SINGLE MOD 13	e original system-generated Material Payment (0010) due to user raybol1 overridding Payment the current Payment Estimate.
POWER	(0010) due to user raybol1 overridding Payment
0860 - Total \$0.00 0870 FIBER OPTIC CABLE, 12-STRAND, SINGLE MOD Material 13 Sep 16, 2022 SYSTEM \$2,825.00 This adjustment offsets the Estimate Item Adjustment (Estimate Exception 57 on the Estimate Item Adjustment offsets the Estimate Item Adjustment (Estimate Item Adjustme	(0010) due to user raybol1 overridding Payment
13 Sep 16, SYSTEM \$2,825.00 This adjustment offsets the Estimate Item Adjustment (Estimate Exception 57 on to	(0010) due to user raybol1 overridding Payment
CABLE, 12- STRAND, SINGLE MOD 13	(0010) due to user raybol1 overridding Payment
13	
2022 Estimate Item Adjustment (
Estimate Exception 27 on t	e original system-generated Material Payment (0008) due to user raybol1 overridding Payment the current Payment Estimate.
14 Oct 3, SYSTEM (\$2,825.00) 2022	
15 Oct 17, SYSTEM \$2,825.00 This adjustment offsets the 2022 Estimate Item Adjustment (e original system-generated Material Payment (0004) due to user raybol1 overridding Payment the current Payment Estimate.
15 Oct 17, 2022 (\$2,825.00)	
- Total \$0.00	
Material - Total \$0.00	
0870 - Total \$0.00	
0890 MISC. ITS Material 4 May 2, SYSTEM \$5,500.00 This adjustment offsets the 2022 SYSTEM Estimate Item Adjustment (e original system-generated Material Payment (0035) due to user vohsr1 overridding Payment the current Payment Estimate.
4 May 2, SYSTEM (\$5,500.00)	·
- Total \$0.00	
Material - Total \$0.00	
0890 - Total \$0.00	
2022 Estimate Item Adjustment (e original system-generated Material Payment (0036) due to user vohsr1 overridding Payment the current Payment Estimate.
4 May 2, SYSTEM (\$6,000.00)	
- Total \$0.00	
Material - Total \$0.00	
0900 - Total \$0.00	
2022 Estimate Item Adjustment (e original system-generated Material Payment (0011) due to user raybol1 overridding Payment the current Payment Estimate.
13 Sep 16, SYSTEM (\$10,500.00)	
2022 Estimate Item Adjustment (e original system-generated Material Payment (0009) due to user raybol1 overridding Payment the current Payment Estimate.
14 Oct 3, SYSTEM (\$10,500.00)	
2022 Estimate Item Adjustment (e original system-generated Material Payment (0005) due to user raybol1 overridding Payment the current Payment Estimate.
15 Oct 17, SYSTEM (\$10,500.00)	
- Total \$0.00	
Material - Total \$0.00	
Material - Total \$0.00 0910 - Total \$0.00	
0910 - Total \$0.00 0930 MISC. ITS Material 2 Apr 4, 2022 SYSTEM \$13,440.00 This adjustment offsets the Estimate Item Adjustment (Estimate Item Adjustment)	e original system-generated Material Payment (0006) due to user vohsr1 overridding Payment ne current Payment Estimate.
0910 - Total \$0.00 0930 MISC. ITS Material 2 Apr 4, 2022 \$13,440.00 This adjustment offsets the Estimate Item Adjustment ((0006) due to user vohsr1 overridding Payment
0910 - Total \$0.00 0930 MISC. ITS Material 2 Apr 4, 2022 \$YSTEM \$13,440.00 This adjustment offsets the Estimate Item Adjustment (Estimate Exception 8 on the Estimate Estimate Exception 8 on the Estimate Estimate Exception 8 on the Estimate	(0006) due to user vohsr1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	0930 -	· Total						\$0.00	
	0960	BRIDGE APPROACH SLAB (MAJOR ROAD)	Material		9	Jul 18, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$45,336.20)	
					10	Aug 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$45,336.20)	
					11	Aug 16, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0076) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$45,336.20)	
					12	Sep 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$45,336.20)	
					13	Sep 16, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$45,336.20)	
					14	Oct 3, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$45,336.20)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	0960 -	· Total						\$0.00	
	0970 DRILI	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$51,220.00)	
					6	Jun 1, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$51,220.00)	
					7	Jun 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$51,220.00)	
					8	Jul 1, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
			3		8	Jul 1, 2022	SYSTEM	(\$51,220.00)	
					9	Jul 18, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$51,220.00)	
					10	Aug 2, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$51,220.00)	·
					11	Aug 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0077) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					11	Aug 16,	SYSTEM	(\$51,220.00)	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
3009	0970	DRILLED SHAFTS	Material			2022				
		(4 FT. 0 IN. DIA.)			12	Sep 2, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	
					12	Sep 2, 2022	SYSTEM	(\$51,220.00)		
					13	Sep 16, 2022	SYSTEM	\$51,220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate.	
					13	Sep 16, 2022	SYSTEM	(\$51,220.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	0970 -	Total						\$0.00		
	0980	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					5	May 16, 2022	SYSTEM	(\$20,544.00)		
					6	Jun 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					6	Jun 1, 2022	SYSTEM	(\$20,544.00)		
					7	Jun 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 18 on the current Payment Estimate.	
					7	Jun 16, 2022	SYSTEM	(\$20,544.00)		
						8	Jul 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$20,544.00)		
					9	Jul 18, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	
					9	Jul 18, 2022	SYSTEM	(\$20,544.00)		
					10	Aug 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.	
					10	Aug 2, 2022	SYSTEM	(\$20,544.00)		
					11	Aug 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0078) due to user vohsr1 overridding Payment Estimate Exception 40 on the current Payment Estimate.	
					11	Aug 16, 2022	SYSTEM	(\$20,544.00)		
					12	Sep 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.	
					12	Sep 2, 2022	SYSTEM	(\$20,544.00)		
					13	Sep 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Paymen Estimate Exception 21 on the current Payment Estimate.	
					13	Sep 16, 2022	SYSTEM	(\$20,544.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	0980 -	Total						\$0.00		
	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material		5	May 16, 2022	SYSTEM	\$13,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					5	May 16, 2022	SYSTEM	(\$13,760.00)		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																
J4P3009	1040	CLASS B CONCRETE (SUBSTRUCTURE)	Material	1,765	6	Jun 1, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.																
		(,			6	Jun 1, 2022	SYSTEM	(\$80,324.00)																	
					7	Jun 16, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 24 on the current Payment Estimate.																
					7	Jun 16, 2022	SYSTEM	(\$80,324.00)	·																
					8	Jul 1, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.																
					8	Jul 1, 2022	SYSTEM	(\$80,324.00)	Estimate Exception 25 on the same in a ginetic Estimate.																
					9	Jul 18, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																
					9	Jul 18, 2022	SYSTEM	(\$80,324.00)	Estimate Exception 44 of the editorial dynamic Estimate.																
					10	Aug 2, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.																
					10	Aug 2, 2022	SYSTEM	(\$80,324.00)																	
					11	Aug 16, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0079) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																
												11	Aug 16, 2022	SYSTEM	(\$80,324.00)										
					12	Sep 2, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.																
								12	Sep 2, 2022	SYSTEM	(\$80,324.00)														
					13	Sep 16, 2022	SYSTEM	\$80,324.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 25 on the current Payment Estimate.																
					13	Sep 16, 2022	SYSTEM	(\$80,324.00)																	
				- Total				\$0.00																	
			Material - Tota	ıl				\$0.00																	
	1040 -	- Total						\$0.00																	
	1050	TYPE D BARRIER	Construction Stockpile		9	Jul 18, 2022	SYSTEM	(\$6,593.71)	Payment Estimate Item Adjustment generated Stockpile Transaction																
				- Total				(\$6,593.71)																	
			Construction	Stockpile - To	otal			(\$6,593.71)																	
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$6,593.71	Payment Estimate Item Adjustment generated Stockpile Transaction																
				- Total				\$6,593.71																	
			Construction	Stockpile STI				\$6,593.71																	
		_	Material		Stockpile of the																9	Jul 18, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$52,020.00)																	
					10	Aug 2, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																
				1	10	Aug 2, 2022	SYSTEM	(\$52,020.00)																	
					11	Aug 16, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0080) due to user vohsr1 overridding Payment Estimate Exception 48 on the current Payment Estimate.																



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
P3009	1050	TYPE D BARRIER	Material		12	Sep 2, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$52,020.00)	
					13	Sep 16, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$52,020.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	1050 -	Total						\$0.00	
	1060	SLAB ON CONCRETE NU- GIRDER	Material		7	Jun 16, 2022	SYSTEM	\$144,235.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					7	Jun 16, 2022	SYSTEM	(\$144,235.20)	
					8	Jul 1, 2022	SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$186,303.80)	
					9	Jul 18, 2022	SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$186,303.80)	
					10	Aug 2, 2022	SYSTEM	\$186,303.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$186,303.80)	
					11	Aug 16, 2022	SYSTEM	\$216,352.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0081) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$216,352.80)	
					12	Sep 2, 2022	SYSTEM	\$240,392.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 56 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$240,392.00)	
					13	Sep 16, 2022	SYSTEM	\$240,392.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$240,392.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
			Other Item Adjustment	SUBI	13	Sep 16, 2022	raybol1	(\$2,120.00)	10% deduct for cost of concrete since the concrete mix used was not the concrete mix specified in the contract.
				SUBI - Total				(\$2,120.00)	
			Other Item Adj	justment - To	tal			(\$2,120.00)	
	1060 -	Total						(\$2,120.00)	
	1080	NU 35, PRESTRESSED CONC NU-GIRDER	Construction Stockpile		7	Jun 16, 2022	SYSTEM	(\$36,307.98)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$36,307.98)	
			Construction S	Stockpile - To				(\$36,307.98)	
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$36,307.98	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$36,307.98	
			Construction S	Stockpile STI	/II - Total			\$36,307.98	
	1080 -	Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J4P3009	1090	REINFORCING STEEL (BRIDGES)	Construction Stockpile		6	Jun 1, 2022	SYSTEM	(\$6,607.60)	Payment Estimate Item Adjustment generated Stockpile Transaction											
				- Total				(\$6,607.60)												
			Construction S	Stockpile - To	otal			(\$6,607.60)												
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$6,607.60	Payment Estimate Item Adjustment generated Stockpile Transaction											
			STIVII	- Total				\$6,607.60												
			Construction S	Stockpile STI	MI - Total			\$6,607.60												
	1090 -	Total						\$0.00												
	1100	REINFORCING STEEL (EPOXY COATED)	Construction Stockpile		5	May 16, 2022	SYSTEM	(\$5,333.75)	Payment Estimate Item Adjustment generated Stockpile Transaction											
		00/(125)			6	Jun 1, 2022	SYSTEM	(\$11,868.91)	Payment Estimate Item Adjustment generated Stockpile Transaction											
				- Total				(\$17,202.66)												
			Construction S	Stockpile - To	otal			(\$17,202.66)												
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$17,202.66	Payment Estimate Item Adjustment generated Stockpile Transaction											
				- Total				\$17,202.66												
			Construction	Stockpile STI	VII - Total			\$17,202.66												
	1100 -	Total						\$0.00												
	1140	VERTICAL DRAIN AT END BENTS	Material		8	Jul 1, 2022	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.											
					8	Jul 1, 2022	SYSTEM	(\$6,000.00)												
				- Total				\$0.00												
			Material - Tota	ĺ				\$0.00												
	1140 -	Total						\$0.00												
	1200		Material		9	Jul 18, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.											
					9	Jul 18, 2022	SYSTEM	(\$45,336.20)												
					10	Aug 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					10	Aug 2, 2022	SYSTEM	(\$45,336.20)												
					11	Aug 16, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0082) due to user vohsr1 overridding Payment Estimate Exception 10 on the current Payment Estimate.											
					11	Aug 16, 2022	SYSTEM	(\$45,336.20)												
					12	Sep 2, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
			18												1	12	Sep 2, 2022	SYSTEM	(\$45,336.20)	
				13	Sep 16, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.												
								13	Sep 16, 2022	SYSTEM	(\$45,336.20)									
					14	Oct 3, 2022	SYSTEM	\$45,336.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					14	Oct 3, 2022	SYSTEM	(\$45,336.20)												
				- Total				\$0.00												
			Material - Tota					\$0.00												
	1200 -	Total						\$0.00												
	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.											



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J4P3009	1210	DRILLED SHAFTS (4 FT. 0 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	(\$43,340.00)															
					6	Jun 1, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 14 on the current Payment Estimate.														
					6	Jun 1, 2022	SYSTEM	(\$43,340.00)															
					7	Jun 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					7	Jun 16, 2022	SYSTEM	(\$43,340.00)															
					8	Jul 1, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
					8	Jul 1, 2022	SYSTEM	(\$43,340.00)															
					9	Jul 18, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.														
					9	Jul 18, 2022	SYSTEM	(\$43,340.00)															
					10	Aug 2, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user vohsr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.														
					10	Aug 2, 2022	SYSTEM	(\$43,340.00)															
					11	Aug 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0083) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.														
														11	Aug 16, 2022	SYSTEM	(\$43,340.00)						
						12	Sep 2, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.													
									12	Sep 2, 2022	SYSTEM	(\$43,340.00)											
						13	Sep 16, 2022	SYSTEM	\$43,340.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 20 on the current Payment Estimate.													
					13	Sep 16, 2022	SYSTEM	(\$43,340.00)															
				- Total				\$0.00															
	4040	T-4-1	Material - Tota	1				\$0.00															
	1210 - 1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		5	May 16, 2022	SYSTEM	\$0.00 \$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.														
								5	May 16, 2022	SYSTEM	(\$20,544.00)	Estimate Endopaid 20 of the different afficient Estimate.											
																					6	Jun 1, 2022	SYSTEM
						6	Jun 1, 2022	SYSTEM	(\$20,544.00)														
					7	Jun 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 21 on the current Payment Estimate.														
					7	Jun 16, 2022	SYSTEM	(\$20,544.00)															
					8	Jul 1, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.														
					8	Jul 1, 2022	SYSTEM	(\$20,544.00)															
					9	Jul 18, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.														



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks		
J4P3009	1220	ROCK SOCKETS (3 FT 6 IN. DIA.)	Material		9	Jul 18, 2022	SYSTEM	(\$20,544.00)			
					10	Aug 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.		
					10	Aug 2, 2022	SYSTEM	(\$20,544.00)			
					11	Aug 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0084) due to user vohsr1 overridding Payment Estimate Exception 42 on the current Payment Estimate.		
					11	Aug 16, 2022	SYSTEM	(\$20,544.00)			
					12	Sep 2, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
					12	Sep 2, 2022	SYSTEM	(\$20,544.00)			
					13	Sep 16, 2022	SYSTEM	\$20,544.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 23 on the current Payment Estimate.		
					13	Sep 16, 2022	SYSTEM	(\$20,544.00)			
				- Total				\$0.00			
			Material - Tota					\$0.00			
	1220 -	Total						\$0.00			
	1280	CLASS B CONCRETE (SUBSTRUCTURE)	Material		5	May 16, 2022	SYSTEM	\$13,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.		
					5	May 16, 2022	SYSTEM	(\$13,920.00)			
							6	Jun 1, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$80,127.00)			
					7	Jun 16, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		
					7	Jun 16, 2022	SYSTEM	(\$80,127.00)			
					8	Jul 1, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user vohsr1 overridding Payment Estimate Exception 31 on the current Payment Estimate.		
					8	Jul 1, 2022	SYSTEM	(\$80,127.00)			
					9	Jul 18, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
					9	Jul 18, 2022	SYSTEM	(\$80,127.00)			
					10	Aug 2, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.		
					10	Aug 2, 2022	SYSTEM	(\$80,127.00)			
					11	Aug 16, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0085) due to user vohsr1 overridding Payment Estimate Exception 46 on the current Payment Estimate.		
					11	Aug 16, 2022	SYSTEM	(\$80,127.00)			
					12	Sep 2, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.		
					12	Sep 2, 2022	SYSTEM	(\$80,127.00)			
					13	Sep 16, 2022	SYSTEM	\$80,127.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 27 on the current Payment Estimate.		



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks														
J4P3009	1280	CLASS B CONCRETE	Material	,,	13	Sep 16, 2022	SYSTEM	(\$80,127.00)															
		(SUBSTRUCTURE)		- Total				\$0.00															
			Material - Tota					\$0.00															
	1280 -	Total						\$0.00															
	1290	TYPE D BARRIER	Construction Stockpile		9	Jul 18, 2022	SYSTEM	(\$6,593.71)	Payment Estimate Item Adjustment generated Stockpile Transaction														
				- Total				(\$6,593.71)															
			Construction S	Stockpile - To	otal			(\$6,593.71)															
			Construction Stockpile		4	May 2, 2022	SYSTEM	\$6,593.71	Payment Estimate Item Adjustment generated Stockpile Transaction														
			STMI	- Total				\$6,593.71															
			Construction S	Stockpile STI	MI - Total			\$6,593.71															
			Material		9	Jul 18, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.														
					9	Jul 18, 2022	SYSTEM	(\$52,020.00)															
							10	Aug 2, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user vohsr1 overridding Payment Estimate Exception 41 on the current Payment Estimate.												
						10	Aug 2, 2022	SYSTEM	(\$52,020.00)														
					11	Aug 16, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0086) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.														
								11	Aug 16, 2022	SYSTEM	(\$52,020.00)												
								12	Sep 2, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 54 on the current Payment Estimate.											
							12	Sep 2, 2022	SYSTEM	(\$52,020.00)													
					13	Sep 16, 2022	SYSTEM	\$52,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 31 on the current Payment Estimate.														
					13	Sep 16, 2022	SYSTEM	(\$52,020.00)															
				- Total	Total			\$0.00															
			Material - Tota					\$0.00															
	1290 -							\$0.00															
	1300	SLAB ON CONCRETE NU- GIRDER			7	Jun 16, 2022	SYSTEM	(\$16,335.42)	Payment Estimate Item Adjustment generated Stockpile Transaction														
		5521																	8	Jul 1, 2022	SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction
					11	Aug 16, 2022	SYSTEM	(\$1,815.05)	Payment Estimate Item Adjustment generated Stockpile Transaction														
				- Total				(\$36,300.94)															
			Construction S	Stockpile - To				(\$36,300.94)															
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$36,300.94	Payment Estimate Item Adjustment generated Stockpile Transaction														
				- Total				\$36,300.94															
			Construction S	Stockpile STI			a. (= =	\$36,300.94															
			Material		7	Jun 16, 2022	SYSTEM	\$108,176.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.														
					7 8		7	Jun 16, 2022	SYSTEM	(\$108,176.40)													
							8	Jul 1, 2022	SYSTEM	\$228,372.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.												
										8	Jul 1, 2022	SYSTEM	(\$228,372.40)										
					9	Jul 18,	SYSTEM	\$228,372.40	This adjustment offsets the original system-generated Material Payment														



	1				_				
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1300	SLAB ON CONCRETE NU-	Material			2022			Estimate Item Adjustment (0025) due to user vohsr1 overridding Payment Estimate Exception 61 on the current Payment Estimate.
		GIRDER			9	Jul 18, 2022	SYSTEM	(\$228,372.40)	
					10	Aug 2, 2022	SYSTEM	\$228,372.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user vohsr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$228,372.40)	
					11	Aug 16, 2022	SYSTEM	\$240,392.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0087) due to user vohsr1 overridding Payment Estimate Exception 54 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$240,392.00)	Estimate Escopean of the descent algorithms and the second of the second
					12	Sep 2, 2022	SYSTEM	\$240,392.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr¹ overridding Payment Estimate Exception 58 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$240,392.00)	Estimate Escopios of the cancel agreement agreement.
					13	Sep 16, 2022	SYSTEM	\$240,392.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user raybol1 overridding Payment Estimate Exception 35 on the current Payment Estimate.
				13	Sep 16, 2022	SYSTEM	(\$240,392.00)	Examinate Exception of the following agricult agricult Estimate.	
				- Total		2022		\$0.00	
		00 - Total	Material - Total					\$0.00	
	1300 -		Material - Tota	al - Total				\$0.00	
	1330	REINFORCING	Construction		6	Jun 1,	SYSTEM	(\$5,063.80)	Payment Estimate Item Adjustment generated Stockpile Transaction
	1000	STEEL (BRIDGES)	Stockpile	- Total			OTOTEM	(\$5,063.80)	Tayloric Edinate Ion / Agadinate generated election / Tarloadator
			Construction S		Total			(\$5,063.80)	
			Construction Stockpile	зюскрие - то	4	May 2, 2022	SYSTEM	\$5,063.80	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$5,063.80	
			Construction S	Stockpile STI	MI - Total			\$5,063.80	
	1330 -	· Total						\$0.00	
	1380	VERTICAL DRAIN AT END BENTS	Material		8	Jul 1, 2022	SYSTEM	\$6,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					8	Jul 1, 2022	SYSTEM	(\$6,000.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1380 -	· Total						\$0.00	
	1440	MECHANICALLY STABILIZED	Construction Stockpile		5	May 16, 2022	SYSTEM	(\$777.26)	Payment Estimate Item Adjustment generated Stockpile Transaction
		EARTH WALL SYS			6	Jun 1, 2022	SYSTEM	(\$86.36)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$863.62)	
			Construction S	Stockpile - To	otal			(\$863.62)	
			Construction Stockpile No		4	May 2, 2022	SYSTEM	\$863.62	Payment Estimate Item Adjustment generated Stockpile Transaction
			Transaction Type	- Total				\$863.62	
			Construction S	Stockpile No	Transacti	on Type -	Total	\$863.62	
			Material		5	May 16, 2022	SYSTEM	\$252,147.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					5	May 16, 2022	SYSTEM	(\$252,147.60)	
					6	Jun 1, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					6	Jun 1,	SYSTEM	(\$280,164.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																							
J4P3009	1440	MECHANICALLY	Material			2022																										
		STABILIZED EARTH WALL SYS			7	Jun 16, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																							
					7	Jun 16, 2022	SYSTEM	(\$280,164.00)																								
					8	Jul 1, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user vohsr1 overridding Payment Estimate Exception 44 on the current Payment Estimate.																							
					8	Jul 1, 2022	SYSTEM	(\$280,164.00)																								
					9	Jul 18, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user vohsr1 overridding Payment Estimate Exception 65 on the current Payment Estimate.																							
					9	Jul 18, 2022	SYSTEM	(\$280,164.00)																								
					10	Aug 2, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user vohsr1 overridding Payment Estimate Exception 50 on the current Payment Estimate.																							
					10	Aug 2, 2022	SYSTEM	(\$280,164.00)																								
					11	Aug 16, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0088) due to user vohsr1 overridding Payment Estimate Exception 56 on the current Payment Estimate.																							
							12	11	Aug 16, 2022	SYSTEM	(\$280,164.00)																					
											12	Sep 2, 2022	SYSTEM	\$280,164.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user vohsr1 overridding Payment Estimate Exception 61 on the current Payment Estimate.																	
												12	Sep 2, 2022	SYSTEM	(\$280,164.00)																	
								2022 Estima	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user raybol1 overridding Payment Estimate Exception 38 on the current Payment Estimate.																							
					13	Sep 16, 2022	SYSTEM	(\$280,164.00)																								
				- Total				\$0.00																								
			Material - Tota	ı				\$0.00																								
		Total						\$0.00																								
	1470	MECHANICALLY STABILIZED EARTH WALL SYS	Construction Stockpile		5	May 16, 2022	SYSTEM	(\$863.61)	Payment Estimate Item Adjustment generated Stockpile Transaction																							
		EARTH WALL 313		- Total				(\$863.61)																								
			Construction S	Stockpile - To	otal			(\$863.61)																								
			Construction Stockpile STMI		4	May 2, 2022	SYSTEM	\$863.61	Payment Estimate Item Adjustment generated Stockpile Transaction																							
			CTIVII	- Total				\$863.61																								
			Construction S	Stockpile STI	MI - Total			\$863.61																								
			Material																							5	May 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 36 on the current Payment Estimate.		
					5	May 16, 2022	SYSTEM	(\$256,650.00)																								
					6	6											6	6	6		6	6	6	6				6	Jun 1, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
																									6	Jun 1, 2022	SYSTEM	(\$256,650.00)				
																												7	Jun 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 43 on the current Payment Estimate.
								7	Jun 16, 2022	SYSTEM	(\$256,650.00)																					
					8	Jul 1, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user vohsr1 overridding Payment Estimate Exception 47 on the current Payment Estimate.																							
					8	Jul 1,	SYSTEM	(\$256,650.00)																								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	1470	MECHANICALLY	Material			2022			
		STABILIZED EARTH WALL SYS			9	Jul 18, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user vohsr1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$256,650.00)	
					10	Aug 2, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user vohsr1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$256,650.00)	
					11	Aug 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0089) due to user vohsr1 overridding Payment Estimate Exception 58 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$256,650.00)	
					12	Sep 2, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user vohsr1 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$256,650.00)	
					13	Sep 16, 2022	SYSTEM	\$256,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user raybol1 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$256,650.00)	
	1470 - Total		- Total				\$0.00		
		Material - Tota				\$0.00			
		- Total						\$0.00	
	5005	POST ANCHOR FOR 2 IN. PSST - 7	Construction Stockpile		14	Oct 3, 2022	SYSTEM	(\$151.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
		GA.		- Total				(\$151.20)	
			Construction S	Stockpile - Total				(\$151.20)	
			Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$151.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI						
				- Total				\$151.20	
			Construction S		VII - Total			\$151.20 \$151.20	
			Construction S Material		MI - Total	Oct 3, 2022	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
							SYSTEM	\$151.20	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment
					14	2022 Oct 3,		\$151.20 \$393.78	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment
					14	2022 Oct 3, 2022 Oct 17,	SYSTEM	\$151.20 \$393.78 (\$393.78)	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment
			Material	Stockpile STI	14 14 15	Oct 3, 2022 Oct 17, 2022 Oct 17,	SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment
				Stockpile STI	14 14 15	Oct 3, 2022 Oct 17, 2022 Oct 17,	SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78)	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment
	5005 -	- Total	Material	Stockpile STI	14 14 15	Oct 3, 2022 Oct 17, 2022 Oct 17,	SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment
	5005 + 5006	- Total 2.5 IN. PSST POST - 12 GA.	Material	Stockpile STI	14 14 15	Oct 3, 2022 Oct 17, 2022 Oct 17,	SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00 \$0.00 \$0.00 (\$1,163.80)	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment
		2.5 IN. PSST POST	Material - Tota Construction Stockpile	- Total - Total	14 14 15 15	2022 Oct 3, 2022 Oct 17, 2022 Oct 17, 2022 Oct 3,	SYSTEM SYSTEM SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00 \$0.00 (\$1,163.80)	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		2.5 IN. PSST POST	Material - Tota Construction Stockpile Construction S	- Total - Total	14 14 15 15	2022 Oct 3, 2022 Oct 17, 2022 Oct 17, 2022 Oct 3, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00 \$0.00 (\$1,163.80) (\$1,163.80)	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction
		2.5 IN. PSST POST	Material - Tota Construction Stockpile	- Total - Total - Total Stockpile - To	14 14 15 15	2022 Oct 3, 2022 Oct 17, 2022 Oct 17, 2022 Oct 3,	SYSTEM SYSTEM SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00 \$0.00 (\$1,163.80) (\$1,163.80) \$1,163.80	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
		2.5 IN. PSST POST	Material - Tota Construction Stockpile Construction Stockpile STMI	- Total - Total Stockpile - Total - Total	14 15 15 15 14 14 11	2022 Oct 3, 2022 Oct 17, 2022 Oct 17, 2022 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00 \$0.00 (\$1,163.80) (\$1,163.80) \$1,163.80	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction
		2.5 IN. PSST POST	Material - Tota Construction Stockpile Construction Stockpile	- Total - Total Stockpile - Total - Total	14 15 15 15 14 14 11	2022 Oct 3, 2022 Oct 17, 2022 Oct 17, 2022 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00 \$0.00 (\$1,163.80) (\$1,163.80) \$1,163.80	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction
		2.5 IN. PSST POST	Material - Tota Construction Stockpile Construction Stockpile STMI	- Total - Total Stockpile - Total - Total	14 15 15 15 14 14 11	2022 Oct 3, 2022 Oct 17, 2022 Oct 17, 2022 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00 \$0.00 (\$1,163.80) (\$1,163.80) \$1,163.80	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction
		2.5 IN. PSST POST	Material - Total Construction Stockpile Construction Stockpile STMI Construction S	- Total - Total Stockpile - Total - Total	14 14 15 15 14 14 11 11 11 11 11 11	2022 Oct 3, 2022 Oct 17, 2022 Oct 17, 2022 Aug 16, 2022 Oct 3,	SYSTEM SYSTEM SYSTEM SYSTEM	\$151.20 \$393.78 (\$393.78) \$393.78 (\$393.78) \$0.00 \$0.00 (\$1,163.80) (\$1,163.80) \$1,163.80 \$1,163.80	Estimate Item Adjustment (0002) due to user raybol1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate. Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009	5006	2.5 IN. PSST POST - 12 GA.	Material			2022			Estimate Item Adjustment (0008) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Oct 17, 2022	SYSTEM	(\$3,091.20)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
	5006 -	· Total						\$0.00	
	5007	POST ANCHOR FOR 2.5 IN. PSST -			14	Oct 3, 2022	SYSTEM	(\$681.60)	Payment Estimate Item Adjustment generated Stockpile Transaction
		7 GA.		- Total				(\$681.60)	
			Construction S	Stockpile - To	tal			(\$681.60)	
			Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$681.60	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$681.60	
			Construction S	Stockpile STI	/II - Total			\$681.60	
			Material		14	Oct 3, 2022	SYSTEM	\$1,883.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$1,883.76)	
					15	Oct 17, 2022	SYSTEM	\$1,883.76	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user raybol1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					15	Oct 17, 2022	SYSTEM	(\$1,883.76)	
				- Total				\$0.00	
			Material - Tota	l				\$0.00	
	5007 -	Total						\$0.00	
	5008	BREAKAWAY ASSEMBLY (PERFORATED	Construction Stockpile		14	Oct 3, 2022	SYSTEM	(\$2,217.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
		SQUARE STEEL TUBE)		- Total				(\$2,217.20)	
			Construction	Stockpile - To	ital			(\$2,217.20)	
			Construction Stockpile STMI		11	Aug 16, 2022	SYSTEM	\$2,217.20	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,217.20	
			Construction S	Stockpile STI				\$2,217.20	
			Material		14	Oct 3, 2022	SYSTEM	\$4,326.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user raybol1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$4,326.00)	
					15	Oct 17, 2022	SYSTEM	\$4,326.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					15	Oct 17, 2022	SYSTEM	(\$4,326.00)	
				- Total				\$0.00	
			Material - Tota	l e				\$0.00	
		· Total						\$0.00	
J4P3009 -								\$60,402.31	
J4P3009B	1500	COMPACTING EMBANKMENT	Material		13	Sep 16, 2022	SYSTEM	\$4,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$4,680.00)	
					14	Oct 3, 2022	SYSTEM	\$4,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$4,680.00)	
					15	Oct 17, 2022	SYSTEM	\$4,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user raybol1 overridding Payment Estimate Exception 1 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J4P3009B	1500	COMPACTING EMBANKMENT	Material		15	Oct 17, 2022	SYSTEM	(\$4,680.00)							
				- Total				\$0.00							
			Material - Tota	l				\$0.00							
	1500 -	Total						\$0.00							
	1520	TYPE 5 AGGREGATE FOR BASE	Material		12	Sep 2, 2022	SYSTEM	\$4,556.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					12	Sep 2, 2022	SYSTEM	(\$4,556.00)							
				- Total				\$0.00							
			Material - Tota	1				\$0.00							
	1520 -	Total						\$0.00							
	1530	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	Material		11	Aug 16, 2022	SYSTEM	\$2,704.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0090) due to user vohsr1 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					11	Aug 16, 2022	SYSTEM	(\$2,704.00)							
					12	Sep 2, 2022	SYSTEM	\$6,944.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					12	Sep 2, 2022	SYSTEM	(\$6,944.00)							
				- Total				\$0.00							
			Material - Total				\$0.00								
	1530 -	Total						\$0.00							
	1540	- Total MISC.	Material		4	May 2, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
											4	May 2, 2022	SYSTEM	(\$2,688.00)	
						5	May 16, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					5	May 16, 2022	SYSTEM	(\$2,688.00)							
					6	Jun 1, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user vohsr1 overridding Payment Estimate Exception 6 on the current Payment Estimate.						
					6	Jun 1, 2022	SYSTEM	(\$2,688.00)							
					7	Jun 16, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 7 on the current Payment Estimate.						
					7	Jun 16, 2022	SYSTEM	(\$2,688.00)							
					8	Jul 1, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					8	Jul 1, 2022	SYSTEM	(\$2,688.00)							
					9	Jul 18, 2022	SYSTEM	\$2,688.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user vohsr1 overridding Payment Estimate Exception 8 on the current Payment Estimate.						
					9	Jul 18, 2022	SYSTEM	(\$2,688.00)							
				- Total				\$0.00							
			Material - Tota					\$0.00							
	1540 -	Total						\$0.00							
	1550	MISC.	Material		13	Sep 16, 2022	SYSTEM	\$42,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.						
					13	Sep 16, 2022	SYSTEM	(\$42,680.00)							
					14	Oct 3,	SYSTEM	\$42,680.00	This adjustment offsets the original system-generated Material Payment						



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3009B	1550	MISC.	Material			2022			Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					14	Oct 3, 2022	SYSTEM	(\$42,680.00)		
					15	Oct 17, 2022	SYSTEM	\$42,680.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user raybol1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	
					15	Oct 17, 2022	SYSTEM	(\$42,680.00)		
				- Total				\$0.00		
	1550 -	Total	Material - Tota	<u> </u>				\$0.00		
	1560	ASPHALTIC	Other Item	ACAD	15	Oct 17,	raybol1	\$0.00 \$14,291.60	AC Price Adjustment for Line 1560 for September 2022.	
	1500	CONCRETE MIXTURE PG 70-22 (SP125C	Adjustment	AOAD	15	2022 Oct 17,	raybol1	\$8,146.25	AC Price Adjustment for Line 1560 for September 2022.	
		MIX)		ACAD To	-	2022	1		,	
			Othor Hore And	ACAD - Tota				\$22,437.85		
	1560 -	Total	Other Item Ad	usument - 10	rtai			\$22,437.85 \$22,437.85		
	1590	PIPE COLLAR, TYPE A	Material		13	Sep 16, 2022	SYSTEM	\$1,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					13	Sep 16, 2022	SYSTEM	(\$1,400.00)	Estimate Exception o on the current Payment Estimate.	
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1590 -	Total						\$0.00		
	1600	CONCRETE MEDIAN	Material		12	Sep 2, 2022	SYSTEM	\$22,470.54	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user vohsr1 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					12	Sep 2, 2022	SYSTEM	(\$22,470.54)		
					13	Sep 16, 2022	SYSTEM	\$28,238.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
						13	Sep 16, 2022	SYSTEM	(\$28,238.94)	
					14	Oct 3, 2022	SYSTEM	\$28,238.94	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					14	Oct 3, 2022	SYSTEM	(\$28,238.94)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1600 -	Total						\$0.00		
	1610	CONCRETE CURB RAMP	Material		13	Sep 16, 2022	SYSTEM	\$29,183.01	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user raybol1 overridding Payment Estimate Exception 12 on the current Payment Estimate.	
					13	Sep 16, 2022	SYSTEM	(\$29,183.01)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1610 -							\$0.00		
	1620	TRUNCATED DOMES	Material		15	Oct 17, 2022	SYSTEM	\$6,989.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user raybol1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					15	Oct 17, 2022	SYSTEM	(\$6,989.40)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1620 -							\$0.00		
	1640	CONCRETE SIDEWALK, 4 IN.	Material		11	Aug 16, 2022	SYSTEM	\$15,574.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0091) due to user vohsr1 overridding Payment	



						_			
ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
)9B	1640	CONCRETE	Material						Estimate Exception 25 on the current Payment Estimate.
		SIDEWALK, 4 IN.			11	Aug 16,	SYSTEM	(\$15,574.20)	
					12	2022 Sep 2,	SYSTEM	\$15,574.20	This adjustment offsets the original system-generated Material Payment
						2022			Estimate Item Adjustment (0035) due to user vohsr1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$15,574.20)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	1640 -	Total						\$0.00	
	1650	CONCRETE CURB (6 IN. HEIGHT AND UNDER)	Material		11	Aug 16, 2022	SYSTEM	\$12,162.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0092) due to user vohsr1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$12,162.15)	
					12	Sep 2, 2022	SYSTEM	\$31,046.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$31,046.40)	
					13	Sep 16, 2022	SYSTEM	\$31,046.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$31,046.40)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1650 -	Total						\$0.00	
	1660	CURB AND GUTTER TYPE B	Material		9	Jul 18, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user vohsr1 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					9	Jul 18, 2022	SYSTEM	(\$19,733.15)	
					10	Aug 2, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user vohsr1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Aug 2, 2022	SYSTEM	(\$19,733.15)	
					11	Aug 16, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0093) due to user vohsr1 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$19,733.15)	
					12	Sep 2, 2022	SYSTEM	\$19,733.15	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user vohsr1 overridding Payment Estimate Exception 32 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$19,733.15)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
	1660 -	Total						\$0.00	
	1700	MISC. PAVED DRAINAGE	Material		12	Sep 2, 2022	SYSTEM	\$7,477.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$7,477.80)	
					13	Sep 16, 2022	SYSTEM	\$16,129.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$16,129.80)	
				- Total				\$0.00	
			Material - Tota	ı				\$0.00	
- 1		Total						\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J4P3009B	1710	CURVED VANE GRTE AND FRAME(2 FT. X 2	Material		13	Sep 16, 2022	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate.	
		FT)			13	Sep 16, 2022	SYSTEM	(\$1,050.00)		
					14	Oct 3, 2022	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					14	Oct 3, 2022	SYSTEM	(\$1,050.00)		
					15	Oct 17, 2022	SYSTEM	\$1,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user raybol1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	
					15	Oct 17, 2022	SYSTEM	(\$1,050.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1710 -	Total						\$0.00		
	1720	MANHOLE FRAME AND COVER, TYPE 4	Material		13	Sep 16, 2022	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.	
					13	Sep 16, 2022	SYSTEM	(\$750.00)		
					14	Oct 3, 2022	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					14	Oct 3, 2022	SYSTEM	(\$750.00)		
					15	Oct 17, 2022	SYSTEM	\$750.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user raybol1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					15	Oct 17, 2022	SYSTEM	(\$750.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1720 -	Total						\$0.00		
	1880	TEMPORARY NON-REMOVABLE TAPE LT/RT ARROW	Material		4	May 2, 2022	SYSTEM	\$920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user vohsr1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					4	May 2, 2022	SYSTEM	(\$920.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1880 -	Total						\$0.00		
	1990	PRECAST CONCRETE MANHOLE - 48 IN.	Material		13	Sep 16, 2022	SYSTEM	\$4,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user raybol1 overridding Payment Estimate Exception 42 on the current Payment Estimate.	
					13	Sep 16, 2022	SYSTEM	(\$4,375.00)		
							14	Oct 3, 2022	SYSTEM	\$4,375.00
					14	Oct 3, 2022	SYSTEM	(\$4,375.00)		
					15	Oct 17, 2022	SYSTEM	\$4,375.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user raybol1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					15	Oct 17, 2022	SYSTEM	(\$4,375.00)		
				- Total				\$0.00		
			Material - Tota					\$0.00		
	1990 -	Total						\$0.00		
	2000	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material		13	Sep 16, 2022	SYSTEM	\$4,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user raybol1 overridding Payment Estimate Exception 43 on the current Payment Estimate.	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4P3009B	2000	PRECAST CONCRETE DROP	Material		13	Sep 16, 2022	SYSTEM	(\$4,650.00)	
		INLET 2 FT X 2 FT			14	Oct 3, 2022	SYSTEM	\$4,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$4,650.00)	
					15	Oct 17, 2022	SYSTEM	\$4,650.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user raybol1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Oct 17, 2022	SYSTEM	(\$4,650.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	2000 -							\$0.00	
	2020	30 IN. GROUP A FLARED END SECT	Material		13	Sep 16, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user raybol1 overridding Payment Estimate Exception 44 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$2,500.00)	
					14	Oct 3, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$2,500.00)	
					15	Oct 17, 2022	SYSTEM	\$2,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user raybol1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					15	Oct 17, 2022	SYSTEM	(\$2,500.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	2020 -	· Total						\$0.00	
	2070	CURB INLET CHECK			13	Sep 16, 2022	SYSTEM	\$315.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user raybol1 overridding Payment Estimate Exception 45 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$315.00)	
				- Total					
			Material - Tota	l e				\$0.00	
	2070 -	Total						\$0.00	
	2200	CABLE, 8 AWG 1 CONDUCTOR	Material		6	Jun 1, 2022	SYSTEM	\$1,140.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user vohsr1 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					6	Jun 1, 2022	SYSTEM	(\$1,140.00)	
				- Total				\$0.00	
			Material - Tota					\$0.00	
	2200 -							\$0.00	
	2250	MISC. HIGHWAY LIGHTING	Material		11	Aug 16, 2022	SYSTEM	\$2,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0094) due to user vohsr1 overridding Payment Estimate Exception 60 on the current Payment Estimate.
					11	Aug 16, 2022	SYSTEM	(\$2,400.00)	
					12	Sep 2, 2022	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user vohsr1 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$4,800.00)	
					13	Sep 16, 2022	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user raybol1 overridding Payment Estimate Exception 46 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$4,800.00)	
					14	Oct 3,	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment



oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
23009B	2250	MISC. HIGHWAY LIGHTING	Material			2022			Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$4,800.00)	
					15	Oct 17, 2022	SYSTEM	\$4,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user raybol1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					15	Oct 17, 2022	SYSTEM	(\$4,800.00)	
				- Total				\$0.00	
	0050		Material - Tota	ıl				\$0.00	
	2250 -				40	0 0	OVOTELL	\$0.00	
	2320	SH-FLAT SHEET - SIGNAL SIGN	Material		12	Sep 2, 2022	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user vohsr1 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$3,360.00)	
					13	Sep 16, 2022	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user raybol1 overridding Payment Estimate Exception 48 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$3,360.00)	
					14	Oct 3, 2022	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Paymen Estimate Exception 18 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$3,360.00)	
					15	Oct 17, 2022	SYSTEM	\$3,360.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user raybol1 overridding Paymen Estimate Exception 12 on the current Payment Estimate.
					15	Oct 17, 2022	SYSTEM	(\$3,360.00)	
				- Total				\$0.00	
			Material - Tota	Material - Total				\$0.00	
	2320 -	- Total						\$0.00	
	2360	POST, TYPE C, 50 FT. ARM OR 15.2 M ARM	Material		12	Sep 2, 2022	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user vohsr1 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					12	Sep 2, 2022	SYSTEM	(\$15,000.00)	
					13	Sep 16, 2022	SYSTEM	\$15,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user raybol1 overridding Paymen Estimate Exception 49 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$15,000.00)	
					14	Oct 3, 2022	SYSTEM	\$15,000.00	This adjustment offerts the original system apparets d Material Decement
						2022			This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user raybol1 overridding Paymen Estimate Exception 19 on the current Payment Estimate.
					14	Oct 3, 2022	SYSTEM	(\$15,000.00)	Estimate Item Adjustment (0022) due to user raybol1 overridding Paymen
					14	Oct 3,	SYSTEM SYSTEM	(\$15,000.00) \$15,000.00	Estimate Item Adjustment (0022) due to user raybol1 overridding Paymen Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment
						Oct 3, 2022 Oct 17,			Estimate Item Adjustment (0022) due to user raybol1 overridding Paymen Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Paymen
				- Total	15	Oct 3, 2022 Oct 17, 2022	SYSTEM	\$15,000.00	Estimate Item Adjustment (0022) due to user raybol1 overridding Payment Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment
			Material - Tota		15	Oct 3, 2022 Oct 17, 2022	SYSTEM	\$15,000.00 (\$15,000.00) \$0.00	Estimate Item Adjustment (0022) due to user raybol1 overridding Paymen Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Paymen
	2360 -				15	Oct 3, 2022 Oct 17, 2022	SYSTEM	\$15,000.00 (\$15,000.00)	Estimate Item Adjustment (0022) due to user raybol1 overridding Paymen Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment
	2360 - 2470	-Total BASE, CONCRETE			15	Oct 3, 2022 Oct 17, 2022	SYSTEM	\$15,000.00 (\$15,000.00) \$0.00	Estimate Item Adjustment (0022) due to user raybol1 overridding Paymen Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Paymen
					15	Oct 3, 2022 Oct 17, 2022 Oct 17, 2022 Sep 2,	SYSTEM	\$15,000.00 (\$15,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0022) due to user raybol1 overridding Paymen Estimate Exception 19 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user raybol1 overridding Payment Estimate Exception 13 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user vohsr1 overridding Payment Estimate Item Adjustment (0042) due to user vohsr1 overridding Payment



L	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
B 2	2470	BASE, CONCRETE	Material		13	Sep 16, 2022	SYSTEM	(\$13,000.00)	
				- Total				\$0.00	
			Material - Tota	ıl				\$0.00	
2	470 -	Total						\$0.00	
	2530	2 IN. PSST POST -	Construction		11	Aug 16,	SYSTEM	\$1,967.25	Payment Estimate Item Adjustment generated Stockpile Transaction
	.550	12 GA.	Stockpile STMI	- Total	"	2022	OTOTEM	\$1,967.25	T ayrient Estimate fem Adjustment generated stockpile Transaction
			Construction		MI Total			\$1,967.25	
0	500	Total	Construction	Stockpile STI	vii - Totai			<u> </u>	
	2530 -		-					\$1,967.25	
2	2540	SH-FLAT SHEET	Construction Stockpile STMI	Total	11	Aug 16, 2022	SYSTEM	\$596.30	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$596.30	
			Construction	Stockpile STI	MI - Total			\$596.30	
2	540 -	Total						\$596.30	
2	2550	ST-STRUCTURAL	Construction Stockpile STMI		11	Aug 16, 2022	SYSTEM	\$4,261.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			2	- Total				\$4,261.00	
			Construction	Stockpile STI	MI - Total			\$4,261.00	
2	550 -	Total						\$4,261.00	
2	2560	SHF-FLAT SHEET FLUORESCENT	Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$196.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$196.20	
			Construction	Stockpile STI	MI - Total			\$196.20	
2	560 -	Total						\$196.20	
5	5009	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$263.55	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$263.55	
			Construction Stockpile STMI - Total					\$263.55	
5	009 -	Total						\$263.55	
	5010	POST ANCHOR FOR 2 IN. PSST - 7 GA.	Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$529.20	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$529.20	
			Construction	Stockpile ST	ockpile STMI - Total				
5	010 -	Total						\$529.20 \$529.20	
		2.5 IN. PSST POST - 12 GA.	Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$341.55	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$341.55	
			Construction		MI - Total			\$341.55	
E	011	Total ————	- Sonoti di Gilotti		. Johan			\$341.55	
	011 -	POST ANCHOR FOR 2.5 IN. PSST -	Construction Stockpile		11	Aug 16, 2022	SYSTEM	\$170.40	Payment Estimate Item Adjustment generated Stockpile Transaction
		7 GA.		- Total				\$170.40	
			Construction		MI - Total			\$170.40	
	012	Construction Stockpile STMI - Total							
	012 -	Total MISC.	Material		12	Sep 2, 2022	SYSTEM	\$170.40 \$1,001.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user vohsr1 overridding Paymen
					12	Sep 2,	SYSTEM	(\$1,001.74)	Estimate Exception 71 on the current Payment Estimate.
						2022		(, ,==)	
					13	Sep 16, 2022	SYSTEM	\$1,001.74	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user raybol1 overridding Payment Estimate Exception 52 on the current Payment Estimate.
					13	Sep 16, 2022	SYSTEM	(\$1,001.74)	
				- Total				\$0.00	
			Material - Tota					\$0.00	





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4P3009B	5014	MISC.	Material		12	Sep 2, 2022	SYSTEM	\$1,480.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user vohsr1 overridding Payment Estimate Exception 73 on the current Payment Estimate.													
					12	Sep 2, 2022	SYSTEM	(\$1,480.50)														
					13	Sep 16, 2022	SYSTEM	\$1,480.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user raybol1 overridding Payment Estimate Exception 54 on the current Payment Estimate.													
					13	Sep 16, 2022	SYSTEM	(\$1,480.50)														
				- Total				\$0.00														
			Material - Total					\$0.00														
	5014 -	Total						\$0.00														
	5015	MISC. HIGHWAY LIGHTING	Material		12	Sep 2, 2022	SYSTEM	\$4,158.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user vohsr1 overridding Payment Estimate Exception 66 on the current Payment Estimate.													
					12	Sep 2, 2022	SYSTEM	(\$4,158.00)														
					13	Sep 16, 2022	SYSTEM	\$4,158.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user raybol1 overridding Payment Estimate Exception 47 on the current Payment Estimate.													
					13	Sep 16, 2022	SYSTEM	(\$4,158.00)														
					14	Oct 3, 2022	SYSTEM	\$4,158.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user raybol1 overridding Payment Estimate Exception 17 on the current Payment Estimate.													
																		14	Oct 3, 2022	SYSTEM	(\$4,158.00)	
						15	Oct 17, 2022	SYSTEM	\$4,158.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user raybol1 overridding Payment Estimate Exception 11 on the current Payment Estimate.												
					15	Oct 17, 2022	SYSTEM	(\$4,158.00)														
				- Total				\$0.00														
			Material - Tota					\$0.00														
	5015 -	Total						\$0.00														
J4P3009B	- Total							\$30,763.30														
Overall - T	otal							\$91,165.61														