

# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 17, 2022

\$2,973,711.26 \$5,300.00 \$2,979,011.26	9	eriod Start October 1, 20 eriod End October 15, 2	211015-C04 Ideker, Inc.	e Number Contract ID Prime Contractor		Progress Estimate Number 7		
By User						Approval Date		
yostj1	d Draft) at the Project Office Level by	Generated and Approved (and should be considered Draft) at the Project Office Level by						
yostj1	ft) at the Resident Engineer Level by	nd should be considered Dra	ewed and Appro	Revi		October 18, 2022		
ramses1	tral Office Controllers Office Level by	ed and Approved at the Cer				October 18, 2022		
unt Complete	% of Current Contract Amou	tual Completion Date	tion Date	Current Comple	pletion Date	Original Comp		
	91.35%		2022	November 4,	4, 2022	November		

Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
November 3, 2021	November 3, 2021	
October 15, 2021	October 15, 2021	
January 3, 2022	January 3, 2022	
May 16, 2022	May 16, 2022	
N J	lovember 3, 2021 October 15, 2021 anuary 3, 2022	October 15, 2021 October 15, 2021  anuary 3, 2022 January 3, 2022

Contract Total Pay For Estimate No. 7										
		This Estimate	Previous	To Date						
211015-C04										
	Total Posted Items Pay	\$55,891.65	\$2,665,576.13	\$2,721,467.78						
	Gross Item Adjustments	\$0.00	\$49,876.27	\$49,876.27						
	Incentive	\$0.00	\$0.00	\$0.00						
	Disincentive	\$0.00	\$0.00	\$0.00						
	Liquidated Damage	\$0.00	\$0.00	\$0.00						
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00						
	,		\$2,715,452.40	\$2,771,344.05						
<b>Contract Total Pa</b>	yable This Estimate:	\$55,891.65								

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Current Installed Qty	Current Installed Amount				
J4S3247	0260	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$26.000	200	\$5,200.00		
	0270	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	EA	\$275.000	7	\$1,925.00		
	0280	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	EA	\$210.000	4	\$840.00		
	0290	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	2	\$900.00				
	0300	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	2	\$900.00				
	0310	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	EA	\$250.000	22	\$5,500.00		
	0320	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.250	72,016	\$18,004.00		
	0330	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	LF	\$0.250	69,283	\$17,320.75		
	0340 6205906A 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING LF \$0.900 5,891								
Project J4S3247 - Total									
Overall - To	tal						\$55,891.65		

#### **Contract Adjustments This Estimate**

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 18



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 17, 2022

Progress Estimate Number	Contract ID		Pay Period Start	,	Original Contract Amount	\$2,973,711.26
7	Prime Contractor	ldeker, Inc.	Pay Period End	October 15, 2022	Net Change Order Amount	\$5,300.00
,					Current Contract Amount	\$2,979,011.26

ject nber	Line No.	Item Description	Adjustment Type	Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
3247	0030	TYPE 5 AGGREGATE FOR	Material	Туре		-23	Unit Price \$14.75	(\$339.25
	0030	BASE (4 IN. THICK)  TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user frizzm	23	\$14.75	\$339.25
					overridding Payment Estimate Exception 1 on the current Payment Estimate.			
	0040	MISC.	Material			-310.47	\$118.69	(\$36,849.68
	0040	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.	310.47	\$118.69	\$36,849.68
	0050	GRAVEL (A) OR CRUSHED STONE (B)	Material			-875.57	\$47.18	(\$41,309.39
C	0050	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.	875.57	\$47.18	\$41,309.39
	0800	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material			-22,712.74	\$57.67	(\$1,309,843.72)
	0080	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.	22,712.74	\$57.67	\$1,309,843.72
	0100	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	Material			-22.5	\$89.10	(\$2,004.75
	0100	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.	22.5	\$89.10	\$2,004.75
	0130	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material			-2	\$500.01	(\$1,000.02
	0130	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user frizzm overridding Payment Estimate Exception 8 on the current Payment Estimate.	2	\$500.01	\$1,000.02
	0140	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material			-521	\$195.50	(\$101,855.50)
	0140	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 9 on the current Payment Estimate.	521	\$195.50	\$101,855.50
	0180	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-818	\$6.50	(\$5,317.00
	0180	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.	818	\$6.50	\$5,317.00

Revision 4/1/2020 Page 2 of 18



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 17, 2022

Progress Estimate Number	Contract ID		Pay Period Start	, .	Original Contract Amount	\$2,973,711.26
7	Prime Contractor	Ideker, Inc.	Pay Period End	October 15, 2022	Net Change Order Amount Current Contract Amount	\$5,300.00 \$2,979,011.26

oject imber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
3247	0220	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			-6	\$5,300.00	(\$31,800.00
	0220	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.	6	\$5,300.00	\$31,800.00
	0260	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material			-200	\$26.00	(\$5,200.00
	0260	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.	200	\$26.00	\$5,200.00
	0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material			-7	\$275.00	(\$1,925.00
	0270	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment Estimate Exception 14 on the current Payment Estimate.	7	\$275.00	\$1,925.00
	0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	Material			-4	\$210.00	(\$840.00
	0280	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.	4	\$210.00	\$840.00
	0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material			-2	\$450.00	(\$900.00
	0290	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.	2	\$450.00	\$900.00
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	Material			-2	\$450.00	(\$900.00
	0300	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.	2	\$450.00	\$900.00
	0310	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	Material			-22	\$250.00	(\$5,500.00
	0310	PREFORMED	Material		This adjustment offsets the original system-	22	\$250.00	\$5,500.00

Revision 4/1/2020 Page 3 of 18

\$0.00



Total

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: October 17, 2022

Prog	jress E	stimate Number 7	Contract Prime Co		211015-C04 deker, Inc.	Pay Period Start Pay Period End	October 1, 2022 October 15, 2022	Net Ch	al Contract A nange Order A nt Contract A	Amount	\$2,973,711.26 \$5,300.00 \$2,979,011.26
Project Number	Line No.	Item Descript	ion	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3247		THERMC PAVEMENT MARKII WHITE M				Adjustmo	terial Payment Estima ent (0015) due to use /ment Estimate Exce e current Payment E	er frizzm ption 18			
	0320	6 IN. WHITE HIC WATERBORNE PA MARKING PAINT	VEMENT	Material					-86,322	\$0.25	(\$21,580.50)
	0320 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS		Material		generated Mai Adjustmo overridding Pay	nt offsets the original terial Payment Estima ent (0016) due to use ment Estimate Exce e current Payment E	ate Item er frizzm ption 19	86,322	\$0.25	\$21,580.50	
	0330	6 IN. YELLOW HIC WATERBORNE PA MARKING PAINT	VEMENT	Material					-69,283	\$0.25	(\$17,320.75)
	0330 6 IN. YELLOW HIGH BU WATERBORNE PAVEM MARKING PAINT, TY BE		VEMENT	Material		generated Mai Adjustmo overridding Pay	nt offsets the original terial Payment Estima ent (0017) due to use ment Estimate Exce e current Payment E	ate Item er frizzm ption 21	69,283	\$0.25	\$17,320.75
	0340	12 IN. WHITE HIC WATERBORNE PA MARKING PAINT	VEMENT	Material					-5,891	\$0.90	(\$5,301.90)
	0340	12 IN. WHITE HIC WATERBORNE PA MARKING PAINT	VEMENT	Material		generated Mai Adjustmo overridding Pay	nt offsets the original terial Payment Estima ent (0018) due to use yment Estimate Exce e current Payment E	ate Item er frizzm ption 23	5,891	\$0.90	\$5,301.90

Revision 4/1/2020 Page 4 of 18



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number Proj. Number Route Description Number												
J4S3247	FAF 152-1(16)	Coldmill and resurface	152	PLATTE	from Route N to the west s	om Route N to the west side of I-29						
Γotals by J	Job Numbe	rs										
J4S3247		d Item Pay Item Adjustmo		Item Pay	This Estimate \$55,891.65 \$0.00 \$55,891.65	Previous \$2,665,576.13 \$49,876.27 \$2,715,452.40	To Date \$2,721,467.78 \$49,876.27 \$2,771,344.05					
	Liquid	tive centive lated Damages Contract Adju:			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00					

Revision 4/1/2020 Page 5 of 18



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 3040504, Project Item Line Number 0030, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 3040504, Project Item Line Number 0030, Material Set 304050496, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	C. Weatherby continues to work with KC Materials to resolve discrepancy. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 3049910, Project Item Line Number 0040, Material Set 304991096, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 3105002, Project Item Line Number 0050, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 4030103, Project Item Line Number 0080, Material Set 403010396, Material 0403SP125CLG - Superpave 12.5 mm, Des C 80 Gyros, Acceptance Action Generic AspHigh is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 5021108, Project Item Line Number 0100, Material Set 502110896, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 5021108, Project Item Line Number 0100, Material Set 502110896, Material 0501CCSPEC - Concrete, Special, misc. or unusual use, Acceptance Action Generic 0501CCSPEC is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6123000A, Project Item Line Number 0130, Material Set 6123000A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6131010, Project Item Line Number 0140, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6131010, Project Item Line Number 0140, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6131015, Project Item Line Number 0180, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6161099, Project Item Line Number 0220, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6200015, Project Item Line Number 0260, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6200021, Project Item Line Number 0270, Material Set 620002196, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6200024, Project Item Line Number 0280, Material Set 620002496, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6200027, Project Item Line Number 0290, Material Set 620002796, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6200030, Project Item Line Number 0300, Material Set 620003096, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6200036, Project Item Line Number 0310, Material Set 620003696, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6205902A, Project Item Line Number 0320, Material Set 6205902A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6205902A, Project Item Line Number 0320, Material Set 6205902A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6205903A, Project Item Line Number 0330, Material Set 6205903A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6205903A, Project Item Line Number 0330, Material Set 6205903A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6205906A, Project Item Line Number 0340, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient.	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3247, Item 6205906A, Project Item Line Number 0340, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr	C. Weatherby continues working with KC Materials to resolve this exception. frizzm 10/17/22	frizzm	Overridden

Revision 4/1/2020 Page 6 of 18



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient.			
Estimate Exception Type: Item Overrun: Contract 211015-C04, Contract Project J4S3247, Project Item Line Number 0040, Contract Line Item Number 0040, Item 3049910, Minor Item.	A change order is in process to resolve overrun. frizzm 10/17/22	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211015-C04, Contract Project J4S3247, Project Item Line Number 0050, Contract Line Item Number 0050, Item 3105002, Minor Item.	A change order is in process to resolve overrun. frizzm 10/17/22	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211015-C04, Contract Project J4S3247, Project Item Line Number 0080, Contract Line Item Number 0080, Item 4030103, Minor Item.	A change order is in process to resolve overrun. frizzm 10/17/22	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211015-C04, Contract Project J4S3247, Project Item Line Number 0060, Contract Line Item Number 0060, Item 4011209, Minor Item.	A change order is in process to resolve overrun. frizzm 10/17/22	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211015-C04, Contract Project J4S3247, Project Item Line Number 0090, Contract Line Item Number 0090, Item 4071005, Minor Item.	A change order is in process to resolve overrun. frizzm 10/17/22	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211015-C04, Contract Project J4S3247, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6133019, Minor Item.	A change order is in process to resolve overrun. frizzm 10/17/22	frizzm	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211015-C04, Contract Project J4S3247, Project Item Line Number 0350, Contract Line Item Number 0350, Item 6221001, Minor Item.	A change order is in process to resolve overrun. frizzm 10/17/22	frizzm	Acknowledged

Revision 4/1/2020 Page 7 of 18



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted am Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POSTEI To Date (See repor generated date)
11015-C04	J4S3247	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	Qty 1.00	\$8,600.00	\$8,600.0
		0001	0020	2153000	SHAPING SLOPES, CLASS III	8.00	0.00	8.00	100F	8.00	\$900.00	\$7,200.0
		0001	0030	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	23.00	0.00	23.00	SQYD	23.00	\$14.75	\$339.2
		0001	0040	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	213.30	0.00	213.30	TONS	310.47	\$118.69	\$36,849.0
		0001	0050	3105002	GRAVEL (A) OR CRUSHED STONE (B)	683.00	0.00	683.00	TONS	875.57	\$47.18	\$41,309.
		0001	0060	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	6,476.50	0.00	6,476.50	TONS	6,703.72	\$57.94	\$388,413.
		0001	0070	4019905	MISC.BITUMINOUS SHOULDER REPAIR	1,225.00	0.00	1,225.00	SQYD	372.00	\$81.70	\$30,392.
		0001	0080	4030103	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX)	22,162.40	0.00	22,162.40	TONS	22,712.74	\$57.67	\$1,309,843.
		0001	0090	4071005	TACK COAT	25,166.00	0.00	25,166.00	GAL	25,959.00	\$2.50	\$64,897
		0001	0100	5021108	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	22.50	0.00	22.50	SQYD	22.50	\$89.10	\$2,004
		0001	0110	6089902	MISC.RAMPED MEDIAN NOSE	2.00	0.00	2.00	EA	2.00	\$1,375.00	\$2,750
		0001	0120	6091010	CONCRETE CURB (6 IN. HEIGHT AND UNDER) TYPE S	60.00	0.00	60.00	LF	0.00	\$45.50	\$0.
		0001	0130	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.01	\$1,000
		0001	0140	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	564.00	0.00	564.00	SQYD	521.00	\$195.50	\$101,855
		0001	0150	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	57.00	0.00	57.00	SQYD	0.00	\$1.00	\$0
		0001	0160	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	57.00	0.00	57.00	SQYD	0.00	\$5.00	\$0
		0001	0170	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	1,056.00	530.00	1,586.00	LF	1,586.00	\$10.00	\$15,860
		0001	0180	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	1,095.00	0.00	1,095.00	EA	818.00	\$6.50	\$5,317
		0001	0190	6133018	FURNISHING AND PLACING BITUMINOUS MATERIAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	8.90	0.00	8.90	TONS	7.60	\$973.97	\$7,402
		0001	0200	6133019	REMOVAL FOR CLASS B PARTIAL DEPTH PAVEMENT REPAIR	26.70	0.00	26.70	SQYD	37.00	\$151.18	\$5,593
		0001	0210	6139905	MISC.CLASS A PARTIAL DEPTH CONCRETE PAVEMENT REPAIR USING FLEXIBLE HOT POLYMER MODIFIED REPAIR MATERIAL	350.00	0.00	350.00	SQYD	0.00	\$654.20	\$0
		0001	0220	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	6.00	0.00	6.00	EA	6.00	\$5,300.00	\$31,800
		0001	0230	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	6.00	0.00	6.00	EA	0.00	\$850.00	\$0
		0001	0240	6169901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	1.00	\$42,000.00	\$42,000
		0001	0250	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$156,882.10	\$156,882
		0001	0260	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	200.00	0.00	200.00	LF	200.00	\$26.00	\$5,200
		0001	0270	6200021	PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW	7.00	0.00	7.00	EA	7.00	\$275.00	\$1,925
		0001	0280	6200024	PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW	4.00	0.00	4.00	EA	4.00	\$210.00	\$840
		0001	0290	6200027	PREFORMED THERMOPLASTIC PAVEMENT MARKING, COMBINATION STR/LT/RT	2.00	0.00	2.00	EA	2.00	\$450.00	\$900
		0001	0300	6200030	PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY)	2.00	0.00	2.00	EA	2.00	\$450.00	\$900
		0001	0310	6200036	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 30 IN WHITE MIDBLOCK	22.00	0.00	22.00	EA	22.00	\$250.00	\$5,500
		0001	0320	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT. TYPE L BEADS	86,742.00	0.00	86,742.00	LF	86,322.00	\$0.25	\$21,580
		0001	0330	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	69,433.00	0.00	69,433.00	LF	69,283.00	\$0.25	\$17,320
		0001	0340	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,981.00	0.00	5,981.00	LF	5,891.00	\$0.90	\$5,301
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	250,735.00	0.00	250,735.00	SQYD	251,787.00	\$0.92	\$231,644
		0001	0360	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,667.00	0.00	2,667.00	SQYD	2,667.00	\$14.12	\$37,658
		0001	0370	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	971.40	0.00	971.40	STA	971.40	\$18.23	\$17,708
		0010	0380	6061061	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN. SPACING	1,775.00	0.00	1,775.00	LF	1,775.00	\$31.75	\$56,356
		0010	0390	6061063	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5 IN. SPACING	263.00	0.00	263.00	LF	263.00	\$44.00	\$11,572
		0010	0400	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	5.00	0.00	5.00	EA	5.00	\$3,000.00	\$15,000
		0010	0410	6061074	MGS HEIGHT AND BLOCK TRANSITION	3.00	0.00	3.00	EA	3.00	\$850.00	\$2,550

Page 8 of 18 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C04	J4S3247	0010	0420	6061080	MGS END ANCHOR	2.00	0.00	2.00	EA	2.00	\$1,100.00	\$2,200.00
		0010	0430	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	10.00	0.00	10.00	EA	10.00	\$2,700.00	\$27,000.00
		0030	0440	9029902	MISC.PULLBOX ADJUSTMENT	1.00	0.00	1.00	EA	0.00	\$7,844.00	\$0.00
		0040	0450	9039902	MISC.SIGN RELOCATION	1.00	0.00	1.00	EA	0.00	\$1,200.00	\$0.00
	Project J	4S3247 - To	tal Value	Posted to E	ate as of Report Generated Date							\$2,721,467.78
211015-C04 Ove	rall - Total	Value Post	ed to Dat	te as of Rep	ort Generated Date							\$2,721,467.78

Page 9 of 18 Revision 4/1/2020



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J4S3247

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Si	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0260	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	10/11/22	10/14/22	200.00	LF		0		5.419		
0270	6200021	PREF THERMO PVMT MARK, LT/RT ARROW	10/11/22	10/14/22	7.00	EA		0		5.419		
0280	6200024	PREF THERMO PVMT MRKG, STRIAGHT ARROW	10/11/22	10/14/22	4.00	EA		0		5.419		
0290	6200027	PREF THERMO PVMT MARKING, COMBO	10/11/22	10/14/22	2.00	EA		0		5.419		
0300	6200030	PREF THERMO PVMT MARK, WORD (ONLY)	10/11/22	10/14/22	2.00	EA		0		5.419		
0310	6200036	PREF THERMO PVMT MARK, 30" WHT MIDBL	10/11/22	10/14/22	22.00	EA		0		5.419		
0320	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	10/11/22	10/14/22	72,016.00	LF		0		5.419		
0330	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	10/11/22	10/14/22	69,283.00	LF		0		5.419		
0340	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	10/11/22	10/14/22	5,891.00	LF		0		5.419		

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 10 of 18



March   Marc	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
	J4S3247	0030	AGGREGATE	Material		4		SYSTEM	\$339.25	Estimate Item Adjustment (0010) due to user frizzm overridding Payment
2022   Seption   SysTEM   Sy						4		SYSTEM	(\$339.25)	
2022   100						5		SYSTEM	\$339.25	Estimate Item Adjustment (0008) due to user weathc1 overridding Payment
Column						5		SYSTEM	(\$339.25)	
2022   7   Cot 17,   SYSTEM   S339.25   This adjustment offsets the original system-generated Material Payment Esterate Exception 1 on the ourset Payment Esterate Inc.						6		SYSTEM	\$339.25	Estimate Item Adjustment (0005) due to user frizzm overridding Payment
2022   SysTem   1,500   SysTem   1,500						6		SYSTEM	(\$339.25)	
1-Total   1-To						7		SYSTEM	\$339.25	Estimate Item Adjustment (0002) due to user frizzm overridding Payment
Total						7		SYSTEM	(\$339.25)	·
Price FUEL   2   Jun 3   SYSTEM   \$6.62   Reference flem Price Adjustment Index Adjustment Type applied is FUEL					- Total				\$0.00	
Total   Sep 30				Material - To	tal				\$0.00	
				Price FUEL		2		SYSTEM	\$6.62	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					- Total				\$6.62	
Material				Price FUEL -	Total				\$6.62	
AGRECATE   FOR BASE										
2022		0040	AGGREGATE	Material		5		SYSTEM	\$36,849.68	Estimate Item Adjustment (0010) due to user weathc1 overridding Payment
2022   Estimate Item Adjustment (0006) due to user frizzm overridding Payment						5		SYSTEM	(\$36,849.68)	
2022   7						6		SYSTEM	\$36,849.68	Estimate Item Adjustment (0006) due to user frizzm overridding Payment
2022   Setimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.						6		SYSTEM	(\$36,849.68)	
Adaptal - Total   S0.00						7		SYSTEM	\$36,849.68	Estimate Item Adjustment (0003) due to user frizzm overridding Payment
Material - Total						7		SYSTEM	(\$36,849.68)	
Overrun   Overrun   5   Sep 16, 2022   SYSTEM   (\$11,533.11)					- Total				\$0.00	
Overrun - Total   (\$11,533.11)				Material - To	tal				\$0.00	
Overrun - Total  Odd - Total  OSS GRAVEL (A) OR CRUSHED STONE (B)  Sep 16, 2022  Sep 16, SYSTEM \$41,309.39 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.  Sep 16, 2022  Sep 16, SYSTEM (\$41,309.39)  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.  Sep 30, SYSTEM \$41,309.39 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate.  Sep 30, SYSTEM (\$41,309.39)  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate.  Oct 17, 2022 SYSTEM (\$41,309.39)				Overrun	Overrun	5		SYSTEM	(\$11,533.11)	
O050 GRAVEL (A) OR CRUSHED STONE (B)  Material  5 Sep 16, 2022  5 Sep 16, 2022  6 Sep 30, 2022  6 Sep 30, 2022  7 Oct 17, 2022  7 Oct 17, 2022  SYSTEM  (\$41,309.39)  (\$41,309.39)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user weathor overridding Payment Estimate Exception 4 on the current Payment Estimate.  5 Sep 16, 2022  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.  6 Sep 30, 2022  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate.					Overrun - T	otal			(\$11,533.11)	
GRAVEL (A) OR CRUSHED STONE (B)  Material  5 Sep 16, 2022  SYSTEM \$41,309.39  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.  5 Sep 16, 2022  6 Sep 30, 2022  SYSTEM \$41,309.39  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.  6 Sep 30, 2022  7 Oct 17, 2022  SYSTEM \$41,309.39  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.  7 Oct 17, 2022  SYSTEM \$41,309.39  This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate.				Overrun - To	tal				(\$11,533.11)	
Estimate Item Adjustment (0012) due to user weathc1 overridding Payment Estimate Exception 4 on the current Payment Estimate.    Sep 16, 2022   SYSTEM (\$41,309.39)		0040	Total						(\$11,533.11)	
6 Sep 30, 2022 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.  6 Sep 30, 2022 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.  7 Oct 17, 2022 SYSTEM (\$41,309.39)		0050	CRUSHED STONE	Material		5		SYSTEM	\$41,309.39	Estimate Item Adjustment (0012) due to user weathc1 overridding Payment
Estimate Item Adjustment (0007) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.  Sep 30, 2022  Oct 17, 2022  SYSTEM (\$41,309.39)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.  SYSTEM (\$41,309.39)						5		SYSTEM	(\$41,309.39)	
7 Oct 17, 2022  SYSTEM \$41,309.39 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.  Oct 17, 2022  SYSTEM (\$41,309.39)						6		SYSTEM	\$41,309.39	Estimate Item Adjustment (0007) due to user frizzm overridding Payment
2022 Estimate Item Adjustment (0004) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.  7 Oct 17, 2022 (\$41,309.39)						6		SYSTEM	(\$41,309.39)	
2022						7		SYSTEM	\$41,309.39	Estimate Item Adjustment (0004) due to user frizzm overridding Payment
						7		SYSTEM	(\$41,309.39)	
					- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3247	0050	GRAVEL (A) OR CRUSHED STONE	Material - To	tal				\$0.00	
		(B)	Overrun	Overrun		Sep 16, 2022	SYSTEM	(\$9,085.45)	
				Overrun - T	otal			(\$9,085.45)	
	0050		Overrun - To	tal				(\$9,085.45)	
	0050 -		0	0	_	0 10	0)/07514	(\$9,085.45)	86 8: 45 45 47 515
	0060	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Overrun	Overrun		Sep 16, 2022	SYSTEM	(\$14,062.83)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - T	otal			(\$14,062.83)	
			Overrun - To	tal	4	04	OVOTEM	(\$14,062.83)	Defended have Drive Adjustment by day Adjustment Tong and its EUE
			Price FUEL		4	Sep 1, 2022	SYSTEM	\$6,302.59	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 16, 2022	SYSTEM	\$24,761.45	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$31,064.04	
			Price FUEL -	Total				\$31,064.04	
	0060 -	Total						\$17,001.21	
	0800	ASPHALTIC CONCRETE MIXTURE PG	Material		3	Aug 17, 2022	SYSTEM	\$786,493.66	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user yosti 1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		70-22 (SP125C MIX)			3	Aug 17, 2022	SYSTEM	(\$786,493.66)	
					4	Sep 1, 2022	SYSTEM	\$1,204,963.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Sep 1, 2022	SYSTEM	(\$1,204,963.90)	
					5	Sep 16, 2022	SYSTEM	\$1,299,174.19	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user weathc1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Sep 16, 2022	SYSTEM	(\$1,299,174.19)	
					6	Sep 30, 2022	SYSTEM	\$1,309,843.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Sep 30, 2022	SYSTEM	(\$1,309,843.72)	
					7	Oct 17, 2022	SYSTEM	\$1,309,843.72	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user frizzm overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$1,309,843.72)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	5	Sep 16, 2022	SYSTEM	(\$23,130.50)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Sep 30, 2022	SYSTEM	(\$11,713.72)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - T	otal			(\$34,844.22)	
			Overrun - To	tal				(\$34,844.22)	
			Price FUEL		3	Aug 16, 2022	SYSTEM	\$53,880.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					4	Sep 1, 2022	SYSTEM	\$28,668.15	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 16, 2022	SYSTEM	\$9,220.09	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Sep 30, 2022	SYSTEM	\$1,044.20	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$92,812.79	
			Price FUEL -	Total				\$92,812.79	
	0080 -	Total						\$57,968.57	
	0090	TACK COAT	Material		3	Aug 17,	SYSTEM	\$28,050.00	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J4S3247	0090	TACK COAT	Material			2022			Estimate Item Adjustment (0012) due to user yostj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					3	Aug 17, 2022	SYSTEM	(\$28,050.00)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
			Overrun	Overrun	5	Sep 16, 2022	SYSTEM	(\$1,557.50)				
					6	Sep 30, 2022	SYSTEM	(\$425.00)				
				Overrun - T	otal			(\$1,982.50)				
			Overrun - To	tal				(\$1,982.50)				
	0090 -	Total						(\$1,982.50)				
	0100	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	Material		2	Jun 3, 2022	SYSTEM	\$2,004.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user weathc1 overridding Payment Estimate Exception 1 on the current Payment Estimate.			
					2	Jun 3, 2022	SYSTEM	(\$2,004.75)				
					3	Aug 17, 2022	SYSTEM	\$2,004.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user yostj1 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					3	Aug 17, 2022	SYSTEM	(\$2,004.75)				
					4	Sep 1, 2022	SYSTEM	\$2,004.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 4 on the current Payment Estimate.			
					4	Sep 1, 2022	SYSTEM	(\$2,004.75)				
					5	Sep 16, 2022	SYSTEM	\$2,004.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user weathc1 overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					5	Sep 16, 2022	SYSTEM	(\$2,004.75)				
					6	Sep 30, 2022	SYSTEM	\$2,004.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					6	Sep 30, 2022	SYSTEM	(\$2,004.75)				
					7	Oct 17, 2022	SYSTEM	\$2,004.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.			
					7	Oct 17, 2022	SYSTEM	(\$2,004.75)				
				- Total				\$0.00				
			Material - To	tal				\$0.00				
			Price FUEL		2	Jun 3, 2022	SYSTEM	\$25.92	Reference Item Price Adjustment Index Adjustment Type applied is FUEL			
				- Total				\$25.92				
			Price FUEL -	Total				\$25.92				
	0100 -	Total						\$25.92				
	0130	TRUCK OR TRAILER MOUNTED ATTEN	Material		3	Aug 17, 2022	SYSTEM	\$1,000.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user yostj 1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
		(TMA)		)		(TMA) 3 Aug 17, SYSTEM (\$1,000.02)						
								4	Sep 1, 2022	SYSTEM	\$1,000.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Sep 1, 2022	SYSTEM	(\$1,000.02)				
					5	Sep 16, 2022	SYSTEM	\$1,000.02	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 8 on the current Payment Estimate.			
					5	Sep 16, 2022	SYSTEM	(\$1,000.02)				



MASSAPT   1900   TRUCKED   Macroal TRANSER	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
	J4S3247	0130	TRAILER MOUNTED ATTEN	Material		6		SYSTEM	\$1,000.02	Estimate Item Adjustment (0004) due to user frizzm overridding Payment					
2022   17   2017   SYSTEM   (\$11,000.007)   1010 to user in turn reverding Payment Estimate Ben Adjustment (official services and services payment Estimate Strangers and Strangers an			(TMA)			6		SYSTEM	(\$1,000.02)						
Total						7		SYSTEM	\$1,000.02	Estimate Item Adjustment (0001) due to user frizzm overridding Payment					
						7		SYSTEM	(\$1,000.02)						
150 -   Total					- Total				\$0.00						
Page 14   Page 15   Page				Material - To	tal										
CONC MAIL FOR FULL DEPTH		0130 -	Total						\$0.00						
2022   3		0140	CONC MATL FOR	Material		2		SYSTEM	\$101,855.50	Estimate Item Adjustment (0004) due to user weathc1 overridding Payment					
2022   September						2		SYSTEM	(\$101,855.50)						
10022   101,855.50   This adjustment offisets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate Exception 9 on the current Payment Estimate Exception 10 on the current Payment Estimate Exception 10 on the current Payment Estimate Estimate Exception 10 on the current Payment Estimate Estimate Exception 12 on the current Payment Estimate Estimate Exception 12 on the current Payment Estimate Estimate Exception 12 on the current Payment Estimate Estimate Estimate Exception 12 on the current Paymen						3		SYSTEM	\$101,855.50	Estimate Item Adjustment (0014) due to user yostj1 overridding Payment					
2022   Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate.						3		SYSTEM	(\$101,855.50)						
2022											4		SYSTEM	\$101,855.50	Estimate Item Adjustment (0014) due to user frizzm overridding Payment
2022   Estimate Item Adjustment (0078) due to user weather overridding Payment Estimate Exception 9 on the current Payment Estimate Estimate Exception 9 on the current Payment Estimate.   This adjustment offset the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.   This adjustment offset the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.   This adjustment offset the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.   This adjustment offset the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.   This adjustment offset the original system-generated Material Payment Payment Estimate.   This adjustment offset the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.   This adjustment offset the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.   This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.   This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.   This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.   This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.   This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.   This adjustment o						4		SYSTEM	(\$101,855.50)						
2022						5		SYSTEM	\$101,855.50	Estimate Item Adjustment (0018) due to user weathc1 overridding Payment					
2022   Estimate Item Adjustment (0f) 0) due to user ritizzm overridding Payment									5		SYSTEM	(\$101,855.50)			
2022   7   Oct 17,   SYSTEM   \$101,855.50   This adjustment offsets the original system-generated Material Payment Estimate Exception 9 on the current Payment Estimate.   Substitution						6		SYSTEM	\$101,855.50	Estimate Item Adjustment (0010) due to user frizzm overridding Payment					
7						6		SYSTEM	(\$101,855.50)						
Total   System   System   System   System   Storon   St						7		SYSTEM	\$101,855.50	Estimate Item Adjustment (0007) due to user frizzm overridding Payment					
Total   S0.00						7		SYSTEM	(\$101,855.50)						
Comparison of Control of Comparison of Control of Comparison of Comparison of Control of Comparison of Control of Comparison of Control of Comparison of Control of					- Total				\$0.00						
Overrun - Total  So.00  Overrun - Total  So.00  Overrun - Total  So.00  Overrun - Total  So.00  Overrun - Total  Overrun - Total  Overrun - Total  So.00  Overrun - Total  Overrun - Total  Overrun - Total  So.00  Overrun - Total  Overrun - Total				Material - To	tal				\$0.00						
PAVEMENT REPAIR SAW CUT (FOR   Sep 30, 2022   SYSTEM   \$5,300.00   Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).    Overrun - Total		0140 -	Total						\$0.00						
(FOR 6 Sep 30, 2022 SYSTEM \$5,300.00 Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is applied (if non-zero).    Overrun - Total		0170	PAVEMENT	Overrun	Overrun	2		SYSTEM	(\$5,300.00)						
Overrun - Total  So.00  DOWEL BAR (DRILLING, FURNISHING AND INST  DOWEL BAR (DRILLING, FURNISHING AND INST  Aug 17, 2022  Aug 17, 2022  Aug 17, 2022  SYSTEM  So.00  This adjustment offsets the original system-generated Material Payment (Estimate Exception 12 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment (So.317.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate Exception 12 on the current Payment Estimate.  Aug 17, 2022  SYSTEM (\$5,317.00)  Aug 17, 2022  SYSTEM (\$5,317.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.						6		SYSTEM	\$5,300.00	previous payment estimates. Price Adjustments of ',10.00000 - 10.00000, 'is					
O180 DOWEL BAR (DRILLING, FURNISHING AND INST  2 Jun 3, 2022  3 Aug 17, 2022  4 Sep 1, SYSTEM \$5,317.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  1 This adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  2 Jun 3, 2022  3 Aug 17, 2022  3 Aug 17, 2022  4 Sep 1, SYSTEM \$5,317.00  This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.  3 Aug 17, 2022  4 Sep 1, SYSTEM \$5,317.00  This adjustment offsets the original system-generated Material Payment Payment Estimate.					Overrun - To	otal			\$0.00						
DOWEL BAR (DRILLING, FURNISHING AND INST  2 Jun 3, 2022 \$SYSTEM \$5,317.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user weathc1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  2 Jun 3, 2022 \$SYSTEM \$5,317.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user yostj1 overridding Payment Estimate Item Adjustment (0015) due to user yostj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  3 Aug 17, 2022 \$SYSTEM \$5,317.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.				Overrun - To	tal				\$0.00						
Company   Comp		0170 -	Total						\$0.00						
2 Jun 3, 2022 3 Aug 17, 2022 \$\$ \$\$5,317.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate. 3 Aug 17, 2022 \$\$ \$\$ \$\$\$ \$\$(\$5,317.00) \$\$ \$\$ \$\$ \$\$ \$\$ 4 Sep 1, SYSTEM \$\$5,317.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 12 on the current Payment Estimate.		0180	(DRILLING, FURNISHING AND	Material		2		SYSTEM	\$5,317.00	Estimate Item Adjustment (0007) due to user weathc1 overridding Payment					
Estimate Item Adjustment (0015) due to user yostj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.  3 Aug 17, 2022  4 Sep 1, SYSTEM \$5,317.00 This adjustment offsets the original system-generated Material Payment			IONI			2		SYSTEM	(\$5,317.00)						
2022 4 Sep 1, SYSTEM \$5,317.00 This adjustment offsets the original system-generated Material Payment						3		SYSTEM	\$5,317.00	Estimate Item Adjustment (0015) due to user yostj1 overridding Payment					
						3		SYSTEM	(\$5,317.00)						
						4		SYSTEM	\$5,317.00						



Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4S3247	0180	DOWEL BAR	Material	Туре					Estimate Exception 9 on the current Payment Estimate.
		(DRILLING, FURNISHING AND INST			4	Sep 1, 2022	SYSTEM	(\$5,317.00)	
					5	Sep 16, 2022	SYSTEM	\$5,317.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user weathc1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Sep 16, 2022	SYSTEM	(\$5,317.00)	
					6	Sep 30, 2022	SYSTEM	\$5,317.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.
					6	Sep 30, 2022	SYSTEM	(\$5,317.00)	
					7	Oct 17, 2022	SYSTEM	\$5,317.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user frizzm overridding Payment Estimate Exception 11 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$5,317.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0180 -	Total						\$0.00	
	0200	REMOVAL FOR CLASS B PARTIAL DEPTH	Overrun	Overrun	3	Aug 17, 2022	SYSTEM	(\$1,557.15)	
		PAVT R		Overrun - T	otal			(\$1,557.15)	
			Overrun - To	tal				(\$1,557.15)	
	0200 -							(\$1,557.15)	
	0220	CMS WITH COMMUNICATION INTERFACE, CONT F	Material		3	Aug 17, 2022	SYSTEM	\$31,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user yostj1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		CONTF			3	Aug 17, 2022	SYSTEM	(\$31,800.00)	
					4	Sep 1, 2022	SYSTEM	\$31,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 10 on the current Payment Estimate.
					4	Sep 1, 2022	SYSTEM	(\$31,800.00)	
					5	Sep 16, 2022	SYSTEM	\$31,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user weathc1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					5	Sep 16, 2022	SYSTEM	(\$31,800.00)	
					6	Sep 30, 2022	SYSTEM	\$31,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Sep 30, 2022	SYSTEM	(\$31,800.00)	
					7	Oct 17, 2022	SYSTEM	\$31,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user frizzm overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$31,800.00)	
				- Total				\$0.00	
	0000	Total	Material - To	tal				\$0.00	
	0220 -	PREF THERMO PVMT MARK, 24 IN WHIT	Material		7	Oct 17, 2022	SYSTEM	<b>\$0.00</b> <b>\$5,200.00</b>	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.
		114 441 111			7	Oct 17, 2022	SYSTEM	(\$5,200.00)	Example Exception to on the out-one raymone Estimate.
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0260 -	Total						\$0.00	
	0270	PREF THERMO PVMT MARK,	Material		7	Oct 17, 2022	SYSTEM	\$1,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user frizzm overridding Payment



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
247	0270	LT/RT ARROW	Material						Estimate Exception 14 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$1,925.00)	
				- Total				\$0.00	
	0270 -	Total	Material - To	tal				\$0.00 \$0.00	
	0270 -	PREF THERMO	Material		7	Oct 17,	SYSTEM	\$840.00	This adjustment offsets the original system-generated Material Payment
	0200	PVMT MRKG, STRIAGHT ARROW	iviateriai		,	2022	STSTEM	\$040.00	Estimate Item Adjustment (0012) due to user frizzm overridding Payment Estimate Exception 15 on the current Payment Estimate.
		7.11.1077			7	Oct 17, 2022	SYSTEM	(\$840.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0280 -	Total						\$0.00	
	0290	PREF THERMO PVMT MARKING, COMBO	Material		7	Oct 17, 2022	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user frizzm overridding Payment Estimate Exception 16 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$900.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0290 -	Total						\$0.00	
	0300	PREF THERMO PVMT MARK, WORD (ONLY)	Material		7	Oct 17, 2022	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 17 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$900.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
ŀ	0300 -				_		01/0==1/	\$0.00	
	0310	PREF THERMO PVMT MARK, 30" WHT MIDBL	Material		7	Oct 17, 2022	SYSTEM	\$5,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user frizzm overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$5,500.00)	
			Material - To	- Total				\$0.00 \$0.00	
	0310 -	Total	Material - 10	tai				\$0.00	
	0320	6 IN. WHITE HIGH BUILD WATERBORNE	Material		5	Sep 16, 2022	SYSTEM	\$3,576.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user weathc1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		PAINT			5	Sep 16, 2022	SYSTEM	(\$3,576.50)	
					6	Sep 30, 2022	SYSTEM	\$3,576.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user frizzm overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Sep 30, 2022	SYSTEM	(\$3,576.50)	
					7	Oct 17, 2022	SYSTEM	\$21,580.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user frizzm overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Oct 17, 2022	SYSTEM	(\$21,580.50)	
				- Total				\$0.00	
			THE RESIDENCE OF THE PARTY OF T	tal				\$0.00	
			Material - To	tai					
	0320 -			tai				\$0.00	
	<b>0320</b> -	6 IN. YELLOW HIGH BUILD WATERBORNE	Material - 10		7	Oct 17, 2022	SYSTEM	\$0.00 \$17,320.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user frizzm overridding Payment Estimate Exception 21 on the current Payment Estimate.
		6 IN. YELLOW HIGH BUILD		- Total	7		SYSTEM SYSTEM		Estimate Item Adjustment (0017) due to user frizzm overridding Payment



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
S3247	0330	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material - To	tal				\$0.00					
	0330 -	Total						\$0.00					
	0340	12 IN. WHITE HIGH BUILD WATERBORNE	Material		7	Oct 17, 2022	SYSTEM	\$5,301.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user frizzm overridding Payment Estimate Exception 23 on the current Payment Estimate.				
		PAINT			7	Oct 17, 2022	SYSTEM	(\$5,301.90)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
	0340 -	Total						\$0.00					
	0350	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	2022		SYSTEM	(\$967.84)					
				Overrun - T	otal			(\$967.84)					
		_	Overrun - To	tal				(\$967.84)					
	0350 -							(\$967.84)					
	0380	MGS GUARDRAIL, 8 FT. POSTS, 6 FT 3 IN	Construction Stockpile		5	Sep 16, 2022	SYSTEM	(\$41,250.50)	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total				(\$41,250.50)					
			Construction	Stockpile - 1	Total			(\$41,250.50)					
			Construction Stockpile STMI		1	Mar 2, 2022	SYSTEM	\$41,250.50	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total				\$41,250.50					
			Construction	Stockpile S	TMI - Tota			\$41,250.50					
	0380 -							\$0.00					
	0390	MGS GUARDRAIL, 6 FT. POSTS, 3 FT 1.5	Construction Stockpile		5	Sep 16, 2022	SYSTEM	(\$8,343.13)	Payment Estimate Item Adjustment generated Stockpile Transaction				
			C						- Total				(\$8,343.13)
			Construction Construction Stockpile STMI	i Stockpile -∃				(\$8,343.13)					
				Takal	1	Mar 2, 2022	SYSTEM	\$8,343.13	Payment Estimate Item Adjustment generated Stockpile Transaction				
			0	- Total	FAN . T-4-1			\$8,343.13					
	0390 -	Takal	Construction	Stockpile S	IMI - Tota			\$8,343.13					
	0400	MGS BRIDGE APP. TRANS SEC	Construction Stockpile		5	Sep 16, 2022	SYSTEM	\$0.00 (\$7,407.40)	Payment Estimate Item Adjustment generated Stockpile Transaction				
		(REG/NO CURB)		- Total		2022		(\$7,407.40)					
				Stockpile - 1				(\$7,407.40)					
			Construction Stockpile STMI		1	Mar 2, 2022	SYSTEM	\$7,407.40	Payment Estimate Item Adjustment generated Stockpile Transaction				
			0 1 11	- Total				\$7,407.40					
	0.400		Construction	Stockpile S	IMI - Iota			\$7,407.40					
	0400 - 0410	MGS HEIGHT	Construction		5	Sep 16,	SYSTEM	\$0.00 (\$1,590.00)	Payment Estimate Item Adjustment generated Stockpile Transaction				
		AND BLOCK TRANSITION	Stockpile	- Total		2022		(\$1,590.00)					
			Construction	Stockpile - 1	[otal			(\$1,590.00)					
			Construction	- этоскрие -	1	Mar 2,	SYSTEM	\$1,590.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
			Stockpile STMI	- Total		2022		\$1,590.00					
			Construction	Stockpile S	TMI - Tota			\$1,590.00					
	0410 -	Total						\$0.00					
	0420	MGS END ANCHOR	Construction Stockpile		5	Sep 16, 2022	SYSTEM	(\$830.00)	Payment Estimate Item Adjustment generated Stockpile Transaction				
		ANCHOR		- Total				(\$830.00)					
			Construction	Stockpile - 1	Γotal			(\$830.00)					





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3247	0420	MGS END ANCHOR	Construction Stockpile STMI		1	Mar 2, 2022	SYSTEM	\$830.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STIVII	- Total				\$830.00	
			Construction	Stockpile S	ГМI - Total			\$830.00	
	0420 -	Total						\$0.00	
	0430	TYPE A CRASHWORTHY	Construction Stockpile		5	Sep 16, 2022	SYSTEM	(\$16,920.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)		- Total				(\$16,920.00)	
			Construction	Stockpile - 1	Γotal			(\$16,920.00)	
			Construction Stockpile		1	Mar 2, 2022	SYSTEM	\$16,920.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$16,920.00	
			Construction	Stockpile S	ГМI - Total			\$16,920.00	
	0430 -	Total						\$0.00	
J4S3247 -	- Total							\$49,876.27	
Overall -	Overall - Total								