

Progress	Estimate Number	ontract ID	211015-C05			Pay Period Start	October 16, 2022	Original Contract Amount	\$2,205,533.07
10		rime ontractor		eavenworth Excavating & Equipment		Pay Period End	November 1, 2022	Net Change Order Amount	(\$6,321.28)
		onnuotor	company, me	•		2110	2022	Current Contract Amount	\$2,199,211.79
Approval Date									By User
November 2, 2022	2		Gen	erated and A	Approved (and	should be considere	d Draft) at the P	Project Office Level by	schwaj2
November 3, 2022	2		Reviewe	d and Appro	ved (and shou	ld be considered Dra	aft) at the Reside	ent Engineer Level by	penner1
November 4, 2022	2			F	Reviewed and	Approved at the Cer	ntral Office Conti	rollers Office Level by	ramses1
Original Com	pletion Date		Current Completi	on Date Actual Completion Date			% of Cu	nt Complete	
Novembe	r 1, 2022		November 1, 2	022				79.72%	
Cor	ntract Informa	ational Da	ites				Milestones		
Date Description	Origina Completion		Current ompletion Date	Date [Description	Original Completion Date	Current Completion D	Days Remaining of ate Milestone	Charge
Acceptance Date				58 at Ward		August 20, 2022	August 20, 20	22 Milestone Comple	Days ete
Awarded Date	November 3,		ovember 3,)21		n Date d Calendar	August 9, 2022	August 16, 20	22 Milestone Comple	ete
Letting Date	October 15, 2	2021 O	ctober 15, 2021	Time					
Notice to Proceed Date	January 3, 20	022 Ja	anuary 3, 2022						
Open to Traffic Date									
Work Began Date	June 1, 2022	2 Ju	ine 1, 2022						

Contract Total Pay For Estimate No. 10 This Estimate Previous To Date 211015-C05 <mark>\$20,343.20</mark> Total Posted Items Pay \$1,732,936.21 \$1,753,279.41 **\$0.00** \$0.00 \$55,599.40 Gross Item Adjustments \$55,599.40 Incentive \$30,000.00 \$30,000.00 Disincentive \$0.00 \$0.00 \$0.00 Liquidated Damage Other Contract Adjustments \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 <mark>\$1,818,535.61</mark> \$1,838,878.81 Contract Total Payable This Estimate: \$20,343.20

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount			
J4S3273	0060	2063000	CLASS 3 EXCAVATION	CUYD	\$3.000	55	\$165.00			
	0280	6141028	GRATE AND BEARING PLATE (5 FT. 1 IN. X 3 FT. 1 IN. OR 1549 MM X 940 MM)	EA	\$3,520.000	1	\$3,520.00			
	0320	6161005	CONSTRUCTION SIGNS	SQFT	\$5.000	180	\$900.00			
	0340	6161025	CHANNELIZER (TRIM LINE)	EA	\$15.000	25	\$375.00			
	0420	6191000	PAVEMENT EDGE TREATMENT	LF	\$13.850	192	\$2,659.20			
	0620	7250315A	15 IN. PIPE GROUP B	LF	\$104.000	28.5	\$2,964.00			
	0700	7269903	MISC.15 IN. CLASS IV REINFORCED CONCRETE PIPE	LF	\$80.000	65	\$5,200.00			
	0750	7311053	PRECAST CONCRETE DROP INLET 5 FT X 3 FT	FT	\$1,010.000	3	\$3,030.00			
	0800	7329902	MISC.15 IN. REINFORCED PRECAST FLARED END SECTION	EA	\$1,530.000	1	\$1,530.00			
Project J4S	3273 - Tota	l					\$20,343.20			
Overall - Total										



Pr	ogress 10	Estimate Number	Prime	211015-C05 Leavenworth Ex Company, Inc.	eavenworth Excavating & Equipment Pay Period Nove			Order (§	62,205,533.07 66,321.28) 62,199,211.79
ine Item	Adjustr	nents This	<u>Estimate</u>						
Project Number	Line No.	Item	Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3273	0050	CON	IPACTING IN CL	JT Material			-23	\$500.00	(\$11,500.00
	0050	COM	MPACTING IN CU	JT Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.	23	\$500.00	\$11,500.00
	0100		AGGREGATE FO BASE (6 IN. THIC				-379.052	\$16.00	(\$6,064.83
	0100		AGGREGATE FC BASE (6 IN. THIC			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.	379.052	\$16.00	\$6,064.83
	0150		TACK COA	AT Material			-2,802	\$2.50	(\$7,005.00
	0150		TACK COA	AT Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 3 on the current Payment Estimate.	2,802	\$2.50	\$7,005.00
	0160		ETE PAVEMENT ON-REINFORCE 15 FT. JOINT	Ď,			-4.656	\$377.30	(\$1,756.71
	0160		ETE PAVEMENT ON-REINFORCE 15 FT. JOINT	D,		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payment Estimate Exception 4 on the current Payment Estimate.	4.656	\$377.30	\$1,756.71
	0190		PIPE AGGREGAT ENT EDGE DRA				-215	\$65.20	(\$14,018.00
	0190		PIPE AGGREGAT ENT EDGE DRA			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.	215	\$65.20	\$14,018.00
	0200		MIS	C. Material			-416	\$134.75	(\$56,056.00
	0200		MIS	C. Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 7 on the current Payment Estimate.	416	\$134.75	\$56,056.00
	0650		MIS	C. Material			-6	\$113.00	(\$678.00)
	0650		MIS	C. Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 8 on the current Payment Estimate.	6	\$113.00	\$678.00
	0660		MIS	C. Material			-74	\$64.75	(\$4,791.50)
	0660		MIS	C. Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate.	74	\$64.75	\$4,791.50
	0800		MIS	C. Material			-4	\$1,530.00	(\$6,120.00
	0800		MIS	C. Material		This adjustment offsets the original system-	4	\$1,530.00	\$6,120.00



Pr	Number 10 Prime		Prime L	11015-C05 eavenworth Ex company, Inc.	cavating & Eq	Pay Period Start uipment Pay Period End	October 16, 2022 November 1, 2022	Original Cor Amount Net Change Amount Current Con Amount	Order (\$2,205,533.07 (\$6,321.28) \$2,199,211.79	
Project Number	Line No.	Item	Description	Adjustment Type	Other Item Adjustment Type	Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
4S3273						generated Material Payme Adjustment (0009) due overridding Payment Estima on the current Pa	to user schwaj2 ate Exception 10				
	1070	SIGNA	L HEAD, TYPE 38	6 Material				-1	\$900.00	(\$900.00	
	1070	SIGNA	AL HEAD, TYPE 35	6 Material		This adjustment offsets the generated Material Payme Adjustment (0010) due overridding Payment Estima on the current Pa	nt Estimate Item to user schwaj2 ate Exception 11	1	\$900.00	\$900.00	
	1080	SIGNA	L HEAD, TYPE 30	C Material				-3	\$940.00	(\$2,820.00	
	1080	SIGNA	L HEAD, TYPE 30	C Material		This adjustment offsets the generated Material Payme Adjustment (0011) due overridding Payment Estima on the current Pa	nt Estimate Item to user schwaj2 ate Exception 12	3	\$940.00	\$2,820.00	
	1090	SIGNA	L HEAD, TYPE 40	C Material				-1	\$1,235.00	(\$1,235.00)	
	1090	SIGNA	IL HEAD, TYPE 40	C Material		This adjustment offsets the generated Material Payme Adjustment (0012) due overridding Payment Estima on the current Pa	nt Estimate Item to user schwaj2 ate Exception 13	1	\$1,235.00	\$1,235.00	
	1100	SH-FLAT	SHEET - SIGNAL SIGN					-30	\$65.50	(\$1,965.00)	
	1100	SH-FLAT	r Sheet - Signai Sign			This adjustment offsets the generated Material Payme Adjustment (0013) due overridding Payment Estima on the current Pa	nt Estimate Item to user schwaj2 ate Exception 14	30	\$65.50	\$1,965.00	
	1120		NAIRE LED-A, 120 OLT COMPATIBLE					-2	\$640.00	(\$1,280.00	
	1120		NAIRE LED-A, 120 OLT COMPATIBLE			This adjustment offsets the generated Material Payme Adjustment (0014) due overridding Payment Estima on the current Pa	nt Estimate Item to user schwaj2 ate Exception 15	2	\$640.00	\$1,280.00	
	1130	FO	TEEL SPAN WIRE R 30 FT. OR 9.0 M NAIRE MOUNTING	1				-4	\$8,005.00	(\$32,020.00)	
	1130	FO	TEEL SPAN WIRE R 30 FT. OR 9.0 M NAIRE MOUNTING	1		This adjustment offsets the generated Material Payme Adjustment (0015) due overridding Payment Estima on the current Pa	nt Estimate Item to user schwaj2 ate Exception 16	4	\$8,005.00	\$32,020.00	
	1140		WIRE ASSEMBLY ESSENGER WITH TETHEF	Í				-407	\$22.10	(\$8,994.70)	
	1140		WIRE ASSEMBLY ESSENGER WITH TETHEF	Í		This adjustment offsets the generated Material Payme Adjustment (0016) due overridding Payment Estima on the current Pa	nt Estimate Item to user schwaj2 ate Exception 18	407	\$22.10	\$8,994.70	
	1150		DLLER ASSEMBLY JSING, NEMA TS2 CONTROLLEF	2				-0.5	\$16,320.00	(\$8,160.00)	
	1150	CONTRO	DLLER ASSEMBLY	/ Material		This adjustment offsets the	original system-	0.5	\$16,320.00	\$8,160.00	



Progress Estimate Number 10 Prime Contract ID Prime		Prime	211015-C05 Leavenworth Ex Company, Inc.	Leavenworth Excavating & Equipment			October 16, 2022 November 1, 2022	Original Cor Amount Net Change Amount Current Con Amount	order (\$	\$2,205,533.07 (\$6,321.28) \$2,199,211.79	
Project Number	Line No.	Item	Description	Adjustment Type	Other Item Adjustment Type		Comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J4S3273		HO	USING, NEMA ⁻ CONTROLL			Adjus overridding	tment (0017) due g Payment Estim	ent Estimate Item e to user schwaj2 ate Exception 19 ayment Estimate.			
	1200		JIT, 3 IN., TREN TH TRACER W						-31.5	\$30.45	(\$959.18
	1200		JIT, 3 IN., TREN TH TRACER W			generateo Adjus overridding	d Material Payme tment (0018) due g Payment Estim	e original system- ent Estimate Item e to user schwaj2 ate Exception 20 ayment Estimate.	31.5	\$30.45	\$959.18
	1220		CABLE, 10 AW ICTOR, POLE A BRACH	ND					-160	\$1.60	(\$256.00
	1220	CONDU	CABLE, 10 AW ICTOR, POLE A BRACH	ND		generateo Adjus overridding	d Material Payme tment (0019) due g Payment Estim	e original system- ent Estimate Item e to user schwaj2 ate Exception 21 ayment Estimate.	160	\$1.60	\$256.00
	1230	CON	CABLE, 8 AW DUCTOR, POW						-45	\$1.75	(\$78.75
	1230	CON	CABLE, 8 AW DUCTOR, POW			generateo Adjus overridding	d Material Payme tment (0020) due g Payment Estim	e original system- ent Estimate Item e to user schwaj2 ate Exception 22 ayment Estimate.	45	\$1.75	\$78.75
	1240		CABLE, 12 AW CONDUCT						-315	\$1.70	(\$535.50
	1240		CABLE, 12 AW CONDUCT			generateo Adjus overridding	d Material Payme tment (0021) due g Payment Estim	e original system- ent Estimate Item e to user schwaj2 ate Exception 23 ayment Estimate.	315	\$1.70	\$535.50
	1280		POWER SUPF BLY, TYPE-2 W GHTING CONTF CABIN	ITH ROL					-0.5	\$4,000.00	(\$2,000.00
	1280		POWER SUPF BLY, TYPE-2 W GHTING CONTF CABIN	ITH ROL		generateo Adjus overridding	d Material Payme tment (0022) due g Payment Estim	e original system- ent Estimate Item e to user schwaj2 ate Exception 24 ayment Estimate.	0.5	\$4,000.00	\$2,000.00
Total											\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J4S3273	FAF 58-1(18)	Intersection improvements, resurfacing and coldmilling	58	CASS	at the intersection of Route 58 and Ward Rd., at the intersection of Route 58 and Route 291, and from e/o Prairie to Route 291 near Raymore							

Totals	by	Job	Numbers	
--------	----	-----	---------	--

J4S3273	This Estimate	Previous	To Date
Posted Item Pay	\$20,343.20	\$1,732,936.21	\$1,753,279.41
Gross Item Adjustments	\$0.00	\$55,599.40	\$55,599.40
Gross Item Pa	ay \$20,343.20	\$1,788,535.61	\$1,808,878.81
Incentive	\$0.00	\$30,000.00	\$30,000.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			1
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 2037075, Project Item Line Number 0050, Material Set 203707596, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	Remaining test have been performed, awaiting testing reports from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 3040506, Project Item Line Number 0100, Material Set 304050696, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Remaining test have been performed, awaiting testing reports from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 4071005, Project Item Line Number 0150, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Awaiting certifications from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 5021332, Project Item Line Number 0160, Material Set 502133296, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Awaiting PAL number confirmation from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 6053030A, Project Item Line Number 0190, Material Set 6053030A96, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Awaiting Central to address PAL number issue.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 6053030A, Project Item Line Number 0190, Material Set 6053030A96, Material 1011GXT1 - Geotextile Fabric for SubsrfDrainage(T1), Acceptance Action Generic 1011GXT1 is insufficient.	Awaiting certifications from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 6089905, Project Item Line Number 0200, Material Set 608990596, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	Received PAL number submission, awaiting Central to verify.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 7259903, Project Item Line Number 0650, Material Set 725990396, Material 1013DMCRPE04 - Underdrain Corrugated PE 4" (100mm), Acceptance Action Generic 1013DMCRPE04 is insufficient.	Received PAL number submission, awaiting Central to verify.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 7259903, Project Item Line Number 0660, Material Set 725990396, Material 1013DMCRPE06 - Underdrain Corrugated PE 6" (150mm), Acceptance Action Generic 1013DMCRPE06 is insufficient.	Received PAL number submission, awaiting Central to verify.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 7329902, Project Item Line Number 0800, Material Set 7329902, Material 1032ESRCF - Conc End Section for Round Pipe, Acceptance Action Generic 1032ESRCF is insufficient.	Awaiting Materials reporting.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9020213, Project Item Line Number 1070, Material Set 902021396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Awaiting submissions from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9020413, Project Item Line Number 1080, Material Set 902041396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Awaiting submissions from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9020414, Project Item Line Number 1090, Material Set 902041496, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Awaiting submissions from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9020833, Project Item Line Number 1100, Material Set 902083396, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient.	Awaiting reporting by Central.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9022651, Project Item Line Number 1120, Material Set 902265196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Working with Materials to confirm if prior submission is correct.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9023502, Project Item Line Number 1130, Material Set 902350296, Material 0902TSSWPS - Span Wire for Traffic Signal Post, Acceptance Action Generic 0902TSSWPS is insufficient.	Awaiting submissions from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9023502, Project Item Line Number 1130, Material Set 902350296, Material 1092TSPS - Traffic Signal Post(s) - All Types, Acceptance Action Generic 1092TSPS is insufficient.	Awaiting submissions from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9023602, Project Item Line Number 1140, Material Set 902360296, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Awaiting submissions from contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9024283, Project Item Line Number 1150, Material Set 902428396, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Awaiting submissions from the contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9025300, Project Item Line Number 1200, Material Set 902530096, Material 1060EC - Electrical Conduit Material, Acceptance Action Generic 1060EC is insufficient.	Awaiting submissions from the contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9028100, Project Item Line Number 1220, Material Set 902810096, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Awaiting submissions from the contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9028208, Project Item Line Number 1230, Material Set 902820896, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Awaiting submissions from the contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9028302, Project Item Line Number 1240, Material Set 902830296, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic 0902TSXX is insufficient.	Awaiting submissions from the contractor.	schwaj2	Overridden
Estimate Exception Type: Insufficient Materials: Project J4S3273, Item 9028621, Project Item Line Number 1280, Material Set 902862196, Material 0902TSXX - Traffic Signals Material, Acceptance Action Generic	Awaiting submissions from the contractor.	schwaj2	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status	
0902TSXX is insufficient.				



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

d date and can differ from the posted amount at the time the Estimate was Generated.

Contract Im.CONTRACT	Project No.	Category	Line No.	ltem Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1015-C05	J4S3273	0001	0010	2013000	CLEARING AND GRUBBING	1.00	0.00	1.00	ACRE	1.00	\$3,555.00	\$3,555.0
		0001	0020	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.90	\$102,955.00	\$92,659.5
		0001	0030	2031000	CLASS A EXCAVATION	5,437.00	0.00	5,437.00	CUYD	4,967.00	\$26.50	\$131,625.
		0001	0040	2036000	COMPACTING EMBANKMENT	1,723.00	0.00	1,723.00	CUYD	1,723.00	\$2.00	\$3,446.
		0001	0050	2037075	COMPACTING IN CUT	23.60	0.00	23.60	STA	23.00	\$500.00	\$11,500.
		0001	0060	2063000	CLASS 3 EXCAVATION	499.00	0.00	499.00	CUYD	499.00	\$3.00	\$1,497.
		0001	0070	2063500	CULVERT CLEANOUT	17.00	0.00	17.00	EA	17.00	\$2,100.00	\$35,700.
		0001	0080	2072000	LINEAR GRADING CLASS 2	1.30	0.00	1.30	STA	0.00	\$2,720.00	\$0.
		0001	0090	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	42.00	0.00	42.00	SQYD	42.00	\$44.00	\$1,848.
		0001	0100	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	7,843.00	0.00	7,843.00	SQYD	6,915.00	\$16.00	\$110,640.
		0001	0110	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	4.00	0.00	4.00	TONS	4.00	\$793.40	\$3,173.
		0001	0120	4013000	BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE)	9.90	0.00	9.90	TONS	9.90	\$656.37	\$6,498.
		0001	0130	4019905	MISC.OPTIONAL PAVEMENT	6,852.00	0.00	6,852.00	SQYD	5,196.00	\$44.16	\$229,455.
		0001	0140	4030101	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP125C MIX)	3,740.40	0.00	3,740.40	TONS	2,774.03	\$61.40	\$170,325.
		0001	0150	4071005	TACK COAT	3,845.00	0.00	3,845.00	GAL	2,802.00	\$2.50	\$7,005.
		0001	0160	5021332	CONCRETE PAVEMENT (8 1/2 IN. NON-REINFORCED, 15 FT.	15.30	0.00	15.30	SQYD	5.40	\$377.30	\$2,037.
		0001	0170	5029905	JOINTS) MISC.8.5 IN. TINTED CONCRETE TRUCK APRON	741.00	0.00	741.00	SQYD	479.00	\$129.10	\$61,838.
		0001	0180	6029902	MISC.WITNESS POST ASSEMBLIES	34.00	0.00	34.00	EA	0.00	\$50.00	\$0.
		0001	0190	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	398.00	0.00	398.00	LF	215.00	\$65.20	\$14,018.
		0001	0200	6089905	MISC.8 IN. STAMPED CONCRETE MEDIAN STRIP	496.00	0.00	496.00	SQYD	416.00	\$134.75	\$56,056
		0001	0210	6092011	INTEGRAL CURB (6 IN. HEIGHT AND UNDER) TYPE A	440.00	0.00	440.00	LF	236.00	\$23.10	\$5,451
		0001	0220	6096010A	FURNISHING TYPE 1 ROCK DITCH LINER	2.00	0.00	2.00	CUYD	0.00	\$80.50	\$0.
		0001	0230	6096041	PLACING TYPE 1 ROCK DITCH LINER	2.00	0.00	2.00	CUYD	0.00	\$159.00	\$0.
		0001	0240	6097000	ROCK LINING	92.00	0.00	92.00	CUYD	92.00	\$106.00	\$9,752
		0001	0250	6099903	MISC.MOD. APWA CURB & GUTTER, TYPE CG-2	767.00	0.00	767.00	LF	333.00	\$28.25	\$9,407
		0001	0260	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$250.00	\$0.
		0001	0270	6141024	GRATE AND BEARING PLATE (5 FT. X 3 FT. OR 1524 MM X 914	1.00	0.00	1.00	EA	1.00	\$2,475.00	\$2,475
					MM)							
		0001	0280	6141028	GRATE AND BEARING PLATE (5 FT. 1 IN. X 3 FT. 1 IN. OR 1549 MM X 940 MM)	1.00	0.00	1.00	EA	1.00	\$3,520.00	\$3,520.
		0001	0290	6141120	CURVED VANE GRATE AND FRAME (2 FT. X 2 FT. OR 600MM X 600MM)	6.00	0.00	6.00	EA	6.00	\$465.00	\$2,790.
		0001	0300	6141121	CURVED VANE GRATE AND FRAME (4 FT. X 2 FT. OR 1200MM X 600MM)	2.00	0.00	2.00	EA	2.00	\$900.00	\$1,800.
		0001	0310	6149902	MISC.MONUMENT BOX	2.00	0.00	2.00	EA	0.00	\$900.00	\$0.
		0001	0320	6161005	CONSTRUCTION SIGNS	2,284.00	0.00	2,284.00	SQFT	1,842.00	\$5.00	\$9,210.
		0001	0330	6161008	ADVANCED WARNING RAIL SYSTEM	10.00	0.00	10.00	EA	10.00	\$50.00	\$500.
		0001	0340	6161025	CHANNELIZER (TRIM LINE)	150.00	0.00	150.00	EA	125.00	\$15.00	\$1,875.
		0001	0350	6161030	TYPE III MOVEABLE BARRICADE	27.00	0.00	27.00	EA	14.00	\$150.00	\$2,100
		0001	0360	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	8.00	0.00	8.00	EA	8.00	\$2,000.00	\$16,000
		0001	0370	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	8.00	0.00	8.00	EA	0.00	\$1,500.00	\$0.
		0001	0380	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	4.00	0.00	4.00	EA	0.00	\$1,700.00	\$0.
		0001	0390	6169902	MISC.TEMPORARY ENTRANCE	1.00	0.00	1.00	EA	1.00	\$2,300.00	\$2,300
		0001	0400	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$211,685.00	\$211,685
		0001	0410	6181020	ADDITIONAL MOBILIZATION FOR SEEDING	4.00	0.00	4.00	EA	0.00	\$600.00	\$0
		0001	0420	6191000	PAVEMENT EDGE TREATMENT	1,221.00	0.00	1,221.00	LF	1,221.00	\$13.85	\$16,910
		0001	0430	6200012	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 12 IN	38.00	0.00	38.00	LF	38.00	\$8.00	\$304.
					WHITE							
		0001	0440	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	169.00	0.00	169.00	LF	0.00	\$16.00	\$0.



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Vote: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

VELLOW VELLOW Ice I	Total Value POSTED To Date (See report generated date) 00 \$1,024.00
211015-C05 J4\$3273 0001 0450 620018 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. 144.00 0.00 144.00 LF 664.00 \$31 0001 0460 620021 PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. 13.00 0.00 13.00 LF 0.00 \$25 0001 0460 620021 PREFORMED THERMOPLASTIC PAVEMENT MARKING, APE 4 IN., WHITE 4,747.00 0.00 4,747.00 LF 0.00 \$ 0001 0470 6205303B TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW 5,146.00 0.00 5,146.00 LF 0.00 \$ 0001 0480 6205303 TEMPORARY REMOVABLE MARKING TAPE, 12 IN., WHITE 148.00 0.00 148.00 LF 0.00 \$ 0001 0480 6205302 TEMPORARY REMOVABLE MARKING TAPE, 12 IN., WHITE 148.00 0.00 2,910.00 LF 0.00 \$ 0001 0500 6205901A 1IN, YELLOW MICH BUILD WATERBORNE PAVEMENT 2,910.00 0.00 2,910.00 LF 0.00	00 \$1,024.00
LEFT/RIGHT ARROW LEFT/RIGHT ARROW <thleft arrow<="" th=""> LEFT/RIGHT ARROW</thleft>	
0001 0480 6205303 TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW 5,146.00 0.00 5,146.00 LF 0.00 \$ 0001 0490 6205303 TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW 5,146.00 0.00 5,146.00 LF 0.00 \$ 0001 0490 6205320 TEMPORARY REMOVABLE MARKING TAPE, 12 IN., WHITE 148.00 0.00 148.00 LF 0.00 \$ 0001 0500 6205901A 4.IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT 2,910.00 0.00 2,910.00 LF 0.00 \$ 0001 0510 6205902A 6.IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING 2,555.00 0.00 2,555.00 LF 0.00 \$ 0001 0510 6206902A 6.IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 2,6376.00 0.00 2,6376.00 LF 10.00 \$ 0001 0520 6206002 4.IN. YELLOW STANDARD WATERBORNE PAVEMENT 21,719.00 0.00 24,719.00 LF 13,224.00 \$ 0001 </td <td>00 \$0.00</td>	00 \$0.00
0001 0490 6205320 TEMPORARY REMOVABLE MARKING TAPE, 12 IN., WHITE 148.00 0.00 148.00 LF 0.00 \$ 0001 0500 6205901A 4.IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT 2,910.00 0.00 2,910.00 LF 0.00 \$ 0001 0510 6205902A 6.IN. WHITE HIGH BUILD WATERBORNE PAVEMENT 2,910.00 0.00 2,955.00 LF 0.00 \$ 0001 0510 6205902A 6.IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING 2,555.00 0.00 2,555.00 LF 0.00 \$ 0001 0520 6206000C 4.IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 26,376.00 0.00 26,376.00 LF 16,959.00 \$ 0001 0520 6206000C 4.IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 26,376.00 0.00 21,719.00 LF 13,224.00 \$ 0001 0540 6206108A 8.IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 845.00 0.00 845.00 LF 0.00 \$ <t< td=""><td>35 \$0.00</td></t<>	35 \$0.00
Notice Construint Construint<	35 \$0.00
MARKING PAINT, TYPE L BEADS 0001 0510 6205902A 6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING 2,555.00 0.00 2,555.00 LF 0.00 \$ 0001 0520 6206000C 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 26,376.00 0.00 26,376.00 LF 16,959.00 \$ 0001 0530 6206001C 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT 21,719.00 0.00 21,719.00 LF 13,224.00 \$ 0001 0540 6206100A 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 845.00 0.00 845.00 LF 0.00 \$ 0001 0540 6206108A 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 845.00 0.00 845.00 LF 0.00 \$ 0001 0550 6207001 PAVEMENT MARKING REMOVAL 11,872.00 LF 0.00 \$	00 \$0.00
No. PAINT, TYPE L BEADS PAINT, TYPE L BEADS PAINT, TYPE L BEADS PAINT, TYPE L BEADS 0001 0520 6206000C 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 26,376.00 0.00 26,376.00 LF 16,959.00 \$ 0001 0530 6206001C 4 IN. VELLOW STANDARD WATERBORNE PAVEMENT 21,719.00 0.00 21,719.00 LF 13,224.00 \$ 0001 0540 6206108A 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 845.00 0.00 845.00 LF 0.00 \$ 0001 0550 6207001 PAVEMENT MARKING REMOVAL 11,872.00 0.00 11,872.00 LF 0.00 \$	35 \$0.00
OOD1 0530 6206001C 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS 21,719.00 0.00 21,719.00 LF 13,224.00 \$ 0001 0540 6206102 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 845.00 0.00 845.00 LF 0.00 \$ 0001 0550 6207001 PAVEMENT MARKING REMOVAL 11,872.00 0.00 11,872.00 LF 0.00 \$	50 \$0.00
MARKING PAINT, TYPE P BEADS MARKING PAINT, TYPE P BEADS MARKING PAINT, TYPE P BEADS 0001 0540 6206108A 8 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING 845.00 0.00 845.00 LF 0.00 \$ 0001 0550 6207001 PAVEMENT MARKING REMOVAL 11,872.00 0.00 11,872.00 LF 0.00 \$	07 \$1,187.13
ODD1 0550 6207001 PAVEMENT MARKING REMOVAL 11,872.00 0.00 11,872.00 LF 0.00 \$	07 \$925.68
	20 \$0.00
	40 \$0.00
0001 0560 6207002 PAVEMENT MARKING REMOVAL (SYMBOLS) 6.00 0.00 6.00 EA 0.00 \$10	00 \$0.00
0001 0570 6209902 MISC.TEMPORARY REMOVABLE MARKING TAPE LEFT OR 6.00 0.00 6.00 EA 0.00 \$10	00 \$0.00
0001 0580 6209903 MISC.PERFORMED THERMOPLASTIC PAVEMENT MARKING, 6 36.00 0.00 36.00 LF 0.00 \$	00 \$0.00
0001 0590 6221001 COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF 38,437.00 0.00 38,437.00 SQYD 27,527.00 \$	37 \$37,711.99
0001 0600 6261000A BITUMINOUS SHOULDER RUMBLE STRIP 157.00 0.00 157.00 STA 140.00 \$3	00 \$4,200.00
0001 0610 6274000 CONTRACTOR FURNISHED SURVEYING AND STAKING 1.00 0.00 1.00 LS 0.80 \$5,00	00 \$4,000.00
0001 0620 7250315A 15 IN. PIPE GROUP B 89.00 0.00 89.00 LF 89.00 \$10	00 \$9,256.00
0001 0630 7250415 15 IN. PIPE GROUP C 44.00 0.00 44.00 LF 44.00 \$10	00 \$4,664.00
0001 0640 7250418 18 IN. PIPE GROUP C 19.00 19.00 19.00 LF 19.00 \$11	00 \$2,090.00
0001 0650 7259903 MISC.4 IN. GROUP B PIPE 18.00 0.00 18.00 LF 6.00 \$11	00 \$678.00
0001 0660 7259903 MISC.6 IN. GROUP B PIPE 96.00 0.00 96.00 LF 74.00 \$6	75 \$4,791.50
0001 0670 7269902 MISC.18 IN. REINFORCED PRECAST FLARED END SECTION 4.00 0.00 4.00 EA 4.00 \$1,65	00 \$6,600.00
0001 0680 7269902 MISC.68 IN. X 43 IN. ELLIPTICAL REINFORCED PRECAST 2.00 0.00 2.00 EA 2.00 \$5,60	00 \$11,200.00
0001 0690 7269903 MISC.12 IN. CLASS IV REINFORCED CONCRETE PIPE 60.00 0.00 LF 60.00 LF 60.00 \$	00 \$4,020.00
0001 0700 7269903 MISC.15 IN. CLASS IV REINFORCED CONCRETE PIPE 305.00 0.00 305.00 LF 305.00 \$	00 \$24,400.00
0001 0710 7269903 MISC.18 IN. CLASS IV REINFORCED CONCRETE PIPE 173.00 0.00 173.00 LF 173.00 \$	00 \$14,186.00
0001 0720 7269903 MISC.68 IN. X 43 IN. ELLIPTICAL CLASS III REINFORCED 56.00 0.00 56.00 LF 56.00 \$39	00 \$21,840.00
0001 0730 7311022 PRECAST CONCRETE DROP INLET 2 FT X 2 FT 23.00 0.00 23.00 FT 23.00 \$	00 \$20,470.00
0001 0740 7311042 PRECAST CONCRETE DROP INLET 4 FT X 2 FT 7.00 0.00 7.00 FT 7.00 \$99	00 \$6,965.00
0001 0750 7311053 PRECAST CONCRETE DROP INLET 5 FT X 3 FT 8.00 0.00 8.00 FT 8.00 \$1,01	00 \$8,080.00
0001 0760 7320015A 15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END 2.00 0.00 2.00 EA 2.00 \$1,13	00 \$2,260.00
0001 0770 7320815A 15 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END 4.00 0.00 4.00 EA 4.00 \$1,13	00 \$4,520.00
0001 0780 7320818A 18 IN. OR ALLOWED SUBSTITUTE GROUP C FLARED END 2.00 0.00 2.00 EA 2.00 \$1,18	00 \$2,370.00
0001 0790 7329902 MISC.12 IN. REINFORCED PRECAST FLARED END SECTION 2.00 0.00 2.00 EA 2.00 \$1,53	00 \$3,060.00
0001 0800 7329902 MISC.15 IN. REINFORCED PRECAST FLARED END SECTION 4.00 0.00 4.00 EA 4.00 \$1,53	00 \$6,120.00
0001 0810 7349903 MISC.4 IN. TRENCH DRAIN 171.00 0.00 171.00 LF 171.00 \$33	00 \$56,772.00
0001 0820 7350001 PIPE LINER FOR EXISTING CULVERT 40.0 0.00 40.00 LF 40.00 \$39	00 \$15,760.00
0001 0830 8051000A SEEDING - COOL SEASON GRASSES 1.50 0.00 1.50 ACRE 1.00 \$1,95	00 \$1,950.00
0001 0840 8061004 SEDIMENT TRAP ROCK 46.90 0.00 46.90 CUYD 35.00 \$12	00 \$4,375.00
0001 0850 8061006 ALTERNATE DITCH CHECK 465.00 0.00 465.00 LF 400.00 \$2	00 \$9,600.00
0001 0860 8061007A CURB INLET CHECK 15.00 0.00 15.00 EA 0.00 \$18	00 \$0.00
0001 0870 8061016 SEDIMENT REMOVAL 147.00 0.00 147.00 CUYD 0.00 \$4	00 \$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211015-C05	J4S3273	0001	0880	8061019	SILT FENCE	2,373.00	0.00	2,373.00	LF	2,216.00	\$3.60	\$7,977.60
		0001	0890	8064129	TYPE 2 TURF REINFORCEMENT MAT	2,180.00	0.00	2,180.00	SQYD	2,180.00	\$4.56	\$9,940.80
		0020	0900	9011030	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	11.00	0.00	11.00	EA	11.00	\$2,015.00	\$22,165.00
		0020	0910	9011110	BRACKET ARM, 10 FT. OR 3.0 M	3.00	0.00	3.00	EA	3.00	\$845.00	\$2,535.00
		0020	0920	9011115	BRACKET ARM, 15 FT. OR 4.6 M	6.00	0.00	6.00	EA	6.00	\$1,025.00	\$6,150.00
		0020	0930	9011311	LUMINAIRE, LED-A	9.00	0.00	9.00	EA	9.00	\$640.00	\$5,760.00
		0020	0940	9012230	BASE MOUNTED CONTROL STATION 240 VOLT - 4 CIRCUIT	1.00	0.00	1.00	EA	1.00	\$7,225.00	\$7,225.00
		0020	0950	9013002	CONDUIT, 2 IN. RIGID, IN TRENCH	994.00	0.00	994.00	LF	994.00	\$8.20	\$8,150.80
		0020	0960	9013003	CONDUIT, 3 IN. RIGID, IN TRENCH	114.00	0.00	114.00	LF	114.00	\$13.85	\$1,578.90
		0020	0970	9013004	CONDUIT, 4 IN. RIGID, IN TRENCH	14.00	0.00	14.00	LF	14.00	\$27.40	\$383.60
		0020	0980	9015010	TRENCHING TYPE I	1,092.00	0.00	1,092.00	LF	1,092.00	\$11.90	\$12,994.80
		0020	0990	9016110	PULL BOX, PREFORMED CLASS 1	5.00	0.00	5.00	EA	5.00	\$1,050.00	\$5,250.00
		0020	1000	9017002	CABLE, 2 AWG 1 CONDUCTOR	210.00	0.00	210.00	LF	210.00	\$5.15	\$1,081.50
		0020	1010	9017008	CABLE, 8 AWG 1 CONDUCTOR	2,920.00	0.00	2,920.00	LF	2,920.00	\$1.95	\$5,694.00
		0020	1020	9017110	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	790.00	0.00	790.00	LF	790.00	\$1.65	\$1,303.50
		0020	1030	9017202	WIRE, 2 AWG, BARE NEUTRAL	100.00	0.00	100.00	LF	100.00	\$4.40	\$440.00
		0020	1040	9017208	WIRE, 8 AWG, BARE NEUTRAL	1,460.00	0.00	1,460.00	LF	1,460.00	\$1.80	\$2,628.00
		0020	1050	9018230	POLE FOUNDATION (30 FT. OR 9.0 M MOUNTING HEIGHT)	11.00	0.00	11.00	EA	11.00	\$1,220.00	\$13,420.00
		0020	1060	9018612	POWER SUPPLY ASSEMBLY, TYPE 2, 240/120 VOLT SERVICE, LIGHTING ONLY	1.00	0.00	1.00	EA	0.00	\$5,600.00	\$0.00
		0030	1070	9020213	SIGNAL HEAD, TYPE 3S	2.00	0.00	2.00	EA	1.00	\$900.00	\$900.00
		0030	1080	9020413	SIGNAL HEAD, TYPE 3C	6.00	0.00	6.00	EA	3.00	\$940.00	\$2,820.00
		0030	1090	9020414	SIGNAL HEAD, TYPE 4C	2.00	0.00	2.00	EA	1.00	\$1,235.00	\$1,235.00
		0030	1100	9020833	SH-FLAT SHEET - SIGNAL SIGN	30.00	0.00	30.00	SQFT	30.00	\$65.50	\$1,965.00
		0030	1110	9020834	SIGNAL SIGN, MOUNTING HARDWARE	4.00	0.00	4.00	EA	0.00	\$176.00	\$0.00
		0030	1120	9022651	LUMINAIRE LED-A, 120 VOLT COMPATIBLE	4.00	0.00	4.00	EA	2.00	\$640.00	\$1,280.00
		0030	1130	9023502	POST, STEEL SPAN WIRE, FOR 30 FT. OR 9.0 M LUMINAIRE MOUNTING	4.00	0.00	4.00	EA	4.00	\$8,005.00	\$32,020.00
		0030	1140	9023602	SPAN WIRE ASSEMBLY, MESSENGER WITH TETHER	407.00	0.00	407.00	LF	407.00	\$22.10	\$8,994.70
		0030	1150	9024283	CONTROLLER ASSEMBLY HOUSING, NEMA TS2 CONTROLLER	1.00	0.00	1.00	EA	0.50	\$16,320.00	\$8,160.00
		0030	1160	9024944	DETECTOR, VEHICLE INDUCTION LOOP (2 CHANNEL - RACK MOUNTED)	4.00	0.00	4.00	EA	0.00	\$197.00	\$0.00
		0030	1170	9024975	VIDEO DETECTION SYSTEM	1.00	-1.00	0.00	EA	0.00	\$22,030.00	\$0.00
		0030	1180	9025020	CONDUIT, 1 IN., LOOP DETECTOR WITH TRACER WIRE	104.00	-104.00	0.00	LF	0.00	\$18.10	\$0.00
		0030	1190	9025200	CONDUIT, 2 IN., TRENCH WITH TRACER WIRE		-1,098.00	0.00	LF	0.00	\$17.75	\$0.00
		0030	1200	9025300	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	63.00	0.00	63.00	LF	31.50	\$30.45	\$959.18
		0030	1210	9027400	CONDUIT, 4 IN., PUSHED WITH TRACER WIRE	131.00	-131.00	0.00	LF	0.00	\$30.20	\$0.00
		0030	1220	9028100	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRACKET	320.00	0.00	320.00	LF	160.00	\$1.60	\$256.00
		0030	1230	9028208	CABLE, 8 AWG 1 CONDUCTOR, POWER	90.00	0.00	90.00	LF	45.00	\$1.75	\$78.75
		0030	1240	9028302	CABLE, 12 AWG 2 CONDUCTOR	630.00	0.00	630.00	LF	315.00	\$1.70	\$535.50
		0030	1250	9028311	CABLE, 16 AWG 7 CONDUCTOR	1,350.00	0.00	1,350.00	LF	0.00	\$2.30	\$0.00
		0030	1260	9028500	CABLE, LOOP DETECTOR, IN DUCT		-1,100.00	0.00	LF	0.00	\$5.40	\$0.00
		0030	1270	9028510	CABLE, LOOP DETECTOR, LEAD-IN		-2,370.00	0.00	LF	0.00	\$1.60	\$0.00
		0030 1280 9028621 POWER SUPPLY ASSEMBLY, TYPE-2 WITH 120V LIGHTING		1.00	0.00	1.00	EA	0.50	\$4,000.00	\$2,000.00		
		0030	1290	9028810	CONTROL CABINET PULL BOX, PREFORMED CLASS 1	6.00	-6.00	0.00	EA	0.00	\$870.00	\$0.00
					PULL BOX, PREFORMED CLASS 3	1.00	0.00	1.00	EA	1.00	\$1,920.00	\$1,920.00
		0030	1310	9029100	BASE, CONCRETE	14.50	0.00	14.50	CUYD	14.50	\$1,880.00	\$27,260.00
		0000			,	. 1.00	0.00	. 4.00	-0.0	. 4.00	,000.00	ç_1,200.00

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Total Party An nems / An Estimates (including uns Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu	es are b	based on R	eport Generated date and can differ from the posted am	ount at the	time the E	stimate wa	s Gener	ated.				
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)		
211015-C05	J4S3273	0040	1330	9031241	BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	1.00	0.00	1.00	EA	1.00	\$406.00	\$406.00		
		0040	1340	9031270A	IN. PSST POST - 12 GA. 202.00 0.00 202.00 LF 165.00 \$26.00									
		0040	1350	9031271	OST ANCHOR FOR 2 IN. PSST - 12 GA. 69.00 0.00 69.00 LF 57.00 \$28.00									
		0040	1360	9031272	2.25 IN. PSST POST - 12 GA.	6.00	0.00	6.00	LF	6.00	\$27.50	\$165.00		
		0040	1370	9031280	2.5 IN. PSST POST - 12 GA.	41.00	0.00	41.00	LF	41.00	\$29.00	\$1,189.00		
		0040	1380	9031281	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	9.00	0.00	9.00	LF	9.00	\$85.00	\$765.00		
		0040	1390	9035004A	SH-FLAT SHEET 197.00 0.00 197.00 SQFT 172.00 \$24.00									
		0040	1400	9035011A	ST-STRUCTURAL	8.00	0.00	8.00	SQFT	8.00	\$29.00	\$232.00		
		0040	1410	9039902	MISC.RELOCATED SIGN ASSEMBLIES	10.00	0.00	10.00	EA	3.00	\$100.00	\$300.00		
		0050	1420	9109902	MISC.CCTV CAMERA ASSEMBLY, TOP MOUNTED, WITH CABLE	1.00	0.00	1.00	EA	0.00	\$6,010.00	\$0.00		
		0050	1430	9109902	MISC.OGL SUBSCRIBER WIRELESS RADIO WITH CABLE	1.00	0.00	1.00	EA	0.00	\$2,270.00	\$0.00		
		0050	1440	9109902	MISC.OGL SWITCH FURNISH AND INSTALL	1.00	0.00	1.00	EA	0.00	\$1,735.00	\$0.00		
		0030	5001	9024975	VIDEO DETECTION SYSTEM 0.00 1.00 EA 0.00 \$49,667.53									
		0030	5002	1046002	VALUE ENGINEERING	0.00	6,321.29	6,321.29	EA	0.00	\$1.00	\$0.00		
	Project J4S3273 - Total Value Posted to Date as of Report Generated Date											\$1,753,279.41		
211015-C05 Ove	rall - Total	Value Post	ted to Da	te as of Repo	ort Generated Date							\$1,753,279.41		



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project:	: J4S3273															
Line Number	Item Code	Description		DWR Date	DWR Approval Date	Quantity Posted	Units		Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance		Comments	
0060	2063000	CLASS 3 EXCAVATION		11/1/22	11/2/22	55.00	CUYD	See Line #0620, #0	700, #0750 for exact locations					DI-60, P-60, and P-61		
0280	6141028	GRATES AND BRG PLATES(5FT 1INX3F	T 1 IN)	11/1/22	11/2/22	1.00	EA			5+08.75	38.71' LT			Grate for DI-60		
0320	6161005	CONSTRUCTION SIGNS		11/1/22 11/2/22 180.00 S		SQFT		850+95.07		860+67.05		3 EA of the following s W020-1: Road Work / W020-4:1-Lane Rd W020-7: Flaggers R2-1: Work Zone 35 M	Ahead			
0340	6161025	CHANNELIZER (TRIM LINE)		11/1/22	11/2/22	25.00	EA			850+95.07		860+67.05				
0420	6191000	PAVEMENT EDGE TREATMENT		11/1/22	11/2/22	192.00	LF			850+95.07		860+67.05		Remaining rock wedg	e for 291/58 intersectio	on
0620	7250315A 7269903	15 IN. PIPE CULVERT GROUP B MISC. RIGID PIPE CULVERT		11/1/22	11/2/22	28.50 65.00	LF		71' LT to 5+78.22 Off 37.20' LT 45' LT to Sta. 5+08.75 Off 38.71' LT					P-60 P-60		
0750	7311053	PRECAST CONCRETE DROP INLET 5 FT	T X 3 FT	11/1/22	11/2/22	3.00	FT	3ta. 4+76.20 Oli 26.	45 ET to Stal 5+06.75 OII 36.71 ET	5+08.75	38.71'			DI-60		
0800	7329902	MISC. FLARED END SECTIONS		11/1/22	11/2/22	1.00	EA			5+78.22	LT 37.20' LT			FES for P-61		
The infor	mation be	elow this line are details for Cons	truction Sig	ans (if ap	plicable).										
Project	Line Number	DWR Date Total Quantity Posted For Date	DWR	Sign Ir	nformation		Station	n Log Mile	Location	1	lumber of Items	SF Each Sign		Special Sign	SF Each Special Sign	Total SF to Post
J4S3273	0320	June 9, 2022 1119	WO20-	-1 48x48	16.00			10.05	58E	1.0	10	16			5	16
				/BRIDGE/R/				10.129, 38.991,	58E, 58W, Ward Rd S	3.0	10	40	Deed O	osed Ahead		40
				-3 48x48 ED AHEAD	16.00 KO	AD		7.273	SOE, SOVV, Ward Rd S	3.0	iu	16	Road Ci	osed Anead		48
			WO20- CLOSE	-3 48x48 ED AHEAD	16.00 RO	AD		10.22, 39.086, 7.311	58E, 58W, Ward Rd S	3.0	10	16	Road CI	osed 500 FT		48
				le ??x??				11.350	MO 291N 50A	19	.50	1		50A - 50K) (31ea @		19.5
				IANTITY OF				12.941	MO 291S 50B	19	50	1	19.5sqin) 50A - 50K) (31ea @		19.5
			BY QU	IANTITY OF	SQUARE	FEET							19.5sqin)		
			Variab BY QU	le ??x?? IANTITY OF	1.00 SPEC	CIAL SIGN		13.134	MO 291N 50B	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @)		19.5
			Variab	le ??x??	1.00 SPEC	CIAL SIGN		13.323	MO 291N 50D	19	.50	1	Detour (50A - 50K) (31ea @		19.5
			Variab	IANTITY OF	1.00 SPEC	CIAL SIGN		13.324	MO 291N 50E	19	.50	1	19.5sqin Detour () 50A - 50K) (31ea @		19.5
			BY QU	IANTITY OF	SQUARE	FEET							19.5sqin)		
				le ??x?? IANTITY OF				13.333	MO 150E 50G	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @)		19.5
				le ??x?? IANTITY OF				13.514	MO 150E 50H	19	.50	1	Detour (19.5sgin	50A - 50K) (31ea @		19.5
			Variab	le ??x??	1.00 SPEC	CIAL SIGN		16.196	MO 150W 50A	19	.50	1	Detour (, 50A - 50K) (31ea @		19.5
				IANTITY OF				173.977	I-49N 50F	19	50	1	19.5sqin) 50A - 50K) (31ea @		19.5
				IANTITY OF				113.811	1-4314 301	19.	.50	1	19.5sqin			19.5
			Variab BY QU	le ??x?? IANTITY OF	1.00 SPEC	CIAL SIGN FEET		174.178	I-49N 50F	19	.50	1	Detour (19.5sgin	50A - 50K) (31ea @		19.5
				le ??x??				176.594	I-49N 50F	19	.50	1	Detour (50A - 50K) (31ea @		19.5
				IANTITY OF				176.849	I-49N 50G	19	.50	1	19.5sqin Detour (9 50A - 50K) (31ea @		19.5
			BY QU	IANTITY OF	SQUARE	FEET							19.5sqin)		
			Variab BY QU	le ??x?? IANTITY OF	1.00 SPEC	FEET		177.632	I-49N 50G	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @)		19.5
			Variab BY QU	le ??x?? IANTITY OF	1.00 SPEC	CIAL SIGN		177.851	I-49N 50G	19	.50	1	Detour (19.5sgin	50A - 50K) (31ea @		19.5
			Variab	le ??x??	1.00 SPEC	CIAL SIGN		177.968	I-49N 50H	19	.50	1		50A - 50K) (31ea @		19.5
				IANTITY OF				20.015	MO 150W 50D	19	50	1	19.5sqin) 50A - 50K) (31ea @		19.5
			BY QU	IANTITY OF	SQUARE	FEET							19.5sqin)		
			Variab BY QU	le ??x?? IANTITY OF	1.00 SPEC	FEET		20.125	MO 150W 50E	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @)		19.5
				le ??x?? IANTITY OF				35.285	MO 291S 50B	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @		19.5
			Variab	le ??x??	1.00 SPEC	CIAL SIGN		35.478	MO 291S 50B	19	.50	1	Detour (50A - 50K) (31ea @		19.5
				IANTITY OF				35.661	MO 291S 50B	19	50	1	19.5sqin) 50A - 50K) (31ea @		19.5
			BY QU	IANTITY OF	SQUARE	FEET							19.5sqin)		
				le ??x?? IANTITY OF				35.822	MO 291S 50C	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @)		19.5
			Variab BY OU	le ??x?? IANTITY OF	1.00 SPEC	CIAL SIGN		37.874	MO 291S 50F	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @		19.5
			WO20-	-1 48x48	16.00			38.845	58W	1.0	10	16	ro.oaqii	7		16
				/BRIDGE/R/					MO 2915, I-495							
				la 24x18 le ??x??				39.366, 9.105 4.227	MO 291S. I-49S MO 58E 56A	2.0		3	Detour (56A & 56B) (2ea @		6
			BY QU	IANTITY OF	SQUARE	FEET							32sqin)			
			Variab BY QU	le ??x?? IANTITY OF	1.00 SPEC	FEET		4.329	MO 58E 50J	19.	.50	1	Detour (19.5sqin	50A - 50K) (31ea @)		19.5
			Variab BY OU	le ??x?? IANTITY OF	1.00 SPEC	CIAL SIGN		4.430	MO 58E 50K	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @		19.5
			Variab	le ??x??	1.00 SPEC	CIAL SIGN		5.389	I-49S 50G	19	.50	1	Detour (50A - 50K) (31ea @		19.5
				IANTITY OF				5.533	I-49S 50G	10	.50	1	19.5sqin) 50A - 50K) (31ea @		19.5
			BY QU	IANTITY OF	SQUARE	FEET						·	19.5sqin)		
				le ??x?? IANTITY OF				5.652	I-49S 50J	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @)		19.5
			Variab	le ??x?? IANTITY OF	1.00 SPEC	CIAL SIGN		5.788	I-49S 50K	19	.50	1		50A - 50K) (31ea @		19.5
			R11-4	60x30 1	12.50 ROA	D		7.004	Ward Rd S	1.0	10	12.5	ra.osqin	7		12.5
			CLOSE	ED TO THR	U TRAFFIC	2										
				-1 48x48 /BRIDGE/R/		K AHEAD		7.235, .342	Ward Rd S, Emerald View Dr N	2.0	U	16				32
			Variab BY OU	le ??x?? IANTITY OF	1.00 SPEC	CIAL SIGN		7.350	I-49S 50A	19	.50	1	Detour (19.5sqin	50A - 50K) (31ea @		19.5
			Variab	le ??x??	1.00 SPEC	CIAL SIGN		9.324	MO 150E 50F	19	.50	1	Detour (50A - 50K) (31ea @		19.5
			BY QU	IANTITY OF -2 48x48	SQUARE	FEET		9.361, 4.047	MO 291N, 58E	2.0		16	19.5sqin)		32
			AHEAD		10.00 DE			0.001, 4.047		2.0		10				32
			R11-2	48x30 1	10.00 ROA	D		9.568, 38.412,	58E, 58W, Ward Rd S	3.0	10	10				30



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

ect	Line Number	DWK Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF Post
273		June 9, 2022		CLOSED		7.349						
				CONST-5 96x48 32.00 POINT OF PRESENCE		9.663, 38.507	58E, 58W	2.00	32			
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		9.674	MO 291N 56B	32.00	1	Detour (56A & 56B) (2ea @ 32sqin)		
				GO20-2 48x24 8.00 END ROAD		9.756, 38.6	58E, 58W	2.00	8			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		9.758, 38.602	58E, 58W	2.00	18			
				R11-4 60x30 12.50 ROAD		9.845, 38.655	58E, 58W	2.00	12.5			
				CLOSED TO THRU TRAFFIC Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		9.884	MO 291N 50A	19.50	1	Detour (50A - 50K) (31ea @		
				CONST-8 48x36 12.00 WORK		9.955, 38.75	58E, 58W	2.00	12	19.5sqin)		
				ZONE NO PHONE ZONE Variable ??x?? 1.00 SPECIAL SIGN		9.976	MO 291N 50A	19.50	1	Detour (50A - 50K) (31ea @		
				BY QUANTITY OF SQUARE FEET R11-4 60x30 12.50 ROAD			On barricade near Prairie Lane	1.00	12.5	19.5sqin)		
				CLOSED TO THRU TRAFFIC R11-4 60x30 12.50 ROAD			On barricade near school on East side of	1.00	12.5			
		August 31,	543	CLOSED TO THRU TRAFFIC WO8-17L 48x48 16.00 SHOULDER		0.050	Ward Rd WB 175th	1.00	16.00			
		2022		DROP-OFF (SYMBOL) WO20-7 48x48 16.00 FLAGGER		9.900	NB 291	1.00	16.00			
				(SYMBOL) WITH FLAGS WO20-1 48x48 16.00								
				ROAD/BRIDGE/RAMP WORK AHEAD		0.100	WB 175th	1.00	16.00			
				GO20-4a 18X12 1.5 PILOT CAR IN USE WAIT & FOLLOW		10.000	NB 291	1.00	1.50			
				GO20-4 36x18 4.50 PILOT CAR FOLLOW ME		10.000	NB 291	1.00	4.50			
				GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR		10.000	NB 291	1.00	8.75			
				GO20-2 48x24 8.00 END ROAD WORK		10.500	NB 291	1.00	8.00			
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		10.700	NB 291	1.00	16.00			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		11.500	EB 58	1.00	16.00			
				WO21-5 48x48 16.00 SHOULDER WORK AHEAD		11.600	EB 58	1.00	16.00			
				WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		11.700	EB 58	1.00	16.00			
				WO8-17L 48x48 16.00 SHOULDER DROP-OFF (SYMBOL)		11.800	EB 58	1.00	16.00			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		11.800	EB 58	1.00	5.00			
				CONST-5 96x48 32.00 POINT OF PRESENCE		38.800	SB 291	1.00	32.00			
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		38.900	SB 291	1.00	18.00			
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		39.000	SB 291	1.00	12.00			
				WO20-1 48x48 16.00		39.100	SB 291	1.00	16.00			
				ROAD/BRIDGE/RAMP WORK AHEAD W020-4 48x48 16.00 ONE LANE		39.100	SB 291	1.00	16.00			
				ROAD AHEAD WO3-4 8x48 16.00 BE		39.200	SB 291	1.00	16.00			
				PREPARED TO STOP W021-5 48x48 16.00 SHOULDER		39.200	SB 291	1.00	16.00			
				WORK AHEAD WO5-1 48x48 16.00		39.300	SB 291	1.00	16.00			
				ROAD/BRIDGE/RAMP NARROWS WO20-7 48x48 16.00 FLAGGER		39.300	SB 291	1.00	16.00			
				(SYMBOL) WITH FLAGS GO20-2 48x24 8.00 END ROAD		39.900	SB 291	1.00	8.00			
				WORK CONST-5 96x48 32.00 POINT OF		9.400	NB 291	1.00	32.00			
				PRESENCE CONST-7 72x36 18.00 RATE OUR		9.500	NB 291	1.00	18.00			
				WORK ZONE								
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		9.600	NB 291	1.00	12.00			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		9.700	NB 291	1.00	16.00			
				WO3-4 8x48 16.00 BE PREPARED TO STOP		9.800	NB 291	1.00	16.00			
				WO21-5 48x48 16.00 SHOULDER WORK AHEAD		9.800	NB 291	1.00	16.00			
				WO5-1 48x48 16.00 ROAD/BRIDGE/RAMP NARROWS		9.900	NB 291	1.00	16.00			
				WO8-17p 30x24 5.00 SHOULDER DROP-OFF (PLAQUE)		0.050	WB 175th	1.00	5.00			



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4S3273	0030	CLASS A EXCAVATION	Price FUEL	Туре	2	Jul 1, 2022	SYSTEM	\$1,180.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Jul 18, 2022	SYSTEM	\$160.65	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Oct 3, 2022	SYSTEM	\$680.00	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$2,020.65	
			Price FUEL	- Total				\$2,020.65	
	0030 -	Total						\$2,020.65	
	0040	COMPACTING EMBANKMENT	Material		3	Jul 18, 2022	SYSTEM	\$3,182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Jul 18, 2022	SYSTEM	(\$3,182.00)	
					4	Aug 2, 2022	SYSTEM	\$3,182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Aug 2, 2022	SYSTEM	(\$3,182.00)	
					5	Aug 16, 2022	SYSTEM	\$3,182.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$3,182.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0040 -	Total						\$0.00	
	0050	COMPACTING IN CUT	Material		3	Jul 18, 2022	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	Jul 18, 2022	SYSTEM	(\$7,400.00)	
					4	Aug 2, 2022	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Aug 2, 2022	SYSTEM	(\$7,400.00)	
					5	Aug 16, 2022	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$7,400.00)	
					6	Sep 2, 2022	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$7,400.00)	
					7	Sep 16, 2022	SYSTEM	\$7,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$7,400.00)	
					8	Oct 3, 2022	SYSTEM	\$11,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$11,500.00)	
					9	Oct 17, 2022	SYSTEM	\$11,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$11,500.00)	
					10	Nov 2, 2022	SYSTEM	\$11,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.



t I	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3 0	0050	COMPACTING IN CUT	Material		10	Nov 2, 2022	SYSTEM	(\$11,500.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
9	0050 -	Total						\$0.00	
C	0090	TYPE 5 AGGREGATE FOR BASE	Price FUEL		4	Aug 2, 2022	SYSTEM	\$10.84	Reference Item Price Adjustment Index Adjustment Type applied is FUEI
		D, IOL		- Total				\$10.84	
			Price FUEL	- Total				\$10.84	
9	0090 -	Total						\$10.84	
C	0100	TYPE 5 AGGREGATE FOR BASE (6 IN.	Material		3	Jul 18, 2022	SYSTEM	\$56,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payme Estimate Exception 3 on the current Payment Estimate.
		THICK)			3	Jul 18, 2022	SYSTEM	(\$56,000.00)	
					4	Aug 2, 2022	SYSTEM	\$81,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payme Estimate Exception 3 on the current Payment Estimate.
					4	Aug 2, 2022	SYSTEM	(\$81,840.00)	
					5	Aug 16, 2022	SYSTEM	\$81,840.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$81,840.00)	
					8	Oct 3, 2022	SYSTEM	\$6,064.83	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payme Estimate Exception 2 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$6,064.83)	
					9	Oct 17, 2022	SYSTEM	\$6,064.83	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payme Estimate Exception 2 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$6,064.83)	
					10	Nov 2, 2022	SYSTEM	\$6,064.83	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payme Estimate Exception 2 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$6,064.83)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
			Price FUEL		3	Jul 18, 2022	SYSTEM	\$1,384.60	Reference Item Price Adjustment Index Adjustment Type applied is FUE
					4	Aug 2, 2022	SYSTEM	\$638.89	Reference Item Price Adjustment Index Adjustment Type applied is FUE
				T .(.)	8	Oct 3, 2022	SYSTEM	\$703.80	Reference Item Price Adjustment Index Adjustment Type applied is FUE
			Duisser	- Total				\$2,727.29	
			Price FUEL	- Total				\$2,727.29	
	0100 -		0.11	1015		4 5	1.15	\$2,727.29	
C	0110	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Other Item Adjustment	ACAD Tot		Aug 2, 2022	schwaj2	\$35.34	AC adjustment for BP-1
			0.1	ACAD - Tota				\$35.34	
			Other Item	Adjustment -	Total			\$35.34	
9	0110 - 0120	BITUMINOUS		ACAD	4	Aug 2,	schwaj2	\$35.34 \$87.45	AC adjustment for Bit Base
C		PAVEMENT	Adjustment			2022			
(MIXTURE		ACAD Tet	al			¢07.45	
(MIXTURE PG64-22 (BAS	Othoritor	ACAD - Tota Adjustment -				\$87.45 \$87.45	



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J4S3273	0130	MISC.	Other Item Adjustment	ACAD	4	Aug 2, 2022	schwaj2	\$24,249.61	AC adjustment for Optional Pavement; includes adjustment for both SP190 lifts and the surface SP125 lift						
				ACAD - Tota	al			\$24,249.61							
			Other Item	Adjustment -	Total			\$24,249.61							
	0130 -	Total						\$24,249.61							
	0140	ASPHALTIC CONCRETE MIXTURE PG 64-22 (SP1	Other Item Adjustment	ACAD	6	Sep 2, 2022	schwaj2	\$26,557.87	AC adjustment for 58 resurfacing work. 8/12/22=\$7,320.95 8/13/22=\$12,574.26 8/14/22=\$6,662.66						
				ACAD - Tota	al			\$26,557.87							
			Other Item	Adjustment -	Total			\$26,557.87							
	0140 -	Total						\$26,557.87							
	0150	TACK COAT	Material		4	Aug 2, 2022	SYSTEM	\$5.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					4	Aug 2, 2022	SYSTEM	(\$5.00)							
					5	Aug 16, 2022	SYSTEM	\$5.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					5	Aug 16, 2022	SYSTEM	(\$5.00)							
							6	Sep 2, 2022	SYSTEM	\$7,005.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
								6	Sep 2, 2022	SYSTEM	(\$7,005.00)				
						7	Sep 16, 2022	SYSTEM	\$7,005.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
						7	Sep 16, 2022	SYSTEM	(\$7,005.00)						
					8	Oct 3, 2022	SYSTEM	\$7,005.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 3 on the current Payment Estimate.						
									8	Oct 3, 2022	SYSTEM	(\$7,005.00)			
						9	Oct 17, 2022	SYSTEM	\$7,005.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 3 on the current Payment Estimate.					
											9	Oct 17, 2022	SYSTEM	(\$7,005.00)	
								10	Nov 2, 2022	SYSTEM	\$7,005.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					10	Nov 2, 2022	SYSTEM	(\$7,005.00)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	0150 -	Total						\$0.00							
	0160	CONCRETE PAVEMENT (8 1/2 IN. NON-REINF,	Material		4	Aug 2, 2022	SYSTEM	\$2,037.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					4	4	4	Aug 2, 2022	SYSTEM	(\$2,037.42)					
					5	Aug 16, 2022	SYSTEM	\$2,037.42	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.						
					5	Aug 16, 2022	SYSTEM	(\$2,037.42)							
					10	Nov 2, 2022	SYSTEM	\$1,756.71	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payment Estimate Exception 4 on the current Payment Estimate.						
					10	Nov 2,	SYSTEM	(\$1,756.71)							



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
J4S3273	0160	CONCRETE	Material			2022								
		PAVEMENT (8 1/2 IN. NON-REINF,		- Total				\$0.00						
			Material - To	otal				\$0.00						
	0160 -	Total						\$0.00						
	0170	MISC.	Material		4	Aug 2, 2022	SYSTEM	\$61,838.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
					4	Aug 2, 2022	SYSTEM	(\$61,838.90)						
					5	Aug 16, 2022	SYSTEM	\$61,838.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 13 on the current Payment Estimate.					
					5	Aug 16, 2022	SYSTEM	(\$61,838.90)						
					6	Sep 2, 2022	SYSTEM	\$61,838.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					6	Sep 2, 2022	SYSTEM	(\$61,838.90)						
					7	Sep 16, 2022	SYSTEM	\$61,838.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
					7	Sep 16, 2022	SYSTEM	(\$61,838.90)						
				- Total				\$0.00						
			Material - To	otal				\$0.00						
	0170 -	Total			_			\$0.00						
	0190	PIPE AGGREGATE PAVEMENT EDGE DRAIN	Material		3	Jul 18, 2022	SYSTEM	\$14,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
								3	Jul 18, 2022	SYSTEM	(\$14,018.00)			
						4	Aug 2, 2022	SYSTEM	\$14,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schwaj2 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
					4	Aug 2, 2022	SYSTEM	(\$14,018.00)						
					5	Aug 16, 2022	SYSTEM	\$14,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
					5	Aug 16, 2022	SYSTEM	(\$14,018.00)						
					6	Sep 2, 2022	SYSTEM	\$14,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
					6	Sep 2, 2022	SYSTEM	(\$14,018.00)						
					7	Sep 16, 2022	SYSTEM	\$14,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate.					
					7	Sep 16, 2022	SYSTEM	(\$14,018.00)						
										8	Oct 3, 2022	SYSTEM	\$14,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$14,018.00)						
		9 Oct 17, SYSTEM \$14,018.00 This adjustment offsets the original system- 2022 Estimate Item Adjustment (0004) due to use	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate.											
					9	Oct 17, 2022	SYSTEM	(\$14,018.00)						
					10	Nov 2, 2022	SYSTEM	\$14,018.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.					



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J4S3273	0190	PIPE AGGREGATE	Material	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	10	Nov 2, 2022	SYSTEM	(\$14,018.00)												
		PAVEMENT EDGE DRAIN		- Total				\$0.00												
			Material - To	otal				\$0.00												
	0190 -	Total						\$0.00												
	0200	MISC. CONCRETE	Material		4	Aug 2, 2022	SYSTEM	\$56,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schwaj2 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
					4	Aug 2, 2022	SYSTEM	(\$56,056.00)												
					5	Aug 16, 2022	SYSTEM	\$56,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payment Estimate Exception 16 on the current Payment Estimate.											
					5	Aug 16, 2022	SYSTEM	(\$56,056.00)												
					6	Sep 2, 2022	SYSTEM	\$56,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 11 on the current Payment Estimate.											
						6	Sep 2, 2022	SYSTEM	(\$56,056.00)											
					7	Sep 16, 2022	SYSTEM	\$56,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 11 on the current Payment Estimate.											
									7	Sep 16, 2022	SYSTEM	(\$56,056.00)								
							8	Oct 3, 2022	SYSTEM	\$56,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 11 on the current Payment Estimate.									
						8	Oct 3, 2022	SYSTEM	(\$56,056.00)											
					9	Oct 17, 2022	SYSTEM	\$56,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 11 on the current Payment Estimate.											
					9	Oct 17, 2022	SYSTEM	(\$56,056.00)												
					10	Nov 2, 2022	SYSTEM	\$56,056.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
					10	Nov 2, 2022	SYSTEM	(\$56,056.00)												
				- Total				\$0.00												
			Material - To	otal				\$0.00												
	0200 -	Total						\$0.00												
	0210	INTEGRAL CURB (6 IN. HEIGHT AND UNDER)	Material	Material		4	Aug 2, 2022	SYSTEM	\$5,451.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schwaj2 overridding Payment Estimate Exception 21 on the current Payment Estimate.										
					4	Aug 2, 2022	SYSTEM	(\$5,451.60)												
					5	Aug 16, 2022	SYSTEM	\$5,451.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment Estimate Exception 20 on the current Payment Estimate.											
					5	Aug 16, 2022	SYSTEM	(\$5,451.60)												
																6	Sep 2, 2022	SYSTEM	\$5,451.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$5,451.60)												
					7	Sep 16, 2022	SYSTEM	\$5,451.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 13 on the current Payment Estimate.											
					7	Sep 16, 2022	SYSTEM	(\$5,451.60)												
				8	Oct 3, 2022	SYSTEM	\$5,451.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payment												



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks												
J4S3273	0210	INTEGRAL CURB (6 IN. HEIGHT	Material						Estimate Exception 12 on the current Payment Estimate.												
		AND UNDER)			8	Oct 3, 2022	SYSTEM	(\$5,451.60)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0210 -	Total						\$0.00													
	0250	MISC. PAVED DRAINAGE	Material		4	Aug 2, 2022	SYSTEM	\$9,407.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 25 on the current Payment Estimate.												
					4	Aug 2, 2022	SYSTEM	(\$9,407.25)													
					5	Aug 16, 2022	SYSTEM	\$9,407.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.												
					5	Aug 16, 2022	SYSTEM	(\$9,407.25)													
					6	Sep 2, 2022	SYSTEM	\$9,407.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
					6	Sep 2, 2022	SYSTEM	(\$9,407.25)													
					7	Sep 16, 2022	SYSTEM	\$9,407.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
									7	Sep 16, 2022	SYSTEM	(\$9,407.25)									
					8	Oct 3, 2022	SYSTEM	\$9,407.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment Estimate Exception 13 on the current Payment Estimate.												
					8	Oct 3, 2022	SYSTEM	(\$9,407.25)													
				- Total				\$0.00													
			Material - To	otal				\$0.00													
	0250 -	Total	Material - T			Material	Material					\$0.00									
	0270	GRATES AND BEARING PLATES (5 FT X 3 FT)	Material		3	Jul 18, 2022	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 7 on the current Payment Estimate.												
						3	Jul 18, 2022	SYSTEM	(\$2,475.00)												
																	4	Aug 2, 2022	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					4	Aug 2, 2022	SYSTEM	(\$2,475.00)													
															5	Aug 16, 2022	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 28 on the current Payment Estimate.		
			5 6 7 7	e		5	Aug 16, 2022	SYSTEM	(\$2,475.00)												
							e			6	Sep 2, 2022	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
					6	Sep 2, 2022	SYSTEM	(\$2,475.00)													
											-	7		7	Sep 16, 2022	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payment Estimate Exception 16 on the current Payment Estimate.			
				7	Sep 16, 2022	SYSTEM	(\$2,475.00)														
				8	8	Oct 3, 2022	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 14 on the current Payment Estimate.												
					8	Oct 3, 2022	SYSTEM	(\$2,475.00)													



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks							
			Туре	Adjustment Type	Number	Date	Ву									
J4S3273	0270	GRATES AND BEARING PLATES (5 FT X 3 FT)	Material		9	Oct 17, 2022	SYSTEM	\$2,475.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 12 on the current Payment Estimate.							
					9	Oct 17, 2022	SYSTEM	(\$2,475.00)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0270 -	Total						\$0.00								
	0290	CURVED VANE GRTE AND FRAME(2 FT. X 2	Material		3	Jul 18, 2022	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payment Estimate Exception 8 on the current Payment Estimate.							
		FT)			3	Jul 18, 2022	SYSTEM	(\$930.00)								
					4	Aug 2, 2022	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schwaj2 overridding Payment Estimate Exception 30 on the current Payment Estimate.							
					4	Aug 2, 2022	SYSTEM	(\$930.00)								
					5	Aug 16, 2022	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schwaj2 overridding Payment Estimate Exception 29 on the current Payment Estimate.							
					5	Aug 16, 2022	SYSTEM	(\$930.00)								
					6	Sep 2, 2022	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment Estimate Exception 17 on the current Payment Estimate.							
					6	Sep 2, 2022	SYSTEM	(\$930.00)								
						7	Sep 16, 2022	SYSTEM	\$930.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					7	Sep 16, 2022	SYSTEM	(\$930.00)								
					8	Oct 3, 2022	SYSTEM	\$2,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
						8	Oct 3, 2022	SYSTEM	(\$2,790.00)							
					9	Oct 17, 2022	SYSTEM	\$2,790.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 13 on the current Payment Estimate.							
					9	Oct 17, 2022	SYSTEM	(\$2,790.00)								
				- Total				\$0.00								
			Material - To	otal				\$0.00								
	0290 -	Total						\$0.00								
	0300	CURVED VANE GRATE AND FRAME(4 FT. X 2	Material	Material	Material	Material	Material	Material	Material	Material		3	Jul 18, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
		FT			3	Jul 18, 2022	SYSTEM	(\$1,800.00)								
					4	Aug 2, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schwaj2 overridding Payment Estimate Exception 31 on the current Payment Estimate.							
					4	Aug 2, 2022	SYSTEM	(\$1,800.00)								
					5	5	5	Aug 16, 2022	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schwaj2 overridding Payment Estimate Exception 30 on the current Payment Estimate.					
					5	Aug 16, 2022	SYSTEM	(\$1,800.00)								
					6	Sep 2, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					6	Sep 2,	SYSTEM	(\$1,800.00)								



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3273	0300	CURVED VANE	Material			2022			
		GRATE AND FRAME(4 FT. X 2 FT			7	Sep 16, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$1,800.00)	
					8	Oct 3, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schwaj2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$1,800.00)	
					9	Oct 17, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$1,800.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0300 -	Total						\$0.00	
	0320	CONSTRUCTION SIGNS	Material		1	Jun 16, 2022	SYSTEM	\$5,595.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Jun 16, 2022	SYSTEM	(\$5,595.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0320 -	Total						\$0.00	
	0330	ADVANCED WARNING RAIL SYSTEM	Material		1	Jun 16, 2022	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jun 16, 2022	SYSTEM	(\$300.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0330 -	Total						\$0.00	
	0350	TYPE III MOVEABLE BARRICADE	Material		1	Jun 16, 2022	SYSTEM	\$2,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jun 16, 2022	SYSTEM	(\$2,100.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0350 - 0360	CMS WITH COMMUNICATION	Material		1	Jun 16, 2022	SYSTEM	\$0.00 \$16,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payment
		INTERFACE, CONT F			1	Jun 16, 2022	SYSTEM	(\$16,000.00)	Estimate Exception 4 on the current Payment Estimate.
				- Total				\$0.00	
			Material - To					\$0.00	
	0360 -	Total						\$0.00	
	0420	PAVEMENT EDGE TREATMENT	Material		8	Oct 3, 2022	SYSTEM	\$14,251.65	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schwaj2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$14,251.65)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0420 -	Total						\$0.00	
	0430	PREF THERMO PAVMT MARKING,	Material		5	Aug 16, 2022	SYSTEM	\$304.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schwaj2 overridding Payment



Nov 5, 2022

Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks										
			Туре	Adjustment Type	Number	Date	Ву												
J4S3273	0430	12 IN WHITE	Material						Estimate Exception 31 on the current Payment Estimate.										
					5	Aug 16,	SYSTEM	(\$304.00)											
				- Total		2022		\$0.00											
			Material - To					\$0.00											
	0430 -	· Total						\$0.00											
	0450	PREF THERMO	Material		5	Aug 16,	SYSTEM	\$1,024.00	This adjustment offsets the original system-generated Material Payment										
		PVMT MARK, 24 IN YELLOW				2022			Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 32 on the current Payment Estimate.										
					5	Aug 16, 2022	SYSTEM	(\$1,024.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
	0450 -	Total						\$0.00											
	0520	4 IN. WHITE WATERBORNE PAVEMENT	Material		5	Aug 16, 2022	SYSTEM	\$161.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 33 on the current Payment Estimate.										
		MARKING			5	Aug 16, 2022	SYSTEM	(\$161.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
			Other Item Adjustment	REFL	6	Sep 2, 2022	schwaj2	\$5.55	Adjustment for retroreflectivity testing										
				REFL - Tota				\$5.55											
			Other Item	Adjustment -	Total			\$5.55											
	0520 -	Total						\$5.55											
	0530	4 IN. YELLOW WATERBORNE PAVEMENT	Material		5	Aug 16, 2022	SYSTEM	\$189.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schwaj2 overridding Payment Estimate Exception 35 on the current Payment Estimate.										
		MARKING			5	Aug 16, 2022	SYSTEM	(\$189.00)											
				- Total				\$0.00											
			Material - To	otal				\$0.00											
			Other Item Adjustment	REFL	6	Sep 2, 2022	schwaj2	(\$95.20)	Adjustment for retroreflectivity testing										
				REFL - Tota	I			(\$95.20)											
			Other Item	Adjustment -	Total			(\$95.20)											
	0530 -							(\$95.20)											
	0630	15 IN. PIPE CULVERT GROUP C	Material		1	Jun 16, 2022	SYSTEM	\$4,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.										
					1	Jun 16, 2022	SYSTEM	(\$4,664.00)											
															2	Jul 1, 2022	SYSTEM	\$4,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user schwaj2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					2	Jul 1, 2022	SYSTEM	(\$4,664.00)											
					3	Jul 18, 2022	SYSTEM	\$4,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 10 on the current Payment Estimate.										
					3	Jul 18, 2022	SYSTEM	(\$4,664.00)											
					4	Aug 2, 2022	SYSTEM	\$4,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Exception 32 on the current Payment Estimate.										
					4	Aug 2, 2022	SYSTEM	(\$4,664.00)											
					5	Aug 16, 2022	SYSTEM	\$4,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate.										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3273	0630	15 IN. PIPE CULVERT GROUP	Material	.)	5	Aug 16, 2022	SYSTEM	(\$4,664.00)	
		С			6	Sep 2, 2022	SYSTEM	\$4,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$4,664.00)	
					7	Sep 16, 2022	SYSTEM	\$4,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$4,664.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0630 -	Total			_			\$0.00	
	0640	18 IN. PIPE CULVERT GROUP C	Material		2	Jul 1, 2022	SYSTEM	\$2,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user schwaj2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					2	Jul 1, 2022	SYSTEM	(\$2,090.00)	
					3	Jul 18, 2022	SYSTEM	\$2,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	Jul 18, 2022	SYSTEM	(\$2,090.00)	
					4	Aug 2, 2022	SYSTEM	\$2,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schwaj2 overridding Payment Estimate Exception 33 on the current Payment Estimate.
					4	Aug 2, 2022	SYSTEM	(\$2,090.00)	
					5	Aug 16, 2022	SYSTEM	\$2,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Exception 38 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$2,090.00)	
					6	Sep 2, 2022	SYSTEM	\$2,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schwaj2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$2,090.00)	
					7	Sep 16, 2022	SYSTEM	\$2,090.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schwaj2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$2,090.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0640	Total						\$0.00	
	0650	MISC. METAL PIPE	Material		3	Jul 18, 2022	SYSTEM	\$678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schwaj2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	Jul 18, 2022	SYSTEM	(\$678.00)	
					4	Aug 2, 2022	SYSTEM	\$678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schwaj2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					4	Aug 2, 2022	SYSTEM	(\$678.00)	
			5	5	Aug 16, 2022	SYSTEM	\$678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schwaj2 overridding Payment Estimate Exception 39 on the current Payment Estimate.	
				5 Aug 16, SYSTEM (\$678.00 2022	(\$678.00)				
					6	Sep 2, 2022	SYSTEM	\$678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schwaj2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J4S3273	0650	MISC. METAL	Material						Estimate Exception 21 on the current Payment Estimate.															
		PIPE			6	Sep 2, 2022	SYSTEM	(\$678.00)																
					7	Sep 16, 2022	SYSTEM	\$678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schwaj2 overridding Payment Estimate Exception 21 on the current Payment Estimate.															
					7	Sep 16, 2022	SYSTEM	(\$678.00)																
					8	Oct 3, 2022	SYSTEM	\$678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schwaj2 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
					8	Oct 3, 2022	SYSTEM	(\$678.00)																
					9	Oct 17, 2022	SYSTEM	\$678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate.															
					9	Oct 17, 2022	SYSTEM	(\$678.00)																
					10	Nov 2, 2022	SYSTEM	\$678.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 8 on the current Payment Estimate.															
					10	Nov 2, 2022	SYSTEM	(\$678.00)																
				- Total				\$0.00																
			Material - To	otal				\$0.00																
	0650 ·	- Total						\$0.00																
	0660	MISC. METAL PIPE	Material		2	Jul 1, 2022	SYSTEM	\$1,295.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user schwaj2 overridding Payment Estimate Exception 3 on the current Payment Estimate.															
							2	Jul 1, 2022	SYSTEM	(\$1,295.00)														
					3	Jul 18, 2022	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schwaj2 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
							3	Jul 18, 2022	SYSTEM	(\$3,108.00)														
					4	Aug 2, 2022	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schwaj2 overridding Payment Estimate Exception 35 on the current Payment Estimate.															
					4	Aug 2, 2022	SYSTEM	(\$3,108.00)																
												5	Aug 16, 2022	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schwaj2 overridding Payment Estimate Exception 40 on the current Payment Estimate.								
										5	Aug 16, 2022	SYSTEM	(\$3,108.00)											
														6	Sep 2, 2022	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schwaj2 overridding Payment Estimate Exception 22 on the current Payment Estimate.						
					6	Sep 2, 2022	SYSTEM	(\$3,108.00)																
			5				7 7 8 8 9												7	Sep 16, 2022	SYSTEM	\$3,108.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schwaj2 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
																							7	Sep 16, 2022
																	8	Oct 3, 2022	SYSTEM	\$4,791.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 19 on the current Payment Estimate.			
													8	8	Oct 3, 2022	SYSTEM	(\$4,791.50)							
																	9			9	Oct 17, 2022	SYSTEM	\$4,791.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$4,791.50)																
						2022																		



Contract ID:190215-D05

	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	By		
J4S3273	0660	MISC. METAL PIPE	Material		10	Nov 2, 2022	SYSTEM	\$4,791.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$4,791.50)	
				- Total				\$0.00	
			Material - Te	otal				\$0.00	
	0660 -	Total						\$0.00	
	0730	PRECAST CONCRETE DROP INLET 2 FT X 2 FT	Material		2	Jul 1, 2022	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user schwaj2 overridding Payment Estimate Exception 4 on the current Payment Estimate.
		A211			2	Jul 1, 2022	SYSTEM	(\$7,120.00)	
					3	Jul 18, 2022	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schwaj2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					3	Jul 18, 2022	SYSTEM	(\$7,120.00)	
					4	Aug 2, 2022	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schwaj2 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					4	Aug 2, 2022	SYSTEM	(\$7,120.00)	
					5	Aug 16, 2022	SYSTEM	\$7,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schwaj2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$7,120.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0730 -	Total						\$0.00	
	0740	PRECAST CONCRETE DROP INLET 4 FT X 2 FT	Material		2	Jul 1, 2022	SYSTEM	\$6,965.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
	0740	CONCRETE	Material		2		SYSTEM SYSTEM		Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment
	0740	CONCRETE DROP INLET 4 FT	Material			2022 Jul 1,		\$6,965.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment
	0740	CONCRETE DROP INLET 4 FT	Material		2	2022 Jul 1, 2022 Jul 18,	SYSTEM	\$6,965.00 (\$6,965.00)	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment
	0740	CONCRETE DROP INLET 4 FT	Material		2 3	2022 Jul 1, 2022 Jul 18, 2022 Jul 18,	SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment
	0740	CONCRETE DROP INLET 4 FT	Material		2 3 3	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2,	SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00)	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment
	0740	CONCRETE DROP INLET 4 FT	Material		2 3 3 4	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, Aug 2,	SYSTEM SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment
	0740	CONCRETE DROP INLET 4 FT	Material		2 3 3 4 4	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.
	0740	CONCRETE DROP INLET 4 FT	Material	- Total	2 3 3 4 4 5	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.
	0740	CONCRETE DROP INLET 4 FT	Material Material - To		2 3 3 4 4 5	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.
	0740	CONCRETE DROP INLET 4 FT X 2 FT			2 3 3 4 4 5	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.
		CONCRETE DROP INLET 4 FT X 2 FT	Material - To		2 3 3 4 4 5	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$0.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 37 on the current Payment Estimate.
	0740 -	CONCRETE DROP INLET 4 FT X 2 FT	Material - To		2 3 3 4 4 5 5	2022 Jul 1, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16, 2022 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schwaj2 overridding Payment Estimate Item Adjustment (0023) due to user schwaj2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
	0740 -	CONCRETE DROP INLET 4 FT X 2 FT	Material - To		2 3 3 4 5 5 5 2	2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022 Aug 2, 2022 Aug 16, 2022 Jul 1, 2022 Jul 1,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$6,965.00 (\$6,965.00) \$6,965.00 (\$6,965.00) (\$6,965.00) \$6,965.00 (\$6,965.00) (\$6,965.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schwaj2 overridding Payment Estimate Item Adjustment (0023) due to user schwaj2 overridding Payment Estimate Exception 42 on the current Payment Estimate.

Nov 5, 2022



Project	1.1	D 1.0		011	- .	0 1 1	0 1 1		
	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3273	0750	PRECAST CONCRETE DROP INLET 5 FT	Material		4	Aug 2, 2022	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schwaj2 overridding Payment Estimate Exception 38 on the current Payment Estimate.
		X 3 FT			4	Aug 2, 2022	SYSTEM	(\$5,050.00)	
					5	Aug 16, 2022	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$5,050.00)	
					6	Sep 2, 2022	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$5,050.00)	
					7	Sep 16, 2022	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$5,050.00)	
					8	Oct 3, 2022	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$5,050.00)	
					9	Oct 17, 2022	SYSTEM	\$5,050.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$5,050.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	0750 -	Total						\$0.00	
	0790	MISC. FLARED END SECTIONS	Material		6	Sep 2, 2022	SYSTEM	\$3,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$3,060.00)	
					-				
					7	Sep 16, 2022	SYSTEM	\$3,060.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7 7		SYSTEM SYSTEM	\$3,060.00 (\$3,060.00)	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment
				- Total		2022 Sep 16,			Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment
			Material - T			2022 Sep 16,		(\$3,060.00)	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment
	0790 -	·Total	Material - T			2022 Sep 16,		(\$3,060.00) \$0.00	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment
	0790 - 0800	Total MISC. FLARED END SECTIONS	Material - To Material			2022 Sep 16,		(\$3,060.00) \$0.00 \$0.00	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment
		MISC. FLARED			7	2022 Sep 16, 2022 Jul 1,	SYSTEM	(\$3,060.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
		MISC. FLARED			2	2022 Sep 16, 2022 Jul 1, 2022 Jul 1,	SYSTEM	(\$3,060.00) \$0.00 \$0.00 \$0.00 \$4,590.00	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
		MISC. FLARED			7 2 2	2022 Sep 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 1, 2022	SYSTEM SYSTEM SYSTEM	(\$3,060.00) \$0.00 \$0.00 \$4,590.00 (\$4,590.00)	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
		MISC. FLARED			7 2 2 3	2022 Sep 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,060.00) \$0.00 \$0.00 \$4,590.00 (\$4,590.00 \$4,590.00	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
		MISC. FLARED			7 2 2 3 3	2022 Sep 16, 2022 Jul 1, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Jul 18, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,060.00) \$0.00 \$0.00 \$4,590.00 (\$4,590.00) \$4,590.00 (\$4,590.00)	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
		MISC. FLARED			7 2 2 3 3 4	2022 Sep 16, 2022 Jul 1, 2022 Jul 18, 2022 Jul 18, 2022 Jul 18, 2022 Aug 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$3,060.00) \$0.00 \$0.00 \$4,590.00 (\$4,590.00) \$4,590.00 (\$4,590.00 \$4,590.00	Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3273	0800	MISC. FLARED	Material			2022			
		END SECTIONS			6	Sep 2, 2022	SYSTEM	\$4,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schwaj2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$4,590.00)	
					7	Sep 16, 2022	SYSTEM	\$4,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schwaj2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$4,590.00)	
					8	Oct 3, 2022	SYSTEM	\$4,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schwaj2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$4,590.00)	
					9	Oct 17, 2022	SYSTEM	\$4,590.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user schwaj2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$4,590.00)	
					10	Nov 2, 2022	SYSTEM	\$6,120.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$6,120.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0800 -	Total						\$0.00	
	0810	MISC. MANHOLE AND PIPE	Material		8	Oct 3, 2022	SYSTEM	\$56,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schwaj2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$56,772.00)	
					9	Oct 17, 2022	SYSTEM	\$56,772.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schwaj2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$56,772.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0810 -	Total						\$0.00	
	0820	PIPE LINER FOR EXISTING CULVERT	Material		7	Sep 16, 2022	SYSTEM	\$15,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schwaj2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$15,760.00)	
					8	Oct 3, 2022	SYSTEM	\$15,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$15,760.00)	
					9	Oct 17, 2022	SYSTEM	\$15,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schwaj2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$15,760.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	0820 -	Total						\$0.00	
	0830	SEEDING - COOL SEASON GRASSES	Material		5	Aug 16, 2022	SYSTEM	\$1,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schwaj2 overridding Payment Estimate Exception 45 on the current Payment Estimate.



Nov 5, 2022

Priori Line Description Addition Oracle Transition Amount Oracle Amount Data Data Data Data Data Data Data Da	_		_				-	_		
BASE Second	Project	Line	Description		Adjustment				Amount	Remarks
Nome Nome <th< td=""><td>J4S3273</td><td>0830</td><td>SEASON</td><td>Material</td><td></td><td>5</td><td></td><td>SYSTEM</td><td>(\$1,950.00)</td><td></td></th<>	J4S3273	0830	SEASON	Material		5		SYSTEM	(\$1,950.00)	
rotat Virtual			GRASSES			6		SYSTEM	\$1,950.00	Estimate Item Adjustment (0018) due to user schwaj2 overridding Payment
Other Statution Statution 0300 SECINITY TOP 12022 1971EB 12020 This adjustment offices the original system-generated Material Payment Estimate Dom Adjustment (Origin to use in Enarging) 1 2022 1971EB 12020 This adjustment offices the original system-generated Material Payment Estimate Dom Adjustment (Origin to use in Enarging) 1 2022 1 1 2022 1 1 2020 1 1 2020 1 1 2020 1 1 2020 1 1 2020 1 1 2020 1 1 2020 1 1 2020 1 1 2020 1 1 2020 1 1 2020 1 1 1 2020 1 1 1 2020 1 <td></td> <td></td> <td></td> <td></td> <td></td> <td>6</td> <td></td> <td>SYSTEM</td> <td>(\$1,950.00)</td> <td></td>						6		SYSTEM	(\$1,950.00)	
OSD = Total Second					- Total				\$0.00	
0840 SEDMENT TAXE ROCK Material bits of particular set of parti				Material - To	otal				\$0.00	
0840 SEDMENT TAXE ROCK Material bits of particular set of parti		0830 -	Total						\$0.00	
No. No. <td></td> <td>0840</td> <td></td> <td>Material</td> <td></td> <td>1</td> <td></td> <td>SYSTEM</td> <td></td> <td>Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment</td>		0840		Material		1		SYSTEM		Estimate Item Adjustment (0006) due to user schwaj2 overridding Payment
Kink Kink <th< td=""><td></td><td></td><td></td><td></td><td></td><td>1</td><td></td><td>SYSTEM</td><td>(\$1,250.00)</td><td></td></th<>						1		SYSTEM	(\$1,250.00)	
Ref 2022 2022 SYSTEM 53.750.00 The adjustment offeets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. 3 Jul 18, 2022, SYSTEM 63.750.00 The adjustment offeets the original system-generated Material Payment Estimate Exception 15 on the current Payment Estimate. 4 Aug 2, 2022, SYSTEM 63.750.00 The adjustment offeets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate. 4 Aug 2, 2022, SYSTEM 63.750.00 The adjustment offeets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate. 6 Aug 2, 2022, SYSTEM 63.750.00 The adjustment offeets the original system-generated Material Payment Estimate Exception 40 on the current Payment Estimate. 7 Aug 1, 2022, SYSTEM 63.750.00 The adjustment offeets the original system-generated Material Payment Estimate Exception 47 on the current Payment Estimate. 8400 Total 950.00 10800 The Current Payment Estimate. 950.00 118 adjustment offeets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate. 98						2		SYSTEM	\$1,250.00	Estimate Item Adjustment (0009) due to user schwaj2 overridding Payment
Kind and an analysis of the strain						2		SYSTEM	(\$1,250.00)	
View View <th< td=""><td></td><td></td><td></td><td></td><td></td><td>3</td><td></td><td>SYSTEM</td><td>\$3,750.00</td><td>Estimate Item Adjustment (0018) due to user schwaj2 overridding Payment</td></th<>						3		SYSTEM	\$3,750.00	Estimate Item Adjustment (0018) due to user schwaj2 overridding Payment
						3		SYSTEM	(\$3,750.00)	
Image: constraint of the second sec						4		SYSTEM	\$3,750.00	Estimate Item Adjustment (0027) due to user schwaj2 overridding Payment
Image: bit is adjustment (0027) due to user schwaj2 overridding Payment Estimate Estimate Exception 47 on the current Payment Estimate. 6 Aug 16, 3202 SYSTEM (S3,750.00) -Total -Total 50.00 0650 ALTERNATE DITCH CHECK Material - Total 50.00 0650 ALTERNATE DITCH CHECK Material - Total 50.00 0650 ALTERNATE Material 5 Aug 16, 325TEM \$9,600.00 0650 ALTERNATE Material 5 Aug 16, 2022 \$YSTEM \$9,600.00 0650 ALTERNATE Material Payment Estimate Exception 40 on the current Payment Estimate. 5 Aug 16, 2022 \$YSTEM \$9,600.00 0650 ALTERNATE Material Payment Estimate 5 Aug 16, 2022 \$YSTEM \$9,600.00 07000 - 50.00 This adjustment offsets the original system-generated Material Payment Estimate. 0880 - - 50.00 This adjustment offsets the original system-generated Material Payment Estimate. 0880 - - 50.00 This adjustment offsets the original system-generated Material Payment Estimate. 0						4		SYSTEM	(\$3,750.00)	
Image: Note of the second s						5		SYSTEM	\$3,750.00	Estimate Item Adjustment (0027) due to user schwaj2 overridding Payment
Material - Total \$0.00 0840 - Total \$0.00 0850 ALTERNATE DITCH CHECK Material - Total \$9,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Item Adjustment (0017) due to user schwaj2 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Item Adjustment (00101) due to user schwaj2 overridding Payment Estimate						5		SYSTEM	(\$3,750.00)	
0840 - Total S0.00 0850 ALTERNATE DITCH CHECK Material 5 Aug 16, 2022 SYSTEM \$9,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schwaj2 overridding Payment Estimate Item Adjustment (0028) due to user schwaj2 overridding Payment 5 Aug 16, 2022 SYSTEM \$9,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schwaj2 overridding Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment 6 Sep 2, 2022 SYSTEM \$9,600.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate. 0 Imaterial - Total 50.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 27 on the current Payment Estimate. 0880 SILT FENCE Material 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 0880 SILT FENCE Material 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 7 on the current Payment Estimate. 1					- Total				\$0.00	
0850 ALTERNATE DITCH CHECK Material 5 Aug 16, 2022 SYSTEM \$9,600.00 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0028) due to user schwaj2 overridding Payment Estimate Exception 48 on the current Payment Estimate. 5 Aug 16, 2022 SYSTEM \$9,600.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 48 on the current Payment Estimate. 6 Sep 2, 2022 SYSTEM \$9,600.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Exception 27 on the current Payment Estimate. 0 V V SYSTEM \$9,600.00 0 V V SYSTEM \$9,600.00 0 V V SYSTEM \$9,600.00 0 V V \$9,600.00 0 V V SYSTEM \$9,600.00 0 V V V SV 0 V V SV \$9,600.00 0 V V SV \$9,600.00 0 V V SV \$9,600.00 0 V V SV SV 0 V V SV SV 0 V S				Material - To	otal				\$0.00	
DITCH CHECK Image: Second Se		0840 -	Total						\$0.00	
0850 - Total Silt FENCE Material - Total SySTEM \$9,60.00 This adjustment offsets the original system-generated Material Payment Estimate. 0850 - Total - Total \$0.00 Sep 2, 2022 SYSTEM \$9,60.00 0850 - Total - Total \$0.00 Sep 2, 2022 SYSTEM \$0.00 0850 - Total - Total \$0.00 Sep 2, 2022 SYSTEM \$0.00 0850 - Total Silt FENCE Material - Total \$0.00 Sep 2, 2022 SYSTEM \$0.00 0850 - Total \$0.00 Silt FENCE Material - Total \$0.00 Silt Signature offsets the original system-generated Material Payment Estimate. 0860 - Total \$0.00 \$0.00 Silt Signature offsets the original system-generated Material Payment Estimate. 0880 Silt FENCE Material 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 3 Jul 18, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment.		0850		Material		5		SYSTEM	\$9,600.00	Estimate Item Adjustment (0028) due to user schwaj2 overridding Payment
Image: Problem in the stand state inter stand state inter stand state inthe stand state int						5		SYSTEM	(\$9,600.00)	
Image: Constraine of the second se						6	Sep 2, 2022	SYSTEM	\$9,600.00	Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment
Material - Total \$0.00 0850 - Total 0850 - Total \$0.00 0880 SILT FENCE Material 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment (0010) due to user schwaj2 overridding Payment 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment 3 Jul 18, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment 2 Jul 18, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated						6		SYSTEM	(\$9,600.00)	
0850 - Total \$0.00 0880 SILT FENCE Material 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 3 Jul 18, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate.					- Total				\$0.00	
0880 SILT FENCE Material 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment 1 Jun 16, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate. 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate. 3 Jul 18, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment				Material - To	otal				\$0.00	
2022 2022 Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment Estimate Exception 7 on the current Payment Estimate. 1 Jun 16, 2022 SYSTEM (\$4,860.00) 2 Jul 1, 2022 SYSTEM \$4,860.00 2 Jul 1, 2022 SYSTEM \$4,860.00 2 Jul 1, 2022 SYSTEM \$4,860.00 3 Jul 18, 2022 SYSTEM \$4,860.00 3 Jul 18, 2022 SYSTEM \$4,860.00 3 Jul 18, 2022 SYSTEM \$4,860.00 2 Jul 18, 2022 SYSTEM \$4,860.00 3 Jul 18, 2022 SYSTEM \$4,860.00 2 Jul 18, 2022 SYSTEM \$4,860.00		0850 -	Total						\$0.00	
2022 2022 2022 2 Jul 1, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment 2 Jul 1, 2022 SYSTEM (\$4,860.00) 2 Jul 1, 2022 SYSTEM (\$4,860.00) 3 Jul 18, 2022 SYSTEM \$4,860.00 3 Jul 18, 2022 SYSTEM \$4,860.00		0880	SILT FENCE	Material		1		SYSTEM	\$4,860.00	Estimate Item Adjustment (0007) due to user schwaj2 overridding Payment
2022 Settimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 9 on the current Payment Estimate. 2 Jul 1, 2022 SYSTEM (\$4,860.00) 3 Jul 18, 2022 SYSTEM \$4,860.00 SYSTEM SYSTEM \$4,860.00						1		SYSTEM	(\$4,860.00)	
2022 3 Jul 18, 2022 SYSTEM \$4,860.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment					2	2		SYSTEM	\$4,860.00	Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment
2022 Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment						2		SYSTEM	(\$4,860.00)	
						3		SYSTEM	\$4,860.00	Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3273	0880	SILT FENCE	Material		3	Jul 18, 2022	SYSTEM	(\$4,860.00)	
					4	Aug 2, 2022	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schwaj2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					4	Aug 2, 2022	SYSTEM	(\$4,860.00)	
					5	Aug 16, 2022	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schwaj2 overridding Payment Estimate Exception 49 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$4,860.00)	
					6	Sep 2, 2022	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schwaj2 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$4,860.00)	
					7	Sep 16, 2022	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$4,860.00)	
					8	Oct 3, 2022	SYSTEM	\$4,860.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$4,860.00)	
					9	Oct 17, 2022	SYSTEM	\$7,977.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$7,977.60)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
		Total			-			\$0.00	
	0890	TYPE 2 TURF REINFORCEMENT MAT	Material		5	Aug 16, 2022	SYSTEM	\$9,940.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schwaj2 overridding Payment Estimate Exception 50 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$9,940.80)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
		- Total						\$0.00	
	0900	LIGHTING POLE, 30 FT. OR 9.0 M, TYPE AT	Material		5	Aug 16, 2022	SYSTEM	\$22,165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schwaj2 overridding Payment Estimate Exception 51 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$22,165.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
		Total			-			\$0.00	
	0910	BRACKET ARM, 10 FT. OR 3.0 M	Material		5	Aug 16, 2022	SYSTEM	\$2,535.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schwaj2 overridding Payment Estimate Exception 53 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$2,535.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
		· Total						\$0.00	
	0920	BRACKET ARM, 15 FT. OR 4.6 M	Material		5	Aug 16, 2022	SYSTEM	\$6,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schwaj2 overridding Payment Estimate Exception 55 on the current Payment Estimate.
									Estimate Exception de on the danoit raymont Estimate.



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks													
J4S3273	0920	BRACKET ARM,	Material			2022																
		15 FT. OR 4.6 M		- Total				\$0.00														
			Material - To	otal				\$0.00														
	0920 -	Total						\$0.00														
	0940	BASE MOUNTED CONTROL STATION	Material		5	Aug 16, 2022	SYSTEM	\$3,612.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schwaj2 overridding Payment Estimate Exception 57 on the current Payment Estimate.													
					5	Aug 16, 2022	SYSTEM	(\$3,612.50)														
					6	Sep 2, 2022	SYSTEM	\$3,612.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schwaj2 overridding Payment Estimate Exception 29 on the current Payment Estimate.													
				6 7	Sep 2, 2022	SYSTEM	(\$3,612.50)															
					7	Sep 16, 2022	SYSTEM	\$3,612.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schwaj2 overridding Payment Estimate Exception 28 on the current Payment Estimate.													
					7	Sep 16, 2022	SYSTEM	(\$3,612.50)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0940 -							\$0.00														
	0950	CONDUIT, 2 IN. RIGID, IN TRENCH	Material		5	Aug 16, 2022	SYSTEM	\$8,150.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schwaj2 overridding Payment Estimate Exception 58 on the current Payment Estimate.													
															5	Aug 16, 2022	SYSTEM	(\$8,150.80)				
																		6	Sep 2, 2022	SYSTEM	\$8,150.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schwaj2 overridding Payment Estimate Exception 30 on the current Payment Estimate.
															6	Sep 2, 2022	SYSTEM	(\$8,150.80)				
					7	7	Sep 16, 2022	SYSTEM	\$8,150.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schwaj2 overridding Payment Estimate Exception 29 on the current Payment Estimate.												
					7	Sep 16, 2022	SYSTEM	(\$8,150.80)														
				- Total				\$0.00														
			Material - To	otal				\$0.00														
	0950 -	Total						\$0.00														
	0960	CONDUIT, 3 IN. RIGID, IN TRENCH	Material		2	Jul 1, 2022	SYSTEM	\$1,578.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 10 on the current Payment Estimate.													
					2	Jul 1, 2022	SYSTEM	(\$1,578.90)														
														3	Jul 18, 2022	SYSTEM	\$1,578.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schwaj2 overridding Payment Estimate Exception 20 on the current Payment Estimate.				
					3	Jul 18, 2022	SYSTEM	(\$1,578.90)														
																4	Aug 2, 2022	SYSTEM	\$1,578.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schwaj2 overridding Payment Estimate Exception 42 on the current Payment Estimate.		
					4	Aug 2, 2022	SYSTEM	(\$1,578.90)														
					5	Aug 16, 2022	SYSTEM	\$1,578.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0036) due to user schwaj2 overridding Payment Estimate Exception 59 on the current Payment Estimate.													
					5	Aug 16, 2022	SYSTEM	(\$1,578.90)														
					6	Sep 2, 2022	SYSTEM	\$1,578.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schwaj2 overridding Payment Estimate Exception 31 on the current Payment Estimate.													



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks						
J4S3273	0960	CONDUIT, 3 IN. RIGID, IN	Material	Туре	6	Sep 2, 2022	SYSTEM	(\$1,578.90)							
		TRENCH			7	Sep 16, 2022	SYSTEM	\$1,578.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schwaj2 overridding Payment Estimate Exception 30 on the current Payment Estimate.						
					7	Sep 16, 2022	SYSTEM	(\$1,578.90)							
				- Total				\$0.00							
			Material - To					\$0.00							
	0960 -	Total						\$0.00							
	0970	CONDUIT, 4 IN. RIGID, IN TRENCH	Material		5	Aug 16, 2022	SYSTEM	\$383.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0037) due to user schwaj2 overridding Payment Estimate Exception 60 on the current Payment Estimate.						
					5	Aug 16, 2022	SYSTEM	(\$383.60)							
					6	Sep 2, 2022	SYSTEM	\$383.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 32 on the current Payment Estimate.						
					6	Sep 2, 2022	SYSTEM	(\$383.60)							
					7	Sep 16, 2022	SYSTEM	\$383.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schwaj2 overridding Payment Estimate Exception 31 on the current Payment Estimate.						
					7	Sep 16, 2022	SYSTEM	(\$383.60)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							
	0970 -	Total						\$0.00							
	0990	PULL BOX, PREFORMED CLASS 1	Material		5	Aug 16, 2022	SYSTEM	\$5,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0038) due to user schwaj2 overridding Payment Estimate Exception 61 on the current Payment Estimate.						
											5	Aug 16, 2022	SYSTEM	(\$5,250.00)	
					6	Sep 2, 2022	SYSTEM	\$5,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schwaj2 overridding Payment Estimate Exception 33 on the current Payment Estimate.						
					6	Sep 2, 2022	SYSTEM	(\$5,250.00)							
					7	Sep 16, 2022	SYSTEM	\$5,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 32 on the current Payment Estimate.						
					7	Sep 16, 2022	SYSTEM	(\$5,250.00)							
				- Total				\$0.00							
			Material - Te	otal				\$0.00							
	0990 -	Total						\$0.00							
	1000	CABLE, 2 AWG 1 CONDUCTOR	Material		5	Aug 16, 2022	SYSTEM	\$540.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0039) due to user schwaj2 overridding Payment Estimate Exception 62 on the current Payment Estimate.						
						!	ţ	5		5	Aug 16, 2022	SYSTEM	(\$540.75)		
			6	6	Sep 2, 2022	SYSTEM	\$540.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schwaj2 overridding Payment Estimate Exception 34 on the current Payment Estimate.							
					6	Sep 2, 2022	SYSTEM	(\$540.75)							
					7	Sep 16, 2022	SYSTEM	\$540.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schwaj2 overridding Payment Estimate Exception 33 on the current Payment Estimate.						
					7	Sep 16, 2022	SYSTEM	(\$540.75)							
				- Total				\$0.00							
			Material - To	otal				\$0.00							



Nov 5, 2022

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
273	1000 -	Total						\$0.00	
	1010	CABLE, 8 AWG 1 CONDUCTOR	Material		5	Aug 16, 2022	SYSTEM	\$2,847.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0040) due to user schwaj2 overridding Payment Estimate Exception 63 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$2,847.00)	
					6	Sep 2, 2022	SYSTEM	\$2,847.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schwaj2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$2,847.00)	
					7	Sep 16, 2022	SYSTEM	\$2,847.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schwaj2 overridding Payment Estimate Exception 34 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$2,847.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1010 -	Total						\$0.00	
	1020	CABLE, 10 AWG 1 CONDUCTOR, POLE & BRACKE	Material		5	Aug 16, 2022	SYSTEM	\$651.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0041) due to user schwaj2 overridding Payment Estimate Exception 64 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$651.75)	
					6	Sep 2, 2022	SYSTEM	\$651.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schwaj2 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$651.75)	
					7	Sep 16, 2022	SYSTEM	\$651.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schwaj2 overridding Payment Estimate Exception 35 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$651.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1020 -	Total						\$0.00	
	1030	WIRE, 2 AWG, BARE NEUTRAL	Material		5	Aug 16, 2022	SYSTEM	\$220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0042) due to user schwaj2 overridding Payment Estimate Exception 65 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$220.00)	
					6	Sep 2, 2022	SYSTEM	\$220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$220.00)	
					7	Sep 16, 2022	SYSTEM	\$220.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user schwaj2 overridding Payment Estimate Exception 36 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$220.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1030 -	Total						\$0.00	
	1040	WIRE, 8 AWG, BARE NEUTRAL	Material		5	Aug 16, 2022	SYSTEM	\$1,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0043) due to user schwaj2 overridding Payment Estimate Exception 66 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$1,314.00)	
					6	Sep 2, 2022	SYSTEM	\$1,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schwaj2 overridding Payment
									Estimate Exception 38 on the current Payment Estimate.



Nov 5, 2022

ct	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
,	LINE	Description	Туре	Adjustment Type	Number	Date	By	Amount	Neihaiks
73	1040	WIRE, 8 AWG, BARE NEUTRAL	Material			2022			
					7	Sep 16, 2022	SYSTEM	\$1,314.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user schwaj2 overridding Payment Estimate Exception 37 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$1,314.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1040 -	Total						\$0.00	
	1050	POLE FOUNDATION (30 FT. OR 9.0 M	Material		5	Aug 16, 2022	SYSTEM	\$13,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0044) due to user schwaj2 overridding Payment Estimate Exception 67 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$13,420.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1050 -	Total						\$0.00	
	1070	SIGNAL HEAD, TYPE 3S	Material		9	Oct 17, 2022	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$900.00)	
					10	Nov 2, 2022	SYSTEM	\$900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user schwaj2 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$900.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1070 -	Total						\$0.00	
	1080	SIGNAL HEAD, TYPE 3C	Material		9	Oct 17, 2022	SYSTEM	\$2,820.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user schwaj2 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$2,820.00)	
					10	Nov 2, 2022	SYSTEM	\$2,820.00	This adjustment offsets the original system-generated Material Payment
									Estimate Item Adjustment (0011) due to user schwaj2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$2,820.00)	
				- Total	10		SYSTEM	(\$2,820.00) \$0.00	
			Material - To		10		SYSTEM	× · · · ·	
	1080 -	Total	Material - To		10		SYSTEM	\$0.00	
	1080 - 1090	Total SIGNAL HEAD, TYPE 4C	Material - To Material		10 9		SYSTEM SYSTEM	\$0.00 \$0.00	
		SIGNAL HEAD,				2022 Oct 17,		\$0.00 \$0.00 \$0.00	Estimate Exception 12 on the current Payment Estimate.
I		SIGNAL HEAD,			9	2022 Oct 17, 2022 Oct 17,	SYSTEM	\$0.00 \$0.00 \$0.00 \$1,235.00	Estimate Exception 12 on the current Payment Estimate.
1		SIGNAL HEAD,			9 9	2022 Oct 17, 2022 Oct 17, 2022 Nov 2,	SYSTEM	\$0.00 \$0.00 \$1,235.00 (\$1,235.00)	Estimate Exception 12 on the current Payment Estimate.
		SIGNAL HEAD,			9 9 10	2022 Oct 17, 2022 Oct 17, 2022 Nov 2, 2022 Nov 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,235.00 (\$1,235.00) \$1,235.00	Estimate Exception 12 on the current Payment Estimate.
		SIGNAL HEAD,		- Total	9 9 10	2022 Oct 17, 2022 Oct 17, 2022 Nov 2, 2022 Nov 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,235.00 (\$1,235.00) \$1,235.00 (\$1,235.00)	Estimate Exception 12 on the current Payment Estimate.
	1090	SIGNAL HEAD,	Material	- Total	9 9 10	2022 Oct 17, 2022 Oct 17, 2022 Nov 2, 2022 Nov 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,235.00 (\$1,235.00) \$1,235.00 (\$1,235.00) (\$1,235.00) \$0.00	Estimate Exception 12 on the current Payment Estimate.
	1090	SIGNAL HEAD, TYPE 4C	Material	- Total	9 9 10	2022 Oct 17, 2022 Oct 17, 2022 Nov 2, 2022 Nov 2,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$1,235.00 (\$1,235.00) \$1,235.00 (\$1,235.00) (\$1,235.00) \$0.00	Estimate Exception 12 on the current Payment Estimate.



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks
J4S3273	1100	SH-FLAT SHEET - SIGNAL SIGN	Material	Туре	10	Nov 2, 2022	SYSTEM	\$1,965.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user schwaj2 overridding Payment
					10	Nov 2, 2022	SYSTEM	(\$1,965.00)	Estimate Exception 14 on the current Payment Estimate.
				- Total		LULL		\$0.00	
			Material - To					\$0.00	
	1100 -	Total						\$0.00	
	1120	LUMINAIRE LED- A, 120 VOLT	Material		9	Oct 17, 2022	SYSTEM	\$1,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schwaj2 overridding Payment
		COMPATIBLE			9	Oct 17, 2022	SYSTEM	(\$1,280.00)	Estimate Exception 26 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	\$1,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user schwaj2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$1,280.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1120 -	Total						\$0.00	
	1130	POST, STEEL SPAN WIRE, FOR 30 FT. OR 9.0	Material		9	Oct 17, 2022	SYSTEM	\$32,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schwaj2 overridding Payment Estimate Exception 27 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$32,020.00)	
					10	Nov 2, 2022	SYSTEM	\$32,020.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user schwaj2 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$32,020.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1130 -	D - Total SPAN WIRE ASSEMBLY, MESSENGER WITH TETHE	Material					\$0.00	
	1140			Material	9	Oct 17, 2022	SYSTEM	\$8,994.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schwaj2 overridding Payment Estimate Exception 29 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$8,994.70)	
					10	Nov 2, 2022	SYSTEM	\$8,994.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user schwaj2 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$8,994.70)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1140 -	Total						\$0.00	
	1150	CONTROLLER ASSEMBLY HOUSING,	Material		7	Sep 16, 2022	SYSTEM	\$8,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user schwaj2 overridding Payment Estimate Exception 38 on the current Payment Estimate.
		,			7	Sep 16, 2022	SYSTEM	(\$8,160.00)	
					8	Oct 3, 2022	SYSTEM	\$8,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schwaj2 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$8,160.00)	
					9	Oct 17, 2022	SYSTEM	\$8,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user schwaj2 overridding Payment Estimate Exception 30 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$8,160.00)	



Nov 5, 2022

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
273	1150	CONTROLLER ASSEMBLY	Material			2022			Estimate Item Adjustment (0017) due to user schwaj2 overridding Payment Estimate Exception 19 on the current Payment Estimate.
		HOUSING,			10	Nov 2, 2022	SYSTEM	(\$8,160.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1150 -	Total						\$0.00	
	1200	CONDUIT, 3 IN., TRENCH WITH TRACER WIRE	Material		9	Oct 17, 2022	SYSTEM	\$959.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user schwaj2 overridding Payment Estimate Exception 31 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$959.18)	
					10	Nov 2, 2022	SYSTEM	\$959.18	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user schwaj2 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$959.18)	
				- Total				\$0.00	
			Material - To						
	1200 -	Total						\$0.00 \$0.00	
	1220	CABLE, 10 AWG 1 CONDUCTOR, POLE AND BRAC	Material		9	Oct 17, 2022	SYSTEM	\$256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user schwaj2 overridding Paymen Estimate Exception 32 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$256.00)	
					10	Nov 2, 2022	SYSTEM	\$256.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user schwaj2 overridding Paymen Estimate Exception 21 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$256.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1220 -	Total						\$0.00	
	1230	CABLE, 8 AWG 1 CONDUCTOR, POWER	Material		9	Oct 17, 2022	SYSTEM	\$78.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user schwaj2 overridding Paymen Estimate Exception 33 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$78.75)	
					10	Nov 2, 2022	SYSTEM	\$78.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user schwaj2 overridding Paymen Estimate Exception 22 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$78.75)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1230 -	Total						\$0.00	
	1240	CABLE, 12 AWG 2 CONDUCTOR	Material		9	Oct 17, 2022	SYSTEM	\$535.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user schwaj2 overridding Paymen Estimate Exception 34 on the current Payment Estimate.
					9	Oct 17, 2022	SYSTEM	(\$535.50)	
					10	Nov 2, 2022	SYSTEM	\$535.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user schwaj2 overridding Paymen Estimate Exception 23 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$535.50)	
				- Total					
			Material - To	otal				\$0.00	
	1240 -	Total						\$0.00	
	1280	POWER SUPPLY	Material		9	Oct 17,	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment



Nov 5, 2022

					-				-
ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
273	1280	120V	Material	Type	9	Oct 17, 2022	SYSTEM	(\$2,000.00)	
					10	Nov 2, 2022	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schwaj2 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					10	Nov 2, 2022	SYSTEM	(\$2,000.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	1280 - Total							\$0.00	
	1300	PULL BOX,	Material		7	San 16	SYSTEM		This adjustment effects the avising outern consisted Material Doument
	1300	PREFORMED CLASS 3	Material			Sep 16, 2022		\$1,920.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schwaj2 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$1,920.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	1300 -	Total						\$0.00	
	1310	BASE, CONCRETE	Material		7	Sep 16, 2022	SYSTEM	\$27,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schwaj2 overridding Payment Estimate Exception 40 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$27,260.00)	
					8	Oct 3, 2022	SYSTEM	\$27,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0022) due to user schwaj2 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					8	Oct 3, 2022	SYSTEM	(\$27,260.00)	
				- Total				\$0.00	
			Material - T	otal				\$0.00	
	1310 -	Total						\$0.00	
ĺ	1320	D CONCRETE FOOTINGS, EMBEDDED	Material		5	Aug 16, 2022	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0045) due to user schwaj2 overridding Payment Estimate Exception 68 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$1,110.00)	
					6	Sep 2, 2022	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0031) due to user schwaj2 overridding Payment Estimate Exception 39 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$1,110.00)	
					7	Sep 16, 2022	SYSTEM	\$1,110.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schwaj2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$1,110.00)	
				- Total				\$0.00	
				- Total					
			Material - Te					\$0.00	
	1320 -	Total	Material - To					\$0.00 \$0.00	
	1320 - 1330	BREAKAWAY ASSEMBLY (PERFORATED			5	Aug 16, 2022	SYSTEM		This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user schwaj2 overridding Payment Estimate Exception 69 on the current Payment Estimate.
		BREAKAWAY ASSEMBLY			5		SYSTEM	\$0.00	Estimate Item Adjustment (0046) due to user schwaj2 overridding Payment
		BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL				2022 Aug 16,		\$0.00 \$406.00	Estimate Item Adjustment (0046) due to user schwaj2 overridding Payment
		BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL			5	2022 Aug 16, 2022 Sep 2,	SYSTEM	\$0.00 \$406.00 (\$406.00)	Estimate Item Adjustment (0046) due to user schwaj2 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schwaj2 overridding Payment
		BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL			5	2022 Aug 16, 2022 Sep 2, 2022 Sep 2,	SYSTEM SYSTEM	\$0.00 \$406.00 (\$406.00) \$406.00	Estimate Item Adjustment (0046) due to user schwaj2 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schwaj2 overridding Payment
		BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL		otal - Total	5	2022 Aug 16, 2022 Sep 2, 2022 Sep 2,	SYSTEM SYSTEM	\$0.00 \$406.00 (\$406.00) \$406.00 (\$406.00)	Estimate Item Adjustment (0046) due to user schwaj2 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schwaj2 overridding Payment
		BREAKAWAY ASSEMBLY (PERFORATED SQUARE STEEL TUBE)	Material	otal - Total	5	2022 Aug 16, 2022 Sep 2, 2022 Sep 2,	SYSTEM SYSTEM	\$0.00 \$406.00 (\$406.00) \$406.00 (\$406.00) \$0.00	Estimate Item Adjustment (0046) due to user schwaj2 overridding Payment Estimate Exception 69 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0032) due to user schwaj2 overridding Payment



Nov 5, 2022

ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3273	1340	2 IN. PSST POST - 12 GA.	Material		5	Aug 16, 2022	SYSTEM	\$4,290.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0047) due to user schwaj2 overridding Payment Estimate Exception 70 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$4,290.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1340 -	Total						\$0.00	
	1350	POST ANCHOR FOR 2 IN. PSST - 12 GA.	Material		5	Aug 16, 2022	SYSTEM	\$1,596.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0048) due to user schwaj2 overridding Payment Estimate Exception 71 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$1,596.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1350 -	Total						\$0.00	
	1360	2.25 IN. PSST POST - 12 GA.	Material		5	Aug 16, 2022	SYSTEM	\$165.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0049) due to user schwaj2 overridding Payment Estimate Exception 72 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$165.00)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	1360 -	Total						\$0.00	
	1370	2.5 IN. PSST POST - 12 GA.	Material		5	Aug 16, 2022	SYSTEM	\$1,189.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0050) due to user schwaj2 overridding Payment Estimate Exception 73 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$1,189.00)	
			- Total					\$0.00	
			Material - To	otal				\$0.00	
	1370 -	Total						\$0.00	
	1380	POST ANCHOR FOR 2.5 IN. PSST - 7 GA.	Material		5	Aug 16, 2022	SYSTEM	\$765.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0051) due to user schwaj2 overridding Payment Estimate Exception 74 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$765.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1380 -	Total		1				\$0.00	
	1390	SH-FLAT SHEET	Material		5	Aug 16, 2022	SYSTEM	\$4,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0052) due to user schwaj2 overridding Payment Estimate Exception 75 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$4,128.00)	
					6	Sep 2, 2022	SYSTEM	\$4,128.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0033) due to user schwaj2 overridding Payment Estimate Exception 41 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$4,128.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1390 -	Total						\$0.00	
	1400	ST-STRUCTURAL	Material		5	Aug 16, 2022	SYSTEM	\$232.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0053) due to user schwaj2 overridding Payment Estimate Exception 76 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$232.00)	



Nov 5, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J4S3273	1400	ST-STRUCTURAL	Material		6	Sep 2, 2022	SYSTEM	(\$232.00)	
				- Total				\$0.00	
			Material - To	otal				\$0.00	
	1400 -	- Total						\$0.00	
	1410	MISC.	Material		5	Aug 16, 2022	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0054) due to user schwaj2 overridding Payment Estimate Exception 77 on the current Payment Estimate.
					5	Aug 16, 2022	SYSTEM	(\$300.00)	
					6	Sep 2, 2022	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0035) due to user schwaj2 overridding Payment Estimate Exception 43 on the current Payment Estimate.
					6	Sep 2, 2022	SYSTEM	(\$300.00)	
					7	Sep 16, 2022	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0034) due to user schwaj2 overridding Payment Estimate Exception 42 on the current Payment Estimate.
					7	Sep 16, 2022	SYSTEM	(\$300.00)	
				- Total					
			Material - To	otal					
	1410 -	Total						\$0.00	
J4S3273 ·	Total							\$55,599.40	
Overall -	Total							\$55,599.40	