

Progress Estimate 3	Number	Contract ID Prime Contract	211119-B01 or W. L. Miller Com		Pay Period Start Pay Period End	August 2, August 18		Original Contract Amount Net Change Order Amount Current Contract Amount	\$4,021,555.36 \$0.00 \$4,021,555.36
Approval Date									By User
August 16, 2022			Generated and Approved (and should be considered Draft) at the Project Office Level by						
August 16, 2022			Reviewed and App	proved (a	and should be cons	sidered Dra	ft) at the	e Resident Engineer Level by	vierss
August 17, 2022				Review	wed and Approved	at the Cen	tral Offic	ce Controllers Office Level by	ramses1
Original Completion	on Date	Current Co	mpletion Date	Ad	ctual Completion Date			% of Current Contract Amoun	t Complete
May 15, 202	May 15, 2023 Ma							60.14%	
	Contract I	nformational Dat	es		Milest	ones			
Date Description	Original C	Completion Date	Current Completio	n Date	No Milestones E	xist for Cor	ntract		
Acceptance Date									
Awarded Date	December	1, 2021	December 1, 2021						
Letting Date	November	19, 2021	November 19, 2021						
Notice to Proceed Date	July 1, 202	22	July 1, 2022						
Open to Traffic Date									
Work Began Date	June 21, 2	022	June 21, 2022						

Contract Total Pay For Estimate No. 3

This Estimate Previous To Date 211119-B01 Total Posted Items Pay Gross Item Adjustments \$74,081.24 \$2,344,387.79 \$2,418,469.03 Incentive \$0.00 \$542,450.60 \$500,062.10 Disincentive \$0.00 \$0.00 \$0.00 Liquidated Damage \$0.00 \$0.00 \$0.00 Other Contract Adjustments \$0.00 \$0.00 \$0.00 Expension \$0.00 \$0.00 \$0.00	Contract Total Payable This Estimate:	\$31,692.74		
Z11119-B01 Total Posted Items Pay \$74,081.24 \$2,344,387.79 \$2,418,469.03 Gross Item Adjustments (\$42,388.50) \$542,450.60 \$500,062.10 Incentive \$0.00 \$0.00 \$0.00 Disincentive \$0.00 \$0.00 \$0.00 Liquidated Damage \$0.00 \$0.00 \$0.00			\$2,886,838.39	\$2,918,531.13
211119-B01 Total Posted Items Pay \$74,081.24 \$2,344,387.79 \$2,418,469.03 Gross Item Adjustments (\$42,388.50) \$542,450.60 \$500,062.10 Incentive \$0.00 \$0.00 \$0.00 Disincentive \$0.00 \$0.00 \$0.00	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
211119-B01 Total Posted Items Pay \$74,081.24 \$2,344,387.79 \$2,418,469.03 Gross Item Adjustments (\$42,388.50) \$542,450.60 \$500,062.10 Incentive \$0.00 \$0.00 \$0.00	Liquidated Damage	\$0.00	\$0.00	\$0.00
211119-B01 Total Posted Items Pay \$74,081.24 \$2,344,387.79 \$2,418,469.03 Gross Item Adjustments (\$42,388.50) \$ 542,450.60 \$500,062.10	Disincentive	\$0.00	\$0.00	\$0.00
211119-B01 Total Posted Items Pay \$74,081.24 \$ 2,344,387.79 \$2,418,469.03	Incentive	\$0.00	\$0.00	\$0.00
211119-B01	Gross Item Adjustments	(\$42,388.50)	\$542,450.60	\$500,062.10
	Total Posted Items Pay	<mark>\$74,081.24</mark>	\$2,344,387.79	\$2,418,469.03
This Estimate Previous To Date	211119-B01			
		This Estimate	Previous	To Date

Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J2MAMD03	0020	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$67.840	90.17	\$6,117.13
	0030	4071005	TACK COAT	GAL	\$2.300	122	\$280.60
	0090	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$30.000	22	\$660.00
	0100	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	EA	\$1,500.000	2	\$3,000.00
	0110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.120	51,388.6	\$6,166.63
	0120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.110	125,135.2	\$13,764.8
	0130	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$2.590	1,160	\$3,004.40
Project J2M	AMD03 - T	otal					\$32,993.63
J2MAMD10	0240	3105002	GRAVEL (A) OR CRUSHED STONE (B)	TONS	\$97.750	55.46	\$5,421.22
	0250	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	TONS	\$67.840	137.21	\$9,308.33
	0260	4071005	TACK COAT	GAL	\$2.300	171	\$393.30
	0310	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	LF	\$30.000	44	\$1,320.00
	0320	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	EA	\$1,500.000	2	\$3,000.00
	0330	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.120	40,237.6	\$4,828.57
	0340	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	LF	\$0.120	104,379.2	\$12,525.50
	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	SQYD	\$2.590	1,656.66	\$4,290.75



Progress Estimate Number 3		Contract ID Prime Contractor	211119-B01 W. L. Miller Company	Pay Period Start Pay Period End				\$4,021,555.36 \$0.00 \$4,021,555.36	
Project Line Item Number Number Code			Item Descriptio	n	Unit	Unit Price	Current Installed Qty	Current Installed Amount	
Project J2MAMD10 - Total									\$41,087.61
Overall - Total									\$74,081.24

Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2MAMD03	0010	GRAVEL (A) OR CRUSHED STONE (B)	MaterialCredit			77.14	\$97.75	\$7,540.44
	0010	GRAVEL (A) OR CRUSHED STONE (B)	Material			-77.14	\$97.75	(\$7,540.44)
	0010	GRAVEL (A) OR CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user peterc6 overridding Payment Estimate Exception 1 on the current Payment Estimate.	77.14	\$97.75	\$7,540.44
	0020	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	90.17	\$3.88	\$350.26
	0020	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL	-90.17	\$71.72	(\$6,467.39)
	0020	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	Other Item Adjustment	Asphalt Cement Price Adjustment	Documentation has been uploaded to eProjects.			\$1,248.52
	0030	TACK COAT	Material			-17,236	\$2.30	(\$39,642.80)
	0030	TACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user peterc6 overridding Payment Estimate Exception 3 on the current Payment Estimate.	17,236	\$2.30	\$39,642.80
	0050	CONSTRUCTION SIGNS	Material			-1,355	\$7.75	(\$10,501.25)
	0050	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user peterc6 overridding Payment Estimate Exception 5 on the current Payment Estimate.	1,355	\$7.75	\$10,501.25
	0060	CHANNELIZER (TRIM LINE)	Material			-25	\$20.00	(\$500.00)
	0060	CHANNELIZER (TRIM LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user peterc6 overridding Payment Estimate Exception 7 on the current Payment Estimate.	25	\$20.00	\$500.00
	0070	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			-2	\$2,800.00	(\$5,600.00)
	0070	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user peterc6 overridding Payment Estimate Exception 9 on the current Payment Estimate.	2	\$2,800.00	\$5,600.00
	0090	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24	Material			-22	\$30.00	(\$660.00)



Progres	s Estin 3		Contract ID Prime Contra	211119-E Ictor W. L. Mill		Pay Period End August 15, 2022 Net Ch	al Contract Ar ange Order A it Contract An	mount \$0	,021,555.36 .00 ,021,555.36
Project Number	Line No.	Item Descri	ption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2MAMD03			IN. WHITE						
	0100	THERM PAVEMENT MAR	REFORMED IOPLASTIC RKING, R/R G MARKER	Material			-2	\$1,500.00	(\$3,000.00
	0110	4 IN. WHITE S WATERBORNE F MARKING PAIN	PAVEMENT	Material			-51,388.6	\$0.12	(\$6,166.63
	0120	4 IN. YELLOW S WATERBORNE F MARKING PAIN	PAVEMENT	Material			-125,135.2	\$0.11	(\$13,764.87
J2MAMD10	0240	GRAVEL (A) OR	CRUSHED STONE (B)	MaterialCredit			92.04	\$97.75	\$8,996.91
	0240	GRAVEL (A) OR	CRUSHED STONE (B)	Material			-147.5	\$97.75	(\$14,418.12)
	0240	GRAVEL (A) OR	CRUSHED STONE (B)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0014) due to user peterce overridding Payment Estimate Exception 2 on the current Payment Estimate.		\$97.75	\$14,418.12
	0250	BITUMINOUS F MIXTUR (SURFACE I	RE PG64-22	Price		Reference Item Price Adjustment Index Adjustment Type applied is FUEL		\$3.88	\$532.98
	0250	BITUMINOUS F MIXTUR (SURFACE I	RE PG64-22	Overrun		Reference Item Price Adjustment Index Adjustment Type applied is FUEL		\$71.72	(\$9,841.30)
	0250	BITUMINOUS F MIXTUR (SURFACE I	RE PG64-22	Other Item Adjustment	Asphalt Cement Price Adjustment	Documentation has been uploaded to eProjects.			\$1,899.84
	0260	T	ACK COAT	Material			-13,746	\$2.30	(\$31,615.80
	0260	T.	ACK COAT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0017) due to user peterc6 overridding Payment Estimate Exception 4 on the current Payment Estimate.		\$2.30	\$31,615.80
	0280	CONSTRUCT	ION SIGNS	Material			-1,131	\$7.75	(\$8,765.25
	0280	CONSTRUCT	ION SIGNS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0018) due to user peterc6 overridding Payment Estimate Exception 6 on the current Payment Estimate.		\$7.75	\$8,765.25
	0290	CHANNELIZER (TRIM LINE)	Material			-15	\$20.00	(\$300.00)
	0290	CHANNELIZER (*	TRIM LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Exception 8 on the current Payment Estimate.		\$20.00	\$300.00
	0310		REFORMED IOPLASTIC ARKING, 24 IN. WHITE	Overrun			-11	\$30.00	(\$330.00)
	0310		REFORMED IOPLASTIC ARKING, 24 IN. WHITE	Material			-44	\$30.00	(\$1,320.00)
	0320		REFORMED IOPLASTIC RKING R/R	Material			-2	\$1,500.00	(\$3,000.00)



Progres	s Estin 3	nate Number	Contract ID Prime Contra	211119-E ctor W. L. Mil	301 ler Company	Pay Period Start Pay Period End	August 2, 2022 August 15, 2022	Net Cha	Contract Au Inge Order A Contract Ar	mount \$0	I,021,555.36).00 I,021,555.36
Project Number	Line No.	Item Des	cription	Adjustment Type	Other Item Adjustment Type	С	comments		Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J2MAMD10		CROSS	ING MARKER								
	0330	WATERBORN	E STANDARD E PAVEMENT AINT, TYPE P BEADS	Material					-40,237.6	\$0.12	(\$4,828.51
	0340	WATERBORN	V STANDARD E PAVEMENT AINT, TYPE P BEADS	Material					-104,379.2	\$0.12	(\$12,525.50
	0350			Overrun					-406.66	\$2.59	(\$1,053.25
Total											(\$42,388.50



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information						
Project Number											
J2MAMD03		Resurface	А	CLARK	from Rte. 136 to Rte. E in Williamstown						
J2MAMD05	2MAMD05 Resurface 149 ADAIR from Rte. 6 to Rte. 11 and from Rte. 11 to Rte. J in Goldsberry										
J2MAMD10		Resurface	U	SCOTLAND	from Rte. 136 to Rte. A 1.9 miles south of Wyaconda						

Totals by Job Numbers

J2MAMD03		This Estimate	Previous	To Date
P	Posted Item Pay	\$32,993.63	\$1,306,477.87	\$1,339,471.50
	Bross Item Adjustments	(\$20,919.67)	\$321,850.93	\$300,931.26
	Gross Item Pay	\$12,073.96	\$1,628,328.80	\$1,640,402.76
	ncentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	iquidated Damages	\$0.00	\$0.00	\$0.00
C	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
J2MAMD05			_ ·	
		This Estimate	Previous	To Date
	osted Item Pay	\$0.00	\$0.00	\$0.00
G	Bross Item Adjustments	\$0.00	\$0.00	\$0.00
	Gross Item Pay	\$0.00	\$0.00	\$0.00
	ncentive	\$0.00	\$0.00	\$0.00
C	Disincentive	\$0.00	\$0.00	\$0.00
	iquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00
J2MAMD10		This Estimate	Previous	To Date
	Posted Item Pay	\$41,087.61	\$1,037,909.92	\$1,078,997.53
	Bross Item Adjustments	(\$21,468,83)	\$220.599.67	\$199.130.84
	Gross Item Pay	\$19,618.78	\$220,599.07 \$1,258,509.59	\$199,130.64 \$1,278,128.37
	Gloss item Pay	\$19,010.70	\$1,256,509.59	\$1,270,120.37
	ncentive	\$0.00	\$0.00	\$0.00
C	Disincentive	\$0.00	\$0.00	\$0.00
L	iquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 3105002, Project Item Line Number 0010, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Need to get with Materials to change testing requirements.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 3105002, Project Item Line Number 0240, Material Set 310500296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Need to get with Materials to change testing requirements.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 4071005, Project Item Line Number 0030, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Paperwork has been received, need to make a sample ID.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 4071005, Project Item Line Number 0260, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	Paperwork has been received, need to make a sample ID.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6161005, Project Item Line Number 0050, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Paperwork has been received, need to make a sample ID.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 6161005, Project Item Line Number 0280, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Paperwork has been received, need to make a sample ID.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6161025, Project Item Line Number 0060, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Paperwork has been received, need to make a sample ID.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 6161025, Project Item Line Number 0290, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Paperwork has been received, need to make a sample ID.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6161098A, Project Item Line Number 0070, Material Set 6161098A96, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Paperwork has been received, need to make a sample ID.	peterc6	Overridden
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6200015, Project Item Line Number 0090, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 6200015, Project Item Line Number 0310, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6200033, Project Item Line Number 0100, Material Set 620003396, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 6200033, Project Item Line Number 0320, Material Set 620003396, Material 1048PMPFWHXX - Pref Mrk Tape Direct Indcat or Shape WH, Acceptance Action Generic 1048PMPFWHXX is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6206000C, Project Item Line Number 0110, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 6206000C, Project Item Line Number 0330, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 6206000C, Project Item Line Number 0330, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD03, Item 6206001C, Project Item Line Number 0120, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 6206001C, Project Item Line Number 0340, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Insufficient Materials: Project J2MAMD10, Item 6206001C, Project Item Line Number 0340, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	Have not received certs. yet.	peterc6	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-B01, Contract Project J2MAMD03, Project Item Line Number 0020, Contract Line Item Number 0020, Item 4020520, Minor Item.	Waiting on Change Order	peterc6	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-B01, Contract Project J2MAMD10, Project Item Line Number 0250, Contract Line Item Number 0250, Item 4020520, Minor Item.	Waiting on Change Order	peterc6	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-B01, Contract Project J2MAMD10, Project Item Line Number 0310, Contract Line Item Number 0310, Item 6200015, Minor Item.	Waiting on Change Order	peterc6	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-B01, Contract Project J2MAMD10, Project Item Line Number 0350, Contract Line Item Number 0350, Item 6221001, Minor Item.	Waiting on Change Order	peterc6	Acknowledged

Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Item Overrun: Contract 211119-B01, Contract Project J2MAMD10, Project Item Line Number 0360, Contract Line Item Number 0360, Item 6224010, Minor Item.	Waiting on Change Order	peterc6	Acknowledged

Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
19-B01	J2MAMD03	0001	0010	3105002	GRAVEL (A) OR CRUSHED STONE (B)	245.00	0.00	245.00	TONS	77.14	\$97.75	\$7,540.4
		0001	0020	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	17,401.70	0.00	17,401.70	TONS	17,809.99	\$67.84	\$1,208,229.7
		0001	0030	4071005	TACK COAT	19,678.00	0.00	19,678.00	GAL	17,236.00	\$2.30	\$39,642.8
		0001	0040	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.0
		0001	0050	6161005	CONSTRUCTION SIGNS	1,934.00	0.00	1,934.00	SQFT	1,355.00	\$7.75	\$10,501.2
		0001	0060	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	25.00	\$20.00	\$500.
		0001	0070	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$2,800.00	\$5,600.0
		0001	0080	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$28,050.00	\$28,050.0
		0001	0090	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN.	22.00	0.00	22.00	LF	22.00	\$30.00	\$660.
		0001	0100	6200033	WHITE PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000.
		0001			CROSSING MARKER							φ0,000.
		0001	0110	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	64,236.00	0.00	64,236.00	LF	51,388.60	\$0.12	\$6,166.
		0001	0120	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	156,419.00	0.00	156,419.00	LF	125,135.20	\$0.11	\$13,764.8
		0001	0130	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	7,362.00	0.00	7,362.00	SQYD	4,254.28	\$2.59	\$11,018.5
		0001	0140	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,445.00	0.00	1,445.00	SQYD	959.44	\$5.00	\$4,797.2
	Project J2M	AMD03 - To	otal Value	Posted to D	ate as of Report Generated Date							\$1,339,471.5
	J2MAMD05	0001	0150	3105002	GRAVEL (A) OR CRUSHED STONE (B)	298.00	0.00	298.00	TONS	0.00	\$100.00	\$0.
		0001	0160	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	20,743.20	0.00	20,743.20	TONS	0.00	\$69.22	\$0.
		0001	0170	4071005	TACK COAT	23,316.00	0.00	23,316.00	GAL	0.00	\$2.30	\$0.
		0001	0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.
		0001	0190	6161005	CONSTRUCTION SIGNS	3,225.00	0.00	3,225.00	SQFT	0.00	\$7.75	\$0.
		0001	0200	6161025	CHANNELIZER (TRIM LINE)	25.00	0.00	25.00	EA	0.00	\$20.00	\$0.
		0001	0210	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$19,625.00	\$0.0
		0001	0220	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	242,955.00	0.00	242,955.00	LF	0.00	\$0.12	\$0.
		0001	0230	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	2,425.00	0.00	2,425.00	SQYD	0.00	\$5.00	\$0.0
	Project J2M	AMD05 - To	otal Value	Posted to D	ate as of Report Generated Date							\$0.0
	J2MAMD10	0001	0240	3105002	GRAVEL (A) OR CRUSHED STONE (B)	170.00	0.00	170.00	TONS	147.50	\$97.75	\$14,418.
		0001	0250	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	13,665.80	0.00	13,665.80	TONS	14,158.85	\$67.84	\$960,536.
		0001	0260	4071005	TACK COAT	15,381.00	0.00	15,381.00	GAL	13,746.00	\$2.30	\$31,615
		0001	0270	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$500.00	\$0.
		0001	0280	6161005	CONSTRUCTION SIGNS	1,667.00	0.00	1,667.00	SQFT	1,131.00	\$7.75	\$8,765.
		0001	0290	6161025	CHANNELIZER (TRIM LINE)	100.00	0.00	100.00	EA	15.00	\$20.00	\$300.
		0001	0300	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$26,725.00	\$26,725.
		0001	0310	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	33.00	0.00	33.00	LF	44.00	\$30.00	\$1,320
		0001	0320	6200033	PREFORMED THERMOPLASTIC PAVEMENT MARKING, R/R CROSSING MARKER	2.00	0.00	2.00	EA	2.00	\$1,500.00	\$3,000
		0001	0330	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	50,297.00	0.00	50,297.00	LF	40,237.60	\$0.12	\$4,828.
		0001	0340	6206001C	MARKING PAINT, TYPE P BEADS	130,474.00	0.00	130,474.00	LF	104,379.20	\$0.12	\$12,525
		0001	0350	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,250.00	0.00	1,250.00	SQYD	1,656.66	\$2.59	\$4,290.
			000-	0001								
		0001	0360	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,599.00	0.00	1,599.00	SQYD	2,134.44	\$5.00	\$10,672 \$1,078,997.



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2MAMD03

Line Number	ltem Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0020	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	8/2/22	8/4/22	90.17	TONS	City of Wyaconda around RR tracks	5.120		5.044		
0030	4071005	TACK COAT	8/2/22	8/4/22	122.00	GAL	City of Wyaconda around RR tracks	5.120		5.044		
0090	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	8/10/22	8/15/22	22.00	LF	Wyaconda					
0100	6200033	PREF THERMO PVMT MARK, R/R XING	8/10/22	8/15/22	2.00	EA	Wyaconda					
0110	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	8/9/22	8/15/22	51,388.60	LF	Whole Job					80% until retro results
0120	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	8/9/22	8/15/22	125,135.20	LF	whole job					80% until retro results
0130	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	8/2/22	8/4/22	1,160.00	SQYD	City of Wyaconda around RR tracks	5.120		5.044		

Project: J2MAMD10

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0240	3105002	GRAVEL (A) OR CRUSHED STONE (B)	8/1/22	8/4/22	55.46	TONS		0.000		5.839		
0250	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	8/3/22	8/4/22	137.21	TONS	City of Gorin around RR tracks	10.554		10.419		
0260	4071005	TACK COAT	8/3/22	8/4/22	171.00	GAL	City of Gorin around RR tracks	10.554		10.419		
0310	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	8/10/22	8/15/22	44.00	LF	Gorin					
0320	6200033	PREF THERMO PVMT MARK, R/R XING	8/10/22	8/15/22	2.00	EA	Gorin					
0330	6206000C	4 IN. WHITE WATERBORNE PAVEMENT MARKING	8/9/22	8/15/22	40,237.60	LF	whole job					80% until retro results
0340	6206001C	4 IN. YELLOW WATERBORNE PAVEMENT MARKING	8/9/22	8/15/22	104,379.20	LF	whole job					80% until retro results
0350	6221001	COLDMILLING BIT. PAVT FOR REM OF SURF.	8/3/22	8/4/22	1,656.66	SQYD	City of Gorin around RR tracks	10.554		10.419		

The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J2MAMD03	0050	June 21, 2022	1323	GO20-4 36x18 4.50 PILOT CAR FOLLOW ME				1.00	4.5			4.5
				GO20-2 48x24 8.00 END ROAD WORK				2.00	8			16
				CONST-7 48x24 8.00 RATE OUR WORK ZONE				2.00	8			16
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES				2.00	10			20
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE				2.00	12			24
				WO8-12 48x48 16.00 NO CENTER LINE				20.00	16			320
				WO8-11 48x48 16.00 UNEVEN LANES				39.00	16			624
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD				6.00	16			96
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD				6.00	16			96
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS				6.00	16			96
				See Special Sign Details				7.00		Pilot Car in Use Wait & Follow	1.50	10.5
		July 18, 2022	32	See Special Sign Details				2.00		WO8-8 48x48 16.00 ROUGH ROAD	16.00	32.00
	0050 - Total											135
J2MAMD10	0280	June 21, 2022	764	WO8-12 48x48 16.00 NO CENTER LINE				14.00	16			224
				WO8-12 48x48 16.00 NO CENTER LINE				29.00	16			464
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE				2.00	12			24
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES				2.00	10			20
				CONST-7 48x24 8.00 RATE OUR WORK ZONE				2.00	8			16
				GO20-2 48x24 8.00 END ROAD WORK				2.00	8			16
		July 18, 2022	367	GO20-4 36x18 4.50 PILOT CAR FOLLOW ME				1.00	4.50			4.50
				WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS				5.00	16.00			80.00
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD				5.00	16.00			80.00
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD				5.00	16.00			80.00
				See Special Sign Details				4.00		WO8-8 48x48 16.00 ROUGH ROAD	16.00	64.00
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD				3.00	16.00			48.00
				See Special Sign Details				7.00		SPECIAL - Pilot Car in Use Wait and Follow	1.50	10.50
	0280 - Total											113



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2MAMD03	0010	GRAVEL (A) OR CRUSHED STONE	Material		1	Jul 15, 2022	SYSTEM	(\$7,540.44)	
		(B)			2	Aug 1, 2022	SYSTEM	(\$7,540.44)	
					3	Aug 16, 2022	SYSTEM	\$7,540.44	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user peterc6 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Aug 16, 2022	SYSTEM	(\$7,540.44)	
				- Total				(\$15,080.88)	
			Material - Tota					(\$15,080.88)	
			MaterialCredit		2	Aug 1, 2022	SYSTEM	\$7,540.44	
					3	Aug 16, 2022	SYSTEM	\$7,540.44	
				- Total				\$15,080.88	
			MaterialCredit	- Total				\$15,080.88	
	00 <u>10</u> -	Total						\$0.00	
	0020	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SUR	Other Item Adjustment	ACAD	1	Jul 15, 2022	vierss	\$226,570.05	
					3	Aug 16, 2022	peterc6	\$1,248.52	Documentation has been uploaded to eProjects.
				ACAD - Tota	al			\$227,818.57	
			Other Item Adj	justment - To	tal			\$227,818.57	
			Overrun	Overrun	1	Jul 15, 2022	SYSTEM	(\$24,052.67)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Aug 16, 2022	SYSTEM	(\$6,467.39)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - T	otal			(\$30,520.06)	
			Overrun - Tota	ıl				(\$30,520.06)	
			Price FUEL		1	Jul 15, 2022	SYSTEM	\$126,873.99	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					3	Aug 16, 2022	SYSTEM	\$350.26	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
								\$127,224.25	
			Price FUEL - T	otal				\$127,224.25	
	0020 -	Total						\$324,522.76	
	0030	TACK COAT	Material		1	Jul 15, 2022	SYSTEM	\$39,362.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user peterc6 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Jul 15, 2022	SYSTEM	(\$39,362.20)	
					2	Aug 1, 2022	SYSTEM	\$39,362.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user peterc6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					2	Aug 1, 2022	SYSTEM	(\$39,362.20)	
					3	Aug 16, 2022	SYSTEM	\$39,642.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user peterc6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Aug 16, 2022	SYSTEM	(\$39,642.80)	
				- Total				\$0.00	
			Material - Total					\$0.00	
	0030 -	Total						\$0.00	
	0050	CONSTRUCTION SIGNS	Material		1	Jul 15, 2022	SYSTEM	\$10,253.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user peterc6 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Jul 15, 2022	SYSTEM	(\$10,253.25)	
					2	Aug 1, 2022	SYSTEM	\$10,501.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user peterc6 overridding Payment Estimate Exception 5 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
J2MAMD03	0050	CONSTRUCTION SIGNS	Material	51	2	Aug 1, 2022	SYSTEM	(\$10,501.25)		
					3	Aug 16, 2022	SYSTEM	\$10,501.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user peterc6 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					3	Aug 16, 2022	SYSTEM	(\$10,501.25)		
				- Total				\$0.00		
			Material - Tota	1				\$0.00		
	0050 -	Total						\$0.00		
	0060	CHANNELIZER (TRIM LINE)	Material		1	Jul 15, 2022	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user peterc6 overridding Payment Estimate Exception 5 on the current Payment Estimate.	
					1	Jul 15, 2022	SYSTEM	(\$500.00)		
					2	Aug 1, 2022	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user peterc6 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					2	Aug 1, 2022	SYSTEM	(\$500.00)		
					3	Aug 16, 2022	SYSTEM	\$500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user peterc6 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
						3	Aug 16, 2022	SYSTEM	(\$500.00)	
				- Total				\$0.00		
			Material - Tota	I				\$0.00		
	0060 -	Total						\$0.00		
	0070	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material		1	Jul 15, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user peterc6 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					1	Jul 15, 2022	SYSTEM	(\$5,600.00)		
					2	Aug 1, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user peterc6 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					2	Aug 1, 2022	SYSTEM	(\$5,600.00)		
					3	Aug 16, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user peterc6 overridding Payment Estimate Exception 9 on the current Payment Estimate.	
					3	Aug 16, 2022	SYSTEM	(\$5,600.00)		
				- Total				\$0.00		
			Material - Tota	1				\$0.00		
	0070 -	Total						\$0.00		
	0090	PREF THERMO PVMT MARK, 24 IN WHIT	Material		3	Aug 16, 2022	SYSTEM	(\$660.00)		
		IN WHIT		- Total				(\$660.00)		
			Material - Tota	I				(\$660.00)		
	0090 -	Total						(\$660.00)		
	0100	PREF THERMO PVMT MARK, R/R XING	Material		3	Aug 16, 2022	SYSTEM	(\$3,000.00)		
				- Total				(\$3,000.00)		
			Material - Tota					(\$3,000.00)		
	0100 -				0		0.10	(\$3,000.00)		
	0110	4 IN. WHITE WATERBORNE PAVEMENT	Material	Total	3	Aug 16, 2022	SYSTEM	(\$6,166.63)		
		MARKING	Marken de la marken	- Total				(\$6,166.63)		
	0440		Material - Tota					(\$6,166.63)		
	0110 -		Matorial		3	Aug 40	QVOTEM	(\$6,166.63)		
	0120	4 IN. YELLOW WATERBORNE	Material		3	Aug 16, 2022	SYSTEM	(\$13,764.87)		



ZAMADO ZAMADO SUBPart SubPart Su	Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
MARING Value and Total Value and Total Value and Total 232AM003 GRAFED PLOSE Face and Total Face and Total Face and Total 234M003 GRAFED PLOSE Face and Total Face and Total Face and Total Face and Total 234M014 GRAFED PLOSE Face and Total Face and Tot		LIIIO	Decemption		Adjustment				, anotant	
distantional problem distantional problem distantional problem distantional problem JAMAND2 10 600 GRAVEL (n) CR Image: Second problem	J2MAMD03	0120		Material	- Total				(\$13,764.87)	
JUMAND1 CPU COUNCE (C) CPUSINED STORE CPUSINED STORE				Material - Tota	ıl				(\$13,764.87)	
220A ND 10 Q240 Q340 <td></td> <td></td> <td>Total</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>			Total							
CRUSHED STONE ICAUSTICATION	J2MAMD03 -	- Total							\$300,931.26	
View Aug. 6 PSTEM 314.418.12 Time alguing method fields the original system-gametedd Material Pyrometed Extension Exception 2 on the current Pyromet Extension - Fouriar - Fou	J2MAMD10	0240	CRUSHED STONE	Material		2		SYSTEM	(\$8,996.91)	
ViewV						3		SYSTEM	\$14,418.12	Estimate Item Adjustment (0014) due to user peterc6 overridding Payment
Material - Total (18,99,01) (18,99,01) (18,99,01) Material - Total -						3		SYSTEM	(\$14,418.12)	
MaterialCreat Image: Signal Sig				Motorial Tota						
Image: constraint of the second se						2	Aug 16	SVSTEM		
Control Status Statu				Watenaicredit		5		STOTEM	φ0,990.91	
0240 - Total Other Item MELENIA PGR-22 (SUR PGR-22					- Total				\$8,996.91	
0250 BTXMEND MXUUE DG8L-22 (SUR MXUUE DG8L-22 (SUR MXUUE DG8L-22 (SUR MXUUE DG8L-22 (SUR MXUUE DG8L-23				MaterialCredit	- Total				\$8,996.91	
Adjustment MCTURE POG-22 (SUR H Adjustment MCTURE POG-20 (SUR H Adjustment MCT		0240 -	Total						\$0.00	
PG64-22 (SIR G A Aug 16, peteros \$1.893.40 Documentation has been uploaded to eProjects. ACAD-131		0250	PAVEMENT		ACAD	2		peterc6	\$179,284.19	Documentation has been uploaded to eProjects.
Other Iton Adjustment - Total Overun Overun Overun SYSTEM SYSTEM Staf.184.03 Reference item Price Adjustment Index Adjustment Type applied is FUEL 0verun - Overun - Overun - Overun SYSTEM (\$9.81.130) Reference item Price Adjustment Index Adjustment Type applied is FUEL Overun - Over						3		peterc6	\$1,899.84	Documentation has been uploaded to eProjects.
Overrun Overrun 2 Aug 1, 2022 SYSTEM (\$28,148,55) Reference Item Price Adjustment Index Adjustment Type applied is FUEL 2022 Contract (\$35,989,85) Overrun - Total Overrun - Total (\$35,989,85) Reference Item Price Adjustment Index Adjustment Type applied is FUEL 2022 Overrun - Total (\$35,989,85) Reference Item Price Adjustment Index Adjustment Type applied is FUEL 2022 Overrun - Total 2 Aug 1, 2022 SYSTEM \$79,138,14 Reference Item Price Adjustment Index Adjustment Type applied is FUEL 2020 Overrun - Total 2 Aug 1, 2022 SYSTEM \$532,280 Reference Item Price Adjustment Index Adjustment Type applied is FUEL 2020 Total SYSTEM \$531,225.00 Total System Si31,225.00 Etimate Item Adjustment Offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 0260 TACK COAT Material Aug 1, 2022 SYSTEM \$31,225.00 Etimate Item Adjustment Offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 0260 CONSTRUCTION Material - Total SySTEM \$31,615.80 This adjustment offsets the original system-generated Material Payment Estimate Exception										
$ \begin{array}{ c c c c c c } \hline c c c c c c c c c c c c c c c c c c $				Other Item Adj	justment - To	tal			\$181,184.03	
$ \begin{array}{ c c c c } \hline \hline$				Overrun	Overrun	2		SYSTEM	(\$26,148.55)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Overrun - Total Visit Sign Sign Sign Sign Sign Sign Sign Sign						3		SYSTEM	(\$9,841.30)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price FUEL 2 Aug 1, 2022 SYSTEN S79,138.41 Reference Item Price Adjustment Index Adjustment Type applied is FUEL - Total - Total - SYSTEN S32.98 Reference Item Price Adjustment Index Adjustment Type applied is FUEL 0250 Total - S79,671.12 - SYSTEN S43.28 Reference Item Price Adjustment Index Adjustment Type applied is FUEL 0260 Total - SYSTEN S43.28 Reference Item Price Adjustment Index Adjustment Type applied is FUEL 0260 Total - SYSTEN SYSTEN S10.50 0260 TACK COAT Material 2 Aug 1, 2022 SYSTEN S31,615.80 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user peterc6 overridding Payment Estimate Item Adjustment (0017) due to user peterc6 overridding Payment Estimate Item Adjustment (0017) due to user peterc6 overridding Payment Estimate Item Adjustment (0017) due to user peterc6 overridding Payment Estimate Item Adjustment (0017) due to user peterc6 overridding Payment Estimate Item Adjustment (017) due to user peterc6 overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 0280 </td <td></td> <td></td> <td></td> <td></td> <td>Overrun - T</td> <td>otal</td> <td></td> <td></td> <td>(\$35,989.85)</td> <td></td>					Overrun - T	otal			(\$35,989.85)	
$ \begin{array}{ c c c } \hline \\ \hline $				Overrun - Tota	ıl				(\$35,989.85)	
Visit Construction State				Price FUEL	ce FUEL	2		SYSTEM	\$79,138.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
Price FUEL - Total S79,671.12 O250 - Total S224,865.30 O260 - Total Aug 1, 2022 SYSTEM \$31,222.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate Estimate Exception 4 on the current Payment Estimate Esception 4 on the current Payment Estimate Estimate Esception 4 on the current Payment Estimate Estimate Estimate Esception 4 on the current Payment Estimate Estimate Esception 4 on the current Payment Estimate. </td <td></td> <td></td> <td></td> <td>3</td> <td></td> <td>SYSTEM</td> <td>\$532.98</td> <td>Reference Item Price Adjustment Index Adjustment Type applied is FUEL</td>						3		SYSTEM	\$532.98	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
0250 - Total S224,865.30 0260 TACK COAT Material 2 Aug 1, 2022 SYSTEM \$31,222.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate Exception 4 on the current Payment Estimate 2 Aug 1, 2022 SYSTEM \$31,222.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate 2 Aug 1, 2022 SYSTEM \$31,615.80 This adjustment offsets the original system-generated Material Payment Estimate - Total - Total SYSTEM \$31,615.80 Stante Exception 4 on the current Payment Estimate. 0260 - Total - Total - Total SYSTEM \$31,615.80 Stante Exception 4 on the current Payment Estimate. 0260 - Total - Total SYSTEM \$1,615.80 SYSTEM \$31,615.80 0260 - Total SYSTEM \$2,022 \$50.00 SYSTEM \$5,921.00 Stimate Item Adjustment offsets the original system-generated Material Payment Estimate 0280 - CONSTRUCTION Material 1 Juli 15, 2022 \$YSTEM \$5,921.00 Stimate Item Adjustment offsets the original system-generated Material Payment Estimate 2022 - 2022 SYSTE					- Total				\$79,671.12	
0260 TACK COAT Material 2 Aug 1, 2022 SYSTEM S31,222.50 This adjustment offsets the original system-generated Material Payment Estimate tem Adjustment (0018) due to user petero6 overridding Payment 2002 2 Aug 1, 2022 SYSTEM S31,222.50 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 2 Aug 1, 2022 SYSTEM S31,615.80 Estimate Exception 4 on the current Payment Estimate. 2 Aug 1, 2022 SYSTEM S31,615.80 Estimate Item Adjustment (0017) due to user petero6 overridding Payment Estimate. 3 Aug 1, 2022 SYSTEM S31,615.80 Estimate Item Adjustment (0017) due to user petero6 overridding Payment Estimate. 0260 - Total - Total - Total S31,615.80 Estimate Item Adjustment (0017) due to user petero6 overridding Payment Estimate. 0260 - Total - Total - Total - Total S30.00 Estimate Item Adjustment (0018) due to user petero6 overridding Payment Estimate. 0280 CONSTRUCTION Material - Total Jul 15, 2022 SYSTEM S5,921.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 0280 CONSTRUCTION Aug 1, 2022 </td <td></td> <td></td> <td></td> <td>Price FUEL - T</td> <td>otal</td> <td></td> <td></td> <td></td> <td>\$79,671.12</td> <td></td>				Price FUEL - T	otal				\$79,671.12	
Vertical integration Vertical integratintegrat Vertical integration		0250 -	Total						\$224,865.30	
$ \begin{array}{ c c c c } \hline 1 \\ 1 \\ 1 \\ $		0260	TACK COAT	Material		2		SYSTEM	\$31,222.50	Estimate Item Adjustment (0018) due to user peterc6 overridding Payment
$ \begin{array}{ c c c c c } \hline \\ \hline $						2	Aug 1, 2022	SYSTEM	(\$31,222.50)	
$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$						3		SYSTEM	\$31,615.80	Estimate Item Adjustment (0017) due to user peterc6 overridding Payment
Material - Total \$0.00 Octo - Total 0280 CONSTRUCTION SIGNS Material 1 Jul 15, 2022 SYSTEM \$5,921.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user peterc6 overridding Payment Estimate Exception 4 on the current Payment Estimate. 2 Aug 1, 2022 SYSTEM \$8,765.25 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Exception 6 on the current Payment Estimate.						3		SYSTEM	(\$31,615.80)	
O260 - Total S0.00 0280 CONSTRUCTION SIGNS Material 1 Jul 15, 2022 SYSTEM \$5,921.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 1 Jul 15, 2022 SYSTEM \$(\$5,921.00) This adjustment offsets the original system-generated Material Payment Estimate. 2 Aug 1, 2022 SYSTEM \$(\$5,921.00) Statute Item Adjustment (0019) due to user peterc6 overridding Payment Estimate. 2 Aug 1, 2022 SYSTEM \$(\$8,765.25) This adjustment offsets the original system-generated Material Payment Estimate. 2 Aug 1, 2022 SYSTEM \$(\$8,765.25) This adjustment offset the original system-generated Material Payment Estimate.					- Total				\$0.00	
0280 CONSTRUCTION SIGNS Material 1 Jul 15, 2022 SYSTEM \$5,921.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. 1 Jul 15, 2022 SYSTEM \$\$5,921.00 This adjustment (0018) due to user peterc6 overridding Payment Estimate Exception 4 on the current Payment Estimate. 2 Aug 1, 2022 SYSTEM \$\$8,765.25 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 2 Aug 1, 2022 SYSTEM \$\$8,765.25 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate.				Material - Tota	1				\$0.00	
SIGNS 2022 2022 Estimate Item Adjustment (0018) due to user peterc6 overridding Payment Estimate Exception 4 on the current Payment Estimate. 1 Jul 15, 2022 SYSTEM (\$5,921.00) 2 Aug 1, 2022 SYSTEM \$8,765.25 This adjustment (0019) due to user peterc6 overridding Payment Estimate. 2 Aug 1, 2022 SYSTEM \$(\$8,765.25) This adjustment (0019) due to user peterc6 overridding Payment Estimate. 2 Aug 1, 2022 SYSTEM \$(\$8,765.25) This adjustment (0019) due to user peterc6 overridding Payment Estimate.		0260 -	Total						\$0.00	
2022 2022 2022 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Exception 6 on the current Payment Estimate. 2 Aug 1, 2022 SYSTEM \$8,765.25 This adjustment offsets the original system-generated Material Payment Estimate Exception 6 on the current Payment Estimate. 2 Aug 1, 2022 SYSTEM \$8,765.25		0280		Material		1		SYSTEM	\$5,921.00	Estimate Item Adjustment (0018) due to user peterc6 overridding Payment
2022 Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Exception 6 on the current Payment Estimate. 2 Aug 1, 2022 2022 SYSTEM 2022 SYSTEM						1		SYSTEM	(\$5,921.00)	
2022						2		SYSTEM	\$8,765.25	Estimate Item Adjustment (0019) due to user peterc6 overridding Payment
3 Aug 16. SYSTEM \$8,765.25 This adjustment offsets the original system-generated Material Payment						2		SYSTEM	(\$8,765.25)	
						3	Aug 16, 2022	SYSTEM	\$8,765.25	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user peterc6 overridding Payment



Aug 18, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J2MAMD10	0280	CONSTRUCTION SIGNS	Material						Estimate Exception 6 on the current Payment Estimate.
					3	Aug 16, 2022	SYSTEM	(\$8,765.25)	
				- Total				\$0.00	
			Material - Total						
	0280 -	Total						\$0.00	
	0290	CHANNELIZER (TRIM LINE)	Material		2	Aug 1, 2022	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user peterc6 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					2	Aug 1, 2022	SYSTEM	(\$300.00)	
					3	Aug 16, 2022	SYSTEM	\$300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user peterc6 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					3	Aug 16, 2022	SYSTEM	(\$300.00)	
				- Total				\$0.00	
			Material - Tota	1				\$0.00	
	0290 -	Total						\$0.00	
	0310	PREF THERMO PVMT MARK, 24 IN WHIT	Material		3	Aug 16, 2022	SYSTEM	(\$1,320.00)	
				- Total				(\$1,320.00)	
			Material - Tota	I				(\$1,320.00)	
			Overrun	Overrun		Aug 16, 2022	SYSTEM	(\$330.00)	
				Overrun - T	otal			(\$330.00)	
			Overrun - Tota	l			(\$330.00)		
	0310 -							(\$1,650.00)	
	0320	PREF THERMO PVMT MARK, R/R XING	Material		3	Aug 16, 2022	SYSTEM	(\$3,000.00)	
			Material Tata	- Total				(\$3,000.00)	
	0320 -	Tetal	Material - Tota					(\$3,000.00)	
	0320 -	4 IN. WHITE	Material		3	Aug 16,	SYSTEM	(\$3,000.00) (\$4,828.51)	
		WATERBORNE PAVEMENT MARKING		- Total		2022		(\$4,828.51)	
		MARKING	Material - Tota					(\$4,828.51)	
	0330 -	· Total						(\$4,828.51)	
	0340	4 IN. YELLOW WATERBORNE	Material		3	Aug 16, 2022	SYSTEM	(\$12,525.50)	
		PAVEMENT MARKING	1	- Total		1		(\$12,525.50)	
			Material - Tota					(\$12,525.50)	
	0340 -	Total						(\$12,525.50)	
	0350	COLDMILLING BIT. PAVT FOR REM OF SURF.	Overrun	Overrun	3	Aug 16, 2022	SYSTEM	(\$1,053.25)	
		NEW OF SURF.		Overrun - T	otal			(\$1,053.25)	
			Overrun - Tota	I				(\$1,053.25)	
	_	Total						(\$1,053.25)	
	0360	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	Overrun	Overrun		Jul 15, 2022	SYSTEM	(\$738.30)	
					2	Aug 1, 2022	SYSTEM	(\$1,938.90)	
			Overrun - Total					(\$2,677.20)	
			Overrun - Tota					(\$2,677.20)	
		Total						(\$2,677.20)	
J2MAMD10								\$199,130.84	
Overall - To	tal							\$500,062.10	