## Pay Estimate Created Date: April 3, 2023

Progress Estimate Number 29			211119-F01 KCI Construction Compa	2	2023 Original Contract Amount 23 Net Change Order Amount Current Contract Amount	\$49,997,800.00 \$872,018.03 \$50,869,818.03
Approval Date						By User
April 3, 2023			Generated and Approv	ved (and should be considered D	raft) at the Project Office Level by	wolkt1
April 4, 2023		F	eviewed and Approved (	and should be considered Draft) a	at the Resident Engineer Level by	morgac1
April 5, 2023			Revie	wed and Approved at the Central	Office Controllers Office Level by	ramses1
Original Complet	ion Date	Current Cor	npletion Date	Actual Completion Date	% of Current Contract Amour	nt Complete
December 15,	2023	Decembe	er 15, 2023		58.15%	

Contract	Informational	Dates

Co	ontract Informational	Dates	Milestones							
Date Description	Original Current Completion Date Completion Date		Date Description	Original Completion Date	Current Completion Date	Days Remaining on Milestone	Diary Charge Days			
Acceptance Date			Milestone - Completion Date	December 15, 2022	December 31, 2022	Milestone Complete				
Awarded Date	December 1, 2021	December 1, 2021								
Letting Date	November 19, 2021	November 19, 2021								
Notice to Proceed Date	January 3, 2022	January 3, 2022								
Open to Traffic Date										
Work Began Date										

Contract To	otal Pay Fo	or Estimate	No. 29						
				This Estimate	Previous		Тс	Date	
Gross Item / Incentive Disincentive Liquidated D		****		\$29,055,777.34 \$2,810.33 \$0.00 \$0.00 \$0.00 \$4,500.18 \$29,063,087.85		\$2 (\$ \$0 \$0 \$0 \$4 \$2			
Contract To	otal Payab	le This Esti	mate:	\$460,369.37				-,,	
ems Paid T	his Estim	ate Period							
Project Number	Line Number	Item Code		Item Description		Unit	Unit Price	Current Installed Qty	Current Installed Amount
J6I3413	0110	6122030	IMPACT ATTENU	ATOR (RELOCATION)		EA	\$875.000	2	\$1,750.00
	0150	6173700B	TEMPORARY TRA FURNISHED / RE	AFFIC BARRIER ANCHOR TAINED	LF	\$26.250	8,225	\$215,906.25	
	0220	6207001	PAVEMENT MAR	KING REMOVAL	LF	\$0.500	9,413	\$4,706.50	
	0230	6209903	MISC.6 IN. WHITE	TEMPORARY PAVEMEN	LF	\$0.350	15,635	\$5,472.25	
	0240	6209903	MISC.6 IN. YELLC	W TEMPORARY PAVEM	ENT MARKING PAINT	LF	\$0.350	15,345	\$5,370.75
	0390	9019902	MISC.LIGHT POL	E REPLACEMENT		EA	\$4,636.000	5	\$23,180.00
	0520	7125200	SURFACE PREPA	RATION FOR RECOATIN	G STRUCTURAL STEEL	SQFT	\$22.750	7,822	\$177,950.50
	0530	7125210	FIELD APPLICATI	ON OF INORGANIC ZINC	PRIMER	SQFT	\$4.600	7,822	\$35,981.20
Project J6	<mark>13413 - To</mark>	tal							\$470,317.45
J6I3500	1310	6131010	FURNISHING ANI DEPTH PAVEMEN	D PLACING CONCRETE N NT REPAIR	IATERIAL FOR FULL	SQYD	\$210.000	171.9	\$36,099.00
	1340	6131014	FULL DEPTH PAV INTERNAL SAW (		IT (FOR PERIMETER AND	LF	\$8.000	47	\$376.00
	1350	6131015	DOWEL BAR (DR FULL DEPTH PAV	LLING, FURNISHING ANI 'EMENT REPAIR	D INSTALLATION) FOR	EA	\$15.000	311	\$4,665.00
	1370	6179903	MISC.CONCRETE	TRAFFIC BARRIER, TYP	E C, TRANSITION	LF	\$220.000	58	\$12,760.00



## Pay Estimate Created Date: April 3, 2023

29		Prime Contractor	KCI Construction Company		Net Change	\$49,997,800.00 \$872,018.03 \$50,869,818.03		
Line lumber	Item Code		Item Description		Unit	Unit Price	Current Installed Qty	Current Installed Amount
1390	6061060	MGS GUARDRAIL			LF	\$33.000	-50	(\$1,650.00)
00 - Tota	al							\$52,250.00
al								\$522,567.45
ן זו 1	Line umber 1390 <b>10 - Tota</b>	Line Item umber Code 1390 6061060 10 - Total	Line Item Jumber Code 1390 6061060 MGS GUARDRAIL 10 - Total	Line Item Item Description Imber Code Item Description I390 6061060 MGS GUARDRAIL I0 - Total	Line Item Code Item Description I390 6061060 MGS GUARDRAIL I0 - Total	Line Item Code Item Description Unit I390 6061060 MGS GUARDRAIL LF I0 - Total	Line Item Code Unit Unit Price Imber Code MGS GUARDRAIL LF \$33.000	Line umberItem CodeItem DescriptionUnitUnit PriceCurrent Installed Qty13906061060MGS GUARDRAILLF\$33.000-50IO - Total

No Contract Adjustments Exist on Contract Line Item Adjustments This Estimate

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J6I3413	0110	IMPACT ATTENUATOR (RELOCATION)	Overrun			-1	\$875.00	(\$875.00)
	0110	IMPACT ATTENUATOR (RELOCATION)	Overrun			-1	\$875.00	(\$875.00)
	0150	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	Overrun			-1,587.5	\$26.25	(\$41,671.88)
	0390	MISC.	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$12,211.20)
	0470	SUBSTRUCTURE REPAIR (FORMED)	Material			-136	\$228.00	(\$31,008.00)
	0470	SUBSTRUCTURE REPAIR (FORMED)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	136	\$228.00	\$31,008.00
	1020	MISC.	Material			-3,644	\$6.00	(\$21,864.00)
	1020	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user wolkt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	3,644	\$6.00	\$21,864.00
J6I3500	1350	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Overrun			-27	\$15.00	(\$405.00)
	1350	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material			-311	\$15.00	(\$4,665.00)
	1350	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	311	\$15.00	\$4,665.00
	1370	MISC.	Overrun			-20	\$220.00	(\$4,400.00)
	1370	MISC.	Overrun			-8	\$220.00	(\$1,760.00)
	1370	MISC.	Material			-58	\$220.00	(\$12,760.00)
	1370	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	58	\$220.00	\$12,760.00
	1760	LATEX MODIFIED CONCRETE WEARING SURFACE	Material			-2,134	\$130.00	(\$277,420.00)

Pay Estimate Created Date: April 3, 2023

Progr		timate Number 29	Contract ID Prime Contr	211119 ractor KCI Co		Pay Period StartMarch 16, 2023Original Contract Amount\$49,997,800ompanyPay Period EndApril 1, 2023Net Change Order Amount\$872,018.03Current Contract Amount\$50,869,818						
Project Number	Line No.	Item Description		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J6I3500	1760		K MODIFIED E WEARING SURFACE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	2,134	\$130.00	\$277,420.00			
Total									(\$62,198.08)			



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information											
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work							
J6I3413	I-255-3(52)	Bridge rehabilitation	I-255	ST LOUIS	at the Mississippi River							
J6I3500	I 255-3(53)	Bridge rehabilitation	I-255	ST LOUIS	over Koch Road							

## Totals by Job Numbers

3413	This Estimate	Previous	To Date
Posted Item Pay	\$470,317.45	\$27,478,324.04	\$27,948,641.49
Gross Item Adjustments	(\$55,633.08)	(\$39,535.58)	(\$95,168.66)
Gross Item Pay	\$414,684.37	\$27,438,788.46	\$27,853,472.83
Incentive	\$0.00	\$0.00	\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$4,268.87	\$4,268.87
3500	This Estimate	Previous	To Date
Posted Item Pay	\$52,250.00	\$1,577,453.30	\$1,629,703.30
Gross Item Adjustments	(\$6,565.00)	\$42,345.91	\$35,780.91
			64 00F 404 04
Gross Item Pay	\$45,685.00	\$1,619,799.21	\$1,665,484.21
Gross Item Pay	<b>\$45,685.00</b> \$0.00	\$1,619,799.21 \$0.00	
	,		\$1,665,484.21 \$0.00 \$0.00
Incentive	\$0.00	\$0.00	\$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J6I3500, Item 5052000, Project Item Line Number 1760, Material Set 505200096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	Working with contractor QC to resolve reporting issues.	wolkt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3500, Item 5052000, Project Item Line Number 1760, Material Set 505200096, Material 1005GECMLSBD - Bridge Wearing Surface Grade E LS/DO, Acceptance Action Generic 1005GECMLSBD is insufficient.	Working with contractor QC to resolve reporting issues.	wolkt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3500, Item 6131015, Project Item Line Number 1350, Material Set 613101596, Material 1039ERDBEP - Epoxy Bonding Agent for Dowels, Acceptance Action Generic 1039ERDBEP is insufficient.	Working with Materials to transfer quantity.	wolkt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3500, Item 6179903, Project Item Line Number 1370, Material Set 6179903, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with contractor QC to resolve reporting issues.	wolkt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3500, Item 6179903, Project Item Line Number 1370, Material Set 6179903, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	Working with contractor QC to resolve reporting issues.	wolkt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3500, Item 6179903, Project Item Line Number 1370, Material Set 6179903, Material 1055CMMLDST2 - White Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST2 is insufficient.	Working with contractor QC to resolve reporting issues.	wolkt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6l3413, Item 7040101, Project Item Line Number 0470, Material Set 704010196, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	Working with contractor QC to resolve reporting issues.	wolkt1	Overridden
Estimate Exception Type: Insufficient Materials: Project J6I3413, Item 7119904, Project Item Line Number 1020, Material Set 7119904, Material 1059PCCBPR - Protective Coat Bents and Piers- Urethane, Acceptance Action Generic 1059PCCBPR is insufficient.	Working with contractor QC to resolve reporting issues.	wolkt1	Overridden
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3413, Project Item Line Number 0110, Contract Line Item Number 0110, Item 6122030, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3413, Project Item Line Number 0150, Contract Line Item Number 0150, Item 6173700B, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3500, Project Item Line Number 1350, Contract Line Item Number 1350, Item 6131015, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3500, Project Item Line Number 1370, Contract Line Item Number 1370, Item 6179903, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3413, Project Item Line Number 0020, Contract Line Item Number 0020, Item 2153000, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3413, Project Item Line Number 0330, Contract Line Item Number 0330, Item 6061060, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3413, Project Item Line Number 0380, Contract Line Item Number 0380, Item 9019902, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3413, Project Item Line Number 0960, Contract Line Item Number 0960, Item 7040101, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211119-F01, Contract Project J6I3500, Project Item Line Number 1300, Contract Line Item Number 1300, Item 2153000, Minor Item.	Overrun being drafted to future change order.	wolkt1	Acknowledged



#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract n.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1119-F01	J6I3413	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.75	\$150,000.00	\$112,500.0
		0001	0020	2153000	SHAPING SLOPES, CLASS III	1.00	7.00	8.00	100F	12.00	\$1,200.00	\$14,400.0
		0001	0030	4029901	MISC.TEMPORARY MEDIAN CROSSOVER EAST	1.00	-1.00	0.00	LS	0.00	\$400,000.00	\$0.0
		0001	0040	4029901	MISC.TEMPORARY MEDIAN CROSSOVER WEST	1.00	0.00	1.00	LS	1.00	\$175,000.00	\$175,000.0
		0001	0050	4030111	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125CLP MIX)	984.70	-467.80	516.90	TONS	516.90	\$142.00	\$73,399.8
		0001	0060	6046018A	18 IN. SLOTTED DRAIN	173.00	96.00	269.00	LF	269.00	\$512.00	\$137,728.0
		0001	0070	6049901	MISC.TRENCH DRAIN	1.00	0.00	1.00	LS	1.00	\$95,000.00	\$95,000.0
		0001	0080	6049901	MISC.WELD DRAINAGE GRATES	1.00	0.00	1.00	LS	1.00	\$40,000.00	\$40,000.0
		0001	0090	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	2.00	2.00	4.00	EA	4.00	\$4,772.00	\$19,088.0
		0001	0100	6122020	REPLACEMENT SAND BARREL	2.00	9.00	11.00	EA	11.00	\$491.00	\$5,401.0
		0001	0110	6122030	IMPACT ATTENUATOR (RELOCATION)	1.00	4.00	5.00	EA	7.00	\$875.00	\$6,125.0
		0001	0120	6151000	OFFICE FOR ENGINEER	24.00	0.00	24.00	MO	12.00	\$2,000.00	\$24,000.0
		0001	0130	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	2.00	6.00	EA	6.00	\$2,800.00	\$16,800.0
		0001	0140	6173000	CONCRETE TRAFFIC BARRIER, TYPE C	668.00	0.00	668.00	LF	0.00	\$116.00	\$0.0
		0001	0150	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	15,450.00	0.00	15,450.00	LF	17,037.50	\$26.25	\$447,234.3
		0001	0160	6175011B	RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED	825.00	863.00	1,688.00	LF	1,688.00	\$15.17	\$25,606.9
		0001	0170	6179901	MISC.TEMPORARY TRAFFIC CONTROL	1.00	0.00	1.00	LS	0.75	\$575,000.00	\$431,250.0
		0001	0180	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$5,458,093.69	\$0.0
		0001	0181	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$5,108,577.69	\$5,108,577.6
		0001	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	30,726.00	0.00	30,726.00	LF	0.00	\$0.30	\$0.
		0001	0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	20,338.00	0.00	20,338.00	LF	0.00	\$0.30	\$0.
		0001	0210	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	326.00	0.00	326.00	LF	0.00	\$2.00	\$0.
		0001	0220	6207001	PAVEMENT MARKING REMOVAL	195,118.00	0.00	195,118.00	LF	74,422.00	\$0.50	\$37,211.0
		0001	0230	6209903	MISC.6 IN. WHITE TEMPORARY PAVEMENT MARKING PAINT	103,524.00	0.00	103,524.00	LF	79,702.00	\$0.35	\$27,895.7
		0001	0240	6209903	MISC.6 IN. YELLOW TEMPORARY PAVEMENT MARKING PAINT	56,662.00	0.00	56,662.00	LF	56,515.00	\$0.35	\$19,780.2
		0001	0250	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	6,132.00	-3,017.00	3,115.00	SQYD	3,115.00	\$6.75	\$21,026.2
		0001	0260	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	55.30	0.00	55.30	STA	0.00	\$325.00	\$0.0
		0001	0270	6262000A	PORTLAND CEMENT CONCRETE SHOULDER RUMBLE STRIP	56.20	0.00	56.20	STA	0.00	\$150.00	\$0.0
		0001	0280	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.75	\$50,000.00	\$37,500.0
		0001	0290	7250318A	18 IN. PIPE GROUP B	450.00	20.00	470.00	LF	470.00	\$62.00	\$29,140.0
		0001	0300	8052000A	SEEDING - WARM SEASON GRASSES	0.40	0.00	0.40	ACRE	0.00	\$15,000.00	\$0.0
		0001	0310	8061006	ALTERNATE DITCH CHECK	30.00	0.00	30.00	LF	0.00	\$20.00	\$0.0
		0001	0320	8061016	SEDIMENT REMOVAL	2.00	0.00	2.00	CUYD	0.00	\$400.00	\$0.0
		0010	0330	6061060	MGS GUARDRAIL	1,563.00	0.00	1,563.00	LF	1,613.00	\$33.00	\$53,229.0
		0010	0340	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	2.00	\$3,700.00	\$7,400.0
		0010	0350	6061080	MGS END ANCHOR	1.00	0.00	1.00	EA	1.00	\$1,400.00	\$1,400.0
		0010	0360	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	1.00	0.00	1.00	EA	1.00	\$3,100.00	\$3,100.0
		0010	0370	6069901	MISC.RELAP GUARDRAIL	1.00	0.00	1.00	LS	1.00	\$3,200.00	\$3,200.0
		0020	0380	9019902	MISC.LIGHT POLE REPAIRS	5.00	0.00	5.00	EA	7.00	\$281.00	\$1,967.0
		0020	0390	9019902	MISC.LIGHT POLE REPLACEMENT	7.00	0.00	7.00	EA	7.00	\$4,636.00	\$32,452.0
		0020	0400	9019902	MISC.NAVIGATION LIGHT REPAIR	1.00	0.00	1.00	EA	1.00	\$2,405.00	\$2,405.
		0070	0410	2161000	SCARIFICATION OF BRIDGE DECK	22,887.00	0.00	22,887.00	SQYD	0.00	\$20.00	\$0.0
		0070	0420	2161501	REMOVAL OF ASPHALT WEARING SURFACE	3,800.00	0.00	3,800.00	SQFT	0.00	\$4.00	\$0.0
		0070	0430	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	306.00	0.00	306.00	LF	0.00	\$4,000.00	\$0.0
		0070	0440	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	306.00	0.00	306.00	LF	0.00	\$100.00	\$0.0



#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Q					Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	Generat	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211119-F01	J6I3413	0070	0450	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	139.00	0.00	139.00	LF	0.00	\$900.00	\$0.00
		0070	0460	5029907	MISC.ULTRA-HIGH PERFORMANCE CONCRETE, JOINT	96.00	0.00	96.00	CUYD	0.00	\$9,200.00	\$0.00
		0070	0465	7031004	DIAMOND GRINDING	22,952.00	0.00	22,952.00	SQYD	0.00	\$0.01	\$0.00
		0070	0470	7040101	SUBSTRUCTURE REPAIR (FORMED)	539.00	0.00	539.00	SQFT	136.00	\$228.00	\$31,008.00
		0070	0480	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	539.00	0.00	539.00	SQFT	0.00	\$228.00	\$0.00
		0070	0490	7049903	MISC.BARRIER CURB REPAIR	11.00	0.00	11.00	LF	0.00	\$350.00	\$0.00
		0070	0500	7101000	REINFORCING STEEL (EPOXY COATED)	27,700.00	0.00	27,700.00	LB	0.00	\$3.00	\$0.00
		0070	0510	7119904	MISC.PROTECTIVE COATING - CONCRETE BENTS & PIERS (URETHANE)	10,930.00	0.00	10,930.00	SQFT	0.00	\$6.00	\$0.00
		0070	0520	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	284,000.00	0.00	284,000.00	SQFT	34,607.00	\$22.75	\$787,309.25
		0070	0530	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	284,000.00	0.00	284,000.00	SQFT	34,607.00	\$4.60	\$159,192.20
		0070	0540	7125385A	INTERMEDIATE FIELD COAT (SYSTEM H)	220,000.00	0.00	220,000.00	SQFT	26,785.00	\$4.60	\$123,211.00
		0070	0550	7125390A	FINISH FIELD COAT (SYSTEM H)	220,000.00	0.00	220,000.00	SQFT	26,785.00	\$4.60	\$123,211.00
		0070	0560	7125396	FINISHED FIELD COAT (SYSTEM I)	64,000.00	0.00	64,000.00	SQFT	0.00	\$5.40	\$0.00
		0070	0570	7129901	MISC.BRIDGE WASHING	1.00	0.00	1.00	LS	0.00	\$85,000.00	\$0.00
		0070	0580	7129901	MISC.CLEARANCE GUAGE	1.00	0.00	1.00	LS	0.00	\$29,500.00	\$0.00
		0070	0590	7129902	MISC.ACCESS DOOR GASKET REPLACEMENT	4.00	0.00	4.00	EA	0.00	\$3,500.00	\$0.00
		0070	0600	7129902	MISC.CABLE SHORING SYSTEM INSTALLATION, CABLE TENSION ADJUSTMENT	8.00	0.00	8.00	EA	0.00	\$61,000.00	\$0.00
		0070	0610	7129902	MISC.CABLE TENSION MEASUREMENT INSPECTION	2.00	0.00	2.00	EA	0.00	\$100,000.00	\$0.00
		0070	0620	7129902	MISC.RESET ROCKER BEARINGS	2.00	0.00	2.00	EA	0.00	\$25,000.00	\$0.00
		0070	0630	7129902	MISC.STEEL RETROFIT - STRUT ACCESS DOOR PIN	1.00	0.00	1.00	EA	0.00	\$2,125.00	\$0.00
		0070 0640	7129902	MISC.STEEL RETROFITS - DRAINAGE TRUSS MEMBER CONNECTION	1.00	0.00	1.00	EA	0.00	\$2,125.00	\$0.00	
		0070	0650	7129902	MISC.STEEL RETROFITS - LADDER LANDING PLATES	32.00	0.00	32.00	EA	0.00	\$3,100.00	\$0.00
			7129902	MISC.STEEL RETROFITS - RECONNECT DRAIN DOWNSPOUT BRACKET	18.00	0.00	18.00	EA	0.00	\$2,200.00	\$0.00	
		0070	0670	7129902	MISC.STEEL RETROFITS - WALKWAY TRUSS BROKEN WELDS	216.00	0.00	216.00	EA	0.00	\$1,100.00	\$0.00
		0070	0680 7129902 MISC.TRIMMING OF STEPS INSIDE ARCH/TIE INTERSECTIO CHAMBER	MISC.TRIMMING OF STEPS INSIDE ARCH/TIE INTERSECTION CHAMBER	112.00	0.00	112.00	EA	104.00	\$2,050.00	\$213,200.00	
		0070	0690	7129903	MISC.CRACK REMOVAL - GRINDING	555.00	0.00	555.00	LF	1.00	\$850.00	\$850.00
		0070	0700	7129903	MISC.FINGER JOINT EXPANSION JOINT SYSTEM (ABUT 1 & BENT 5)	102.00	0.00	102.00	LF	0.00	\$5,000.00	\$0.00
		0070	0710	7129903	MISC.FINGER JOINT EXPANSION JOINT SYSTEM (BENTS 9 & 13)	102.00	0.00	102.00	LF	0.00	\$6,500.00	\$0.00
		0070	0720	7129903	MISC.HANGER CABLE REPLACEMENT	3,228.00	0.00	3,228.00	LF	0.00	\$400.00	\$0.00
		0070	0730	7129903	MISC.METALIZING HANGER CABLES	2,800.00	0.00	2,800.00	LF	0.00	\$81.00	\$0.00
		0070	0740	7129903	MISC.WELD INSPECTION	4,568.00	0.00	4,568.00	LF	261.00	\$31.00	\$8,091.00
		0070	0750	7129903	MISC.WELD REPAIR	230.00	0.00	230.00	LF	0.00	\$1,250.00	\$0.00
		0070	0760	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	102.00	0.00	102.00	LF	0.00	\$600.00	\$0.00
		0070	0770	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	306.00	0.00	306.00	LF	0.00	\$55.00	\$0.00
		0071	0780	2161001	TOTAL SURFACE HYDRO DEMOLITION	22,952.00	-22,952.00	0.00	SQYD	0.00	\$48.00	\$0.00
		0071	0790	2161503	REMOVAL OF EXISTING DECK REPAIR	600.00	-600.00	0.00	SQFT	0.00	\$32.00	\$0.00
		0071	0800	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	53.00	-53.00	0.00	CY	0.00	\$700.00	\$0.00
		0071	0810	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	22,952.00	-22,952.00	0.00	SQYD	0.00	\$70.00	\$0.00
		0071	0830	7040106	FULL DEPTH REPAIR	100.00	-100.00	0.00	SQFT	0.00	\$130.00	\$0.00
		0073	0880	2161000	SCARIFICATION OF BRIDGE DECK	22,856.00	0.00	22,856.00	SQYD	22,856.00	\$20.00	\$457,120.00
		0073	0890	2161501	REMOVAL OF ASPHALT WEARING SURFACE	1,226.00	0.00	1,226.00	SQFT	1,226.00	\$4.00	\$4,904.00
		0073	0900	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT CONCRETE	306.00	0.00	306.00	LF	306.00	\$4,000.00	\$1,224,000.00
		0073	0910	2165000	REMOVAL OF EXISTING EXPANSION JOINT SEAL OR SEALANT	306.00	0.00	306.00	LF	306.00	\$100.00	\$30,600.00
		0073	0920	2169903	MISC.REMOVE AND REPLACE BARRIER CURB	118.00	20.00	138.00	LF	138.00	\$910.00	\$125,580.00
		0073	0930	5029907	MISC.FURNISH POLYESTER POLYMER CONCRETE MATERIAL	631.00	5.00	636.00	CUYD	635.50	\$2,975.00	\$1,890,612.50



#### Total Paid / All Items / All Estimates (Including this Estimate)

Contract		Category		Item	Report Generated date and can differ from the posted am Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTED
Nm.CONTRACT	No.	outogory	No.	Code	Coonplant	Quantity	Change Order	Current Quantity	onic	Posted Approved Qty	onici noo	To Date (See report generated date)
211119-F01	J6I3413	0073	0940	5029907	MISC.ULTRA-HIGH PERFORMANCE CONCRETE, JOINT	81.00	0.00	81.00	CUYD	81.00	\$9,460.00	\$766,260.00
		0073	0950	5059905	MISC.PLACE POLYESTER POLYMER WEARING SURFACE	22,705.00	173.00	22,878.00	SQYD	22,878.00	\$14.00	\$320,292.00
		0073	0955	7031004	DIAMOND GRINDING	22,705.00	0.00	22,705.00	SQYD	0.00	\$0.01	\$0.00
		0073	0960	7040101	SUBSTRUCTURE REPAIR (FORMED)	454.00	0.00	454.00	SQFT	675.00	\$228.00	\$153,900.00
		0073	0970	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	454.00	-454.00	0.00	SQFT	0.00	\$228.00	\$0.00
		0073	0980	7040104	HALF-SOLE REPAIR	1,000.00	-247.00	753.00	SQFT	753.00	\$54.00	\$40,662.00
		0073	0990	7040106	FULL DEPTH REPAIR	100.00	-11.00	89.00	SQFT	89.00	\$130.00	\$11,570.00
		0073	1000	7049903	MISC.BARRIER CURB REPAIR	22.00	-6.00	16.00	LF	16.00	\$350.00	\$5,600.00
		0073	1010	7101000	REINFORCING STEEL (EPOXY COATED)	22,630.00	0.00	22,630.00	LB	22,630.00	\$3.00	\$67,890.00
		0073	1020	7119904	MISC.PROTECTIVE COATING - CONCRETE BENTS & PIERS (URETHANE)	10,930.00	0.00	10,930.00	SQFT	3,644.00	\$6.00	\$21,864.00
		0073	1030	7125200	SURFACE PREPARATION FOR RECOATING STRUCTURAL STEEL	284,000.00	0.00	284,000.00	SQFT	284,000.00	\$22.75	\$6,461,000.00
		0073	1040	7125210	FIELD APPLICATION OF INORGANIC ZINC PRIMER	284,000.00	0.00	284,000.00	SQFT	284,000.00	\$4.60	\$1,306,400.00
		0073	1050	7125385A	INTERMEDIATE FIELD COAT (SYSTEM H)	220,000.00	0.00	220,000.00	SQFT	220,000.00	\$4.60	\$1,012,000.00
		0073	1060	7125390A	FINISH FIELD COAT (SYSTEM H)	220,000.00	0.00	220,000.00	SQFT	220,000.00	\$4.60	\$1,012,000.00
		0073	1070	7125396	FINISHED FIELD COAT (SYSTEM I)	64,000.00	0.00	64,000.00	SQFT	64,000.00	\$5.40	\$345,600.00
		0073	1080	7129901	MISC.BRIDGE WASHING	1.00	0.00	1.00	LS	1.00	\$85,000.00	\$85,000.00
		0073	1090	7129901	MISC.CLEARANCE GUAGE	1.00	0.00	1.00	LS	0.00	\$29,500.00	\$0.00
		0073	1100	7129902	MISC.ACCESS DOOR GASKET REPLACEMENT	4.00	0.00	4.00	EA	4.00	\$3,500.00	\$14,000.00
		0073	1110	7129902	MISC.CABLE SHORING SYSTEM INSTALLATION, CABLE TENSION ADJUSTMENT	2.00	-1.00	1.00	EA	1.00	\$58,840.00	\$58,840.00
		0073	1120	7129902	MISC.CABLE TENSION MEASUREMENT INSPECTION	2.00	0.00	2.00	EA	2.00	\$100,000.00	\$200,000.00
		0073	1130	7129902	MISC.STEEL RETROFIT - APPROACH SPAN DRAIN PIPE EXTENSION	1.00	1.00	2.00	EA	2.00	\$3,500.00	\$7,000.00
		0073	1140	7129902	MISC.STEEL RETROFIT - STRINGER BEARING BOLT REPLACEMENT	1.00	5.00	6.00	EA	6.00	\$2,800.00	\$16,800.00
		0073	1150	7129902	MISC.STEEL RETROFITS - DRAINAGE TRUSS MEMBER CONNECTION	4.00	-4.00	0.00	EA	0.00	\$2,800.00	\$0.00
		0073	1160	7129902	MISC.STEEL RETROFITS - LADDER LANDING PLATES	32.00	4.00	36.00	EA	36.00	\$3,100.00	\$111,600.00
		0073	1170	7129902	MISC.STEEL RETROFITS - PIN AND LINK PLATE WASHER REPLACEMENT	11.00	0.00	11.00	EA	11.00	\$18,200.00	\$200,200.00
		0073	1180	7129902	MISC.STEEL RETROFITS - RECONNECT DRAIN DOWNSPOUT BRACKET	36.00	-36.00	0.00	EA	0.00	\$2,800.00	\$0.00
		0073	1190	7129902	MISC.STEEL RETROFITS - WALKWAY RAILING SPLICE PLATE	1.00	1.00	2.00	EA	2.00	\$3,550.00	\$7,100.00
		0073	1200	7129902	MISC.STEEL RETROFITS - WALKWAY TRUSS BROKEN WELDS	216.00	-25.00	191.00	EA	191.00	\$1,125.00	\$214,875.00
		0073	1210	7129903	MISC.CRACK REMOVAL - GRINDING	56.00	-52.00	4.00	LF	4.00	\$850.00	\$3,400.00
		0073	1220	7129903	MISC.FINGER JOINT EXPANSION JOINT SYSTEM (ABUT 1 &	102.00	0.00	102.00	LF	102.00	\$5,000.00	\$510,000.00
		0073	1230	7129903	MISC.FINGER JOINT EXPANSION JOINT SYSTEM (BENTS 9 &	102.00	0.00	102.00	LF	102.00	\$6,500.00	\$663,000.00
		0073	1240	7129903	13) MISC.METALIZING HANGER CABLES	3,400.00	0.00	3,400.00	LF	3,400.00	\$81.00	\$275,400.00
		0073	1250	7129903	MISC.WELD INSPECTION	4,568.00	0.00	4,568.00	LF	4,568.00	\$31.00	\$141,608.00
		0073	1260	7129903	MISC.WELD REPAIR	20.00	-18.00	2.00	LF	2.00	\$1,600.00	\$3,200.00
		0073	1270	7172001	STRIP SEAL EXPANSION JOINT SYSTEM	102.00	0.00	102.00	LF	102.00	\$600.00	\$61,200.00
		0073	1280	7174002	PREFORMED SILICONE OR EPDM EXPANSION JOINT SEAL	306.00	0.00	306.00	LF	306.00	\$55.00	\$16,830.00
		0001	5001	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	0.00	24.00	24.00	EA	12.00	\$1,155.00	\$13,860.00
		0001	5002	6189901	MISC.Payment for Contract Bond	0.00	1.00	1.00	LS	1.00	\$349,516.00	\$349,516.00
		0001	5003	4071005	TACK COAT	0.00	425.00	425.00	GAL	425.00	\$10.50	\$4,462.50
		0001	5004	4039905	MISC.10.5 INCHES, ASPHALTIC CONCRETE PAVEMENT SP125C	0.00	1,546.00	1,546.00	SQYD	1,546.00	\$115.67	\$178,825.82
		0001	5005	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	0.00	1,546.00	1,546.00	SQYD	1,546.00	\$30.39	\$46,982.94
		0001	5006	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$14,437.50	\$14,437.50
	0001         5007         4029901         MISC.Temporary Median Crossover East			0.00	1.00	1.00	LS	0.75	\$535,276.85	\$401,457.64		
		0001	5008	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	0.00	1.00	1.00	LS	1.00	\$11,400.00	\$11,400.00



#### Total Paid / All Items / All Estimates (Including this Estimate)

						Report Generated date and can differ from the posted am	ount at the	time the Es	stimate was	Genera	ted.		
			Category			Description		Change	Current	Unit	Posted Approved	Unit Price	To Date (See report
No.         No. <td>211119-F01</td> <td>J6I3413</td> <td>0001</td> <td>5009</td> <td>6179901</td> <td>MISC.Mobilization</td> <td>0.00</td> <td>1.00</td> <td>1.00</td> <td>LS</td> <td></td> <td>\$19,993.37</td> <td>\$19,993.37</td>	211119-F01	J6I3413	0001	5009	6179901	MISC.Mobilization	0.00	1.00	1.00	LS		\$19,993.37	\$19,993.37
No.         No.         Solid         Sol			0001	5010	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$8,652.84	\$8,652.84
No.No			0001	5011	7269903	MISC.8" PVC PIPE SCHEDULE 40	0.00	240.00	240.00	LF	240.00	\$44.06	\$10,574.40
Image         Image <th< td=""><td></td><td></td><td>0001</td><td>5012</td><td>5021110</td><td>CONCRETE PAVEMENT (10 IN. NON-REINF)</td><td>0.00</td><td>216.90</td><td>216.90</td><td>SQYD</td><td>216.90</td><td>\$80.20</td><td>\$17,395.38</td></th<>			0001	5012	5021110	CONCRETE PAVEMENT (10 IN. NON-REINF)	0.00	216.90	216.90	SQYD	216.90	\$80.20	\$17,395.38
No.No			0073	5013	7129902		0.00	10.00	10.00	EA	10.00	\$4,803.54	\$48,035.40
Image: Note of the section o			0073	5014	7129902	MISC.STEEL RETROFITS - LADDER WELD REPAIR	0.00	2.00	2.00	EA	2.00	\$1,050.00	\$2,100.00
No.No			0073	5015	7129902		0.00	4.00	4.00	EA	4.00	\$6,988.98	\$27,955.92
No No No No 			0001	5016	4029901	MISC.TEMPORARY EMERGENCY CROSSOVER	0.00	1.00	1.00	LS	1.00	\$7,052.84	\$7,052.84
Image: Note of the set of th			0001	5017	6169901	MISC.LUMP SUM TRAFFIC CONTROL	0.00	1.00	1.00	LS	1.00	\$1,926.75	\$1,926.75
NoSinceSin			0073	5018	2169901	MISC.Removal of Expansion Joint & Adjacent Concrete	0.00	1.00	1.00	LS	1.00	\$417,579.50	\$417,579.50
No.No.C. Boson Have AssemblesA.C. B.I.D.			0073	5019	7040103	SUPERSTRUCTURE REPAIR (UNFORMED)	0.00	140.00	140.00	SQFT	140.00	\$228.00	\$31,920.00
Image: Note of the start of			0001	5020	6049901	MISC.(Weld Existing Drainage Grates Bridge No. A18503)	0.00	1.00	1.00	LS	1.00	\$13,868.86	\$13,868.86
NormNo			0020	5021	9019901	MISC.(Beacon Flasher Assemblies)	0.00	1.00	1.00	LS	1.00	\$3,398.85	\$3,398.85
60716074608460807MISC-PLACE POLYMER POLYMER CONCRETE WATER00717000 <td></td> <td></td> <td>0001</td> <td>5022</td> <td>6049901</td> <td>MISC.(Inlet Top Replacement)</td> <td>0.00</td> <td>1.00</td> <td>1.00</td> <td>LS</td> <td>1.00</td> <td>\$13,447.99</td> <td>\$13,447.99</td>			0001	5022	6049901	MISC.(Inlet Top Replacement)	0.00	1.00	1.00	LS	1.00	\$13,447.99	\$13,447.99
60716025605999Misciple/CP POLYESTER POLYMER CONCRETE WEARING0.0022.852022.85209.0100.005.0105244.000100160277.04104Indic Owar Preparations for Physicster Polymer Concreto Overling0.000.000.000.000.008.0008.00008.0000100160207.00107.001060207.00107.00108.0007.00108.0008.000008.000008.000008.00			0071	5023	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.00	\$143,350.95	\$0.00
Image: Note of the section of Pailon in the pailon of Pailon i		0071 5024 5029907 MISC.FURNISH POLYESTER POLYMER CONCRETE MATERIAL	0.00	717.00	717.00	CUYD	0.00	\$2,872.13	\$0.00				
00710070740104MALF-SOLR REPAIR0.000			0071	5025	5059905		0.00	22,952.00	22,952.00	SQYD	0.00	\$14.42	\$0.00
Incl 10071StopTotal Depth REPAR0.000.000.000.000.005070.00510.00510.00POINT VIEW VIEW VIEW VIEW VIEW VIEW VIEW VIEW			0071	5026	7049901	MISC.Deck Preparations for Polyester Polymer Concrete Overlay	0.00	1.00	1.00	LS	0.00	\$244,000.00	\$0.00
Point         Usint of the point point of the point of the point			0071	5027	7040104	HALF-SOLE REPAIR	0.00	0.00	0.00	SQFT	0.00	\$55.00	\$0.00
B15500         D001         1290         202010         REMOVAL OF IMPROVEMENTS         1 00         0.00         1 00         0.01         0.05         550,000.00           0001         1300         215300         SHAPINS CLORES ILIAS III         3 00         0.00         3 00         100F         4.480         550,000.00           0001         1310         613101         FURNISHING AND FLACING CONCRETE MATERIAL FOR FULL         211.20         0.00         211.20         50/0         0.00         516.00         556.00			0071	5028	7040106	FULL DEPTH REPAIR	0.00	0.00	0.00	SQFT	0.00	\$130.00	\$0.00
0000130015000SHAPING SLOPES, CLASS III3000.000S.000100F4.4.805900.0000101310FLYIN SYMMENT REPAR21100.000211061075210.005210.005210.000010132061301FLYIN SYMENT REPAR22200.0022006.002.0006.000518.000010132061301TYPE 1 OR SAGREGATE FOR RASE (A IN. THCK)22000.001.080.007.000581.00581.000010134061301TYPE 1 OR SAGREGATE FOR RASE (A IN. THCK)22000.001.080.007.0058.0058.7000011134061301TYPE 1 OR SAGREGATE FOR RASE (A IN. THCK)22000.001.080.001.080.0058.0058.700.000011134061301TYPE 1 OR SAGREGATE FOR RASE (A IN. THCK)28.000.001.080.001.0859.700.0058.0058.700.000011134061301TYPE 1 OR SAGREGATE FOR RASE (A IN. THCK)28.000.002.04.001.0859.700.0058.0058.700.000011134061300DOWE LARAE (DELLIDERFIT HATENETICA RATION IN TALLATION)30.000.0050.001.0859.700.0058.0058.700		Project J	613413 - To	otal Value	Posted to I	Date as of Report Generated Date							\$27,948,641.47
10011306131010EURNISHING AND PLACING CONCRETE MATERIAL FOR FULL211.200.00211.20SOYD171.90\$21.00		J613500	0001	1290	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.50	\$50,000.00	\$25,000.00
Internal 1000In			0001	1300	2153000	SHAPING SLOPES, CLASS III	3.00	0.00	3.00	100F	4.80	\$900.00	\$4,320.00
0001130613103TYPE 1 OR S AGGREGATE FOR BASE (4 IN, THICK) (PAVELENE T REPAIR22.000.0022.00SOYD0.00S18.00S18.000001134013104S10104CULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER INTERNAL SAW CUTS)1.080.000.001.080.00I.F970.00S38.00S7.760.0000011350613015OWEL BAR PAVEMENT REPAIR SAW CUTS)224.000.00228.40CA50.406.00S3.25S163.0100011360613991MISC.CONCRETE TRAFFIC BARRIER, TYPE C, TRANSITION30.000.00S0.406.00LE50.406.00S3.250S12.760.000001138061100MOBILZATION0.011.000.001.001.001.00S3.00S22.000S22.00000101390606108MOBILZATIONCONCETE TRAFFIC BARRIER, TYPE C, TRANSITION SECTION0.001.001.001.00S3.000S22.00001011400606108MOBILZATIONCALIERO2.000.002.112.00LE50.405.00S3.3700.0001011400606108MOSE DADANCHOR2.002.000.002.00EA3.00S3.000S3.3700.0001011410606108MOSE DADANCHOR4.000.004.00CA1.003.00S3.000S3.3700.0001011410606108MOSE DADANCHOR1.000.001.004.00S0.010.00S0.015.00S0.00010			0001	1310	6131010		211.20	0.00	211.20	SQYD	171.90	\$210.00	\$36,099.00
India			0001	1320	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	22.00	0.00	22.00	SQYD	0.00	\$18.00	\$0.00
Math         Note         Field         Note         Note </td <td></td> <td></td> <td>0001</td> <td>1330</td> <td>6131013</td> <td></td> <td>22.00</td> <td>0.00</td> <td>22.00</td> <td>SQYD</td> <td>0.00</td> <td>\$18.00</td> <td>\$0.00</td>			0001	1330	6131013		22.00	0.00	22.00	SQYD	0.00	\$18.00	\$0.00
Norm         FOR         FULL DEPTH PAVEMENT REPAIR         FOR         FULL DEPTH FAVEMENT REPAIR         FOR         FULL DEPTH FAVEMENT REPAIR           0011         1300         13091         MISC Class A Partial Dapht Concrete Pavement Repair Using biolek, hot Polymer Modified Repair Material         59.6700         9.284.0         50.406.0         LB         50.406.0         LS         53.20         S122.00           0001         1300         1300         0100         0.00         1.00         0.00         LS         0.04         53.00         S3.20         S122.000           0001         1300         601600         MCBULZATION         1.00         0.00         2.112.0         0.01         LS         0.44         53.000         S3.700.00           0101         1400         6061600         MCS BRIDGE APPROACH TRANSITION SECTION         2.012         0.00         2.412         0.01         1.40         S3.700.00         S3.700.00           0101         1400         6061080         MCS BRIDGE APPROACH TRANSITION SECTION         4.00         0.00         4.00         E.4         0.00         S3.100.00         S3.700.00           0101         1402         6063014         TYPE A CRASHWORTHY END TERMINAL (MASH)         6.00         0.00         4.430.0			0001	1340	6131014		1,080.00	0.00	1,080.00	LF	970.00	\$8.00	\$7,760.00
Internal Piecklie, Hot Polymer Modified Repair MaterialInterna			0001	1350	6131015		284.00	0.00	284.00	EA	311.00	\$15.00	\$4,665.00
Normal         Normal<			0001	1360	6139911		59,670.00	-9,264.00	50,406.00	LB	50,406.00	\$3.25	\$163,819.50
No.No			0001	1370	6179903	MISC.CONCRETE TRAFFIC BARRIER, TYPE C, TRANSITION	30.00	0.00	30.00	LF	58.00	\$220.00	\$12,760.00
No.No.Rest of the set			0001	1380	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.84	\$300,000.00	\$252,000.00
International (REGULARINO CURB)         International			0010	1390	6061060	MGS GUARDRAIL	2,112.00	0.00	2,112.00	LF	362.50	\$33.00	\$11,962.50
No.         No. <td></td> <td></td> <td>0010</td> <td>1400</td> <td>6061069</td> <td></td> <td>2.00</td> <td>0.00</td> <td>2.00</td> <td>EA</td> <td>1.00</td> <td>\$3,700.00</td> <td>\$3,700.00</td>			0010	1400	6061069		2.00	0.00	2.00	EA	1.00	\$3,700.00	\$3,700.00
1000         1430         2161000         SCARIFICATION OF BRIDGE DECK         438.00         0.00         438.00         SQP         0.00         \$39.00         \$30.00           0070         1440         2161501         REMOVAL OF ASPHALT WEARING SURFACE         11,308.00         0.00         11,308.00         SQFT         0.00         \$2.00         \$2.00         \$0.00           0070         1450         2164000         CURB REMOVAL         382.00         382.00         382.00         382.00         1.19.08.00         SQFT         0.00         \$80.00         \$0.00           0070         1455         703104         DIAMOND GRINDING         1.695.00         0.000         1.695.00         SQFT         0.000         \$1.00.00         \$0.00         \$0.00           0070         1460         7034219A         TYPE D BARRIER         382.00         1.695.00         382.00         1.69         \$0.00         \$1.69         \$QFT         1.00.00         \$1.00.00         \$0.00.00         \$1.00.00         \$1.00.00         \$0.00.00         \$0.00.00         \$1.00.00         \$1.00.00         \$0.00.00         \$0.00.00         \$0.00.00         \$1.00.00         \$1.00.00         \$1.00.00         \$1.00.00         \$1.00.00         \$1.00.00         \$1.00.00			0010	1410	6061080	MGS END ANCHOR	4.00	0.00	4.00	EA	2.00	\$1,400.00	\$2,800.00
No.         No. <td></td> <td></td> <td>0010</td> <td>1420</td> <td>6063014</td> <td>TYPE A CRASHWORTHY END TERMINAL (MASH)</td> <td>6.00</td> <td>0.00</td> <td>6.00</td> <td>EA</td> <td>3.00</td> <td>\$3,100.00</td> <td>\$9,300.00</td>			0010	1420	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	6.00	0.00	6.00	EA	3.00	\$3,100.00	\$9,300.00
Norm         Norm <th< td=""><td></td><td></td><td>0070</td><td>1430</td><td>2161000</td><td>SCARIFICATION OF BRIDGE DECK</td><td>438.00</td><td>0.00</td><td>438.00</td><td>SQYD</td><td>0.00</td><td>\$30.00</td><td>\$0.00</td></th<>			0070	1430	2161000	SCARIFICATION OF BRIDGE DECK	438.00	0.00	438.00	SQYD	0.00	\$30.00	\$0.00
Norm         Norm <th< td=""><td></td><td></td><td>0070</td><td>1440</td><td>2161501</td><td>REMOVAL OF ASPHALT WEARING SURFACE</td><td>11,308.00</td><td>0.00</td><td>11,308.00</td><td>SQFT</td><td>0.00</td><td>\$2.00</td><td>\$0.00</td></th<>			0070	1440	2161501	REMOVAL OF ASPHALT WEARING SURFACE	11,308.00	0.00	11,308.00	SQFT	0.00	\$2.00	\$0.00
Kolo         Kolo <th< td=""><td></td><td></td><td>0070</td><td>1450</td><td>2164000</td><td>CURB REMOVAL</td><td>382.00</td><td>0.00</td><td>382.00</td><td>LF</td><td>0.00</td><td>\$80.00</td><td>\$0.00</td></th<>			0070	1450	2164000	CURB REMOVAL	382.00	0.00	382.00	LF	0.00	\$80.00	\$0.00
Note         Note <th< td=""><td></td><td></td><td>0070</td><td>1455</td><td>7031004</td><td>DIAMOND GRINDING</td><td>1,695.00</td><td>0.00</td><td>1,695.00</td><td>SQYD</td><td>0.00</td><td>\$0.01</td><td>\$0.00</td></th<>			0070	1455	7031004	DIAMOND GRINDING	1,695.00	0.00	1,695.00	SQYD	0.00	\$0.01	\$0.00
0070         1480         7040106         FULL DEPTH REPAIR         1500         0.00         1500         SQF         0.00         \$\$250.00         \$\$0.00         \$\$0.00         \$\$0.00         \$\$250.00         \$\$0.00         \$\$0.00         \$\$0.00         \$\$0.00         \$\$250.00         \$\$0.			0070	1460	7034219A	TYPE D BARRIER	382.00	0.00	382.00	LF	0.00	\$175.00	\$0.00
Norm         Norm <th< td=""><td></td><td></td><td>0070</td><td>1470</td><td>7040102</td><td>SUBSTRUCTURE REPAIR (UNFORMED)</td><td>5.00</td><td>0.00</td><td>5.00</td><td>SQFT</td><td>1.00</td><td>\$300.00</td><td>\$300.00</td></th<>			0070	1470	7040102	SUBSTRUCTURE REPAIR (UNFORMED)	5.00	0.00	5.00	SQFT	1.00	\$300.00	\$300.00
0070         1500         7040112         DECK REPAIR WITH VOID TUBE REPLACEMENT         1,150.00         0.00         1,150.00         SQFT         0.00         \$160.00         \$0.00			0070	1480	7040106	FULL DEPTH REPAIR	150.00	0.00	150.00	SQFT	0.00	\$250.00	\$0.00
			0070	1490	7040107	SLAB EDGE REPAIR (BRIDGES)	60.00	0.00	60.00	LF	6.00	\$230.00	\$1,380.00
0070         1510         7040113         CLEANING AND EPOXY COATING         15.00         0.00         15.00         SQFT         0.00         \$200.00         \$0.00			0070	1500	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,150.00	0.00	1,150.00	SQFT	0.00	\$160.00	\$0.00
			0070	1510	7040113	CLEANING AND EPOXY COATING	15.00	0.00	15.00	SQFT	0.00	\$200.00	\$0.00



#### Total Paid / All Items / All Estimates (Including this Estimate)

the posted amount at the time the Estimate was Generated.

D.CONTRACT	roject No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTEI To Date (See report generated date)
1119-F01 J6	13500	0070	1520	7173002	SILICONE EXPANSION JOINT SEALANT	144.00	0.00	144.00	LF	0.00	\$45.00	\$0.0
		0070	1530	9029901	MISC.BRIDGE MOUNTING SIGNS WITHOUT BRACKETS	1.00	0.00	1.00	LS	0.00	\$2,500.00	\$0.0
		0071	1540	2161001	TOTAL SURFACE HYDRO DEMOLITION	1,695.00	0.00	1,695.00	SQYD	0.00	\$67.00	\$0.0
		0071	1550	2161503	REMOVAL OF EXISTING DECK REPAIR	500.00	0.00	500.00	SQFT	0.00	\$30.00	\$0.0
		0071	1560	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	25.00	0.00	25.00	CY	0.00	\$700.00	\$0.0
		0071	1570	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	1,695.00	0.00	1,695.00	SQYD	0.00	\$130.00	\$0.
		0071	1590	7040104	HALF-SOLE REPAIR	1,550.00	0.00	1,550.00	SQFT	0.00	\$55.00	\$0.
		0073	1630	2161000	SCARIFICATION OF BRIDGE DECK	534.00	0.00	534.00	SQYD	534.00	\$30.00	\$16,020.
		0073	1640	2161501	REMOVAL OF ASPHALT WEARING SURFACE	14,393.00	0.00	14,393.00	SQFT	14,393.00	\$2.00	\$28,786.
		0073	1650	2164000	CURB REMOVAL	411.00	0.00	411.00	LF	411.00	\$80.00	\$32,880.
		0073	1655	7031004	DIAMOND GRINDING	2,134.00	0.00	2,134.00	SQYD	2,134.00	\$0.01	\$21.
		0073	1660	7034219A	TYPE D BARRIER	411.00	0.00	411.00	LF	411.00	\$175.00	\$71,925.
		0073	1670	7040106	FULL DEPTH REPAIR	150.00	-150.00	0.00	SQFT	0.00	\$250.00	\$0.
		0073	1680	7040107	SLAB EDGE REPAIR (BRIDGES)	60.00	0.00	60.00	LF	9.00	\$230.00	\$2,070.
		0073	1690	7040112	DECK REPAIR WITH VOID TUBE REPLACEMENT	1,150.00	-752.00	398.00	SQFT	398.00	\$160.00	\$63,680
		0073	1700	7040113	CLEANING AND EPOXY COATING	15.00	0.00	15.00	SQFT	0.00	\$200.00	\$0.
		0073	1710	7172054	OPEN CELL FOAM JOINT SEAL	190.00	0.00	190.00	LF	0.00	\$60.00	\$0.
		0073	1720	7173002	SILICONE EXPANSION JOINT SEALANT	165.00	0.00	165.00	LF	165.00	\$45.00	\$7,425
		0074	1730	2161001	TOTAL SURFACE HYDRO DEMOLITION	2,134.00	0.00	2,134.00	SQYD	2,134.00	\$67.00	\$142,978.
		0074	1740	2161503	REMOVAL OF EXISTING DECK REPAIR	500.00	-227.00	273.00	SQFT	273.00	\$30.00	\$8,190.
		0074	1750	5050004	SUPPLEMENTARY WEARING SURFACE MATERIAL	26.00	59.20	85.20	CY	85.20	\$700.00	\$59,640
		0074	1760	5052000	LATEX MODIFIED CONCRETE WEARING SURFACE	2,134.00	0.00	2,134.00	SQYD	2,134.00	\$130.00	\$277,420.
		0074	1780	7040104	HALF-SOLE REPAIR	1,550.00	2,324.00	3,874.00	SQFT	3,874.00	\$55.00	\$213,070.
		0070	5101	6221003	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (GREATER THAN 3 IN. THICK)	0.00	1,240.00	1,240.00	SQYD	1,240.00	\$13.65	\$16,926.
		0070	5102	4030105	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125C MIX)	0.00	196.70	196.70	TONS	196.70	\$234.15	\$46,057.
		0070	5103	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$20,895.00	\$20,895.
		0070	5104	7049901	MISC.Deck Repair	0.00	1.00	1.00	LS	1.00	\$19,705.74	\$19,705
		0073	5105	7049902	MISC.BARRIER CURB RETROFIT	0.00	60.00	60.00	EA	60.00	\$324.84	\$19,490
		0073	5106	7049901	MISC.Barrier Curb Retrofit	0.00	1.00	1.00	LS	1.00	\$11,669.27	\$11,669
		0001	5107	2022010	REMOVAL OF IMPROVEMENTS	0.00	1.00	1.00	LS	1.00	\$3,036.90	\$3,036
		0070	5108	7049901	MISC.(Deck Repair During Traffic Stage 1)	0.00	1.00	1.00	LS	1.00	\$31,951.34	\$31,951.
Pr	oject J	613500 - To	tal Value	Posted to D	Date as of Report Generated Date							\$1,629,703.



# Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0110	6122030	IMPACT ATTENUATOR (RELOCATION)	3/22/23	4/3/23	1.00	EA	EB I-255	690+/-00	RT CL			Stage 2 EB at east bypass
			3/30/23	4/3/23	1.00	EA	WB I-255	690+/-00	LT CL			Stage 2 WB at east bypass
0150	6173700B	TEMP. TRAFFIC BARRIER ANCHORED., CONT	3/22/23	4/3/23	7,862.50	LF	EB I-255	120+/-20	RT CL	690+/-00	RT CL	Stage 2 EB bypass
			3/30/23	4/3/23	362.50	LF	WB I-255	686+/-37	LT CL	690+/-00	LT CL	Stage 2 east bypass WB
0220	6207001	PAVEMENT MARKING REMOVAL	3/16/23	4/3/23	9,413.00	LF	EB I-255	109+06	RT CL	682+/-30	RT CL	Stage 2 EB
0230	6209903	MISC. PAVEMENT MARKINGS	3/16/23	4/3/23	15,635.00	LF	EB I-255	109+06	RT CL	682+/-30	RT CL	Stage 2 EB
0240	6209903	MISC. PAVEMENT MARKINGS	3/16/23	4/3/23	15,345.00	LF	EB I-255	109+06	RT CL	682+/-30	RT CL	Stage 2 EB
0390	9019902	MISC. HIGHWAY LIGHTING	3/31/23	4/3/23	1.00	EA	WB I-255	707+60	LT CL	710+04	LT CL	Span 9
				4/3/23	1.00	EA	WB I-255	715+04	LT CL	717+48	LT CL	Span 12 A18503
				4/3/23	3.00	EA	Span 13 A18503	717+48	LT CL	726+57	LT CL	
0520	7125200	SURFACE PREPARATION FOR RECOATING	3/31/23	4/3/23	7,822.00	SQFT	WB I-255	728+58	LT CL	730+60	LT CL	Span 15 (100%)
0530	7125210	FIELD APPLICATION OF INORGANIC ZINC	3/31/23	4/3/23	7,822.00	SQFT	WB I-255	728+58	LT CL	730+60	LT CL	Span 15 (100%)

#### Project: J6I3500

Line Number	ltem Code	Description	DWR Date	DWR Approval Date		Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
1310	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	3/23/23	4/3/23	5.30	SQYD	SB Koch					#1
				4/3/23	5.30	SQYD	SB Koch					#3
				4/3/23	8.70	SQYD	SB Koch					#5
				4/3/23	20.00	SQYD	SB Koch					#2
			3/28/23	4/3/23	6.40	SQYD	SB Koch					#12
				4/3/23	16.50	SQYD	SB Koch					#11
				4/3/23	21.40	SQYD	SB Koch					#4
			3/30/23	4/3/23	4.20	SQYD	SB Koch					#9
				4/3/23	5.30	SQYD	NB Koch					#14
				4/3/23	5.30	SQYD	NB Koch					#17
				4/3/23	6.00	SQYD	NB Koch					#20
				4/3/23	6.70	SQYD	SB Koch					#7
				4/3/23	7.50	SQYD	SB Koch					#8
				4/3/23	18.10	SQYD	SB Koch					#10
				4/3/23	25.00	SQYD	NB Koch					#19
			3/31/23	4/3/23	10.20	SQYD	NB Koch					#21
1340	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	3/23/23	4/3/23	7.00	LF	SB Koch					#5
				4/3/23	12.00	LF	SB Koch					#2
			3/28/23	4/3/23	12.00	LF	SB Koch					#4
			3/30/23	4/3/23	16.00	LF	NB Koch					#19
1350	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	3/23/23	4/3/23	8.00	EA	SB Koch					#5
				4/3/23	12.00	EA	SB Koch					#2
				4/3/23	23.00	EA	SB Koch					#1
				4/3/23	24.00	EA	SB Koch					#3
			3/28/23	4/3/23	16.00	EA	SB Koch					#4
				4/3/23	22.00	EA	SB Koch					#11
				4/3/23	22.00	EA	SB Koch					#12
			3/30/23	4/3/23	8.00	EA	NB Koch					#17
				4/3/23	8.00	EA	SB Koch					#8
				4/3/23	8.00	EA	SB Koch					#9
				4/3/23	19.00	EA	NB Koch					#19
				4/3/23	22.00	EA	SB Koch					#7
				4/3/23	24.00	EA	NB Koch					#14
				4/3/23	24.00	EA	NB Koch					#20
				4/3/23	25.00	EA	SB Koch					#10
			3/31/23	4/3/23	46.00	EA	SB Koch					#21
1370	6179903	MISC. CONCRETE TRAFFIC BARRIER	3/22/23	4/3/23	20.00	LF	I-255	135+30	CL	135+50	CL	East of A2590
			3/27/23	4/3/23	38.00	LF	I-255	133+02	CL	133+40	CL	West of A2590
1390	6061060	MGS GUARDRAIL	3/31/23	4/3/23	-50.00	LF	EB I-255	123+19	RT CL	124+96	RT CL	Run #4 Correction

The information below this line are details for Construction Signs (if applicable). No Data Available



Apr 6, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
613413	0020	SHAPING SLOPES, CLASS	Overrun	Overrun	21	Dec 2, 2022	SYSTEM	(\$7,800.00)	
		111			24	Jan 17, 2023	SYSTEM	\$7,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',1200.00000 - 1200.00000, 'is applied (if non-zero).
					26	Feb 16, 2023	SYSTEM	(\$4,800.00)	
				Overrun - T	otal			(\$4,800.00)	
			Overrun - To	tal				(\$4,800.00)	
	0020 -	Total						(\$4,800.00)	
	0030	MISC. BITUMINOUS	Construction Stockpile		12	Jul 18, 2022	SYSTEM	(\$9,609.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
		PAVEMENT (SURF. LEVEL)		- Total				(\$9,609.50)	
			Construction	I Stockpile - 1	Fotal			(\$9,609.50)	
			Construction		2	Feb 17,	SYSTEM	\$7,499.50	Payment Estimate Item Adjustment generated Stockpile Transaction
			Stockpile			2022			
					5	Apr 4, 2022	SYSTEM	\$2,110.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$9,609.50	
			Construction	1 Stockpile S	TMI - Tota			\$9,609.50	
	0030 -	Total						\$0.00	
	0040	MISC. BITUMINOUS PAVEMENT	Material		6	Apr 18, 2022	SYSTEM	\$175,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
		(SURF. LEVEL)			6	Apr 18, 2022	SYSTEM	(\$175,000.00)	
					15	Sep 2, 2022	SYSTEM	\$175,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Sep 2, 2022	SYSTEM	(\$175,000.00)	
					16	Sep 16, 2022	SYSTEM	\$175,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					16	Sep 16, 2022	SYSTEM	(\$175,000.00)	
					17	Oct 3, 2022	SYSTEM	\$175,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Oct 3, 2022	SYSTEM	(\$175,000.00)	
					18	Oct 17, 2022	SYSTEM	\$175,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					18	Oct 17, 2022	SYSTEM	(\$175,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0040 -	Total						\$0.00	
	0050	ASPHALTIC CONCRETE MIXTURE PG	Other Item Adjustment	ACAD	12	Jul 18, 2022	fernam1	\$927.19	Asphalt Cement Price Adjustment (Tons) for SP125 in the Second Period of March 2022, Adjustment should have been on Estimate 0005. Asphalt paved on 3/16/22 & 3/25/22.
		76-22 (SP1		ACAD - Tot	al			\$927.19	
			Other Item A	l djustment - 1	otal			\$927.19	
	0050 -	Total						\$927.19	
	0060	18 IN. SLOTTED DRAIN	Overrun	Overrun	6	Apr 18, 2022	SYSTEM	(\$49,152.00)	
					12	Jul 18, 2022	SYSTEM	\$49,152.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',512.00000 - 512.00000, 'is applied (if non-zero).
				Overrun - Total	\$0.00				
			Overrun - To	tal				\$0.00	



Apr 6, 2023

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
3413	0060 -	Total						\$0.00	
	0090	IMPACT ATTENUATOR 70	Overrun	Overrun	5	Apr 4, 2022	SYSTEM	(\$4,772.00)	
		MPH (SAND BARREL ARRAY)			6	Apr 18, 2022	SYSTEM	(\$4,772.00)	
					9	Jun 1, 2022	SYSTEM	\$9,544.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',4772.00000 - 4772.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0090 -							\$0.00	
	0100	REPLACEMENT SAND BARREL	Overrun	Overrun		Sep 2, 2022	SYSTEM	(\$3,437.00)	
					21	Dec 2, 2022	SYSTEM	(\$982.00)	
					27 Mar 2, SY 2023		SYSTEM	\$4,419.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',491.00000 - 491.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
		Fotal IMPACT ATTENUATOR (RELOCATION)	Overrun - To	otal				\$0.00	
	0100 - 0110	IMPACT	Overrun	Overrun	8	May 16,	SYSTEM	\$0.00 (\$1,750.00)	
					9	2022 Jun 1, 2022	SYSTEM	\$875.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',875.00000 - 875.00000, 'is applied (if non-zero).
					15	Sep 2, 2022	SYSTEM	\$875.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',875.00000 - 875.00000, 'is applied (if non-zero).
					29	Apr 3, 2023	SYSTEM	(\$1,750.00)	
				Overrun -		- Total		(\$1,750.00)	
			Overrun - To	Total				(\$1,750.00)	
	0110 -	Total						(\$1,750.00)	
	0130	CMS W/O COMMUNICATION INTERFACE,	Overrun	Overrun	Overrun 7		SYSTEM	(\$5,600.00)	
		CONT F/			9	Jun 1, 2022	SYSTEM	\$5,600.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2800.00000 - 2800.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	otal				\$0.00	
	0130 -	Total						\$0.00	
	0150	TEMP. TRAFFIC BARRIER ANCHORED.,	Overrun	Overrun	29	Apr 3, 2023	SYSTEM	(\$41,671.88)	
		CONT		Overrun - T	otal			(\$41,671.88)	
			Overrun - To	tal				(\$41,671.88)	
	0150 -	Total						(\$41,671.88)	
	0160	RELOC TEMPORARY TRAFFIC	Overrun	Overrun	7	May 2, 2022	SYSTEM	(\$3,034.00)	
		BARRIER			8	May 16, 2022	SYSTEM	(\$2,654.75)	
					9	Jun 1, 2022	SYSTEM	\$5,688.75	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.17000 - 15.17000, 'is applied (if non-zero).
					22	Dec 16, 2022	SYSTEM	(\$10,057.71)	
					27	Mar 2, 2023	SYSTEM	\$10,057.71	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',15.17000 - 15.17000, 'is applied (if non-zero).
				Overrun - T	un - Total			\$0.00	
			Overrun - To	tal				\$0.00	



Apr 6, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3413	0160 -	Total						\$0.00	
	0290	18 IN. PIPE CULVERT GROUP B	Overrun	Overrun	6	Apr 18, 2022	SYSTEM	(\$1,240.00)	
		J			12	Jul 18, 2022	SYSTEM	\$1,240.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',62.00000 - 62.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0290 -	Total						\$0.00	
	0330	MGS GUARDRAIL	Construction Stockpile		21	Dec 2, 2022	SYSTEM	(\$26,095.04)	Payment Estimate Item Adjustment generated Stockpile Transaction
					26	Feb 16, 2023	SYSTEM	(\$5,446.30)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$31,541.34)	
			Construction	Stockpile - 1	rotal		_	(\$31,541.34)	
			Construction Stockpile STMI		2	Feb 17, 2022	SYSTEM	\$31,541.34	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$31,541.34	
			Construction					\$31,541.34	
			Overrun	Overrun		Feb 16, 2023	SYSTEM	(\$1,650.00)	
				Overrun - T	otal			(\$1,650.00)	
			Overrun - To	tal				(\$1,650.00)	
		APP. TRANS SEC (REG/NO CURB)	-					(\$1,650.00)	
	0340		Construction Stockpile		21	Dec 2, 2022	SYSTEM	(\$4,220.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total				(\$4,220.00)	
			Construction Stockpile	Stockpile -	5	Apr 4, 2022	SYSTEM	\$4,220.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$4,220.00	
			Construction	Stockpile S	IMI - Total			\$4,220.00	
	0340 -	Total						\$0.00	
	0350	MGS END ANCHOR	Construction Stockpile		26	Feb 16, 2023	SYSTEM	(\$855.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$855.00)	
			Construction	Stockpile - 1	ſotal			(\$855.00)	
			Construction Stockpile		2	Feb 17, 2022	SYSTEM	\$855.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$855.00	
			Construction	Stockpile S	ſMI - Tota			\$855.00	
	0350 -							\$0.00	
	0360	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		26	Feb 16, 2023	SYSTEM	(\$1,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		(MASH)		- Total				(\$1,950.00)	
			Construction	Stockpile - 1				(\$1,950.00)	
			Construction Stockpile STMI		2	Feb 17, 2022	SYSTEM	\$1,950.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$1,950.00	
			Construction	Stockpile S	MI - Tota			\$1,950.00	
	0360 -		Construct!		22	Dec do	OVOTEN	\$0.00	Devenent Estimate Ham Adjustment successful Ot 11 T
	0380	MISC. HIGHWAY LIGHTING	Construction Stockpile		22 28	Dec 16, 2022	SYSTEM	(\$120.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
					20	Mar 17, 2023	STOTEM	(\$480.82)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$601.02)	
			Construction	Stockpile - 1	otal			(\$601.02)	



Apr 6, 2023

last	Line	Description	Adjustment	Other	Eat	Created	Created	Amount	Demerice
ject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
413	0380	MISC. HIGHWAY LIGHTING	Construction Stockpile STMI		15	Sep 2, 2022	SYSTEM	\$601.02	Payment Estimate Item Adjustment generated Stockpile Transaction
			511/1	- Total				\$601.02	
			Construction	n Stockpile S	TMI - Tota			\$601.02	
			Material		22	Dec 16, 2022	SYSTEM	\$281.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wolkt1 overridding Payment Estimate Exception 25 on the current Payment Estimate.
					22	Dec 16, 2022	SYSTEM	(\$281.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	28	Mar 17, 2023	SYSTEM	(\$562.00)	
				Overrun - T	otal			(\$562.00)	
			Overrun - To	tal				(\$562.00)	
	0380 -	Total			_		_	(\$562.00)	
	0390	MISC. HIGHWAY LIGHTING	Construction Stockpile		22	Dec 16, 2022	SYSTEM	(\$4,884.48)	Payment Estimate Item Adjustment generated Stockpile Transaction
					29	Apr 3, 2023	SYSTEM	(\$12,211.20)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$17,095.68)	
			Construction	n Stockpile - 1	Total			(\$17,095.68)	
			Construction Stockpile STMI		15	Sep 2, 2022	SYSTEM	\$17,095.68	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$17,095.68	
			Construction	n Stockpile ST	TMI - Tota			\$17,095.68	
			Material		22	Dec 16, 2022	SYSTEM	\$9,272.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 26 on the current Payment Estimate.
					22	Dec 16, 2022	SYSTEM	(\$9,272.00)	
					23	Jan 3, 2023	SYSTEM	\$9,272.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					23	Jan 3, 2023	SYSTEM	(\$9,272.00)	
					24	Jan 17, 2023	SYSTEM	\$9,272.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wolkt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					24	Jan 17, 2023	SYSTEM	(\$9,272.00)	
					25	Feb 2, 2023	SYSTEM	\$9,272.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					25	Feb 2, 2023	SYSTEM	(\$9,272.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0390 -	Total						\$0.00	
	0400	MISC. HIGHWAY LIGHTING	Material		22	Dec 16, 2022	SYSTEM	\$2,405.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wolkt1 overridding Payment Estimate Exception 28 on the current Payment Estimate.
					22	Dec 16, 2022	SYSTEM	(\$2,405.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0400 -	Total						\$0.00	
	0470	SUBSTRUCTURE REPAIR (FORMED)	Material		26	Feb 16, 2023	SYSTEM	\$16,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wolkt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		, - ·- )			26	Feb 16, 2023	SYSTEM	(\$16,872.00)	



Draiget	Line	Description	Adjustment	Other	Eat	Created	Created	Amount	Pamarka
Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3413	0470	SUBSTRUCTURE REPAIR (FORMED)	Material		27	Mar 2, 2023	SYSTEM	\$16,872.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wolkt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					27	Mar 2, 2023	SYSTEM	(\$16,872.00)	
					28	Mar 17, 2023	SYSTEM	\$31,008.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wolkt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					28	Mar 17, 2023	SYSTEM	(\$31,008.00)	
					29	Apr 3, 2023	SYSTEM	\$31,008.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					29	Apr 3, 2023	SYSTEM	(\$31,008.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0470 -	Total						\$0.00	
	0920	MISC. REMOVALS	Material		21	Dec 2, 2022	SYSTEM	\$125,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					21	Dec 2, 2022	SYSTEM	(\$125,580.00)	
					22	Dec 16, 2022	SYSTEM	\$125,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					22	Dec 16, 2022	SYSTEM	(\$125,580.00)	
					23	Jan 3, 2023	SYSTEM	\$125,580.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					23	Jan 3, 2023	SYSTEM	(\$125,580.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	21	Dec 2, 2022	SYSTEM	(\$18,200.00)	
					24	Jan 17, 2023	SYSTEM	\$18,200.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',910.00000 - 910.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0920 -	Total						\$0.00	
	0930	MISC.	Overrun	Overrun	19	Nov 1, 2022	SYSTEM	(\$13,387.50)	
					24	Jan 17, 2023	SYSTEM	\$13,387.50	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2975.00000 - 2975.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0930 -	Total						\$0.00	
	0940	MISC.	Material		17	Oct 3, 2022	SYSTEM	\$618,684.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					17	Oct 3, 2022	SYSTEM	(\$618,684.00)	
					18	Oct 17, 2022	SYSTEM	\$618,684.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					18	Oct 17, 2022	SYSTEM	(\$618,684.00)	
					19	Nov 1, 2022	SYSTEM	\$618,684.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.



Apr 6, 2023

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
13	0940	MISC.	Material		19	Nov 1, 2022	SYSTEM	(\$618,684.00)		
					20	Nov 16, 2022	SYSTEM	\$618,684.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	
					20	Nov 16, 2022	SYSTEM	(\$618,684.00)		
					21	Dec 2, 2022	SYSTEM	\$766,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					21	Dec 2, 2022	SYSTEM	(\$766,260.00)		
					22	Dec 16, 2022	SYSTEM	\$766,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	
					22	Dec 16, 2022	SYSTEM	(\$766,260.00)		
					23	Jan 3, 2023	SYSTEM	\$766,260.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wolkt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	
					23	Jan 3, 2023	SYSTEM	(\$766,260.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
	0940 -	Total						\$0.00		
	0950	MISC.	Material		18	Oct 17, 2022	SYSTEM	\$150,473.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	
					18	Oct 17, 2022	SYSTEM	(\$150,473.40)		
					19	Nov 1, 2022	SYSTEM	\$320,292.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wolkt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	
					19	Nov 1, 2022	SYSTEM	(\$320,292.00)		
					20	Nov 16, 2022	SYSTEM	\$320,292.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wolkt1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	
					20	Nov 16, 2022	SYSTEM	(\$320,292.00)		
				- Total				\$0.00		
			Material - Tot	tal				\$0.00		
			Overrun	Overrun	19	Nov 1, 2022	SYSTEM	(\$2,422.00)		
						24	Jan 17,	SYSTEM	<b>AA AAA</b>	
					27	2023	STOTEM	\$2,422.00		
				Overrun - T			STOTEM	\$2,422.00	previous payment estimates. Price Adjustments of ',14.00000 - 14.00000, 'is	
			Overrun - To				STOTEM		previous payment estimates. Price Adjustments of ',14.00000 - 14.00000, 'is	
	0950 -	Total	Overrun - To					\$0.00	previous payment estimates. Price Adjustments of ',14.00000 - 14.00000, 'is	
	<b>0950 -</b> 0960	Total SUBSTRUCTURE REPAIR (FORMED)	Overrun - To Material				SYSTEM	\$0.00 \$0.00	previous payment estimates. Price Adjustments of ',14.00000 - 14.00000, 'is	
		SUBSTRUCTURE REPAIR			otal	2023 Aug 2,		\$0.00 \$0.00 \$0.00	previous payment estimates. Price Adjustments of ',14.00000 - 14.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment	
I		SUBSTRUCTURE REPAIR			otal 13	2023 Aug 2, 2022 Aug 2,	SYSTEM	\$0.00 \$0.00 \$0.00 \$12,540.00	previous payment estimates. Price Adjustments of ',14.00000 - 14.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment	
I		SUBSTRUCTURE REPAIR			otal 13 13	2023 Aug 2, 2022 Aug 2, 2022 Aug 16,	SYSTEM	\$0.00 \$0.00 \$12,540.00 (\$12,540.00)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment	
		SUBSTRUCTURE REPAIR			otal 13 13 14	2023 Aug 2, 2022 Aug 2, 2022 Aug 16, 2022 Aug 16,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$12,540.00 \$12,540.00 \$12,540.00	previous payment estimates. Price Adjustments of ',14.00000 - 14.00000, 'is applied (if non-zero). This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user wolkt1 overridding Payment	



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J6I3413	0960	SUBSTRUCTURE REPAIR (FORMED)	Material		16	Sep 16, 2022	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user fernam1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					16	Sep 16, 2022	SYSTEM	(\$12,540.00)	
					17	Oct 3, 2022	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					17	Oct 3, 2022	SYSTEM	(\$12,540.00)	
					18	Oct 17, 2022	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					18	Oct 17, 2022	SYSTEM	(\$12,540.00)	
					19	Nov 1, 2022	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wolkt1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					19	Nov 1, 2022	SYSTEM	(\$12,540.00)	
					20	Nov 16, 2022	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wolkt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					20	Nov 16, 2022	SYSTEM	(\$12,540.00)	
					21	Dec 2, 2022	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wolkt1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					21	Dec 2, 2022	SYSTEM	(\$12,540.00)	
					22	Dec 16, 2022	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wolkt1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					22	Dec 16, 2022	SYSTEM	(\$12,540.00)	
					23	Jan 3, 2023	SYSTEM	\$12,540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wolkt1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					23	Jan 3, 2023	SYSTEM	(\$12,540.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
			Overrun	Overrun	27	Mar 2, 2023	SYSTEM	(\$11,172.00)	
					28	Mar 17, 2023	SYSTEM	(\$39,216.00)	
				Overrun - T	otal			(\$50,388.00)	
			Overrun - To	tal				(\$50,388.00)	
	0960 -				10	0.1.1-	0)/075	(\$50,388.00)	
	0980	HALF-SOLE REPAIR	Material		18	Oct 17, 2022	SYSTEM	\$40,662.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fernam1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					18	Oct 17, 2022	SYSTEM	(\$40,662.00)	
					19	Nov 1, 2022	SYSTEM	\$40,662.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wolkt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					19	Nov 1, 2022	SYSTEM	(\$40,662.00)	
					20	Nov 16, 2022	SYSTEM	\$40,662.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wolkt1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					20	Nov 16, 2022	SYSTEM	(\$40,662.00)	
				- Total				\$0.00	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3413	0980	HALF-SOLE REPAIR	Material - To	tal				\$0.00	
	0980 -	Total						\$0.00	
	0990	FULL DEPTH REPAIR	Material		18	Oct 17, 2022	SYSTEM	\$11,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					18	Oct 17, 2022	SYSTEM	(\$11,570.00)	
					19	Nov 1, 2022	SYSTEM	\$11,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					19	Nov 1, 2022	SYSTEM	(\$11,570.00)	
					20	Nov 16, 2022	SYSTEM	\$11,570.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					20	Nov 16, 2022	SYSTEM	(\$11,570.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0990 -	Total						\$0.00	
	1010	REINFORCING STEEL (EPOXY COATED)	Material		17	Oct 3, 2022	SYSTEM	\$67,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fernam1 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					17	Oct 3, 2022	SYSTEM	(\$67,890.00)	
					18	Oct 17, 2022	SYSTEM	\$67,890.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fernam1 overridding Payment Estimate Exception 19 on the current Payment Estimate.
					18	Oct 17, 2022	SYSTEM	(\$67,890.00)	
				- Total				\$0.00	
			Material - To					\$0.00 \$0.00	
	1010 -	Total	Material - To						
	<b>1010</b> - 1020	Total MISC.	Material - To		22	Dec 16, 2022	SYSTEM	\$0.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					22 22		SYSTEM	\$0.00 \$0.00	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment
						2022 Dec 16,		\$0.00 \$0.00 \$21,864.00	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment
					22	2022 Dec 16, 2022 Jan 3,	SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00)	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment
					22 23	2022 Dec 16, 2022 Jan 3, 2023 Jan 3,	SYSTEM SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00) \$21,864.00	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment
					22 23 23	2022 Dec 16, 2022 Jan 3, 2023 Jan 3, 2023 Jan 17,	SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00)	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment
					22 23 23 24	2022 Dec 16, 2022 Jan 3, 2023 Jan 3, 2023 Jan 17, 2023 Jan 17,	SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment
					22 23 23 24 24	2022 Dec 16, 2022 Jan 3, 2023 Jan 3, 2023 Jan 17, 2023 Feb 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00)	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.
					22 23 23 24 24 25	2022 Dec 16, 2022 Jan 3, 2023 Jan 3, 2023 Jan 17, 2023 Jan 17, 2023 Feb 2, 2023 Feb 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.
					22 23 23 24 24 25 25	2022 Dec 16, 2022 Jan 3, 2023 Jan 17, 2023 Jan 17, 2023 Feb 2, 2023 Feb 2, 2023 Feb 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00)	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					22 23 23 24 24 25 25 26	2022 Dec16, 2023 Jan 3, 2023 Jan 4, 2023 Jan 17, 2023 Jan 17, 2023 Feb 2, 2023 Feb 2, 2023 Feb 16, Feb 16,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					22 23 23 24 24 25 25 25 26	2022 Dec 16, 2022 Jan 3, 2023 Jan 17, 2023 Jan 17, 2023 Feb 2, 2023 Feb 2, 2023 Feb 16, 2023 Mar 2,	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	\$0.00 \$0.00 \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00) \$21,864.00 (\$21,864.00)	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 10 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 4 on the current Payment Estimate.



Apr 6, 2023

				1					
roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
613413	1020	MISC.	Material			2023			Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					28	Mar 17, 2023	SYSTEM	(\$21,864.00)	
					29	Apr 3, 2023	SYSTEM	\$21,864.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wolkt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					29	Apr 3, 2023	SYSTEM	(\$21,864.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1020 -	Total						\$0.00	
	1100	MISC.	. Material		23	Jan 3, 2023	SYSTEM	\$14,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wolkt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					23	Jan 3, 2023	SYSTEM	(\$14,000.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1100 -	Total						\$0.00	
	1130	MISC.	Overrun	Overrun	21	Dec 2, 2022	SYSTEM	(\$3,500.00)	
					24	Jan 17, 2023	SYSTEM	\$3,500.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3500.00000 - 3500.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	1130 -	Total						\$0.00	
	1140	MISC.	Overrun	Overrun	18	Oct 17, 2022	SYSTEM	(\$2,800.00)	
						Nov 1, 2022	SYSTEM	\$2,800.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',2800.00000 - 2800.00000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	tal				\$0.00	
- 1	1140 -	Total						\$0.00	
	1190	MISC.	Overrun	Overrun	12	Jul 18, 2022	SYSTEM	(\$3,550.00)	
					15	Sep 2, 2022	SYSTEM	\$3,550.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3550.00000 - 3550.00000, 'is applied (if non-zero).
				Overrun - Total				\$0.00	
			Overrun - To	tal				\$0.00	
	1190 -	Total						\$0.00	
	1240	MISC. STRUCTURAL STEEL	Material		17	Oct 3, 2022	SYSTEM	\$89,100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 20 on the current Payment Estimate.
		CONSTRUCTION			17	Oct 3, 2022	SYSTEM	(\$89,100.00)	
					18	Oct 17, 2022	SYSTEM	\$153,900.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user fernam1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					18	Oct 17, 2022	SYSTEM	(\$153,900.00)	
					19	Nov 1, 2022	SYSTEM	\$275,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wolkt1 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					19	Nov 1, 2022	SYSTEM	(\$275,400.00)	
					20	Nov 16, 2022	SYSTEM	\$275,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wolkt1 overridding Payment Estimate Exception 20 on the current Payment Estimate.



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
13413	1240	MISC. STRUCTURAL	Material		20	Nov 16, 2022	SYSTEM	(\$275,400.00)	
		STEEL CONSTRUCTION			21	Dec 2, 2022	SYSTEM	\$275,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wolkt1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					21	Dec 2, 2022	SYSTEM	(\$275,400.00)	
					22	Dec 16, 2022	SYSTEM	\$275,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wolkt1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					22	Dec 16, 2022	SYSTEM	(\$275,400.00)	
					23	Jan 3, 2023	SYSTEM	\$275,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wolk11 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					23	Jan 3, 2023	SYSTEM	(\$275,400.00)	
					24	Jan 17, 2023	SYSTEM	\$275,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wolkt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					24	Jan 17, 2023	SYSTEM	(\$275,400.00)	
				- Total				\$0.00	
			Material - Tot	tal				\$0.00	
	1240 -							\$0.00	
	1280	PREFORMED SILICONE OR EPDM EXP. JOINT SEAL	Material		20	Nov 16, 2022	SYSTEM	\$8,415.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user wolkt1 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					20	Nov 16, 2022	SYSTEM	(\$8,415.00)	
					21	Dec 2, 2022	SYSTEM	\$16,830.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wolkt1 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					21	Dec 2, 2022	SYSTEM	(\$16,830.00)	
					22	Dec 16, 2022	SYSTEM	\$16,830.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wolkt1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					22	Dec 16, 2022	SYSTEM	(\$16,830.00)	
				- Total				\$0.00	
			Material - Tot	al - Total				\$0.00	
	1280 - 5004	Total MISC.	Other Item Adjustment		12	Jul 18, 2022	fernam1	\$0.00 \$325.74	Asphalt Cement Price Adjustment (SQYD) for SP125 in the Second Period of March 2022, Adjustment should have been on Estimate 0005. Asphalt paved
					12	Jul 18, 2022	fernam1	\$616.32	on 3/25/22. Asphalt Cement Price Adjustment (SQYD) for SP190 in the Second Period of March 2022, Adjustment should have been on Estimate 0005. Asphalt paved
				ACAD T		2022		¢0.40.00	on 3/17/22 & 3/24/2022.
			Other Item A	ACAD - Tota				\$942.06 \$942.06	
	5004 -	Total						\$942.06	
	5004	Total MISC. BITUMINOUS	Construction Stockpile		12	Jul 18, 2022	SYSTEM	(\$6,726.65)	Payment Estimate Item Adjustment generated Stockpile Transaction
		PAVEMENT (SURF. LEVEL)			22	Dec 16, 2022	SYSTEM	(\$480.47)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$7,207.12)	
			Construction	Stockpile - 1	Fotal			(\$7,207.12)	
			Construction Stockpile STMA		12	Jul 18, 2022	SYSTEM	\$2,110.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$2,110.00	
			Construction	Stockpile S			OVOTT	\$2,110.00	
			Construction		12	Jul 18,	SYSTEM	\$7,499.50	Payment Estimate Item Adjustment generated Stockpile Transaction



Apr 6, 2023

Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks					
1612/112	5007	MIRC	Stockpilo	Туре		2022								
J6I3413	5007	MISC. BITUMINOUS	Stockpile STMI	- Total				\$7,499.50						
		PAVEMENT (SURF. LEVEL)	Construction		Stockpile STMI - Total									
			Other Item Adjustment	ACAD		Jul 18, 2022	fernam1	\$7,499.50 \$320.55	Asphalt Cement Price Adjustment (SQYD) for SP125 in the Second Period of April 2022, Adjustment should have been on Estimate 0007. Asphalt paved on 4/21/22.					
					12	Jul 18, 2022	fernam1	\$1,061.04	Asphalt Cement Price Adjustment (SQYD) for SP190 in the Second Period of April 2022, Adjustment should have been on Estimate 0007. Asphalt paved on 4/18/22 & 4/19/22.					
				ACAD - Tot	al			\$1,381.59						
			Other Item A	djustment - T	otal			\$1,381.59						
	5007 -	Total						\$3,783.97						
	5012	CONCRETE PAVEMENT (10 IN. NON-REINF)	Material		16	Sep 16, 2022	SYSTEM	\$17,395.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					16	Sep 16, 2022	SYSTEM	(\$17,395.38)						
					17	Oct 3, 2022	SYSTEM	\$17,395.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					17	Oct 3, 2022	SYSTEM	(\$17,395.38)						
						18	Oct 17, 2022	SYSTEM	\$17,395.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					18	Oct 17, 2022	SYSTEM	(\$17,395.38)						
											19	Nov 1, 2022	SYSTEM	\$17,395.38
					19	Nov 1, 2022	SYSTEM	(\$17,395.38)						
					20	Nov 16, 2022	SYSTEM	\$17,395.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					20	Nov 16, 2022	SYSTEM	(\$17,395.38)						
					21	Dec 2, 2022	SYSTEM	\$17,395.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wolkt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					21	Dec 2, 2022	SYSTEM	(\$17,395.38)						
					22	Dec 16, 2022	SYSTEM	\$17,395.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user wolkt1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					22	Dec 16, 2022	SYSTEM	(\$17,395.38)						
						23	Jan 3, 2023	SYSTEM	\$17,395.38	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 2 on the current Payment Estimate.				
					23	Jan 3, 2023	SYSTEM	(\$17,395.38)						
				- Total				\$0.00						
			Material - Total					\$0.00						
	5012 -	Total						\$0.00						
	5021	MISC. HIGHWAY LIGHTING			27	Mar 2, 2023	SYSTEM	\$3,398.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wolkt1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					27	Mar 2, 2023	SYSTEM	(\$3,398.85)						
				- Total				\$0.00						
			Material - Tot	al				\$0.00						
	5021 -	Total						\$0.00						
J6I3413 ·	Total							(\$95,168.66)						



Apr 6, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
613500	1300	SHAPING SLOPES, CLASS	Overrun	Overrun	26	Feb 16, 2023	SYSTEM	(\$360.00)	
		111			27	Mar 2, 2023	SYSTEM	(\$1,260.00)	
				Overrun - T	otal			(\$1,620.00)	
			Overrun - To	tal				(\$1,620.00)	
	1300 -	Total						(\$1,620.00)	
	1350	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		29	Apr 3, 2023	SYSTEM	\$4,665.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user wolkt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					29	Apr 3, 2023	SYSTEM	(\$4,665.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
			Overrun	Overrun	29	Apr 3, 2023	SYSTEM	(\$405.00)	
				Overrun - T	otal			(\$405.00)	
			Overrun - To	tal				(\$405.00)	
	1350 -	Total			_			(\$405.00)	
	1370	MISC. CONCRETE TRAFFIC BARRIER	Material		29	Apr 3, 2023	SYSTEM	\$12,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					29	Apr 3, 2023	SYSTEM	(\$12,760.00)	
				- Total				\$0.00	
			Material - Tot	al				\$0.00	
			Overrun	Overrun	29	Apr 3, 2023	SYSTEM	(\$6,160.00)	
				Overrun - T	otal			(\$6,160.00)	
			Overrun - To	tal				(\$6,160.00)	
	1370 -	Total						(\$6,160.00)	
	1390	MGS GUARDRAIL	Construction Stockpile		22	Dec 16, 2022	SYSTEM	(\$1,009.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					26	Feb 16, 2023	SYSTEM	(\$4,540.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
					27	Mar 2, 2023	SYSTEM	(\$2,774.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$8,324.25)	
			Construction	Stockpile - 1	1			(\$8,324.25)	
			Construction Stockpile STMI		2	Feb 17, 2022	SYSTEM	\$42,620.16	Payment Estimate Item Adjustment generated Stockpile Transaction
			0	- Total				\$42,620.16	
	1000		Construction	Stockpile S	rmi - Tota			\$42,620.16	
	1390 - 1400	MGS BRIDGE	Construction		22	Dec 16,	SYSTEM	\$34,295.91 (\$2,110.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
		APP. TRANS SEC (REG/NO CURB)	Stockpile	- Total		2022		(\$2,110.00)	
			Construction	Stockpile - 1	Total			(\$2,110.00)	
			Construction Stockpile STMI		5	Apr 4, 2022	SYSTEM	\$4,220.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			3 mil	- Total				\$4,220.00	
			Construction	Stockpile S	TMI - Tota			\$4,220.00	
	1400 -	Total						\$2,110.00	
	1410	MGS END ANCHOR	Construction Stockpile		26	Feb 16, 2023	SYSTEM	(\$855.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
					27	Mar 2, 2023	SYSTEM	(\$855.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$1,710.00)	



Apr 6, 2023

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J6I3500	1410	MGS END	Construction	1 Stockpile - 1	Fotal			(\$1,710.00)											
		ANCHOR	Construction Stockpile		2	Feb 17, 2022	SYSTEM	\$3,420.00	Payment Estimate Item Adjustment generated Stockpile Transaction										
			STMI	- Total				\$3,420.00											
			Construction	Stockpile S	MI - Total			\$3,420.00											
	1410 -	Total						\$1,710.00											
	1420	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		22	Dec 16, 2022	SYSTEM	(\$1,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
		(MASH)			26	Feb 16, 2023	SYSTEM	(\$1,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
					27	Mar 2, 2023	SYSTEM	(\$1,950.00)	Payment Estimate Item Adjustment generated Stockpile Transaction										
				- Total				(\$5,850.00)											
				1 Stockpile - 1			01/07514	(\$5,850.00)											
			Construction Stockpile STMI		2	Feb 17, 2022	SYSTEM	\$11,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction										
					- Total														
			Construction	Stockpile S	MI - Total			\$11,700.00											
	1420 -							\$5,850.00											
	1660	TYPE D BARRIER	Material		15	Sep 2, 2022	SYSTEM	\$19,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fernam1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
								15	Sep 2, 2022	SYSTEM	(\$19,950.00)								
															16	Sep 16, 2022	SYSTEM	\$19,950.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user fernam1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
										16	Sep 16, 2022	SYSTEM	(\$19,950.00)						
					17	Oct 3, 2022	SYSTEM	\$38,850.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user fernam1 overridding Payment Estimate Exception 8 on the current Payment Estimate.										
					17	Oct 3, 2022	SYSTEM	(\$38,850.00)											
					18	Oct 17, 2022	SYSTEM	\$71,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user fernam1 overridding Payment Estimate Exception 9 on the current Payment Estimate.										
					18	Oct 17, 2022	SYSTEM	(\$71,925.00)											
					19	Nov 1, 2022	SYSTEM	\$71,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wolkt1 overridding Payment Estimate Exception 8 on the current Payment Estimate.										
					19	Nov 1, 2022	SYSTEM	(\$71,925.00)											
								20	Nov 16, 2022	SYSTEM	\$71,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wolkt1 overridding Payment Estimate Exception 11 on the current Payment Estimate.							
					20	Nov 16, 2022	SYSTEM	(\$71,925.00)											
					21	Dec 2, 2022	SYSTEM	\$71,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user wolkt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
					21	Dec 2, 2022	SYSTEM	(\$71,925.00)											
					22	Dec 16, 2022	SYSTEM	\$71,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user wolkt1 overridding Payment Estimate Exception 15 on the current Payment Estimate.										
					22	Dec 16, 2022	SYSTEM	(\$71,925.00)											
					23	Jan 3, 2023	SYSTEM	\$71,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user wolkt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.										
					23	Jan 3, 2023	SYSTEM	(\$71,925.00)											



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
00	1660	TYPE D BARRIER	Material		24	Jan 17, 2023	SYSTEM	\$71,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wolk11 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					24	Jan 17, 2023	SYSTEM	(\$71,925.00)	
					25	Feb 2, 2023	SYSTEM	\$71,925.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wolkt1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					25	Feb 2, 2023	SYSTEM	(\$71,925.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1660 -	Total						\$0.00	
	1690	DECK REPAIR WITH VOID TUBE REPLACEMENT	Material		9	Jun 1, 2022	SYSTEM	\$960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Jun 1, 2022	SYSTEM	(\$960.00)	
					10	Jun 16, 2022	SYSTEM	\$7,280.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user grossd1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Jun 16, 2022	SYSTEM	(\$7,280.00)	
					13	Aug 2, 2022	SYSTEM	\$100,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user wolk11 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Aug 2, 2022	SYSTEM	(\$100,400.00)	
					16	Sep 16, 2022	SYSTEM	\$126,320.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user fernam1 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					16	Sep 16, 2022	SYSTEM	(\$126,320.00)	
					17	Oct 3, 2022	SYSTEM	\$126,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user fernam1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					17	Oct 3, 2022	SYSTEM	(\$126,400.00)	
					18	Oct 17, 2022	SYSTEM	\$126,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user fernam1 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					18	Oct 17, 2022	SYSTEM	(\$126,400.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1690 -	Total						\$0.00	
	1750	SUPPLEMENTARY WEARING	Overrun	Overrun	21	Dec 2, 2022	SYSTEM	(\$41,440.00)	
		SURFACE MATERIAL			24	Jan 17, 2023	SYSTEM	\$41,440.00	Unit price based on averaged overrun adjustments for installed quantity on al previous payment estimates. Price Adjustments of ',700.00000 - 700.00000, applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
			Overrun - ro					\$0.00	
	1750 -	Total	Overrun - To						
	<b>1750</b> - 1760	LATEX MODIFIED CONCRETE WEARING	Material		20	Nov 16, 2022	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
		LATEX MODIFIED CONCRETE			20 20		SYSTEM SYSTEM		Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment
		LATEX MODIFIED CONCRETE WEARING				2022 Nov 16,		\$277,420.00	Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J6I3500	1760	LATEX MODIFIED CONCRETE WEARING SURFACE	Material		22	Dec 16, 2022	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user wolkt1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					22	Dec 16, 2022	SYSTEM	(\$277,420.00)	
					23	Jan 3, 2023	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					23	Jan 3, 2023	SYSTEM	(\$277,420.00)	
					24	Jan 17, 2023	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					24	Jan 17, 2023	SYSTEM	(\$277,420.00)	
					25	Feb 2, 2023	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					25	Feb 2, 2023	SYSTEM	(\$277,420.00)	
					26	Feb 16, 2023	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					26	Feb 16, 2023	SYSTEM	(\$277,420.00)	
					27	Mar 2, 2023	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					27	Mar 2, 2023	SYSTEM	(\$277,420.00)	
					28	Mar 17, 2023	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					28	Mar 17, 2023	SYSTEM	(\$277,420.00)	
					29	Apr 3, 2023	SYSTEM	\$277,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					29	Apr 3, 2023	SYSTEM	(\$277,420.00)	
				- Total				\$0.00	
	1760	Total	Material - To	tal				\$0.00 \$0.00	
	1780 -	- Total HALF-SOLE REPAIR	Material		8	May 16, 2022	SYSTEM	\$13,585.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user wolkt1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	May 16, 2022	SYSTEM	(\$13,585.00)	
					10	Jun 16, 2022	SYSTEM	\$85,250.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user grosso1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Jun 16, 2022	SYSTEM	(\$85,250.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	1780 -	Total						\$0.00	
J6I3500 -								\$35,780.91	
Overall -	Total							(\$59,387.75)	