

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2022

| Progress Estima | ate Number | Contract ID Prime Contractor | 211119-H15 Emery Sapp & Sons, | | er 16, 2022 Original Contract Amount er 30, 2022 Net Change Order Amount Current Contract Amount | t (\$4,610.00) |
|-----------------------|-------------|---------------------------------|----------------------------------|-----------------------------------|--|----------------|
| Approval Date | | | | | | By User |
| September 30, 2022 | | | Generated and A | Approved (and should be considere | ed Draft) at the Project Office Level by | ellisc2 |
| October 3, 2022 | | | Reviewed and Appro | ved (and should be considered Dr | aft) at the Resident Engineer Level by | bollis1 |
| October 4, 2022 | | | F | Reviewed and Approved at the Cer | ntral Office Controllers Office Level by | ramses1 |
| Original Comp | letion Date | Current Co | mpletion Date | Actual Completion Date | % of Current Contract Amount | nt Complete |
| November | 1, 2022 | Novemb | per 1, 2022 | | 96.54% | |

| | Contract Informational Dat | tes | Milestones |
|------------------------|----------------------------|--------------------------------|----------------------------------|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract |
| Acceptance Date | | | |
| Awarded Date | December 1, 2021 | December 1, 2021 | |
| Letting Date | November 19, 2021 | November 19, 2021 | |
| Notice to Proceed Date | January 31, 2022 | January 31, 2022 | |
| Open to Traffic Date | | | |
| Work Began Date | | | |

| Contract Total Pa | y For Estimate No. 7 | | | | |
|-------------------|----------------------------|---------------|----------------|----------------|--|
| | | This Estimate | Previous | To Date | |
| 211119-H15 | | | | | |
| | Total Posted Items Pay | \$0.00 | \$2,185,181.31 | \$2,185,181.31 | |
| | Gross Item Adjustments | \$3,394.30 | \$173,668.25 | \$177,062.55 | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | |
| | Liquidated Damage | \$0.00 | \$0.00 | \$0.00 | |
| | Other Contract Adjustments | \$0.00 | \$0.00 | \$0.00 | |
| | | | \$2,358,849.56 | \$2,362,243.86 | |
| Contract Total Pa | yable This Estimate: | \$3,394.30 | | | |

Items Paid This Estimate Period

No Data Available Contract Adjustments This Estimate

| | | tments Exist on Contract ments This Estimate | | | | | | |
|-------------------|-------------|---|--------------------------|----------------------------------|---|------------------------|---------------------------------------|----------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J9S3651 | 0080 | TACK COAT | Material | | | -12,286 | \$2.50 | (\$30,715.00) |
| | 0080 | TACK COAT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. | 12,286 | \$2.50 | \$30,715.00 |
| | 0190 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -89,600 | \$0.11 | (\$9,856.00) |
| | 0190 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. | 89,600 | \$0.11 | \$9,856.00 |
| | 0190 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | Retroreflectivity Adjustment | Payment of 20% withholding for reflectivity results | | | \$1,971.20 |
| | 0190 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | Retroreflectivity Adjustment | Retro reflectivity results 105% bonus | | | \$492.80 |

Page 1 of 14 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: September 30, 2022

Progress Estimate Number 7 Contract ID 211119-H15 Prime Contractor Emery Sapp & Sons, Inc. Pay Period Start September 16, 2022 Original Contract Amount \$2,268,187.05 Pay Period End September 30, 2022 Net Change Order Amount \$4,4610.00) Current Contract Amount \$2,263,577.05

| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
|-------------------|-------------|--|--------------------|----------------------------------|--|------------------------|---------------------------------------|-------------------|
| 9S3651 | 0200 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -33,829 | \$0.11 | (\$3,721.19 |
| | 0200 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. | 33,829 | \$0.11 | \$3,721.19 |
| | 0200 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | | Retroreflectivity Adjustment | Payment of 20% withholding for reflectivity results | | | \$744.24 |
| | 0200 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | | Retroreflectivity Adjustment | Retro reflectivity results 105% bonus | | | \$186.06 |
| | 0250 | SEEDING - COOL SEASON GRASSES | Material | | | -9 | \$2,430.00 | (\$21,870.00 |
| | 0250 | SEEDING - COOL SEASON GRASSES | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 7 on the current Payment Estimate. | 9 | \$2,430.00 | \$21,870.00 |
| | 0350 | SHF-FLAT SHEET FLUORESCENT | Material | | | -30 | \$32.00 | (\$960.00 |
| | 0350 | SHF-FLAT SHEET FLUORESCENT | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 12 on the current Payment Estimate. | 30 | \$32.00 | \$960.00 |
| | 0360 | MISC. | Material | | | -2 | \$12,800.00 | (\$25,600.00 |
| | 0360 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. | 2 | \$12,800.00 | \$25,600.00 |
| otal | | | | | | | | \$3,394.30 |

Revision 4/1/2020 Page 2 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | | | | | (| Contract Project Information | 1 |
|-------------------|----------------------------|-----------------------------------|---------|-------------|-------------------------|--------------------------------|--------------------------------|
| Project Number | Federal Proj. Number | Project Description | Route | County | | | Location of Work |
| J9S3651 | FAS S703(85) | Resurface and add shoulders | В | MISSISSIPPI | from Rte. 62 in Bertral | nd to Rte. 80 | |
| Totals by J | Job Numbe | rs | | | | | |
| J9S3651 | | | | | This Estimate | Previous | To Date |
| | | d Item Pay Item Adjustm | ents | | \$0.00 \$3,394.30 | \$2,185,181.31 \$173,668.25 | \$2,185,181.31 \$177,062.55 |
| | | ,, | | s Item Pay | \$3,394.30 | \$2,358,849.56 | \$2,362,243.86 |
| | Incent | tive | | | \$0.00 | \$0.00 | \$0.00 |
| | Disino | entive | | | \$0.00 | \$0.00 | \$0.00 |
| | Liquic | lated Damage: | s | | \$0.00 | \$0.00 | \$0.00 |
| | 046 | Comtunat Adia | atmanta | | CO OO | ድር ርር | ¢0.00 |

Revision 4/1/2020 Page 3 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Ferrou | | | |
|---|-----------------------------------|---------------|--------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 4071005, Project Item Line Number 0080, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 6206000C, Project Item Line Number 0190, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 6206000C, Project Item Line Number 0190, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 6206001C, Project Item Line Number 0200, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 6206001C, Project Item Line Number 0200, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 7039902, Project Item Line Number 0360, Material Set 7039902, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 8051000A, Project Item Line Number 0250, Material Set 8051000A96, Material 0805SD - Grass Seed -Seed, Acceptance Action Generic 0805SD is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 8051000A, Project Item Line Number 0250, Material Set 8051000A96, Material 0801AG - Agricultural Lime -Effective Nuetralizer, Acceptance Action Generic 0801AG is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 8051000A, Project Item Line Number 0250, Material Set 8051000A96, Material 0801FZ - Fertilizer, Acceptance Action Generic 0801FZ is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 8051000A, Project Item Line Number 0250, Material Set 8051000A96, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 8051000A, Project Item Line Number 0250, Material Set 8051000A96, Material 0802MLSP - Overspray Slick Paper, Acceptance Action Generic 0802MLSP is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J9S3651, Item 9035069A, Project Item Line Number 0350, Material Set 9035069A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient. | No Remark was entered by Engineer | ellisc2 | Overridden |
| Estimate Exception Type: Item Overrun: Contract 211119-H15, Contract Project J9S3651, Project Item Line Number 0040, Contract Line Item Number 0040, Item 3105002, Minor Item. | No Remark was entered by Engineer | ellisc2 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 211119-H15, Contract Project J9S3651, Project Item Line Number 0220, Contract Line Item Number 0220, Item 6224010, Minor Item. | No Remark was entered by Engineer | ellisc2 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 211119-H15, Contract Project J9S3651, Project Item Line Number 0300, Contract Line Item Number 0300, Item 8061019, Minor Item. | No Remark was entered by Engineer | ellisc2 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 211119-H15, Contract Project J9S3651, Project Item Line Number 0190, Contract Line Item Number 0190, Item 6206000C, Minor Item. | No Remark was entered by Engineer | ellisc2 | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 211119-H15, Contract Project J9S3651, Project Item Line Number 0200, Item 6206001C, Minor Item. | No Remark was entered by Engineer | ellisc2 | Acknowledged |

Revision 4/1/2020 Page 4 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|---------------|--|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--|
| 211119-H15 | J9S3651 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$5,400.00 | \$5,400.00 |
| | | 0001 | 0020 | 2129900 | MISC.mics. shoulder grading | 894.00 | 0.00 | 894.00 | 100F | 894.00 | \$162.00 | \$144,828.00 |
| | | 0001 | 0030 | 3049907 | MISC.type 1 aggregate for base | 15.00 | 0.00 | 15.00 | CUYD | 15.00 | \$104.00 | \$1,560.00 |
| | | 0001 | 0040 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 60.00 | 0.00 | 60.00 | TONS | 123.00 | \$66.00 | \$8,118.00 |
| | | 0001 | 0050 | 4011211 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-2) | 14,630.00 | 0.00 | 14,630.00 | TONS | 14,541.00 | \$70.50 | \$1,025,140.50 |
| | | 0001 | 0060 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | 9.20 | 0.00 | 9.20 | TONS | 9.20 | \$240.00 | \$2,208.00 |
| | | 0001 | 0070 | 4019910 | MISC.optional shoulder base | 9,609.90 | 0.00 | 9,609.90 | TONS | 9,184.00 | \$63.00 | \$578,592.00 |
| | | 0001 | 0080 | 4071005 | TACK COAT | 12,300.00 | 0.00 | 12,300.00 | GAL | 12,286.00 | \$2.50 | \$30,715.00 |
| | | 0001 | 0090 | 6096020 | FURNISHING TYPE 2 ROCK DITCH LINER | 27.00 | 0.00 | 27.00 | CUYD | 0.00 | \$149.00 | \$0.00 |
| | | 0001 | 0100 | 6123000A | TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$850.00 | \$1,700.00 |
| | | 0001 | 0110 | 6161005 | CONSTRUCTION SIGNS | 1,518.00 | 0.00 | 1,518.00 | SQFT | 1,045.00 | \$5.00 | \$5,225.00 |
| | | 0001 | 0120 | 6161008 | ADVANCED WARNING RAIL SYSTEM | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$43.00 | \$0.00 |
| | | 0001 | 0130 | 6161025 | CHANNELIZER (TRIM LINE) | 100.00 | 0.00 | 100.00 | EA | 25.00 | \$11.00 | \$275.00 |
| | | 0001 | 0140 | 6161030 | TYPE III MOVEABLE BARRICADE | 6.00 | 0.00 | 6.00 | EA | 0.00 | \$134.00 | \$0.00 |
| | | 0001 | 0150 | 6161040 | FLASHING ARROW PANEL | 2.00 | 0.00 | 2.00 | EA | 0.00 | \$270.00 | \$0.00 |
| | | 0001 | 0160 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$5,180.00 | \$10,360.00 |
| | | 0001 | 0170 | 6181000 | MOBILIZATION | 1.00 | -1.00 | 0.00 | LS | 0.00 | \$139,000.82 | \$0.00 |
| | | 0001 | 0171 | 6181000 | MOBILIZATION | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$129,324.82 | \$129,324.82 |
| | | 0001 | 0180 | 6181020 | ADDITIONAL MOBILIZATION FOR SEEDING | 3.00 | 0.00 | 3.00 | EA | 0.00 | \$600.00 | \$0.00 |
| | | 0001 | 0190 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 87,754.00 | 0.00 | 87,754.00 | LF | 89,600.00 | \$0.11 | \$9,856.00 |
| | | 0001 | 0200 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 30,380.00 | 0.00 | 30,380.00 | LF | 33,829.00 | \$0.11 | \$3,721.19 |
| | | 0001 | 0210 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 2,778.00 | 0.00 | 2,778.00 | SQYD | 2,778.00 | \$2.50 | \$6,945.00 |
| | | 0001 | 0220 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 1,701.00 | 0.00 | 1,701.00 | SQYD | 1,745.00 | \$11.50 | \$20,067.50 |
| | | 0001 | 0230 | 6261000A | BITUMINOUS SHOULDER RUMBLE STRIP | 842.60 | 0.00 | 842.60 | STA | 842.60 | \$15.65 | \$13,186.69 |
| | | 0001 | 0240 | 7250318A | 18 IN. PIPE GROUP B | 55.00 | 0.00 | 55.00 | LF | 55.00 | \$190.00 | \$10,450.00 |
| | | 0001 | 0250 | 8051000A | SEEDING - COOL SEASON GRASSES | 20.50 | 0.00 | 20.50 | ACRE | 9.00 | \$2,430.00 | \$21,870.00 |
| | | 0001 | 0260 | 8061005 | ROCK DITCH CHECK | 3,000.00 | -2,800.00 | 200.00 | LF | 200.00 | \$14.00 | \$2,800.00 |
| | | 0001 | 0270 | 8061006 | ALTERNATE DITCH CHECK | 300.00 | 840.00 | 1,140.00 | LF | 1,140.00 | \$11.00 | \$12,540.00 |
| | | 0001 | 0280 | 8061016 | SEDIMENT REMOVAL | 300.00 | 0.00 | 300.00 | CUYD | 0.00 | \$16.00 | \$0.00 |
| | | 0001 | 0290 | 8061017 | TEMPORARY SEEDING | 4.00 | 0.00 | 4.00 | ACRE | 0.00 | \$1,835.00 | \$0.00 |
| | | 0001 | 0300 | 8061019 | SILT FENCE | 1,000.00 | 6,760.00 | 7,760.00 | LF | 7,940.00 | \$3.75 | \$29,775.00 |
| | | 0010 | 0310 | 6063020 | TYPE C CRASHWORTHY END TERMINAL (MASH) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$35,300.00 | \$70,600.00 |
| | | 0040 | 0320 | 9031260 | WOOD POST, 4 IN. BY 4 IN. | 30.00 | 0.00 | 30.00 | LF | 0.00 | \$21.60 | \$0.00 |
| | | 0040 | 0330 | 9031270A | 2 IN. PSST POST - 12 GA. | 74.00 | 0.00 | 74.00 | LF | 74.00 | \$32.40 | \$2,397.60 |
| | | 0040 | 0340 | 9031271 | POST ANCHOR FOR 2 IN. PSST - 12 GA. | 30.00 | 0.00 | 30.00 | LF | 30.00 | \$43.00 | \$1,290.00 |
| | | 0040 | 0350 | 9035069A | SHF-FLAT SHEET FLUORESCENT | 30.00 | 0.00 | 30.00 | SQFT | 30.00 | \$32.00 | \$960.00 |
| | | 0070 | 0360 | 7039902 | MISC.End Post Modification | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$12,800.00 | \$25,600.00 |
| | | 0001 | 5001 | 6189901 | MISC.Adjust Mobilization for Contract Bond | 0.00 | 1.00 | 1.00 | LS | 1.00 | \$9,676.00 | \$9,676.00 |
| | Project J | 9S3651 - To | otal Value | Posted to D | late as of Report Generated Date | | | | | | | \$2,185,181.30 |
| 211119-H15 Ove | erall - Total | Value Post | ted to Da | te as of Repo | ort Generated Date | | | | | | | \$2,185,181.30 |

Page 5 of 14 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| Project | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post | | |
|---------|----------------|------------------|---------------------------------------|---|---------|-------------|---|-----------------|--------------------|-----------------|-------------------------|---------------------|--|--|
| J9S3651 | 0110 | July 5, 2022 | 116 | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.174 | Rte C West | 1.00 | 16.00 | | | 16.00 | | |
| | | | | GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES | | 0.143 | Rte B North | 1.00 | 10.00 | | | 10.00 | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.102 | Rte CC N | 1.00 | 16.00 | | | 16.00 | | |
| | | | | CONST-7 48x24 8.00 RATE OUR WORK ZONE | | 0.029 | Rte B North | 1.00 | 8.00 | | | 8.00 | | |
| | | | | GO20-2 48x24 8.00 END ROAD WORK | | 8.902 | Rte B South | 1.00 | 8.00 | | | 8.00 | | |
| | | | | GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES | | 19.773 | US 62 West | 1.00 | 10.00 | | | 10.00 | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 2.980 | County Road 416 West | 1.00 | 16.00 | | | 16.00 | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 66.542 | US 62 East | 1.00 | 16.00 | | | 16.00 | | |
| | | | | GO20-2 48x24 8.00 END ROAD WORK | | 66.815 | US 62 East | 1.00 | 8.00 | | | 8.00 | | |
| | | | | CONST-7 48x24 8.00 RATE OUR WORK ZONE | | 19.647 | US 62 West | 1.00 | 8.00 | | | 8.00 | | |
| | | July 6, 2022 | 184 | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.705 | Rte B North | 1.00 | 16 | | | 16 | | |
| | | | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | | 0.259 | Rte B North | 1.00 | 12 | | | 12 | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.03 | IS 57S to Rt B | 1.00 | 16 | | | 16 | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.021 | IS 57N to Rt B | 1.00 | 16 | | | 10 | | |
| | | | | WO20-4 48x48 16.00 ONE LANE ROAD AHEAD | | 0.811 | Rte B North | 1.00 | 16 | | | 16 | | |
| | | | | WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS | | 7.612 | Rte B South | 1.00 | 16 | | | 16 | | |
| | | | | | | | WO3-4 8x48 16.00 BE PREPARED TO STOP | | 7.498 | Rte B South | 1.00 | 16 | | |
| | | | | WO20-4 48x48 16.00 ONE LANE ROAD AHEAD | | 7.401 | Rte B South | 1.00 | 16 | | | 16 | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 7.276 | Rte B South | 1.00 | 16 | | | 16 | | |
| | | | | CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE | | 19.898 | US 62 West | 1.00 | 12 | | | 12 | | |
| | | | | WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS | | 1.007 | Rte B North | 1.00 | 16 | | | 16 | | |
| | | | | WO3-4 8x48 16.00 BE PREPARED TO STOP | | 0.907 | Rte B North | 1.00 | 16 | | | 16 | | |
| | | July 7, 2022 | 48 | GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR | | 0.000 | Rte B Various | 5.00 | 8.75 | | | 43.75 | | |
| | | | | GO20-4 36x18 4.50 PILOT CAR FOLLOW ME | | 0.000 | Rte B Various | 1.00 | 4.50 | | | 4.50 | | |
| | | July 8, 2022 | 96 | WO20-4 48x48 16.00 ONE LANE ROAD AHEAD | | 6.901 | Rte B South | 1.00 | 16.00 | | | 16.00 | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 6.746 | Rte B South | 1.00 | 16.00 | | | 16.00 | | |
| | | | | WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS | | 0.946 | Rte B North | 1.00 | 16.00 | | | 16.00 | | |
| | | | | WO20-4 48x48 16.00 ONE LANE ROAD AHEAD | | 0.857 | Rte B North | 1.00 | 16.00 | | | 16.00 | | |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.705 | Rte B North | 1.00 | 16.00 | | | 16.00 | | |
| | | | | WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS | | 7.037 | Rte B South | 1.00 | 16.00 | | | 16.00 | | |
| | | July 18, 2022 | 464 | WO8-12 48x48 16.00 NO CENTER LINE | | 0.089 | Rte B South | 1 | 16.00 | | | 16.00 | | |
| | | | | WO8-11 48x48 16.00 UNEVEN | | 0.133 | Rte B South | 1.00 | 16.00 | | | 16.00 | | |

Revision 4/1/2020 Page 6 of 14



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

| | | | | r Construction Signs (if applicat | | | | | | _ | | |
|---------|----------------|------------------|---------------------------------------|---|---------|-------------|-------------|-----------------|--------------------|-----------------|-------------------------|---------------------|
| Project | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post |
| J9S3651 | 0110 | July 18, 2022 | 464 | LANES | | | | | | | | |
| | | 2022 | | WO8-11 48x48 16.00 UNEVEN LANES | | 8.762 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 8.710 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 8.208 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 7.290 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 0.312 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 0.380 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 0.607 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 0.642 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 1.419 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 1.678 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 2.431 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 2.474 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 2.732 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 2.768 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 3.557 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 4.095 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 4.173 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 4.613 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 4.920 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 4.977 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 5.000 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 5.043 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 5.993 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 6.112 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 7.093 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-11 48x48 16.00 UNEVEN LANES | | 7.137 | Rte B South | 1.00 | 16.00 | | | 16.00 |
| | | | | WO8-12 48x48 16.00 NO CENTER LINE | | 7.240 | Rte B North | 1.00 | 16.00 | | | 16.00 |
| | | August 4, 2022 | 137 | GO20-4a 42x30 8.75 PLEASE WAIT FOR PILOT CAR | | 0.000 | Rte B South | 1 | 8.75 | | | 8.75 |
| | | | | WO20-4 48x48 16.00 ONE LANE ROAD AHEAD | | 0.000 | Rte B South | 2.00 | 16.00 | | | 32.00 |
| | | | | WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD | | 0.000 | Rte B South | 2.00 | 16.00 | | | 32.00 |
| | | | | WO3-4 8x48 16.00 BE PREPARED TO STOP | | 0.000 | Rte B South | 2.00 | 16.00 | | | 32.00 |

Revision 4/1/2020 Page 7 of 14

Report Generated on October 5, 2022



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

| Project | Line Number | DWR Date | Total Quantity Posted For DWR Date | Sign Information | Station | Log Mile | Location | Number of Items | SF Each Sign | Special Sign | SF Each Special Sign | Total SF to Post |
|---------|----------------|-------------------|------------------------------------|---|---------|-------------|-------------|-----------------|--------------------|-----------------|-------------------------|---------------------|
| J9S3651 | 0110 | August 4, 2022 | 137 | WO20-7 48x48 16.00 FLAGGER (SYMBOL) WITH FLAGS | | 0.000 | Rte B South | 2.00 | 16.00 | | | 32.00 |
| | 0110 - To | otal | | | | | | | | | | 1045 |

Revision 4/1/2020 Page 8 of 14



| oject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-------|---------------|--|--------------------------|-----------------------------|-------------------|--|----------------------|--|---|
| 3651 | 0030 | MISC. AGGREGATE FOR BASE | Material | | 2 | Jul 17, 2022 | SYSTEM | \$1,560.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 2 | Jul 16, 2022 | SYSTEM | (\$1,560.00) | |
| | | | | | 3 | Aug 1, 2022 | SYSTEM | \$1,560.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 3 | Aug 1, 2022 | SYSTEM | (\$1,560.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0030 - | Total | | | | | | \$0.00 | |
| | 0040 | GRAVEL (A) OR CRUSHED STONE | Overrun | Overrun | 4 | Aug 15, 2022 | SYSTEM | (\$4,158.00) | |
| | | (B) | | Overrun - T | otal | | | (\$4,158.00) | |
| | | | Overrun - T | otal | | | | (\$4,158.00) | |
| | 0040 - | Total | | | | | | (\$4,158.00) | |
| | 0050 | BIT. PAVEMENT MIXTURE PG64-22 (BP-2) | Other Item Adjustment | ACAD | 3 | Aug 1, 2022 | ellisc2 | \$115,761.74 | 7/18: \$18,016.39 7/19: \$19,461.91 7/20: \$14,339.56 7/21: \$15,998.29 7/26: \$17,400.03 7/27: \$7,539.38 7/28: \$18,756.94 7/29: \$2,940.57 8/1: \$1,308.67 Total = \$115,761.74 |
| | | | | ACAD - Tota | al | | | \$115,761.74 | |
| | | | Other Item | Adjustment - | Total | | | \$115,761.74 | |
| | 0050 - | Total | | | | | | \$115,761.74 | |
| | 0060 | BITUMINOUS PAVEMENT MIXTURE | Other Item Adjustment | ACAD | | Jul 16, 2022 | ellisc2 | \$66.59 | 7/12: \$ 66.59 |
| | | PG64-22 (BAS | | ACAD - Total | al | | | \$66.59 | |
| | | | Other Item | Adjustment - | Total | | | \$66.59 | |
| | 0060 - | | | | | | | \$66.59 | |
| | 0070 | MISC. | Other Item Adjustment | ACAD | 2 | Jul 16, 2022 | ellisc2 | \$66,410.22 | 7/7: \$10,003.24 7/11: \$8,731.54 |
| | | | | | | | | | 7/12: \$14,224.22 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$66,410.22 |
| | | | | | 3 | Aug 1, 2022 | ellisc2 | \$66.59 | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 |
| | | | | ACAD - Tota | | | ellisc2 | \$66.59 \$66,476.81 | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$66,410.22 |
| | | | Other Item . | ACAD - Tot Adjustment - | al | | ellisc2 | | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$66,410.22 |
| | 0070 - | · Total | Other Item | | al | | ellisc2 | \$66,476.81 | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$66,410.22 |
| | 0070 - | · Total TACK COAT | Other Item | | al | | ellisc2 | \$66,476.81 \$66,476.81 | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$66,410.22 |
| | | | | | al Total | 2022 Jul 17, | | \$66,476.81 \$66,476.81 \$66,476.81 | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$66,410.22 7/12 payment error correction \$66.59 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment |
| | | | | | al Total 2 | Jul 17, 2022 Jul 16, | SYSTEM | \$66,476.81 \$66,476.81 \$66,476.81 \$2,125.00 | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$66,410.22 7/12 payment error correction \$66.59 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment |
| | | | | | Total 2 | Jul 17, 2022 Jul 16, 2022 Aug 1, | SYSTEM | \$66,476.81 \$66,476.81 \$66,476.81 \$2,125.00 (\$2,125.00) | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$ 66,410.22 7/12 payment error correction \$66.59 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment |
| | | | | | Total 2 2 3 | Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 Aug 1, | SYSTEM SYSTEM | \$66,476.81 \$66,476.81 \$66,476.81 \$2,125.00 (\$2,125.00) \$30,715.00 | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$ 66,410.22 7/12 payment error correction \$66.59 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment |
| | | | | | Total 2 2 3 3 | Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 Aug 1, 2022 | SYSTEM SYSTEM SYSTEM | \$66,476.81 \$66,476.81 \$66,476.81 \$2,125.00 (\$2,125.00) \$30,715.00 | 7/13: \$17,179.36 7/14: \$7,354.17 7/15: \$8,917.69 Total: \$66,410.22 7/12 payment error correction \$66.59 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate. |



| | Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks | | | |
|---------|--------------------|---|--------------------|---------------------|------------------|---|------------------------------------|---|---|--|--|--|
| J9S3651 | 0080 | TACK COAT | Material | Туре | | 2022 | | | Estimate Item Adjustment (0006) due to user ellisc2 overridding Payment | | | |
| | | | | | 5 | Sep 1, | SYSTEM | (\$30,715.00) | Estimate Exception 1 on the current Payment Estimate. | | | |
| | | | | | 6 | 2022 San 46 | SYSTEM | \$30,715.00 | This adjustment offsets the original system generated Material Dayment | | | |
| | | | | | 0 | Sep 16, 2022 | STSTEM | \$30,715.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | (\$30,715.00) | | | | |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | \$30,715.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user ellisc2 overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | (\$30,715.00) | | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | |
| | 0080 - | | | | | | | \$0.00 | | | | |
| | 0110 | CONSTRUCTION SIGNS | Material | | 2 | Jul 17, 2022 | SYSTEM | \$2,220.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | |
| | | | | | 2 | Jul 16, 2022 | SYSTEM | (\$2,220.00) | | | | |
| | | | | | 3 | Aug 1, 2022 | SYSTEM | \$4,540.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | |
| | | | | | 3 | Aug 1, 2022 | SYSTEM | (\$4,540.00) | | | | |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | \$5,225.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | (\$5,225.00) | | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | | | | | | ψ0.00 | | | | |
| | | | Material - To | otal | | | | \$0.00 | | | | |
| | 0110 - | · Total | Material - To | otal | | | | | | | | |
| | 0110 - 0130 | CHANNELIZER (TRIM LINE) | | otal | 2 | Jul 17, 2022 | SYSTEM | \$0.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | |
| | | CHANNELIZER | | otal | 2 | | SYSTEM | \$0.00 \$0.00 | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment | | | |
| | | CHANNELIZER | | otal | | 2022 Jul 16, | | \$0.00 \$0.00 \$220.00 | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment | | | |
| | | CHANNELIZER | | otal | 2 | Jul 16, 2022 Aug 1, | SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment | | | |
| | | CHANNELIZER | | otal | 3 | Jul 16, 2022 Aug 1, 2022 Aug 1, | SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) \$220.00 | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment | | | |
| | | CHANNELIZER | | otal | 3 | 2022 Jul 16, 2022 Aug 1, 2022 Aug 1, 2022 Aug 15, | SYSTEM SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) \$220.00 | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment | | | |
| | | CHANNELIZER | | - Total | 2 3 3 4 | 2022 Jul 16, 2022 Aug 1, 2022 Aug 1, 2022 Aug 15, 2022 | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) \$220.00 (\$220.00) | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment | | | |
| | | CHANNELIZER | | - Total | 2 3 3 4 | 2022 Jul 16, 2022 Aug 1, 2022 Aug 1, 2022 Aug 15, 2022 | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) \$220.00 (\$220.00) \$275.00 | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment | | | |
| | | CHANNELIZER (TRIM LINE) | Material | - Total | 2 3 3 4 | 2022 Jul 16, 2022 Aug 1, 2022 Aug 1, 2022 Aug 15, 2022 | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) \$220.00 (\$220.00) \$275.00 (\$275.00) | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment | | | |
| | 0130 | CHANNELIZER (TRIM LINE) Total CMS W/O COMMUNICATION INTERFACE, | Material | - Total | 2 3 3 4 | 2022 Jul 16, 2022 Aug 1, 2022 Aug 1, 2022 Aug 15, 2022 | SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) \$220.00 (\$220.00) \$275.00 (\$275.00) \$0.00 | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment | | | |
| | 0130 | CHANNELIZER (TRIM LINE) Total CMS W/O COMMUNICATION | Material - To | - Total | 2 3 3 4 | 2022 Jul 16, 2022 Aug 1, 2022 Aug 17, 2022 Aug 15, 2022 Jul 15, 2022 | SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) \$220.00 (\$220.00) \$275.00 (\$275.00) \$0.00 \$0.00 | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment | | | |
| | 0130 | CHANNELIZER (TRIM LINE) Total CMS W/O COMMUNICATION INTERFACE, | Material - To | - Total | 2 3 3 4 4 4 | 2022 Jul 16, 2022 Aug 1, 2022 Aug 15, 2022 Aug 15, 2022 Jul 17, 2022 Jul 16, | SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$0.00 \$0.00 \$220.00 (\$220.00) \$220.00 (\$220.00) \$275.00 (\$275.00) \$0.00 \$0.00 \$10,360.00 | Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment Estimate Exception 3 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment Estimate Item Adjustment (0010) due to user ellisc2 overridding Payment | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---|--------------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J9S3651 | 0160 | CMS W/O COMMUNICATION INTERFACE, CONT F/ | Material | | 4 | Aug 15, 2022 | SYSTEM | \$10,360.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | (\$10,360.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0160 - | Total | | | | | | \$0.00 | |
| | 0190 | 4 IN. WHITE WATERBORNE PAVEMENT | Material | | 5 | Sep 1, 2022 | SYSTEM | \$9,856.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | MARKING | | | 5 | Sep 1, 2022 | SYSTEM | (\$9,856.00) | |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | \$9,856.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | (\$9,856.00) | |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | \$9,856.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ellisc2 overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | (\$9,856.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | | | Other Item Adjustment | | 5 | Sep 2, 2022 | ellisc2 | (\$1,971.20) | \$9856.00 paid, 20% with held for reflectivity results |
| | | | | | 7 | Sep 30, 2022 | ellisc2 | \$1,971.20 | Payment of 20% withholding for reflectivity results |
| | | | | | 7 | Sep 30, 2022 | ellisc2 | \$492.80 | Retro reflectivity results 105% bonus |
| | | | | REFL - Total | | | | \$492.80 | |
| | | | Other Item | her Item Adjustment - Total | | | | | |
| | | | Overrun | Overrun | 5 | Sep 1, 2022 | SYSTEM | (\$203.06) | |
| | | | | Overrun - T | otal | | | (\$203.06) | |
| | | | Overrun - Total | | | | | (\$203.06) | |
| | 0190 - | Total | | | | | | \$289.74 | |
| | 0200 | 4 IN. YELLOW WATERBORNE PAVEMENT | | rial | 5 | Sep 1, 2022 | SYSTEM | \$3,721.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | MARKING | | | 5 | Sep 1, 2022 | SYSTEM | (\$3,721.19) | |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | \$3,721.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | (\$3,721.19) | |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | \$3,721.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ellisc2 overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | (\$3,721.19) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | | | Other Item Adjustment | REFL | 5 | Sep 2, 2022 | ellisc2 | (\$744.24) | \$3721.19 paid, 20% with held for reflectivity results |
| | | | | | 7 | Sep 30, 2022 | ellisc2 | \$744.24 | Payment of 20% withholding for reflectivity results |
| | | | | | 7 | Sep 30, 2022 | ellisc2 | \$186.06 | Retro reflectivity results 105% bonus |
| | | | | REFL - Tota | ıl | | | \$186.06 | |



| | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | |
|---------|--------------------|---|-------------------------------------|-----------------------------|------------------------|---|---|--|---|--|--|--|
| J9S3651 | 0200 | 4 IN. YELLOW WATERBORNE PAVEMENT MARKING | Other Item | Adjustment - | Total | | | \$186.06 | | | | |
| | | | Overrun | Overrun | 5 | Sep 1, 2022 | SYSTEM | (\$379.39) | | | | |
| | | | | Overrun - T | otal | | | (\$379.39) | | | | |
| | | | Overrun - Total | | | | | | | | | |
| | 0200 - | · Total | | | | | | (\$193.33) | | | | |
| | 0220 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | Overrun | run Overrun | 3 | Aug 1, 2022 | SYSTEM | (\$184.00) | | | | |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | (\$322.00) | | | | |
| | | | | Overrun - T | otal | | | (\$506.00) | | | | |
| | | | Overrun - T | otal | | | | (\$506.00) | | | | |
| | 0220 - | · Total | | | | | | (\$506.00) | | | | |
| | 0250 | SEEDING - COOL SEASON GRASSES | Material | | 5 | Sep 1, 2022 | SYSTEM | \$21,870.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | |
| | | | | | 5 | Sep 1, 2022 | SYSTEM | (\$21,870.00) | | | | |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | \$21,870.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | (\$21,870.00) | | | | |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | \$21,870.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ellisc2 overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | (\$21,870.00) | | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | Material - Total | | | | | \$0.00 | | | | |
| | | | Other Item Adjustment | | 5 | Sep 2, | ellisc2 | (04.274.00) | | | | |
| | | | | OTHR | 5 | 2022 | CIIISOZ | (\$4,374.00) | \$21870 paid, 20% with held for acceptable growth | | | |
| | | | | OTHR | 6 | | ellisc2 | \$4,374.00 | \$21870 paid, 20% with held for acceptable growth Acceptable growth | | | |
| | | | | OTHR - Tota | 6 | 2022 Sep 16, | | , , , | | | | |
| | | | Adjustment | | 6 al | 2022 Sep 16, | | \$4,374.00 | | | | |
| | 0250 - | - Total | Adjustment | OTHR - Tota | 6 al | 2022 Sep 16, | | \$4,374.00 \$0.00 | | | | |
| | 0250 - 0260 | Total ROCK DITCH CHECK | Adjustment | OTHR - Tota | 6 al | 2022 Sep 16, | | \$4,374.00 \$0.00 \$0.00 | | | | |
| | | ROCK DITCH | Adjustment Other Item | OTHR - Tota | 6 al Total | 2022 Sep 16, 2022 Jul 17, | ellisc2 | \$4,374.00 \$0.00 \$0.00 \$0.00 | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment | | | |
| | | ROCK DITCH | Adjustment Other Item | OTHR - Tota | 6 al Total | 2022 Sep 16, 2022 Jul 17, 2022 Jul 16, | ellisc2 | \$4,374.00 \$0.00 \$0.00 \$0.00 \$2,800.00 | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment | | | |
| | | ROCK DITCH | Adjustment Other Item | OTHR - Tota | 6 Total 2 | 2022 Sep 16, 2022 Jul 17, 2022 Jul 16, 2022 Aug 1, | ellisc2 SYSTEM SYSTEM | \$4,374.00 \$0.00 \$0.00 \$0.00 \$2,800.00 (\$2,800.00) | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment | | | |
| | | ROCK DITCH | Adjustment Other Item | OTHR - Tota | 6 Total 2 2 3 | 2022 Sep 16, 2022 Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 | ellisc2 SYSTEM SYSTEM SYSTEM | \$4,374.00 \$0.00 \$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00 | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment | | | |
| | | ROCK DITCH | Adjustment Other Item | OTHR - Tota | 6 al Total 2 2 3 3 3 | Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 Aug 15, | ellisc2 SYSTEM SYSTEM SYSTEM SYSTEM | \$4,374.00 \$0.00 \$0.00 \$0.00 \$2,800.00 (\$2,800.00) (\$2,800.00) | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user ellisc2 overridding Payment | | | |
| | | ROCK DITCH | Adjustment Other Item | OTHR - Tota | 6 al Total 2 2 3 3 4 | 2022 Sep 16, 2022 Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 Aug 15, 2022 Aug 15, | ellisc2 SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,374.00 \$0.00 \$0.00 \$2,800.00 \$2,800.00 \$2,800.00 (\$2,800.00) \$2,800.00 | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user ellisc2 overridding Payment | | | |
| | | ROCK DITCH | Adjustment Other Item | OTHR - Tota Adjustment - | 6 al Total 2 2 3 3 4 | 2022 Sep 16, 2022 Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 Aug 15, 2022 Aug 15, | ellisc2 SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,374.00 \$0.00 \$0.00 \$2,800.00 \$2,800.00 (\$2,800.00) \$2,800.00 (\$2,800.00) | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user ellisc2 overridding Payment | | | |
| | 0260 | ROCK DITCH | Other Item | OTHR - Tota Adjustment - | 6 al Total 2 2 3 3 4 | 2022 Sep 16, 2022 Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 Aug 15, 2022 Aug 15, | ellisc2 SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,374.00 \$0.00 \$0.00 \$2,800.00 \$2,800.00 \$2,800.00 (\$2,800.00) \$2,800.00 \$2,800.00 | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user ellisc2 overridding Payment | | | |
| | 0260 | ROCK DITCH CHECK | Other Item Material Material - To | OTHR - Tota Adjustment - | 6 al Total 2 2 3 3 4 | 2022 Sep 16, 2022 Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 Aug 15, 2022 Aug 15, | ellisc2 SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,374.00 \$0.00 \$0.00 \$2,800.00 \$2,800.00 \$2,800.00 \$2,800.00 \$2,800.00 \$2,800.00 | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user ellisc2 overridding Payment | | | |
| | 0260 | ROCK DITCH CHECK | Other Item Material Material - To | OTHR - Tota Adjustment - | 6 al Total 2 2 3 3 4 4 | Jul 17, 2022 Jul 16, 2022 Aug 1, 2022 Aug 15, 2022 Jul 15, 2022 Jul 17, 2022 | ellisc2 SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM | \$4,374.00 \$0.00 \$0.00 \$0.00 \$2,800.00 (\$2,800.00) \$2,800.00 (\$2,800.00) \$2,800.00 \$0.00 \$0.00 | Acceptable growth This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user ellisc2 overridding Payment Estimate Exception 5 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Exception 5 on the current Payment Estimate. | | | |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks |
|---------|--------|-------------------------------|---------------|--------------------|--------|-----------------|---------|---------------|---|
| | | | Туре | Adjustment Type | Number | Date | Ву | | |
| J9S3651 | 0270 | ALTERNATE DITCH CHECK | Material | | | 2022 | | | Estimate Item Adjustment (0008) due to user ellisc2 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 3 | Aug 1, 2022 | SYSTEM | (\$12,540.00) | |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | \$12,540.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | (\$12,540.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | l - Total | | | | \$0.00 | |
| | | | Overrun | Overrun | 2 | Jul 16, 2022 | SYSTEM | (\$9,240.00) | |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | \$9,240.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',11.00000 - 11.00000, 'is applied (if non-zero). |
| | | | | Overrun - T | otal | | | \$0.00 | |
| | | | Overrun - T | otal | | | | \$0.00 | |
| | 0270 - | Total | | | | | | \$0.00 | |
| | 0300 | SILT FENCE | Material | | 2 | Jul 17, 2022 | SYSTEM | \$29,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 2 | Jul 16, 2022 | SYSTEM | (\$29,100.00) | |
| | | | | | 3 | Aug 1, 2022 | SYSTEM | \$29,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 3 | Aug 1, 2022 | SYSTEM | (\$29,100.00) | |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | \$29,100.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user ellisc2 overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | (\$29,100.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | - Total | | | | \$0.00 | |
| | | | Overrun | Overrun | 2 | Jul 16, 2022 | SYSTEM | (\$25,350.00) | |
| | | | | | 4 | Aug 15, 2022 | SYSTEM | \$25,350.00 | Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',3.75000 - 3.75000, 'is applied (if non-zero). |
| | | | | | 5 | Sep 1, 2022 | SYSTEM | (\$675.00) | |
| | | | | Overrun - Total | | | | (\$675.00) | |
| | | | Overrun - T | | | | | (\$675.00) | |
| | 0300 - | Total | | | | | | (\$675.00) | |
| | 0350 | SHF-FLAT SHEET FLUORESCENT | Material | | 5 | Sep 1, 2022 | SYSTEM | \$960.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user ellisc2 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 5 | Sep 1, 2022 | SYSTEM | (\$960.00) | |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | \$960.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | (\$960.00) | |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | \$960.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ellisc2 overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | (\$960.00) | , -, |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | | | | | \$0.00 | |
| | | | | | | | | | |





| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------|--------------|--------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|--|
| J9S3651 | 0350 - | Total | | | | | | \$0.00 | |
| | 0360 | MISC. CONCRETE CONSTRUCTION | Material | terial | 5 | Sep 1, 2022 | SYSTEM | \$25,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 5 | Sep 1, 2022 | SYSTEM | (\$25,600.00) | |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | \$25,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 6 | Sep 16, 2022 | SYSTEM | (\$25,600.00) | |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | \$25,600.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user ellisc2 overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 7 | Sep 30, 2022 | SYSTEM | (\$25,600.00) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - To | otal | | | | \$0.00 | |
| | 0360 - Total | | | | | | | | |
| J9S3651 | - Total | | | | | | | \$177,062.55 | |
| Overall - | Total | | | | | | | \$177,062.55 | |