

Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 29, 2022

| Progress Estimate Number | Contract ID | 211217-B06 | Pay Period Start December 16, 2022 Original Contract | Amount \$2,035,102.58 | |
|--------------------------|-----------------|------------------------------------|------------------------------------------------------|------------------------------|--|
| 14 | Prime Contracto | or S & A Equipment & Builders, LL0 | C Pay Period End December 29, 2022 Net Change Orde | r Amount \$3,962.11 | |
| 1-7 | | | Current Contract | Amount \$2,039,064.69 | |

| Approval Date | | | | | | | | |
|--------------------------|--|------------------------------------------------------------------------------------------|--------------------------------------------------------|------------------------------------------|--------|--|--|--|
| December 29, 2022 | | Generated and | d Approved (and should be consider | ed Draft) at the Project Office Level by | vierss | | | |
| December 29, 2022 | | Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by | | | | | | |
| January 4, 2023 | | Reviewed and Approved at the Central Office Controllers Office Level by | | | | | | |
| Original Completion Date | | Current Completion Date | Date Actual Completion Date % of Current Contract Amou | | | | | |

| Original Completion Date | Current Completion Date | Actual Completion Date | % of Current Contract Amount Complete | | | | |
|--------------------------|-------------------------|------------------------|---------------------------------------|--|--|--|--|
| November 1, 2022 | November 1, 2022 | November 10, 2022 | 98.43% | | | | |

| | Milestones | | |
|------------------------|--------------------------|--------------------------------|----------------------------------|
| Date Description | Original Completion Date | Current Completion Date | No Milestones Exist for Contract |
| Acceptance Date | November 10, 2022 | November 10, 2022 | |
| Awarded Date | January 5, 2022 | January 5, 2022 | |
| Letting Date | December 17, 2021 | December 17, 2021 | |
| Notice to Proceed Date | February 7, 2022 | February 7, 2022 | |
| Open to Traffic Date | | | |
| Work Began Date | June 24, 2022 | June 24, 2022 | |

| Contract Total Pay For Estimate No. 14 | | | | | | | | | |
|----------------------------------------|----------------------------|---------------|----------------|----------------|--|--|--|--|--|
| | | This Estimate | Previous | To Date | | | | | |
| 211217-B06 | | | | | | | | | |
| | Total Posted Items Pay | \$1,531.92 | \$2,005,604.80 | \$2,007,136.72 | | | | | |
| | Gross Item Adjustments | \$165.97 | (\$200,024.85) | (\$199,858.88) | | | | | |
| | Incentive | \$0.00 | \$0.00 | \$0.00 | | | | | |
| | Disincentive | \$0.00 | \$0.00 | \$0.00 | | | | | |
| | Liquidated Damage | (\$24,450.00) | \$0.00 | (\$24,450.00) | | | | | |
| | Other Contract Adjustments | \$55,300.00 | (\$55,300.00) | \$0.00 | | | | | |
| | | | \$1,750,279.95 | \$1,782,827.84 | | | | | |
| Contract Total Pa | yable This Estimate: | \$32,547.89 | | | | | | | |

Items Paid This Estimate Period

| Project Number | Line Number | Item Code | Item Description | Unit | Unit Price | Current Installed Qty | Current Installed Amount | | |
|-------------------|-------------------------|--------------|-----------------------------------------------------------------------|------|---------------|--------------------------|-----------------------------|--|--|
| J2S3369 | 0340 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.260 | 2,591 | \$673.66 | | |
| | 0350 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | LF | \$0.260 | 3,301 | \$858.26 | | |
| Project J2S3 | Project J2S3369 - Total | | | | | | | | |
| Overall - Total | | | | | | | | | |

Contract Adjustments This Estimate

| Adj Type | Entered By | Comments | Time Units | Rate | Amount |
|-----------------|------------|-----------------------------------------------------|------------|----------|---------------|
| | vierss | Charging 6 days of RUC for November 2, 3, 7-10. | -25.60 | \$750.00 | (\$19,200.00) |
| | vierss | returning anticipated LD's on estimate 10 | | | \$31,600.00 |
| | vierss | Charging 7 days Admin Costs for November 2-4, 7-10. | -7 | \$750.00 | (\$5,250.00) |
| | vierss | returning incorrectly charged LD's on estimate 11 | | | \$23,700.00 |
| Overall - Total | | | | | \$30,850.00 |

\$30,850.00 These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments

ine Item Adjustments This Estimate

Revision 4/1/2020 Page 1 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 29, 2022

Progress Estimate Number
14

Contract ID 211217-B06 Pay Period Start December 16, 2022 Original Contract Amount \$2,035,102.58
Prime Contractor S & A Equipment & Builders, LLC Pay Period End December 29, 2022 Net Change Order Amount \$3,962.11
Current Contract Amount \$2,039,064.69

| | | | | | G | urrent Contra | act Amount | \$2,039,064.69 |
|------|-----------------------------------------|----------------------------------------------------------------------------------|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|---------------------------------------|-------------------|
| | ine Io. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| 9 00 | 060 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | Material | | | -10,844 | \$7.38 | (\$80,028.72 |
| 00 | 060 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. | 10,844 | \$7.38 | \$80,028.72 |
| 00 | 070 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | | -85.2 | \$48.56 | (\$4,137.31 |
| 00 | 070 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. | 85.2 | \$48.56 | \$4,137.31 |
| 01 | 110 | MISC. | Material | | | -10,128 | \$63.67 | (\$644,849.76 |
| 01 | 110 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. | 10,128 | \$63.67 | \$644,849.76 |
| 01 | 150 | CONCRETE PAVEMENT (8 IN. NON-REINF) | Material | | | -626 | \$77.52 | (\$48,527.52 |
| | CONCRETE PAVEMENT (8 IN. NON-REINF) | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 5 on the current Payment Estimate. | 626 | \$77.52 | \$48,527.52 | |
| 02 | 290 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | | -120 | \$25.24 | (\$3,028.80) |
| 02 | 290 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 7 on the current Payment Estimate. | 120 | \$25.24 | \$3,028.80 |
| 03 | 330 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | | -349 | \$6.31 | (\$2,202.19) |
| 03 | 330 | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. | 349 | \$6.31 | \$2,202.19 |
| 03 | 340 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -12,955 | \$0.26 | (\$3,368.30) |
| 03 | 340 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate. | 12,955 | \$0.26 | \$3,368.30 |
| 03 | 340 | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | Retroreflectivity Adjustment | | | | \$112.33 |
| 03 | 350 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -16,505 | \$0.26 | (\$4,291.30) |

Revision 4/1/2020 Page 2 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: December 29, 2022

Progress Estimate Number
14 Contract ID 211217-B06 Pay Period Start December 16, 2022 Original Contract Amount \$2,035,102.58
Prime Contractor S & A Equipment & Builders, LLC Pay Period End December 29, 2022 Net Change Order Amount \$3,962.11
Current Contract Amount \$2,039,064.69

| | | | | | | arrent Contra | ici Amount | \$2,039,004.09 |
|-------------------|-------------|---------------------------------------------------------------------------------|--------------------------|----------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|---------------------------------------|-------------------|
| Project Number | Line No. | Item Description | Adjustment Type | Other Item Adjustment Type | Comments | Adjustment Quantity | Line Item Adjustment Unit Price | Adjustment amount |
| J2S3369 | 0350 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 12 on the current Payment Estimate. | 16,505 | \$0.26 | \$4,291.30 |
| | 0350 | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Other Item Adjustment | Retroreflectivity Adjustment | | | | \$53.64 |
| | 0360 | 24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | | -81 | \$12.62 | (\$1,022.22) |
| | 0360 | 24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. | 81 | \$12.62 | \$1,022.22 |
| | 0490 | MISC. | Material | | | -0.8 | \$8,940.18 | (\$7,152.14) |
| | 0490 | MISC. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. | 0.8 | \$8,940.18 | \$7,152.14 |
| | 0560 | 2 IN. PSST POST - 12 GA. | Material | | | -163 | \$13.94 | (\$2,272.22) |
| | 0560 | 2 IN. PSST POST - 12 GA. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. | 163 | \$13.94 | \$2,272.22 |
| | 0570 | POST ANCHOR FOR 2 IN. PSST - 7 GA. | Material | | | -42 | \$36.81 | (\$1,546.02) |
| | 0570 | POST ANCHOR FOR 2 IN. PSST - 7 GA. | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. | 42 | \$36.81 | \$1,546.02 |
| | 0580 | SH-FLAT SHEET | Material | | | -87 | \$19.20 | (\$1,670.40) |
| | 0580 | SH-FLAT SHEET | Material | | This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 20 on the current Payment Estimate. | 87 | \$19.20 | \$1,670.40 |
| Total | | | | | | | | \$165.97 |
| | | | | | | | | |

Revision 4/1/2020 Page 3 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

| | Contract Project Information | | | | | | | | | | |
|-------------------|------------------------------|----------------------------------------------------|-----------|-----------|-------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------|--|--|--|--|
| Project Number | Federal Proj. Number | Project Description | Route | County | | Location of Work | | | | | |
| J2S3369 | | Grading and pavement | BUS 63 | ADAIR | from Route 63 west outer ro | om Route 63 west outer road to Route 6 north junction in Kirksville | | | | | |
| Totals by J | Job Numb | ers | | | | | | | | | |
| J2S3369 | | ed Item Pay s Item Adjustn | | s Item Pa | This Estimate \$1,531.92 \$165.97 \$1,697.89 | Previous \$2,005,604.80 (\$200,024.85) \$1,805,579.95 | To Date \$2,007,136.72 (\$199,858.88) \$1,807,277.84 | | | | |
| | Liqui | ntive centive dated Damage r Contract Adj | | s | \$0.00 \$0.00 (\$24,450.00) \$55,300.00 | \$0.00 \$0.00 \$0.00 (\$55,300.00) | \$0.00 \$0.00 (\$24,450.00) \$0.00 | | | | |

Revision 4/1/2020 Page 4 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

| Exceptions (Discrepancies) This Estimate Period | | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|---------------|--------------|
| Exceptions / Discrepencies | Explanation | Entered By | Status |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 3040143, Project Item Line Number 0060, Material Set 304014396, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 3105002, Project Item Line Number 0070, Material Set 310500296, Material 1007T1ABLD - Agg Base Type 1 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLD is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 4019905, Project Item Line Number 0110, Material Set 401990596, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action Generic 0501CCPAEA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 4019905, Project Item Line Number 0110, Material Set 401990596, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 5021108, Project Item Line Number 0150, Material Set 502110896, Material 0501CCPA.A - Concrete, Pavement w/Air, Acceptance Action Generic 0501CCPA.A is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 5021108, Project Item Line Number 0150, Material Set 502110896, Material 0501CCPAEA - Concrete, Pavement HES w/Air, Acceptance Action Generic 0501CCPAEA is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6200015, Project Item Line Number 0290, Material Set 620001596, Material 1048PMPFWH - Performed Thermoplastic Marking Tape Wh, Acceptance Action Generic 1048PMPFWH is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6205906A, Project Item Line Number 0330, Material Set 6205906A96, Material 1048PMTRHBWBWH - Marking Paint Acrylic Watr HiBld White, Acceptance Action Generic 1048PMTRHBWBWH is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6205906A, Project Item Line Number 0330, Material Set 6205906A96, Material 1048PMRBEMTL - Reflective Glass Beads Type L Embedm Ctd, Acceptance Action Generic 1048PMRBEMTL is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6206000C, Project Item Line Number 0340, Material Set 6206000C96, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6206000C, Project Item Line Number 0340, Material Set 6206000C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6206001C, Project Item Line Number 0350, Material Set 6206001C96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6206001C, Project Item Line Number 0350, Material Set 6206001C96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6206125A, Project Item Line Number 0360, Material Set 6206125A96, Material 1048PMTRHBWBYL - Marking Paint Acrylic Watr HiBld Yellow, Acceptance Action Generic 1048PMTRHBWBYL is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6206125A, Project Item Line Number 0360, Material Set 6206125A96, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 6206125A, Project Item Line Number 0360, Material Set 6206125A96, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 8059901, Project Item Line Number 0490, Material Set 805990196, Material 0802MLST - Mulch Straw (Vegetative Mulch), Acceptance Action Generic 0802MLST is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 9031270A, Project Item Line Number 0560, Material Set 9031270A96, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 9031273, Project Item Line Number 0570, Material Set 903127396, Material 0903HSTS - Tubular Steel Sign Support, Acceptance Action Generic 0903HSTS is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Insufficient Materials: Project J2S3369, Item 9035004A, Project Item Line Number 0580, Material Set 9035004A96, Material 1042SM - Sign Material, Acceptance Action Generic 1042SM is insufficient. | No Remark was entered by Engineer | buckj | Overridden |
| Estimate Exception Type: Item Overrun: Contract 211217-B06, Contract Project J2S3369, Project Item Line Number 0150, Contract Line Item Number 0150, Item 5021108, Minor Item. | No Remark was entered by Engineer | buckj | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 211217-B06, Contract Project J2S3369, Project Item Line Number 0330, Contract Line Item Number 0330, Item 6205906A, Minor Item. | No Remark was entered by Engineer | buckj | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 211217-B06, Contract Project J2S3369, Project Item Line Number 0360, Contract Line Item Number 0360, Item 6206125A, Minor Item. | No Remark was entered by Engineer | buckj | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 211217-B06, Contract Project J2S3369, Project Item Line Number 0090, Contract Line Item Number 0090, Item 4011209, Minor Item. | No Remark was entered by Engineer | buckj | Acknowledged |
| Estimate Exception Type: Item Overrun: Contract 211217-B06, Contract Project J2S3369, Project Item Line Number 0130, Contract Line Item Number 0130, Item 4071007, Minor Item. | No Remark was entered by Engineer | buckj | Acknowledged |

Revision 4/1/2020 Page 5 of 20



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | port Generated date and can differ from the posted amo | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|----------|-------------|--------------|----------------------------------------------------------------------------------------------------|-----------------|------------------------|------------------------------|------|------------------------------------|--------------|--------------------------------------------------------------|
| 211217-B06 | J2S3369 | 0001 | 0010 | 2022010 | REMOVAL OF IMPROVEMENTS | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$219,180.17 | \$219,180.17 |
| | | 0001 | 0020 | 2031000 | CLASS A EXCAVATION | 4,267.00 | 0.00 | 4,267.00 | CUYD | 4,267.00 | \$22.74 | \$97,031.58 |
| | | 0001 | 0030 | 2036000 | COMPACTING EMBANKMENT | 1,058.00 | 0.00 | 1,058.00 | CUYD | 1,058.00 | \$6.08 | \$6,432.64 |
| | | 0001 | 0040 | 2063000 | CLASS 3 EXCAVATION | 75.00 | 0.00 | 75.00 | CUYD | 75.00 | \$24.57 | \$1,842.75 |
| | | 0001 | 0050 | 2101006A | SUBGRADE COMPACTION (6-INCH DEPTH) | 34.00 | 0.00 | 34.00 | 100F | 34.00 | \$435.37 | \$14,802.58 |
| | | 0001 | 0060 | 3040143 | TYPE 1 AGGREGATE FOR BASE (4 IN. THICK) | 11,234.00 | 0.00 | 11,234.00 | SQYD | 10,844.00 | \$7.38 | \$80,028.72 |
| | | 0001 | 0070 | 3105002 | GRAVEL (A) OR CRUSHED STONE (B) | 21.00 | 64.20 | 85.20 | TONS | 85.20 | \$48.56 | \$4,137.31 |
| | | 0001 | 0080 | 3109910 | MISC.Permanent Aggregate Edge Treatment | 48.00 | 0.00 | 48.00 | TONS | 48.00 | \$66.91 | \$3,211.68 |
| | | 0001 | 0090 | 4011209 | BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1) | 673.00 | 0.00 | 673.00 | TONS | 722.44 | \$136.73 | \$98,779.22 |
| | | 0001 | 0100 | 4013000 | BITUMINOUS PAVEMENT MIXTURE PG64-22 (BASE) | 46.00 | 0.00 | 46.00 | TONS | 34.82 | \$136.73 | \$4,760.94 |
| | | 0001 | 0110 | 4019905 | MISC.OPTIONAL PAVEMENT (8" CONCRETE OR 9.25" HMA) | 10,546.00 | 0.00 | 10,546.00 | SQYD | 10,128.00 | \$63.67 | \$644,849.76 |
| | | 0001 | 0120 | 4030103 | ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125C MIX) | 3,182.00 | 0.00 | 3,182.00 | TONS | 3,127.27 | \$136.73 | \$427,591.63 |
| | | 0001 | 0130 | 4071007 | TACK COAT - LOW OR NON-TRACKING | 2,803.00 | 0.00 | 2,803.00 | GAL | 3,491.00 | \$3.16 | \$11,031.56 |
| | | 0001 | 0140 | 4079912 | MISC.TACK COAT - POLYMER MODIFIED EMULSION MEMBRANE | 437.00 | 0.00 | 437.00 | GAL | 437.00 | \$15.78 | \$6,895.86 |
| | | 0001 | 0150 | 5021108 | CONCRETE PAVEMENT (8 IN. NON-REINF) | 582.00 | 0.00 | 582.00 | SQYD | 626.00 | \$77.52 | \$48,527.52 |
| | | 0001 | 0160 | 6042020 | ADJUSTING BASIN OR INLET | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$1,112.34 | \$1,112.34 |
| | | 0001 | 0170 | 6044011 | PIPE COLLAR, TYPE A | 3.00 | 0.00 | 3.00 | EA | 3.00 | \$966.77 | \$2,900.31 |
| | | 0001 | 0180 | 6044013 | PIPE COLLAR, TYPE C | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,045.54 | \$2,091.08 |
| | | 0001 | 0190 | 6049902 | MISC.REMOVE & RESET INLET GRATE & FRAME | 1.00 | 0.00 | 1.00 | EA | 0.00 | \$964.42 | \$0.00 |
| | | 0001 | 0200 | 6057000 | AGGREGATE DRAIN | 288.00 | 0.00 | 288.00 | LF | 288.00 | \$59.40 | \$17,107.20 |
| | | 0001 | 0210 | 6096010A | FURNISHING TYPE 1 ROCK DITCH LINER | 44.00 | 0.00 | 44.00 | CUYD | 44.00 | \$50.93 | \$2,240.92 |
| | | 0001 | 0220 | 6096041 | PLACING TYPE 1 ROCK DITCH LINER | 44.00 | 0.00 | 44.00 | CUYD | 44.00 | \$52.68 | \$2,317.92 |
| | | 0001 | 0230 | 6097000 | ROCK LINING | 9.00 | 0.00 | 9.00 | CUYD | 9.00 | \$132.51 | \$1,192.59 |
| | | 0001 | 0240 | 6161005 | CONSTRUCTION SIGNS | 596.00 | 0.00 | 596.00 | SQFT | 467.00 | \$7.10 | \$3,315.70 |
| | | 0001 | 0250 | 6161025 | CHANNELIZER (TRIM LINE) | 200.00 | 0.00 | 200.00 | EA | 200.00 | \$16.83 | \$3,366.00 |
| | | 0001 | 0260 | 6161030 | TYPE III MOVEABLE BARRICADE | 12.00 | 0.00 | 12.00 | EA | 10.00 | \$115.70 | \$1,157.00 |
| | | 0001 | 0270 | 6161098A | CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$7,099.56 | \$14,199.12 |
| | | 0001 | 0280 | 6181000 | MOBILIZATION | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$131,904.64 | \$131,904.64 |
| | | 0001 | 0290 | 6200015 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE | 124.00 | 0.00 | 124.00 | LF | 120.00 | \$25.24 | \$3,028.80 |
| | | 0001 | 0300 | 6200021 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, LEFT/RIGHT ARROW | 27.00 | 0.00 | 27.00 | EA | 27.00 | \$347.09 | \$9,371.43 |
| | | 0001 | 0310 | 6200024 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, STRAIGHT ARROW | 4.00 | 0.00 | 4.00 | EA | 4.00 | \$315.54 | \$1,262.16 |
| | | 0001 | 0320 | 6200030 | PREFORMED THERMOPLASTIC PAVEMENT MARKING, WORD (ONLY) | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$736.25 | \$1,472.50 |
| | | 0001 | 0330 | 6205906A | 12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS | 271.00 | 0.00 | 271.00 | LF | 349.00 | \$6.31 | \$2,202.19 |
| | | 0001 | 0340 | 6206000C | 4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 12,955.00 | 0.00 | 12,955.00 | LF | 12,955.00 | \$0.26 | \$3,368.30 |
| | | 0001 | 0350 | 6206001C | 4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 16,505.00 | 0.00 | 16,505.00 | LF | 16,505.00 | \$0.26 | \$4,291.30 |
| | | 0001 | 0360 | 6206125A | 24 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS | 74.00 | 0.00 | 74.00 | LF | 81.00 | \$12.62 | \$1,022.22 |
| | | 0001 | 0370 | 6209902 | MISC.helmeted bicyclist symbol | 10.00 | 0.00 | 10.00 | EA | 10.00 | \$525.89 | \$5,258.90 |
| | | 0001 | 0380 | 6221001 | COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS) | 3,068.00 | 0.00 | 3,068.00 | SQYD | 3,040.00 | \$5.26 | \$15,990.40 |
| | | 0001 | 0390 | 6224010 | MODIFIED COLDMILLING (DEPTH TRANSITIONS) | 1,025.00 | 0.00 | 1,025.00 | SQYD | 1,025.00 | \$14.73 | \$15,098.25 |
| | | 0001 | 0400 | 6274000 | CONTRACTOR FURNISHED SURVEYING AND STAKING | 1.00 | 0.00 | 1.00 | LS | 1.00 | \$36,812.52 | \$36,812.52 |
| | | 0001 | 0410 | 7250315A | 15 IN. PIPE GROUP B | 160.00 | 0.00 | 160.00 | LF | 160.00 | \$69.03 | \$11,044.80 |
| | | 0001 | 0420 | 7250318A | 18 IN. PIPE GROUP B | 60.00 | 0.00 | 60.00 | LF | 60.00 | \$90.24 | \$5,414.40 |
| | | 0001 | 0430 | 7261018 | 18 IN. PIPE GROUP A | 14.00 | 0.00 | 14.00 | LF | 14.00 | \$157.11 | \$2,199.54 |

Page 6 of 20 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

| Contract Nm.CONTRACT | Project No. | Category | Line No. | Item Code | Description | Bid Quantity | Net Change Order | Total Current Quantity | Unit | Total Posted Approved Qty | Unit Price | Total Value POSTED To Date (See report generated date) |
|-------------------------|----------------|-------------|-------------|---------------|---------------------------------------------------------|-----------------|------------------------|------------------------------|------|------------------------------------|------------|--------------------------------------------------------------|
| 211217-B06 | J2S3369 | 0001 | 0440 | 7261024 | 24 IN. PIPE GROUP A | 17.00 | 0.00 | 17.00 | LF | 17.00 | \$141.08 | \$2,398.36 |
| | | 0001 | 0450 | 7320015A | 15 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 1.00 | 0.00 | 1.00 | EA | 1.00 | \$967.36 | \$967.36 |
| | | 0001 | 0460 | 7320018A | 18 IN. OR ALLOWED SUBSTITUTE GROUP B FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$1,040.93 | \$2,081.86 |
| | | 0001 | 0470 | 7320618A | 18 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$724.19 | \$1,448.38 |
| | | 0001 | 0480 | 7320624A | 24 IN. OR ALLOWED SUBSTITUTE GROUP A FLARED END SECTION | 2.00 | 0.00 | 2.00 | EA | 2.00 | \$769.46 | \$1,538.92 |
| | | 0001 | 0490 | 8059901 | MISC.SEEDING - COOL SEASON | 1.00 | 0.00 | 1.00 | LS | 0.80 | \$8,940.18 | \$7,152.14 |
| | | 0001 | 0500 | 8061004 | SEDIMENT TRAP ROCK | 12.20 | 0.00 | 12.20 | CUYD | 12.20 | \$68.37 | \$834.11 |
| | | 0001 | 0510 | 8061006 | ALTERNATE DITCH CHECK | 200.00 | 339.00 | 539.00 | LF | 539.00 | \$11.04 | \$5,950.56 |
| | | 0001 | 0520 | 8061016 | SEDIMENT REMOVAL | 54.00 | 0.00 | 54.00 | CUYD | 0.00 | \$21.41 | \$0.00 |
| | | 0001 | 0530 | 8061017 | TEMPORARY SEEDING | 1.00 | 0.00 | 1.00 | ACRE | 1.00 | \$5,784.82 | \$5,784.82 |
| | | 0001 | 0540 | 8061019 | SILT FENCE | 1,400.00 | -1,150.00 | 250.00 | LF | 90.00 | \$2.52 | \$226.80 |
| | | 0040 | 0550 | 9031010 | CONCRETE FOOTINGS, EMBEDDED | 1.40 | 0.00 | 1.40 | CUYD | 1.30 | \$2,629.47 | \$3,418.31 |
| | | 0040 | 0560 | 9031270A | 2 IN. PSST POST - 12 GA. | 174.00 | 0.00 | 174.00 | LF | 163.00 | \$13.94 | \$2,272.22 |
| | | 0040 | 0570 | 9031273 | POST ANCHOR FOR 2 IN. PSST - 7 GA. | 45.00 | 0.00 | 45.00 | LF | 42.00 | \$36.81 | \$1,546.02 |
| | | 0040 | 0580 | 9035004A | SH-FLAT SHEET | 93.00 | 0.00 | 93.00 | SQFT | 87.00 | \$19.20 | \$1,670.40 |
| | Project J | 2S3369 - To | otal Value | Posted to D | Pate as of Report Generated Date | | | | | | | \$2,007,136.72 |
| 211217-B06 Ove | erall - Total | Value Pos | ted to Da | te as of Repo | ort Generated Date | | | | | | | \$2,007,136.72 |

Page 7 of 20 Revision 4/1/2020



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J2S3369

| Line Number | Item Code | Description | DWR Date | DWR Approval Date | | Units | Location | From Station/ Log Mile | | Offset/ Distance | Comments |
|----------------|--------------|------------------------------------------|-------------|-------------------------|----------|-------|----------|------------------------------|--------|---------------------|----------|
| 0340 | 6206000C | 4 IN. WHITE WATERBORNE PAVEMENT MARKING | 12/29/22 | 12/29/22 | 2,591.00 | LF | | 422+66.21 | 485+00 | | |
| 0350 | 6206001C | 4 IN. YELLOW WATERBORNE PAVEMENT MARKING | 12/29/22 | 12/29/22 | 3,301.00 | LF | 100% Pay | 422+66.21 | 485+00 | | |

The information below this line are details for Construction Signs (if applicable).

No Data Available

Revision 4/1/2020 Page 8 of 20



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | | |
|---------|--------|-------------------------------------------|--------------------|-----------------------------|----------------|-----------------|-----------------|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|-------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| J2S3369 | 0020 | CLASS A EXCAVATION | Price FUEL | | 3 | Jul 15, 2022 | SYSTEM | \$280.36 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | \$407.64 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | |
| | | | | | 6 | Sep 1, 2022 | SYSTEM | \$476.00 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | \$91.85 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | |
| | | | | - Total | | | | \$1,255.85 | | | | | |
| | | | Price FUEL - T | otal | | | | \$1,255.85 | | | | | |
| | 0020 - | Total | | | | | | \$1,255.85 | | | | | |
| | 0030 | COMPACTING EMBANKMENT | Material | | 6 | Sep 1, 2022 | SYSTEM | \$3,648.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 6 | Sep 1, 2022 | SYSTEM | (\$3,648.00) | , | | | | |
| | | | | | 7 | Sep 16, 2022 | SYSTEM | \$3,648.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 7 | Sep 16, 2022 | SYSTEM | (\$3,648.00) | , | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - Tota | | | | | \$0.00 | | | | | |
| | 0030 - | Total | | | | | | \$0.00 | | | | | |
| | 0050 | SUBGRADE COMPACTION (6- INCH DEPTH) | Material | Material | | 3 | Jul 15, 2022 | SYSTEM | \$4,789.07 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | |
| | | | | | | 3 | Jul 15, 2022 | SYSTEM | (\$4,789.07) | Estimate Exception 1 on the editorit 1 dynois Estimate. | | | |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | \$4,789.07 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user vierss overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | (\$4,789.07) | | | | | |
| | | | | | 5 | Aug 16, 2022 | SYSTEM | \$9,142.77 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 5 | Aug 16, 2022 | SYSTEM | (\$9,142.77) | | | | | |
| | | | | - Total | | | | \$0.00 | | | | | |
| | | | Material - Tota | | | | | \$0.00 | | | | | |
| | 0050 - | Total | | | | | | \$0.00 | | | | | |
| | 0060 | TYPE 1 AGGREGATE FOR BASE (4 IN. | Material | Material | Material | Material | Material | | 3 | Jul 15, 2022 | SYSTEM | \$18,036.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | THICK) | | | 3 | Jul 15, 2022 | SYSTEM | (\$18,036.72) | | | | | |
| | | | | | 6 | Sep 1, 2022 | SYSTEM | \$69,037.69 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | |
| | | | | | 6 | Sep 1, 2022 | SYSTEM | (\$69,037.69) | | | | | |
| | | | | | 7 | Sep 16, 2022 | SYSTEM | \$76,928.38 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | | |
| | | | | | 7 | Sep 16, 2022 | SYSTEM | (\$76,928.38) | | | | | |
| | | | | | 8 | Sep 30, 2022 | SYSTEM | \$79,039.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |
| | | | | | 8 | Sep 30, 2022 | SYSTEM | (\$79,039.80) | | | | | |
| | | | | | 9 | Oct 17, 2022 | SYSTEM | \$79,039.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|---------------------------------------|--------------------|-----------------------------|----------------|-----------------------------------------------------------------------------------|----------------------|--------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| J2S3369 | 0060 | TYPE 1 AGGREGATE | Material | | 9 | Oct 17, 2022 | SYSTEM | (\$79,039.80) | |
| | | FOR BASE (4 IN. THICK) | | | 10 | Nov 2, 2022 | SYSTEM | \$79,039.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 10 | Nov 2, 2022 | SYSTEM | (\$79,039.80) | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | \$79,039.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$79,039.80) | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$80,028.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$80,028.72) | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$80,028.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$80,028.72) | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | \$80,028.72 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | (\$80,028.72) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | | | Price FUEL | | 3 | Jul 15, 2022 | SYSTEM | \$630.55 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 5 | Aug 16, 2022 | SYSTEM | \$434.20 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 6 | Sep 1, 2022 | SYSTEM | \$799.36 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 7 | Sep 16, 2022 | SYSTEM | \$272.63 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 8 | Sep 30, 2022 | SYSTEM | \$72.96 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$34.57 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | | - Total | | | | \$2,244.27 | |
| | | | Price FUEL - 1 | Total | | | | \$2,244.27 | |
| | 0060 - | | | | | | | \$2,244.27 | |
| | 0070 | GRAVEL (A) OR CRUSHED STONE (B) | Material | | 3 | Jul 15, 2022 | SYSTEM | \$3,117.55 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | | 3 | Jul 15, 2022 | SYSTEM | (\$3,117.55) | |
| | | | | | | | | | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | \$4,137.31 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, | SYSTEM | \$4,137.31 (\$4,137.31) | Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | | | | | | Nov 15, 2022 Nov 15, | | | Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | | | | | 11 | Nov 15, 2022 Nov 15, 2022 Dec 1, | SYSTEM | (\$4,137.31) | Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | | | | | 11 12 | Nov 15, 2022 Nov 15, 2022 Dec 1, 2022 | SYSTEM SYSTEM | (\$4,137.31) \$4,137.31 | Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment |
| | | | | | 11 12 12 | Nov 15, 2022 Nov 15, 2022 Dec 1, 2022 Dec 1, 2022 Dec 15, | SYSTEM SYSTEM SYSTEM | (\$4,137.31) \$4,137.31 (\$4,137.31) | Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | | | |
|---------|--------|--------------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|--------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| J2S3369 | 0070 | GRAVEL (A) OR CRUSHED STONE | Material | | | D 00 | OVOTEM | (04.407.04) | Estimate Exception 2 on the current Payment Estimate. | | | |
| | | (B) | | | 14 | Dec 29, 2022 | SYSTEM | (\$4,137.31) | | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | 0050 | | Material - Tota | al | | | | \$0.00 | | | | |
| | | Total | | | 4.4 | N. 45 | OVOTEM | \$0.00 | | | | |
| | 0800 | MISC. GRAVEL OR CR. STONE | Material | | 11 | Nov 15, 2022 | SYSTEM | \$3,211.68 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$3,211.68) | | | | |
| | | | | - Total | | | | \$0.00 | | | | |
| | | | Material - Tota | al | | | | \$0.00 | | | | |
| | 0080 - | - Total | | | | | | \$0.00 | | | | |
| | 0090 | BIT. PAVEMENT MIXTURE PG64-22 (BP-1) | Overrun | Overrun | 10 | Nov 2, 2022 | SYSTEM | (\$6,909.30) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | |
| | | F G04-22 (BF-1) | | Overrun - T | otal | | | (\$6,909.30) | | | | |
| | | | Overrun - Tota | al | | | | (\$6,909.30) | | | | |
| | | | Price FUEL | | 10 | Nov 2, 2022 | SYSTEM | \$2,182.64 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | |
| | | | | - Total | | | | \$2,182.64 | | | | |
| | | | Price FUEL - 1 | Γotal | | | | \$2,182.64 | | | | |
| | 0090 - | Total | | | | | | (\$4,726.66) | | | | |
| | 0100 | | Price FUEL | | 10 | Nov 2, 2022 | SYSTEM | \$105.20 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | |
| | | | | - Total | | | | \$105.20 | | | | |
| | | | Price FUEL - 1 | Total | | | | \$105.20 | | | | |
| | 0100 - | Total | | | | | | \$105.20 | | | | |
| | 0110 | MISC. | Material | | 4 | Jul 29, 2022 | SYSTEM | (\$145,014.79) | | | | |
| | | | | | 5 | Aug 16, 2022 | SYSTEM | (\$311,664.65) | | | | |
| | | | | | 7 | Sep 16, 2022 | SYSTEM | \$663,785.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. | | | |
| | | | | | 7 | Sep 16, 2022 | SYSTEM | (\$663,785.22) | | | | |
| | | | | | 8 | Sep 30, 2022 | SYSTEM | \$670,285.92 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | |
| | | | | | 8 | Sep 30, 2022 | SYSTEM | (\$670,285.92) | | | | |
| | | | | | 9 | Oct 17, 2022 | SYSTEM | \$670,285.92 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | |
| | | | | | 9 | Oct 17, 2022 | SYSTEM | (\$670,285.92) | | | | |
| | | | | | 10 | Nov 2, 2022 | SYSTEM | \$670,285.92 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 2 on the current Payment Estimate. | | | |
| | | | | | 10 | Nov 2, 2022 | SYSTEM | (\$670,285.92) | | | | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | \$670,285.92 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate. | | | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$670,285.92) | | | | |
| | | | | | | | 12 | 12 | Dec 1, 2022 | SYSTEM | \$644,849.76 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user buckj overridding Payment |
| | | | | | | | | | Estimate Exception 3 on the current Payment Estimate. | | | |



| USS USS | Dreinst | Lina | Dogorintian | Adiuotesant | Other | Ect | Crostad | Crocted | Amerint | Domestra | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|--------|------------------------|--------------------|---------------|----------------|-----------------|---------------|----------------|-----------------------------------------------------------------------|--|--|--------|--|
| 2022 | Project | Line | Description | Adjustment Type | | Est. Number | Created Date | Created By | Amount | Remarks | | | | |
| 1 | J2S3369 | 0110 | MISC. | Material | | 13 | | SYSTEM | \$644,849.76 | Estimate Item Adjustment (0003) due to user buckj overridding Payment | | | | |
| 2022 14 | | | | | | 13 | | SYSTEM | (\$644,849.76) | | | | | |
| 1010 Total | | | | | | 14 | | SYSTEM | \$644,849.76 | Estimate Item Adjustment (0003) due to user buckj overridding Payment | | | | |
| Material - Total | | | | | | 14 | | SYSTEM | (\$644,849.76) | | | | | |
| Material Credit | | | | | - Total | | | | (\$456,679.44) | | | | | |
| 2002 1 9/9TEM 3311,694.05 10 10 10 10 10 10 10 | | | | Material - Tota | | | | | (\$456,679.44) | | | | | |
| 1010 - Total | | | | MaterialCredit | | 5 | | SYSTEM | \$145,014.79 | | | | | |
| Material Credit = Total Substitute Sub | | | | | | 6 | | SYSTEM | \$311,664.65 | | | | | |
| 110 Total | | | | | - Total | | | | \$456,679.44 | | | | | |
| 11 | | | | MaterialCredit | - Total | | | | \$456,679.44 | | | | | |
| CONCRETE MIXTURE PG 70-22 (SPT2SC MIX) | | 0110 - | Total | | | | | | \$0.00 | | | | | |
| 11 | | 0120 | CONCRETE MIXTURE PG | Material | | 11 | | SYSTEM | \$427,591.63 | Estimate Item Adjustment (0007) due to user buckj overridding Payment | | | | |
| 2022 Estimate Item Adjustment (0003) due to user buck) overridding Payment | | | | | | 11 | | SYSTEM | (\$427,591.63) | | | | | |
| Total S0.00 | | | | | | 12 | | SYSTEM | \$427,591.63 | Estimate Item Adjustment (0004) due to user buckj overridding Payment | | | | |
| Material - Total SUBI 10 Nov 2, vierss (\$203,201.29) 50% deduction due to incorrect oil grade used in the supplied mix. Additional test results are pending. SUBI - Total (\$203,201.29) (\$203,201.29) | | | | | | 12 | | SYSTEM | (\$427,591.63) | | | | | |
| Other Item Adjustment SUBI 10 Nov 2, 2022 vierss (\$203.201.29) 50% deduction due to incorrect oil grade used in the supplied mix. Additional test results are pending. SUBI - Total (\$203.201.29) | | | | | | | | | - Total | | | | \$0.00 | |
| Adjustment 2022 SYSTEM (\$203,201.29) | | | | Material - Total | | | | | \$0.00 | | | | | |
| Other Item Adjustment - Total | | | | | SUBI | 10 | | vierss | (\$203,201.29) | | | | | |
| Price FUEL | | | | | SUBI - Total | | | | (\$203,201.29) | | | | | |
| 2022 11 | | | | Other Item Ad | justment - To | tal | | | (\$203,201.29) | | | | | |
| Total S9,864.85 S9,864.8 | | | | Price FUEL | | 10 | | SYSTEM | \$8,979.91 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | |
| Price FUEL - Total \$9,864.85 | | | | | | 11 | | SYSTEM | \$884.94 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL | | | | |
| 10 | | | | | | | | | | | | | | |
| TACK COAT- LOW OR NON- TRACKING 10 | | | | Price FUEL - T | otal | | | | | | | | | |
| LOW OR NON-TRACKING | | 0120 - | Total | | | | | | (\$193,336.44) | | | | | |
| 2022 | | 0130 | LOW OR NON- | Material | | 10 | | SYSTEM | \$8,857.48 | Estimate Item Adjustment (0010) due to user buckj overridding Payment | | | | |
| 2022 Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 7 on the current Payment Estimate. | | | | | | 10 | | SYSTEM | (\$8,857.48) | | | | | |
| Description Continue | | | | | | 11 | | SYSTEM | \$11,031.56 | Estimate Item Adjustment (0009) due to user buckj overridding Payment | | | | |
| Material - Total | | | | | | 11 | | SYSTEM | (\$11,031.56) | | | | | |
| Overrun | | | | | - Total | | | | \$0.00 | | | | | |
| 2022 (\$2,174.08) | | | | Material - Tota | | | | | \$0.00 | | | | | |
| Overrun - Total (\$2,174.08) 0130 - Total (\$2,174.08) 0140 MISC. NON STANDARD TACK 10 Nov 2, SYSTEM \$6,895.86 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment | | | | Overrun | Overrun | 11 | | SYSTEM | (\$2,174.08) | | | | | |
| 0130 - Total 0140 MISC. NON STANDARD TACK 0140 MISC. NON STANDARD TACK 0140 MISC. NON STANDARD TACK 0150 MISC. NON STANDARD TACK 0160 MISC. NON STANDARD TACK 0170 Material System-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment | | | | | Overrun - To | otal | | | (\$2,174.08) | | | | | |
| 0140 MISC. NON Material 10 Nov 2, SYSTEM \$6,895.86 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment | | | | Overrun - Tota | ıl | | | | (\$2,174.08) | | | | | |
| STANDARD TACK 2022 Estimate Item Adjustment (0011) due to user buckj overridding Payment | | 0130 - | Total | | | | | | | | | | | |
| | | 0140 | STANDARD TACK | Material | | 10 | | SYSTEM | \$6,895.86 | Estimate Item Adjustment (0011) due to user buckj overridding Payment | | | | |



| t Lir | e Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-------|----------------------------------------------|--------------------|---------------------------------------|----------------|-----------------|---------------|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 9 014 | 0 MISC. NON STANDARD TACK | Material | , , , , , , , , , , , , , , , , , , , | 10 | Nov 2, 2022 | SYSTEM | (\$6,895.86) | |
| | COAT | | | 11 | Nov 15, 2022 | SYSTEM | \$6,895.86 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | 11 | Nov 15, 2022 | SYSTEM | (\$6,895.86) | |
| | | | - Total | | | | \$0.00 | |
| | | Material - Tota | ıl | | | | \$0.00 | |
| 014 | 0 - Total | | | | | | \$0.00 | |
| 01 | O CONCRETE PAVEMENT (8 IN. NON-REINF) | Material | | 8 | Sep 30, 2022 | SYSTEM | \$14,263.68 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 3 on the current Payment Estimate. |
| | | | | 8 | Sep 30, 2022 | SYSTEM | (\$14,263.68) | |
| | | | | 9 | Oct 17, 2022 | SYSTEM | \$14,263.68 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 9 | Oct 17, 2022 | SYSTEM | (\$14,263.68) | |
| | | | | 10 | Nov 2, 2022 | SYSTEM | \$14,263.68 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 10 | Nov 2, 2022 | SYSTEM | (\$14,263.68) | |
| | | | | 11 | Nov 15, 2022 | SYSTEM | \$14,263.68 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | | | 11 | Nov 15, 2022 | SYSTEM | (\$14,263.68) | |
| | | | | 12 | Dec 1, 2022 | SYSTEM | \$48,527.52 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | 12 | Dec 1, 2022 | SYSTEM | (\$48,527.52) | |
| | | | | 13 | Dec 15, 2022 | SYSTEM | \$48,527.52 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 13 | Dec 15, 2022 | SYSTEM | (\$48,527.52) | |
| | | | | 14 | Dec 29, 2022 | SYSTEM | \$48,527.52 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user buckj overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | 14 | Dec 29, 2022 | SYSTEM | (\$48,527.52) | |
| | | | - Total | | | | \$0.00 | |
| | | Material - Tota | ıl | | | | \$0.00 | |
| | | Overrun | Overrun | | Dec 1, 2022 | SYSTEM | (\$3,456.29) | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | Overrun - T | otal | | | (\$3,456.29) | |
| | | Overrun - Tota | al | | | | (\$3,456.29) | |
| | | Price FUEL | | 8 | Sep 30, 2022 | SYSTEM | \$187.68 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | | Total | 12 | Dec 1, 2022 | SYSTEM | \$456.14 | Reference Item Price Adjustment Index Adjustment Type applied is FUEL |
| | | Price FUEL - 1 | - Total | | | | \$643.82 \$643.82 | |
| 0.1 | i0 - Total | PIICE FUEL - | Otal | | | | (\$2,812.47) | |
| 013 | | Material | | 4 | Jul 29, 2022 | SYSTEM | \$1,933.54 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user vierss overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | 4 | Jul 29, 2022 | SYSTEM | (\$1,933.54) | , |
| | | | - Total | | | | \$0.00 | |



| oject | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-------|--------|------------------------------------------|--------------------|-----------------------------|------------------------|-----------------|---------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 3369 | 0170 | PIPE COLLAR, TYPE A | Material - Tota | | | | | \$0.00 | |
| | 0170 - | Total | | | | | | \$0.00 | |
| | 0180 | PIPE COLLAR, TYPE C | Material | | 4 | Jul 29, 2022 | SYSTEM | \$2,091.08 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vierss overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | (\$2,091.08) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0180 - | Total | | | | | | \$0.00 | |
| | 0200 | AGGREGATE DRAIN | Material | | 3 | Jul 15, 2022 | SYSTEM | \$5,346.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user buckj overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 3 | Jul 15, 2022 | SYSTEM | (\$5,346.00) | |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | \$5,346.00 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user vierss overridding Payment Estimate Exception 6 on the current Payment Estimate. |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | (\$5,346.00) | |
| | | | | | 5 | Aug 16, 2022 | SYSTEM | \$8,553.60 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user vierss overridding Payment Estimate Exception 4 on the current Payment Estimate. |
| | | | | | 5 | Aug 16, 2022 | SYSTEM | (\$8,553.60) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | l | | | | \$0.00 | |
| | 0200 - | Total | | | | | | \$0.00 | |
| | 0210 | FURNISHING TYPE 1 ROCK DITCH LINER | Material | | 11 | Nov 15, 2022 | SYSTEM | \$2,240.92 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 11 on the current Payment Estimate. |
| | | | | | 11 Nov 15, SYSTEM 2022 | | | (\$2,240.92) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | l | | | | \$0.00 | |
| | 0210 - | | | | | | | \$0.00 | |
| | 0230 | ROCK LINING | Material | | 11 | Nov 15, 2022 | SYSTEM | \$1,192.59 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$1,192.59) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0230 - | | | | | | | \$0.00 | |
| | 0240 | CONSTRUCTION SIGNS | Material | | 2 | Jul 1, 2022 | SYSTEM | (\$624.80) | |
| | | | | - Total | | | | (\$624.80) | |
| | | | Material - Tota | | | | | (\$624.80) | |
| | | | MaterialCredit | | 3 | Jul 15, 2022 | SYSTEM | \$624.80 | |
| | | | | - Total | | | | \$624.80 | |
| | | | MaterialCredit | - Total | | | | \$624.80 | |
| | 0240 - | | | | | | | \$0.00 | |
| | 0250 | CHANNELIZER (TRIM LINE) | Material | | 2 | Jul 1, 2022 | SYSTEM | (\$3,366.00) | |
| | | | | - Total | | | | (\$3,366.00) | |
| | | | Material - Tota | | | | | (\$3,366.00) | |
| | | | MaterialCredit | | 3 | Jul 15, 2022 | SYSTEM | \$3,366.00 | |
| | | | | - Total | | | | \$3,366.00 | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------|------------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| J2S3369 | 0250 | CHANNELIZER (TRIM LINE) | MaterialCredit | - Total | | | | \$3,366.00 | |
| | 0250 - | Total | | | | | | \$0.00 | |
| | 0270 | CMS W/O COMMUNICATION INTERFACE, | Material | | 1 | Jun 16, 2022 | SYSTEM | \$14,199.12 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user buckj overridding Payment Estimate Exception 1 on the current Payment Estimate. |
| | | CONT F/ | | | 1 | Jun 16, 2022 | SYSTEM | (\$14,199.12) | |
| | | | | | 2 | Jul 1, 2022 | SYSTEM | (\$14,199.12) | |
| | | | | - Total | | | | (\$14,199.12) | |
| | | | Material - Tota | l | | | | (\$14,199.12) | |
| | | | MaterialCredit | | 3 | Jul 15, 2022 | SYSTEM | \$14,199.12 | |
| | | | | - Total | | | | \$14,199.12 | |
| | | | MaterialCredit | - Total | | | | \$14,199.12 | |
| | 0270 - | Total | | | | | | \$0.00 | |
| | 0290 | PREF THERMO PVMT MARK, 24 IN WHIT | Material | | 11 | Nov 15, 2022 | SYSTEM | \$3,028.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 13 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$3,028.80) | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$3,028.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$3,028.80) | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$3,028.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$3,028.80) | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | \$3,028.80 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user buckj overridding Payment Estimate Exception 7 on the current Payment Estimate. |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | (\$3,028.80) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0290 - | Total | | | | | | \$0.00 | |
| | 0300 | PREF THERMO PVMT MARK, LT/RT ARROW | Material | | 11 | Nov 15, 2022 | SYSTEM | \$9,371.43 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$9,371.43) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | 0300 - | Total | | | | | | \$0.00 | |
| | 0310 | PREF THERMO PVMT MRKG, STRIAGHT | Material | | 11 | Nov 15, 2022 | SYSTEM | \$1,262.16 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | ARROW | | | 11 | Nov 15, 2022 | SYSTEM | (\$1,262.16) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | | | | \$0.00 | |
| | | Total | | | | | | \$0.00 | |
| | 0320 | PREF THERMO PVMT MARK, WORD (ONLY) | Material | | 11 | Nov 15, 2022 | SYSTEM | \$1,472.50 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user buckj overridding Payment Estimate Exception 16 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$1,472.50) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | I | | | | \$0.00 | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks | |
|---------|--------|---------------------------------------------------|--------------------------|-----------------------------|----------------|-----------------|---------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| J2S3369 | 0320 - | Total | | | | | | \$0.00 | | |
| | 0330 | 12 IN. WHITE HIGH BUILD WATERBORNE | Material | | 11 | Nov 15, 2022 | SYSTEM | \$2,202.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. | |
| | | PAINT | | | 11 | Nov 15, 2022 | SYSTEM | (\$2,202.19) | | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$2,202.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 9 on the current Payment Estimate. | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$2,202.19) | | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$2,202.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$2,202.19) | | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | \$2,202.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user buckj overridding Payment Estimate Exception 8 on the current Payment Estimate. | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | (\$2,202.19) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - Tota | | | | | \$0.00 | | |
| | | | Overrun | Overrun | 11 | Nov 15, 2022 | SYSTEM | (\$492.18) | | |
| | | | | Overrun - To | otal | | | (\$492.18) | | |
| | | | Overrun - Tota | | | | | (\$492.18) | | |
| | 0330 - | Total | | | | | | (\$492.18) | | |
| | 0340 | | Material | | 11 | Nov 15, 2022 | SYSTEM | \$2,694.64 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$2,694.64) | | |
| | | | | | | | | 12 | Dec 1, 2022 | SYSTEM |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$2,694.64) | | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$2,694.64 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$2,694.64) | | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | \$3,368.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user buckj overridding Payment Estimate Exception 10 on the current Payment Estimate. | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | (\$3,368.30) | | |
| | | | | - Total | | | | \$0.00 | | |
| | | | Material - Tota | l e | | | | \$0.00 | | |
| | | | Other Item Adjustment | REFL | 14 | Dec 29, 2022 | buckj | \$112.33 | | |
| | | | | REFL - Tota | I | | | \$112.33 | | |
| | | | Other Item Ad | justment - To | tal | | | \$112.33 | | |
| | 0340 - | | | | | | | \$112.33 | | |
| | 0350 | 4 IN. YELLOW WATERBORNE PAVEMENT MARKING | Material | | 11 | Nov 15, 2022 | SYSTEM | \$3,433.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user buckj overridding Payment Estimate Exception 21 on the current Payment Estimate. | |
| | | WARKING | | | 11 | Nov 15, 2022 | SYSTEM | (\$3,433.04) | | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$3,433.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 13 on the current Payment Estimate. | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$3,433.04) | | |
| | | | | | | | | | | |



| | | _ | | | | | | | |
|---------|--------|---------------------------------------------------|--------------------------|---------------------|----------------|-------------------------|---------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Project | Line | Description | Adjustment Type | Other Adjustment | Est. Number | Created Date | Created By | Amount | Remarks |
| J2S3369 | 0350 | 4 IN. YELLOW WATERBORNE | Material | Туре | 13 | Dec 15, 2022 | SYSTEM | \$3,433.04 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment |
| | | PAVEMENT MARKING | | | 13 | Dec 15, | SYSTEM | (\$3,433.04) | Estimate Exception 12 on the current Payment Estimate. |
| | | | | | 14 | 2022 Dec 29, 2022 | SYSTEM | \$4,291.30 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user buckj overridding Payment |
| | | | | | 14 | Dec 29, | SYSTEM | (\$4,291.30) | Estimate Exception 12 on the current Payment Estimate. |
| | | | | | | 2022 | | | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | | 4.4 | D 00 | | \$0.00 | |
| | | | Other Item Adjustment | REFL | | Dec 29, 2022 | buckj | \$53.64 | |
| | | | | REFL - Tota | | | | \$53.64 | |
| | | | Other Item Ad | justment - To | tal | | | \$53.64 | |
| | 0350 - | Total | | | | | | \$53.64 | |
| | 0360 | 24 IN. YELLOW WATERBORNE PAVEMENT MARKIN | Material | | 11 | Nov 15, 2022 | SYSTEM | \$1,022.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user buckj overridding Payment Estimate Exception 23 on the current Payment Estimate. |
| | | IVIZALINI | | | 11 | Nov 15, 2022 | SYSTEM | (\$1,022.22) | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$1,022.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 15 on the current Payment Estimate. |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$1,022.22) | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$1,022.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$1,022.22) | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | \$1,022.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user buckj overridding Payment Estimate Exception 14 on the current Payment Estimate. |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | (\$1,022.22) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | | | Overrun | Overrun | 11 | Nov 15, 2022 | SYSTEM | (\$88.34) | |
| | | | | Overrun - T | otal | | | (\$88.34) | |
| | | | Overrun - Tota | al | | | | (\$88.34) | |
| | 0360 - | Total | | | | | | (\$88.34) | |
| | 0370 | MISC. PAVEMENT MARKINGS | Material | | 11 | Nov 15, 2022 | SYSTEM | \$5,258.90 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0024) due to user buckj overridding Payment Estimate Exception 26 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$5,258.90) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | 0370 - | Total | | | | | | \$0.00 | |
| | 0450 | 15 IN. GROUP B FLARED END SEC | Material | | 4 | Jul 29, 2022 | SYSTEM | \$967.36 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user vierss overridding Payment Estimate Exception 8 on the current Payment Estimate. |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | (\$967.36) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | 1 | | | | \$0.00 | |
| | 0450 - | Total | | | | | | \$0.00 | |
| | 0470 | 18 IN. GROUP A FLARED END SECT | Material | | 4 | Jul 29, 2022 | SYSTEM | \$724.19 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user vierss overridding Payment Estimate Exception 9 on the current Payment Estimate. |
| | | OLOT | | | | | | | Louinate Endoption o on the outlone aymone Estimate. |



| Project | Line | Description | Adjustment | Other | Est. | Created | Created | Amount | Remarks | | |
|---------|--------|--------------------------------------|-----------------|--------------------|--------|-----------------|---------|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | | | Туре | Adjustment Type | Number | Date | Ву | | | | |
| J2S3369 | 0470 | 18 IN. GROUP A FLARED END SECT | Material | | 4 | Jul 29, 2022 | SYSTEM | (\$724.19) | | | |
| | | SECT | | - Total | | | | \$0.00 | | | |
| | | | Material - Tota | | | | | \$0.00 | | | |
| | 0470 - | · Total | | | | | | \$0.00 | | | |
| | 0480 | 24 IN. GROUP A FLARED END SECT | Material | | 4 | Jul 29, 2022 | SYSTEM | \$1,538.92 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user vierss overridding Payment Estimate Exception 10 on the current Payment Estimate. | | |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | (\$1,538.92) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - Tota | ıl | | | | \$0.00 | | | |
| | 0480 - | · Total | | | | | | \$0.00 | | | |
| | 0490 | MISC. SEEDING | Material | | 11 | Nov 15, 2022 | SYSTEM | \$7,152.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0025) due to user buckj overridding Payment Estimate Exception 27 on the current Payment Estimate. | | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$7,152.14) | | | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$7,152.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. | | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$7,152.14) | | | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$7,152.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. | | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$7,152.14) | | | |
| | | | | | | | 14 | Dec 29, 2022 | SYSTEM | \$7,152.14 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 17 on the current Payment Estimate. |
| | | | | | | | | | 14 | Dec 29, 2022 | SYSTEM |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - Tota | | | | | \$0.00 | | | |
| | 0490 - | ·Total | | | | | | \$0.00 | | | |
| | 0500 | SEDIMENT TRAP ROCK | Material | | 11 | Nov 15, 2022 | SYSTEM | \$834.11 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0026) due to user buckj overridding Payment Estimate Exception 28 on the current Payment Estimate. | | |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$834.11) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - Tota | ıl | | | | \$0.00 | | | |
| | 0500 - | Total | | | | | | \$0.00 | | | |
| | 0510 | ALTERNATE DITCH CHECK | Material | | 3 | Jul 15, 2022 | SYSTEM | \$5,950.56 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user buckj overridding Payment Estimate Exception 6 on the current Payment Estimate. | | |
| | | | | | 3 | Jul 15, 2022 | SYSTEM | (\$5,950.56) | | | |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | \$5,950.56 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vierss overridding Payment Estimate Exception 11 on the current Payment Estimate. | | |
| | | | | | 4 | Jul 29, 2022 | SYSTEM | (\$5,950.56) | | | |
| | | | | | 5 | Aug 16, 2022 | SYSTEM | \$5,950.56 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user vierss overridding Payment Estimate Exception 5 on the current Payment Estimate. | | |
| | | | | | 5 | Aug 16, 2022 | SYSTEM | (\$5,950.56) | | | |
| | | | | - Total | | | | \$0.00 | | | |
| | | | Material - Tota | | | | | \$0.00 | | | |
| | 0510 - | · Total | | | | | | \$0.00 | | | |
| | 0530 | TEMPORARY | Material | | 7 | Sep 16, | SYSTEM | \$5,784.82 | This adjustment offsets the original system-generated Material Payment | | |
| | | | | | | | | | | | |



| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|---------|--------------|------------------------------------------|--------------------|-----------------------------|----------------|-----------------|---------------|--------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| J2S3369 | 0530 | SEEDING | Material | | | 2022 | | | Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 5 on the current Payment Estimate. |
| | | | | | 7 | Sep 16, 2022 | SYSTEM | (\$5,784.82) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Tota | ıl | | | | \$0.00 | |
| | 0530 - | Total | | | | | | \$0.00 | |
| | 0550 | CONCRETE FOOTINGS, EMBEDDED | Material | | 11 | Nov 15, 2022 | SYSTEM | \$3,418.31 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0027) due to user buckj overridding Payment Estimate Exception 29 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$3,418.31) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 0550 - | ·Total | | | | | | \$0.00 | |
| | 0560 | 2 IN. PSST POST- 12 GA. | Material | | 11 | Nov 15, 2022 | SYSTEM | \$2,272.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0028) due to user buckj overridding Payment Estimate Exception 30 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$2,272.22) | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$2,272.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$2,272.22) | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$2,272.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$2,272.22) | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | \$2,272.22 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user buckj overridding Payment Estimate Exception 18 on the current Payment Estimate. |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | (\$2,272.22) | |
| | | | | - Total | | | | \$0.00 | |
| | | Material - Total | | | | | | \$0.00 | |
| | 0560 - | Total | | | | | | | |
| | 0570 | POST ANCHOR FOR 2 IN. PSST - 7 GA. | Material | | 11 | Nov 15, 2022 | SYSTEM | \$1,546.02 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0029) due to user buckj overridding Payment Estimate Exception 31 on the current Payment Estimate. |
| | | | | | 11 | Nov 15, 2022 | SYSTEM | (\$1,546.02) | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$1,546.02 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user buckj overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$1,546.02) | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$1,546.02 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$1,546.02) | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | \$1,546.02 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user buckj overridding Payment Estimate Exception 19 on the current Payment Estimate. |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | (\$1,546.02) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 0570 - Total | | | | | | | \$0.00 | |
| | 0580 | SH-FLAT SHEET | Material | | 11 | Nov 15, 2022 | SYSTEM | \$1,670.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0030) due to user buckj overridding Payment Estimate Exception 32 on the current Payment Estimate. |

Jan 5, 2023



Line Item Adjustments by Estimate

| Project | Line | Description | Adjustment Type | Other Adjustment Type | Est. Number | Created Date | Created By | Amount | Remarks |
|-----------------|---------|---------------|--------------------|-----------------------------|----------------|-----------------|---------------|----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| J2S3369 | 0580 | SH-FLAT SHEET | Material | | 11 | Nov 15, 2022 | SYSTEM | (\$1,670.40) | |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | \$1,670.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user buckj overridding Payment Estimate Exception 21 on the current Payment Estimate. |
| | | | | | 12 | Dec 1, 2022 | SYSTEM | (\$1,670.40) | |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | \$1,670.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 13 | Dec 15, 2022 | SYSTEM | (\$1,670.40) | |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | \$1,670.40 | This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user buckj overridding Payment Estimate Exception 20 on the current Payment Estimate. |
| | | | | | 14 | Dec 29, 2022 | SYSTEM | (\$1,670.40) | |
| | | | | - Total | | | | \$0.00 | |
| | | | Material - Total | | | | | \$0.00 | |
| | 0580 - | Total | | | | | | \$0.00 | |
| J2S3369 - | - Total | | | | | | | (\$199,858.88) | |
| Overall - Total | | | | | | | | (\$199,858.88) | |