#### Pay Estimate Created Date: November 17, 2022

Progress Estimate N 10		Contract ID Prime Contracto	211217-D01 r Capital Paving & Constru	Pay Period Start ction, LLC Pay Period End	November 2 November 1		Original Contract Amount Net Change Order Amount Current Contract Amount	\$14,336,218.81 (\$6,057.17) \$14,330,161.64
Approval Date								By User
November 18, 2022			Gene	erated and Approved (and should	l be considere	ed Draft)	at the Project Office Level by	webers1
November 18, 2022			Reviewed	I and Approved (and should be o	onsidered Dra	aft) at the	e Resident Engineer Level by	webers1
November 18, 2022				Reviewed and Appro	ved at the Cer	ntral Offic	ce Controllers Office Level by	ramses1
Original Complet	ion Date	Curre	ent Completion Date	Actual Completion Date	e	%	Complete	
November 1, 2	2022	N	lovember 1, 2022				98.60%	
	Contract In	formational Date	es	Milestones				
Date Description	Original Co	ompletion Date	Current Completion Date	No Milestones Exist for Contra	ct			
Acceptance Date								
Awarded Date	January 5, 2	2022	January 5, 2022					
Letting Date	December ?	17, 2021	December 17, 2021					
Notice to Proceed Date	March 7, 20	)22	March 7, 2022					
Open to Traffic Date								
Work Began Date								

### Contract Total Pay For Estimate No. 10

		This Estimate	Previous	To Date	
211217-D01					
	Total Posted Items Pay	\$44,690.99	\$14,085,415.96	\$14,130,106.95	
	Gross Item Adjustments	\$28,668.64	\$1,959,236.83	\$1,987,905.47	
	Incentive	\$0.00	\$511,079.96	\$511,079.96	
	Disincentive	\$0.00	(\$21,000.00)	(\$21,000.00)	
	Liquidated Damage	(\$14,000.00)	\$0.00	(\$14,000.00)	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	,		\$16,534,732.75	\$16,594,092.38	
Contract Total Payat	ole This Estimate:	\$59,359.63			

Items Paid This Estimate Period

Project Number	Line Number	Item Code		Item Description		Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5I3252	0040	2153000	SHAPING SLOPES, CLA	SS III		100F	\$623.000	-0.74	(\$461.02)
	0080	3107002	GRAVEL (A) OR CRUSH	ED STONE (B) OR CHAT (C)		TONS	\$41.840	-0.27	(\$11.30)
	0170	4071005	TACK COAT			GAL	\$2.200	1	\$2.20
	0270	6161005	CONSTRUCTION SIGNS	3		SQFT	\$7.500	502.07	\$3,765.53
	0290	6161025	CHANNELIZER (TRIM LI	NE)		EA	\$20.000	-4	(\$80.00)
	0310	6161033	DIRECTIONAL INDICAT	OR BARRICADE		EA	\$75.000	31	\$2,325.00
	0320	6161040	FLASHING ARROW PAN	IEL		EA	\$1,000.000	2	\$2,000.00
	0330	6161052	WARNING LIGHT, TYPE	В		EA	\$55.000	6	\$330.00
	0340	6161055	SEQUENTIAL FLASHING	G WARNING LIGHT		EA	\$95.000	41	\$3,895.00
	0350	6161099	CHANGEABLE MESSAG FURNISHED, CONTRAC	E SIGN WITH COMMUNICATION I	NTERFACE, CONTRACTOF	R EA	\$3,200.000	1	\$3,200.00
	0370	6200015	PREFORMED THERMO	PLASTIC PAVEMENT MARKING, 24	4 IN. WHITE	LF	\$18.000	299	\$5,382.00
	0380	6200018	PREFORMED THERMO	PLASTIC PAVEMENT MARKING, 24	4 IN. YELLOW	LF	\$18.000	53	\$954.00
	0390	6205902A	6 IN. WHITE HIGH BUILD	D WATERBORNE PAVEMENT MAR	KING PAINT, TYPE L BEAD	DS LF	\$0.210	18,324	\$3,848.04
	0400	6205903A	6 IN. YELLOW HIGH BU	LD WATERBORNE PAVEMENT MA	ARKING PAINT, TYPE L BEA	ADS LF	\$0.210	7,243	\$1,521.03
	0410	6205906A	12 IN. WHITE HIGH BUIL	D WATERBORNE PAVEMENT MA	RKING PAINT, TYPE L BEA	DS LF	\$0.600	5,935	\$3,561.00
	0420	6209901	MISC.TEMPORARY PAV	EMENT MARKNING PAINT		LS	\$0.010	0.5	\$0.01
	0430	6209902	MISC.AIRCRAFT SPEED	MEARSUREMENT MARKINGS		EA	\$250.000	12	\$3,000.00
	0450	6224010	MODIFIED COLDMILLIN	G (DEPTH TRANSITIONS)		SQYD	\$1.960	125	\$245.00
	0470	6061060	MGS GUARDRAIL			LF	\$29.000	0.5	\$14.50
	5001	7173002	SILICONE EXPANSION	JOINT SEALANT		LF	\$40.000	140	\$5,600.00
	5002	7173002	SILICONE EXPANSION	JOINT SEALANT		LF	\$40.000	140	\$5,600.00
Project J5	13252 - Tota	al							\$44,690.99
Overall - T	otal								\$44,690.99
ontract Adj	justments	This Estima	<u>ate</u>						
A	dj Type		Entered By	Comments	Time Units	Ra	ate		Amount
OTHRL	iquidated D	amage	fenecj1	9 days of Administrative Costs for Liquidated Damages from Nov 2	-7		\$2,000.0	0	(\$14,000.00

#### Pay Estimate Created Date: November 17, 2022

Prog	ress Es	stimate Numbe 10			1217-D01 pital Paving & Col	nstruction, LLC	Pay Period Start Pay Period End		er 15, 2022	Net Chang	Contract Am ge Order An ontract Amo	nount (\$6,0	,336,218.81 )57.17) ,330,161.64
	Adj T	уре	Entered	d By	Com	ments	Time Units	S	F	Rate		Amou	int
					B.3.0. Per the partial day the v shall accrue cost of \$2 weekends o This does not User Costs as B.4.0. The spe be discussed ar	inclusive) per JSP JSP, each day or vork is incomplete an administrative 000, not including r de jure holidays. include any Road sociated with JSP excifics of those will d addressed with tor at a later time.							
Overall -	Total		These a	mounts are	listed in the Ince	ntive, Disincentiv	ve, Liquidated Dar	nages or C	Other Contra	ict Adjustr	ments		(\$14,000.0
ne Item	Adjust	ments This Est				·		Ū					
Project Number	Line No.	Item De	scription	Adjustment Type	Other Item Adjustment Type		Comm	ents			Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
1513252	0080		OR CRUSHED ) OR CHAT (C)	Material							-2,045	\$41.84	(\$85,562.80
	0080		OR CRUSHED ) OR CHAT (C)	Material		Payment E	tment offsets the or Estimate Item Adjus yment Estimate Exc	tment (001	6) due to use n the current	er fenecj1	2,045	\$41.84	\$85,562.80
	0111		PAVEMENT (11 REINFORCED)	Material							-364	\$121.60	(\$44,262.4
	0111	CONCRETE P INCH NON-F	PAVEMENT (11 REINFORCED)	Material		Payment E	tment offsets the or Estimate Item Adjus yment Estimate Exc	tment (001	5) due to use n the current	er fenecj1	364	\$121.60	\$44,262.4
	0121		PAVEMENT(8 J. NON-REINF)	Material							-328	\$68.80	(\$22,566.4
	0121		PAVEMENT ( 8 N. NON-REINF)	Material		Payment E	tment offsets the or Estimate Item Adjus yment Estimate Exc	tment (001-	<ol> <li>due to use n the current</li> </ol>	er fenecj1	328	\$68.80	\$22,566.40
	0170		TACK COAT	Overrun							-1	\$2.20	(\$2.2
	0230	REPAIR S PEI	TH PAVEMENT AW CUT (FOR RIMETER AND AL SAW CUTS)	Overrun			ased on averaged Il previous paymen ',6.00000 -	t estimates		tments of	2,508	\$6.00	\$15,048.0
	0240	FUR INSTALLATIC	AR (DRILLING, RNISHING AND DN) FOR FULL MENT REPAIR	Overrun			ased on averaged Il previous paymen ',7.25000 -	t estimates		tments of	1,704	\$7.25	\$12,354.0
	0390	WATERBORN	E HIGH BUILD NE PAVEMENT PAINT, TYPE L BEADS		Retroreflectivity Adjustment		Please refer to http: 90,0400_Retrorefle						\$743.9
	0400	WATERBORN	W HIGH BUILD NE PAVEMENT PAINT, TYPE L BEADS		Retroreflectivity Adjustment		Please refer to http: 90,0400_Retrorefle						\$524.8
	5001		E EXPANSION DINT SEALANT	Material							-140	\$40.00	(\$5,600.0
	5001		E EXPANSION DINT SEALANT	Material		Payment E	tment offsets the or Estimate Item Adjus yment Estimate Exc	tment (001	7) due to use n the current	er fenecj1	140	\$40.00	\$5,600.0
	5002		E EXPANSION DINT SEALANT	Material							-140	\$40.00	(\$5,600.0
	5002		E EXPANSION DINT SEALANT	Material		Payment E	tment offsets the or Estimate Item Adjus yment Estimate Exc	tment (001	8) due to use n the current	er fenecj1	140	\$40.00	\$5,600.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information	1
Project Number	Federal Proj. Number	Project Description	Route	County			Location of Work
J5I3252	FAF 70-3(284)	Coldmill and resurface	I-70	COOPER	from the Saline County lir	ne to west of the Missouri R	iver
Totals by .	Job Numbe	ers					
J513252		d Item Pay Item Adjustm		Item Pay	This Estimate \$44,690.99 \$28,668.64 <b>\$73,359.63</b>	Previous \$14,085,415.96 \$1,959,236.83 <b>\$16,044,652.79</b>	To Date \$14,130,106.95 \$1,987,905.47 <b>\$16,118,012.42</b>
	Liquid	tive centive lated Damages Contract Adju			\$0.00 \$0.00 (\$14,000.00) \$0.00	\$511,079.96 (\$21,000.00) \$0.00 \$0.00	\$511,079.96 (\$21,000.00) (\$14,000.00) \$0.00



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5I3252, Item 3107002, Project Item Line Number 0080, Material Set 310700296, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5/3252, Item 5021108, Project Item Line Number 0121, Material Set 502110896, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3252, Item 5021108, Project Item Line Number 0121, Material Set 502110896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3252, Item 5021111, Project Item Line Number 0111, Material Set 502111196, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3252, Item 5021111, Project Item Line Number 0111, Material Set 502111196, Material 1057JMTBE28019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3252, Item 6131018, Project Item Line Number 0260, Material Set 613101896, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3252, Item 6131018, Project Item Line Number 0260, Material Set 613101896, Material 1057JMTBE42019 - Tie Bar Ep Ctd 40" No. 6/M19 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3252, Item 7173002, Project Item Line Number 5001, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3252, Item 7173002, Project Item Line Number 5002, Material Set 717300296, Material 1057JMJCSS - Silicon Sealant for Sawed/Formed Jnts @, Acceptance Action Generic 1057JMJCSS is insufficient.	Working with Materials and Contractor to resolve.	fenecj1	Overridden
Estimate Exception Type: Item Overrun: Contract 211217-D01, Contract Project J5I3252, Project Item Line Number 0170, Contract Line Item Number 0170, Item 4071005, Minor Item.	This item will be addressed in future Change Order.	fenecj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211217-D01, Contract Project J5I3252, Project Item Line Number 0130, Contract Line Item Number 0130, Item 4030132, Minor Item.	This item will be addressed in future Change Order.	fenecj1	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211217-D01, Contract Project J5I3252, Project Item Line Number 0490, Contract Line Item Number 0490, Item 6061080, Minor Item.	This item will be addressed in future Change Order.	fenecj1	Acknowledged



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted Q	uantities	and Valu			Report Generated date and can differ from the posted am	ount at the ti	me the Es	timate was (	Generate	ed.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-D01	J5I3252	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	1.00	\$35,000.00	\$35,000.00
		0001	0020	2101006A	SUBGRADE COMPACTION (6-INCH DEPTH)	7.00	-3.00	4.00	100F	4.00	\$200.00	\$800.00
		0001	0030	2121000A	SUBGRADING AND SHOULDERING CLASS 1	7.00	-3.00	4.00	100F	4.00	\$2,871.00	\$11,484.00
		0001	0040	2153000	SHAPING SLOPES, CLASS III	231.00	-6.75	224.25	100F	212.00	\$623.00	\$132,076.00
		0001	0050	3030600	FURNISHING ROCK BASE MATERIAL	636.00	-64.00	572.00	SQYD	572.00	\$34.40	\$19,676.80
		0001	0060	3030610A	PLACING ROCK BASE	636.00	-64.00	572.00	SQYD	572.00	\$9.25	\$5,291.00
		0001	0070	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	328.00	0.00	328.00	SQYD	328.00	\$11.50	\$3,772.00
		0001	0080	3107002	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT (C)	2,188.00	0.00	2,188.00	TONS	2,045.00	\$41.84	\$85,562.80
		0001	0090	4010150	TYPE A2 SHOULDER	231.00	-23.00	208.00	SQYD	208.00	\$49.25	\$10,244.00
		0001	0100	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	5,891.80	0.00	5,891.80	TONS	5,615.10	\$62.12	\$348,810.01
		0001	0110	4019905	MISC.11" PCCP or 13" HMA OPTIONAL PAVEMENT	404.00	-404.00	0.00	SQYD	0.00	\$121.60	\$0.00
		0001	0111	5021111	CONCRETE PAVEMENT (11 INCH NON-REINFORCED)	0.00	364.00	364.00	SQYD	364.00	\$121.60	\$44,262.40
		0001	0120	4019905	MISC.8" PCCP or 10" HMA OPTIONAL PAVEMENT	328.00	-328.00	0.00	SQYD	0.00	\$68.80	\$0.00
		0001	0121	5021108	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	0.00	328.00	328.00	SQYD	328.00	\$68.80	\$22,566.40
		0001	0130	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	97,335.50	-2,331.30	95,004.20	TONS	95,147.70	\$105.50	\$10,038,082.35
		0001	0140	4031056	ASPHALT PERFORMANCE TESTING	1.00	0.00	1.00	LS	0.00	\$6,000.00	\$0.00
		0001	0150	4031058	INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.00	\$54,837.80	\$0.00
		0001	0160	4031059	PAVER-MOUNTED THERMAL PROFILES	1.00	0.00	1.00	LS	0.00	\$24,680.68	\$0.00
		0001	0170	4071005	TACK COAT	98,956.00	0.00	98,956.00	GAL	102,423.00	\$2.20	\$225,330.60
		0001	0180	4099905	MISC.Surface Sealing Treatment	194,213.00	0.00	194,213.00	SQYD	194,213.00	\$1.48	\$287,435.24
		0001	0190	4139905	MISC.High Friction Surface Treatment (BAUXITE)	17,966.00	0.00	17,966.00	SQYD	17,966.00	\$20.00	\$359,320.00
		0001	0200	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	2.00	\$500.00	\$1,000.00
		0001	0210	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	2,772.00	-176.60	2,595.40	SQYD	2,595.40	\$210.45	\$546,201.93
		0001	0220	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	277.00	-277.00	0.00	SQYD	0.00	\$2.00	\$0.00
		0001	0230	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	3,863.00	2,508.00	6,371.00	LF	6,371.00	\$6.00	\$38,226.00
		0001	0240	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	341.00	1,704.00	2,045.00	EA	2,045.00	\$7.25	\$14,826.25
		0001	0250	6131017	DOWEL BAR (FURNISHING AND INSTALLATION WITH BASKETS) FOR FULL DEPTH PAVEMENT REPAIR	1,111.00	-740.00	371.00	EA	371.00	\$9.00	\$3,339.00
		0001	0260	6131018	TIE BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR (TYPE L JOINTS)	730.00	-414.00	316.00	EA	316.00	\$8.75	\$2,765.00
		0001	0270	6161005	CONSTRUCTION SIGNS	1,097.00	672.00	1,769.00	SQFT	1,591.00	\$7.50	\$11,932.50
		0001	0280	6161008	ADVANCED WARNING RAIL SYSTEM	8.00	0.00	8.00	EA	6.00	\$35.00	\$210.00
		0001	0290	6161025	CHANNELIZER (TRIM LINE)	450.00	0.00	450.00	EA	310.00	\$20.00	\$6,200.00
		0001	0300	6161030	TYPE III MOVEABLE BARRICADE	6.00	0.00	6.00	EA	6.00	\$150.00	\$900.00
		0001	0310	6161033	DIRECTIONAL INDICATOR BARRICADE	30.00	30.00	60.00	EA	60.00	\$75.00	\$4,500.00
		0001	0320	6161040	FLASHING ARROW PANEL	2.00	2.00	4.00	EA	4.00	\$1,000.00	\$4,000.00
		0001	0330	6161052	WARNING LIGHT, TYPE B	12.00	0.00	12.00	EA	9.00	\$55.00	\$495.00
		0001	0340	6161055	SEQUENTIAL FLASHING WARNING LIGHT	30.00	30.00	60.00	EA	60.00	\$95.00	\$5,700.00
		0001	0350	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	4.00	\$3,200.00	\$12,800.00
		0001	0360	6181000	MOBILIZATION	1.00	0.00	1.00	LS	1.00	\$228,500.00	\$228,500.00
		0001	0370	6200015	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. WHITE	361.00	0.00	361.00	LF	299.00	\$18.00	\$5,382.00
		0001	0380	6200018	PREFORMED THERMOPLASTIC PAVEMENT MARKING, 24 IN. YELLOW	107.00	0.00	107.00	LF	53.00	\$18.00	\$954.00
		0001	0390	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	366,437.00	0.00	366,437.00	LF	182,424.76	\$0.21	\$38,309.20
		0001	0400	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	294,010.00	0.00	294,010.00	LF	146,334.00	\$0.21	\$30,730.14
		0001	0410	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	11,153.00	0.00	11,153.00	LF	5,935.00	\$0.60	\$3,561.00
		0001	0420	6209901	MISC.TEMPORARY PAVEMENT MARKNING PAINT	1.00	0.00	1.00	LS	0.50	\$0.01	\$0.00



### Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
1217-D01	J5I3252	0001	0430	6209902	MISC.AIRCRAFT SPEED MEARSUREMENT MARKINGS	12.00	0.00	12.00	EA	12.00	\$250.00	\$3,000.00
		0001	0440	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	1,050,575.00	0.00	1,050,575.00	SQYD	1,050,575.00	\$0.46	\$483,264.50
		0001	0450	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	1,042.00	0.00	1,042.00	SQYD	1,042.00	\$1.96	\$2,042.32
		0001	0460	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	5,324.00	0.00	5,324.00	STA	5,324.00	\$8.75	\$46,585.00
		0010	0470	6061060	MGS GUARDRAIL	14,550.00	-575.00	13,975.00	LF	13,975.00	\$29.00	\$405,275.00
		0010	0480	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	16.00	0.00	16.00	EA	15.00	\$3,674.00	\$55,110.00
		0010	0490	6061080	MGS END ANCHOR	27.00	-2.00	25.00	EA	26.00	\$1,256.00	\$32,656.00
		0010	0500	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	88.00	-2.00	86.00	EA	86.00	\$2,807.00	\$241,402.00
		0001	5001	7173002	SILICONE EXPANSION JOINT SEALANT	0.00	140.00	140.00	LF	140.00	\$40.00	\$5,600.00
		0001	5002	7173002	SILICONE EXPANSION JOINT SEALANT	0.00	140.00	140.00	LF	140.00	\$40.00	\$5,600.00
		0001	5003	4030132	ASPHALTIC CONCRETE MIXTURE PG 76-22 (SP125BSM MIX)	0.00	2,331.30	2,331.30	TONS	2,331.30	\$105.50	\$245,952.15
		0010	5004	6061074	MGS HEIGHT AND BLOCK TRANSITION	0.00	40.00	40.00	EA	14.00	\$955.31	\$13,374.34
	Project J	1513252 - To	otal Value	Posted to D	Date as of Report Generated Date							\$14,130,106.94
1217-D01 Ove	rall - Tota	I Value Pos	ted to Da	ate as of Rep	oort Generated Date							\$14,130,106.94

Revision 4/1/2020



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0040	2153000	SHAPING SLOPES, CLASS III	11/7/22	11/8/22	-0.74	100F		149.523				Corrected and rounded to plan. Plan called for 12.25 sta more than actually needed.
0080	3107002	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT	11/7/22	11/8/22	-0.27	TONS		112.958				Rounding down to pay this item to the nearest whole number per the spec
0170	4071005	TACK COAT	11/9/22	11/9/22	1.00	GAL		86.713				Rounding per spec. This corrects for an intermediate round early in the project that should not have been done.
0270	6161005	CONSTRUCTION SIGNS	11/9/22	11/9/22	502.07	SQFT	Various lane drops along I-70	86.713				Paying to plan. Actual sq footage is 440.75
0290	6161025	CHANNELIZER (TRIM LINE)	11/9/22	11/9/22	-4.00	EA		86.713				Miscalculated previous posting, entered 22 when it should have been 18
0310	6161033	DIRECTIONAL INDICATOR BARRICADE	11/9/22	11/9/22	31.00	EA		86.713		113.056		Four Lane Drops Total. Paying for Change order 0005
0320	6161040	FLASHING ARROW PANEL	11/9/22	11/9/22	1.00	EA		86.713		113.056		
			11/15/22	11/17/22	1.00	EA	Moving lane drop, both sides I-70.	86.713		113.056		
0330	6161052	WARNING LIGHT, TYPE B	11/9/22	11/9/22	6.00	EA	Rte K Ramps	Rte K Ramps				
0340	6161055	SEQUENTIAL FLASHING WARNING LIGHT	11/9/22	11/9/22	41.00	EA		86.713				Paying for Change order 0005
0350	6161099	CMS WITH COMMUNICATION INTERFACE, CONT F	11/7/22	11/8/22	1.00	EA	About 1mi east of Rte 87 on WB direction.	142.000				
0370	6200015	PREF THERMO PVMT MARK, 24 IN WHIT	11/7/22	11/8/22	299.00	LF	Off ramps at Rte 179 (EB, WB), Rte B (EB, WB), Rte 41 (WB), Rte K (WB)	138.303		159.841		
0380	6200018	PREF THERMO PVMT MARK, 24 IN YELLOW	11/3/22	11/7/22	107.00	LF	Off ramps at Rte 179	111.204		111.204		
			11/7/22	11/8/22	-54.00	LF		86.713		113.056		Hashes only amounted to 53ft in total. Originally paid to plan, but they only applied about 53ft of hash bars.
0390	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAINT	11/10/22	11/10/22	1,317.00	LF	Eastbound 6" Dotted lines	86.713		113.056		
				11/10/22	17,007.00	LF	Right edge of EB Ramps	86.713		113.056		
0400	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	11/10/22	11/10/22	7,243.00	LF	Left edge of EB Ramps	86.713		113.056		
0410	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAINT	11/10/22	11/10/22	5,935.00	LF	EB Gore Areas	86.713		113.056		
0420	6209901	MISC. PAVEMENT MARKINGS	11/10/22	11/10/22	0.50	LS	WB I-70	136.949		163.248		This pays for the temp striping they applied to WB I-70. They did not do temp stripes on the eastbound side, so I'm only paying half.
0430	6209902	MISC. PAVEMENT MARKINGS	11/7/22	11/8/22	12.00	EA	WB I-70 PL and DL	150.600		150.850		Also includes 6 markings on the EB side that were applied on Saturday.
0450	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	11/7/22	11/8/22	125.00	SQYD		158.730				Paying to Plan
0470	6061060	MGS GUARDRAIL	11/7/22	11/8/22	0.50	LF		112.958				Rounding to pay this item to the nearest whole number per the spec
5001	7173002	SILICONE EXPANSION JOINT SEALANT	11/3/22	11/7/22	140.00	LF	WB I-70 Chouteau Ck Bridge A5118	154.872		154.925		Louis Company did this.
5002	7173002	SILICONE EXPANSION JOINT SEALANT	11/2/22	11/3/22	140.00	LF	EB I-70 Chouteau Ck Bridge A5119	95.076		95.129		Louis Co did this.

The information below this line are details for Construction Signs (if applicable). No Data Available



t	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
2	0020	SUBGRADE COMPACTION	Material		7	Oct 2, 2022	SYSTEM	(\$1,200.00)	
		(6-INCH DEPTH)			8	Oct 17, 2022	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0023) due to user fenecj1 overridding Payme Estimate Exception 1 on the current Payment Estimate.
					8	Oct 17, 2022	SYSTEM	(\$800.00)	
					9	Nov 2, 2022	SYSTEM	\$800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ackert1 overridding Payme Estimate Exception 1 on the current Payment Estimate.
					9	Nov 2, 2022	SYSTEM	(\$800.00)	
				- Total				(\$1,200.00)	
			Material - Tota	al				(\$1,200.00)	
			MaterialCredit		8	Oct 17, 2022	SYSTEM	\$1,200.00	
				- Total				\$1,200.00	
			MaterialCredit	t - Total				\$1,200.00	
	0020 -	Total						\$0.00	
	0070	TYPE 5 AGGREGATE	Material		7	Oct 2, 2022	SYSTEM	(\$3,772.00)	
		FOR BASE (6 IN. THICK)			8	Oct 17, 2022	SYSTEM	\$3,772.00	This adjustment offsets the original system-generated Material Paymen Estimate Item Adjustment (0009) due to user fenecj1 overridding Payme Estimate Exception 2 on the current Payment Estimate.
					8	Oct 17, 2022	SYSTEM	(\$3,772.00)	
					9	Nov 2, 2022	SYSTEM	\$3,772.00	This adjustment offsets the original system-generated Material Paymen Estimate Item Adjustment (0005) due to user ackert1 overridding Paym Estimate Exception 2 on the current Payment Estimate.
					9	Nov 2, 2022	SYSTEM	(\$3,772.00)	
				- Total				(\$3,772.00)	
			Material - Tota	al				(\$3,772.00)	
			MaterialCredit		8	Oct 17, 2022	SYSTEM	\$3,772.00	
				- Total				\$3,772.00	
			MaterialCredit	t - Total				\$3,772.00	
	0070 -	Total						\$0.00	
	0080	GRAVEL (A) OR CRUSHED STONE (B) OR CHAT	Material		8	Oct 17, 2022	SYSTEM	\$69,751.88	This adjustment offsets the original system-generated Material Paymen Estimate Item Adjustment (0010) due to user fenecj1 overridding Paym Estimate Exception 3 on the current Payment Estimate.
		CHAI			8	Oct 17, 2022	SYSTEM	(\$69,751.88)	
					10	Nov 17, 2022	SYSTEM	\$85,562.80	This adjustment offsets the original system-generated Material Paymen Estimate Item Adjustment (0016) due to user fenecj1 overridding Payme Estimate Exception 1 on the current Payment Estimate.
					10	Nov 17, 2022	SYSTEM	(\$85,562.80)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
	- 0800	Total						\$0.00	
	0090	TYPE A2 SHOULDER	Material		7	Oct 2, 2022	SYSTEM	(\$10,244.00)	
					8	Oct 17, 2022	SYSTEM	\$10,244.00	This adjustment offsets the original system-generated Material Paymen Estimate Item Adjustment (0012) due to user fenecj1 overridding Payme Estimate Exception 4 on the current Payment Estimate.
					8	Oct 17, 2022	SYSTEM	(\$10,244.00)	
					9	Nov 2, 2022	SYSTEM	\$10,244.00	This adjustment offsets the original system-generated Material Paymen Estimate Item Adjustment (0006) due to user ackert1 overridding Paym Estimate Exception 4 on the current Payment Estimate.



Nov 19, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3252	0090	TYPE A2	Material	- Total				(\$10,244.00)	
		SHOULDER	Material - Tota					(\$10,244.00)	
			MaterialCredit		8	Oct 17, 2022	SYSTEM	\$10,244.00	
				- Total				\$10,244.00	
			MaterialCredit	- Total				\$10,244.00	
	0090 -	Total						\$0.00	
	0100	BIT. PAVEMENT MIXTURE	Other Item Adjustment	ACAD	6	Sep 16, 2022	ackert1	\$50,114.77	5615.1 and 3.5% Virgin Asphalt
		PG64-22 (BP-1)		ACAD - Tot	al			\$50,114.77	
			Other Item Ad	justment - To	tal			\$50,114.77	
			Price FUEL		6	Sep 16, 2022	SYSTEM	\$31,691.62	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$31,691.62	
			Price FUEL - T	otal				\$31,691.62	
	0100 -	Total						\$81,806.39	
	0111	CONCRETE	Material		7	Oct 2,	SYSTEM	(\$44,262.40)	
		PAVEMENT (11 IN. NON-REINF)			8	2022 Oct 17,	SYSTEM	\$44,262.40	This adjustment offsets the original system-generated Material Payment
						2022		<i>(* ( / * * * * * * * * * * * * * * * * *</i>	Estimate Item Adjustment (0021) due to user fenecj1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Oct 17, 2022	SYSTEM	(\$44,262.40)	
					9	Nov 2, 2022	SYSTEM	\$44,262.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ackert1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					9	Nov 2, 2022	SYSTEM	(\$44,262.40)	
					10	Nov 17, 2022	SYSTEM	\$44,262.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user fenecj1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					10	Nov 17, 2022	SYSTEM	(\$44,262.40)	
				- Total				(\$44,262.40)	
			Material - Tota					(\$44,262.40)	
			MaterialCredit		8	Oct 17, 2022	SYSTEM	\$44,262.40	
				- Total				\$44,262.40	
			MaterialCredit	- Total				\$44,262.40	
	0111 -	Total						\$0.00	
	0121	CONCRETE PAVEMENT ( 8	Material		7	Oct 2, 2022	SYSTEM	(\$22,566.40)	
		IN. NON-REINF)			8	Oct 17, 2022	SYSTEM	\$22,566.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user fenecj1 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					8	Oct 17, 2022	SYSTEM	(\$22,566.40)	
					9	Nov 2, 2022	SYSTEM	\$22,566.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ackert1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Nov 2, 2022	SYSTEM	(\$22,566.40)	
					10	Nov 17, 2022	SYSTEM	\$22,566.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user fenecj1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Nov 17, 2022	SYSTEM	(\$22,566.40)	
				- Total				(\$22,566.40)	
			Material - Tota	I				(\$22,566.40)	
			MaterialCredit		8	Oct 17, 2022	SYSTEM	\$22,566.40	



Nov 19, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
513252	0121	CONCRETE	MaterialCredit	- Total				\$22,566.40	
		PAVEMENT ( 8 IN. NON-REINF)	MaterialCredit	- Total				\$22,566.40	
	0121 -	Total						\$0.00	
	0130	ASPHALTIC CONCRETE MIXTURE PG	Other Item Adjustment	ACAD	4	Aug 16, 2022	ackert1	\$305,280.83	http://eprojects/Docs/5l3252/211217- D01_J5l3252_AC_Index_Price_Adjustment_Hot_Mix_Asphalt_Ton.pdf
		76-22 (SP1			5	Sep 1, 2022	ackert1	\$399,462.78	26,325.91 tons this pay period
					6	Sep 16, 2022	ackert1	\$204,295.01	13133.72 Tons at 6.1 % Virgin AC
					7	Oct 2, 2022	ackert1	\$408,491.88	Represents 26,261.13 Tons 6.10% Virgin AC%
					8	Oct 17, 2022	fenecj1	\$144,784.85	AC Adjustment for 9307.93 Tons at 6.1% VAC for Mix SP125 22-84A.
				ACAD - Tot	al			\$1,462,315.35	
			Other Item Ad	justment - To	tal			\$1,462,315.35	
			Overrun	Overrun	8	Oct 17, 2022	SYSTEM	(\$15,572.79)	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				Overrun - T	otal			(\$15,572.79)	
			Overrun - Tota					(\$15,572.79)	
			Price FUEL		4	Aug 16, 2022	SYSTEM	\$79,486.18	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					5	Sep 1, 2022	SYSTEM	\$104,008.42	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					6	Sep 16, 2022	SYSTEM	\$74,126.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					7	Oct 1, 2022	SYSTEM	\$148,217.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					8	Oct 17, 2022	SYSTEM	\$28,121.12	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$433,960.24	
			Price FUEL - T	otal				\$433,960.24	
	0130 -	Total						\$1,880,702.80	
	0170	TACK COAT	Overrun	Overrun	8	Oct 17, 2022	SYSTEM	(\$7,625.20)	
					10	Nov 17, 2022	SYSTEM	(\$2.20)	
				Overrun - T	otal			(\$7,627.40)	
			Overrun - Tota	al				(\$7,627.40)	
	0170 -	Total						(\$7,627.40)	
	0180	MISC. SCRUB SEAL	Material		7	Oct 2, 2022	SYSTEM	(\$130,440.50)	
				- Total				(\$130,440.50)	
			Material - Tota	l 🗌				(\$130,440.50)	
			MaterialCredit		8	Oct 17, 2022	SYSTEM	\$130,440.50	
				- Total				\$130,440.50	
			MaterialCredit					\$130,440.50	
	0180 -							\$130,440.50 \$0.00	
	0180 - 0210	FURN & PLACE CONC MATL FOR FULL	MaterialCredit Material		3	Aug 1, 2022	SYSTEM	\$130,440.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user ackert1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		FURN & PLACE CONC MATL			3 3		SYSTEM	\$130,440.50 \$0.00	Estimate Item Adjustment (0003) due to user ackert1 overridding Payment
		FURN & PLACE CONC MATL FOR FULL				2022 Aug 1,		\$130,440.50 \$0.00 \$77,744.44	Estimate Item Adjustment (0003) due to user ackert1 overridding Payment
		FURN & PLACE CONC MATL FOR FULL			3	2022 Aug 1, 2022 Aug 16,	SYSTEM	\$130,440.50 \$0.00 \$77,744.44 (\$77,744.44)	Estimate Item Adjustment (0003) due to user ackert1 overridding Payment Estimate Exception 2 on the current Payment Estimate. This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user ackert1 overridding Payment



Nov 19, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J513252	0210	FURN & PLACE CONC MATL FOR FULL DEPTH	Material - Tota	l				\$0.00	
	0210 -	10 - Total							
	0230	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	Overrun	Overrun	5	Sep 1, 2022	SYSTEM	(\$1,770.00)	
					6	Sep 16, 2022	SYSTEM	(\$7,602.00)	
					7	Oct 2, 2022	SYSTEM	(\$5,676.00)	
					10	Nov 17, 2022	SYSTEM	\$15,048.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.00000 - 6.00000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Total					\$0.00	
	0230 -	Total						\$0.00	
	0240	DOWEL BAR (DRILLING, FURNISHING	Material		3	Aug 1, 2022	SYSTEM	\$2,537.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user ackert1 overridding Payment Estimate Exception 3 on the current Payment Estimate.
		AND INST			3	Aug 1, 2022	SYSTEM	(\$2,537.50)	
				- Total				\$0.00	
			Material - Tota	al				\$0.00	
			Overrun	Overrun	3	Aug 1, 2022	SYSTEM	(\$65.25)	
					4	Aug 16, 2022	SYSTEM	(\$3,857.00)	
					5	Sep 1, 2022	SYSTEM	(\$3,335.00)	
					6	Sep 16, 2022 Oct 2,	SYSTEM	(\$2,465.00)	
					10	2022 Nov 17,	SYSTEM	\$12,354.00	Unit price based on averaged overrun adjustments for installed quantity on all
						2022			previous payment estimates. Price Adjustments of ',7.25000 - 7.25000,' is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - Tota	al				\$0.00	
	0240 -							\$0.00	
	0250	DOWEL BAR (FURNISH AND INSTALL WITH BASK	SH AND L WITH		3	Aug 1, 2022	SYSTEM	\$216.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user ackert1 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					3	Aug 1, 2022	SYSTEM	(\$216.00)	
					5	Sep 1, 2022	SYSTEM	\$1,719.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user ackert1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Sep 1, 2022	SYSTEM	(\$1,719.00)	
			- Total					\$0.00	
			Material - Tota	al				\$0.00	
	0250 -							\$0.00	
	0260	TIE BAR (DRILL, FURN & INSTAL) (TYPE L	Material		3	Aug 1, 2022	SYSTEM	\$568.75	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user ackert1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					3	Aug 1, 2022	SYSTEM	(\$568.75)	
				- Total				\$0.00	
			Material - Tota	Material - Total					
	0260 -	Total	tal					\$0.00	
	0390	6 IN. WHITE	Material		7	Oct 3,	SYSTEM	\$34,461.16	This adjustment offsets the original system-generated Material Payment



Nov 19, 2022

ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
52	0390	HIGH BUILD WATERBORNE	Material			2022			Estimate Item Adjustment (0045) due to user ackert1 overridding Payment Estimate Exception 22 on the current Payment Estimate.
		PAINT			7	Oct 2, 2022	SYSTEM	(\$34,461.16)	
				- Total				\$0.00	
			Material - Total					\$0.00	
			Other Item Adjustment	OVRN	7	Oct 2, 2022	ackert1	(\$6,892.23)	Withhold 20% until we have retro results from Sec 620.12.2.4 of the EPG Ackert1
				OVRN - Tota	al			(\$6,892.23)	
				REFL	10	Nov 17, 2022	fenecj1	\$743.95	Please refer to http://eprojects/Docs/513252/211217- D01_J513252_0390,0400_Retroreflectivity_Payment_Adjustment.pdf
				REFL - Tota	ıl			\$743.95	
			Other Item Ad	justment - To	tal			(\$6,148.28)	
	0390 - `	Total						(\$6,148.28)	
1	0400	6 IN. YELLOW HIGH BUILD WATERBORNE PAINT	Material		7	Oct 3, 2022	SYSTEM	\$29,209.11	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0046) due to user ackert1 overridding Payment Estimate Exception 24 on the current Payment Estimate.
					7	Oct 2, 2022	SYSTEM	(\$29,209.11)	
				- Total				\$0.00	
			Material - Tota	I				\$0.00	
			Other Item Adjustment	OTHR		Oct 2, 2022	ackert1	(\$5,841.82)	Withhold 20% until we have retro results from Sec 620.12.2.4 of the EPG Ackert1
				OTHR - Tota	al			(\$5,841.82)	
				REFL		Nov 17, 2022	fenecj1	\$524.89	Please refer to http://eprojects/Docs/5l3252/211217- D01_J5l3252_0390,0400_Retroreflectivity_Payment_Adjustment.pdf
				REFL - Tota				\$524.89	
			Other Item Ad	justment - To	tal			(\$5,316.93)	
	0400 - `							(\$5,316.93)	
	0470	MGS GUARDRAIL	Construction Stockpile		5	Sep 1, 2022	SYSTEM	(\$66,431.97)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Sep 16, 2022 Oct 1,	SYSTEM	(\$100,780.31)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total	/	2022	STSTEM	(\$112,147.72)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction		tal				
			Construction	Stockpile - To		Maria	OVOTEM	(\$279,360.00)	Devenuent Estimate litera Adiustroant anno acted Ota durita Tanara attar
			Construction Stockpile STMI	Tetel	1	May 2, 2022	SYSTEM	\$279,360.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			Construction	- Total Stocknile STML Total				\$279,360.00	
	0470	Total	Construction Stockpile STMI - Total					\$279,360.00	
	0470 - 1	Total MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile		5	Sep 1, 2022	SYSTEM	\$0.00 (\$14,711.54)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Sep 16, 2022	SYSTEM	(\$18,389.42)	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	Oct 1, 2022	SYSTEM	(\$3,619.04)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$36,720.00)	
			Construction	Stockpile - To	otal			(\$36,720.00)	
			Construction Stockpile		1	May 2, 2022	SYSTEM	\$36,720.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$36,720.00	
			Construction Stockpile STMI - Total					\$36,720.00	
	0480 -	Total						\$0.00	
1	0490	MGS END ANCHOR	Construction Stockpile		5	Sep 1, 2022	SYSTEM	(\$2,712.72)	Payment Estimate Item Adjustment generated Stockpile Transaction
					6	Sep 16,	SYSTEM	(\$6,781.79)	Payment Estimate Item Adjustment generated Stockpile Transaction



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
52	0490	MGS END	Construction			2022			
		ANCHOR	Stockpile		7	Oct 1, 2022	SYSTEM	(\$10,850.86)	Payment Estimate Item Adjustment generated Stockpile Transaction
					8	Oct 17, 2022	SYSTEM	(\$1,254.63)	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				(\$21,600.00)	
			Construction	Stockpile - To	otal			(\$21,600.00)	
			Construction Stockpile STMI		1	May 2, 2022	SYSTEM	\$21,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$21,600.00	
			Construction	Stockpile STI	MI - Total			\$21,600.00	
			Overrun	Overrun	9	Nov 2, 2022	SYSTEM	(\$1,256.00)	
				Overrun - T	otal			(\$1,256.00)	
			Overrun - Tota	al				(\$1,256.00)	
	0490 -	Total						(\$1,256.00)	
1	0500	TYPE A CRASHWORTHY END TERMINAL	Construction Stockpile		5	Sep 1, 2022	SYSTEM	(\$57,459.75)	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)			6	Sep 16, 2022	SYSTEM	(\$48,840.79)	Payment Estimate Item Adjustment generated Stockpile Transaction
					7	Oct 1, 2022	SYSTEM	(\$54,299.46)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total					(\$160,600.00)	
			Construction Stockpile - To					(\$160,600.00)	
			Construction Stockpile STMI		1	May 2, 2022	SYSTEM	\$160,600.00	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$160,600.00	
			Construction	Stockpile STI	MI - Total			\$160,600.00	
	0500 - Total								
								\$0.00	
	5001	SILICONE EXPANSION JOINT SEALANT	Material		10	Nov 17, 2022	SYSTEM	\$5,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001	EXPANSION	Material		10 10		SYSTEM SYSTEM		Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment
	5001	EXPANSION	Material	- Total		2022 Nov 17,		\$5,600.00	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment
	5001	EXPANSION	Material Material - Tota			2022 Nov 17,		\$5,600.00 (\$5,600.00)	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment
	5001	EXPANSION JOINT SEALANT				2022 Nov 17,		\$5,600.00 (\$5,600.00) <b>\$0.00</b>	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment
		EXPANSION JOINT SEALANT				2022 Nov 17,		\$5,600.00 (\$5,600.00) \$0.00 \$0.00	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment
	5001 -	EXPANSION JOINT SEALANT	Material - Tota		10	2022 Nov 17, 2022 Nov 17, 2022	SYSTEM	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 -	EXPANSION JOINT SEALANT	Material - Tota		10	2022 Nov 17, 2022 Nov 17, 2022 Nov 17,	SYSTEM	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 -	EXPANSION JOINT SEALANT	Material - Tota	al - Total	10	2022 Nov 17, 2022 Nov 17, 2022 Nov 17,	SYSTEM	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00)	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 -	EXPANSION JOINT SEALANT	Material - Tota Material	al - Total	10	2022 Nov 17, 2022 Nov 17, 2022 Nov 17,	SYSTEM	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00) \$0.00	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 - 5002	EXPANSION JOINT SEALANT	Material - Tota Material	al - Total	10	2022 Nov 17, 2022 Nov 17, 2022 Nov 17,	SYSTEM	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00) \$0.00 \$0.00	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 - 5002 5002 -	EXPANSION JOINT SEALANT	Material - Tota Material Material - Tota	al - Total al	10	2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00) (\$5,600.00) \$0.00 \$0.00	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 - 5002 5002 -	Total Total Total Total Total Total	Material - Tota Material Material - Tota	al - Total al ACAD	10 10 10 5 al	2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022	SYSTEM SYSTEM SYSTEM	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00) (\$5,600.00) \$0.00 \$0.00 \$36,534.39	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 - 5002 5002 -	Total Total Total Total Total Total	Material - Tota Material Material - Tota	- Total al ACAD ACAD - Tota	10 10 10 5 5 al 6	2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Sep 1, 2022	SYSTEM SYSTEM SYSTEM ackert1	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$36,534.39 \$36,534.39	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 - 5002 5002 -	Total Total Total Total Total Total	Material - Tota Material Material - Tota	- Total al ACAD - Tota FUEL - Tota	10 10 10 5 5 6	2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Sep 1, 2022	SYSTEM SYSTEM SYSTEM ackert1	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$36,534.39 \$36,534.39 \$9,210.50	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 - 5002 5002 -	EXPANSION JOINT SEALANT	Material - Tota Material Material - Tota Other Item Adjustment	- Total al ACAD - Tota FUEL - Tota	10 10 10 5 5 6	2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Sep 1, 2022	SYSTEM SYSTEM SYSTEM ackert1	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$36,534.39 \$36,534.39 \$9,210.50	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
	5001 - 5002 - 5003 -	EXPANSION JOINT SEALANT	Material - Tota Material Material - Tota Other Item Adjustment	- Total al ACAD - Tota FUEL - Tota	10 10 10 5 5 6	2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Nov 17, 2022 Sep 1, 2022	SYSTEM SYSTEM SYSTEM ackert1	\$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$5,600.00 (\$5,600.00) \$0.00 \$0.00 \$36,534.39 \$36,534.39 \$9,210.50 \$9,210.50	Estimate Item Adjustment (0017) due to user fenecj1 overridding Payment Estimate Exception 8 on the current Payment Estimate.



Nov 19, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J5I3252	5004	MGS HEIGHT AND BLOCK TRANSITION		- Total				\$0.00	
			Material - Tota	al				\$0.00	
	5004 -	Total						\$0.00	
J5I3252	- Total						\$1,987,905.47		
Overall - Total									