

Pay Estimate Created Date: December 15, 2022

Progress Estima 17	e Number	Contract ID Prime Contracto	211217-H05 r Apex Paving Co			December 2, 2 December 15	2022	Original Contract Amount Net Change Order Amount Current Contract Amount	\$10,080,771.09 \$258,097.15 \$10,338,868.24		
Approval Date									By User		
December 16, 2022			Generated and A	pproved (and should	d be considered	l Draft) a	at the Project Office Level by	holtb3		
December 19, 2022											
December 20, 022 Reviewed and Approved at the Central Office Controllers Office Lev									el by ramses1		
Original Comple	tion Date	Current Con	npletion Date	Actu	al Comple	tion Date	9	6 of Current Contract Amou	int Complete		
July 31, 20	23	July 3	1, 2023					41.14%			
	Contrac	t Informational Dat	tes		Milestones						
Date Description	Original	Completion Date	ion Date	No Miles	tones Exist for	Contrac	t				
Acceptance Date											
Awarded Date	January	5, 2022	January 5, 2022								
Letting Date	Decemb	er 17, 2021	December 17, 202	21							
Notice to Proceed D	ate March 7	, 2022	March 7, 2022								
Open to Traffic Date											
Work Began Date	April 14,	2022	April 14, 2022								

Contract Total Pay	For Estimate No. 17			
		This Estimate	Previous	To Date
211217-H05				
	Total Posted Items Pay	\$0.00	\$4,253,925.75	\$4,253,925.75
	Gross Item Adjustments	\$0.00	\$281,791.10	\$281,791.10
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damage	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$5,595.04	\$78,402.14	\$83,997.18
			<mark>\$4,614,118.99</mark>	\$4,619,714.03
Contract Total Paya	able This Estimate:	\$5,595.04		

Items Paid This Estimate Period

No Data Available

Contract Adjustments This E	stimate				
Adj Type	Entered By	Comments	Time Units	Rate	Amount
ABIROther Contract Adjustment	holtb3	Northbound Driving Lane = \$8244.39 Northbound Passing Lane = \$891.29			\$9,135.68
ADIROther Contract Adjustment	holtb3	Northbound Driving Lane = - \$891.29 Northbound Passing Lane = -\$2649.35			(\$3,540.64)
Overall - Total					\$5,595.04

These amounts are listed in the Incentive, Disincentive, Liquidated Damages or Other Contract Adjustments <u>ate</u>

ine Item Adjustments This Estima				
	ine Item Ad	liustments	This	Estima

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material			-258.1	\$12.00	(\$3,097.20)
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	258.1	\$12.00	\$3,097.20
	0070	MISC.	Material			-1,482.61	\$44.27	(\$65,635.14)



Pay Estimate Created Date: December 15, 2022

Prog		17 Contract I Prime Con		217-H05 x Paving Co.	Pay Period End December 15, 2022 Net C	hal Contract A hange Order nt Contract A	Amount \$2	0,080,771.09 58,097.15 0,338,868.24
[⊃] roject lumber	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
913597	0070	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.		\$44.27	\$65,635.14
	0080	TYPE A3 SHOULDER	Material			-117.33	\$37.51	(\$4,401.05
	0080	TYPE A3 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.	117.33	\$37.51	\$4,401.05
	0135	MISC.	Material			-21,464	\$2.60	(\$55,806.40
	0135	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.	21,464	\$2.60	\$55,806.40
	0150	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material			-140.8	\$90.00	(\$12,672.00
	0150	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.		\$90.00	\$12,672.00
	0200	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-321.8	\$6.00	(\$1,930.80
	0200	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.		\$6.00	\$1,930.80
	0420	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material			-60	\$10.00	(\$600.00
	0420	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.		\$10.00	\$600.00
	0470	MISC.	Material			-0.35	\$16,769.52	(\$5,869.33
	0470	MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.		\$16,769.52	\$5,869.33
	0500	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	Material			-25,981	\$3.85	(\$100,026.85
	0500	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.	25,981	\$3.85	\$100,026.85
	0510	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	Material			-2,274	\$3.85	(\$8,754.90)
	0510	SLAB JACKING MATERIAL HIGH DENSITY	Material		This adjustment offsets the original system- generated Material Payment Estimate Item		\$3.85	\$8,754.90



Pay Estimate Created Date: December 15, 2022

Prog	Progress Estimate Number Contract ID 211217-H05 Pay Period Start December 2, 2022 Original Contract Contractor 17 17 Apex Paving Co. Pay Period End December 15, 2022 Original Contractor								0,080,771.09 58,097.15 0,338,868.24
Project Number	Line No.	Item Descri	iption	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3597		POLY	URETHANE			Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.			
	0570	CURB	BLOCKOUT	Material			-611	\$125.07	(\$76,417.77
	0570	CURB	BLOCKOUT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.	611	\$125.07	\$76,417.77
Total									\$0.0



Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

	Contract Project Information										
Project Number Federal Proj. Number Project Description Route County Location of Work											
J9I3597	3597 I Resurface 155 PEMISCOT from Rte. 412 to Tennessee State line										
Totals by .	Job Number	S									
J9I3597		l Item Pay Item Adjustme		Item Pay	This Estimate \$0.00 \$0.00 \$0.00	Previous \$4,253,925.75 \$281,791.10 \$4,535,716.85	To Date \$4,253,925.75 \$281,791.10 \$4,535,716.85				
					\$0.00 \$0.00 \$0.00 \$5.595.04	\$0.00 \$0.00 \$0.00 \$78.402.14	\$0.00 \$0.00 \$0.00 \$83.997.18				



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions (Discrepancies) This Estimate Period Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 3049910, Project Item Line Number 0070, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4071005, Project Item Line Number 0130, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4079912, Project Item Line Number 0135, Material Set 407991296, Material 1015EASS1VH - Emulsified Asphalt - Trackless Tack, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6053030A, Project Item Line Number 0160, Material Set 6053030A96, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6131012, Project Item Line Number 0200, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade orEmbankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6205309, Project Item Line Number 0420, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6209901, Project Item Line Number 0470, Material Set 620990196, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6209901, Project Item Line Number 0470, Material Set 620990196, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6209901, Project Item Line Number 0470, Material Set 620990196, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6252001, Project Item Line Number 0500, Material Set 625200196, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6252003, Project Item Line Number 0510, Material Set 625200396, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100507CPCMLD - PCCP or Masonry 0-3/4" Max LS/DO, Acceptance Action Generic 100507CPCMLD is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,	No Remark was entered by Engineer	holtb3	Overridden



Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 100510CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9/3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9/3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Item Overrun: Contract 211217-H05, Contract Project J9I3597, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6131012, Minor Item.	No Remark was entered by Engineer	holtb3	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211217-H05, Contract Project J9I3597, Project Item Line Number 0210, Contract Line Item Number 0210, Item 6131013, Minor Item.	No Remark was entered by Engineer	holtb3	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211217-H05, Contract Project J9I3597, Project Item Line Number 0310, Contract Line Item Number 0310, Item 6161030, Minor Item.	No Remark was entered by Engineer	holtb3	Acknowledged



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate) Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Note: Posted G	luantities	and Valu	ies are l	based on F	Report Generated date and can differ from the posted am	ount at the	time the E	stimate was	Genera	ted.		
Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H05	J9I3597	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.80	\$76,208.14	\$60,966.51
		0001	0020	2039907	MISC.TRENCHING FOR PIPE AGGREGATE EDGE DRAIN	100.00	0.00	100.00	CUYD	23.60	\$190.00	\$4,484.00
		0001	0030	2129900	MISC.SHOULDER GRADING	46.00	0.00	46.00	100F	0.00	\$227.95	\$0.00
		0001	0035	2159903	MISC.Modified Shaping Slopes Class III	1,760.00	0.00	1,760.00	LF	0.00	\$10.00	\$0.00
		0001	0040	3030600	FURNISHING ROCK BASE MATERIAL	977.00	0.00	977.00	SQYD	398.90	\$25.00	\$9,972.50
		0001	0050	3030610A	PLACING ROCK BASE	977.00	0.00	977.00	SQYD	398.90	\$10.00	\$3,989.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,081.00	0.00	1,081.00	SQYD	258.10	\$12.00	\$3,097.20
		0001	0070	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	9,357.00	0.00	9,357.00	TONS	1,482.61	\$44.27	\$65,635.14
		0001	0080	4010151	TYPE A3 SHOULDER	9,827.30	0.00	9,827.30	SQYD	117.33	\$37.51	\$4,401.05
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	22,548.10	0.00	22,548.10	TONS	6,236.93	\$78.78	\$491,345.35
		0001	0095	4019901	MISC.NRRA SUPPLEMENTARY TEST SECTIONS	1.00	0.00	1.00	LS	0.00	\$144,283.66	\$0.00
		0001	0120	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	42,848.90	0.00	42,848.90	TONS	13,628.42	\$93.78	\$1,278,073.23
		0001	0124	4031058	INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.50	\$40,470.36	\$20,235.18
		0001	0125	4031059	PAVER-MOUNTED THERMAL PROFILES	1.00	0.00	1.00	LS	0.50	\$4,855.28	\$2,427.64
		0001	0130	4071005	TACK COAT	12,646.00	0.00	12,646.00	GAL	3,515.00	\$2.33	\$8,189.95
		0001	0135	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	73,357.00	0.00	73,357.00	GAL	21,464.00	\$2.60	\$55,806.40
		0001	0140	4134000	BITUMINOUS FOG SEAL	14,167.00	0.00	14,167.00	GAL	0.00	\$3.39	\$0.00
		0001	0150	5021109	CONCRETE PAVEMENT (9 IN. NON-REINF)	345.00	0.00	345.00	SQYD	140.80	\$90.00	\$12,672.00
		0001	0160	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	4,034.00	0.00	4,034.00	LF	955.70	\$15.00	\$14,335.50
		0001	0170	6054020	OUTLET PIPES AND SPLASH PADS	34.00	0.00	34.00	EA	8.00	\$1,350.00	\$10,800.00
		0001	0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	2.00	\$0.00	\$0.00
		0001	0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL	1,144.00	648.00	1,792.00	SQYD	1,687.80	\$225.00	\$379,755.00
		0001	0200	6131012	DEPTH PAVEMENT REPAIR SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	321.80	\$6.00	\$1,930.80
		0001	0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	321.80	\$8.00	\$2,574.40
		0001	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	4,724.00	3,182.00	7,906.00	LF	6,291.00	\$10.00	\$62,910.00
		0001	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	2,100.00	1,899.00	3,999.00	EA	3,495.00	\$8.00	\$27,960.00
		0001	0240	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	49.40	0.00	49.40	CUYD	0.00	\$1,650.00	\$0.00
		0001	0250	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	395.60	0.00	395.60	SQYD	0.00	\$115.00	\$0.00
		0001	0260	6134001	DOWEL BAR RETROFIT	10,680.00	0.00	10,680.00	EA	9,219.00	\$90.00	\$829,710.00
		0001	0270	6139903	MISC.TYPE E EXPANSION JOINT	456.00	0.00	456.00	LF	252.00	\$30.00	\$7,560.00
		0001	0280	6161005	CONSTRUCTION SIGNS	4,196.00	0.00	4,196.00	SQFT	1,883.00	\$8.00	\$15,064.00
		0001	0290	6161008	ADVANCED WARNING RAIL SYSTEM	12.00	0.00	12.00	EA	12.00	\$35.00	\$420.00
		0001	0300	6161025	CHANNELIZER (TRIM LINE)	962.00	0.00	962.00	EA	245.00	\$20.00	\$4,900.00
		0001	0310	6161030	TYPE III MOVEABLE BARRICADE	4.00	0.00	4.00	EA	6.00	\$150.00	\$900.00
		0001	0320	6161033	DIRECTIONAL INDICATOR BARRICADE	178.00	0.00	178.00	EA	32.00	\$0.00	\$0.00
		0001	0330	6161040	FLASHING ARROW PANEL	9.00	0.00	9.00	EA	4.00	\$1,000.00	\$4,000.00
		0001	0340	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	2.00	\$3,200.00	\$6,400.00
		0001	0350	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$10,000.00	\$10,000.00
		0001	0360	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	0.00	\$0.00	\$0.00
		0001	0370	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	160.00	0.00	160.00	LF	0.00	\$178.29	\$0.00
		0001	0380	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$263,893.91	\$197,920.43
		0001	0390	6200039	PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF RAMP WRONG WAY ARROW	4.00	0.00	4.00	EA	0.00	\$1,500.00	\$0.00
		0001	0400	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,200.00	0.00	1,200.00	LF	1,200.00	\$2.00	\$2,400.00
		0001	0410	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	2,000.00	\$2.00	\$4,000.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
11217-H05	J9I3597	0001	0420	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	60.00	0.00	60.00	LF	60.00	\$10.00	\$600.00
		0001	0430	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	151,103.00	0.00	151,103.00	LF	0.00	\$0.22	\$0.00
		0001	0440	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	123,088.00	0.00	123,088.00	LF	0.00	\$0.22	\$0.00
		0001	0450	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,530.00	0.00	7,530.00	LF	0.00	\$1.00	\$0.00
		0001	0460	6207001	PAVEMENT MARKING REMOVAL	4,060.00	0.00	4,060.00	LF	4,060.00	\$2.00	\$8,120.00
		0001	0470	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.35	\$16,769.52	\$5,869.33
		0001	0480	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	49,344.00	0.00	49,344.00	SQYD	13,584.00	\$2.15	\$29,205.60
		0001	0490	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,967.00	0.00	22,967.00	SQYD	5,522.10	\$6.20	\$34,237.02
		0001	0500	6252001	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	10,022.00	15,959.00	25,981.00	LB	25,981.00	\$3.85	\$100,026.85
		0001	0510	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	2,274.00	0.00	2,274.00	LB	2,274.00	\$3.85	\$8,754.90
		0001	0520	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,109.70	0.00	2,109.70	STA	0.00	\$24.50	\$0.00
		0010	0530	6061060	MGS GUARDRAIL	8,588.00	0.00	8,588.00	LF	8,388.00	\$32.00	\$268,416.00
		0010	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	10.00	0.00	10.00	EA	8.00	\$3,700.00	\$29,600.00
		0010	0550	6061080	MGS END ANCHOR	18.00	0.00	18.00	EA	16.00	\$1,500.00	\$24,000.00
		0010	0560	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	22.00	0.00	22.00	EA	20.00	\$3,000.00	\$60,000.00
		0070	0570	7034600	CURB BLOCKOUT	611.00	0.00	611.00	LF	611.00	\$125.07	\$76,417.77
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	28.00	28.00	EA	28.00	\$137.25	\$3,843.00
	Project .	J9I3597 - To	otal Value	e Posted to D	Date as of Report Generated Date							\$4,253,925.75
1217-H05 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	oort Generated Date							\$4,253,925.75



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

The info	ormation	below th	is line are deta	ils for Construction Signs (if ap	plicable	<u>).</u>						
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9I3597	0280	April 14, 2022	156	GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.972	Route I-155	2.00	10		10.00	20
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.474	Route I-155	2.00	10		10.00	20
				GO20-2 48x24 8.00 END ROAD WORK		1.5	Route I-155	2.00	8		8.00	16
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		2	Route I-155	2.00	18		18.00	36
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		2.5	Route I-155	4.00	12		12.00	48
		April 26, 2022	540	WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16			64
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.474	I-155 NBL	4.00	16			64
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.474	I-155 NBL	4.00	16			64
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		0.474	I-155 NBL	6.00	16			96
				WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16			64
				R4-1 36x48 12.00 DO NOT PASS		0.474	I-155 NBL	4.00	12			48
				See Special Sign Details	0.		I-155 NBL					
				CONST-3A 60x48 20.00 FINE SIGN		0.474	I-155 NBL	3.00	20			60
				WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		0.474	I-155 NBL	2.00	16			32
				R2-1 36x48 12.00 SPEED LIMIT XX		0.474	I-155 NBL	4.00	12			48
		June 10,	625	MO4-8a 24x18 3.00 END DETOUR		18.5	Route I-55	2.00	3			6
		2022	625	WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.4	Exit 1A Ramp 3	1.00	16			16
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.2	Exit 1A Ramp 3	1.00	16			16
				R11-2 48x30 10.00 ROAD CLOSED		0.1	Exit 1A Ramp 3	2.00	10			20
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		29.531	Route 84 / Route U & Ramps	4.00	16			64
				R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW		30.061	Route 84 / Route U & Ramps	4.00	6			24
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		3.2	Exit 1A Ramp 3	64.00	1			64
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		3.2	Exit 1A Ramp 3	253.50	1			253.5
				WO20-2 48x48 16.00 DETOUR AHEAD		3.2	Exit 1A Ramp 3	1.00	16			16
				WO3-4 8x48 16.00 BE PREPARED TO STOP		29.814	Route 84 / Route U & Ramps	4.00	16			64
				R2-1 36x48 12.00 SPEED LIMIT XX		29.741	Route 84 / Route U & Ramps	2.00	12			24
				R1-2 48 TRI 6.93 YIELD		29.741	Route 84 / Route U & Ramps	2.00	6.93			13.86
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		29.741	Route 84 / Route U & Ramps	2.00	6			12
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		29.631	Route 84 / Route U & Ramps	2.00	16			32
		November 15, 2022	352	WO8-9 48x48 16.00 LOW SHOULDER		0.473 - 6.976	NBL	8.00	16.00			128.00
				WO8-11 48x48 16.00 UNEVEN LANES		0.473 - 6.976	NBL	14.00	16.00			224.00
		November 16, 2022	210	WO20-3 48x48 16.00 ROAD CLOSED AHEAD		10.477	NBL I 155	1.00	16.00	W020-3a sign not in list		16.00
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		10.432	NBL I-155	1.00	16.00			16.00



Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work. The information below this line are details for Construction Signs (if applicable).

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J913597	0280	November 16, 2022	210	See Special Sign Details		9.995	NBL I 155	1.00		Special detour closed ahead assembly 56	32.00	32.00
				See Special Sign Details		0.339 and 196.973	NBL I 155 RAMP TO I 55 AND SBL I 55	2.00		Special detour route assembly 50Y	19.50	39.00
				See Special Sign Details		0.185 and 372.914	NBL I 55 and Route 84	2.00		Special detour route assembly 50E	19.50	39.00
				R11-2 48x30 10.00 ROAD CLOSED		0.004	NBL I 155 Ramp	1.00	10.00			10.00
				MO4-8a 24x18 3.00 END DETOUR		191.174	SBL I 55	1.00	3.00			3.00
				WO20-2 48x48 16.00 DETOUR AHEAD		9.826	NBL I 155	1.00	16.00			16.00
				See Special Sign Details		10.106 and 191.091	NBL I 155 AND NBL I 55	2.00		Special detour route assembly 50X	19.50	39.00
	0280 - To	otal										1867.36



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE	Material		3	May 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$3,097.20)	
					4	May 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$3,097.20)	
					5	Jun 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$3,097.20)	
					6	Jun 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$3,097.20)	
					7	Jul 1, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$3,097.20)	
					8	Jul 18, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$3,097.20)	
					9	Aug 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$3,097.20)	
					10	Sep 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 2, 2022	SYSTEM	(\$3,097.20)	
					11	Sep 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$3,097.20)	
					12	Sep 30, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Sep 30, 2022	SYSTEM	(\$3,097.20)	
					13	Oct 17, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$3,097.20)	
					14	Nov 1, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Nov 1, 2022	SYSTEM	(\$3,097.20)	
					15	Nov 15, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$3,097.20)	
					16	Dec 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0060	TYPE 5	Material						Estimate Exception 1 on the current Payment Estimate.
		AGGREGATE FOR BASE			16	Dec 2, 2022	SYSTEM	(\$3,097.20)	
					17	Dec 15, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$3,097.20)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
			Price FUEL		3	May 2, 2022	SYSTEM	\$50.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$50.33	
			Price FUEL -	Total				\$50.33	
	0060 -	Total						\$50.33	
	0070	MISC. AGGREGATE FOR BASE	Material		14	Nov 1, 2022	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					14	Nov 1, 2022	SYSTEM	(\$65,635.14)	
					15	Nov 15, 2022	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$65,635.14)	
					16	Dec 2, 2022	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					16	Dec 2, 2022	SYSTEM	(\$65,635.14)	
					17	Dec 15, 2022	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$65,635.14)	
				- Total				\$0.00	
			Material - To	al				\$0.00	
	0070 -	Total						\$0.00	
	0080	TYPE A3 SHOULDER	Material		4	May 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$4,401.05)	
					5	Jun 2, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$4,401.05)	
					6	Jun 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$4,401.05)	
					7	Jul 1, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$4,401.05)	
					8	Jul 18, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$4,401.05)	
					9	Aug 16,	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0080	TYPE A3 SHOULDER	Material	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		2022			Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$4,401.05)	
					10	Sep 2, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Sep 2, 2022	SYSTEM	(\$4,401.05)	
					11	Sep 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$4,401.05)	
					12	Sep 30, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					12	Sep 30, 2022	SYSTEM	(\$4,401.05)	
					13	Oct 17, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$4,401.05)	
					14	Nov 1, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					14	Nov 1, 2022	SYSTEM	(\$4,401.05)	
					15	Nov 15, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$4,401.05)	
					16	Dec 2, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					16	Dec 2, 2022	SYSTEM	(\$4,401.05)	
					17	Dec 15, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$4,401.05)	
			Material - To	- Total				\$0.00 \$0.00	
	0080 -	Total						\$0.00	
	0090	BIT. PAVEMENT MIXTURE	Other Item Adjustment	ACAD	12	Sep 30, 2022	holtb3	\$10,437.58	AC adjustments for period ending 09/30/2022
		PG64-22 (BP-1)	,		13	Oct 17, 2022	holtb3	\$3,282.35	AC adjustment for period ending 10/15/22.
					14	Nov 2, 2022	holtb3	\$47,819.04	AC adjustment for period ending 11/1/22.
				ACAD - Tot	al			\$61,538.97	
			Other Item A	l djustment - T	otal			\$61,538.97	
			Price FUEL		4	May 16, 2022	SYSTEM	\$312.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					12	Sep 30, 2022	SYSTEM	\$5,923.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					13	Oct 17, 2022	SYSTEM	\$997.15	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
					14	Nov 1, 2022	SYSTEM	\$14,526.99	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$21,760.03	



Dec 21, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J9I3597	0090	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Price FUEL -	Total				\$21,760.03												
	0090 -	Total						\$83,299.00												
	0120	ASPHALTIC CONCRETE	Other Item Adjustment	ACAD	12	Sep 30, 2022	holtb3	\$2,163.53	AC adjustment for period ending 09/30/2022											
		MIXTURE PG 70-22 (SP1			13	Oct 17, 2022	holtb3	\$65,077.17	AC adjustment for period ending 10/15/22.											
					14	Nov 2, 2022	holtb3	\$78,719.68	AC adjustment for period ending 11/1/22.											
				ACAD - Tota	al			\$145,960.38												
			Other Item A	.djustment - T	otal			\$145,960.38												
			Price FUEL		12	Sep 30, 2022	SYSTEM	\$1,140.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					13	Oct 17, 2022	SYSTEM	\$18,357.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
					14	Nov 1, 2022	SYSTEM	\$22,206.16	Reference Item Price Adjustment Index Adjustment Type applied is FUEL											
				- Total				\$41,704.01												
			Price FUEL -	Total				\$41,704.01												
	0120 -	Total						\$187,664.39												
	0130	TACK COAT	Material		12	Sep 30, 2022	SYSTEM	\$1,985.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					12	Sep 30, 2022	SYSTEM	(\$1,985.16)												
					13	Oct 17, 2022	SYSTEM	\$2,886.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 5 on the current Payment Estimate.											
					13	Oct 17, 2022	SYSTEM	(\$2,886.87)												
					14	Nov 1, 2022	SYSTEM	\$8,189.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
																14	Nov 1, 2022	SYSTEM	(\$8,189.95)	
								15	Nov 15, 2022	SYSTEM	\$8,189.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.								
					15	Nov 15, 2022	SYSTEM	(\$8,189.95)												
					16	Dec 2, 2022	SYSTEM	\$8,189.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					16	Dec 2, 2022	SYSTEM	(\$8,189.95)												
				- Total				\$0.00												
			Material - To	tal				\$0.00												
	0130 -	Total						\$0.00												
	0135	MISC. NON STANDARD TACK COAT	Material		12	Sep 30, 2022	SYSTEM	\$1,508.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					12	Sep 30, 2022	SYSTEM	(\$1,508.00)												
				13	13	Oct 17, 2022	SYSTEM	\$33,722.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.											
					13	Oct 17, 2022	SYSTEM	(\$33,722.00)												
					14	Nov 1, 2022	SYSTEM	\$55,806.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.											
					14	Nov 1, 2022	SYSTEM	(\$55,806.40)												



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks
			Туре	Adjustment Type	Number	Date	Ву		
J9I3597	0135	MISC. NON STANDARD TACK COAT	Material		15	Nov 15, 2022	SYSTEM	\$55,806.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$55,806.40)	
					16	Dec 2, 2022	SYSTEM	\$55,806.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					16	Dec 2, 2022	SYSTEM	(\$55,806.40)	
					17	Dec 15, 2022	SYSTEM	\$55,806.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$55,806.40)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0135 -	Total						\$0.00	
	0150	CONCRETE PAVEMENT (9 IN. NON-REINF)	Material		3	May 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$12,672.00)	
					4	May 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$12,672.00)	
					5	Jun 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$12,672.00)	
					6	Jun 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$12,672.00)	
					7	Jul 1, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$12,672.00)	
					8	Jul 18, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$12,672.00)	
					9	Aug 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$12,672.00)	
					10	Sep 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Sep 2, 2022	SYSTEM	(\$12,672.00)	
					11	Sep 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$12,672.00)	
					12	Sep 30, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.



ct	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
97	0150	CONCRETE PAVEMENT (9	Material		12	Sep 30, 2022	SYSTEM	(\$12,672.00)	
		IN. NON-REINF)			13	Oct 17, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$12,672.00)	
					14	Nov 1, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Nov 1, 2022	SYSTEM	(\$12,672.00)	
					15	Nov 15, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$12,672.00)	
					16	Dec 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	Dec 2, 2022	SYSTEM	(\$12,672.00)	
					17	Dec 15, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$12,672.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Price FUEL		3	May 2, 2022	SYSTEM	\$120.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL
				- Total				\$120.81	
			Price FUEL -	Total				\$120.81	
	0150 -							\$120.81	
	0160	PIPE AGGREGATE PAVEMENT EDGE DRAIN	Material		4	May 16, 2022	SYSTEM	\$14,335.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payme Estimate Exception 10 on the current Payment Estimate.
		LUGE DIVAN			4	May 16, 2022	SYSTEM	(\$14,335.50)	
					5	Jun 2, 2022	SYSTEM	\$14,335.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payme Estimate Exception 10 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$14,335.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
	0170	OUTLET PIPES AND SPLASH PADS	Material		4	May 16, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payme Estimate Exception 13 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$10,800.00)	
					5	Jun 2, 2022	SYSTEM	\$10,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payme Estimate Exception 13 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$10,800.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0170 -	Total						\$0.00	
	0190	FURN & PLACE CONC MATL FOR FULL DEPTH	Material		4	May 16, 2022	SYSTEM	\$19,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payme Estimate Exception 17 on the current Payment Estimate.



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J9I3597	0190	FURN & PLACE CONC MATL	Material		4	May 16, 2022	SYSTEM	(\$19,800.00)												
		FOR FULL DEPTH			5	Jun 2, 2022	SYSTEM	\$39,600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.											
					5	Jun 2, 2022	SYSTEM	(\$39,600.00)												
				- Total				\$0.00												
			Material - Tot	tal				\$0.00												
	0190 -	Total						\$0.00												
	0200	SUBGRADE COMPACTION (6 IN. DEPTH)	Material		4	May 16, 2022	SYSTEM	\$54.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.											
		(PAVEM			4	May 16, 2022	SYSTEM	(\$54.00)												
					5	Jun 2, 2022	SYSTEM	\$106.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.											
					5	Jun 2, 2022	SYSTEM	(\$106.80)												
					6	Jun 16, 2022	SYSTEM	\$106.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.											
					6	Jun 16, 2022	SYSTEM	(\$106.80)												
					7	Jul 1, 2022	SYSTEM	\$298.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.											
					7	Jul 1, 2022	SYSTEM	(\$298.80)												
					8	Jul 18, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.											
					8	Jul 18, 2022	SYSTEM	(\$504.60)												
					9	Aug 16, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.											
							9	Aug 16, 2022	SYSTEM	(\$504.60)										
					10	Sep 2, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.											
					10	Sep 2, 2022	SYSTEM	(\$504.60)												
							11	Sep 16, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.									
					11	Sep 16, 2022	SYSTEM	(\$504.60)												
					12	Sep 30, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user holtb3 overridding Payment Estimate Exception 14 on the current Payment Estimate.											
					12	Sep 30, 2022	SYSTEM	(\$504.60)												
									13	Oct 17, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 14 on the current Payment Estimate.							
					13	Oct 17, 2022	SYSTEM	(\$504.60)												
														14			14	Nov 1, 2022	SYSTEM	\$504.60
									14	Nov 1, 2022	SYSTEM	(\$504.60)								
					15	Nov 15,	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment											



FURNISHING AND INST FURNISHING AND INST Image: Furnishing and the current Payment Estimate Image: Furnishing and the current Payment Estimate 4 May 16 SYSTEM (\$880.00) 5 Jun 2, 2022 SYSTEM \$1,760.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. 6 Jun 2, 2022 SYSTEM \$1,760.00 Estimate Exception 21 on the current Payment Estimate. 7 Total SYSTEM \$1,760.00 Image: Strength and										
1557 020 DSURGINANE IN DEPTH IN IN DEPTH IN	roject	Line	Description						Amount	Remarks
COMPACTION (F) (F)(V) R) (F)(V) R					Туре					
(PAVEM Image: Part of the second	13597	0200	COMPACTION (6	Material			2022			
View View <th< td=""><td></td><td></td><td></td><td></td><td></td><td>15</td><td></td><td>SYSTEM</td><td>(\$504.60)</td><td></td></th<>						15		SYSTEM	(\$504.60)	
View View <th< td=""><td></td><td></td><td></td><td></td><td></td><td>16</td><td></td><td>SYSTEM</td><td>\$1,930.80</td><td>Estimate Item Adjustment (0003) due to user holtb3 overridding Payment</td></th<>						16		SYSTEM	\$1,930.80	Estimate Item Adjustment (0003) due to user holtb3 overridding Payment
View View <th< td=""><td></td><td></td><td></td><td></td><td></td><td>16</td><td></td><td>SYSTEM</td><td>(\$1,930.80)</td><td></td></th<>						16		SYSTEM	(\$1,930.80)	
Control Control <t< td=""><td></td><td></td><td></td><td></td><td></td><td>17</td><td></td><td>SYSTEM</td><td>\$1,930.80</td><td>Estimate Item Adjustment (0006) due to user holtb3 overridding Payment</td></t<>						17		SYSTEM	\$1,930.80	Estimate Item Adjustment (0006) due to user holtb3 overridding Payment
Idanial - Total Unrun Overrun Overrun Dec 2. SYSTEM (61,246,80) Overrun - Total						17		SYSTEM	(\$1,930.80)	
Overrun Overrun 16 Doc.2 SYSTEM (S1.248.80) Overrun - Total Overrun - Total (S1.248.80) Overrun - Total (S1.248.80) Overrun - Total (S1.248.80) Overrun - Total (S1.248.80) Overrun - Total (S1.248.80) Overrun - Total (S1.248.80) Overrun - Total Overrun - Total (S1.662.40) Overrun - Total (S1.662.40) Overrun - Total Overrun - Total (S1.662.40) Overrun - Total (S1.662.40) Overrun - Total Overrun - Total (S1.662.40) This edjustment offsets the original system-generated Material Payment Estimate Icondyloa I over woodkit overridding Payment Icondyloa I over over I over I I					- Total				\$0.00	
Control <				Material - To	tal				\$0.00	
Overrun - Total Overrun - Total (\$1,246.80) 0200 - Total Overrun - Total (\$1,662.40) 0210 Type I ORS II IN Type I O				Overrun	Overrun	16		SYSTEM	(\$1,246.80)	
0200 - Total CVPCE 1 OR S FOR RASE (N) FOR RASE (N) FOR RASE (N) TH Overrun TO TO TO TO TO TO TO TO TO TO TO TO TO					Overrun - T	otal	1		(\$1,246.80)	
0200 - Total CVPCE 1 OR S FOR RASE (N) FOR RASE (N) FOR RASE (N) TH Overrun TO TO TO TO TO TO TO TO TO TO TO TO TO				Overrun - To						
0210 FOR BASE (1 H) CVERTUR - FOR BASE (1 H) H Overrun 1 06 Dec.2 (202 SYSTEM (216-240) (216-240) 0210 - Total Overrun - Total (31.662.40) (31.662.40) 0230 C020 - Total DVMEL BAR (DRLING, FARDINST AND INST Material 4 May 16, 2022 SYSTEM (38.60.00) 0240 - Total		0200	Total							
AGGREGATE FOR BASE (A), TH Querrun - Total C11.000 0210 - Total 097000 101 011 0110000000000000000000000000000000000				Overrun	0.46	16	Dec 2	QVOTEM		
Overrun - Total Overrun - Total (\$1,62.40) 0210 - Total (\$1,62.40) This adjustment officies the original system generated Material Payment. Estimate Exception 21 on the current Payment Estimate. 0230 POWEL BAR ND INST 4 May 16, 2022 SYSTEM \$880.00 This adjustment officies the original system-generated Material Payment Estimate Estimate Exception 21 on the current Payment Estimate. 4 May 16, 2022 SYSTEM \$1,760.00 This adjustment offices the original system-generated Material Payment Estimate Exception 21 on the current Payment Estimate. • • • \$1,760.00 This adjustment offices on averaged overnun adjustment for installed quantity on previous payment estimate. • • • \$1,760.00 Internet • \$0.00 • • • \$1,760.00 Internet • \$0.00 • • • \$1,760.00 Internet • \$0.00 • • • \$0.00 Internet • \$0.00 • • • \$0.000 Internet • \$0.000 • • • \$1.000 Payment		0210	AGGREGATE FOR BASE (4 IN.	Overrun				SYSTEM		
O210 - Total (\$1,62,40) 0230 DOWEL BAR (DRILLING, FURNISHING ANDINST Material 4 May 16, 2022 SYSTEM \$880.00 This adjustment offsets the original system-generated Material Payment Estimate Tex-applica 21 on the current Payment Estimate. 4 May 16, 2022 SYSTEM \$880.00 This adjustment offsets the original system-generated Material Payment Estimate Tex-applica 21 on the current Payment Estimate. 6 Jun 2, 2022 SYSTEM \$1,760.00 This adjustment offsets the original system-generated Material Payment Estimate Tex-applica 21 on the current Payment Estimate. 6 Jun 2, 2022 SYSTEM \$1,760.00 This adjustment offsets the original system-generated Material Payment Estimate Tex-applica 21 on the current Payment Estimate. 6 Jun 2, 2022 SYSTEM \$1,760.00 This adjustment offsets the original system-generated Material Payment Estimate Tex-applica 21 on the current Payment Estimate. 7 Total Total Start 30.00 Start 30.00 0verrun - Total Start 30.00 Start 30.00 This adjustment offsets the original system-generated Material Payment Estimate Tex-applica 21 on the current Payment Estimate. 0220 - Total Overrun - Total \$0.000 This adjustment offsets the original system			TH			otal				
0230 DOWEL BAR (DRULING DRUCE) Material (DRULING DRUCE) Material 4 May 16, 2022 SYSTEM \$880.00 This adjustment offsets the original system-generated Material Payment. Estimate Exception 21 on the current Payment Estimate. 4 May 16, 2022 SYSTEM \$1760.00 This adjustment offsets the original system-generated Material Payment. Estimate Exception 21 on the current Payment Estimate. 5 Jun 2, 2022 SYSTEM \$1760.00 This adjustment offsets the original system-generated Material Payment. Estimate Exception 21 on the current Payment Estimate. 6 Jun 2, 2022 SYSTEM \$1760.00 This adjustment offsets the original system-generated Material Payment. 6 Jun 2, 2022 SYSTEM \$1760.00 This adjustment offsets the original system-generated Material Payment. 6 Jun 2, 2022 SYSTEM \$1760.00 This adjustment offsets the original system-generated Material Payment. 6 Jun 2, 2022 SYSTEM \$1056.00 Unit price based on averaged overun adjustments for installed quantity on provide your payment estimate. Price Adjustments of 's.00000 - 's.00000, 's.000000, 's.00000, 's.00000, 's.00000, 's.00000, 's.000				Overrun - To	tal				(\$1,662.40)	
(CRLLING, AND INST AND INST		0210 -	Total						(\$1,662.40)	
		0230	(DRILLING, FURNISHING	Material		4		SYSTEM	\$880.00	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment
Value Value Value Value SYSTEM (\$1,760.00) - Total - Total - Total \$0.00 SYSTEM (\$1,760.00) Verrun 0 - Total \$0.00 SYSTEM (\$1,760.00) Verrun 12 \$9.30 \$YSTEM (\$1,056.00) Introduction of the current Payment Estimate. Verrun 12 \$9.30 \$YSTEM (\$1,056.00) Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of '8.00000 - 8.00000, '8 applied (fi non-zero). Verrun - Total Verrun - Total \$0.00 Verrun - Total \$0.00 Verrun - Total 2022 \$YSTEM \$1,055.00 Unit price based on averaged overrun adjustments of '8.00000 - 8.00000, '8 applied (fi non-zero). Verrun - Total Verrun - Total \$0.00 Verrun - Total \$0.00 0260 DOWEL BAR Material - Total \$9.57EM \$40,500.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 0260 DOWEL BAR Material - Total \$9.57EM \$40,500.00 Thi			AND INST			4		SYSTEM	(\$880.00)	
$ \begin{array}{ c c c c } \hline \begin{tabular}{ c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c } \hline \begin{tabular}{ c c c c c c c c } \hline \begin{tabular}{ c c c c c c c c c c c c c c c c c c c$						5		SYSTEM	\$1,760.00	Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment
Material - Total Source Source Overrun Overrun 12 Sep 30, 2022 SYSTEM (\$1.056.00) 13 Oct 17, 2022 SYSTEM \$1.066.00 Unit price based on averaged overrun adjustments for installed quantity on previous payment estimates. Price Adjustments of '.8.00000 - 8.00000, 's applied (if non-zero). Overrun - Total State \$0.00 Previous payment estimates. Price Adjustments of '.8.00000 - 8.00000, 's applied (if non-zero). Overrun - Total State \$0.00 SYSTEM \$0.00 Overrun - Total \$0.00 This adjustment offsets the original system-generated Material Payment. Estimate Leen Adjustment (0010) due to user woodsk1 overridding Payment Estimate. 0280 DOWEL BAR RETROFIT 4 May 16, 2022 SYSTEM \$40,500.00 5 Jun 2, 2022 SYSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment. Estimate Exception 22 on the current Payment Estimate. 0260 - Total - Total \$1022 SYSTEM \$143,640.00 0260 - Total State \$102, \$12, \$12, \$12, \$12, \$12, \$12, \$12, \$1						5		SYSTEM	(\$1,760.00)	
Overrun Overrun 12 Sep 30, SYSTEM (\$1,056.00) Unit price based on averaged overrun adjustments for installed quantity on applied (if non-zero). Overrun - Total Overrun - Total \$1,056.00 Unit price based on averaged overrun adjustments of '8.00000 - 8.00000, is applied (if non-zero). Overrun - Total Overrun - Total \$0.00 \$0.000 \$0.000 Overrun - Total \$0.00 \$0.000 \$0.000 \$0.000 Overrun - Total \$0.00 \$0.000 This adjustment offsets the original system-generated Material Payment. Estimate Exception 22 on the current Payment Estimate. 0260 DOWEL BAR RETROFIT Material \$40 \$2022 \$SYSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment. 0260 DOWEL BAR RETROFIT \$4 May 16, 2022 \$SYSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment. 0260 DOWEL BAR RETROFIT \$100,2, 2022 \$SYSTEM \$143,640.00 This adjustment offsets the original system-generated Material Payment. 0260- Total -Total \$\$0.00 \$\$143,640.00 \$\$143,640.00 \$\$143,640.00					- Total				\$0.00	
0200 - Total 0200 - Total <td< td=""><td></td><td></td><td></td><td>Material - To</td><td>tal</td><td></td><td></td><td></td><td>\$0.00</td><td></td></td<>				Material - To	tal				\$0.00	
0202 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				Overrun	Overrun	12		SYSTEM	(\$1,056.00)	
Overrun - Total \$0.00 0230 - Total \$0.00 0260 DOWEL BAR RETROFIT Material 4 May 16, 2022 \$YSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment Estimate. 0260 DOWEL BAR RETROFIT 4 May 16, SYSTEM 2022 \$YSTEM (\$40,500.00) This adjustment offsets the original system-generated Material Payment Estimate. 1 4 May 16, SYSTEM 2022 \$YSTEM (\$40,500.00) This adjustment offsets the original system-generated Material Payment Estimate. 1 5 Jun 2, 2022 \$YSTEM (\$143,640.00) This adjustment (0010) due to user woodsk1 overridding Payment Estimate. 0260 - Total - Total \$\$0.00 \$\$0.00 This adjustment offsets the original system-generated Material Payment Estimate. 0260 - Total - Total \$\$0.00 \$\$143,640.00 This adjustment (0010) due to user woodsk1 overridding Payment Estimate. 0260 - Total - Total \$\$0.00 \$\$143,640.00 \$\$0.00 0270 MISC. Material - Total \$\$0.00 \$\$143,640.00 This adjustment offsets the original system-generated Material Payment Estimate. 0270 MISC. Material - Total \$\$0.00 \$\$143,640.00 This						13		SYSTEM	\$1,056.00	
O230 - Total S0.00 0260 DOWEL BAR RETROFIT Material May 16, 2022 SYSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 4 May 16, 2022 SYSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 5 Jun 2, 2022 SYSTEM \$143,640.00 This adjustment (0010) due to user woodsk1 overridding Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate. 6 Jun 2, 2022 SYSTEM \$143,640.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 7 Total SYSTEM \$143,640.00 This adjustment offsets the original system-generated Material Payment Estimate Exception 22 on the current Payment Estimate. 0260 - Total Stote \$0.00 Stote \$0.00 0270 MiSc. Material \$101,2 \$YSTEM \$720.00 This adjustment offsets the original system-generated Material Payment					Overrun - T	otal			\$0.00	
0260 DOWEL BAR RETROFIT Material 4 May 16, 2022 SYSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment Estimate. 4 May 16, 2022 SYSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment Estimate. 4 May 16, 2022 SYSTEM \$40,500.00 This adjustment offsets the original system-generated Material Payment Estimate. 5 Jun 2, 2022 SYSTEM \$143,640.00 This adjustment offsets the original system-generated Material Payment Estimate. • • • \$1002 SYSTEM \$143,640.00 • • • \$2022 SYSTEM \$143,640.00 • • • \$2022 SYSTEM \$143,640.00 • • • \$2022 SYSTEM \$143,640.00 • • • • \$0.000 • • • • • \$0.000 • • • • • • \$0.000 • • • • • \$0.000 • • •				Overrun - To	tal				\$0.00	
RETROFIT RETROFIT 2022 RETROFIT 2022 Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate. 4 May 16, 2022 SYSTEM (\$40,500.00) 5 Jun 2, 2022 SYSTEM \$143,640.00 Frita - Total SYSTEM \$143,640.00 Retrial - Total SYSTEM \$143,640.00 This adjustment offsets the original system-generated Material Payment Estimate. 0260 - Total - Total SYSTEM \$143,640.00 This adjustment (0010) due to user woodsk1 overridding Payment Estimate. 0270 MISC. Material 5 Jun 2, SYSTEM \$1202 0270 MISC. Material 5 Jun 2, SYSTEM \$720.00		0230 -	Total						\$0.00	
Vertical Control Vertical Control Vertical Control Vertical Control Vertical Control Vertical Contro Vertical Control Vertical		0260		Material		4		SYSTEM	\$40,500.00	Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment
0260 - Total 2022 \$VSTEM \$\$143,640.00\$ 0260 - Total \$\$0.00 \$\$0.00 0270 MISC. Material \$\$140,2 \$YSTEM \$\$143,640.00\$ 0270 MISC. Material \$\$140,2 \$YSTEM \$\$0.00 0270 MISC. Material \$\$140,2 \$YSTEM \$\$100,0						4		SYSTEM	(\$40,500.00)	
O260 - Total Solution						5		SYSTEM	\$143,640.00	Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment
Material - Total \$0.00 0260 - Total \$0.00 0270 MISC. Material 5 Jun 2, SYSTEM \$720.00 This adjustment offsets the original system-generated Material Payment						5		SYSTEM	(\$143,640.00)	
O260 - Total \$0.00 0270 MISC. Material 5 Jun 2, SYSTEM \$720.00 This adjustment offsets the original system-generated Material Payment					- Total				\$0.00	
0270 MISC. Material 5 Jun 2, SYSTEM \$720.00 This adjustment offsets the original system-generated Material Payment				Material - To	tal				\$0.00	
		0260 -	Total						\$0.00	
REPAIR Estimate Exception 250 the current Payment Estimate.		0270	PAVEMENT	Material		5	Jun 2, 2022	SYSTEM	\$720.00	Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment



Dec 21, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks															
J9I3597	0270	MISC. PAVEMENT	Material		5	Jun 2, 2022	SYSTEM	(\$720.00)																
		REPAIR		- Total				\$0.00																
			Material - To	tal				\$0.00																
	0270 -	Total						\$0.00																
	0310	TYPE III MOVEABLE BARRICADE	Overrun	Overrun	16	Dec 2, 2022	SYSTEM	(\$300.00)																
		DAIMICADE		Overrun - T	otal			(\$300.00)																
			Overrun - To	tal				(\$300.00)																
	0310 -	Total		_	_	_		(\$300.00)																
	0420	TEMPORARY REMOVABLE MARKING TAPE,	Material		6	Jun 16, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
		24 IN.			6	Jun 16, 2022	SYSTEM	(\$600.00)																
					7	Jul 1, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
					7	Jul 1, 2022	SYSTEM	(\$600.00)																
					8	Jul 18, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
					8	Jul 18, 2022	SYSTEM	(\$600.00)																
					9	Aug 16, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
					9	Aug 16, 2022	SYSTEM	(\$600.00)																
					10	Sep 2, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
					10	Sep 2, 2022	SYSTEM	(\$600.00)																
					11	Sep 16, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.															
												11	Sep 16, 2022	SYSTEM	(\$600.00)									
						12	Sep 30, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.														
					12	Sep 30, 2022	SYSTEM	(\$600.00)																
					13	Oct 17, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.															
					13	Oct 17, 2022	SYSTEM	(\$600.00)																
					14	Nov 1, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.															
					14	Nov 1, 2022	SYSTEM	(\$600.00)																
					15	Nov 15, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.															
			15	15	Nov 15, 2022	SYSTEM	(\$600.00)																	
													1	10	-					16	Dec 2, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					16	Dec 2, 2022	SYSTEM	(\$600.00)																



Project	Line	Description	Adjustment	Other	Est.	Created	Created	Amount	Remarks							
			Туре	Adjustment Type	Number	Date	Ву									
J9I3597	0420	TEMPORARY REMOVABLE MARKING TAPE,	Material		17	Dec 15, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
		24 IN.			17	Dec 15, 2022	SYSTEM	(\$600.00)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0420 -	Total						\$0.00								
	0470	MISC. PAVEMENT MARKINGS	Material		15	Nov 15, 2022	SYSTEM	\$5,869.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					15	Nov 15, 2022	SYSTEM	(\$5,869.33)								
					16	Dec 2, 2022	SYSTEM	\$5,869.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.							
					16	Dec 2, 2022	SYSTEM	(\$5,869.33)								
					17	Dec 15, 2022	SYSTEM	\$5,869.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.							
					17	Dec 15, 2022	SYSTEM	(\$5,869.33)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
	0470 -	Total						\$0.00								
		Material		7	Jul 1, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.								
				IANE									7	Jul 1, 2022	SYSTEM	(\$38,584.70)
							8	Jul 18, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user george2 overridding Payment Estimate Exception 14 on the current Payment Estimate.					
												8	Jul 18, 2022	SYSTEM	(\$38,584.70)	
													9	Aug 16, 2022	SYSTEM	\$38,584.70
					9	Aug 16, 2022	SYSTEM	(\$38,584.70)								
								10	Sep 2, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user george2 overridding Payment Estimate Exception 14 on the current Payment Estimate.				
					10	Sep 2, 2022	SYSTEM	(\$38,584.70)								
										11	Sep 16, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user george2 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
					11	Sep 16, 2022	SYSTEM	(\$38,584.70)								
						12	Sep 30, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.						
								12 Sep 30, SYSTEM (\$38,584.70) 2022								
					13	Oct 17, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
					13	Oct 17, 2022	SYSTEM	(\$38,584.70)								
					14	Nov 1, 2022	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment Estimate Exception 19 on the current Payment Estimate.							
					14	Nov 1,	SYSTEM	(\$100,026.85)								



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0500	UNDERSEAL	Material			2022			
		MATL HIGH DENSITY POLYURETHANE			15	Nov 15, 2022	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$100,026.85)	
					16	Dec 2, 2022	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					16	Dec 2, 2022	SYSTEM	(\$100,026.85)	
					17	Dec 15, 2022	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$100,026.85)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0500 -	- Total						\$0.00	
	0510	SLAB JACKING MATL HIGH DENSITY POLYURETH	Material		7	Jul 1, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$8,754.90)	
					8	Jul 18, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$8,754.90)	
					9	Aug 16, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$8,754.90)	
					10	Sep 2, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					10	Sep 2, 2022	SYSTEM	(\$8,754.90)	
					11	Sep 16, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$8,754.90)	
					12	Sep 30, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					12	Sep 30, 2022	SYSTEM	(\$8,754.90)	
					13	Oct 17, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$8,754.90)	
					14	Nov 1, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.
					14	Nov 1, 2022	SYSTEM	(\$8,754.90)	
					15	Nov 15, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$8,754.90)	
					16	Dec 2, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user holtb3 overridding Payment



Lin	e Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
051		Material						Estimate Exception 22 on the current Payment Estimate.
	MATL HIGH DENSITY POLYURETH			16	Dec 2, 2022	SYSTEM	(\$8,754.90)	
				17	Dec 15, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.
				17	Dec 15, 2022	SYSTEM	(\$8,754.90)	
			- Total				\$0.00	
		Material - To	tal				\$0.00	
051	0 - Total						\$0.00	
053	60 MGS GUARDRAIL	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$116,280.48)	Payment Estimate Item Adjustment generated Stockpile Transaction
				3	May 2, 2022	SYSTEM	(\$52,979.50)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				(\$169,259.98)	
		Construction	n Stockpile - 1	「otal			(\$169,259.98)	
		Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$173,295.75	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$173,295.75	
		Construction	n Stockpile S⊺	TMI - Tota			\$173,295.75	
053	0 - Total						\$4,035.77	
054	APP. TRANS	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$16,880.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	SEC (REG/NO CURB)		- Total				(\$16,880.00)	
		Construction Stockpile - Total					(\$16,880.00)	
		Construction Stockpile STMI	1	Mar 16, 2022	SYSTEM	\$21,100.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
		SIMI	- Total				\$21,100.00	
		Construction	n Stockpile S	TMI - Tota			\$21,100.00	
054	l0 - Total						\$4,220.00	
055	60 MGS END ANCHOR	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$5,130.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				3	May 2, 2022	SYSTEM	(\$8,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				(\$13,680.00)	
		Construction	n Stockpile - 1	「otal			(\$13,680.00)	
		Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$15,390.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			- Total				\$15,390.00	
		Construction	n Stockpile S	「MI - Tota			\$15,390.00	
055	i0 - Total						\$1,710.00	
056	CRASHWORTHY	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
				2 3		SYSTEM SYSTEM		Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
	CRASHWORTHY END TERMINAL	Stockpile	- Total	3	2022 May 2,		(\$19,500.00) (\$19,500.00) (\$39,000.00)	
	CRASHWORTHY END TERMINAL	Stockpile	- Total Stockpile - 1	3 Fotal	2022 May 2, 2022	SYSTEM	(\$19,500.00) (\$19,500.00) (\$39,000.00) (\$39,000.00)	Payment Estimate Item Adjustment generated Stockpile Transaction
	CRASHWORTHY END TERMINAL	Stockpile	1 Stockpile - 1	3	2022 May 2,		(\$19,500.00) (\$19,500.00) (\$39,000.00) (\$39,000.00) \$42,900.00	
	CRASHWORTHY END TERMINAL	Stockpile Construction Construction Stockpile STMI	Stockpile - 1 - Total	3 Fotal 1	2022 May 2, 2022 Mar 16, 2022	SYSTEM	(\$19,500.00) (\$19,500.00) (\$39,000.00) (\$39,000.00) \$42,900.00 \$42,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction
056	CRASHWORTHY END TERMINAL (MASH)	Stockpile Construction Construction Stockpile STMI	1 Stockpile - 1	3 Fotal 1	2022 May 2, 2022 Mar 16, 2022	SYSTEM	(\$19,500.00) (\$19,500.00) (\$39,000.00) (\$39,000.00) \$42,900.00 \$42,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction
056	CRASHWORTHY END TERMINAL (MASH)	Stockpile Construction Stockpile STMI Construction	Stockpile - 1 - Total	3 Total 1 TMI - Total	2022 May 2, 2022 Mar 16, 2022	SYSTEM	(\$19,500.00) (\$19,500.00) (\$39,000.00) (\$39,000.00) \$42,900.00 \$42,900.00 \$42,900.00 \$3,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction Payment Estimate Item Adjustment generated Stockpile Transaction
056	CRASHWORTHY END TERMINAL (MASH)	Stockpile Construction Construction Stockpile STMI	Stockpile - 1 - Total	3 Fotal 1	2022 May 2, 2022 Mar 16, 2022	SYSTEM	(\$19,500.00) (\$19,500.00) (\$39,000.00) (\$39,000.00) \$42,900.00 \$42,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9I3597	0570	CURB BLOCKOUT	Material		8	Jul 18, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					8	Jul 18, 2022	SYSTEM	(\$76,417.77)					
					9	Aug 16, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					9	Aug 16, 2022	SYSTEM	(\$76,417.77)					
					10	Sep 2, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					10	Sep 2, 2022	SYSTEM	(\$76,417.77)					
					11	Sep 16, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.				
					11	Sep 16, 2022	SYSTEM	(\$76,417.77)					
					12	Sep 30, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.				
					12	Sep 30, 2022	SYSTEM	(\$76,417.77)					
									13	Oct 17, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$76,417.77)					
					14	Nov 1, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0020) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					14	Nov 1, 2022	SYSTEM	(\$76,417.77)					
					15	Nov 15, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 23 on the current Payment Estimate.				
					15	Nov 15, 2022	SYSTEM	(\$76,417.77)					
					16	Dec 2, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user holtb3 overridding Payment Estimate Exception 23 on the current Payment Estimate.				
					16	Dec 2, 2022	SYSTEM	(\$76,417.77)					
					17	Dec 15, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
					17	Dec 15, 2022	SYSTEM	(\$76,417.77)					
				- Total			\$0.00						
	0570 -	Total	Material - To					\$0.00					
		SEQUENTIAL	Material		14	Nov 1	SYSTEM	\$0.00	This adjustment offsets the original system generated Material Development				
	5002	FLASHING WARNING LIGHT	Material		14	Nov 1, 2022		\$3,843.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.				
					14	Nov 1, 2022	SYSTEM	(\$3,843.00)					
									15	Nov 15, 2022	SYSTEM	\$3,843.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$3,843.00)					
					16	Dec 2, 2022	SYSTEM	\$3,843.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.				



Dec 21, 2022

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	5002	SEQUENTIAL FLASHING WARNING LIGHT			16	Dec 2, 2022	SYSTEM	(\$3,843.00)	
				- Total				\$0.00	
	Material - Total							\$0.00	
	5002 - Total							\$0.00	
J9I3597 ·	Total						\$281,791.10		
Overall -	Total						\$281,791.10		