

#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 16, 2023

Progress Estimate Number 19		Contract ID Prime Contractor	211217-H05 Apex Paving Co.	Pay Period Start Pay Period End	January 2, 2023 January 15, 2023	Original Contract Amount Net Change Order Amount Current Contract Amount	\$10,080,771.09 \$258,097.15 \$10,338,868.24
Approval Date							By User
January 16, 2023		(	Generated and App	proved (and should l	be considered Dra	ft) at the Project Office Level by	holtb3
January 17, 2023		Revi	ewed and Approve	d (and should be co	nsidered Draft) at	the Resident Engineer Level by	bollis1
January 18, 2023			Re	viewed and Approve	ed at the Central O	ffice Controllers Office Level by	ramses1
Original Comp	letion Date	Current Comp	Current Completion Date Actual Completion Date % of Current Contract Ame				
July 31, 2	2023	July 31, 2	July 31, 2023 41.869				

	Contract Informational Dates									
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract							
Acceptance Date										
Awarded Date	January 5, 2022	January 5, 2022								
Letting Date	December 17, 2021	December 17, 2021								
Notice to Proceed Date	March 7, 2022	March 7, 2022								
Open to Traffic Date										
Work Began Date	April 14, 2022	April 14, 2022								

Contract Total Pay For Estimate No. 19											
		This Estimate	Previous	To Date							
211217-H05											
	Total Posted Items Pay Gross Item Adjustments Incentive Disincentive Liquidated Damage Other Contract Adjustments	\$54,248.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$4,273,365.75 \$281,791.10 \$0.00 \$0.00 \$0.00 \$83,997.18 \$4,639,154.03	\$4,327,613.75 \$281,791.10 \$0.00 \$0.00 \$0.00 \$83,997.18 \$4,693,402.03							
Contract Total Pa	ayable This Estimate:	\$54,248.00	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	+ 1,000,000							

#### Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9I3597	0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	SQYD	\$225.000	64	\$14,400.00
	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	LF	\$10.000	276	\$2,760.00
	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR	EA	\$8.000	136	\$1,088.00
	0260	6134001	DOWEL BAR RETROFIT	EA	\$90.000	384	\$34,560.00
	0270	6139903	MISC.TYPE E EXPANSION JOINT	LF	\$30.000	48	\$1,440.00
	0320	6161033	DIRECTIONAL INDICATOR BARRICADE	EA	\$0.000	146	\$0.00
Project J9I	3597 - Tot	al					\$54,248.00
Overall - T	otal						\$54,248.00

#### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)				-258.1	\$12.00	(\$3,097.20)
	0060	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)			This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on	258.1	\$12.00	\$3,097.20

Revision 4/1/2020 Page 1 of 25



# Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 16, 2023

Progress Estimate Number
19
Contract ID 211217-H05 Pay Period Start January 2, 2023 Original Contract Amount Substituting Substitution Substituting Substituting

						· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
t Liner No		Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
7				the current Payment Estimate.			
007	0 MISC.	Material			-1,482.61	\$44.27	(\$65,635.14
007	0 MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.	1,482.61	\$44.27	\$65,635.14
008	0 TYPE A3 SHOULDER	Material			-117.33	\$37.51	(\$4,401.05
008	0 TYPE A3 SHOULDER	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.	117.33	\$37.51	\$4,401.05
013	5 MISC.	Material			-21,464	\$2.60	(\$55,806.40
013	5 MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.	21,464	\$2.60	\$55,806.40
015	0 CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material			-140.8	\$90.00	(\$12,672.00
015	0 CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.	140.8	\$90.00	\$12,672.00
020	O SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material			-321.8	\$6.00	(\$1,930.80
020	0 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.	321.8	\$6.00	\$1,930.80
042	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material			-60	\$10.00	(\$600.00
042	0 TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.	60	\$10.00	\$600.00
047	0 MISC.	Material			-0.35	\$16,769.52	(\$5,869.33
047	0 MISC.	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.	0.35	\$16,769.52	\$5,869.33
050	0 UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	SITY			-25,981	\$3.85	(\$100,026.85
050	0 UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.	25,981	\$3.85	\$100,026.85
051	0 SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	Material			-2,274	\$3.85	(\$8,754.90)

Revision 4/1/2020 Page 2 of 25



#### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: January 16, 2023

Prog	Progress Estimate Number 19				I217-H05 ex Paving Co.	Pay Period End January 15, 2023 Net Ch	al Contract A ange Order A t Contract Ar	Amount \$2	\$10,080,771.09 \$258,097.15 \$10,338,868.24	
Project Number	Line No.							Line Item Adjustment Unit Price	Adjustment amount	
J9I3597	0510		MATERIAL I DENSITY RETHANE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.	2,274	\$3.85	\$8,754.90	
	0570	CURB B	LOCKOUT	Material			-611	\$125.07	(\$76,417.77)	
	0570	CURB BLOCKOU		Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.	611	\$125.07	\$76,417.77	
Total									\$0.00	

Revision 4/1/2020 Page 3 of 25



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					(	Contract Project Information				
Project Number	Federal Proj. Number	Proj. Number Description								
J9I3597	I 155-1(123)	Resurface	155	PEMISCOT	from Rte. 412 to Tenn	essee State line				
Totals by .	Job Number	s								
J9I3597		Item Pay Item Adjustme		Item Pay	This Estimate \$54,248.00 \$0.00 \$54,248.00	Previous \$4,273,365.75 \$281,791.10 \$4,555,156.85	To Date \$4,327,613.75 \$281,791.10 \$4,609,404.85			
			tments		\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$83,997.18	\$0.00 \$0.00 \$0.00 \$83,997.18			

Revision 4/1/2020 Page 4 of 25



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions (Discrepancies) This Estimate Period			
Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9l3597, Item 3040504, Project Item Line Number 0060, Material Set 304050496, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 3049910, Project Item Line Number 0070, Material Set 304991096, Material 0304SBT15KP - Compacted Type 1 & 5 Base, Acceptance Action Generic 0304SBT15KP is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1007T1ABLDT5 - Agg Base Type 1 & 5 Limestone/Dolomite, Acceptance Action Generic 1007T1ABLDT5 is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4010151, Project Item Line Number 0080, Material Set 401015196, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4071005, Project Item Line Number 0130, Material Set 407100596, Material 1015EASS1H - Emulsified Asphalt SS-1H, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 4079912, Project Item Line Number 0135, Material Set 407991296, Material 1015EASS1VH - Emulsified Asphalt - Trackless Tack, Acceptance Action Generic AspEmulsion is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMDAEC4.11 - Dowel Assemblies Epoxy Ctd Gr40 1 1/4" @, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE42016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 60/M420@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 5021109, Project Item Line Number 0150, Material Set 502110996, Material 1057JMTBE28016 - Tie Bar Ep Ctd 30" No. 5/M16 Gr 40/M280@, Acceptance Action Generic ReinforcingMisc is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6053030A, Project Item Line Number 0160, Material Set 6053030A96, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6131010, Project Item Line Number 0190, Material Set 613101096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6131012, Project Item Line Number 0200, Material Set 613101296, Material 0200XXCS - Compacted Soil for Subgrade or Embankment, Acceptance Action Generic 0200XXCS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6205309, Project Item Line Number 0420, Material Set 620530996, Material 1048PMT - Marking Tape, Acceptance Action Generic 1048PMT is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6209901, Project Item Line Number 0470, Material Set 620990196, Material 1048PMTRWBWH - Marking Paint Acrylic Waterborne White, Acceptance Action Generic 1048PMTRWBWH is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6209901, Project Item Line Number 0470, Material Set 620990196, Material 1048PMTRWBYL - Marking Paint Acrylic Waterborne Yellow, Acceptance Action Generic 1048PMTRWBYL is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6209901, Project Item Line Number 0470, Material Set 620990196, Material 1048PMRBTP - Reflective Glass Beads Type P Perf Spec, Acceptance Action Generic 1048PMRBTP is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6252001, Project Item Line Number 0500, Material Set 625200196, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 6252003, Project Item Line Number 0510, Material Set 625200396, Material 0625PLUTUS - Polyurethane for UnderSealing of PVMT, Acceptance Action Generic 0625PLUTUS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100507CPCMLD - PCCP or Masonry 0-3/4" Max LS/DO, Acceptance Action Generic 100507CPCMLD is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO,	No Remark was entered by Engineer	holtb3	Overridden

Revision 4/1/2020 Page 5 of 25



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

#### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Acceptance Action Generic 100510CPCMLD is insufficient.			
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1039ERRAS - Epoxy Bonding Agent-Resin Anchor Systems, Acceptance Action Generic 1039ERRAS is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1055CMMLDST1D - Clear Pavement-Bridge Dissipating Cure @, Acceptance Action Generic 1055CMMLDST1D is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9I3597, Item 7034600, Project Item Line Number 0570, Material Set 703460096, Material 1053CSSIL - Concrete Sealer (CS) - Silane @, Acceptance Action Generic 1053CSSIL is insufficient.	No Remark was entered by Engineer	holtb3	Overridden
Estimate Exception Type: Item Overrun: Contract 211217-H05, Contract Project J9l3597, Project Item Line Number 0210, Contract Line Item Number 0210, Item 6131013, Minor Item.	No Remark was entered by Engineer	holtb3	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211217-H05, Contract Project J9l3597, Project Item Line Number 0310, Contract Line Item Number 0310, Item 6161030, Minor Item.	No Remark was entered by Engineer	holtb3	Acknowledged
Estimate Exception Type: Item Overrun: Contract 211217-H05, Contract Project J9l3597, Project Item Line Number 0200, Contract Line Item Number 0200, Item 6131012, Minor Item.	No Remark was entered by Engineer	holtb3	Acknowledged

Revision 4/1/2020 Page 6 of 25



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H05	J9I3597	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.80	\$76,208.14	\$60,966.51
		0001	0020	2039907	MISC.TRENCHING FOR PIPE AGGREGATE EDGE DRAIN	100.00	0.00	100.00	CUYD	23.60	\$190.00	\$4,484.00
		0001	0030	2129900	MISC.SHOULDER GRADING	46.00	0.00	46.00	100F	0.00	\$227.95	\$0.00
		0001	0035	2159903	MISC.Modified Shaping Slopes Class III	1,760.00	0.00	1,760.00	LF	0.00	\$10.00	\$0.00
		0001	0040	3030600	FURNISHING ROCK BASE MATERIAL	977.00	0.00	977.00	SQYD	398.90 398.90	\$25.00 \$10.00	\$9,972.50
		0001	0050	3030610A	10A PLACING ROCK BASE	977.00	0.00	977.00				\$3,989.00
		0001	0060	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	1,081.00	0.00	1,081.00	SQYD	258.10	\$12.00	\$3,097.20
		0001	0070	3049910	MISC.PERMANENT AGGREGATE EDGE TREATMENT	9,357.00	0.00	9,357.00	TONS	1,482.61	\$44.27	\$65,635.14
		0001	0080	4010151	TYPE A3 SHOULDER	9,827.30	0.00	9,827.30	SQYD	117.33	\$37.51	\$4,401.05
		0001	0090	4011209	BITUMINOUS PAVEMENT MIXTURE PG64-22, (BP-1)	22,548.10	0.00	22,548.10	TONS	6,236.93	\$78.78	\$491,345.35
		0001	0095	4019901	MISC.NRRA SUPPLEMENTARY TEST SECTIONS	1.00	0.00	1.00	LS	0.00	\$144,283.66	\$0.00
		0001	0120	4030109	ASPHALTIC CONCRETE MIXTURE PG 70-22 (SP125CLP MIX)	42,848.90	0.00	42,848.90	TONS	13,628.42	\$93.78	\$1,278,073.23
		0001	0124	4031058	INTELLIGENT COMPACTION	1.00	0.00	1.00	LS	0.50	\$40,470.36	\$20,235.18
		0001	0125	4031059	PAVER-MOUNTED THERMAL PROFILES	1.00	0.00	1.00	LS	0.50	\$4,855.28	\$2,427.64
		0001	0130	4071005	TACK COAT	12,646.00	0.00	12,646.00	GAL	3,515.00	\$2.33	\$8,189.95
		0001	0135	4079912	MISC.MODIFIED BONDED ASPHALTIC CONCRETE PAVEMENT	73,357.00	0.00	73,357.00	GAL	21,464.00	\$2.60	\$55,806.40
		0001	0140	4134000	BITUMINOUS FOG SEAL	14,167.00	0.00	14,167.00	GAL	0.00	\$3.39	\$0.00
		0001	0150	5021109	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	345.00	0.00	345.00	SQYD	140.80	\$90.00	\$12,672.00
		0001	0160	6053030A	PIPE AGGREGATE PAVEMENT EDGE DRAIN	4,034.00	0.00	4,034.00	LF	955.70	\$15.00	\$14,335.50
		0001	0170	6054020	OUTLET PIPES AND SPLASH PADS	34.00	0.00	34.00	EA	8.00	\$1,350.00	\$10,800.00
		0001 0	0180	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	4.00	0.00	4.00	EA	2.00	\$0.00	\$0.00
			0190	6131010	FURNISHING AND PLACING CONCRETE MATERIAL FOR FULL DEPTH PAVEMENT REPAIR	1,144.00	648.00	1,792.00	SQYD	1,787.80	\$225.00	\$402,255.00
		0001	0200	6131012	SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	321.80	\$6.00	\$1,930.80
		0001	0210	6131013	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN. THICK) (PAVEMENT REPAIR)	114.00	0.00	114.00	SQYD	321.80	\$8.00	\$2,574.40
		0001	0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR PERIMETER AND INTERNAL SAW CUTS)	4,724.00	3,182.00	7,906.00	LF	6,735.00	\$10.00	\$67,350.00
		0001	0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INSTALLATION) FOR FULL DEPTH PAVEMENT REPAIR		1,899.00	3,999.00	EA	3,667.00	\$8.00	\$29,336.00
		0001	0240	6132018	FURNISHING AND PLACING CONCRETE MATERIAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	49.40	0.00	49.40	CUYD	0.00	\$1,650.00	\$0.00
		0001	0250	6132019	REMOVAL FOR CLASS A PARTIAL DEPTH PAVEMENT REPAIR	395.60	0.00	395.60	SQYD	0.00	\$115.00	\$0.00
		0001	0260	6134001	DOWEL BAR RETROFIT	10,680.00	0.00	10,680.00	EA	9,819.00	\$90.00	\$883,710.00
		0001	0270	6139903	MISC.TYPE E EXPANSION JOINT	456.00	0.00	456.00	LF	324.00	\$30.00	\$9,720.00
		0001	0280	6161005	CONSTRUCTION SIGNS	4,196.00	0.00	4,196.00	SQFT	1,883.00	\$8.00	\$15,064.00
		0001	0290	6161008	ADVANCED WARNING RAIL SYSTEM	12.00	0.00	12.00	EA	12.00	\$35.00	\$420.00
		0001	0300	6161025	CHANNELIZER (TRIM LINE)	962.00	0.00	962.00	EA	245.00	\$20.00	\$4,900.00
		0001	0310	6161030	TYPE III MOVEABLE BARRICADE	4.00	0.00	4.00	EA	6.00	\$150.00	\$900.00
		0001	0320	6161033	DIRECTIONAL INDICATOR BARRICADE	178.00	0.00	178.00	EA	178.00	\$0.00	\$0.00
		0001	0330	6161040	FLASHING ARROW PANEL	9.00	0.00	9.00	EA	4.00	\$1,000.00	\$4,000.00
		0001	0340	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	4.00	0.00	4.00	EA	2.00	\$3,200.00	\$6,400.00
		0001	0350	6162000A	WORK ZONE TRAFFIC SIGNAL SYSTEM	1.00	0.00	1.00	EA	1.00	\$10,000.00	\$10,000.00
		0001	0360	6162004	TEMPORARY SHORT-TERM RUMBLE STRIPS	16.00	0.00	16.00	EA	0.00	\$0.00	\$0.00
		0001	0370	6172000	CONCRETE TRAFFIC BARRIER, TYPE B	160.00	0.00	160.00	LF	0.00	\$178.29	\$0.00
		0001	0380	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.75	\$263,893.91	\$197,920.43
		0001	0390	6200039	PREFORMED THERMOPLASTIC PAVEMENT MARKING, OFF RAMP WRONG WAY ARROW	4.00	0.00	4.00	EA	0.00	\$1,500.00	\$0.00
		0001	0400	6205301B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., WHITE	1,200.00	0.00	1,200.00	LF	1,200.00	\$2.00	\$2,400.00
		0001	0410	6205303B	TEMPORARY REMOVABLE MARKING TAPE 4 IN., YELLOW	2,000.00	0.00	2,000.00	LF	2,000.00	\$2.00	\$4,000.00

Page 7 of 25 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H05	J9I3597	0001	0420	6205309	TEMPORARY REMOVABLE MARKING TAPE, 24 IN., WHITE	60.00	0.00	60.00	LF	60.00	\$10.00	\$600.00
		0001	0430	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	151,103.00	0.00	151,103.00	LF	0.00	\$0.22	\$0.00
		0001	0440	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	123,088.00	0.00	123,088.00	LF	0.00	\$0.22	\$0.00
		0001	0450	6205906A	12 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	7,530.00	0.00	7,530.00	LF	0.00	\$1.00	\$0.00
		0001	0460	6207001	PAVEMENT MARKING REMOVAL	4,060.00	0.00	4,060.00	LF	4,060.00	\$2.00	\$8,120.00
		0001	0470	6209901	MISC.TEMPORARY PAVEMENT MARKING PAINT	1.00	0.00	1.00	LS	0.35	\$16,769.52	\$5,869.33
		0001	0480	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	49,344.00	0.00	49,344.00	SQYD	13,584.00	\$2.15	\$29,205.60
		0001	0490	6224010	MODIFIED COLDMILLING (DEPTH TRANSITIONS)	22,967.00	0.00	22,967.00	SQYD	5,522.10	\$6.20	\$34,237.02
		0001	0500	6252001	UNDERSEALING MATERIAL HIGH DENSITY POLYURETHANE	10,022.00	15,959.00	25,981.00	LB	25,981.00	\$3.85	\$100,026.85
		0001	0510	6252003	SLAB JACKING MATERIAL HIGH DENSITY POLYURETHANE	2,274.00	0.00	2,274.00	LB	2,274.00	\$3.85	\$8,754.90
		0001	0520	6261000A	BITUMINOUS SHOULDER RUMBLE STRIP	2,109.70	0.00	2,109.70	STA	0.00	\$24.50	\$0.00
		0010	0530	6061060	MGS GUARDRAIL	8,588.00	0.00	8,588.00	LF	8,388.00	\$32.00	\$268,416.00
		0010	0540	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	10.00	0.00	10.00	EA	8.00	\$3,700.00	\$29,600.00
		0010	0550	6061080	MGS END ANCHOR	18.00	0.00	18.00	EA	16.00	\$1,500.00	\$24,000.00
		0010	0560	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	22.00	0.00	22.00	EA	20.00	\$3,000.00	\$60,000.00
		0070	0570	7034600	CURB BLOCKOUT	611.00	0.00	611.00	LF	611.00	\$125.07	\$76,417.77
		0001	5002	6161055	SEQUENTIAL FLASHING WARNING LIGHT	0.00	28.00	28.00	EA	28.00	\$137.25	\$3,843.00
	Project .	J9I3597 - To	tal Value	Posted to E	Date as of Report Generated Date							\$4,338,401.75
211217-H05 Ove	erall - Tota	I Value Pos	ted to Da	ate as of Rep	ort Generated Date							\$4,338,401.75

Page 8 of 25 Revision 4/1/2020



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: .1913597

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0190	6131010	FURN & PLACE CONC MATL FOR FULL DEPTH	1/9/23	1/9/23	8.00	SQYD	SBPL	4.644				
			1/10/23	1/11/23	48.00	SQYD	SBPL	5.011		7.099		
			1/12/23	1/12/23	8.00	SQYD	SBPL	8.219				
0220	6131014	FULL DEPTH PAVEMENT REPAIR SAW CUT (FOR	1/9/23	1/9/23	36.00	LF	SBPL	4.644				
			1/10/23	1/11/23	204.00	LF	SBPL	5.011		7.099		
			1/12/23	1/12/23	36.00	LF	SBPL	8.219				
0230	6131015	DOWEL BAR (DRILLING, FURNISHING AND INST	1/9/23	1/9/23	19.00	EA	SBPL	4.644				
			1/10/23	1/11/23	97.00	EA	SBPL	5.011		7.099		
			1/12/23	1/12/23	20.00	EA	SBPL	8.219				
0260	6134001	DOWEL BAR RETROFIT	1/9/23	1/9/23	114.00	EA	SBPL	4.865		4.768		
			1/10/23	1/11/23	54.00	EA	SBPL	6.049		6.928		
			1/11/23	1/16/23	120.00	EA	SBPL	7.19		7.853		
			1/13/23	1/13/23	96.00	EA	SBPL	7.853		8.201		
0270	6139903	MISC. PAVEMENT REPAIR	1/10/23	1/11/23	36.00	LF	SBPL	5.011		6.973		
			1/12/23	1/12/23	12.00	LF	SBPL	5.011				
0320	6161033	DIRECTIONAL INDICATOR BARRICADE	1/13/23	1/13/23	146.00	EA	NB and SB Locations	0.481		10.250		

roject	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
913597	0280	April 14, 2022	156	GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		.972	Route I-155	2.00	10		10.00	2
				GO20-1 60x24 10.00 ROAD WORK NEXT XX MILES		0.474	Route I-155	2.00	10		10.00	2
				GO20-2 48x24 8.00 END ROAD WORK		1.5	Route I-155	2.00	8		8.00	
				CONST-7 72x36 18.00 RATE OUR WORK ZONE		2	Route I-155	2.00	18		18.00	
				CONST-8 48x36 12.00 WORK ZONE NO PHONE ZONE		2.5	Route I-155	4.00	12		12.00	
		April 26, 2022	540	WO4-1aR 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		0.474	I-155 NBL	4.00	16			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.474	I-155 NBL	4.00	16			
				WO20-6a 48x48 16.00 RIGHT/CENTER/LEFT LANE CLOSED		0.474	I-155 NBL	6.00	16			
				WO4-1aL 48x48 16.00 MERGE (ARROW SYMBOL)		0.474	I-155 NBL	4.00	16			
				R4-1 36x48 12.00 DO NOT PASS		0.474	I-155 NBL	4.00	12			
				See Special Sign Details	0.		I-155 NBL					
				CONST-3A 60x48 20.00 FINE SIGN		0.474	I-155 NBL	3.00	20			
				WO4-1R 48x48 16.00 MERGE (SYMBOL FROM RIGHT)		0.474	I-155 NBL	2.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX		0.474	I-155 NBL	4.00	12			
		June 10, 2022	625	MO4-8a 24x18 3.00 END DETOUR		18.5	Route I-55	2.00	3			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.4	Exit 1A Ramp 3	1.00	16			
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		0.2	Exit 1A Ramp 3	1.00	16			
				R11-2 48x30 10.00 ROAD CLOSED		0.1	Exit 1A Ramp 3	2.00	10			
				WO20-1 48x48 16.00 ROAD/BRIDGE/RAMP WORK AHEAD		29.531	Route 84 / Route U & Ramps	4.00	16			
				R10-6 24x36 6.00 STOP HERE ON RED (45 DEGREE ARROW		30.061	Route 84 / Route U & Ramps	4.00	6			
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		3.2	Exit 1A Ramp 3	64.00	1			
				Variable ??x?? 1.00 SPECIAL SIGN BY QUANTITY OF SQUARE FEET		3.2	Exit 1A Ramp 3	253.50	1			25
				WO20-2 48x48 16.00 DETOUR AHEAD		3.2	Exit 1A Ramp 3	1.00	16			
				WO3-4 8x48 16.00 BE PREPARED TO STOP		29.814	Route 84 / Route U & Ramps	4.00	16			
				R2-1 36x48 12.00 SPEED LIMIT XX		29.741	Route 84 / Route U & Ramps	2.00	12			
				R1-2 48 TRI 6.93 YIELD		29.741	Route 84 / Route U & Ramps	2.00	6.93			10
				GO20-5aP 36x24 6.00 WORK ZONE (PLAQUE)		29.741	Route 84 / Route U & Ramps	2.00	6			
				WO20-4 48x48 16.00 ONE LANE ROAD AHEAD		29.631	Route 84 / Route U & Ramps	2.00	16			
		November 15, 2022	352	WO8-9 48x48 16.00 LOW SHOULDER		0.473 - 6.976	NBL	8.00	16.00			128
				WO8-11 48x48 16.00 UNEVEN LANES		0.473 - 6.976	NBL	14.00	16.00			224
		November 16, 2022	210	WO20-3 48x48 16.00 ROAD CLOSED AHEAD		10.477	NBL I 155	1.00	16.00	W020-3a sign not in list		16
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		10.432	NBL I-155	1.00	16.00			16
				See Special Sign Details		9.995	NBL I 155	1.00		Special detour closed ahead assembly 56	32.00	32
				See Special Sign Details		0.339 and 196.973	NBL I 155 RAMP TO I 55 AND SBL I 55	2.00		Special detour route assembly 50Y	19.50	39
				See Special Sign Details		0.185 and 372.914	NBL I 55 and Route 84	2.00		Special detour route assembly 50E	19.50	39
				R11-2 48x30 10.00 ROAD CLOSED		0.004	NBL I 155 Ramp	1.00	10.00			10

Revision 4/1/2020 Page 9 of 25



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line	

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J913597	0280	November 16,	210	MO4-8a 24x18 3.00 END DETOUR		191.174	SBL I 55	1.00	3.00			3.00
		2022		WO20-2 48x48 16.00 DETOUR AHEAD		9.826	NBL I 155	1.00	16.00			16.00
				See Special Sign Details		10.106 and 191.091	NBL I 155 AND NBL I 55	2.00		Special detour route assembly 50X	19.50	39.00
	0280 - Tota											1867.36

Revision 4/1/2020 Page 10 of 25





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0060	TYPE 5 AGGREGATE FOR BASE	Material		3	May 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	May 2, 2022	SYSTEM	(\$3,097.20)	
					4	May 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	May 16, 2022	SYSTEM	(\$3,097.20)	
					5	Jun 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$3,097.20)	
					6	Jun 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$3,097.20)	
					7	Jul 1, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$3,097.20)	
					8	Jul 18, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$3,097.20)	
					9	Aug 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$3,097.20)	
					10	Sep 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					10	Sep 2, 2022	SYSTEM	(\$3,097.20)	
					11	Sep 16, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user george2 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$3,097.20)	
					12	Sep 30, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					12	Sep 30, 2022	SYSTEM	(\$3,097.20)	
					13	Oct 17, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$3,097.20)	
					14	Nov 1, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					14	Nov 1, 2022	SYSTEM	(\$3,097.20)	
					15	Nov 15, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$3,097.20)	
					16	Dec 2, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks										
J9I3597	0060	TYPE 5 AGGREGATE	Material						Estimate Exception 1 on the current Payment Estimate.										
		FOR BASE			16	Dec 2, 2022	SYSTEM	(\$3,097.20)											
					17	Dec 15, 2022	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					17	Dec 15, 2022	SYSTEM	(\$3,097.20)											
					18	Jan 3, 2023	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					18	Jan 3, 2023	SYSTEM	(\$3,097.20)											
					19	Jan 16, 2023	SYSTEM	\$3,097.20	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user holtb3 overridding Payment Estimate Exception 1 on the current Payment Estimate.										
					19	Jan 16, 2023	SYSTEM	(\$3,097.20)											
				- Total				\$0.00											
			Material - To	tal				\$0.00											
			Price FUEL		3	May 2, 2022	SYSTEM	\$50.33	Reference Item Price Adjustment Index Adjustment Type applied is FUEL										
				- Total				\$50.33											
			Price FUEL -	Total				\$50.33											
	0060 -	Total						\$50.33											
	0070	MISC. AGGREGATE FOR BASE	Material		14	Nov 1, 2022	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					14	Nov 1, 2022	SYSTEM	(\$65,635.14)											
								15	Nov 15, 2022	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.							
						15	Nov 15, 2022	SYSTEM	(\$65,635.14)										
						16	Dec 2, 2022	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.									
					16	Dec 2, 2022	SYSTEM	(\$65,635.14)											
					17	Dec 15, 2022	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
										17	Dec 15, 2022	SYSTEM	(\$65,635.14)						
					18	Jan 3, 2023	SYSTEM	(\$65,635.14)											
					19	Jan 16, 2023	SYSTEM	\$65,635.14	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					19	Jan 16, 2023	SYSTEM	(\$65,635.14)											
				- Total				\$0.00											
			Material - To	tal				\$0.00											
	0070 -							\$0.00											
	0800	TYPE A3 SHOULDER	Material		4	May 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					4	May 16, 2022	SYSTEM	(\$4,401.05)											
					5	Jun 2,	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment										





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks											
J9I3597	0800	TYPE A3 SHOULDER	Material			2022			Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					5	Jun 2, 2022	SYSTEM	(\$4,401.05)												
					6	Jun 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					6	Jun 16, 2022	SYSTEM	(\$4,401.05)												
					7	Jul 1, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					7	Jul 1, 2022	SYSTEM	(\$4,401.05)												
					8	Jul 18, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					8	Jul 18, 2022	SYSTEM	(\$4,401.05)												
					9	Aug 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					9	Aug 16, 2022	SYSTEM	(\$4,401.05)												
					10	Sep 2, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					10	Sep 2, 2022	SYSTEM	(\$4,401.05)												
					11	Sep 16, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user george2 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					11	Sep 16, 2022	SYSTEM	(\$4,401.05)												
					12	Sep 30, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
					12	Sep 30, 2022	SYSTEM	(\$4,401.05)												
					13	Oct 17, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 2 on the current Payment Estimate.											
																13	Oct 17, 2022	SYSTEM	(\$4,401.05)	
												14	Nov 1, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					14	Nov 1, 2022	SYSTEM	(\$4,401.05)												
					15	Nov 15, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					15	Nov 15, 2022	SYSTEM	(\$4,401.05)												
					16	Dec 2, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.											
					16	Dec 2, 2022	SYSTEM	(\$4,401.05)												
						17	Dec 15, 2022	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.										
					17	Dec 15, 2022	SYSTEM	(\$4,401.05)												
				18	Jan 3, 2023	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.												



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																				
J9I3597	0800	TYPE A3 SHOULDER	Material		18	Jan 3, 2023	SYSTEM	(\$4,401.05)																					
					19	Jan 16, 2023	SYSTEM	\$4,401.05	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 3 on the current Payment Estimate.																				
					19	Jan 16, 2023	SYSTEM	(\$4,401.05)																					
				- Total				\$0.00																					
			Material - To	tal				\$0.00																					
	0080 -	Total						\$0.00																					
	0090	BIT. PAVEMENT MIXTURE PG64-22 (BP-1)	Other Item Adjustment	ACAD	12	Sep 30, 2022	holtb3	\$10,437.58	AC adjustments for period ending 09/30/2022																				
		F G04-22 (DF-1)			13	Oct 17, 2022	holtb3	\$3,282.35	AC adjustment for period ending 10/15/22.																				
					14	Nov 2, 2022	holtb3	\$47,819.04	AC adjustment for period ending 11/1/22.																				
				ACAD - Tota	al			\$61,538.97																					
			Other Item A	.djustment - T	otal			\$61,538.97																					
			Price FUEL		4	May 16, 2022	SYSTEM	\$312.35	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
				12	Sep 30, 2022	SYSTEM	\$5,923.54	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																					
					13	Oct 17, 2022	SYSTEM	\$997.15	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
				14	Nov 1, 2022	SYSTEM	\$14,526.99	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																					
			- Total				\$21,760.03																						
			Price FUEL -	Total				\$21,760.03																					
	0090 -	Total						\$83,299.00																					
	0120				ACAD	12	Sep 30, 2022	holtb3	\$2,163.53	AC adjustment for period ending 09/30/2022																			
									13	Oct 17, 2022	holtb3	\$65,077.17	AC adjustment for period ending 10/15/22.																
					14	Nov 2, 2022	holtb3	\$78,719.68	AC adjustment for period ending 11/1/22.																				
				ACAD - Tota	al			\$145,960.38																					
			Other Item A	djustment - T	otal			\$145,960.38																					
			Price FUEL		12	Sep 30, 2022	SYSTEM	\$1,140.14	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
					13	Oct 17, 2022	SYSTEM	\$18,357.71	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
																									14	Nov 1,	SYSTEM		
						2022	0101211	\$22,206.16	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
				- Total			91912	\$41,704.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
i i			Price FUEL -					\$41,704.01 \$41,704.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
	0120 -	Total	Price FUEL -				9.9.2	\$41,704.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL																				
	<b>0120</b> - <b>0130</b>	Total TACK COAT	Price FUEL -		12		SYSTEM	\$41,704.01 \$41,704.01	Reference Item Price Adjustment Index Adjustment Type applied is FUEL  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 5 on the current Payment Estimate.																				
						2022 Sep 30,		\$41,704.01 \$41,704.01 \$187,664.39	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment																				
					12	Sep 30, 2022 Sep 30,	SYSTEM	\$41,704.01 \$41,704.01 \$187,664.39 \$1,985.16	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment																				
					12	Sep 30, 2022 Sep 30, 2022 Oct 17,	SYSTEM	\$41,704.01 \$41,704.01 \$187,664.39 \$1,985.16 (\$1,985.16)	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment																				
					12 12 13	Sep 30, 2022  Sep 30, 2022  Oct 17, 2022  Oct 17,	SYSTEM SYSTEM SYSTEM	\$41,704.01 \$41,704.01 \$187,664.39 \$1,985.16 (\$1,985.16) \$2,886.87	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment																				



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks									
597	0130	TACK COAT	Material		15	Nov 15, 2022	SYSTEM	\$8,189.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					15	Nov 15, 2022	SYSTEM	(\$8,189.95)										
					16	Dec 2, 2022	SYSTEM	\$8,189.95	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					16	Dec 2, 2022	SYSTEM	(\$8,189.95)										
				- Total				\$0.00										
			Material - Tot	tal				\$0.00										
	0130 -	Total						\$0.00										
	0135	MISC. NON STANDARD TACK COAT	Material		12	Sep 30, 2022	SYSTEM	\$1,508.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					12	Sep 30, 2022	SYSTEM	(\$1,508.00)										
					13	Oct 17, 2022	SYSTEM	\$33,722.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 6 on the current Payment Estimate.									
					13	Oct 17, 2022	SYSTEM	(\$33,722.00)										
									14	Nov 1, 2022	SYSTEM	\$55,806.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.					
											14	14	Nov 1, 2022	SYSTEM	(\$55,806.40)			
											15	Nov 15, 2022	SYSTEM	\$55,806.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					16	Dec 2, 2022	SYSTEM	\$55,806.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.									
									16	Dec 2, 2022	SYSTEM	(\$55,806.40)						
					17	2022 E	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.											
					17	Dec 15, 2022	SYSTEM	(\$55,806.40)										
										18	Jan 3, 2023	SYSTEM	\$55,806.40	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.				
										18	Jan 3, 2023	SYSTEM	(\$55,806.40)					
																19	Jan 16, 2023	SYSTEM
					19	Jan 16, 2023	SYSTEM	(\$55,806.40)										
				- Total				\$0.00										
		135 - Total	Material - Tot	tal				\$0.00										
								\$0.00										
	0150	CONCRETE PAVEMENT ( 9 IN. NON-REINF)	Material	3	May 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.										
					3	May 2, 2022	SYSTEM	(\$12,672.00)										
				4	4	May 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.									
					4	May 16,	SYSTEM	(\$12,672.00)										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0150	CONCRETE	Material			2022			
		PAVEMENT ( 9 IN. NON-REINF)			5	Jun 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					5	Jun 2, 2022	SYSTEM	(\$12,672.00)	
					6	Jun 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$12,672.00)	
					7	Jul 1, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$12,672.00)	
					8	Jul 18, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$12,672.00)	
					9	Aug 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$12,672.00)	
					10	Sep 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					10	Sep 2, 2022	SYSTEM	(\$12,672.00)	
					11	Sep 16, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user george2 overridding Payment Estimate Exception 5 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$12,672.00)	
					12	Sep 30, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					12	Sep 30, 2022	SYSTEM	(\$12,672.00)	
					13	Oct 17, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$12,672.00)	
					14	Nov 1, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					14	Nov 1, 2022	SYSTEM	(\$12,672.00)	
					15	Nov 15, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$12,672.00)	
					16	Dec 2, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					16	Dec 2, 2022	SYSTEM	(\$12,672.00)	
					17	Dec 15, 2022	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user holtb3 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$12,672.00)	
					18	Jan 3,	SYSTEM	\$12,672.00	This adjustment offsets the original system-generated Material Payment



150   CONCRETE   Makeral   Type   2023	Project	Line	Description	Adjustment Type	Other Adjustment	Est. Number	Created Date	Created By	Amount	Remarks									
PAVEMENT   6	913597	0150	CONCRETE	Material	Туре		2023			Estimate Item Adjustment (0005) due to user holth3 overridding Payment									
19	710001	0130	PAVEMENT (9	Waterial															
2023   SYSTEM   Estimate Exception 5 on the current Peyment Estimate Proposed (0005) aux is user habitals overriding Psyment Estimate Proposed (0005) aux is user habitals overriding Psyment Estimate Psyment Psyment Estimate Psyment Ps						18		SYSTEM	(\$12,672.00)										
Total						19		SYSTEM	\$12,672.00	Estimate Item Adjustment (0005) due to user holtb3 overridding Payment									
Material Total						19		SYSTEM	(\$12,672.00)										
Price FUEL   3					- Total				\$0.00										
Price FUEL - Total				Material - To	tal				\$0.00										
Price   Full   Total				Price FUEL		3		SYSTEM	\$120.81	Reference Item Price Adjustment Index Adjustment Type applied is FUEL									
					- Total				\$120.81										
				Price FUEL -	Total				\$120.81										
AGGREGATE   PAPEMENT   Editimate Item Adjustment (0005) due to user woodskt overridding Payment Estimate Exception 10 on the current Payment Estimate.																			
A		0160	AGGREGATE PAVEMENT	Material		4	May 16, 2022	SYSTEM	\$14,335.50	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment									
2022   Estimate Item Adjustment (0005) due to user woodskit overridding Payment Estimate Exception 10 on the current Payment Estimate.			EDGE DIVAIN			4		SYSTEM	(\$14,335.50)										
170   OUTLET PIPES   Material - Total   S0.00						5		SYSTEM	\$14,335.50	Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment									
Material - Total						5		SYSTEM	(\$14,335.50)										
OTO   OUTLET PIPES   AND SPLASH   AND SPLASH   AND SPLASH   PADS					- Total				\$0.00										
OUTLET PIPES   AND SPLASH   FADS   AND SPLASH   AND SPLASH   FADS				Material - To	tal				\$0.00										
AND SPLASH PADS		0160 -	Total						\$0.00										
2022   5 Jun 2, 2022   5 Jun 2   5 SYSTEM   \$10,800.00   This adjustment offsets the original system-generated Material Payment Estimate Exception 13 on the current Payment Estimate Estimate Exception 13 on the current Payment Estimate Exception 13 on the current Payment Estimate Estimate Exception 13 on the current Payment Estimate Estimate Exception 17 on the current Payment Estimate Exception 18 on the Current Payment Estimate Exception 19 on the current Payment		0170	OUTLET PIPES AND SPLASH	1	Material		4		SYSTEM	\$10,800.00	Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment								
2022   Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.									4		SYSTEM	(\$10,800.00)							
170 - Total																			5
Material - Total   \$0.00						5		SYSTEM	(\$10,800.00)										
Sumariance   Sum					- Total				\$0.00										
FURN & PLACE CONC MATL FOR FULL DEPTH  A May 16, 2022  5 Jun 2, 2022  6 SYSTEM (\$39,600.00)  This adjustment offsets the original system-generated Material Payment Estimate Exception 17 on the current Payment Estimate.  Total  So.00  1090 - Total  SUBGRADE COMPACTION (6 IN. DEPTH)  (PAVEM)  A May 16, SYSTEM (\$39,600.00)  SUBGRADE COMPACTION (6 IN. DEPTH)  (PAVEM)  A May 16, SYSTEM (\$39,600.00)  SUBGRADE COMPACTION (6 IN. DEPTH)  A May 16, SYSTEM (\$54.00)  SYSTEM (\$54.00)  SYSTEM (\$54.00)  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  SO.00  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.				Material - To	tal				\$0.00										
CONC MATL FOR FULL DEPTH    A		0170 -	Total						\$0.00										
A		0190	CONC MATL FOR FULL	Material		4		SYSTEM	\$19,800.00	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment									
2022 Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 17 on the current Payment Estimate.  5 Jun 2, 2022 SYSTEM (\$39,600.00)  - Total S0.00  Material - Total S0.00  0200 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM IN. DEPTH) (PAVEM STATE OF SUBJECT OF SUBJEC			DEPTH			4		SYSTEM	(\$19,800.00)										
-Total \$0.00  Material - Total \$0.00  O190 - Total \$0.00  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM PAVEM Feb. 10 In. DEPTH) (PAVEM 55 Jun 2, SYSTEM \$106.80 This adjustment offsets the original system-generated Material Payment Estimate Exception 20 on the current Payment Estimate.						5		SYSTEM	\$39,600.00	Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment									
Material - Total   S0.00		0200				5		SYSTEM	(\$39,600.00)										
O190 - Total  SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM)  4 May 16, 2022 \$ SYSTEM \$54.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  4 May 16, 2022 \$ SYSTEM \$54.00 \$ SYSTEM \$54.00 \$ SYSTEM \$54.00 \$ SYSTEM \$ SY																			
O200 SUBGRADE COMPACTION (6 IN. DEPTH) (PAVEM PAVEM 4 May 16, 2022 5 Jun 2, SYSTEM \$54.00 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  4 May 16, 2022 (\$54.00)  5 Jun 2, SYSTEM \$106.80 This adjustment offsets the original system-generated Material Payment				Material - To	tal														
COMPACTION (6 IN. DEPTH) (PAVEM  A May 16, 2022  Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 20 on the current Payment Estimate.  4 May 16, 2022  5 Jun 2, SYSTEM \$106.80 This adjustment offsets the original system-generated Material Payment								a											
4 May 16, 2022 (\$54.00)  5 Jun 2, SYSTEM \$106.80 This adjustment offsets the original system-generated Material Payment			COMPACTION (6 IN. DEPTH)	Material		4		SYSTEM	\$54.00	Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment									
						4		SYSTEM	(\$54.00)										
						5		SYSTEM	\$106.80										



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0200	SUBGRADE	Material						Estimate Exception 20 on the current Payment Estimate.
		COMPACTION (6 IN. DEPTH) (PAVEM			5	Jun 2, 2022	SYSTEM	(\$106.80)	
					6	Jun 16, 2022	SYSTEM	\$106.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	Jun 16, 2022	SYSTEM	(\$106.80)	
					7	Jul 1, 2022	SYSTEM	\$298.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$298.80)	
					8	Jul 18, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$504.60)	
					9	Aug 16, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$504.60)	
					10	Sep 2, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					10	Sep 2, 2022	SYSTEM	(\$504.60)	
					11	Sep 16, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user george2 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$504.60)	
					12	Sep 30, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user holtb3 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					12	Sep 30, 2022	SYSTEM	(\$504.60)	
					13	Oct 17, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$504.60)	
					14	Nov 1, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					14	Nov 1, 2022	SYSTEM	(\$504.60)	
					15	Nov 15, 2022	SYSTEM	\$504.60	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$504.60)	
					16	Dec 2, 2022	SYSTEM	\$1,930.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					16	Dec 2, 2022	SYSTEM	(\$1,930.80)	
					17	Dec 15, 2022	SYSTEM	\$1,930.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$1,930.80)	
					18	Jan 3, 2023	SYSTEM	\$1,930.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					18	Jan 3,	SYSTEM	(\$1,930.80)	



roject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
13597	0200	SUBGRADE COMPACTION (6	Material			2023							
		IN. DEPTH) (PAVEM			19	Jan 16, 2023	SYSTEM	\$1,930.80	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.				
					19	Jan 16, 2023	SYSTEM	(\$1,930.80)					
				- Total				\$0.00					
			Material - To	tal				\$0.00					
			Overrun	Overrun	16	Dec 2, 2022	SYSTEM	(\$1,246.80)					
				Overrun - T	otal			(\$1,246.80)					
			Overrun - To	tal				(\$1,246.80)					
	0200 -							(\$1,246.80)					
	0210	TYPE 1 OR 5 AGGREGATE FOR BASE (4 IN.	Overrun	Overrun		Dec 2, 2022	SYSTEM	(\$1,662.40)					
		TH	O	Overrun - T	otai			(\$1,662.40)					
	0040	Takal	Overrun - To	tai				(\$1,662.40)					
	0210 -		Metarial		4	Men 12	CVOTELL	(\$1,662.40)	This adjustment effects the adjustment of the state of th				
	0230	DOWEL BAR (DRILLING, FURNISHING AND INST	Material		4	May 16, 2022	SYSTEM	\$880.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					4	May 16, 2022	SYSTEM	(\$880.00)					
					5	Jun 2, 2022	SYSTEM	\$1,760.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user woodsk1 overridding Payment Estimate Exception 21 on the current Payment Estimate.				
					5	Jun 2, 2022	SYSTEM	(\$1,760.00)					
				- Total									
			Material - To	tal				\$0.00					
			Overrun	Overrun	12	Sep 30, 2022	SYSTEM	(\$1,056.00)					
					13	Oct 17, 2022	SYSTEM	\$1,056.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',8.00000 - 8.00000, 'is applied (if non-zero).				
				Overrun - T	otal			\$0.00					
			Overrun - To	tal				\$0.00					
	0230 -	Total						\$0.00					
	0260	DOWEL BAR RETROFIT	Material		4	May 16, 2022	SYSTEM	\$40,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user woodsk1 overridding Payment Estimate Exception 22 on the current Payment Estimate.				
								4	May 16, 2022	SYSTEM	(\$40,500.00)		
											5	Jun 2, 2022	SYSTEM
					5	Jun 2, 2022	SYSTEM	(\$143,640.00)					
				- Total				\$0.00					
			Material - To	Material - Total									
	0260 -	Total						\$0.00					
	0270	MISC. PAVEMENT REPAIR	Material		5	Jun 2, 2022	SYSTEM	\$720.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user woodsk1 overridding Payment Estimate Exception 25 on the current Payment Estimate.				
		132173113			-	Jun 2,	SYSTEM	(\$720.00)					
					5	2022		,					
				- Total	5			\$0.00					
			Material - To		5			, ,					
	0270 -	Total	Material - To		5			\$0.00					



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9I3597	0310	MOVEABLE BARRICADE	Overrun			2022			
		D/WWWO/IDE		Overrun - T	otal			(\$300.00)	
			Overrun - To	tal				(\$300.00)	
	0310 -						01/0751/	(\$300.00)	
	0420	TEMPORARY REMOVABLE MARKING TAPE, 24 IN.	Material		6	Jun 16, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
		27 113.			6	Jun 16, 2022	SYSTEM	(\$600.00)	
					7	Jul 1, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user woodsk1 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					7	Jul 1, 2022	SYSTEM	(\$600.00)	
					8	Jul 18, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					8	Jul 18, 2022	SYSTEM	(\$600.00)	
					9	Aug 16, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$600.00)	
					10	Sep 2, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					10	Sep 2, 2022	SYSTEM	(\$600.00)	
					11	Sep 16, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user george2 overridding Payment Estimate Exception 13 on the current Payment Estimate.
					11	Sep 16, 2022	SYSTEM	(\$600.00)	
					12	Sep 30, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					12	Sep 30, 2022	SYSTEM	(\$600.00)	
					13	Oct 17, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 15 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$600.00)	
						14	Nov 1, 2022	SYSTEM	\$600.00
					14	Nov 1, 2022	SYSTEM	(\$600.00)	
					15	Nov 15, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$600.00)	
						16	Dec 2, 2022	SYSTEM	\$600.00
					16	Dec 2, 2022	SYSTEM	(\$600.00)	
					17	Dec 15, 2022	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.
					17	Dec 15, 2022	SYSTEM	(\$600.00)	
					18	Jan 3, 2023	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks						
J9I3597	0420	TEMPORARY REMOVABLE	Material						Estimate Exception 16 on the current Payment Estimate.						
		MARKING TAPE, 24 IN.			18	Jan 3, 2023	SYSTEM	(\$600.00)							
					19	Jan 16, 2023	SYSTEM	\$600.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.						
					19	Jan 16, 2023	SYSTEM	(\$600.00)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							
	0420 -	Total						\$0.00							
	0470	MISC. PAVEMENT MARKINGS	Material		15	Nov 15, 2022	SYSTEM	\$5,869.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.						
					15	Nov 15, 2022	SYSTEM	(\$5,869.33)							
					16	Dec 2, 2022	SYSTEM	\$5,869.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.						
					16	Dec 2, 2022	SYSTEM	(\$5,869.33)							
					17	Dec 15, 2022	SYSTEM	\$5,869.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					17	Dec 15, 2022	SYSTEM	(\$5,869.33)							
					18	Jan 3, 2023	SYSTEM	\$5,869.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					18	Jan 3, 2023	SYSTEM	(\$5,869.33)							
					19	Jan 16, 2023	SYSTEM	\$5,869.33	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.						
					19	Jan 16, 2023	SYSTEM	(\$5,869.33)							
				- Total				\$0.00							
			Material - To	tal				\$0.00							
	0470 -	Total						\$0.00							
	0500	UNDERSEAL MATL HIGH DENSITY POLYURETHANE	Material		7	Jul 1, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user woodsk1 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
		POLITIKANE									7	Jul 1, 2022	SYSTEM	(\$38,584.70)	
					8	Jul 18, 2022	SYSTEM	(\$38,584.70)							
											9	Aug 16, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user george2 overridding Payment Estimate Exception 14 on the current Payment Estimate.
					9	Aug 16, 2022	SYSTEM	(\$38,584.70)							
					10	Sep 2, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user george2 overridding Payment Estimate Exception 14 on the current Payment Estimate.						
					10	Sep 2, 2022	SYSTEM	(\$38,584.70)							
									11	Sep 16, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user george2 overridding Payment Estimate Exception 14 on the current Payment Estimate.		
					11	Sep 16, 2022	SYSTEM	(\$38,584.70)							



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks							
J9I3597	0500	UNDERSEAL MATL HIGH DENSITY	Material		12	Sep 30, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
		POLYURETHANE			12	Sep 30, 2022	SYSTEM	(\$38,584.70)								
					13	Oct 17, 2022	SYSTEM	\$38,584.70	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.							
										13	Oct 17, 2022	SYSTEM	(\$38,584.70)			
					14	Nov 1, 2022	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment Estimate Exception 19 on the current Payment Estimate.							
					14	Nov 1, 2022	SYSTEM	(\$100,026.85)								
					15	Nov 15, 2022	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.							
					15	Nov 15, 2022	SYSTEM	(\$100,026.85)								
					16	Dec 2, 2022	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.							
					16	Dec 2, 2022	SYSTEM	(\$100,026.85)								
					17	Dec 15, 2022	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
					17	Dec 15, 2022	SYSTEM	(\$100,026.85)								
												18	Jan 3, 2023	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.
							18	Jan 3, 2023	SYSTEM	(\$100,026.85)						
					19	Jan 16, 2023	SYSTEM	\$100,026.85	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.							
					19	Jan 16, 2023	SYSTEM	(\$100,026.85)								
				- Total				\$0.00								
			Material - To	tal				\$0.00								
		Total						\$0.00								
	0510	SLAB JACKING MATL HIGH DENSITY POLYURETH	Material	terial	7	Jul 1, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user woodsk1 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
					7	Jul 1, 2022	SYSTEM	(\$8,754.90)								
							8	Jul 18, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.					
					8	Jul 18, 2022	SYSTEM	(\$8,754.90)								
					9	Aug 16, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
					9	Aug 16, 2022	SYSTEM	(\$8,754.90)								
					10	Sep 2, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.							
					10	Sep 2, 2022	SYSTEM	(\$8,754.90)								
					11	Sep 16, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user george2 overridding Payment Estimate Exception 15 on the current Payment Estimate.							



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
97	0510	SLAB JACKING MATL HIGH	Material		11	Sep 16, 2022	SYSTEM	(\$8,754.90)		
		DENSITY POLYURETH			12	Sep 30, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
					12	Sep 30, 2022	SYSTEM	(\$8,754.90)		
						13	Oct 17, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0014) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					13	Oct 17, 2022	SYSTEM	(\$8,754.90)		
					14	Nov 1, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0019) due to user holtb3 overridding Payment Estimate Exception 20 on the current Payment Estimate.	
					14	Nov 1, 2022	SYSTEM	(\$8,754.90)		
					15	Nov 15, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					15	Nov 15, 2022	SYSTEM	(\$8,754.90)		
					16	Dec 2, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0016) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					16	Dec 2, 2022	SYSTEM	(\$8,754.90)		
					17	Dec 15, 2022	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
					17	Dec 15, 2022	SYSTEM	(\$8,754.90)		
						18	Jan 3, 2023	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.
					18	Jan 3, 2023	SYSTEM	(\$8,754.90)		
					19	Jan 16, 2023	SYSTEM	\$8,754.90	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
					19	Jan 16, 2023	SYSTEM	(\$8,754.90)		
				- Total				\$0.00		
	0510 -	Total	Material - To	tal				\$0.00 \$0.00		
	0530	MGS	Construction		2	Apr 18,	SYSTEM	(\$116,280.48)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		GUARDRAIL	Stockpile		3	2022 May 2,	SYSTEM	(\$52,979.50)	Payment Estimate Item Adjustment generated Stockpile Transaction	
				- Total		2022		(\$160.250.09)		
			Construction	Stockpile - 1	Total			(\$169,259.98) (\$169,259.98)		
			Construction Stockpile	- отоокрис -	1	Mar 16, 2022	SYSTEM	\$173,295.75	Payment Estimate Item Adjustment generated Stockpile Transaction	
			STMI	- Total				\$173,295.75		
			Construction	Stockpile S	TMI - Tota			\$173,295.75		
	0530 -	Total						\$4,035.77		
	0540	MGS BRIDGE APP. TRANS SEC (REG/NO	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$16,880.00)	Payment Estimate Item Adjustment generated Stockpile Transaction	
		CURB)		- Total				(\$16,880.00)		
			Construction	Stockpile - 1	Γotal			(\$16,880.00)		
			Construction		1	Mar 16,	SYSTEM	\$21,100.00	Payment Estimate Item Adjustment generated Stockpile Transaction	
			Stockpile STMI			2022		, , , , , , , , , , , , , , , , , , , ,	, , , ,	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks																			
J9I3597	0540	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction	Stockpile S	ГМI - Total			\$21,100.00																				
	0540 -	Total						\$4,220.00																				
	0550	550 MGS END ANCHOR	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$5,130.00)	Payment Estimate Item Adjustment generated Stockpile Transaction																			
					3	May 2, 2022	SYSTEM	(\$8,550.00)	Payment Estimate Item Adjustment generated Stockpile Transaction																			
				- Total				(\$13,680.00)																				
				Stockpile - 1				(\$13,680.00)																				
			Construction Stockpile STMI	- Total	1	Mar 16, 2022	SYSTEM	\$15,390.00 \$15,390.00	Payment Estimate Item Adjustment generated Stockpile Transaction																			
			Construction	Stockpile S	FML Total			\$15,390.00																				
	0550 -	Total	Construction	i Stockpile S	i wii - Totai			\$1,710.00																				
	0560	TYPE A CRASHWORTHY	Construction Stockpile		2	Apr 18, 2022	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction																			
		END TERMINAL (MASH)			3	May 2, 2022	SYSTEM	(\$19,500.00)	Payment Estimate Item Adjustment generated Stockpile Transaction																			
				- Total				(\$39,000.00)																				
			Construction	Stockpile - 1	Total			(\$39,000.00)																				
			Construction Stockpile STMI		1	Mar 16, 2022	SYSTEM	\$42,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction																			
				- Total				\$42,900.00																				
	0560 -	Takal	Construction	Stockpile S	IMI - Total			\$42,900.00																				
	0570	CURB	Material		7	lul 1	SYSTEM	\$3,900.00	This adjustment offsets the original system generated Material Downent																			
	0370	BLOCKOUT	iviateriai		,	Jul 1, 2022	STSTEM	\$38,146.35	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user woodsk1 overridding Payment Estimate Exception 16 on the current Payment Estimate.																			
					7	Jul 1, 2022	SYSTEM	(\$38,146.35)																				
					8	Jul 18, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.																			
							8	Jul 18, 2022	SYSTEM	(\$76,417.77)																		
										9	Aug 16, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.														
																								9	Aug 16, 2022	SYSTEM	(\$76,417.77)	
														10	Sep 2, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.										
								10	Sep 2, 2022	SYSTEM	(\$76,417.77)																	
												11	Sep 16, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user george2 overridding Payment Estimate Exception 16 on the current Payment Estimate.												
								11	Sep 16, 2022	SYSTEM	(\$76,417.77)																	
														12	Sep 30, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.										
					12	Sep 30, 2022	SYSTEM	(\$76,417.77)																				
					13	Oct 17, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0015) due to user holtb3 overridding Payment Estimate Exception 18 on the current Payment Estimate.																			
					13	Oct 17, 2022	SYSTEM	(\$76,417.77)																				
					14	Nov 1,	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment																			





oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks	
13597	0570	CURB BLOCKOUT	Material			2022			Estimate Item Adjustment (0020) due to user holtb3 overridding Payment Estimate Exception 21 on the current Payment Estimate.	
					14	Nov 1, 2022	SYSTEM	(\$76,417.77)		
						15	Nov 15, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0012) due to user holtb3 overridding Payment Estimate Exception 23 on the current Payment Estimate.
					15	Nov 15, 2022	SYSTEM	(\$76,417.77)		
					16	Dec 2, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0017) due to user holtb3 overridding Payment Estimate Exception 23 on the current Payment Estimate.	
					16	Dec 2, 2022	SYSTEM	(\$76,417.77)		
					17	Dec 15, 2022	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					17	Dec 15, 2022	SYSTEM	(\$76,417.77)		
					18	Jan 3, 2023	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.	
					18	Jan 3, 2023	SYSTEM	(\$76,417.77)		
						19	Jan 16, 2023	SYSTEM	\$76,417.77	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user holtb3 overridding Payment Estimate Exception 22 on the current Payment Estimate.
					19	Jan 16, 2023	SYSTEM	(\$76,417.77)		
				- Total				\$0.00		
			Material - To	tal				\$0.00		
	0570 -	Total						\$0.00		
	5002	SEQUENTIAL FLASHING WARNING LIGHT	G	Material		14	Nov 1, 2022	SYSTEM	\$3,843.00	This adjustment offsets the original system-generated Material Payment
		WARNING LIGHT							Estimate Item Adjustment (0021) due to user holtb3 overridding Payment Estimate Exception 17 on the current Payment Estimate.	
		WARNING LIGHT			14	Nov 1, 2022	SYSTEM	(\$3,843.00)		
		WARNING LIGHT			14	Nov 1,	SYSTEM	(\$3,843.00) \$3,843.00		
		WARNING LIGHT				Nov 1, 2022 Nov 15,			Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment	
		WARNING LIGHT			15	Nov 1, 2022 Nov 15, 2022 Nov 15,	SYSTEM	\$3,843.00	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment	
		WARNING LIGHT			15	Nov 1, 2022 Nov 15, 2022 Nov 15, 2022 Dec 2,	SYSTEM	\$3,843.00	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment	
		WARNING LIGHT		- Total	15 15	Nov 1, 2022 Nov 15, 2022 Nov 15, 2022 Dec 2, 2022	SYSTEM SYSTEM	\$3,843.00 (\$3,843.00) \$3,843.00	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment	
		WARNING LIGHT	Material - To		15 15	Nov 1, 2022 Nov 15, 2022 Nov 15, 2022 Dec 2, 2022	SYSTEM SYSTEM	\$3,843.00 (\$3,843.00) \$3,843.00 (\$3,843.00)	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment	
	5002 -		Material - To		15 15	Nov 1, 2022 Nov 15, 2022 Nov 15, 2022 Dec 2, 2022	SYSTEM SYSTEM	\$3,843.00 (\$3,843.00) \$3,843.00 (\$3,843.00)	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment	
13597 -			Material - To		15 15	Nov 1, 2022 Nov 15, 2022 Nov 15, 2022 Dec 2, 2022	SYSTEM SYSTEM	\$3,843.00 (\$3,843.00) \$3,843.00 (\$3,843.00) \$0.00	Estimate Exception 17 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0013) due to user holtb3 overridding Payment Estimate Exception 16 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0018) due to user holtb3 overridding Payment	