

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2022

Progress Estima	ate Number	Contract ID Prime Contractor	211217-H06 Robertson Contractors, Inc.			Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,569,406.64 \$387,364.40 \$3,956,771.04
Approval Date							By User
July 1, 2022			Generated and Approved	(and should be consi	dered Draft) at	the Project Office Level by	bollis1
July 1, 2022		R	Reviewed and Approved (and	should be considered	d Draft) at the F	Resident Engineer Level by	bollis1
July 5, 2022			Reviewed	and Approved at the	Central Office	Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2022	December 1, 2022		77.01%

	Contract Informational Dat	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	January 5, 2022	January 5, 2022	
Letting Date	December 17, 2021	December 17, 2021	
Notice to Proceed Date	February 7, 2022	February 7, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total Pay	For Estimate No. 10				
		This Estimate	Previous	To Date	
211217-H06					
	Total Posted Items Pay	\$375,318.30	\$2,671,786.50	\$3,047,104.80	
	Gross Item Adjustments	(\$24,936.21)	\$142,371.61	\$117,435.40	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$2,814,158.11	\$3,164,540.20	
<b>Contract Total Pay</b>	/able This Estimate:	\$350,382.09			

### **Items Paid This Estimate Period**

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J9S3560	0340	7034222	SLAB ON CONCRETE BEAM	SQYD	\$430.000	37.3	\$16,039.00
	0490	7034222	SLAB ON CONCRETE BEAM	SQYD	\$430.000	708.7	\$304,741.00
	0520	7123610	SLAB DRAIN	EA	\$350.000	44	\$15,400.00
	5003	7029902	MISC.Changing end plates for 36" Piling from 3/4" to 2" thickness.	EA	\$2,174.350	8	\$17,394.80
	5004	7029902	MISC.Changing end plates for 36" Piling from 3/4" to 2" thickness.	EA	\$2,174.350	10	\$21,743.50
Project J9S35	60 - Total						\$375,318.30
Overall - Tota	ı						\$375,318.30

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

		ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3560	0020	POROUS BACKFILL	Material			-36	\$95.00	(\$3,420.00)
	0020	POROUS BACKFILL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.	36	\$95.00	\$3,420.00
	0340	SLAB ON CONCRETE BEAM	Material			-746	\$430.00	(\$320,780.00)
	0340	SLAB ON CONCRETE BEAM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item	746	\$430.00	\$320,780.00

Revision 4/1/2020 Page 1 of 15

(\$24,936.21)



Total

### Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 30, 2022

Progr		timate Number 10	Contract ID Prime Contr	211217 ractor Roberts				r Amount	\$3,569,406.64 \$387,364.40 \$3,956,771.04	
Project Number	Line No.	Item Desc	ription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount	
J9S3560						Adjustment (0004) due to user woodsk1 overridding Payment Estimate Exception 3 on the current Payment Estimate.				
	0490	SLAB ON CONC	RETE BEAM	Construction Stockpile		Payment Estimate Item Adjustment generated Stockpile Transaction			(\$24,936.21)	
	0490	SLAB ON CONC	RETE BEAM	Material			-708.7	\$430.00	(\$304,741.00)	
	0490	SLAB ON CONC	RETE BEAM	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	708.7	\$430.00	\$304,741.00	

Revision 4/1/2020 Page 2 of 15



### Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					C	ontract Project Informatio	n
Project Number	Federal Proj. Number	Project Description	Route	County		,	Location of Work
J9S3560	FAS S703(5)	Bridge Replacement	162	NEW MADRID	over Drainage Ditches 1 & 2	251	
J9S3562	FAS S703(8)	Culvert replacement	162	NEW MADRID	over Drainage Ditch 62		
Totals by .	Job Numb	ers					
J9S3560		ed Item Pay s Item Adjustm		Item Pay	This Estimate \$375,318.30 (\$24,936.21) \$350,382.09	Previous \$2,671,786.50 \$142,371.61 \$2,814,158.11 \$0.00	To Date \$3,047,104.80 \$117,435.40 \$3,164,540.20 \$0.00
	Disin Liqui	centive dated Damages r Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00
J9S3562		ed Item Pay s Item Adjustm		Item Pay	This Estimate \$0.00 \$0.00 <b>\$0.00</b>	Previous \$0.00 \$0.00 \$0.00	<b>To Date</b> \$0.00 \$0.00 <b>\$0.00</b>
	Liqui	itive centive dated Damages r Contract Adju			\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00	\$0.00 \$0.00 \$0.00 \$0.00

Revision 4/1/2020 Page 3 of 15



### Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

### **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 2064000, Project Item Line Number 0020, Material Set 206400096, Material 1009G5DRLS - Agg for Drainage Gr5 Limestone, Acceptance Action Generic 1009G5DRLS is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 2064000, Project Item Line Number 0020, Material Set 206400096, Material 1009G3DRLD - Agg for Drainage Gr3 Limestone/Dolomite, Acceptance Action Generic 1009G3DRLD is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7034222, Project Item Line Number 0340, Material Set 703422296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7034222, Project Item Line Number 0490, Material Set 703422296, Material 0501CCB2MDA - Concrete, Modified B-2 w/Air, Acceptance Action Generic 0501CCB2MDA is insufficient.	No Remark was entered by Engineer	woodsk1	Overridden

Revision 4/1/2020 Page 4 of 15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	eport Generated date and can differ from the posted ame Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved	Unit Price	Total Value POST To Date (See repo generated date)
1217-H06	J9S3560	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	Qty 0.87	\$12,500.00	\$10,825
		0001	0020	2064000	POROUS BACKFILL	72.00	0.00	72.00	CUYD	36.00	\$95.00	\$3,420
		0001	0030	2079909	MISC.MODIFIED LINEAR GRADING, CLASS 2	7.90	0.00	7.90	STA	0.00	\$2,400.00	\$0
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,213.00	0.00	1,213.00	SQYD	0.00	\$15.50	\$0
		0001	0050	3105003	GRAVEL (A) OR CRUSHED STONE (B)	32.00	0.00	32.00	SQYD	0.00	\$25.00	\$0
		0001	0060	4039905	MISC.OPTIONAL PAVEMENT	1,213.00	0.00	1,213.00	SQYD	0.00	\$57.00	\$0
		0001	0070	6113020	FURNISHING TYPE 2 ROCK BLANKET	1,005.00	0.00	1,005.00	CUYD	961.00	\$40.00	\$38,44
			0080	6113040	PLACING TYPE 2 ROCK BLANKET	1,005.00	0.00	1,005.00	CUYD	961.00	\$18.00	\$17,29
		0001	0090	6161005	CONSTRUCTION SIGNS	613.00	728.00	1,341.00	SQFT	1,341.00	\$6.50	\$8,71
		0001										
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$25.00	\$10
		0001	0110	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$135.00	\$1,35
		0001	0120	6161052	WARNING LIGHT, TYPE B	12.00	0.00	12.00	EA	12.00	\$45.00	\$54
		0001	0130	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,00
		0001	0140	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$155,000.00	\$
		0001	0141	6181000	MOBILIZATION	0.00	1.00	1.00	LS	1.00	\$130,514.00	\$130,51
		0001	0150	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,128.00	0.00	2,128.00	LF	0.00	\$0.50	\$
		0001	0160	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,341.00	0.00	1,341.00	SQYD	1,268.00	\$4.00	\$5,07
		0001	0170	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	1.00	\$15,000.00	\$15,00
		0001	0180	8051000A	SEEDING - COOL SEASON GRASSES	1.00	0.00	1.00	ACRE	0.00	\$5,350.00	
		0001	0190	8061016	SEDIMENT REMOVAL	18.00	0.00	18.00	CUYD	0.00	\$5.00	
		0001	0200	8061017	TEMPORARY SEEDING	0.20	0.00	0.20	ACRE	0.00	\$15,000.00	
		0001	0210	8061019	SILT FENCE	1,264.00	0.00	1,264.00	LF	0.00	\$2.70	
		0001	0220	8061050	TYPE C BERM	313.00	0.00	313.00	LF	0.00	\$10.00	
		0010	0230	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	0.00	\$5,033.56	
		0010	0240	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,507.98	
		0010	0250	6063017	TYPE C CRASHWORTHY END TERMINAL	6.00	-6.00	0.00	EA	0.00	\$27,807.91	
		0070	0260	2061000	CLASS 1 EXCAVATION	50.00	0.00	50.00	CUYD	50.00	\$50.00	\$2,5
		0070	0270	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$50,000.00	\$50,0
		0070	0280	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	107.00	0.00	107.00	SQYD	0.00	\$160.00	
		0070	0290	7021316	GALVANIZED CAST-IN-PLACE CONCRETE PILES (16 IN)	648.00	-158.00	490.00	LF	490.00	\$235.00	\$115,1
		0070	0300	7025001	DYNAMIC PILE TESTING	4.00	2.00	6.00	EA	6.00	\$3,000.00	\$18,0
		0070	0310	7029903	MISC.GALVANIZED CAST-IN-PLACE CONCRETE PILES (36 IN)	450.00	449.00	899.00	LF	899.00	\$425.00	\$382,0
		0070	0320	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	50.40	0.00	50.40	CUYD	36.80	\$980.00	\$36,0
		0070	0330	7034216	TYPE H BARRIER	505.00	0.00	505.00	LF	0.00	\$125.00	
		0070	0340	7034222	SLAB ON CONCRETE BEAM	746.00	0.00	746.00	SQYD	746.00	\$430.00	\$320,7
		0070	0350	7056051A	33 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	994.00	0.00	994.00	LF	994.00	\$445.00	\$442,3
		0070	0360	7061060	REINFORCING STEEL (BRIDGES)	5,690.00	0.00	5,690.00	LB	5,690.00	\$2.10	\$11,9
		0070	0370	7123610	SLAB DRAIN	44.00	0.00	44.00	EA	44.00	\$350.00	\$15,4
		0070	0380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	2.00	\$1,600.00	\$3,2
		0070	0390	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$300.00	\$2,4
			0400	7161000			0.00	16.00		16.00	\$450.00	\$7,2
		0070			LAMINATED NEOPRENE BEARING PAD	16.00			EA			
		0071	0410	2061000	CLASS 1 EXCAVATION	50.00	0.00	50.00	CUYD	50.00	\$50.00	\$2,5
		0071	0420	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$50,000.00	\$50,0
		0071	0430		BRIDGE APPROACH SLAB (MINOR ROAD)	107.00	0.00	107.00	SQYD	0.00	\$160.00	
		0071	0440	7021316	GALVANIZED CAST-IN-PLACE CONCRETE PILES (16 IN)	456.00	-49.00	407.00	LF	407.00	\$235.00	\$

Page 5 of 15 Revision 4/1/2020



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

9\$3560	0071	0450	700=0-						Qty		generated date)
	0071		7025001	DYNAMIC PILE TESTING	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.0
		0460	7029903	MISC.GALVANIZED CAST-IN-PLACE CONCRETE PILES (36 IN)	450.00	342.00	792.00	LF	792.00	\$425.00	\$336,600.0
	0071	0470	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	50.40	0.00	50.40	CUYD	50.40	\$980.00	\$49,392.0
	0071	0480	7034216	TYPE H BARRIER	505.00	0.00	505.00	LF	0.00	\$125.00	\$0.0
	0071	0490	7034222	SLAB ON CONCRETE BEAM	746.00	0.00	746.00	SQYD	708.70	\$430.00	\$304,741.0
	0071	0500	7056051A	81060 REINFORCING STEEL (BRIDGES) 5,69	994.00	0.00	994.00	LF	994.00	\$445.00	\$442,330.0
	0071	0510	7061060		5,690.00	0.00	5,690.00	LB	5,690.00	\$2.10	\$11,949.0
	0071	0520	7123610		44.00	0.00	0.00 44.00	EA	44.00	\$350.00	\$15,400.0
	0071	0530	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,565.00	\$0.0
	0071	0540	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	8.00	\$1,600.00	\$12,800.0
	0071	0550	7161002	LAMINATED NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	16.00	\$300.00	\$4,800.0
	0001	5001	6199901	MISC.Payment for Contract Bond	0.00	1.00	1.00	LS	1.00	\$24,486.00	\$24,486.0
	0010	5002	6063020	TYPE C CRASHWORTHY END TERMINAL (MASH)	0.00	6.00	6.00	EA	0.00	\$36,135.26	\$0.0
	0070	5003	7029902	MISC.Changing end plates for 36" Piling from 3/4" to 2" thickness.	0.00	8.00	8.00	EA	8.00	\$2,174.35	\$17,394.8
	0071	5004	7029902	MISC.Changing end plates for 36" Piling from 3/4" to 2" thickness.	0.00	10.00	10.00	EA	10.00	\$2,174.35	\$21,743.5
roject J9	S3560 - To	otal Value	Posted to D	ate as of Report Generated Date							\$3,047,104.8
9S3562	0001	0560	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$8,500.00	\$0.0
	0001	0570	2063000	CLASS 3 EXCAVATION	67.00	0.00	67.00	CUYD	0.00	\$25.00	\$0.0
	0001	0580	2079909	MISC.MODIFIED LINEAR GRADING, CLASS 2	1.80	0.00	1.80	STA	0.00	\$7,500.00	\$0.0
	0001	0590	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	102.00	0.00	102.00	SQYD	0.00	\$22.00	\$0.0
	0001	0600	4019905	MISC.Optional Pavement	102.00	0.00	102.00	SQYD	0.00	\$56.00	\$0.
	0001	0610	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE	19.70	0.00	19.70	TONS	0.00	\$145.00	\$0.0
	0001	0620	4071005	TACK COAT	28.00	0.00	28.00	GAL	0.00	\$5.00	\$0.0
	0001	0630	6097000	ROCK LINING	26.00	0.00	26.00	CUYD	0.00	\$85.00	\$0.
	0001	0640	6149902	MISC.36 IN FLAP GATE	2.00	0.00	2.00	EA	0.00	\$1,500.00	\$0.
	0001	0650	6161005	CONSTRUCTION SIGNS	578.00	0.00	578.00	SQFT	0.00	\$6.50	\$0.
	0001	0660	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	0.00	\$25.00	\$0.
	0001	0670	6161030	TYPE III MOVEABLE BARRICADE	11.00	0.00	11.00	EA	0.00	\$135.00	\$0.
	0001	0680	6161052	WARNING LIGHT, TYPE B	18.00	0.00	18.00	EA	0.00	\$45.00	\$0.
	0001	0690	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED.	2.00	0.00	2.00	EA	0.00	\$1,800.00	\$0.0
	0001	0700	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$35,000.00	\$0.
	0001	0710	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	368.00	0.00	368.00	LF	0.00	\$0.50	\$0.
	0001	0720	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	46.00	0.00	46.00	LF	0.00	\$0.50	\$0.
	0001	0730	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF	347.00	0.00	347.00	SQYD	0.00	\$10.00	\$0.
	0001	0740	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$5,000.00	\$0.
	0001	0750	7250436	36 IN. PIPE GROUP C	76.00	0.00	76.00	LF	0.00	\$95.00	\$0.
	0001	0760	8051000A	SEEDING - COOL SEASON GRASSES	1.00	0.00	1.00	ACRE	0.00	\$5,350.00	\$0.
	0001	0770	8061005	ROCK DITCH CHECK	20.00	0.00	20.00	LF	0.00	\$28.50	\$0.
	0001	0780	8061016	SEDIMENT REMOVAL	6.00	0.00	6.00	CUYD	0.00	\$5.00	\$0.
		0790	8061017	TEMPORARY SEEDING	0.10	0.00	0.10	ACRE	0.00	\$15,000.00	\$0.
											\$0.
					185.00	0.00	185.00	CUYD	0.00	\$50.00	\$0.
											\$0.0
											\$0.
		0071 0071 0071 0071 0071 0001 0000 0070 0071 0001	0071 0530 0071 0540 0071 0550 0071 0550 0001 5001 0010 5002 0070 5003 0071 5004  283562 0001 0560 0001 0590 0001 0690 0001 0600 0001 0640 0001 0650 0001 0660 0001 0660 0001 0670 0001 0680 0001 0690 0001 0690 0001 0700 0001 0700 0001 0700 0001 0720 0001 0740 0001 0750 0001 0750 0001 0750 0001 0750 0001 0750 0001 0750 0001 0750 0001 0760 0001 0760 0001 0770 0001 0780 0001 0790 0001 0790 0001 0790 0001 0790	0071 0530 7151001 0071 0540 7161000 0071 0550 7161002 0001 5001 6199901 0010 5002 6063020 0070 5003 7029902 0071 5004 7029902 0071 5004 7029902 0071 5004 7029902 0071 5004 7029909 0001 0560 2022010 0001 0580 2079909 0001 0590 3040506 0001 0690 4019905 0001 0610 4020520 0001 0630 6097000 0001 0640 6149902 0001 0650 6161005 0001 0660 6161008 0001 0660 6161008 0001 0670 6161030 0001 0690 6161098A 0001 0700 6181000 0001 0710 6206000C 0001 0720 6206001C 0001 0740 6274000 0001 0750 7250436 0001 0760 8051000A 0001 0760 8051000A 0001 0780 8061017 0001 0790 8061017 0001 0790 8061017	0071   0530   7151001   VERTICAL DRAIN AT END BENTS	0071   0550   7151001   VERTICAL DRAIN AT END BENTS   2.00	0071   0530   7151001   VERTICAL DRAIN AT END BENTS   2.00   0.00	0071   0530   7151001   VERTICAL DRAIN AT END BENTS   2.00   0.00   2.00   0.071   0540   7161000   PLAIN NEOPPENE BEARING PAD   8.00   0.00   6.00   0.00	DOT1   0530   7151001   VERTICAL DRAIN AT END BENTS   2.00   0.00   2.00   EA		0071   0500   7151001   VERTICAL DRAIN AT END BENTS   2.00   0.00   2.00   EA   0.00   51,665.00

Revision 4/1/2020 Page 6 of 15



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description		Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
211217-H06	J9S3562	0070	0840	7034041	CLASS B-1 CONCRETE (CULVERTS)		141.60	0.00	141.60	CUYD	0.00	\$985.00	\$0.00
		0070	0850	7061030	REINFORCING STEEL (CULVERTS)	2	27,490.00	0.00	27,490.00	LB	0.00	\$1.85	\$0.00
	Project J	9S3562 - To	tal Value	Posted to D	late as of Report Generated Date								\$0.00
211217-H06 Ove	217-H06 Overall - Total Value Posted to Date as of Report Generated Date								\$3,047,104.80				

Revision 4/1/2020 Page 7 of 15



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3560

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0340	7034222	SLAB ON CONCRETE BEAM	6/29/22	6/29/22	37.30	SQYD	Bridge A8991	389+48.25		392+00.75		Bridge achieved 7-Day wet cure pay remaining 5%. Pay = 37.30 SY
0490	7034222	SLAB ON CONCRETE BEAM	6/29/22	6/29/22	708.70	SQYD	Bridge A8992	393+59.25		396+11.75		Deck Forming = 35% Rebar tiled in place = 20% Concrete placement = 40% Total = 95% Plan = 746 SY x 0.95 = 708.7 SY Pay = 708.7 SY
0520	7123610	SLAB DRAIN	6/29/22	6/29/22	44.00	EA	Bridge A8992	393+59.25		396+11.75		
5003	7029902	MISC. BEARING PILE	6/29/22	6/29/22	8.00	EA	Bridge A8991	390+29.50		391+19.50		Bent 2 = 4 Bent 3 = 4
5004	7029902	MISC. BEARING PILE	6/29/22	6/29/22	10.00	EA	Bridge A8992	394+40.50		395+30.50		Bent 2 = 5 Bent 3 = 5

Project	Line	DWR Date	Total Quantity Posted For DWR	Sign Information	Station	Log	Location	Number of	SF Each	Special Sign	SF Each Special	Total SF t			
	Number		Date			Mile		Items	Sign		Sign	Post			
3560	0090	February 15, 2022	1277	See Special Sign Details		0.111	Rte F South	1.00		Numbered Route Sign Blank 36" x 78" 50D	19.50	1			
				See Special Sign Details		1.082	Rte EE West	1.00		Numbered Route Sign Blank 36" x 78" 50E	19.50	1			
				See Special Sign Details		1.836	Rte J North	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50	1			
				MO4-8a 24x18 3.00 END DETOUR		11.602	Rte 162 West	1.00	3		3.00				
				See Special Sign Details		13.292	Rte 162 East	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50	1			
				See Special Sign Details		13.542	Rte 162 West	1.00		Special Sign 56A 96" x 48"	32.00				
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		13.589	Rte 162 West	1.00	12.5	N	12.50	1			
				See Special Sign Details		14.494	Rte B North	1.00		Numbered Route Sign Blank 36" x 78" 50E	19.50				
				See Special Sign Details		14.748	153 North in Gideon	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		15.38	153 North	1.00		Numbered Route Sign Blank 36" x 78" 50C	19.50				
				See Special Sign Details		16.208	Rte 162 East	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		16.637	Rte 162 East	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		16.771	153 North	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		16.943	Rte 162 East	1.00		Numbered Route Sign Blank 36" x 78" 50C	19.50				
				See Special Sign Details		17.028	Rte W West	2.00		Numbered Route Sign Blank 36" x 78" 50B 50E	19.50				
				See Special Sign Details		17.143	Rte 62 East	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		17.915	153 North	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		18.967	Rte 153 South	2.00		Numbered Route Sign Blank 36" x 78" 50B 50E	19.50				
				See Special Sign Details		2.063	Rte NN South	1.00		Numbered Route Sign Blank 36" x 78" 50B	19.50				
				See Special Sign Details		2.134	Rte J South	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		20.024	Rte 162 West	1.00		Special Sign 56B 96" x 48"	32.00				
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		20.058	Rte 162 West	1.00	12.5		12.50				
				See Special Sign Details		20.122	Rte 62 East	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		20.946	Rte 162 West	1.00	16		16.00				
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		21.046	Rte 162 West	1.00	16	Road Closed 500 FT	16.00				
								R11-2 48x30 10.00 ROAD CLOSED		21.189	Rte 162 West	1.00	10		10.00
				See Special Sign Details		23.054	Rte 62 East	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		26.340	Rte 62 East	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		27.793	Rte 153 North	1.00		Numbered Route Sign Blank 36" x 78" 50C	19.50				
				See Special Sign Details		28.869	153 South	1.00		Numbered Route Sign Blank 36" x 78" 50C	19.50				
				See Special Sign Details		29.021	Rte 62 East	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		3.67	162 East	1.00		Special Sign 56C 96" x 48"	32.00				
				R11-4 60x30 12.50 ROAD CLOSED TO THRU TRAFFIC		3.709	162 East	1.00	12.5		12.50				
				See Special Sign Details		3.81	Rte J North	1.00		Numbered Route Sign Blank 36" x 78" 50C	19.50				
				See Special Sign Details		3.859	Rte J South	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		30.253	153 South	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				MO4-8a 24x18 3.00 END DETOUR		31.564	153 South	1.00	3		3.00				
				See Special Sign Details		31.929	Rte 62 East	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		34.233	Rte 62 East	1.00		Numbered Route Sign Blank 36" x 78" 50C	19.50				
				See Special Sign Details		347.739	Rte 61 South	1.00		Numbered Route Sign Blank 36" x 78" 50E	19.50				
				See Special Sign Details		349.13	Rte 61 South	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		350.228	Rte 61 South	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		351.852	Rte 61 South	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		353.267	Rte 61 South	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		355.317	Rte 61 South	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		357.419	Rte 61 South	1.00		Numbered Route Sign Blank 36" x 78" 50A	19.50				
				See Special Sign Details		36.314	Rte 61 North	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		38.578	Rte 61 North	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		4.364	Rte B South	1.00		Numbered Route Sign Blank 36" x 78" 50C	19.50				
				See Special Sign Details		40.331	Rte 61 North	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		42.043	Rte 61 North	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		43.430	Rte 61 North	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		44.765	Rte 61 North	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		45.955	Rte 61 North	1.00		Numbered Route Sign Blank 36" x 78" 50D	19.50				
				See Special Sign Details		54.777	Rte 62 West	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		57.487	Rte 62 West	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				
				See Special Sign Details		6.298	Rte F South	1.00		Numbered Route Sign Blank 36" x 78" 50D	19.50				
				See Special Sign Details		60.366	Rte 62 West	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50				

Revision 4/1/2020 Page 8 of 15



### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The information below this line are details for Construction Signs (if applicable)

Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9S3560			1277	See Special Sign Details		66.584	Rte 62 West	1.00		Numbered Route Sign Blank 36" x 78" 50F	19.50	19.5
		2022		See Special Sign Details		69.162	Rte 62 West	1.00		Numbered Route Sign Blank 36" x 78" 50D	19.50	19.5
				See Special Sign Details		7.02	Rte EE East	1.00		Numbered Route Sign Blank 36" x 78" 50D	19.50	19.5
				See Special Sign Details		7.678	Rte M West	1.00		Numbered Route Sign Blank 36" x 78" 50E	19.50	19.5
				WO20-3 48x48 16.00 ROAD CLOSED AHEAD		8.053	Rte 162 East	1.00	16		16.00	16
			64	WO20-3 48x48 16.00 ROAD CLOSED AHEAD		8.177	Rte 162 East	1.00	16	Road Closed 500 FT	16.00	16
				R11-2 48x30 10.00 ROAD CLOSED		8.297	Rte 162 East	1.00	10		10.00	10
		May 2, 2022		CONST-5 96x48 32.00 POINT OF PRESENCE		7.931	Eastbound Rte 162	1.00	32	Focus on Bridges	32.00	32
				CONST-5 96x48 32.00 POINT OF PRESENCE		19.939	Westbound Rte 162	1.00	32	Focus on Bridges	32.00	32
	0090 - Total											1340.5

Revision 4/1/2020 Page 9 of 15

## MoDOT

### Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3560	0020	POROUS BACKFILL	Material		9	Jun 16, 2022	SYSTEM	\$3,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					9	Jun 16, 2022	SYSTEM	(\$3,420.00)	
					10	Jun 30, 2022	SYSTEM	\$3,420.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user woodsk1 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					10	Jun 30, 2022	SYSTEM	(\$3,420.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0020 -	Total						\$0.00	
	0070	FURNISHING TYPE 2 ROCK BLANKET	Material		3	Mar 16, 2022	SYSTEM	\$19,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					3	Mar 16, 2022	SYSTEM	(\$19,960.00)	
					4	Apr 5, 2022	SYSTEM	\$19,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					4	Apr 5, 2022	SYSTEM	(\$19,960.00)	
					5	Apr 18, 2022	SYSTEM	\$19,960.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					5	Apr 18, 2022	SYSTEM	(\$19,960.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0070 -	Total						\$0.00	
	0090	CONSTRUCTION SIGNS	Material		1	Feb 16, 2022	SYSTEM	\$8,300.50	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.
					1	Feb 16, 2022	SYSTEM	(\$8,300.50)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
			Overrun	Overrun	1	Feb 16, 2022	SYSTEM	\$4,316.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0001) overridding Payment Estimate Exception 6 on the current Payment Estimate. Material Insufficiency Quantity 1277.000; Overrun Quantity Balance 664.00.
					1	Feb 16, 2022	SYSTEM	(\$4,316.00)	
					2	Mar 3, 2022	SYSTEM	(\$4,316.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					5	Apr 18, 2022	SYSTEM	\$4,316.00	Unit price based on averaged overrun adjustments for installed quantity on all previous payment estimates. Price Adjustments of ',6.50000 - 6.50000, 'is applied (if non-zero).
				Overrun - T	otal			\$0.00	
			Overrun - To	tal				\$0.00	
	0090 -							\$0.00	
	0100	ADVANCED WARNING RAIL SYSTEM	Material		1	Feb 16, 2022	SYSTEM	\$100.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					1	Feb 16, 2022	SYSTEM	(\$100.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0100 -							\$0.00	
	0110	TYPE III MOVEABLE BARRICADE	Material		1	Feb 16, 2022	SYSTEM	\$1,350.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					1	Feb 16,	SYSTEM	(\$1,350.00)	



Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
J9S3560	0110	TYPE III MOVEABLE	Material			2022			
		BARRICADE		- Total				\$0.00	
			Material - To	tal				\$0.00	
	0110 -							\$0.00	
	0120	WARNING LIGHT, TYPE B	Material		1	Feb 16, 2022	SYSTEM	\$540.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 4 on the current Payment Estimate.
					1	Feb 16, 2022	SYSTEM	(\$540.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -	Total						\$0.00	
	0130	CMS W/O COMMUNICATION INTERFACE,	Material		1	Feb 16, 2022	SYSTEM	\$7,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.
		CONT F/			1	Feb 16, 2022	SYSTEM	(\$7,000.00)	
				- Total				\$0.00	
			Material - To					\$0.00	
	0130 -	Total						\$0.00	
	0160	PERMANENT EROSION CONTROL	Material		3	Mar 16, 2022	SYSTEM	\$2,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
		GEOTEXTILE	EOTEXTILE		3	Mar 16, 2022	SYSTEM	(\$2,640.00)	
					4	Apr 5, 2022	SYSTEM	\$2,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					4	Apr 5, 2022	SYSTEM	(\$2,640.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0160 -	Total						\$0.00	
	0230	MGS BRIDGE APP. TRANS SEC (REG/NO CURB)	Construction Stockpile STMI		6	May 2, 2022	SYSTEM	\$6,835.40	Payment Estimate Item Adjustment generated Stockpile Transaction
				- Total				\$6,835.40	
			Construction	1 Stockpile S	ΓΜΙ - Total			\$6,835.40	
	0230 -		0 : ::			м. с	over:	\$6,835.40	Downsta Fether de New Adhart
	0240	TYPE A CRASHWORTHY	Construction Stockpile		6	May 2, 2022	SYSTEM	\$3,900.00	Payment Estimate Item Adjustment generated Stockpile Transaction
		END TERMINAL (MASH)	STMI	- Total				\$3,900.00	
			Construction	Stockpile S	ГМI - Total			\$3,900.00	
	0240 -	Total						\$3,900.00	
	0290	GALVANIZED CIP CONCR PILES (16 IN)	Material		3	Mar 16, 2022	SYSTEM	\$115,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					3	Mar 16, 2022	SYSTEM	(\$115,150.00)	
					4	Apr 5, 2022	SYSTEM	\$115,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.
					4	Apr 5, 2022	SYSTEM	(\$115,150.00)	
					5	Apr 18, 2022	SYSTEM	\$115,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.
					5	Apr 18, 2022	SYSTEM	(\$115,150.00)	
					6	May 2, 2022	SYSTEM	\$115,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.



Section   Column	Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
7	J9S3560	0290	CONCR PILES (16	Material		6		SYSTEM	(\$115,150.00)	
8			IIV)			7		SYSTEM	\$115,150.00	Estimate Item Adjustment (0001) due to user brooks3 overridding Payment
2022						7		SYSTEM	(\$115,150.00)	
2022   9						8		SYSTEM	\$115,150.00	Estimate Item Adjustment (0003) due to user brooks3 overridding Payment
2022   Jun 16, SYSTEM   SSS2,075.00						8		SYSTEM	(\$115,150.00)	
Section   Sect						9		SYSTEM	\$115,150.00	Estimate Item Adjustment (0002) due to user brooks3 overridding Payment
Material - Total						9		SYSTEM	(\$115,150.00)	
Material   Secretarian					- Total				\$0.00	
MISC. BEARING   Material				Material - To	tal				\$0.00	
Estimate Exception 6 on the current Payment Estimate		0290 -	Total						\$0.00	
10022		0310		Material		5		SYSTEM	\$382,075.00	Estimate Item Adjustment (0003) due to user brooks3 overridding Payment
2022   Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.						5		SYSTEM	(\$382,075.00)	
2002   This adjustment offsets the original system-generated Material Payment Estimate Exception 2 on the current Payment Estimate Extended (0002) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.						6		SYSTEM	\$382,075.00	Estimate Item Adjustment (0004) due to user brooks3 overridding Payment
2022   Estimate Item Adjustment (0002) due to user brooks overridding Payment Estimate Exception 9 on the current Payment Estimate Exception 9 on the current Payment Estimate Item Adjustment (0004) due to user brooks overridding Payment Estimate Item Adjustment (0004) due to user brooks overridding Payment Estimate Item Adjustment (0004) due to user brooks overridding Payment Estimate Item Adjustment (0004) due to user brooks overridding Payment Estimate Item Adjustment offsets the original system-generated Material Payment Estimate Estimate Exception 5 on the current Payment Estimate Payment Item						6		SYSTEM	(\$382,075.00)	
2022   SYSTEM   2382,075.00   This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.						7		SYSTEM	\$382,075.00	Estimate Item Adjustment (0002) due to user brooks3 overridding Payment
Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 5 on the current Payment Estimate.  8 Jun 1, 2022   9 Jun 16, SYSTEM   \$382,075.00    9 Jun 16, SYSTEM   \$382,075.00    1 This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.  1 Total						7		SYSTEM	(\$382,075.00)	
2022						8		SYSTEM	\$382,075.00	Estimate Item Adjustment (0004) due to user brooks3 overridding Payment
Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.  9 Jun 16, 2022  S0.00  Material - Total  S0.00  Material - Total  Other Item Adjustment  OVRN 5 Apr 18, 2022  Apr 18, 2022  Fall Quantity = 450 LF As-Built Quantity = 450 LF As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity.  449 LF at \$425.00 = -\$190.825.00.  Apr 18, 2022  SYSTEM \$190.825.00  Pay Quantity = 450 LF As-Built Quantity = 4						8		SYSTEM	(\$382,075.00)	
Total  So.00  Material - Total  Other Item Adjustment  OVRN 5 Apr 18, 2022  Apr 18, 2022  SYSTEM \$190,825.00  6 May 2, 2022  SYSTEM \$190,825.00  Fay Quantity = 450 LF As-Built Quantity, until a change order is created to justify the increase in plan quantity, until a change order is created to justify the increase in plan quantity and the plan quantity, until a change order is created to justify the increase in plan quantity and the plan quantity, until a change order is created to justify the increase in plan quantity. In the plan quantity, until a change order is created to justify the increase in plan quantity. This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, until a change order is created to justify the increase in plan quantity. This line item adjustment is necessary to offset the system override for line item 0310. This line item was adjusted based on quantity on pay estimate 0005. Pay estimate 0006 is including it for pay; this item can not be fully paid until a change order has been created to justify the overrun in quantity.  This line item adjustment is necessary to repay the system override for line item 0310 from pay estimate 0006. The overrun for line item 0310 was processed in Change Order 0004 on 5/17/2022.						9		SYSTEM	\$382,075.00	Estimate Item Adjustment (0003) due to user brooks3 overridding Payment
Solution   Company   Com						9		SYSTEM	(\$382,075.00)	
Other Item Adjustment  OVRN 5 Apr 18, 2022   brooks3 (\$190,825.00)   Pay Quantity = 450 LF As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, until a change order is created to justify the increase in plan quantity, 440 LF at \$425.00 = -\$190,825.00.    Apr 18, 2022   SYSTEM   \$190,825.00   Pay Quantity = 450 LF As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, until a change order is created to justify the increase in plan quantity, 449 LF at \$425.00 = -\$190,825.00.    Apr 18, 2022   Brooks3 (\$190,825.00)   Pay Quantity = 450 LF As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, 449 LF at \$425.00 = -\$190,825.00.    Apr 18, 2022   Brooks3 (\$190,825.00)   This line item adjustment is necessary to offset the system override for line item 0310. This line item was adjusted based on quantity on pay estimate 0005. Pay estimate 0006 is including it for pay; this item can not be fully paid until a change order has been created to justify the overrun in quantity.    Apr 18, 2022   Brooks3 (\$190,825.00)   This line item adjustment is necessary to repay the system override for line item 0310 from pay estimate 0006. The overrun for line item 0310 was processed in Change Order 0004 on 5/17/2022.					- Total				\$0.00	
As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, until a change order is created to justify the increase in plan quantity.  6 May 2, 2022  8 190,825.00  Pay Quantity = 450 LF As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, until a change order is created to justify the increase in plan quantity, until a change order is created to justify the increase in plan quantity, until a change order is created to justify the increase in plan quantity, -449 LF at \$425.00 = -\$190,825.00.  6 May 2, 2022  brooks3 (\$190,825.00)  This line item adjustment is necessary to offset the system override for line item 0310. This line item was adjusted based on quantity on pay estimate 0005. Pay estimate 0006 is including it for pay; this item can not be fully paid until a change order has been created to justify the overrun in quantity.  7 May 17, 2022  This line item adjustment is necessary to repay the system override for line item 0310 from pay estimate 0006. The overrun for line item 0310 was processed in Change Order 0004 on 5/17/2022.				Material - To	tal				\$0.00	
As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, until a change order is created to justify the increase in plan quantity, -449 LF at \$425.00 = -\$190,825.00.  6 May 2, 2022  brooks3 (\$190,825.00) This line item adjustment is necessary to offset the system override for line item 0310. This line item was adjusted based on quantity on pay estimate 0005. Pay estimate 0006 is including it for pay; this item can not be fully paid until a change order has been created to justify the overrun in quantity.  7 May 17, 2022  This line item adjustment is necessary to repay the system override for line item 0310 from pay estimate 0006. The overrun for line item 0310 was processed in Change Order 0004 on 5/17/2022.						5		brooks3	(\$190,825.00)	As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, until a change order is created to justify the increase in plan quantity.
item 0310. This line item was adjusted based on quantity on pay estimate 0005. Pay estimate 0006 is including it for pay; this item can not be fully paid until a change order has been created to justify the overrun in quantity.  7 May 17, 2022  This line item adjustment is necessary to repay the system override for line item 0310 from pay estimate 0006. The overrun for line item 0310 was processed in Change Order 0004 on 5/17/2022.						6		SYSTEM	\$190,825.00	As-Built Quantity = 899 LF This line item adjustment is necessary to reduce the as-built quantity to the plan quantity, until a change order is created to justify the increase in plan quantity.
2022 item 0310 from pay estimate 0006. The overrun for line item 0310 was processed in Change Order 0004 on 5/17/2022.  OVRN - Total \$0.00						6		brooks3	(\$190,825.00)	item 0310. This line item was adjusted based on quantity on pay estimate 0005. Pay estimate 0006 is including it for pay; this item can not be fully paid
						7		brooks3	\$190,825.00	item 0310 from pay estimate 0006. The overrun for line item 0310 was
Other Item Adjustment - Total \$0.00					OVRN - Tot	al			\$0.00	
				Other Item A	.djustment - T	otal			\$0.00	



ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
560	0310	MISC. BEARING PILE	Overrun	Overrun	5	Apr 18, 2022	SYSTEM	\$190,825.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0002) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 899.000; Overrun Quantity Balance 449.00.
					5	Apr 18, 2022	SYSTEM	(\$190,825.00)	
					6	May 2, 2022	SYSTEM	(\$190,825.00)	Averaged Price Adjustment from this item on all previous payment estimates of '0.00000' is applied (if non-zero).
					6	May 2, 2022	SYSTEM	\$190,825.00	This adjustment offsets the original system-generated Overrun Payment Estimate Item Adjustment (0003) overridding Payment Estimate Exception 15 on the current Payment Estimate. Material Insufficiency Quantity 899.000; Overrun Quantity Balance 449.00.
				Overrun - T	otal			\$0.00	
			Overrun - To	otal				\$0.00	
	0310 -	Total						\$0.00	
	0320	CLASS B CONCRETE (SUBSTRUCTURE)	Material		3	Mar 16, 2022	SYSTEM	\$22,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Mar 16, 2022	SYSTEM	(\$22,736.00)	
					4	Apr 5, 2022	SYSTEM	\$22,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					4	Apr 5, 2022	SYSTEM	(\$22,736.00)	
					5	Apr 18, 2022	SYSTEM	\$36,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user brooks3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					5	Apr 18, 2022	SYSTEM	(\$36,064.00)	
					6	May 2, 2022	SYSTEM	\$36,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user brooks3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					6	May 2, 2022	SYSTEM	(\$36,064.00)	
					7	May 17, 2022	SYSTEM	\$36,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					7	May 17, 2022	SYSTEM	(\$36,064.00)	
					8	Jun 1, 2022	SYSTEM	\$36,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user brooks3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					8	Jun 1, 2022	SYSTEM	(\$36,064.00)	
					9	Jun 16, 2022	SYSTEM	\$36,064.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					9	Jun 16, 2022	SYSTEM	(\$36,064.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0320 -							\$0.00	
	0340	SLAB ON CONCRETE BEAM	Construction Stockpile		8	Jun 1, 2022	SYSTEM	(\$24,936.21)	Payment Estimate Item Adjustment generated Stockpile Transaction
			Canaturati	- Total	Cotol			(\$24,936.21)	
			Construction Stockpile	i Stockpile - 1	6	May 2, 2022	SYSTEM	(\$24,936.21) \$24,936.21	Payment Estimate Item Adjustment generated Stockpile Transaction
			STMI	- Total				\$24,936.21	
			Construction	Stockpile S	ΓΜΙ - Total			\$24,936.21	
			Material		8	Jun 1, 2022	SYSTEM	\$176,429.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 17 on the current Payment Estimate.
					8	Jun 1,	SYSTEM	(\$176,429.00)	

## MoDOT

## Line Item Adjustments by Estimate

Туре	Remarks
J9S3560         0340         SLAB ON CONCRETE BEAM         Material         2022	
9 Jun 16, SYSTEM \$304,741.00 This adjustment offs 2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0005) due to user brooks3 overridding Payment 15 on the current Payment Estimate.
9 Jun 16, SYSTEM (\$304,741.00) 2022	
2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0004) due to user woodsk1 overridding Payment 3 on the current Payment Estimate.
10 Jun 30, SYSTEM (\$320,780.00) 2022	
- Total \$0.00	
Material - Total \$0.00	
0340 - Total \$0.00	
CONCR PILES (16 2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0009) due to user brooks3 overridding Payment 4 on the current Payment Estimate.
6 May 2, SYSTEM (\$95,645.00)	
2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0004) due to user brooks3 overridding Payment 4 on the current Payment Estimate.
7 May 17, SYSTEM (\$95,645.00) 2022	
2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0006) due to user brooks3 overridding Payment 3 on the current Payment Estimate.
8 Jun 1, SYSTEM (\$95,645.00)	
2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0006) due to user brooks3 overridding Payment 5 on the current Payment Estimate.
9 Jun 16, SYSTEM (\$95,645.00)	
- Total \$0.00	
Material - Total \$0.00	
0440 - Total \$0.00	
PILE 2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0007) due to user brooks3 overridding Payment 8 on the current Payment Estimate.
8 Jun 1, 2022 (\$336,600.00)	
2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0007) due to user brooks3 overridding Payment 9 on the current Payment Estimate.
9 Jun 16, SYSTEM (\$336,600.00)	
- Total \$0.00	
Material - Total \$0.00	
0460 - Total \$0.00	
CONCRETE 2022 Estimate Item Adjus	sets the original system-generated Material Payment stment (0005) due to user brooks3 overridding Payment 15 on the current Payment Estimate.
7 May 17, SYSTEM (\$22,736.00)	
	sets the original system-generated Material Payment stment (0008) due to user brooks3 overridding Payment 14 on the current Payment Estimate.
SYSTEM   STANDARD   STANDA	sets the original system-generated Material Payment stment (0008) due to user brooks3 overridding Payment 13 on the current Payment Estimate.





Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J9S3560	0470	CLASS B	Material	- Total				\$0.00					
		CONCRETE (SUBSTRUCTURE)	Material - Tot	al				\$0.00					
	0470 -	Total						\$0.00					
	0490	SLAB ON CONCRETE BEAM	Construction Stockpile		10	Jun 30, 2022	SYSTEM	(\$24,936.21)	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total				(\$24,936.21)					
			Construction	Stockpile - 1	Γotal			(\$24,936.21)					
			Construction Stockpile		6	May 2, 2022	SYSTEM	\$24,936.21	Payment Estimate Item Adjustment generated Stockpile Transaction				
			STMI	- Total				\$24,936.21					
			Construction	Stockpile S1	ГМI - Total			\$24,936.21					
			Material		10	Jun 30, 2022	SYSTEM	\$304,741.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user woodsk1 overridding Payment Estimate Exception 4 on the current Payment Estimate.				
					10	Jun 30, 2022	SYSTEM	(\$304,741.00)					
				- Total				\$0.00					
			Material - Tot	al				\$0.00					
	0490 -	Total						\$0.00					
	0510	REINFORCING STEEL (BRIDGES)	Construction Stockpile		8	Jun 1, 2022	SYSTEM	(\$3,904.60)	Payment Estimate Item Adjustment generated Stockpile Transaction				
				- Total				(\$3,904.60)					
			Construction	Stockpile - 1	Total			(\$3,904.60)					
			Construction Stockpile STMI		6	May 2, 2022	SYSTEM	\$3,904.60	Payment Estimate Item Adjustment generated Stockpile Transaction				
			OTIVII	- Total				\$3,904.60					
			Construction	Stockpile S1	MI - Total			\$3,904.60					
								Material		8	Jun 1, 2022	SYSTEM	\$11,949.00
					8	Jun 1, 2022	SYSTEM	(\$11,949.00)					
				- Total				\$0.00					
			Material - Tot	al				\$0.00					
	0510 -	Total						\$0.00					
	5002	TYPE C CRASHWORTHY END TERMINAL	Construction Stockpile STMI		6	May 2, 2022	SYSTEM	\$106,700.00	Payment Estimate Item Adjustment generated Stockpile Transaction				
		(MASH)		- Total				\$106,700.00					
			Construction	Stockpile S1	ГМI - Total			\$106,700.00					
	5002 -	Total						\$106,700.00					
J9S3560 -	Total							\$117,435.40					
Overall -	Total							\$117,435.40					