## Pay Estimate Created Date: April 5, 2022

Progress Estimate N 4	lumber	Contract ID Prime Contractor	211217-H06 Robertson Contra	ctors, Inc.			Original Contract Amount Net Change Order Amount Current Contract Amount	\$3,569,406.64 \$0.00 \$3,569,406.64
Approval Date								By User
April 5, 2022			Generated and A	Approved (	and should be cons	sidered Draft) at	the Project Office Level by	bollis1
April 5, 2022		R	eviewed and Appro	ved (and s	should be considere	Resident Engineer Level by	bollis1	
April 6, 2022			I	Reviewed	and Approved at the	e Central Office	Controllers Office Level by	ramses1
Original Completio	n Date	Current Con	npletion Date	Actu	al Completion Dat	e %	of Current Contract Amount	Complete
December 1, 20	22	Decembe	er 1, 2022				11.40%	
	Contrac	ct Informational Dat	tes		Mileste	ones		
Date Description	Origina	I Completion Date	Current Complet	tion Date	No Milestones Ex	ist for Contract		
Acceptance Date								
Awarded Date	January	5, 2022	January 5, 2022					
Letting Date	Decemb	per 17, 2021	December 17, 20	21				
Notice to Proceed Date	Februar	y 7, 2022	February 7, 2022					
Open to Traffic Date								
Work Began Date								

Contract Total Pa	ay For Estimate No. 4				
		This Estimate	Previous	To Date	
211217-H06					
	Total Posted Items Pay	\$82,628.50	\$324,193.00	\$406,821.50	
	Gross Item Adjustments	\$0.00	(\$4,316.00)	(\$4,316.00)	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
			\$319,877.00	\$402,505.50	
Contract Total Pa	avable This Estimate:	\$82.628.50			

# Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount					
J9S3560					\$130,514.000	0.25	\$32,628.50					
	0420 2160500 REM		REMOVAL OF BRIDGES	LS	\$50,000.000	1	\$50,000.00					
Project J9S3560 -	Total						\$82,628.50					
Overall - Total	rall - Total											

# Contract Adjustments This Estimate

No	Contra	ct Ad	justments	Exist	on C	ontract
Lin	o Itom	Δdiu	etmonte	Thie F	etim	ato

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J9S3560	0070	FURNISHING TYPE 2 ROCK BLANKET	Material			-499	\$40.00	(\$19,960.00)
	0070	FURNISHING TYPE 2 ROCK BLANKET	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0001) due to user brooks3 overridding Payment Estimate Exception 1 on the current Payment Estimate.	499	\$40.00	\$19,960.00
	0160	PERMANENT EROSION CONTROL GEOTEXTILE	Material			-660	\$4.00	(\$2,640.00)
	0160	PERMANENT EROSION CONTROL GEOTEXTILE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.	660	\$4.00	\$2,640.00
	0290	GALVANIZED CAST-IN-	Material			-490	\$235.00	(\$115,150.00)



# Pay Estimate Created Date: April 5, 2022

Progre	ess Esti	imate Number 4	Contract ID Prime Contra		211217-H06 Pay Period Start March 16, 2022 Original Contract Amo ctor Robertson Contractors, Inc. Pay Period End April 1, 2022 Net Change Order Amo Current Contract Amo							
Project Number	Line No.	Item Dese	cription	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount			
J9S3560		PLACE CONC	CRETE PILES (16 IN)									
	0290	GALVANIZ PLACE CONC	ED CAST-IN- CRETE PILES (16 IN)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.	490	\$235.00	\$115,150.00			
	0320		CONCRETE	Material			-23.2	\$980.00	(\$22,736.00			
	0320		CONCRETE TRUCTURE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.	23.2	\$980.00	\$22,736.0			
Total	· · · · ·								\$0.0			



# Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J9S3560	FAS S703(5)	Bridge Replacement	162	NEW MADRID	over Drainage Ditches 1 & 251
J9S3562	FAS S703(8)	Culvert replacement	162	NEW MADRID	over Drainage Ditch 62

## Totals by Job Numbers

53560	This Estimate	Previous	To Date
Posted Item Pay	\$82,628.50	\$324,193.00	\$406,821.50
Gross Item Adjustments	\$0.00	(\$4,316.00)	(\$4,316.00)
Gross Item Pay	\$82,628.50	\$319,877.00	\$402,505.50
Incentive	\$0.00	\$0.00	<b>*</b> 0.00
Incentive			\$0.00
Disincentive	\$0.00	\$0.00	\$0.00
Liquidated Damages	\$0.00	\$0.00	\$0.00
Other Contract Adjustments	\$0.00	\$0.00	\$0.00
53562	This Estimate	Previous	To Date
Posted Item Pay	\$0.00	\$0.00	\$0.00
Gross Item Adjustments	\$0.00	\$0.00	\$0.00
Gross Item Pay	\$0.00	\$0.00	\$0.00
Incentive	\$0.00	\$0.00	\$0.00
Incentive Disincentive	\$0.00 \$0.00	\$0.00	\$0.00



# Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

# Exceptions (Discrepancies) This Estimate Period

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 6113020, Project Item Line Number 0070, Material Set 611302096, Material 0611EPM - Embankment Protection Material, Acceptance Action Generic 0611EPM is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 6240103A, Project Item Line Number 0160, Material Set 6240103A96, Material 1011GXT3 - Geotextile Fabric for ErosionControl(T3), Acceptance Action Generic 1011GXT3 is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7021316, Project Item Line Number 0290, Material Set 702131696, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7021316, Project Item Line Number 0290, Material Set 702131696, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7021316, Project Item Line Number 0290, Material Set 702131696, Material 0702PLCPCCZC - Bearing Piles Shell Casing for CIP Galvd, Acceptance Action Generic 0702PLCPCCZC is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7021316, Project Item Line Number 0290, Material Set 702131696, Material 0501CCB1 - Concrete, Class B-1 No Air, Acceptance Action Generic 0501CCB1 is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7032003, Project Item Line Number 0320, Material Set 703200396, Material 100510CPCMLD - PCCP or Masonry 1" Max LS/DO, Acceptance Action Generic 100510CPCMLD is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7032003, Project Item Line Number 0320, Material Set 703200396, Material 1005FACCNSCA - Natural Sand for Conc Class A, Acceptance Action Generic 1005FACCNSCA is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7032003, Project Item Line Number 0320, Material Set 703200396, Material 0501CCBA - Concrete, Class B w/Air, Acceptance Action Generic 0501CCBA is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Insufficient Materials: Project J9S3560, Item 7032003, Project Item Line Number 0320, Material Set 703200396, Material 0501CCB1.A - Concrete, Class B-1 w/Air, Acceptance Action Generic 0501CCB1.A is insufficient.	No Remark was entered by Engineer	brooks3	Overridden
Estimate Exception Type: Item Overrun: Contract 211217-H06, Contract Project J9S3560, Project Item Line Number 0090, Contract Line Item Number 0090, Item 6161005, Minor Item.	No Remark was entered by Engineer	brooks3	Acknowledged

# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

#### Total Paid / All Items / All Estimates (Including this Estimate)

Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract m.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTE To Date (See repor generated date)
11217-H06	J9S3560	0001	0010	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.87	\$12,500.00	\$10,825.0
		0001	0020	2064000	POROUS BACKFILL	72.00	0.00	72.00	CUYD	0.00	\$95.00	\$0.0
		0001	0030	2079909	MISC.MODIFIED LINEAR GRADING, CLASS 2	7.90	0.00	7.90	STA	0.00	\$2,400.00	\$0.0
		0001	0040	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	1,213.00	0.00	1,213.00	SQYD	0.00	\$15.50	\$0.0
		0001	0050	3105003	GRAVEL (A) OR CRUSHED STONE (B)	32.00	0.00	32.00	SQYD	0.00	\$25.00	\$0.0
		0001	0060	4039905	MISC.OPTIONAL PAVEMENT	1,213.00	0.00	1,213.00	SQYD	0.00	\$57.00	\$0.0
		0001	0070	6113020	FURNISHING TYPE 2 ROCK BLANKET	1,005.00	0.00	1,005.00	CUYD	499.00	\$40.00	\$19,960.0
		0001	0080	6113040	PLACING TYPE 2 ROCK BLANKET	1,005.00	0.00	1,005.00	CUYD	499.00	\$18.00	\$8,982.0
		0001	0090	6161005	CONSTRUCTION SIGNS	613.00	0.00	613.00	SQFT	1,277.00	\$6.50	\$8,300.
		0001	0100	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	4.00	\$25.00	\$100.0
		0001	0110	6161030	TYPE III MOVEABLE BARRICADE	10.00	0.00	10.00	EA	10.00	\$135.00	\$1,350.0
		0001	0120	6161052	WARNING LIGHT, TYPE B	12.00	0.00	12.00	EA	12.00	\$45.00	\$540.0
		0001	0130	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	2.00	\$3,500.00	\$7,000.0
		0001	0140	6181000	MOBILIZATION	1.00	-1.00	0.00	LS	0.00	\$155,000.00	\$0.
		0001	0141	6181000	MOBILIZATION	0.00	1.00	1.00	LS	0.50	\$130,514.00	\$65,257.0
		0001	0150	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	2,128.00	0.00	2,128.00	LF	0.00	\$0.50	\$0.0
		0001	0160	6240103A	PERMANENT EROSION CONTROL GEOTEXTILE	1,341.00	0.00	1,341.00	SQYD	660.00	\$4.00	\$2,640.
		0001	0170	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.33	\$15,000.00	\$4,995.0
		0001	0180	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$5,350.00	\$0.0
		0001	0190	8061016	SEDIMENT REMOVAL	18.00	0.00	18.00	CUYD	0.00	\$5.00	\$0.
		0001	0200	8061017	TEMPORARY SEEDING AND MULCHING	0.20	0.00	0.20	ACRE	0.00	\$15,000.00	\$0.
		0001	0210	8061019	SILT FENCE	1,264.00	0.00	1,264.00	LF	0.00	\$2.70	\$0.
		0001	0220	8061050	TYPE C BERM	313.00	0.00	313.00	LF	0.00	\$10.00	\$0.
		0010	0230	6061069	MGS BRIDGE APPROACH TRANSITION SECTION (REGULAR/NO CURB)	2.00	0.00	2.00	EA	0.00	\$5,033.56	\$0.
		0010	0240	6063014	TYPE A CRASHWORTHY END TERMINAL (MASH)	2.00	0.00	2.00	EA	0.00	\$3,507.98	\$0.
		0010	0250	6063017	TYPE C CRASHWORTHY END TERMINAL	6.00	0.00	6.00	EA	0.00	\$27,807.91	\$0.
		0070	0260	2061000	CLASS 1 EXCAVATION	50.00	0.00	50.00	CUYD	50.00	\$50.00	\$2,500.
		0070	0270	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$50,000.00	\$50,000.
		0070	0280	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	107.00	0.00	107.00	SQYD	0.00	\$160.00	\$0.
		0070	0290	7021316	GALVANIZED CAST-IN-PLACE CONCRETE PILES (16 IN)	648.00	0.00	648.00	LF	490.00	\$235.00	\$115,150.
		0070	0300	7025001	DYNAMIC PILE TESTING	4.00	0.00	4.00	EA	4.00	\$3,000.00	\$12,000.
		0070	0310	7029903	MISC.GALVANIZED CAST-IN-PLACE CONCRETE PILES (36 IN)	450.00	0.00	450.00	LF	899.00	\$425.00	\$382,075.
		0070	0320	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	50.40	0.00	50.40	CUYD	23.20	\$980.00	\$22,736.
		0070	0330	7034216	TYPE H BARRIER	505.00	0.00	505.00	LF	0.00	\$125.00	\$0.
		0070	0340	7034222	SLAB ON CONCRETE BEAM	746.00	0.00	746.00	SQYD	0.00	\$430.00	\$0.
		0070	0350	7056051A	33 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	994.00	0.00	994.00	LF	0.00	\$445.00	\$0.
		0070	0360	7061060	REINFORCING STEEL (BRIDGES)	5,690.00	0.00	5,690.00	LB	0.00	\$2.10	\$0.
		0070	0370	7123610	SLAB DRAIN	44.00	0.00	44.00	EA	0.00	\$350.00	\$0.
		0070	0380	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,600.00	\$0.
		0070	0390	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$300.00	\$0.
		0070	0400	7161002	LAMINATED NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	0.00	\$450.00	\$0.
		0071	0410	2061000	CLASS 1 EXCAVATION	50.00	0.00	50.00	CUYD	0.00	\$50.00	\$0.
		0071	0420	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	1.00	\$50,000.00	\$50,000.
		0071	0430	5031011A	BRIDGE APPROACH SLAB (MINOR ROAD)	107.00	0.00	107.00	SQYD	0.00	\$160.00	\$00,000.
		007.1	00				0.00			0.00	÷	<i>4</i> 0.

# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

# Total Paid / All Items / All Estimates (Including this Estimate)

d date and can differ from the posted amount at the time the Estimate was Generated.

ontract ONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POST To Date (See rep generated date
7-H06	J9S3560	0071	0450	7025001	DYNAMIC PILE TESTING	4.00	0.00	4.00	EA	0.00	\$3,000.00	\$0
		0071	0460	7029903	MISC.GALVANIZED CAST-IN-PLACE CONCRETE PILES (36 IN)	450.00	0.00	450.00	LF	0.00	\$425.00	\$0
		0071	0470	7032003	CLASS B CONCRETE (SUBSTRUCTURE)	50.40	0.00	50.40	CUYD	0.00	\$980.00	\$0
		0071	0480	7034216	TYPE H BARRIER	505.00	0.00	505.00	LF	0.00	\$125.00	\$0
		0071	0490	7034222	SLAB ON CONCRETE BEAM	746.00	0.00	746.00	SQYD	0.00	\$430.00	\$0
		0071	0500	7056051A	33 IN., PRESTRESSED CONCRETE SPREAD BOX BEAM	994.00	0.00	994.00	LF	0.00	\$445.00	\$0
		0071	0510	7061060	REINFORCING STEEL (BRIDGES)	5,690.00	0.00	5,690.00	LB	0.00	\$2.10	\$0
		0071	0520	7123610	SLAB DRAIN	44.00	0.00	44.00	EA	0.00	\$350.00	\$0
		0071	0530	7151001	VERTICAL DRAIN AT END BENTS	2.00	0.00	2.00	EA	0.00	\$1,565.00	\$0
		0071	0540	7161000	PLAIN NEOPRENE BEARING PAD	8.00	0.00	8.00	EA	0.00	\$1,600.00	\$
		0071	0550	7161002	LAMINATED NEOPRENE BEARING PAD	16.00	0.00	16.00	EA	0.00	\$300.00	\$
		0001	5001	6199901	MISC.Payment for Contract Bond	0.00	1.00	1.00	LS	1.00	\$24,486.00	\$24,48
	Project JS	9S3560 - To	otal Value	Posted to D	Date as of Report Generated Date							\$788,89
	J9S3562	0001	0560	2022010	REMOVAL OF IMPROVEMENTS	1.00	0.00	1.00	LS	0.00	\$8,500.00	Ş
		0001	0570	2063000	CLASS 3 EXCAVATION	67.00	0.00	67.00	CUYD	0.00	\$25.00	S
		0001	0580	2079909	MISC.MODIFIED LINEAR GRADING, CLASS 2	1.80	0.00	1.80	STA	0.00	\$7,500.00	ş
		0001	0590	3040506	TYPE 5 AGGREGATE FOR BASE (6 IN. THICK)	102.00	0.00	102.00	SQYD	0.00	\$22.00	S
		0001	0600	4019905	MISC.Optional Pavement	102.00	0.00	102.00	SQYD	0.00	\$56.00	Ş
		0001	0610	4020520	BITUMINOUS PAVEMENT MIXTURE PG64-22 (SURFACE LEVELING)	19.70	0.00	19.70	TONS	0.00	\$145.00	S
		0001	0620	4071005	TACK COAT	28.00	0.00	28.00	GAL	0.00	\$5.00	5
		0001	0630	6097000	ROCK LINING	26.00	0.00	26.00	CUYD	0.00	\$85.00	Ş
		0001	0640	6149902	MISC.36 IN FLAP GATE	2.00	0.00	2.00	EA	0.00	\$1,500.00	Ş
		0001	0650	6161005	CONSTRUCTION SIGNS	578.00	0.00	578.00	SQFT	0.00	\$6.50	ę
		0001	0660	6161008	ADVANCED WARNING RAIL SYSTEM	4.00	0.00	4.00	EA	0.00	\$25.00	:
		0001	0670	6161030	TYPE III MOVEABLE BARRICADE	11.00	0.00	11.00	EA	0.00	\$135.00	:
		0001	0680	6161052	WARNING LIGHT, TYPE B	18.00	0.00	18.00	EA	0.00	\$45.00	:
		0001	0690	6161098A	CHANGEABLE MESSAGE SIGN WITHOUT COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	2.00	0.00	2.00	EA	0.00	\$1,800.00	Ş
		0001	0700	6181000	MOBILIZATION	1.00	0.00	1.00	LS	0.00	\$35,000.00	Ş
		0001	0710	6206000C	4 IN. WHITE STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	368.00	0.00	368.00	LF	0.00	\$0.50	:
		0001	0720	6206001C	4 IN. YELLOW STANDARD WATERBORNE PAVEMENT MARKING PAINT, TYPE P BEADS	46.00	0.00	46.00	LF	0.00	\$0.50	c.
		0001	0730	6221001	COLDMILLING BITUMINOUS PAVEMENT FOR REMOVAL OF SURFACING (3 IN. THICK OR LESS)	347.00	0.00	347.00	SQYD	0.00	\$10.00	:
		0001	0740	6274000	CONTRACTOR FURNISHED SURVEYING AND STAKING	1.00	0.00	1.00	LS	0.00	\$5,000.00	ę
		0001	0750	7250436	36 IN. PIPE GROUP C	76.00	0.00	76.00	LF	0.00	\$95.00	:
		0001	0760	8051000A	SEEDING - COOL SEASON MIXTURES	1.00	0.00	1.00	ACRE	0.00	\$5,350.00	
		0001	0770	8061005	ROCK DITCH CHECK	20.00	0.00	20.00	LF	0.00	\$28.50	
		0001	0780	8061016	SEDIMENT REMOVAL	6.00	0.00	6.00	CUYD	0.00	\$5.00	:
		0001	0790	8061017	TEMPORARY SEEDING AND MULCHING	0.10	0.00	0.10	ACRE	0.00	\$15,000.00	:
		0001	0800	8061019	SILT FENCE	399.00	0.00	399.00	LF	0.00	\$2.70	:
		0070	0810	2063300	CLASS 4 EXCAVATION	185.00	0.00	185.00	CUYD	0.00	\$50.00	:
		0070	0820	2069901	MISC.DEWATERING	1.00	0.00	1.00	LS	0.00	\$30,000.00	:
		0070	0830	2160500	REMOVAL OF BRIDGES	1.00	0.00	1.00	LS	0.00	\$12,500.00	:
		0070	0840	7034041	CLASS B-1 CONCRETE (CULVERTS)	141.60	0.00	141.60	CUYD	0.00	\$985.00	:
		0070	0850	7061030	REINFORCING STEEL (CULVERTS)	27,490.00	0.00	27,490.00	LB	0.00	\$1.85	ş



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

Page 7 of 10

#### The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J9S3560

Revision 4/1/2020

0141	Item Code 6181000	MOBILIZATION	Description	DWR Date 4/1/22	DWR Approval Date 4/5/22	Quantity Posted 0.25		Bridges A89	Q1 and 10	Location		From Offs Station/ Dista Log Mile 389+48.25		Offset/ Distance	10% Complete -	Comments Pay 50% Mobilization			
		MOBILIZATION REMOVAL OF BRIE	IGES		4/5/22 3/31/22	0.25		Bridges A89 Rte 162	or and A8	σσL		389+48.25 393+65	396+11.75 396+06.17		10% Complete = Bridge L0455				
infor	mation be	elow this line ar	e details for Construction Sig	ns (if a	pplicabl	<u>e).</u>				1									
oject	Line Number	DWR Date	Total Quantity Posted For DWR Date		Sign Information		Sign Information			Station	Log Mile	Location	Number of Items	SF Each Sign		Special S	lign	SF Each Special Sign	Total SF Post
3560	0090	February 15, 2022	1277	See Sp	oecial Sign	Details			0.111	Rte F South	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50D	19.50			
		LOLL			oecial Sign				1.082	Rte EE West	1.00				nk 36" x 78" 50E	19.50			
					becial Sign				1.836	Rte J North	1.00	3	Numbered Rou	ite Sign Bla	nk 36" x 78" 50A	19.50			
					a 24x18 becial Sign		DETOU	ĸ	11.602 13.292	Rte 162 West Rte 162 East	1.00	3	Numbered Rou	ite Sign Bla	nk 36" x 78" 50F	3.00			
					pecial Sign				13.542	Rte 162 West	1.00		Special Sign 56			32.00			
				R11-4	60x30	12.50 ROA	D		13.589	Rte 162 West	1.00	12.5				12.50			
					ED TO THE		С		14.494	Rte B North	1.00		Numbers of Day	ta Oira Dia	-1. 001 - 701 505	19.50			
					pecial Sign				14.494	153 North in	1.00				nk 36" x 78" 50E nk 36" x 78" 50A	19.50			
										Gideon									
					becial Sign				15.38	153 North	1.00				nk 36" x 78" 50C	19.50			
					becial Sign				16.208	Rte 162 East	1.00				nk 36" x 78" 50F	19.50			
					pecial Sign				16.637 16.771	Rte 162 East 153 North	1.00				nk 36" x 78" 50F nk 36" x 78" 50A	19.50			
					becial Sign				16.943	Rte 162 East	1.00				nk 36" x 78" 50A	19.50			
							pecial Sign				17.028	Rte W West	2.00				nk 36" x 78" 50B	19.50	
													50E						
					becial Sign				17.143	Rte 62 East	1.00			*	nk 36" x 78" 50A	19.50			
					pecial Sign				17.915	153 North Rte 153 South	1.00			•	nk 36" x 78" 50A	19.50			
				See Sp	pecial Sign	DetailS			18.967	Ne 153 South	2.00		50E	na aigii bla	nk 36" x 78" 50B	19.50			
					oecial Sign				2.063	Rte NN South	1.00				nk 36" x 78" 50B	19.50			
					becial Sign				2.134	Rte J South	1.00				nk 36" x 78" 50F	19.50			
					ecial Sign		D		20.024	Rte 162 West Rte 162 West	1.00	12.5	Special Sign 56	ыВ 96" x 48		32.00			
				CLOSE	60x30 ED TO THR	12.50 ROA RU TRAFFI	C		20.058	Rte 162 West	1.00	12.5				12.50			
					oecial Sign				20.122	Rte 62 East	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50A	19.50			
					-3 48x48 ED AHEAD		DAD		20.946	Rte 162 West	1.00	16				16.00			
				WO20-	-3 48x48 16.00 ROAD			21.046	Rte 162 West	1.00	16	Road Closed 5	00 FT		16.00				
				CLOSED AHEAD R11-2 48x30 10.00 ROAD CLOSED			04.400	Di 100.11	4.00					40.00					
							21.189	Rte 162 West	1.00	10				10.00					
				See Sp	oecial Sign	Details			23.054	Rte 62 East	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50A	19.50			
					pecial Sign				26.340	Rte 62 East	1.00				nk 36" x 78" 50A	19.50			
					becial Sign				27.793	Rte 153 North	1.00				nk 36" x 78" 50C	19.50			
					becial Sign				28.869	153 South	1.00				nk 36" x 78" 50C	19.50			
					pecial Sign				29.021 3.67	Rte 62 East 162 East	1.00		Special Sign 56		nk 36" x 78" 50A	19.50 32.00			
							Ū		3.709	162 East	1.00	12.5	opecial oigh oc	JC 90 X 40		12.50			
					60x30 ED TO THF		с												
					becial Sign				3.81	Rte J North	1.00				nk 36" x 78" 50C	19.50			
					pecial Sign				3.859	Rte J South 153 South	1.00				nk 36" x 78" 50F nk 36" x 78" 50F	19.50			
					a 24x18			R	31.564	153 South	1.00	3	Numbered Kou	ite olgit bia	11K 30 X 78 30F	3.00			
					becial Sign		5 52100		31.929	Rte 62 East	1.00	0	Numbered Rou	ite Sign Bla	nk 36" x 78" 50A	19.50			
					becial Sign				34.233	Rte 62 East	1.00		Numbered Rou	te Sign Bla	nk 36" x 78" 50C	19.50			
				See Sp	becial Sign	Details			347.739	Rte 61 South	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50E	19.50			
				See Sp	pecial Sign	Details			349.13	Rte 61 South	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50A	19.50			
					pecial Sign					Rte 61 South	1.00			•	nk 36" x 78" 50A	19.50			
					pecial Sign					Rte 61 South	1.00				nk 36" x 78" 50A	19.50			
					pecial Sign					Rte 61 South	1.00				nk 36" x 78" 50A nk 36" x 78" 50A	19.50			
					pecial Sign					Rte 61 South Rte 61 South	1.00				nk 36" x 78" 50A nk 36" x 78" 50A	19.50			
					becial Sign				36.314	Rte 61 North	1.00				nk 36" x 78" 50A	19.50			
					ecial Sign				38.578	Rte 61 North	1.00				nk 36" x 78" 50F	19.50			
					pecial Sign				4.364	Rte B South	1.00				nk 36" x 78" 50C	19.50			
				See Sp	becial Sign	Details			40.331	Rte 61 North	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50F	19.50			
					oecial Sign				42.043	Rte 61 North	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50F	19.50			
					oecial Sign				43.430	Rte 61 North	1.00				nk 36" x 78" 50F	19.50			
					becial Sign				44.765	Rte 61 North	1.00				nk 36" x 78" 50F	19.50			
					becial Sign				45.955 54.777	Rte 61 North	1.00				nk 36" x 78" 50D	19.50			
					pecial Sign				54.777	Rte 62 West Rte 62 West	1.00				nk 36" x 78" 50F nk 36" x 78" 50F	19.50			
					becial Sign				6.298	Rte F South	1.00				nk 36" x 78" 50D	19.50			
					becial Sign				60.366	Rte 62 West	1.00				nk 36" x 78" 50F	19.50			
					becial Sign				63.395	Rte 62 West	1.00				nk 36" x 78" 50F	19.50			
				See Sp	oecial Sign	Details			66.584	Rte 62 West	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50F	19.50			
				See Sp	oecial Sign	Details			69.162	Rte 62 West	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50D	19.50			
					oecial Sign				7.02	Rte EE East	1.00				nk 36" x 78" 50D	19.50			
					oecial Sign				7.678	Rte M West	1.00		Numbered Rou	ite Sign Bla	nk 36" x 78" 50E	19.50			
				WO20- CLOSE	-3 48x48 ED AHEAD	16.00 RC	DAD		8.053	Rte 162 East	1.00	16				16.00			
						16.00 RC			8.177	Rte 162 East	1.00	16	Road Closed 5			16.00			



#### Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

# The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

The info	rmation bei	ow this line are	details for Construction Sign	is (il applicable).								
Project	Line Number	DWR Date	Total Quantity Posted For DWR Date	Sign Information	Station	Log Mile	Location	Number of Items	SF Each Sign	Special Sign	SF Each Special Sign	Total SF to Post
J9S3560	0090	February 15, 2022	1277	R11-2 48x30 10.00 ROAD CLOSED		8.297	Rte 162 East	1.00	10		10.00	10
	0090 - Total										1276.5	



# Line Item Adjustments by Estimate

Contract ID:190621-F01

Project     Line     Description     Adjustment Type     Other Adjustment Type     Created Date     Created Date     Amount By     Amount     Remarks       9S3560     070     FURNISHING TYPE 2 ROCK BLANKET     Matrial     Matrial     VIC     SYSTEM     \$19,960.00     This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0001) due to user brook3 override Estimate Exception 1 on the current Payment Estimate.       983560     Matrial - TYPE 2 ROCK BLANKET     Matrial - Gas     SYSTEM     \$19,960.00     This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0001) due to user brook3 override Estimate Item Adjustment (0001) due to user brook3 override Estimate Exception 1 on the current Payment Estimate.       0070 - Total     - Total     - Total     \$19,960.00     This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0001) due to user brook3 override Estimate Exception 1 on the current Payment Estimate.       - Total     - Total     - Total     \$0.00     Stread     \$19,960.00     This adjustment offsets the original system-generated Materia Estimate Exception 1 on the current Payment Estimate.       0707 - Total     - Total     - Total     \$0.00     Stread     \$8,300.50     This adjustment offsets the original system-generated Materia Estimate Item Adjustement (0	ing Payment Payment
Image: TYPE 2 ROCK BLANKET   TYPE 2 ROCK BLANKET   2022   Image: System 4 (0001) due to user brooks3 override Estimate Exception 1 on the current Payment Estimate.     Image:	ing Payment Payment
0090   CONSTRUCTION   Material   1   Feb 16, SYSTEM   \$8,300.50   This adjustment offsets the original system-generated Material Estimate     0090   CONSTRUCTION   Material   1   Feb 16, SYSTEM   \$8,300.50   This adjustment offsets the original system-generated Material Estimate	
0090 CONSTRUCTION SIGNS Material 1 Feb 16, 2022 SYSTEM 2022 \$8,300.50 This adjustment (0002) due to user brooks3 override Estimate Exception 1 on the current Payment Estimate.	
0070 - Total \$0.00   0090 CONSTRUCTION SIGNS Material 1 Feb 16, 2022 SYSTEM 2022 \$8,300.50 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0002) due to user brooks3 override	
Material - Total \$0.00   0070 - Total \$0.00   0090 CONSTRUCTION SIGNS Material 1 Feb 16, 2022 SYSTEM 2022 \$8,300.50 This adjustment offsets the original system-generated Material Estimate Item Adjustment (0002) due to user brooks3 override	
0070 - Total   \$0.00     0090   CONSTRUCTION SIGNS   Material   1   Feb 16, 2022   SYSTEM   \$8,300.50   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0002) due to user brooks3 override	
0090 CONSTRUCTION Material 1 Feb 16, SYSTEM \$8,300.50 This adjustment offsets the original system-generated Materia 2022 Signs 2022 Signs 2022 Strain	
SIGNS 2022 Estimate Item Adjustment (0002) due to user brooks3 override	
1 Feb 16, SYSTEM (\$8,300.50) 2022	
- Total \$0.00	
Material - Total \$0.00	
OverrunOverrun1Feb 16, 2022SYSTEM\$4,316.00This adjustment offsets the original system-generated Overrun Estimate Item Adjustment (0001) overridding Payment Estimate on the current Payment Estimate. Material Insufficiency Quan Overrun Quantity Balance 664.00.	te Exception 6
1 Feb 16, SYSTEM (\$4,316.00) 2022	
2 Mar 3, 2022 SYSTEM (\$4,316.00) Averaged Price Adjustment from this item on all previous pays of '0.00000' is applied (if non-zero).	ient estimates
Overrun - Total (\$4,316.00)	
Overrun - Total     (\$4,316.00)       Overrun - Total     (\$4,316.00)	
Overrun - Total (\$4,316.00)	
Overrun - Total (\$4,316.00)   0090 - Total (\$4,316.00)   0100 ADVANCED WARNING RAIL Material 1 Feb 16, 2022 SYSTEM \$100.00 This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0003) due to user brooks3 override	
Overrun - Total (\$4,316.00)   0090 - Total (\$4,316.00)   0100 ADVANCED WARNING RAIL SYSTEM Material   1 Feb 16, 2022 SYSTEM	
Overrun - Total (\$4,316.00)   0090 - Total (\$4,316.00)   0100 ADVANCED WARNING RAIL SYSTEM Material   1 Feb 16, 2022   2022 SYSTEM   1 Feb 16, 2022   SYSTEM   1 Feb 16, 2022   SYSTEM	
Overrun - Total   (\$4,316.00)     0090 - Total   (\$4,316.00)     0100   ADVANCED WARNING RAIL SYSTEM   Material   1   Feb 16, 2022   SYSTEM   \$100.00   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0003) due to user brooks3 override Estimate Exception 2 on the current Payment Estimate.     - Total   - Total   \$0.00   \$0.00	
Overrun - Total   (\$4,316.00)     0090 - Total   (\$4,316.00)     0100   ADVANCED WARNING RAIL SYSTEM   Material     1   Feb 16, 2022   SYSTEM   \$100.00     1   Feb 16, 2022   SYSTEM   (\$100.00)     - Total   - Total   \$0.00     Material - Total   - Total   \$0.00	
Overrun - Total   (\$4,316.00)     0090 - Total   (\$4,316.00)     0100   ADVANCED WARNING RAIL SYSTEM   Material - Total   1   Feb 16, 2022   SYSTEM   \$100.00   This adjustment offsets the original system-generated Material Estimate Item Adjustment (0003) due to user brooks3 override Estimate Exception 2 on the current Payment Estimate.     - Total   - Total   \$90.00     0100 - Total   Material - Total   \$0.00     0100 - Total   1   Feb 16, 2022   SYSTEM     0100 - Total   1   Feb 16, 2022   SYSTEM     0100 - Total   1   Feb 16, 2022   SYSTEM     0110   TYPE III MOVEABLE   Material   1   Feb 16, 2022   SYSTEM   \$1,350.00   This adjustment offsets the original system-generated Material Estimate Item Adjustment (0004) due to user brooks3 override	
Overrun - Total   Overrun - Total   (\$4,316.00)     0090 - Total   (\$4,316.00)   (\$4,316.00)     0100   ADVANCED WARNING RAIL SYSTEM   Material   1   Feb 16, 2022   SYSTEM   \$100.00   This adjustment offsets the original system-generated Material Estimate Item Adjustment (0003) due to user brooks3 override Estimate Exception 2 on the current Payment Estimate.     0100 - Total   - Total   Feb 16, 2022   SYSTEM   (\$100.00)     0100 - Total   - Total   - Total   \$0.00     0100 - Total   1   Feb 16, 2022   SYSTEM   \$1,100.00     0100 - Total   - Total   - Total   \$0.00   System-generated Material     0110   TYPE III MOVEABLE BARRICADE   Material   1   Feb 16, 2022   SYSTEM   \$1,350.00   This adjustment offsets the original system-generated Material Estimate Item Adjustment (0004) due to user brooks3 override Estimate Item Adjustment (0004) due to user brooks3 override Estimate Exception 3 on the current Payment Estimate.	
$ \begin{array}{ c c c c c c } \hline \mbox{Overrun - Total} & ($4,316.00) \\ \hline \mbox{O090 - Total} & ($4,316.00) \\ \hline \mbox{Overrun - Total} & ADVANCED \\ \hline \mbox{WARNING RALL} \\ SYSTEM \\ \hline \mbox{WARNING RALL} \\ SYSTEM \\ \hline \mbox{Veral - Total} & 1 & Feb 16, \\ & & & & & & & & & & & & & & & & & & $	
Overrun - Total   Overrun - Total   (\$4,316.00)     0090 - Total   (\$4,316.00)   This adjustment offsets the original system-generated Material System System     0100   ADVANCED WARNING RALL SYSTEM   Material   1   Feb 16, 2022   \$\SYSTEM   \$\SYSTEM (\$100.00)   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0003) due to user brooks3 override Estimate Exception 2 on the current Payment Estimate.     0100 - Total   - Total   50.00   - Total   \$\SYSTEM \$\System \System \S	
Overrun - Total   (\$4,316.00)     0090 - Total   (\$4,316.00)     0100   ADVANCED WARNING RAIL SYSTEM   Material   1   Feb 16, 2022   SYSTEM   \$100.00   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0003) due to user brooks3 override Estimate Exception 2 on the current Payment Estimate.     - Total   - Total   5VSTEM   \$(\$100.00)     - Total   - Total   50.00     0100 - Total   Material - Total   50.00     0100 - Total   1   Feb 16, 2022   SYSTEM     0110   TYPE II MOVEABLE BARRICADE   Material   1   Feb 16, 2022   SYSTEM   \$1,350.00     0110   TYPE II Move Addition   Material   1   Feb 16, 2022   SYSTEM   \$1,350.00     0110   Total   Feb 16, 2022   SYSTEM   \$1,350.00   This adjustment offsets the original system-generated Materia Estimate Exception 3 on the current Payment Estimate.     0110   Total   Feb 16, 2022   SYSTEM   \$1,350.00   This adjustment (0004) due to user brooks3 override Estimate Exception 3 on the current Payment Estimate.     0   - Total   SYSTEM   \$0.00   \$0.00   \$0.00	ing Payment
Overrun - Total   (\$4,316.00)     0090 - Total   (\$4,316.00)     0100   ADVANCED WARNING RALL SYSTEM   Material   1   Feb 16, 2022   SYSTEM   \$100.00   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0003) due to user brooks3 override Estimate Exception 2 on the current Payment Estimate.     0100   - Total   - Total   50.00     0100 - Total   - Total   - Total   \$0.00     0100 - Total   Material - Total   \$0.00     0100 - Total   TYPE III MOVEABLE BARRICADE   Material   1   Feb 16, 2022   SYSTEM   \$1,350.00   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0004) due to user brooks3 override Estimate Item Adjustment (0004) due to user brooks3 override Estimate Item Adjustment (0004) due to user brooks3 override Estimate Exception 3 on the current Payment Estimate.     0110   Total   - Total   \$2022   \$SYSTEM   \$1,350.00     0110 - Total   - Total   \$2022   \$SYSTEM   \$1,350.00   This adjustment offsets the original system-generated Materia Estimate Exception 3 on the current Payment Estimate.     0110 - Total   - Total   \$0.00   \$1,350.00   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0005) due to user brooks3 ov	ing Payment
Overrun - Total   (\$4,316.00)     0990 - Total   (\$4,316.00)     0100   ADVANCED WARNING RAIL SYSTEM   Material - Total   1   Feb 16, 2022   SYSTEM   \$100.00   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0003) due to user brooks3 override Estimate Item Adjustment (0003) due to user brooks3 override Estimate Item Adjustment (0003) due to user brooks3 override Estimate Item Adjustment (0004) due to user brooks3 override Estimate Item Adjustment (0004) due to user brooks3 override Estimate Item Adjustment offsets the original system-generated Materia Estimate Item Adjustment offsets the original system-generated Materia Estimate Item Adjustment (0004) due to user brooks3 override Estimate Item Adjustment (0005) due to user brooks3 override Estimate I	ing Payment
Overrun - Total   (\$4,316.00)     0900 - Total   (\$4,316.00)     0100   ADVANCED WARNING RAIL SYSTEM   Material   1   Feb 16, 2022   SYSTEM   \$100.00   This adjustment offsets the original system-generated Materia Estimate Item Adjustment (0003) due to user brooks 3 override Estimate Exception 2 on the current Payment Estimate.     0100   - Total   Feb 16, 2022   SYSTEM   (\$100.00)     0100 - Total   Image: Contrained trained tr	ing Payment
Overrun - Total     (\$4,316.00)       0090 - Total     (\$4,316.00)       0100     ADVANCED WARNING RAIL SYSTEM     Material       0100     ADVANCED WARNING RAIL SYSTEM     Material       0100     Total       0100     TYPE III MOVEABLE BARRICADE     Material       0110     TYPE III MATERIAL Total     Material       0110     TYPE III MOVEABLE BARRICADE     Material       0110     Total     1     Feb 16, 2022     SYSTEM     \$1,350.00       0110     Total     1     Feb 16, 2022     SYSTEM     \$1,350.00       0110     Total     50.00     This adjustment offsets the original system-generated Materia Feb 16, 2022     SYSTEM     \$1,350.00	ing Payment
Overrun - Total     (\$4,316.00)       0990 - Total     (\$4,316.00)       0100     WARNING Material     Material     2022     \$VSTEM     \$100.00     This adjustment offsets the original system-generated Material Exception 2 on the current Payment Estimate.       0100     WARNING Material     1     Feb 16, SYSTEM     \$100.00     This adjustment (003) due to user brocks3 override Estimate Exception 2 on the current Payment Estimate.       0100 - Total     - Total     50.00     This adjustment offsets the original system-generated Material - Total       0100 - Total     TYPE III     Material - Total     \$0.00     This adjustment offsets the original system-generated Material Estimate Exception 3 on the current Payment Estimate.       0110     TYPE III     Material - Total     \$0.202     \$YSTEM     \$1,350.00     This adjustment offsets the original system-generated Material Estimate Exception 3 on the current Payment Estimate.       0110     TYPE III     Material - Total     \$0.00     This adjustment offsets the original system-generated Material - Total       0110     TYPE III     Material - Total     \$0.00     This adjustment offsets the original system-generated Material - Total       0120     WARNING LIGHT, TYPE B     Material - Total     \$0.00	Payment ing Payment ing Payment Payment
Overnun - Total     (\$4,316.00)       090 - Total     (\$4,316.00)       0100     ADVANCED WARNING SYSTEM     haterial SYSTEM     1     \$2022     \$VSTEM     \$100.00     This adjustment offsets the original system-generated Materia Estimate litem Adjustment (0003) due to user trooks 30 wends Estimate litem Adjustment (0003) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0004) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (0005) due to user trooks 30 wends Estimate litem Adjustment (000	Payment ing Payment ing Payment Payment



# Line Item Adjustments by Estimate

Apr 7, 2022

Contract ID:190621-F01

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks			
J9S3560	0130	CMS W/O COMMUNICATION INTERFACE, CONT F/	Material - To	Material - Total				\$0.00				
	0130 -	Total						\$0.00				
	0160	PERMANENT EROSION CONTROL	Material		3	Mar 16, 2022	SYSTEM	\$2,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
		GEOTEXTILE			3	Mar 16, 2022	SYSTEM	(\$2,640.00)				
					4	Apr 5, 2022	SYSTEM	\$2,640.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user brooks3 overridding Payment Estimate Exception 2 on the current Payment Estimate.			
					4	Apr 5, 2022	SYSTEM	(\$2,640.00)				
				- Total				\$0.00				
			Material - Total					\$0.00				
	0160 -	Total						\$0.00				
	0290	GALVANIZED CIP CONCR PILES (16 IN)	Material		3	Mar 16, 2022	SYSTEM	\$115,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					3	Mar 16, 2022	SYSTEM	(\$115,150.00)				
					4	Apr 5, 2022	SYSTEM	\$115,150.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user brooks3 overridding Payment Estimate Exception 3 on the current Payment Estimate.			
					4	Apr 5, 2022	SYSTEM	(\$115,150.00)				
				- Total				\$0.00				
			Material - Total					\$0.00				
	0290 -	Total						\$0.00				
	0320	CLASS B CONCRETE (SUBSTRUCTURE)	Material	Material	Material	Material		3	Mar 16, 2022	SYSTEM	\$22,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.
					3	Mar 16, 2022	SYSTEM	(\$22,736.00)				
					4	Apr 5, 2022	SYSTEM	\$22,736.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user brooks3 overridding Payment Estimate Exception 7 on the current Payment Estimate.			
					4	Apr 5, 2022	SYSTEM	(\$22,736.00)				
				- Total				\$0.00				
			Material - Total					\$0.00				
	0320 - Total							\$0.00				
J9S3560 -	9S3560 - Total							(\$4,316.00)				
Overall -	verall - Total							(\$4,316.00)				