

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 3, 2022

Progress Estimate Number	Contract ID	220121-D01	Pay Period Start	May 16, 2022	Original Contract Amount	\$1,976,543.14
4	<b>Prime Contractor</b>	Lehman Construction, LLC	Pay Period End	June 1, 2022	Net Change Order Amount	\$347,855.00
7					Current Contract Amount	\$2,324,398.14

Approval Date		By User
June 3, 2022	Generated and Approved (and should be considered Draft) at the Project Office Level by	shankb1
June 3, 2022	Reviewed and Approved (and should be considered Draft) at the Resident Engineer Level by	abbote1
June 6, 2022	Reviewed and Approved at the Central Office Controllers Office Level by	ramses1

Original Completion Date	Current Completion Date	Actual Completion Date	% of Current Contract Amount Complete
December 1, 2022	December 1, 2022		22.29%

	Contract Informational Date	tes	Milestones
Date Description	Original Completion Date	<b>Current Completion Date</b>	No Milestones Exist for Contract
Acceptance Date			
Awarded Date	February 2, 2022	February 2, 2022	
Letting Date	January 21, 2022	January 21, 2022	
Notice to Proceed Date	March 7, 2022	March 7, 2022	
Open to Traffic Date			
Work Began Date			

Contract Total P	ay For Estimate No. 4				
		This Estimate	Previous	To Date	
220121-D01					
	Total Posted Items Pay	\$61,358.00	\$456,793.50	\$518,151.50	
	Gross Item Adjustments	\$0.00	\$57,408.00	\$57,408.00	
	Incentive	\$0.00	\$0.00	\$0.00	
	Disincentive	\$0.00	\$0.00	\$0.00	
	Liquidated Damage	\$0.00	\$0.00	\$0.00	
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00	
	•		\$514,201.50	\$575,559.50	
Contract Total Pa	avable This Estimate:	\$61,358,00			

## Items Paid This Estimate Period

Project Number	Line Number	Item Code	Item Description	Unit	Unit Price	Current Installed Qty	Current Installed Amount
J5I3381	0350	2161501	REMOVAL OF ASPHALT WEARING SURFACE	SQFT	\$1.000	13,514	\$13,514.00
	0420	7034214	CLASS B-2 CONCRETE	CUYD	\$2,200.000	20	\$44,000.00
	0470	7101000	REINFORCING STEEL (EPOXY COATED)	LB	\$4.000	881	\$3,524.00
	0480	7110100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (URETHANE)	LS	\$3,200.000	0.1	\$320.00
Project J5I33	81 - Total						\$61,358.00
Overall - Total	al						\$61,358.00

### Contract Adjustments This Estimate

No Contract Adjustments Exist on Contract

Line Item	Adjust	ments This Estimate						
Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5l3381	0010	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material			-1	\$3,300.00	(\$3,300.00)
	0010	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.	1	\$3,300.00	\$3,300.00
	0050	CONSTRUCTION SIGNS	Material			-1,208	\$8.00	(\$9,664.00)
	0050	CONSTRUCTION SIGNS	Material		This adjustment offsets the original system-	1,208	\$8.00	\$9,664.00

Revision 4/1/2020 Page 1 of 12

## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 3, 2022

Progress Estimate Number
4

Contract ID 220121-D01 Pay Period Start May 16, 2022 Original Contract Amount \$1,976,543.14
Pay Period End June 1, 2022 Net Change Order Amount Current Contract Amount \$347,855.00

roject umber	Line No.	Item Description	Adjustment Type	Other Item Adjustment	Comments	Adjustment Quantity	Line Item Adjustment	Adjustment amount
13381				Туре	generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.		Unit Price	
	0070	CHANNELIZER (TRIM LINE)	Material			-120	\$18.00	(\$2,160.00
	0070	CHANNELIZER (TRIM LINE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.	120	\$18.00	\$2,160.00
	0800	DIRECTIONAL INDICATOR BARRICADE	Material			-30	\$50.00	(\$1,500.00
	0800	DIRECTIONAL INDICATOR BARRICADE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.	30	\$50.00	\$1,500.00
	0090	FLASHING ARROW PANEL	Material			-2	\$1,000.00	(\$2,000.00
	0090	FLASHING ARROW PANEL	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.	2	\$1,000.00	\$2,000.00
	0100	SEQUENTIAL FLASHING WARNING LIGHT	Material			-30	\$60.00	(\$1,800.00
	0100	SEQUENTIAL FLASHING WARNING LIGHT	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.	30	\$60.00	\$1,800.00
	0110	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material			-10	\$4,500.00	(\$45,000.00
	0110	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.	10	\$4,500.00	\$45,000.00
	0120	TEMPORARY LONG-TERM RUMBLE STRIPS	Material			-4	\$1,100.00	(\$4,400.00
	0120	TEMPORARY LONG-TERM RUMBLE STRIPS	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.	4	\$1,100.00	\$4,400.00
	0140	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	Material			-576	\$26.50	(\$15,264.00
	0140	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED / RETAINED	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.	576	\$26.50	\$15,264.00
	0420	CLASS B-2 CONCRETE	Material			-20	\$2,200.00	(\$44,000.00)

Revision 4/1/2020 Page 2 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary

Pay Estimate Created Date: June 3, 2022

Progress Estimate Number					Original Contract Amount	
4	Prime Contractor	Lehman Construction, LLC	Pay Period End	June 1, 2022	Net Change Order Amount	\$347,855.00
4					<b>Current Contract Amount</b>	\$2,324,398.14

Project Number	Line No.	Item Description	Adjustment Type	Other Item Adjustment Type	Comments	Adjustment Quantity	Line Item Adjustment Unit Price	Adjustment amount
J5l3381	0420	CLASS B-2 CONCRETE	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.	20	\$2,200.00	\$44,000.00
	0480	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (URETHANE)	Material			-0.1	\$3,200.00	(\$320.00)
	0480	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (URETHANE)	Material		This adjustment offsets the original system- generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.	0.1	\$3,200.00	\$320.00
Total								\$0.00

Revision 4/1/2020 Page 3 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Project Details

					Contract Project Information
Project Number	Federal Proj. Number	Project Description	Route	County	Location of Work
J5I3381	I 44-2(325)	2 Bridge rehabilitations	44	PULASKI	over the Roubidoux Creek and over Trophy Lane near St Robert

	44-2(325) rehabilitations			
Totals by J	ob Numbers			
J5I3381		This Estimate	Previous	To Date
	Posted Item Pay	\$61,358.00	\$456,793.50	\$518,151.50
	Gross Item Adjustments	\$0.00	\$57,408.00	\$57,408.00
	Gross Item Pay	\$61,358.00	\$514,201.50	\$575,559.50
	Incentive	\$0.00	\$0.00	\$0.00
	Disincentive	\$0.00	\$0.00	\$0.00
	Liquidated Damages	\$0.00	\$0.00	\$0.00
	Other Contract Adjustments	\$0.00	\$0.00	\$0.00

Revision 4/1/2020 Page 4 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Exceptions

## **Exceptions (Discrepancies) This Estimate Period**

Exceptions / Discrepencies	Explanation	Entered By	Status
Estimate Exception Type: Insufficient Materials: Project J5I3381, Item 6122019, Project Item Line Number 0010, Material Set 612201996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3381, Item 6161005, Project Item Line Number 0050, Material Set 616100596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3381, Item 6161025, Project Item Line Number 0070, Material Set 616102596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3381, Item 6161033, Project Item Line Number 0080, Material Set 616103396, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3381, Item 6161040, Project Item Line Number 0090, Material Set 616104096, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3381, Item 6161055, Project Item Line Number 0100, Material Set 616105596, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3381, Item 6161099, Project Item Line Number 0110, Material Set 616109996, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5I3381, Item 6162002, Project Item Line Number 0120, Material Set 616200296, Material 0616TMTC - Temporary Traffic Control Devices, Acceptance Action Generic 0616TMTC is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3381, Item 6173700B, Project Item Line Number 0140, Material Set 6173700B96, Material 0617TCRCTF - Type F Concrete Traffic Barrier, Acceptance Action Generic 0617TCRCTF is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3381, Item 7034214, Project Item Line Number 0420, Material Set 703421496, Material 0501CCB2.A - Concrete, Class B-2 w/Air, Acceptance Action Generic 0501CCB2.A is insufficient.	Pending Testing	shankb1	Overridden
Estimate Exception Type: Insufficient Materials: Project J5l3381, Item 7110100, Project Item Line Number 0480, Material Set 711010096, Material 1059PCCBPR - Protective Coat Bents and Piers-Urethane, Acceptance Action Generic 1059PCCBPR is insufficient.	Pending Testing	shankb1	Overridden

Revision 4/1/2020 Page 5 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Project No.	Category	Line	Item	Description	Bid	Net	Total	Unit	Total	Unit Price	Total Value POSTE
		No.	Code	2000,pao.	Quantity	Change Order	Current Quantity	Offic	Posted Approved Qty	OTHER FIGO	To Date (See repor generated date)
J5I3381	0001	0010	6122019	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	3.00	0.00	3.00	EA	1.00	\$3,300.00	\$3,300.0
	0001	0020	6122020	REPLACEMENT SAND BARREL	6.00	0.00	6.00	EA	0.00	\$310.00	\$0.0
	0001	0030	6122030	IMPACT ATTENUATOR (RELOCATION)	3.00	0.00	3.00	EA	0.00	\$950.00	\$0.0
	0001	0040	6123000A	TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)	2.00	0.00	2.00	EA	0.00	\$2,156.00	\$0.0
	0001	0050	6161005	CONSTRUCTION SIGNS	1,651.00	0.00	1,651.00	SQFT	1,208.00	\$8.00	\$9,664.0
	0001	0060	6161008	ADVANCED WARNING RAIL SYSTEM	6.00	0.00	6.00	EA	0.00	\$100.00	\$0.0
	0001	0070	6161025	CHANNELIZER (TRIM LINE)	120.00	0.00	120.00	EA	120.00	\$18.00	\$2,160.0
	0001	0800	6161033	DIRECTIONAL INDICATOR BARRICADE	45.00	0.00	45.00	EA	30.00	\$50.00	\$1,500.0
	0001	0090	6161040	FLASHING ARROW PANEL	3.00	0.00	3.00	EA	2.00	\$1,000.00	\$2,000.0
	0001	0100	6161055	SEQUENTIAL FLASHING WARNING LIGHT	45.00	0.00	45.00	EA	30.00	\$60.00	\$1,800.0
	0001	0110	6161099	CHANGEABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE, CONTRACTOR FURNISHED, CONTRACTOR PETANLIC	10.00	0.00	10.00	EA	10.00	\$4,500.00	\$45,000.0
	0001	0120	6162002	TEMPORARY LONG-TERM RUMBLE STRIPS	6.00	0.00	6.00	EA	4.00	\$1,100.00	\$4,400.
	0001	0130	6169901	MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM	1.00	0.00	1.00	LS	0.35	\$29,000.00	\$10,150.
	0001	0140	6173700B	TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR	2,075.00	0.00	2,075.00	LF	576.00	\$26.50	\$15,264.
		0150	61750110	FURNISHED / RETAINED	2.075.00	0.00	2.075.00	15	0.00	¢19.00	\$0.
											\$110,000.
					.,		.,				\$0.
											\$0
	0001	0190	6205902A	6 IN. WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	8,040.00	0.00	8,040.00	LF	0.00	\$1.00	\$0
	0001	0200	6205903A	6 IN. YELLOW HIGH BUILD WATERBORNE PAVEMENT MARKING PAINT, TYPE L BEADS	5,930.00	0.00	5,930.00	LF	0.00	\$1.00	\$0
											\$301
											\$0
	0070	0230	2164500	CONCRETE	96.00	0.00	96.00	LF	0.00	\$399.00	\$0
	0070	0240	6233000	EPOXY POLYMER WEARING SURFACE	3,269.00	0.00	3,269.00	SQYD	0.00	\$41.55	\$0
	0070	0250	7033013	PENETRATING CONCRETE SEALER	1,052.00	0.00	1,052.00	SY	0.00	\$4.85	\$0
	0070	0260	7034214	CLASS B-2 CONCRETE	42.10	0.00	42.10	CUYD	0.00	\$1,000.00	\$0
	0070	0270	7040104	HALF-SOLE REPAIR	200.00	0.00	200.00	SQFT	0.00	\$95.00	\$0
	0070	0280	7040106	FULL DEPTH REPAIR	25.00	0.00	25.00	SQFT	0.00	\$280.00	\$0
	0070	0290	7049902	MISC.BARRIER ANCHOR REPLACEMENT	165.00	0.00	165.00	EA	0.00	\$100.00	\$0
	0070	0300	7049903	MISC.BARRIER REPAIR	450.00	0.00	450.00	LF	0.00	\$100.00	\$0
	0070	0310	7101000	REINFORCING STEEL (EPOXY COATED)	3,480.00	0.00	3,480.00	LB	0.00	\$4.00	\$0
	0070	0320	7125102	SURFACE PREPARATION FOR APPLYING EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$3,000.00	\$0
	0070	0330	7125960	ALUMINUM EPOXY-MASTIC PRIMER	1.00	0.00	1.00	LS	0.00	\$2,000.00	\$0
	0071	0340	2161001	TOTAL SURFACE HYDRO DEMOLITION	2,903.00	0.00	2,903.00	SQYD	0.00	\$8.23	\$0
	0071	0350	2161501	REMOVAL OF ASPHALT WEARING SURFACE	26,128.00	0.00	26,128.00	SQFT	13,514.00	\$1.00	\$13,514
	0071	0360	2161503	REMOVAL OF EXISTING DECK REPAIR	100.00	0.00	100.00	SQFT	0.00	\$65.00	\$0
	0071	0370	2164500	REMOVAL OF EXISTING EXPANSION JOINT & ADJACENT	84.00	0.00	84.00	LF	0.00	\$385.00	\$0
	0071	0380	2165000		84.00	0.00	84.00	LF	0.00	\$35.00	\$0
											\$0
											\$0
											\$0
											\$44,000
	0071	0430	7034600	FULL DEPTH REPAIR	1,431.00	0.00	1,431.00	SQFT	0.00	\$110.00 \$155.00	\$0 \$0
	513381	0001 0001 0001 0001 0001 0001 0001 000	0001         0020           0001         0030           0001         0040           0001         0050           0001         0060           0001         0070           0001         0080           0001         0090           0001         0100           0001         0110           0001         0130           0001         0140           0001         0150           0001         0160           0001         0170           0001         0180           0001         0190           0001         0210           0001         0210           0001         0220           0070         0220           0070         0220           0070         0240           0070         0250           0070         0260           0070         0280           0070         0280           0070         0300           0070         0310           0070         0320           0070         0330           0071         0340           0071 <td>0001         0020         6122020           0001         0030         6122030           0001         0040         6123000A           0001         0050         6161005           0001         0060         6161008           0001         0070         6161025           0001         0080         6161033           0001         0090         6161040           0001         0100         6161055           0001         0110         6161099           0001         0120         6162002           0001         0130         6169901           0001         0140         6173700B           0001         0140         6173700B           0001         0140         6175011B           0001         0150         6175011B           0001         0160         6181000           0001         0170         6205301B           0001         0180         6205303B           0001         0180         6205303B           0001         0190         6205902A           0001         0210         6205903A           0001         0220         2161500</td> <td>0001         0020         6122020         REPLACEMENT SAND BARREL           0001         0030         6122030         IMPACT ATTENUATOR (RELOCATION)           0001         0040         6123000A         TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)           0001         0060         6161005         CONSTRUCTION SIGNS           0001         0060         6161008         ADVANCED WARNING RAIL SYSTEM           0001         0060         6161040         FLASHING ARROW PANEL           0001         0060         6161040         FLASHING ARROW PANEL           0001         0100         6161040         FLASHING ARROW PANEL           0001         0100         6161040         FLASHING ARROW PANEL           0001         0100         6161099         CHANGGRABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE. CONTRACTOR RETAINED           0001         0120         6162002         TEMPORARY LONG-TERM RUMBLE STRIPS           0001         0130         6169001         MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM           0001         0140         6173008         TEMPORARY TRAFFIC BARRIER ANCHORED. CONTRACTOR FUNISHED. CONTRACTOR FUNISHED.           0001         0150         61750118         RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED. CONTRACTOR FUNISHED.           0001</td> <td>  0001   0020   6122000   REPLACEMENT SAND BARREL   6.00   0001   0030   6122030   IMPACT ATTENUATOR (RELOCATION)   3.00   0001   0040   6123000A   TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)   2.00   0001   0050   616100S   CONSTRUCTION SIGNS   1.651.00   0001   0060   616100S   ADVANCED WARNING RALL SYSTEM   6.00   0001   0060   616100S   DIRECTIONAL INDICATOR BARRICADE   45.00   0001   0060   616100S   SEQUENTIAL FLASHING WARNING LIGHT   45.00   0001   0100   616100S   SEQUENTIAL FLASHING WARNING LIGHT   45.00   0001   0100   616100S   SEQUENTIAL FLASHING WARNING LIGHT   45.00   0001   0120   616800Z   TEMPORARY LONG-TERM RUMBLE STRIPS   6.00   0001   0120   616800Z   TEMPORARY LONG-TERM RUMBLE STRIPS   6.00   0001   0130   6168001   MISC WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM   1.00   0001   0140   6113700B   TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED/ RETAINED   0001   0160   6151000   MOBILIZATION   1.00   0001   0160   6151000   MOBILIZATION   1.00   0001   0160   6151001   MOBILIZATION   1.00   0001   0160   6151000   MOBILIZATION   1.00   0001   0160   6205002A   61N WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING TAPE 4 IN., VELLOW   26,980.00   0001   0120   6205002A   61N WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING SURFACE   9,780.00   0001   0200   020</td> <td>                                     </td> <td>0001         0020         6122020         REPLACEMENT SAND BARREL         6.00         0.00         6.00           0001         0010         6122030         MPACT ATTENUATOR (RELOCATION)         3.00         0.00         3.00           0001         0010         6120300         TRUCK OR TRALET MOUNTED ATTENUATOR (TMA)         2.00         0.00         2.00           0001         0010         6161005         CONSTRUCTION SIGNS         1.651.00         0.00         0.00         6.00           0001         0070         6161003         ADVANCED WARRING RAIL SYSTEM         6.00         0.00         1.600         6.00           0001         0070         6161003         SIRECCTIONAL BOLATOR BARRICADE         45.00         0.00         45.00           0001         0090         61610045         FLASHING ARROW PAREL         3.00         0.00         3.00           0001         0110         6160019         CHANGEABLE MESSAGE BIGN WITH COMMUNICATION         40.00         0.00         45.00           0001         0120         6160019         CHASHING ARROW PAREL         3.00         0.00         6.00           0001         0120         6160019         CHASHING ARRING AR</td> <td>  0001   0000   012000   012000   012000   012000   01200   01200   01200   012000  </td> <td>  COOT   GROOT   GROOT</td> <td>  CODITION   CODITION</td>	0001         0020         6122020           0001         0030         6122030           0001         0040         6123000A           0001         0050         6161005           0001         0060         6161008           0001         0070         6161025           0001         0080         6161033           0001         0090         6161040           0001         0100         6161055           0001         0110         6161099           0001         0120         6162002           0001         0130         6169901           0001         0140         6173700B           0001         0140         6173700B           0001         0140         6175011B           0001         0150         6175011B           0001         0160         6181000           0001         0170         6205301B           0001         0180         6205303B           0001         0180         6205303B           0001         0190         6205902A           0001         0210         6205903A           0001         0220         2161500	0001         0020         6122020         REPLACEMENT SAND BARREL           0001         0030         6122030         IMPACT ATTENUATOR (RELOCATION)           0001         0040         6123000A         TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)           0001         0060         6161005         CONSTRUCTION SIGNS           0001         0060         6161008         ADVANCED WARNING RAIL SYSTEM           0001         0060         6161040         FLASHING ARROW PANEL           0001         0060         6161040         FLASHING ARROW PANEL           0001         0100         6161040         FLASHING ARROW PANEL           0001         0100         6161040         FLASHING ARROW PANEL           0001         0100         6161099         CHANGGRABLE MESSAGE SIGN WITH COMMUNICATION INTERFACE. CONTRACTOR RETAINED           0001         0120         6162002         TEMPORARY LONG-TERM RUMBLE STRIPS           0001         0130         6169001         MISC.WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM           0001         0140         6173008         TEMPORARY TRAFFIC BARRIER ANCHORED. CONTRACTOR FUNISHED. CONTRACTOR FUNISHED.           0001         0150         61750118         RELOCATING TEMPORARY TRAFFIC BARRIER ANCHORED. CONTRACTOR FUNISHED.           0001	0001   0020   6122000   REPLACEMENT SAND BARREL   6.00   0001   0030   6122030   IMPACT ATTENUATOR (RELOCATION)   3.00   0001   0040   6123000A   TRUCK OR TRAILER MOUNTED ATTENUATOR (TMA)   2.00   0001   0050   616100S   CONSTRUCTION SIGNS   1.651.00   0001   0060   616100S   ADVANCED WARNING RALL SYSTEM   6.00   0001   0060   616100S   DIRECTIONAL INDICATOR BARRICADE   45.00   0001   0060   616100S   SEQUENTIAL FLASHING WARNING LIGHT   45.00   0001   0100   616100S   SEQUENTIAL FLASHING WARNING LIGHT   45.00   0001   0100   616100S   SEQUENTIAL FLASHING WARNING LIGHT   45.00   0001   0120   616800Z   TEMPORARY LONG-TERM RUMBLE STRIPS   6.00   0001   0120   616800Z   TEMPORARY LONG-TERM RUMBLE STRIPS   6.00   0001   0130   6168001   MISC WORK ZONE INTELLIGENT TRANSPORTATION SYSTEM   1.00   0001   0140   6113700B   TEMPORARY TRAFFIC BARRIER ANCHORED, CONTRACTOR FURNISHED/ RETAINED   0001   0160   6151000   MOBILIZATION   1.00   0001   0160   6151000   MOBILIZATION   1.00   0001   0160   6151001   MOBILIZATION   1.00   0001   0160   6151000   MOBILIZATION   1.00   0001   0160   6205002A   61N WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING TAPE 4 IN., VELLOW   26,980.00   0001   0120   6205002A   61N WHITE HIGH BUILD WATERBORNE PAVEMENT MARKING SURFACE   9,780.00   0001   0200   020		0001         0020         6122020         REPLACEMENT SAND BARREL         6.00         0.00         6.00           0001         0010         6122030         MPACT ATTENUATOR (RELOCATION)         3.00         0.00         3.00           0001         0010         6120300         TRUCK OR TRALET MOUNTED ATTENUATOR (TMA)         2.00         0.00         2.00           0001         0010         6161005         CONSTRUCTION SIGNS         1.651.00         0.00         0.00         6.00           0001         0070         6161003         ADVANCED WARRING RAIL SYSTEM         6.00         0.00         1.600         6.00           0001         0070         6161003         SIRECCTIONAL BOLATOR BARRICADE         45.00         0.00         45.00           0001         0090         61610045         FLASHING ARROW PAREL         3.00         0.00         3.00           0001         0110         6160019         CHANGEABLE MESSAGE BIGN WITH COMMUNICATION         40.00         0.00         45.00           0001         0120         6160019         CHASHING ARROW PAREL         3.00         0.00         6.00           0001         0120         6160019         CHASHING ARRING AR	0001   0000   012000   012000   012000   012000   01200   01200   01200   012000	COOT   GROOT   GROOT	CODITION   CODITION

Revision 4/1/2020 Page 6 of 12



# Missouri Department of Transportation Contractor's Pay Estimate Summary Contract Line Items and Total Paid for All Estimates

Total Paid / All Items / All Estimates (Including this Estimate)
Note: Posted Quantities and Values are based on Report Generated date and can differ from the posted amount at the time the Estimate was Generated.

Contract Nm.CONTRACT	Project No.	Category	Line No.	Item Code	Description	Bid Quantity	Net Change Order	Total Current Quantity	Unit	Total Posted Approved Qty	Unit Price	Total Value POSTED To Date (See report generated date)
220121-D01	J5I3381	0071	0450	7040107	SLAB EDGE REPAIR (BRIDGES)	20.00	0.00	20.00	LF	0.00	\$120.00	\$0.00
		0071	0460	7049902	MISC.PLUGGING CURB OUTLET	48.00	0.00	48.00	EA	0.00	\$75.10	\$0.00
		0071	0470	7101000	REINFORCING STEEL (EPOXY COATED)	1,770.00	0.00	1,770.00	LB	881.00	\$4.00	\$3,524.00
		0071	0480	7110100	PROTECTIVE COATING - CONCRETE BENTS AND PIERS (URETHANE)	1.00	0.00	1.00	LS	0.10	\$3,200.00	\$320.00
		0071	0490	7129902	MISC.CORED SLAB DRAIN	52.00	0.00	52.00	EA	0.00	\$709.00	\$0.00
		0071	0500	7172002	STRIP SEAL	84.00	0.00	84.00	LF	0.00	\$280.00	\$0.00
		0001	5001	5021108	CONCRETE PAVEMENT ( 8 IN. NON-REINF)	0.00	2,399.00	2,399.00	SQYD	1,689.10	\$130.00	\$219,583.00
		0001	5002	3040504	TYPE 5 AGGREGATE FOR BASE (4 IN. THICK)	0.00	2,399.00	2,399.00	SQYD	2,111.40	\$15.00	\$31,671.00
	Project .	J5I3381 - To	otal Value	Posted to D	Date as of Report Generated Date							\$518,151.50
220121-D01 Ove	erall - Tota	I Value Pos	sted to Da	ate as of Rep	port Generated Date							\$518,151.50

Revision 4/1/2020 Page 7 of 12



## Missouri Department of Transportation Contractor's Pay Estimate Summary Installed Locations of Paid Line Items (This Estimate Only)

## The information below this line is supplemental to the Estimate and is provided for confirmation of detail, location and quantity of work.

Project: J5l3381

Line Number	Item Code	Description	DWR Date	DWR Approval Date	Quantity Posted	Units	Location	From Station/ Log Mile	Offset/ Distance	To Station/ Log Mile	Offset/ Distance	Comments
0350	2161501	REMOVAL OF ASPHALT WEARING SURFACE	6/1/22	6/3/22	13,514.00	SQFT	Removal of Asphalt from WB and EB PL on trophy lane bridges	.1				
0420	7034214	CLASS B-2 CONCRETE	6/1/22	6/3/22	20.00	CUYD	EB and WB PL Bent 1 Trophy lane bridges					
0470	7101000	REINFORCING STEEL (EPOXY COATED)	6/1/22	6/3/22	881.00	LB	EB and WB PL Bent 1 Trophy Lane bridges					
0480	7110100	PROTECTIVE COATING - CONCRETE BENTS AND	6/1/22	6/3/22	0.10	LS	Bent 1 and 5 coatings EB and WB Trophy Lane Bridges					

The information below this line are details for Construction Signs (if applicable). No Data Available

Revision 4/1/2020 Page 8 of 12



## Line Item Adjustments by Estimate

ect	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks					
381	0010	IMPACT ATTENUATOR 70 MPH (SAND BARREL ARRAY)	Material		3	May 17, 2022	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
		DAINEL ANIVAT)			3	May 17, 2022	SYSTEM	(\$3,300.00)						
					4	Jun 3, 2022	SYSTEM	\$3,300.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.					
					4	Jun 3, 2022	SYSTEM	(\$3,300.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
	0010 -	Total						\$0.00						
	0050	CONSTRUCTION SIGNS			2	May 2, 2022	SYSTEM	\$4,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0002) due to user shankb1 overridding Payment Estimate Exception 4 on the current Payment Estimate.					
					2	May 2, 2022	SYSTEM	(\$4,160.00)						
					3	May 17, 2022	SYSTEM	\$9,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
					3	May 17, 2022	SYSTEM	(\$9,664.00)						
					4	Jun 3, 2022	SYSTEM	\$9,664.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 2 on the current Payment Estimate.					
					4	Jun 3, 2022	SYSTEM	(\$9,664.00)						
				- Total				\$0.00						
			Material - To	tal				\$0.00						
	0050 -	Total						\$0.00						
	0070	CHANNELIZER (TRIM LINE)	Material		2	May 2, 2022	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.					
										2	May 2, 2022	SYSTEM	(\$2,160.00)	
					3	May 17,	CVCTEM		This adjustment effects the evisinal eveters represented Material Deciment					
						2022	SYSTEM	\$2,160.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.					
					3		SYSTEM	\$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment					
						2022 May 17,			Estimate Item Adjustment (0003) due to user shankb1 overridding Payment					
					3	2022 May 17, 2022 Jun 3,	SYSTEM	(\$2,160.00)	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment					
				- Total	3	May 17, 2022  Jun 3, 2022  Jun 3,	SYSTEM SYSTEM	(\$2,160.00) \$2,160.00	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment					
			Material - To		3	May 17, 2022  Jun 3, 2022  Jun 3,	SYSTEM SYSTEM	(\$2,160.00) \$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment					
	0070 -	Total	Material - To		3	May 17, 2022  Jun 3, 2022  Jun 3,	SYSTEM SYSTEM	(\$2,160.00) \$2,160.00 (\$2,160.00)	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment					
	<b>0070 -</b> 0080	Total  DIRECTIONAL INDICATOR BARRICADE	Material - To		3	May 17, 2022  Jun 3, 2022  Jun 3,	SYSTEM SYSTEM	(\$2,160.00) \$2,160.00 (\$2,160.00) \$0.00	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment					
		DIRECTIONAL INDICATOR			3 4 4	2022 May 17, 2022 Jun 3, 2022 Jun 3, 2022	SYSTEM SYSTEM SYSTEM	(\$2,160.00) \$2,160.00 (\$2,160.00) \$0.00 \$0.00	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment					
		DIRECTIONAL INDICATOR			3 4 4	2022 May 17, 2022 Jun 3, 2022 Jun 3, 2022 May 2, 2022	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,160.00) \$2,160.00 (\$2,160.00) \$0.00 \$0.00 \$1,500.00	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment					
		DIRECTIONAL INDICATOR			3 4 4 2 2 2	2022 May 17, 2022 Jun 3, 2022 Jun 3, 2022 May 2, 2022 May 2, 2022 May 17,	SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,160.00) \$2,160.00 (\$2,160.00) \$0.00 \$0.00 \$1,500.00	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment					
		DIRECTIONAL INDICATOR			2 2 3	2022 May 17, 2022 Jun 3, 2022 Jun 3, 2022 May 2, 2022 May 2, 2022 May 17, 2022	SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM SYSTEM	(\$2,160.00) \$2,160.00 (\$2,160.00) \$0.00 \$0.00 \$1,500.00 \$1,500.00	Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0003) due to user shankb1 overridding Payment Estimate Exception 3 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment Estimate Item Adjustment (0004) due to user shankb1 overridding Payment					



## Line Item Adjustments by Estimate

oject	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks								
3381	0800	DIRECTIONAL INDICATOR	Material	- Total				\$0.00									
		BARRICADE	Material - To	tal				\$0.00									
	0080 -	Total						\$0.00									
	0090	FLASHING ARROW PANEL	Material		2	May 2, 2022	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
					2	May 2, 2022	SYSTEM	(\$2,000.00)									
					3	May 17, 2022	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.								
					3	May 17, 2022	SYSTEM	(\$2,000.00)									
					4	Jun 3, 2022	SYSTEM	\$2,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0005) due to user shankb1 overridding Payment Estimate Exception 5 on the current Payment Estimate.								
					4	Jun 3, 2022	SYSTEM	(\$2,000.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0090 -	Total						\$0.00									
	0100	SEQUENTIAL FLASHING WARNING LIGHT	Material		2	May 2, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.								
					2	May 2, 2022	SYSTEM	(\$1,800.00)									
					3	May 17, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					3	May 17, 2022	SYSTEM	(\$1,800.00)									
													4	Jun 3, 2022	SYSTEM	\$1,800.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0006) due to user shankb1 overridding Payment Estimate Exception 6 on the current Payment Estimate.
					4	Jun 3, 2022	SYSTEM	(\$1,800.00)									
				- Total				\$0.00									
			Material - To	Total				\$0.00									
	0100 -	Total						\$0.00									
	0110	CMS WITH COMMUNICATION INTERFACE, CONT F	Material		1	Apr 19, 2022	SYSTEM	\$40,500.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0001) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.								
		33111			1	Apr 19, 2022	SYSTEM	(\$40,500.00)									
					2	May 2, 2022	SYSTEM	\$45,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.								
					2	May 2, 2022	SYSTEM	(\$45,000.00)									
					3	May 17, 2022	SYSTEM	\$45,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.								
					3	May 17, 2022	SYSTEM	(\$45,000.00)									
					4	Jun 3, 2022	SYSTEM	\$45,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0007) due to user shankb1 overridding Payment Estimate Exception 7 on the current Payment Estimate.								
					4	Jun 3, 2022	SYSTEM	(\$45,000.00)									
				- Total				\$0.00									
			Material - To	tal				\$0.00									
	0110 -	Total						\$0.00									
	0120	TEMPORARY	Material		2	May 2,	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment								



## Line Item Adjustments by Estimate

	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks
31	0120	LONG-TERM RUMBLE STRIPS	Material			2022			Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
					2	May 2, 2022	SYSTEM	(\$4,400.00)	
					3	May 17, 2022	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.
					3	May 17, 2022	SYSTEM	(\$4,400.00)	
					4	Jun 3, 2022	SYSTEM	\$4,400.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0008) due to user shankb1 overridding Payment Estimate Exception 8 on the current Payment Estimate.
					4	Jun 3, 2022	SYSTEM	(\$4,400.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0120 -							\$0.00	
	0140	TEMP. TRAFFIC BARRIER ANCHORED., CONT	Material		3	May 17, 2022	SYSTEM	\$15,264.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 12 on the current Payment Estimate.
					3	May 17, 2022	SYSTEM	(\$15,264.00)	
					4	Jun 3, 2022	SYSTEM	\$15,264.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 9 on the current Payment Estimate.
					4	Jun 3, 2022	SYSTEM	(\$15,264.00)	
				- Total				\$0.00	
			Material - To	tal				\$0.00	
	0140 -	Total						\$0.00	
	0240	EPOXY POLYMER WEARING SURFACE	Construction Stockpile STMI		2	May 2, 2022	SYSTEM	\$57,408.00	Payment Estimate Item Adjustment generated Stockpile Transaction
			011111	- Total				\$57,408.00	
			Construction	Stockpile S	TMI - Total			\$57,408.00	
	0240 -	Total							
								\$57,408.00	
	0420	CLASS B-2 CONCRETE	Material		4	Jun 3, 2022	SYSTEM	\$57,408.00 \$44,000.00	This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.
	0420	CLASS B-2	Material		4		SYSTEM		Estimate Item Adjustment (0010) due to user shankb1 overridding Payment
	0420	CLASS B-2		- Total		2022 Jun 3,		\$44,000.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment
		CLASS B-2 CONCRETE	Material  Material - To			2022 Jun 3,		\$44,000.00 (\$44,000.00) \$0.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment
	0420 -	CLASS B-2 CONCRETE				2022 Jun 3,		\$44,000.00 (\$44,000.00) \$0.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment
		CLASS B-2 CONCRETE  Total  PROTECTIVE COATING - CONCRETE	Material - To			2022 Jun 3,		\$44,000.00 (\$44,000.00) \$0.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment
	0420 -	CLASS B-2 CONCRETE  Total  PROTECTIVE COATING -	Material - To	tal	4	Jun 3, 2022	SYSTEM	\$44,000.00 (\$44,000.00) \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment
	0420 -	CLASS B-2 CONCRETE  Total  PROTECTIVE COATING - CONCRETE	Material - To	- Total	4	Jun 3, 2022  Jun 3, 2022  Jun 3, 2022	SYSTEM	\$44,000.00 (\$44,000.00) \$0.00 \$0.00 \$320.00 (\$320.00)	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment
	<b>0420 -</b> 0480	CLASS B-2 CONCRETE  Total  PROTECTIVE COATING - CONCRETE BENTS AND	Material - To	- Total	4	Jun 3, 2022  Jun 3, 2022  Jun 3, 2022	SYSTEM	\$44,000.00 (\$44,000.00) \$0.00 \$0.00 \$320.00 (\$320.00) \$0.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment
	0420 - 0480	CLASS B-2 CONCRETE  Total  PROTECTIVE COATING-CONCRETE BENTS AND	Material - To	- Total	4 4	Jun 3, 2022  Jun 3, 2022  Jun 3, 2022	SYSTEM SYSTEM	\$44,000.00 (\$44,000.00) \$0.00 \$0.00 \$320.00 (\$320.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment
	<b>0420 -</b> 0480	CLASS B-2 CONCRETE  Total  PROTECTIVE COATING - CONCRETE BENTS AND	Material - To	- Total	4	Jun 3, 2022  Jun 3, 2022  Jun 3, 2022	SYSTEM	\$44,000.00 (\$44,000.00) \$0.00 \$0.00 \$320.00 (\$320.00) \$0.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment
	0420 - 0480	CLASS B-2 CONCRETE  Total  PROTECTIVE COATING- CONCRETE BENTS AND  Total  CONCRETE PAVEMENT (8 IN.	Material - To	- Total	4 4	Jun 3, 2022  Jun 3, 2022  Jun 3, 2022  May 2,	SYSTEM SYSTEM	\$44,000.00 (\$44,000.00) \$0.00 \$0.00 \$320.00 (\$320.00) \$0.00 \$0.00 \$0.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment
	0420 - 0480	CLASS B-2 CONCRETE  Total  PROTECTIVE COATING- CONCRETE BENTS AND  Total  CONCRETE PAVEMENT (8 IN.	Material - To	- Total	4 4	Jun 3, 2022  Jun 3, 2022  Jun 3, 2022  May 2, 2022  May 2,	SYSTEM  SYSTEM  SYSTEM	\$44,000.00 (\$44,000.00) \$0.00 \$0.00 \$320.00 (\$320.00) \$0.00 \$0.00 \$126,425.00	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment
	0420 - 0480	CLASS B-2 CONCRETE  Total  PROTECTIVE COATING- CONCRETE BENTS AND  Total  CONCRETE PAVEMENT (8 IN.	Material - To	- Total	4 4 2 2 2	Jun 3, 2022  Jun 3, 2022  Jun 3, 2022  May 2, 2022  May 17, May 17,	SYSTEM  SYSTEM  SYSTEM  SYSTEM	\$44,000.00  (\$44,000.00)  \$0.00  \$0.00  \$320.00  \$320.00  \$0.00  \$0.00  \$126,425.00  (\$126,425.00)	Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Exception 10 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0011) due to user shankb1 overridding Payment Estimate Exception 11 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0009) due to user shankb1 overridding Payment Estimate Exception 1 on the current Payment Estimate.  This adjustment offsets the original system-generated Material Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment Estimate Item Adjustment (0010) due to user shankb1 overridding Payment

Jun 7, 2022



## Line Item Adjustments by Estimate

Project	Line	Description	Adjustment Type	Other Adjustment Type	Est. Number	Created Date	Created By	Amount	Remarks				
J5I3381	5001	CONCRETE PAVEMENT ( 8 IN. NON-REINF)		tal				\$0.00					
	5001 -	Total						\$0.00					
J5I3381	381 - Total												
Overall -	verall - Total												